

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2018

Reclamation District No. 0108 River Farms

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Colusa Basin Drain	Left	20.64	10/09/2018 10/09/2018	Zach Jojola

LM Start		Rating **	A	Issue No.	5
LM End		Issue Type +	Ma	Location *	N/A
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Operations & Maintenance Manuals			°	°
DWR ID	DWR_RD0108_01_s_2013_5				
Comment Code					
Inspector Comment					
RD 108 has O&M manuals.					

No Photos

LM Start		Rating **	A	Issue No.	7
LM End		Issue Type +	Ma	Location *	N/A
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Emergency Supplies & Equipment			°	°
DWR ID	DWR_RD0108_01_s_2013_7				
Comment Code					
Inspector Comment					
RD 108 maintains a stockpile of flood response materials.					

No Photos

LM Start		Rating **	A	Issue No.	9
LM End		Issue Type +	Ma	Location *	N/A
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Flood Preparedness & Training			°	°
DWR ID	DWR_RD0108_01_s_2013_9				
Comment Code					
Inspector Comment					
RD 108 has written response plans and regular flood response training.					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2018

Reclamation District No. 0108 River Farms

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Colusa Basin Drain	Left	20.64	10/09/2018 10/09/2018	Zach Jojola

LM Start	0.06	Rating **	M	Issue No.	29
LM End	0.06	Issue Type +	Ma	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP LMA Responsibility			38.822897°	38.822897°
				-121.797000°	-121.797000°
DWR ID	17943				
Comment Code					
Inspector Comment					
FS_ID:37608 DS_ID:17943 EP_NO: 9396 Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: Need to contact owner to determine status of structure. Notes indicate crossing has been abandoned. Owner will need to coordinate with CVFPB and DWR inspector to determine how to properly abandon. FIELD_STRUCT_DESC: *ABANDONED* 1 of 5: 72-inch reinforced concrete gravity drainage pipe or culvert through the levee, 31.6 feet below the crown. Slide gate on each end. (Retention of five 72-inch pipes through the levee [HLM 0.08] authorized under Automatic Board Order (ABO) issued as Permit No. 9736, 1974 - Reclamation District No. 108 [RD0108]). [Additional Reference(s): DWR Levee Log, 1991. USACE Sacramento O&M Manual 132, October 1959, (HLM 0.08), referenced as five 6-foot by 8-foot concrete drainage culverts]. FS Date: 6/10/2014					

Photo 1 of 3 : UCIP_FA_2018_37608_68207.jpg



View of concrete structure visible on waterward side.

LM Start	0.06	Rating **	M	Issue No.	29 (cont)
LM End	0.06	Issue Type +	Ma	Location *	

Photo 2 of 3 : UCIP_FA_2018_37608_68210.jpg



Dense vegetation on waterward side.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2018

Reclamation District No. 0108 River Farms

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Colusa Basin Drain	Left	20.64	10/09/2018 10/09/2018	Zach Jojola

LM Start	0.06	Rating **	M	Issue No.	29 (cont)	
LM End	0.06	Issue Type +	Ma	Location *		
Category	Supplemental			GPS Latitude/Longitude		
				Start	End	
Item	DWR UCIP LMA Responsibility			38.822897°	38.822897°	
				-121.797000°	-121.797000°	
DWR ID	17943					
Comment Code						
Inspector Comment						
FS_ID:37608 DS_ID:17943 EP_NO: 9396 Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: Need to contact owner to determine status of structure. Notes indicate crossing has been abandoned. Owner will need to coordinate with CVFPB and DWR inspector to determine how to properly abandon. FIELD_STRUCT_DESC: *ABANDONED* 1 of 5: 72-inch reinforced concrete gravity drainage pipe or culvert through the levee, 31.6 feet below the crown. Slide gate on each end. (Retention of five 72-inch pipes through the levee [HLM 0.08] authorized under Automatic Board Order (ABO) issued as Permit No. 9736, 1974 - Reclamation District No. 108 [RD0108]). [Additional Reference(s): DWR Levee Log, 1991. USACE Sacramento O&M Manual 132, October 1959, (HLM 0.08), referenced as five 6-foot by 8-foot concrete drainage culverts]. FS Date: 6/10/2014						

Photo 3 of 3 : UCIP_FA_2018_37608_68208.jpg



View of concrete structure visible on landward side.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2018

Reclamation District No. 0108 River Farms

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Colusa Basin Drain	Left	20.64	10/09/2018 10/09/2018	Zach Jojola

LM Start	0.06	Rating **	M	Issue No.	30
LM End	0.06	Issue Type +	Ma	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP LMA Responsibility			38.822919 °	38.822919 °
				-121.797046 °	-121.797046 °
DWR ID	22386				
Comment Code					
Inspector Comment					
FS_ID:37609 DS_ID:22386 EP_NO: 9396 Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: Need to contact owner to determine status of structure. Notes indicate crossing has been abandoned. Owner will need to coordinate with CVFPB and DWR inspector to determine how to properly abandon. FIELD_STRUCT_DESC: *ABANDONED* 2 of 5: 72-inch reinforced concrete gravity drainage pipe or culvert through the levee, 31.6 feet below the crown. Slide gate on each end. (Retention of five 72-inch pipes through the levee [HLM 0.08] authorized under Automatic Board Order (ABO) issued as Permit No. 9736, 1974 - Reclamation District No. 108 [RD0108]). [Additional Reference(s): DWR Levee Log, 1991. USACE Sacramento O&M Manual 132, October 1959, (HLM 0.08), referenced as five 6-foot by 8-foot concrete drainage culverts]. FS Date: 6/10/2014					

Photo 1 of 3 : UCIP_FA_2018_37609_68211.jpg



Concrete structure located on waterward side.

LM Start	0.06	Rating **	M	Issue No.	30 (cont)
LM End	0.06	Issue Type +	Ma	Location *	

Photo 2 of 3 : UCIP_FA_2018_37609_68215.jpg



Dense vegetation covers the waterward slope.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2018

Reclamation District No. 0108 River Farms

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Colusa Basin Drain	Left	20.64	10/09/2018 10/09/2018	Zach Jojola

LM Start	0.06	Rating **	M	Issue No.	30 (cont)	
LM End	0.06	Issue Type +	Ma	Location *		
Category	Supplemental			GPS Latitude/Longitude		
				Start	End	
Item	DWR UCIP LMA Responsibility			38.822919 °	38.822919 °	
				-121.797046 °	-121.797046 °	
DWR ID	22386					
Comment Code						
Inspector Comment						
FS_ID:37609 DS_ID:22386 EP_NO: 9396 Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: Need to contact owner to determine status of structure. Notes indicate crossing has been abandoned. Owner will need to coordinate with CVFPB and DWR inspector to determine how to properly abandon. FIELD_STRUCT_DESC: *ABANDONED* 2 of 5: 72-inch reinforced concrete gravity drainage pipe or culvert through the levee, 31.6 feet below the crown. Slide gate on each end. (Retention of five 72-inch pipes through the levee [HLM 0.08] authorized under Automatic Board Order (ABO) issued as Permit No. 9736, 1974 - Reclamation District No. 108 [RD0108]). [Additional Reference(s): DWR Levee Log, 1991. USACE Sacramento O&M Manual 132, October 1959, (HLM 0.08), referenced as five 6-foot by 8-foot concrete drainage culverts]. FS Date: 6/10/2014						

Photo 3 of 3 : UCIP_FA_2018_37609_68213.jpg



View of concrete structure located on landward side.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2018

Reclamation District No. 0108 River Farms

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Colusa Basin Drain	Left	20.64	10/09/2018 10/09/2018	Zach Jojola

LM Start	0.06	Rating **	M	Issue No.	31
LM End	0.06	Issue Type +	Ma	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP LMA Responsibility			38.822933 °	38.822933 °
				-121.797081 °	-121.797081 °
DWR ID	22387				
Comment Code					
Inspector Comment					
FS_ID:37610 DS_ID:22387 EP_NO: 9396 Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: Need to contact owner to determine status of structure. Notes indicate crossing has been abandoned. Owner will need to coordinate with CVFPB and DWR inspector to determine how to properly abandon. FIELD_STRUCT_DESC: *ABANDONED* 3 of 5: 72-inch reinforced concrete gravity drainage pipe or culvert through the levee, 31.6 feet below the crown. Slide gate on each end. (Retention of five 72-inch pipes through the levee [HLM 0.08] authorized under Automatic Board Order (ABO) issued as Permit No. 9736, 1974 - Reclamation District No. 108 [RD0108]). [Additional Reference(s): DWR Levee Log, 1991. USACE Sacramento O&M Manual 132, October 1959, (HLM 0.08), referenced as five 6-foot by 8-foot concrete drainage culverts]. FS Date: 6/10/2014					

Photo 1 of 3 : UCIP_FA_2018_37610_68216.jpg



Concrete structure located on waterward side.

LM Start	0.06	Rating **	M	Issue No.	31 (cont)
LM End	0.06	Issue Type +	Ma	Location *	

Photo 2 of 3 : UCIP_FA_2018_37610_68219.jpg



Dense vegetation covers waterward side slope.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2018

Reclamation District No. 0108 River Farms

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Colusa Basin Drain	Left	20.64	10/09/2018 10/09/2018	Zach Jojola

LM Start	0.06	Rating **	M	Issue No.	31 (cont)	
LM End	0.06	Issue Type +	Ma	Location *		
Category	Supplemental			GPS Latitude/Longitude		
				Start	End	
Item	DWR UCIP LMA Responsibility			38.822933 °	38.822933 °	
				-121.797081 °	-121.797081 °	
DWR ID	22387					
Comment Code						
Inspector Comment						
FS_ID:37610 DS_ID:22387 EP_NO: 9396 Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: Need to contact owner to determine status of structure. Notes indicate crossing has been abandoned. Owner will need to coordinate with CVFPB and DWR inspector to determine how to properly abandon. FIELD_STRUCT_DESC: *ABANDONED* 3 of 5: 72-inch reinforced concrete gravity drainage pipe or culvert through the levee, 31.6 feet below the crown. Slide gate on each end. (Retention of five 72-inch pipes through the levee [HLM 0.08] authorized under Automatic Board Order (ABO) issued as Permit No. 9736, 1974 - Reclamation District No. 108 [RD0108]). [Additional Reference(s): DWR Levee Log, 1991. USACE Sacramento O&M Manual 132, October 1959, (HLM 0.08), referenced as five 6-foot by 8-foot concrete drainage culverts]. FS Date: 6/10/2014						

Photo 3 of 3 : UCIP_FA_2018_37610_68217.jpg



Concrete structure located on landward side.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2018

Reclamation District No. 0108 River Farms

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Colusa Basin Drain	Left	20.64	10/09/2018 10/09/2018	Zach Jojola

LM Start	0.06	Rating **	M	Issue No.	32
LM End	0.06	Issue Type +	Ma	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP LMA Responsibility			38.822897°	38.822897°
				-121.797000°	-121.797000°
DWR ID	22388				
Comment Code					
Inspector Comment					
FS_ID:37611 DS_ID:22388 EP_NO: 9396 Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: Need to contact owner to determine status of structure. Notes indicate crossing has been abandoned. Owner will need to coordinate with CVFPB and DWR inspector to determine how to properly abandon. FIELD_STRUCT_DESC: *ABANDONED* 4 of 5: 72-inch reinforced concrete gravity drainage pipe or culvert through the levee, 31.6 feet below the crown. Slide gate on each end. (Retention of five 72-inch pipes through the levee [HLM 0.08] authorized under Automatic Board Order (ABO) issued as Permit No. 9736, 1974 - Reclamation District No. 108 [RD0108]). [Additional Reference(s): DWR Levee Log, 1991. USACE Sacramento O&M Manual 132, October 1959, (HLM 0.08), referenced as five 6-foot by 8-foot concrete drainage culverts]. FS Date: 6/10/2014					

Photo 1 of 3 : UCIP_FA_2018_37611_68220.jpg



Concrete structure located on waterward side.

LM Start	0.06	Rating **	M	Issue No.	32 (cont)
LM End	0.06	Issue Type +	Ma	Location *	

Photo 2 of 3 : UCIP_FA_2018_37611_68224.jpg



Waterward slope covered by dense vegetation.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2018

Reclamation District No. 0108 River Farms

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Colusa Basin Drain	Left	20.64	10/09/2018 10/09/2018	Zach Jojola

LM Start	0.06	Rating **	M	Issue No.	32 (cont)	
LM End	0.06	Issue Type +	Ma	Location *		
Category	Supplemental			GPS Latitude/Longitude		
				Start	End	
Item	DWR UCIP LMA Responsibility			38.822897°	38.822897°	
				-121.797000°	-121.797000°	
DWR ID	22388					
Comment Code						
Inspector Comment						
FS_ID:37611 DS_ID:22388 EP_NO: 9396 Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: Need to contact owner to determine status of structure. Notes indicate crossing has been abandoned. Owner will need to coordinate with CVFPB and DWR inspector to determine how to properly abandon. FIELD_STRUCT_DESC: *ABANDONED* 4 of 5: 72-inch reinforced concrete gravity drainage pipe or culvert through the levee, 31.6 feet below the crown. Slide gate on each end. (Retention of five 72-inch pipes through the levee [HLM 0.08] authorized under Automatic Board Order (ABO) issued as Permit No. 9736, 1974 - Reclamation District No. 108 [RD0108]). [Additional Reference(s): DWR Levee Log, 1991. USACE Sacramento O&M Manual 132, October 1959, (HLM 0.08), referenced as five 6-foot by 8-foot concrete drainage culverts]. FS Date: 6/10/2014						

Photo 3 of 3 : UCIP_FA_2018_37611_68222.jpg



Concrete structure visible on landward side.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2018

Reclamation District No. 0108 River Farms

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Colusa Basin Drain	Left	20.64	10/09/2018 10/09/2018	Zach Jojola

LM Start	0.07	Rating **	M	Issue No.	33
LM End	0.07	Issue Type +	Ma	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP LMA Responsibility			38.822954 °	38.822954 °
				-121.797135 °	-121.797135 °
DWR ID	22389				
Comment Code					
Inspector Comment					
FS_ID:37607 DS_ID:22389 EP_NO: 9396 Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: Need to contact owner to determine status of structure. Notes indicate crossing has been abandoned. Owner will need to coordinate with CVFPB and DWR inspector to determine how to properly abandon. FIELD_STRUCT_DESC: *ABANDONED* 5 of 5: 72-inch reinforced concrete gravity drainage pipe or culvert through the levee, 31.6 feet below the crown. Slide gate on each end. (Retention of five 72-inch pipes through the levee [HLM 0.08] authorized under Automatic Board Order (ABO) issued as Permit No. 9736, 1974 - Reclamation District No. 108 [RD0108]). [Additional Reference(s): DWR Levee Log, 1991. USACE Sacramento O&M Manual 132, October 1959, (HLM 0.08), referenced as five 6-foot by 8-foot concrete drainage culverts]. FS Date: 6/10/2014					

Photo 1 of 3 : UCIP_FA_2018_37607_68203.jpg



Concrete structure located on waterward side.

LM Start	0.07	Rating **	M	Issue No.	33 (cont)
LM End	0.07	Issue Type +	Ma	Location *	

Photo 2 of 3 : UCIP_FA_2018_37607_68206.jpg



Waterward slope covered by dense vegetation.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2018

Reclamation District No. 0108 River Farms

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Colusa Basin Drain	Left	20.64	10/09/2018 10/09/2018	Zach Jojola

LM Start	0.07	Rating **	M	Issue No.	33 (cont)	
LM End	0.07	Issue Type +	Ma	Location *		
Category	Supplemental			GPS Latitude/Longitude		
				Start	End	
Item	DWR UCIP LMA Responsibility			38.822954 °	38.822954 °	
				-121.797135 °	-121.797135 °	
DWR ID	22389					
Comment Code						
Inspector Comment						
FS_ID:37607 DS_ID:22389 EP_NO: 9396 Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: Need to contact owner to determine status of structure. Notes indicate crossing has been abandoned. Owner will need to coordinate with CVFPB and DWR inspector to determine how to properly abandon. FIELD_STRUCT_DESC: *ABANDONED* 5 of 5: 72-inch reinforced concrete gravity drainage pipe or culvert through the levee, 31.6 feet below the crown. Slide gate on each end. (Retention of five 72-inch pipes through the levee [HLM 0.08] authorized under Automatic Board Order (ABO) issued as Permit No. 9736, 1974 - Reclamation District No. 108 [RD0108]). [Additional Reference(s): DWR Levee Log, 1991. USACE Sacramento O&M Manual 132, October 1959, (HLM 0.08), referenced as five 6-foot by 8-foot concrete drainage culverts]. FS Date: 6/10/2014						

Photo 3 of 3 : UCIP_FA_2018_37607_68204.jpg



Concrete structure located on landward side.

LM Start	10.77	Rating **	C	Issue No.	21
LM End	10.77	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Erosion / Bank Caving			38.918902 °	38.918902 °
				-121.914589 °	-121.914589 °
DWR ID	DWR_RD0108_01_s_2018_21				
Comment Code					
E2 : Schedule repair of erosion site prior to the next inspection.					
Inspector Comment					
Minor erosion on landside slope.					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2018

Reclamation District No. 0108 River Farms

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Colusa Basin Drain	Left	20.64	10/09/2018 10/09/2018	Zach Jojola

LM Start	14.42	Rating **	C	Issue No.	28
LM End	14.42	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			38.966547 °	38.966547 °
				-121.922360 °	-121.922360 °
DWR ID	DWR_RD0108_01_f_2017_28				
Comment Code					
A3 : No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.					
Inspector Comment					
Small rodent holes on landside slope. Recommend monitoring for future activity.					

No Photos

LM Start	19.27	Rating **	A/W	Issue No.	13
LM End	19.35	Issue Type +	Ma	Location *	WS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	2017 USACE Erosion Survey, DRAFT			39.016727 °	39.017516 °
				-121.985411 °	-121.986374 °
DWR ID	DWR_RD0108_01_f _ 2018_13				
Comment Code					
Inspector Comment					
2017 Site ID: CBD 19.2 L					
Status: Eroding					
2017 Field Notes: Access Issues - Could not observe					
Site History: 2011 - Toe scour at the bottom of a steep bank, large sections of the toe are sliding down. Erosion may be due to the upstream bend.					
DWR Inspector Notes: Doesn't appear to be an issue at this time. Recommend monitoring.					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2018

Reclamation District No. 0108 River Farms

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Castle Properties	Right	0.28	10/12/2018 10/12/2018	Zach Jojola

LM Start	0.06	Rating **	C	Issue No.	1
LM End	0.06	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			38.796756 °	38.796756 °
				-121.727099 °	-121.727099 °
DWR ID	DWR_RD0108_02_s_2018_1				
Comment Code					
TR : Tree or limb					
Inspector Comment					
Fallen tree branch on wanterside slope.					

No Photos

LM Start	0.15	Rating **	A	Issue No.	2
LM End	0.15	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.797784°	38.797784°
				-121.726039°	-121.726039°
DWR ID	DWR_RD0108_02_f_2018_2				
Comment Code					
V1 : Control annual grass and weeds on the levee slopes and easements.					
Inspector Comment					
The LMA maintains the vegetation at a high level.					

Photo 1 of 1 : FA_2018_RD0108_590_2_20181012_00002.jpg



View of the maintained landside slope. Fall 2018.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---