

**Flood Control Project Maintenance
Levee Inspections**

Fall 2014 Levee Maintenance Deficiency Summary Report

Overall LMA & Unit Ratings, including USACE Erosion Survey

Sacramento River Basin

RD0307 Reclamation District No. 0307 Lisbon	Overall LMA Rating	Total LMA Miles						
	M	6.56						
Rated Item	Maintenance Deficiency				Enforcement		Design & System Obsolescence	
	M Miles	U Miles	M + 4U Miles	Threshold %	M Miles	U Miles	M Miles	U Miles
<i>Earthen Levee</i>								
Vegetation	0.08	0.06	0.32	4.88%				
Trim / Thin Trees	0.18		0.18	2.74%				
Encroachments					0.08	0.19		
Animal Control	0.13		0.13	1.98%				
Flood Preparedness & Training	0.07		0.07	1.07%				
<i>LMA Totals:</i>	0.46	0.06	0.70	10.67%	0.08	0.19	0.00	0.00

**Flood Control Project Maintenance
Levee Inspections
LMA District Cover Sheet
Fall 2014 Levee Inspection Results**

Reclamation District No. 0307 Lisbon

	Spring (March - May)	Summer ** (June - August)	Fall (September - November)	Winter ** (December - February)
* Overall LMA Rating (Fall Only)			M	

** Non-receipt of Summer or Winter Inspection Reports may effect overall annual rating.

* **SPRING INSPECTIONS:** Overall maintenance ratings are not determined for the spring inspection results. Individual maintenance deficiencies are rated using the same criteria in the spring and in the fall.

FALL INSPECTIONS: The overall maintenance rating shown above is based on operation and maintenance deficiencies identified within the attached unit inspection reports. This rating is not intended to be an indication of risk.

Comments

**Flood Control Project Maintenance
Levee Inspections**

Unit Cover Sheet

Fall 2014 Levee Inspection Results

Reclamation District No. 0307 Lisbon

Waterway		Bank	Unit Miles	
Unit No. 01 Sacramento River		Right	6.56	
	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - February)
Unit Maintenance Rating (Fall Only)			M	
Date of Inspection	04/08/2014 - 04/08/2014		10/22/2014 - 10/22/2014	
DWR Inspector	Herman Phillips		Herman Phillips	
Accompanied By	Mr. Pete Dwyer R.D.307			

Summer & Winter Inspections

The Local Maintaining Agency (LMA) is responsible for summer and winter inspections. The LMA is required to submit a report regarding summer and winter inspections to the California Department of Water Resources (DWR).

DWR must be informed on the:

- a) completion of the inspection
- b) any changes other than the results of normal maintenance
- c) corrections to deficiencies noted in this report

If additional items are noted, further documentation of those items must also be submitted.

The LMA should submit this information to DWR using the LMA web application tool available at:

<http://cdec.water.ca.gov/lma.html>

If the LMA is unable to submit information on this webpage, please contact DWR for assistance.

The LMA should submit the information and any associated documentation by September 30 for summer inspections and March 31 for winter inspections.

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2014

Reclamation District No. 0307 Lisbon

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	6.56	10/22/2014 10/22/2014	Herman Phillips

LM Start		Rating **	A	Issue No.	34
LM End		Issue Type +	Ma	Location *	LS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Operations & Maintenance Manuals			°	°
				°	°
DWR ID	DWR_RD0307_01_f_2014_34				
Action/Comments					
Inspector Comments: RD 307 has the O&M Manual on hand.					

No Photos

LM Start		Rating **	A	Issue No.	35
LM End		Issue Type +	Ma	Location *	N/A
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Emergency Supplies & Equipment			°	°
				°	°
DWR ID	DWR_RD0307_01_f_2014_35				
Action/Comments					
Inspector Comments: The District according to Mr. Pete Dwyer is part of Delta Emergence plan where supplies are kept in central location where they can gain access if and when needed.					

No Photos

LM Start		Rating **	M	Issue No.	36
LM End		Issue Type +	Ma	Location *	N/A
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Flood Preparedness & Training			°	°
				°	°
DWR ID	DWR_RD0307_01_f_2014_36				
Action/Comments					
Inspector Comments: RD 307 hasn't been to any recent training classes.					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	--	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2014

Reclamation District No. 0307 Lisbon

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	6.56	10/22/2014 10/22/2014	Herman Phillips

LM Start	0.01	Rating **	A	Issue No.	2
LM End	1.12	Issue Type +	Ma	Location *	WS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Vegetation		38.480037 °	38.472882 °	
			-121.549545 °	-121.532300 °	
DWR ID	DWR_RD0307_01_f_2014_2				
Action/Comments					
Control annual grass and weeds on the levee slopes and easements.					

No Photos

LM Start	0.01	Rating **	A	Issue No.	1
LM End	1.65	Issue Type +	Ma	Location *	N/A
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Vegetation		38.480037 °	38.473162 °	
			-121.549550 °	-121.322640 °	
DWR ID	DWR_RD0307_01_f_2014_1				
Action/Comments					
Control annual grass and weeds on the levee slopes and easements. Inspector Comments: District has done a great job of removing unwanted vegetation from levee section, landward.					

Photo 1 of 1 : FA_2014_RD0307_166_1_20141103_00003.jpg



Looking downstream from levee mile 0.01 landside to levee mile 1.65.

LM Start	0.19	Rating **	M	Issue No.	3
LM End	0.19	Issue Type +	En	Location *	WS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Encroachments		38.478078 °	38.478078 °	
			-121.547065 °	-121.547065 °	
DWR ID	DWR_RD0307_01_f_2014_3				
Action/Comments					
Tree or limb					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2014

Reclamation District No. 0307 Lisbon

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	6.56	10/22/2014 10/22/2014	Herman Phillips

LM Start	0.59	Rating **	M	Issue No.	4
LM End	0.59	Issue Type +	En	Location *	LS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Encroachments		38.474533 °	38.474533 °	
			-121.541470 °	-121.541468 °	
DWR ID	DWR_RD0307_01_f_2014_4				
Action/Comments					
Equipment					

No Photos

LM Start	0.93	Rating **	M	Issue No.	5
LM End	0.93	Issue Type +	En	Location *	WS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Encroachments		38.472863 °	38.472863 °	
			-121.535675 °	-121.535675 °	
DWR ID	DWR_RD0307_01_f_2014_5				
Action/Comments					
Debris					

No Photos

LM Start	1.12	Rating **	M	Issue No.	6
LM End	1.12	Issue Type +	En	Location *	WS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Encroachments		38.472882 °	38.472882 °	
			-121.532300 °	-121.532300 °	
DWR ID	DWR_RD0307_01_f_2014_6				
Action/Comments					
Garbage					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2014

Reclamation District No. 0307 Lisbon

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	6.56	10/22/2014 10/22/2014	Herman Phillips

LM Start	1.12	Rating **	M	Issue No.	7
LM End	1.13	Issue Type +	Ma	Location *	WS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Vegetation		38.472882 °	38.472867 °	
			-121.532300 °	-121.531983 °	
DWR ID	DWR_RD0307_01_f_2014_7				
Action/Comments					
Remove the wild growth other than native grasses from the levee slopes. Inspector Comments: Bambo on waterside slope and shoulder, spray after cutting.					

No Photos

LM Start	1.17	Rating **	A	Issue No.	8
LM End	1.55	Issue Type +	Ma	Location *	WS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Vegetation		38.472830 °	38.473107 °	
			-121.531325 °	-121.524330 °	
DWR ID	DWR_RD0307_01_f_2014_8				
Action/Comments					
Control annual grass and weeds on the levee slopes and easements.					

No Photos

LM Start	1.31	Rating **	U	Issue No.	9
LM End	1.31	Issue Type +	En	Location *	WS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Encroachments		38.472827 °	38.472827 °	
			-121.528785 °	-121.528785 °	
DWR ID	DWR_RD0307_01_f_2014_9				
Action/Comments					
Tree or limb					

Photo 1 of 1 : FA_2014_RD0307_166_9_20141103_00001.jpg



This tree needs to be removed from the waterside slope.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	--	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2014

Reclamation District No. 0307 Lisbon

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	6.56	10/22/2014 10/22/2014	Herman Phillips

LM Start	1.37	Rating **	U	Issue No.	10
LM End	1.37	Issue Type +	En	Location *	WS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Encroachments		38.472880 °	38.472880 °	
			-121.527733 °	-121.527733 °	
DWR ID	DWR_RD0307_01_f_2014_10				
Action/Comments					
Tree or limb					

Photo 1 of 1 : FA_2014_RD0307_166_10_20141103_00002.jpg



Remove unwanted trees from waterside slope. These trees are dead and are resting on the slope.

LM Start	1.56	Rating **	A/W	Issue No.	11
LM End	1.56	Issue Type +	Ma	Location *	WS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Vegetation		38.473140 °	38.473140 °	
			-121.524240 °	-121.524240 °	
DWR ID	DWR_RD0307_01_f_2014_11				
Action/Comments					
Control annual grass and weeds on the levee slopes and easements.					

No Photos

LM Start	1.60	Rating **	M	Issue No.	12
LM End	1.60	Issue Type +	En	Location *	WS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Encroachments		38.473093 °	38.473093 °	
			-121.523408 °	-121.523408 °	
DWR ID	DWR_RD0307_01_f_2014_12				
Action/Comments					
Tree or limb					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	--	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2014

Reclamation District No. 0307 Lisbon

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	6.56	10/22/2014 10/22/2014	Herman Phillips

LM Start	1.63	Rating **	M	Issue No.	13
LM End	1.63	Issue Type +	En	Location *	WS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Encroachments		38.473083 °	38.473083 °	
			-121.522912 °	-121.522912 °	
DWR ID	DWR_RD0307_01_f_2014_13				
Action/Comments					
Tree or limb					

No Photos

LM Start	1.71	Rating **	U	Issue No.	14
LM End	1.82	Issue Type +	En	Location *	WS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Encroachments		38.473243 °	38.473277 °	
			-121.521460 °	-121.519537 °	
DWR ID	DWR_RD0307_01_f_2014_14				
Action/Comments					
Garbage Inspector Comments: Remove encroachments from levee section waterward slope.					

Photo 1 of 1 : FA_2014_RD0307_166_14_20141103_00004.jpg



Garbage and debris dumped on waterside levee slope.

LM Start	1.83	Rating **	M	Issue No.	16
LM End	1.83	Issue Type +	En	Location *	WS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Encroachments		38.473255 °	38.473255 °	
			-121.519105 °	-121.519105 °	
DWR ID	DWR_RD0307_01_f_2014_16				
Action/Comments					
Tree or limb					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2014

Reclamation District No. 0307 Lisbon

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	6.56	10/22/2014 10/22/2014	Herman Phillips

LM Start	1.83	Rating **	M	Issue No.	17
LM End	1.83	Issue Type +	Ma	Location *	LS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Vegetation		38.473255 °	38.473255 °	
			-121.519105 °	-121.519105 °	
DWR ID	DWR_RD0307_01_f_2014_17				
Action/Comments					
Remove the wild growth other than native grasses from the levee slopes. Inspector Comments: Remove this fig tree from the levee slope landward.					

No Photos

LM Start	1.83	Rating **	M	Issue No.	15
LM End	1.83	Issue Type +	Ma	Location *	LS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Trim / Thin Trees		38.473255 °	38.473255 °	
			-121.519105 °	-121.519110 °	
DWR ID	DWR_RD0307_01_f_2014_15				
Action/Comments					
Trim trees to at least five feet above ground level.					

No Photos

LM Start	2.46	Rating **	M	Issue No.	18
LM End	2.47	Issue Type +	Ma	Location *	WS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Vegetation		38.471022 °	38.470913 °	
			-121.508262 °	-121.508102 °	
DWR ID	DWR_RD0307_01_f_2014_18				
Action/Comments					
Remove the wild growth other than native grasses from the levee slopes.					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2014

Reclamation District No. 0307 Lisbon

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	6.56	10/22/2014 10/22/2014	Herman Phillips

LM Start	2.85	Rating **	M	Issue No.	19
LM End	2.85	Issue Type +	Ma	Location *	LS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Trim / Thin Trees		38.466078 °	38.466078 °	
			-121.505525 °	-121.505525 °	
DWR ID	DWR_RD0307_01_f_2014_19				
Action/Comments					
Thin trees to allow visibility of the ground and room to flood fight.					

No Photos

LM Start	2.98	Rating **	M	Issue No.	20
LM End	3.02	Issue Type +	Ma	Location *	WS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Vegetation		38.464173 °	38.463763 °	
			-121.505308 °	-121.505303 °	
DWR ID	DWR_RD0307_01_f_2014_20				
Action/Comments					
Remove the wild growth other than native grasses from the levee slopes.					

No Photos

LM Start	3.48	Rating **	M	Issue No.	21
LM End	3.58	Issue Type +	Ma	Location *	LS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Animal Control		38.457192 °	38.455917 °	
			-121.503923 °	-121.503505 °	
DWR ID	DWR_RD0307_01_f_2014_21				
Action/Comments					
Exterminate rodents and backfill and compact or grout burrows.					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2014

Reclamation District No. 0307 Lisbon

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	6.56	10/22/2014 10/22/2014	Herman Phillips

LM Start	3.50	Rating **	M	Issue No.	23
LM End	3.65	Issue Type +	Ma	Location *	LS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Trim / Thin Trees		38.455637 °	38.454863 °	
			-121.503400 °	-121.503225 °	
DWR ID	DWR_RD0307_01_f_2014_23				
Action/Comments					
Thin trees to allow visibility of the ground and room to flood fight. Inspector Comments: Remove the fig tree from the levee slope landside levee section.					

No Photos

LM Start	3.58	Rating **	M	Issue No.	22
LM End	3.58	Issue Type +	Ma	Location *	LS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Trim / Thin Trees		38.455917 °	38.455917 °	
			-121.503510 °	-121.503505 °	
DWR ID	DWR_RD0307_01_f_2014_22				
Action/Comments					
Thin trees to allow visibility of the ground and room to flood fight.					

No Photos

LM Start	3.92	Rating **	M	Issue No.	24
LM End	3.92	Issue Type +	En	Location *	WS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Encroachments		38.451123 °	38.451123 °	
			-121.502622 °	-121.502622 °	
DWR ID	DWR_RD0307_01_f_2014_24				
Action/Comments					
Tree or limb					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	--	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2014

Reclamation District No. 0307 Lisbon

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	6.56	10/22/2014 10/22/2014	Herman Phillips

LM Start	4.17	Rating **	M	Issue No.	25
LM End	4.18	Issue Type +	Ma	Location *	LS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Vegetation		38.447455 °	38.447323 °	
			-121.502772 °	-121.502767 °	
DWR ID	DWR_RD0307_01_f_2014_25				
Action/Comments					
Remove the wild growth other than native grasses from the levee slopes. Inspector Comments: Remove the blakberries from the landsde levee slope.					

No Photos

LM Start	4.37	Rating **	U	Issue No.	26
LM End	4.37	Issue Type +	En	Location *	N/A
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Encroachments		38.444612 °	38.444612 °	
			-121.503100 °	-121.503100 °	
DWR ID	DWR_RD0307_01_f_2014_26				
Action/Comments					
Building Inspector Comments: This pumphouse was built without a permit, the district is aware of the encroachment.					

Photo 1 of 1 : FA_2014_RD0307_166_26_20141103_00005.jpg



This pump house was built without CVFPB Permit.

LM Start	4.45	Rating **	U	Issue No.	27
LM End	4.45	Issue Type +	En	Location *	N/A
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Encroachments		38.443517 °	38.443517 °	
			-121.503338 °	-121.503338 °	
DWR ID	DWR_RD0307_01_f_2014_27				
Action/Comments					
Crops Inspector Comments: There are grapes planted on the levee slope landside without permit from the CVFPB. This issue has been reported and recorded in previous inspections.					

Photo 1 of 1 : FA_2014_RD0307_166_27_20141103_00006.jpg



Unwanted grapes placed on levee slope, these grapes has been reported to both district and CVFPB. No permit.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	--	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2014

Reclamation District No. 0307 Lisbon

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	6.56	10/22/2014 10/22/2014	Herman Phillips

LM Start	5.40	Rating **	U	Issue No.	28
LM End	5.44	Issue Type +	En	Location *	N/A
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Encroachments		38.435728 °	38.435662 °	
			-121.516023 °	-121.516735 °	
DWR ID	DWR_RD0307_01_f_2014_28				
Action/Comments					
Tree or limb Inspector Comments: Unauthorized planting of small oleander trees on the levee slope landside, no permit for this encroachment. 15 trees at this location.					

Photo 1 of 2 : FA_2014_RD0307_166_28_20141103_00007.jpg



15 Oleander trees planted on the landside levee slope, no permit. Looking upstream from levee mile 5.40.

LM Start	5.40	Rating **	U	Issue No.	28 (cont)
LM End	5.44	Issue Type +	En	Location *	N/A

Photo 2 of 2 : FA_2014_RD0307_166_28_20141103_00008.jpg



Looking downstream from levee mile 5.40 landward at small trees planted on the levee section.

LM Start	5.46	Rating **	U	Issue No.	29
LM End	5.52	Issue Type +	Ma	Location *	LS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Vegetation		38.435638 °	38.435610 °	
			-121.517148 °	-121.518135 °	
DWR ID	DWR_RD0307_01_f_2014_29				
Action/Comments					
Remove the wild growth other than native grasses from the levee slopes.					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	--	---

