

**Flood Control Project Maintenance  
Levee Inspections**

**Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2015**

**Reclamation District No. 0369 Libby McNeil**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	0.78	09/25/2015 09/25/2015	Herman Phillips

LM Start		Rating **	M	Issue No.	<b>22</b>
LM End		Issue Type +	Ma	Location *	LS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Flood Preparedness & Training			°	°
DWR ID	DWR_RD0369_01_f_2012_22				
Action/Comments					
Inspector Comments: RD 369 members have not been flood fight trained.					

No Photos

LM Start		Rating **	M	Issue No.	<b>27</b>
LM End		Issue Type +	Ma	Location *	LS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Operations & Maintenance Manuals			°	°
DWR ID	DWR_RD0369_01_f_2014_27				
Action/Comments					
Inspector Comments: RD 369 has no O&M Manual on hand.					

No Photos

LM Start		Rating **	M	Issue No.	<b>28</b>
LM End		Issue Type +	Ma	Location *	LS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Emergency Supplies & Equipment			°	°
DWR ID	DWR_RD0369_01_f_2014_28				
Action/Comments					
Inspector Comments: RD 369 have no emergency supplies on hand.					

No Photos

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---

**Flood Control Project Maintenance  
Levee Inspections**

**Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2015**

**Reclamation District No. 0369 Libby McNeil**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	0.78	09/25/2015 09/25/2015	Herman Phillips

LM Start	<b>-0.01</b>	Rating **	A/W	Issue No.	<b>1</b>
LM End	<b>0.56</b>	Issue Type +	Ma	Location *	WS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Vegetation		38.258904 °	38.252708 °	
			-121.517904 °	-121.511260 °	
DWR ID	DWR_RD0369_01_s_2012_1				
Action/Comments					
Remove the wild growth other than native grasses from the levee slopes.					

No Photos

LM Start	<b>0.02</b>	Rating **	M	Issue No.	<b>6</b>
LM End	<b>0.10</b>	Issue Type +	Ma	Location *	WS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Vegetation		38.258645 °	38.257842 °	
			-121.517580 °	-121.516463 °	
DWR ID	DWR_RD0369_01_f_2015_6				
Action/Comments					
Control annual grass and weeds on the levee slopes and easements. Inspector Comments: Downstream from where this photo was taken we met the goat contractor with goats working this waterside slope and shoulder. From here to levee mile 0.78 waterside is good.					

Photo 1 of 1 : FA\_2015\_RD0369\_207\_6\_20150928\_00002.jpg



RD 369 Looking downstream at the waterside levee section.

LM Start	<b>0.29</b>	Rating **	M	Issue No.	<b>17</b>
LM End	<b>0.31</b>	Issue Type +	Ma	Location *	LS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Trim / Thin Trees		38.255925 °	38.255745 °	
			-121.513930 °	-121.513713 °	
DWR ID	DWR_RD0369_01_f_2014_17				
Action/Comments					
Trim trees to at least five feet above ground level. Inspector Comments: The trees along this section needs trimming.					

No Photos

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

**Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2015**

**Reclamation District No. 0369 Libby McNeil**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	0.78	09/25/2015 09/25/2015	Herman Phillips

LM Start	<b>0.72</b>	Rating **	M	Issue No.	<b>8</b>
LM End	<b>0.75</b>	Issue Type +	Ma	Location *	LS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Vegetation		38.250597 °	38.250215 °	
			-121.510240 °	-121.509990 °	
DWR ID	DWR_RD0369_01_s_2014_8				
Action/Comments					
Remove the wild growth other than native grasses from the levee slopes.					

No Photos

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---