

**Flood Control Project Maintenance
Levee Inspections
LMA District Cover Sheet
Spring 2009 Levee Inspection Results**

Reclamation District No. 0501

	Spring (March - May)	Summer ** (June - August)	Fall (September - November)	Winter ** (December - February)
* Overall LMA Rating (Fall Only)				

** Non-receipt of Summer or Winter Inspection Reports may effect overall annual rating.

* **SPRING INSPECTIONS:** Overall maintenance ratings are not determined for the spring inspection results. Individual maintenance deficiencies are rated using the same criteria in the spring and in the fall.

FALL INSPECTIONS: The overall maintenance rating shown above is based on operation and maintenance deficiencies identified within the attached unit inspection reports.

Comments

**Flood Control Project Maintenance
Levee Inspections
Unit Cover Sheet
Spring 2009 Levee Inspection Results
Reclamation District No. 0501**

Waterway		Bank	Unit Miles
Unit No. 01 Steamboat Slough		Right	6.80

	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - February)
Unit Maintenance Rating (Fall Only)				
Date of Inspection	4/6/2009 - 4/6/2009			
DWR Inspector	Herman Phillips			
Accompanied By				

Check one:

During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.

During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

Comments

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :

DWR Summer/Winter Inspection Reports
3310 El Camino Avenue, Room LL-30
Sacramento, CA 95821-9000.

X _____
Signature of LMA Representative Date

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2009

Reclamation District No. 0501

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Steamboat Slough	Right	6.80	04/06/2009 04/06/2009	Herman Phillips

LMR Line	Levee Mile		Category	Item	Location *	Rating **	Action/Comment	GPS Latitude/Longitude		Photo	Issue
	Start	End						Start	End		
1	0.00	0.04	Earthen Levee	Trim / Thin Trees	LS	M	Trim trees to at least five feet above ground level.	°	°		962
2	0.05	0.37	Earthen Levee	Vegetation	LS	M	Control annual grass and weeds on the levee slopes and easements.	38.253708 ° -121.602170 °	38.249207 ° -121.603130 °		65
3	0.05	0.15	Earthen Levee	Vegetation	WS	M	Control annual grass and weeds on the levee slopes and easements.	38.253707 ° -121.602173 °	38.252380 ° -121.602965 °		66
4	0.06	0.10	Earthen Levee	Vegetation	LS	M	Control annual grass and weeds on the levee slopes and easements.	38.184760 ° -121.658453 °	38.185400 ° -121.658737 °		87
5	0.13	0.37	Earthen Levee	Trim / Thin Trees	LS	M	Trim trees to at least five feet above ground level.	38.252658 ° -121.602835 °	38.249205 ° -121.603128 °		67
6	0.18	0.22	Earthen Levee	Vegetation	WS	M	Control annual grass and weeds on the levee slopes and easements.	38.251927 ° -121.603085 °	38.251382 ° -121.603155 °		68
7	0.20	0.28	Earthen Levee	Trim / Thin Trees	LS	C	Trim trees to at least five feet above ground level.	38.251665 ° -121.603060 °	38.250540 ° -121.603080 °		16
8	0.51	0.51	Earthen Levee	Trim / Thin Trees	LS	M	Trim trees to at least five feet above ground level.	°	°		963
9	0.54	0.54	Earthen Levee	Trim / Thin Trees	LS	M	Trim trees to at least five feet above ground level.	38.246707 ° -121.602925 °	38.246707 ° -121.602925 °		69
10	0.64	0.70	Earthen Levee	Vegetation	LS	M	Control annual grass and weeds on the levee slopes and easements.	38.245268 ° -121.602927 °	38.244458 ° -121.602978 °		70
11	0.66	0.70	Earthen Levee	Trim / Thin Trees	LS	M	Trim trees to at least five feet above ground level.	38.245010 ° -121.602955 °	38.244523 ° -121.602940 °		18
12	0.69	1.20	Earthen Levee	Animal Control	LS	M	Exterminate rodents and backfill and compact or grout burrows.	38.244667 ° -121.602967 °	38.237470 ° -121.604418 °		71
13	0.76	2.17	Earthen Levee	Vegetation	LS	M	Control annual grass and weeds on the levee slopes and easements.	38.243647 ° -121.603110 °	38.223662 ° -121.603572 °		72
14	1.04	1.12	Earthen Levee	Vegetation	WS	M	Control annual grass and weeds on the levee slopes and easements.	38.239632 ° -121.604137 °	38.238540 ° -121.604397 °		73
15	1.63	2.04	Earthen Levee	Vegetation	WS	M	Control annual grass and weeds on the levee slopes and easements.	38.231375 ° -121.603587 °	38.225592 ° -121.603923 °		74
16	1.96	1.96	Earthen Levee	Vegetation	WS	C	Elderberries are blocking visibility and flood fight capability.	38.226665 ° -121.604133 °	38.226608 ° -121.604127 °		25
17	2.04	2.10	Earthen Levee	Erosion / Bank Caving	WS	M	Note and monitor erosion site.	38.225500 ° -121.603887 °	38.224738 ° -121.603750 °		26

*** Location**
 LS : Land Side
 WS : Water Side
 CR : Crown

**** Rating**
 A : Acceptable PO : Partially Obstructing C : Corrected
 M : Minimally Acceptable CO : Completely Obstructing
 U : Unacceptable N : Not Inspected

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2009

Reclamation District No. 0501

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Steamboat Slough	Right	6.80	04/06/2009 04/06/2009	Herman Phillips

LMR Line	Levee Mile		Category	Item	Location	Rating	Action/Comment	GPS Latitude/Longitude		Photo	Issue
	Start	End						Start	End		
18	2.24	2.29	Earthen Levee	Trim / Thin Trees	LS	M	Trim trees to at least five feet above ground level.	38.222758 ° -121.603348 °	38.222030 ° -121.603303 °		27
19	2.36	2.37	Earthen Levee	Trim / Thin Trees	LS	M	Trim trees to at least five feet above ground level.	° °	° °		964
20	2.45	2.91	Earthen Levee	Vegetation	LS	M	Control annual grass and weeds on the levee slopes and easements.	38.219783 ° -121.604260 °	38.214412 ° -121.608987 °		75
21	2.55	2.60	Earthen Levee	Trim / Thin Trees	LS	U	Trim trees to at least five feet above ground level.	38.218470 ° -121.605105 °	38.217875 ° -121.605532 °		32
22	2.65	2.65	Earthen Levee	Trim / Thin Trees	LS	M	Trim trees to at least five feet above ground level.	38.217287 ° -121.606083 °	38.217287 ° -121.606083 °		33
23	2.67	2.73	Earthen Levee	Trim / Thin Trees	LS	M	Trim trees to at least five feet above ground level.	38.217030 ° -121.606303 °	38.216408 ° -121.607057 °		34
24	2.84	3.31	Earthen Levee	Vegetation	WS	M	Remove the wild growth other than native grasses from the levee slopes.	38.215112 ° -121.608273 °	38.208925 ° -121.611162 °		36
25	2.92	2.97	Earthen Levee	Encroachments	LS	PO	Landscaping	38.214235 ° -121.608993 °	38.213547 ° -121.609527 °		37
26	2.96	3.02	Earthen Levee	Vegetation	WS	M	Control annual grass and weeds on the levee slopes and easements.	38.213780 ° -121.609448 °	38.213063 ° -121.609942 °		76
27	3.01	3.02	Earthen Levee	Encroachments	LS	C	Prunings	38.213117 ° -121.609812 °	38.213030 ° -121.609852 °		39
28	3.05	3.12	Boat Survey	Boat Survey Erosion	LS	M	Inspector Comments: none	38.212568 ° -121.609707 °	38.211581 ° -121.609834 °		961
29	3.25	3.29	Earthen Levee	Vegetation	WS	M	Control annual grass and weeds on the levee slopes and easements.	38.209833 ° -121.610857 °	38.209225 ° -121.611132 °		77
30	3.26	3.72	Earthen Levee	Vegetation	LS	M	Control annual grass and weeds on the levee slopes and easements.	38.209702 ° -121.610953 °	38.203412 ° -121.613395 °		78
31	3.27	3.33	Earthen Levee	Trim / Thin Trees	LS	U	Trim trees to at least five feet above ground level.	38.209548 ° -121.610882 °	38.208632 ° -121.611275 °		41
32	3.33	3.33	Earthen Levee	Trim / Thin Trees	LS	C	Trim trees to at least five feet above ground level.	38.208710 ° -121.611242 °	38.208710 ° -121.611242 °		42
33	3.34	3.36	Earthen Levee	Trim / Thin Trees	LS	U	Trim trees to at least five feet above ground level.	38.208468 ° -121.611348 °	38.208292 ° -121.611437 °		43
34	3.59	3.60	Earthen Levee	Trim / Thin Trees	WS	C	Trim trees to at least five feet above ground level.	38.205157 ° -121.612795 °	38.204985 ° -121.612867 °		46

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected C : Corrected
--	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2009

Reclamation District No. 0501

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Steamboat Slough	Right	6.80	04/06/2009 04/06/2009	Herman Phillips

LMR Line	Levee Mile		Category	Item	Location	Rating	Action/Comment	GPS Latitude/Longitude		Photo	Issue
	Start	End						Start	End		
35	3.60	3.66	Earthen Levee	Trim / Thin Trees	LS	U	Trim and thin trees to allow visibility of the ground and room to flood fight.	38.204983 ° -121.612868 °	38.204227 ° -121.613045 °		47
36	3.74	3.76	Earthen Levee	Vegetation	WS	M	Remove the wild growth other than native grasses from the levee slopes.	38.202997 ° -121.613447 °	38.202730 ° -121.613520 °		49
37	3.76	3.80	Earthen Levee	Vegetation	LS	M	Remove the wild growth other than native grasses from the levee slopes.	38.202820 ° -121.613498 °	38.202197 ° -121.613732 °		50
38	3.76	3.80	Earthen Levee	Trim / Thin Trees	LS	U	Thin trees to allow visibility of the ground and room to flood fight.	38.202812 ° -121.613495 °	38.202213 ° -121.613733 °		51
39	3.76	4.16	Earthen Levee	Trim / Thin Trees	LS	U	Thin trees to allow visibility of the ground and room to flood fight.	38.202818 ° -121.613545 °	38.197492 ° -121.616342 °		79
40	3.80	4.16	Earthen Levee	Vegetation	LS	U	Remove the wild growth other than native grasses from the levee slopes.	38.202202 ° -121.613732 °	38.197475 ° -121.616317 °		52
41	3.80	3.95	Earthen Levee	Vegetation	WS	M	Control annual grass and weeds on the levee slopes and easements.	38.202177 ° -121.613737 °	38.200138 ° -121.614610 °		80
42	4.11	4.16	Earthen Levee	Vegetation	WS	M	Control annual grass and weeds on the levee slopes and easements.	38.198155 ° -121.615930 °	38.197495 ° -121.616333 °		81
43	4.34	4.37	Earthen Levee	Vegetation	WS	M	Control annual grass and weeds on the levee slopes and easements.	38.195695 ° -121.618717 °	38.195510 ° -121.619192 °		82
44	4.67	4.69	Earthen Levee	Vegetation	LS	C	Control annual grass and weeds on the levee slopes and easements.	38.194303 ° -121.624387 °	38.194325 ° -121.624728 °		83
45	4.81	4.96	Earthen Levee	Vegetation	WS	M	Remove the wild growth other than native grasses from the levee slopes.	38.194722 ° -121.626912 °	38.194863 ° -121.629583 °		56
46	4.93	4.94	Earthen Levee	Vegetation	LS	M	Control annual grass and weeds on the levee slopes and easements.	38.194885 ° -121.629067 °	38.194870 ° -121.629352 °		84
47	5.06	5.86	Earthen Levee	Vegetation	LS	M	Remove the wild growth other than native grasses from the levee slopes.	38.195027 ° -121.631408 °	38.189615 ° -121.644050 °		59
48	5.40	5.73	Earthen Levee	Vegetation	LS	M	Control annual grass and weeds on the levee slopes and easements.	38.192982 ° -121.637040 °	38.190727 ° -121.642112 °		86
49	5.40	5.73	Earthen Levee	Vegetation	LS	M	Control annual grass and weeds on the levee slopes and easements.	38.192983 ° -121.637042 °	38.190727 ° -121.642117 °		85
50	5.82	6.07	Earthen Levee	Trim / Thin Trees	LS	C	Trim trees to at least five feet above ground level.	38.189985 ° -121.643632 °	38.187383 ° -121.646530 °		61
51	6.16	6.16	Boat Survey	Boat Survey Erosion	LS	U	Inspector Comments: tree hazards	38.186210 ° 121.647540 °	38.186120 ° 121.647680 °		960

*** Location**
 LS : Land Side
 WS : Water Side
 CR : Crown

**** Rating**
 A : Acceptable
 M : Minimally Acceptable
 U : Unacceptable
 PO : Partially Obstructing
 CO : Completely Obstructing
 N : Not Inspected
 C : Corrected

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2009

Reclamation District No. 0501

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Steamboat Slough	Right	6.80	04/06/2009 04/06/2009	Herman Phillips

LMR Line	Levee Mile		Category	Item	Location *	Rating **	Action/Comment	GPS Latitude/Longitude		Photo	Issue
	Start	End						Start	End		
52	6.48	6.54	Earthen Levee	Vegetation	LS	M	Remove the wild growth other than native grasses from the levee slopes.	38.184792 ° -121.652962 °	38.184522 ° -121.654080 °		64

*** Location**
 LS : Land Side
 WS : Water Side
 CR : Crown

**** Rating**
 A : Acceptable PO : Partially Obstructing C : Corrected
 M : Minimally Acceptable CO : Completely Obstructing
 U : Unacceptable N : Not Inspected

**Flood Control Project Maintenance
Levee Inspections
Unit Cover Sheet
Spring 2009 Levee Inspection Results
Reclamation District No. 0501**

Waterway		Bank	Unit Miles
Unit No. 02 Cache Slough		Left	3.60

	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - February)
Unit Maintenance Rating (Fall Only)				
Date of Inspection	4/20/2009 - 4/20/2009			
DWR Inspector	Herman Phillips			
Accompanied By				

Check one:

During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.

During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

Comments

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :

DWR Summer/Winter Inspection Reports
3310 El Camino Avenue, Room LL-30
Sacramento, CA 95821-9000.

X _____
Signature of LMA Representative Date

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2009

Reclamation District No. 0501

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Cache Slough	Left	3.60	04/20/2009 04/20/2009	Herman Phillips

LMR Line	Levee Mile		Category	Item	Location *	Rating **	Action/Comment	GPS Latitude/Longitude		Photo	Issue
	Start	End						Start	End		
1	0.10	2.89	Earthen Levee	Animal Control	LS	M	Exterminate rodents and backfill and compact or grout burrows.	38.228967 ° -121.672237 °	38.218500 ° -121.669783 °		17
2	0.31	1.15	Earthen Levee	Vegetation	WS	M	Remove the wild growth other than native grasses from the levee slopes.	38.188107 ° -121.658012 °	38.199775 ° -121.655375 °		14
3	0.98	1.16	Earthen Levee	Crown Surface / Depressions / Rutting	CR	M	Keep the crown roadway free of vegetation.	38.197318 ° -121.655395 °	38.199902 ° -121.655320 °		4
4	1.13	1.17	Boat Survey	Boat Survey Erosion	CR	M	Inspector Comments: slumping, beaver holes	38.200020 ° -121.655712 °	38.199531 ° -121.655836 °		906
5	1.30	1.40	Earthen Levee	Cracking	CR	U	Monitor and have inspected by geotechnical engineer.	38.201928 ° -121.655008 °	38.203362 ° -121.654865 °		6
6	1.48	1.71	Earthen Levee	Cracking	CR	U	Monitor and have inspected by geotechnical engineer.	38.204375 ° -121.655042 °	38.207620 ° -121.656207 °		7
7	1.73	1.75	Earthen Levee	Encroachments	WS	C	Debris	38.207873 ° -121.656140 °	38.208060 ° -121.655958 °		9
8	1.83	2.12	Earthen Levee	Cracking	CR	M	Monitor and have inspected by geotechnical engineer.	38.209170 ° -121.655662 °	38.210392 ° -121.660483 °		10
9	1.96	2.87	Earthen Levee	Vegetation	LS	U	Control annual grass and weeds on the levee slopes and easements.	38.209333 ° -121.657847 °	38.218207 ° -121.669545 °		15
10	2.00	3.51	Earthen Levee	Vegetation	WS	M	Control annual grass and weeds on the levee slopes and easements.	38.209493 ° -121.658557 °	38.226932 ° -121.672923 °		16
11	3.03	3.56	Earthen Levee	Vegetation	LS	M	Control annual grass and weeds on the levee slopes and easements.	38.220317 ° -121.670917 °	38.227692 ° -121.673060 °		18
12	3.47	3.50	Earthen Levee	Trim / Thin Trees	WS	M	Trim trees to at least five feet above ground level.	38.226345 ° -121.672938 °	38.226887 ° -121.672983 °		13

*** Location**
 LS : Land Side
 WS : Water Side
 CR : Crown

**** Rating**
 A : Acceptable PO : Partially Obstructing C : Corrected
 M : Minimally Acceptable CO : Completely Obstructing
 U : Unacceptable N : Not Inspected

**Flood Control Project Maintenance
Levee Inspections
Unit Cover Sheet
Spring 2009 Levee Inspection Results
Reclamation District No. 0501**

Waterway		Bank	Unit Miles
Unit No. 03 Miner Slough		Left	7.80

	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - February)
Unit Maintenance Rating (Fall Only)				
Date of Inspection	4/20/2009 - 4/20/2009			
DWR Inspector	Herman Phillips			
Accompanied By				

Check one:

During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.

During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

Comments

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :

DWR Summer/Winter Inspection Reports
3310 El Camino Avenue, Room LL-30
Sacramento, CA 95821-9000.

X _____
Signature of LMA Representative Date

**Flood Control Project Maintenance
Levee Inspections
Levee Inspection Report By Mile - Spring 2009**

Reclamation District No. 0501

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 Miner Slough	Left	7.80	04/20/2009 04/20/2009	Herman Phillips

LMR Line	Levee Mile		Category	Item	Location *	Rating **	Action/Comment	GPS Latitude/Longitude		Photo	Issue
	Start	End						Start	End		
1	0.09	1.63	Earthen Levee	Vegetation	LS	M	Control annual grass and weeds on the levee slopes and easements.	38.229850 ° -121.671140 °	38.473800 ° -121.657930 °		41
2	0.09	1.69	Earthen Levee	Vegetation	WS	M	Control annual grass and weeds on the levee slopes and easements.	38.229850 ° -121.671140 °	38.247850 ° -121.657180 °		42
3	0.61	0.62	Earthen Levee	Trim / Thin Trees	WS	M	Trim trees to at least five feet above ground level.	38.234213 ° -121.665748 °	38.234290 ° -121.665657 °		5
4	0.82	0.84	Earthen Levee	Trim / Thin Trees	WS	M	Trim trees to at least five feet above ground level.	38.237202 ° -121.665057 °	38.237363 ° -121.665043 °		6
5	1.57	1.57	Earthen Levee	Vegetation	LS	M	Remove the wild growth other than native grasses from the levee slopes.	38.246660 ° -121.688600 °	38.666000 ° -121.690000 °		43
6	1.74	1.75	Earthen Levee	Trim / Thin Trees	WS	U	Trim trees to at least five feet above ground level.	38.247300 ° -121.658142 °	38.247377 ° -121.657997 °		10
7	1.81	1.81	Earthen Levee	Trim / Thin Trees	WS	M	Trim trees to at least five feet above ground level.	38.247820 ° -121.657192 °	38.247833 ° -121.657137 °		11
8	2.23	2.27	Earthen Levee	Trim / Thin Trees	WS	U	Thin trees to allow visibility of the ground and room to flood fight.	38.253727 ° -121.655487 °	38.254223 ° -121.655133 °		14
9	2.64	3.89	Earthen Levee	Vegetation	LS	M	Control annual grass and weeds on the levee slopes and easements.	38.257218 ° -121.651443 °	38.270062 ° -121.641497 °		35
10	2.65	2.77	Earthen Levee	Trim / Thin Trees	WS	U	Thin trees to allow visibility of the ground and room to flood fight.	38.257278 ° -121.651417 °	38.259067 ° -121.651462 °		16
11	2.97	4.87	Earthen Levee	Vegetation	WS	M	Control annual grass and weeds on the levee slopes and easements.	38.261707 ° -121.650857 °	38.281307 ° -121.641292 °		36
12	3.52	3.55	Earthen Levee	Trim / Thin Trees	WS	U	Thin trees to allow visibility of the ground and room to flood fight.	38.265523 ° -121.642537 °	38.265778 ° -121.642243 °		21
13	3.69	3.70	Earthen Levee	Trim / Thin Trees	LS	U	Thin trees to allow visibility of the ground and room to flood fight.	38.267485 ° -121.640667 °	38.267578 ° -121.640507 °		22
14	3.71	3.73	Earthen Levee	Encroachments	LS	PO	Buildings	38.267642 ° -121.640452 °	38.267907 ° -121.640327 °		23
15	3.73	3.80	Earthen Levee	Trim / Thin Trees	LS	U	Thin trees to allow visibility of the ground and room to flood fight.	38.267927 ° -121.640332 °	38.268932 ° -121.640597 °		24
16	4.99	5.95	Earthen Levee	Vegetation	LS	M	Control annual grass and weeds on the levee slopes and easements.	38.282143 ° -121.643157 °	38.290308 ° -121.636865 °		37
17	5.02	5.97	Earthen Levee	Vegetation	WS	M	Control annual grass and weeds on the levee slopes and easements.	38.282645 ° -121.643170 °	38.290280 ° -121.636638 °		38

*** Location**
 LS : Land Side
 WS : Water Side
 CR : Crown

**** Rating**
 A : Acceptable PO : Partially Obstructing C : Corrected
 M : Minimally Acceptable CO : Completely Obstructing
 U : Unacceptable N : Not Inspected

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2009

Reclamation District No. 0501

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 Miner Slough	Left	7.80	04/20/2009 04/20/2009	Herman Phillips

LMR Line	Levee Mile		Category	Item	Location	Rating	Action/Comment	GPS Latitude/Longitude		Photo	Issue
	Start	End						Start	End		
18	5.57	5.75	Earthen Levee	Vegetation	WS	M	Remove the wild growth other than native grasses from the levee slopes. Inspector Comments: District in process of burning both water side and land side of the remainder of this unit working their way to unit 4.	38.289092 ° -121.643378 °	38.289662 ° -121.640412 °		27
19	6.24	6.29	Earthen Levee	Vegetation	WS	U	Remove the wild growth other than native grasses from the levee slopes.	38.291548 ° -121.632075 °	38.291360 ° -121.631195 °		30
20	7.65	7.65	Earthen Levee	Encroachments	LS	PO	Stairways Inspector Comments: New resident has placed steps on landward slope, put up fence for grapes placed with 10-toe of land side. Took GPS AND THREE PHOTOS.	38.286785 ° -121.608583 °	38.286785 ° -121.608583 °		40
21	7.65	7.65	Earthen Levee	Encroachments	LS	C	Fences	38.286785 ° -121.608582 °	38.286785 ° -121.608582 °		39
22	7.67	7.69	Earthen Levee	Encroachments	LS	PO	Landscaping	38.286653 ° -121.608398 °	38.286342 ° -121.608183 °		33
23	7.76	7.79	Earthen Levee	Vegetation	LS	M	Remove the wild growth other than native grasses from the levee slopes.	38.285807 ° -121.607258 °	38.285668 ° -121.606657 °		34

*** Location**
 LS : Land Side
 WS : Water Side
 CR : Crown

**** Rating**
 A : Acceptable PO : Partially Obstructing C : Corrected
 M : Minimally Acceptable CO : Completely Obstructing
 U : Unacceptable N : Not Inspected

**Flood Control Project Maintenance
Levee Inspections
Unit Cover Sheet
Spring 2009 Levee Inspection Results
Reclamation District No. 0501**

Waterway		Bank	Unit Miles
Unit No. 04 Sutter Slough		Right	2.30

	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - February)
Unit Maintenance Rating (Fall Only)				
Date of Inspection	4/20/2009 - 4/20/2009			
DWR Inspector	Herman Phillips			
Accompanied By				

Check one:

During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.

During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

Comments

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :

DWR Summer/Winter Inspection Reports
3310 El Camino Avenue, Room LL-30
Sacramento, CA 95821-9000.

X _____
Signature of LMA Representative Date

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2009

Reclamation District No. 0501

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 04 Sutter Slough	Right	2.30	04/20/2009 04/20/2009	Herman Phillips

LMR Line	Levee Mile		Category	Item	Location *	Rating **	Action/Comment	GPS Latitude/Longitude		Photo	Issue
	Start	End						Start	End		
1	0.00	1.28	Earthen Levee	Vegetation	LS	M	Control annual grass and weeds on the levee slopes and easements.	38.254377 ° -121.601628 °	38.268773 ° -121.604190 °		28
2	0.02	0.02	Earthen Levee	Vegetation	WS	M	Elderberries are blocking visibility and flood fight capability.	38.254025 ° -121.601752 °	38.254025 ° -121.601752 °		25
3	0.02	0.02	Earthen Levee	Vegetation	WS	M	Remove the wild growth other than native grasses from the levee slopes.	38.254025 ° -121.601752 °	38.254025 ° -121.601752 °		20
4	0.24	0.38	Earthen Levee	Vegetation	LS	M	Control annual grass and weeds on the levee slopes and easements.	38.282942 ° -121.603310 °	38.281302 ° -121.601905 °		26
5	0.50	1.15	Earthen Levee	Vegetation	LS	U	Remove the wild growth other than native grasses from the levee slopes.	38.279532 ° -121.601325 °	38.270747 ° -121.604477 °		3
6	0.50	0.78	Earthen Levee	Vegetation	LS	M	Control annual grass and weeds on the levee slopes and easements.	38.279522 ° -121.601302 °	38.275657 ° -121.602153 °		27
7	0.79	0.79	Earthen Levee	Trim / Thin Trees	LS	M	Trim trees to at least five feet above ground level.	38.275540 ° -121.602223 °	38.275473 ° -121.602248 °		4
8	0.85	0.88	Earthen Levee	Vegetation	LS	U	Remove the wild growth other than native grasses from the levee slopes.	38.274717 ° -121.602690 °	38.274372 ° -121.602957 °		5
9	1.01	1.01	Earthen Levee	Trim / Thin Trees	LS	M	Trim trees to at least five feet above ground level.	38.272733 ° -121.603940 °	38.272700 ° -121.603953 °		7
10	1.26	1.27	Earthen Levee	Trim / Thin Trees	LS	M	Trim trees to at least five feet above ground level.	38.269173 ° -121.604218 °	38.269050 ° -121.604170 °		9
11	1.31	1.52	Earthen Levee	Vegetation	WS	C	Control annual grass and weeds on the levee slopes and easements.	38.268425 ° -121.604012 °	38.265617 ° -121.602538 °		29
12	1.67	1.76	Earthen Levee	Trim / Thin Trees	LS	M	Trim and thin trees to allow visibility of the ground and room to flood fight.	38.263565 ° -121.602013 °	38.262287 ° -121.601722 °		12
13	1.84	1.87	Earthen Levee	Trim / Thin Trees	LS	U	Thin trees to allow visibility of the ground and room to flood fight.	38.261142 ° -121.601542 °	38.260653 ° -121.601435 °		14
14	2.18	2.20	Earthen Levee	Trim / Thin Trees	LS	M	Trim trees to at least five feet above ground level.	38.256275 ° -121.600933 °	38.255990 ° -121.601015 °		13
15	2.21	2.32	Earthen Levee	Encroachments	LS	CO	Landscaping	38.255877 ° -121.601057 °	38.254382 ° -121.601498 °		16

*** Location**
 LS : Land Side
 WS : Water Side
 CR : Crown

**** Rating**
 A : Acceptable
 M : Minimally Acceptable
 U : Unacceptable
 PO : Partially Obstructing
 CO : Completely Obstructing
 N : Not Inspected
 C : Corrected