

**Flood Control Project Maintenance  
Levee Inspections****LMA District Cover Sheet****Spring 2011 Levee Inspection Results****Reclamation District No. 0755 Randall**

	Spring (March - May)	Summer ** (June - August)	Fall (September - November)	Winter ** (December - February)
* Overall LMA Rating (Fall Only)				

\*\* Non-receipt of Summer or Winter Inspection Reports may effect overall annual rating.

\*  
SPRING INSPECTIONS: Overall maintenance ratings are not determined for the spring inspection results. Individual maintenance deficiencies are rated using the same criteria in the spring and in the fall.

FALL INSPECTIONS: The overall maintenance rating shown above is based on operation and maintenance deficiencies identified within the attached unit inspection reports.

Comments


**Flood Control Project Maintenance  
Levee Inspections**

**Unit Cover Sheet**

**Spring 2011 Levee Inspection Results**

**Reclamation District No. 0755 Randall**

Waterway			Bank	Unit Miles
Unit No. 01 Sacramento River			Left	1.86

  

	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - February)
Unit Maintenance Rating (Fall Only)				
Date of Inspection	3/30/2011 - 3/30/2011			
DWR Inspector	Herman Phillips			
Accompanied By	Gil COSIO RD 755			
	Matthew Hemly RD755			
	None None			
	Mr. Matthew Hemly RD 755			

Check one:

- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.
- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

Comments

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :

DWR Summer/Winter Inspection Reports  
3310 El Camino Avenue, Suite 200  
Sacramento, CA 95821-9000

**X**

Signature of LMA Representative

Date

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2011**

**Reclamation District No. 0755 Randall**

Waterway						Bank	Unit Miles	Inspection Start/End	Inspector	
Unit No. 01 Sacramento River						Left	1.86	03/30/2011 03/30/2011	Herman Phillips	

  

LMR No.	Levee Mile		Category	Item	Location	Rating	Action/Comment	GPS Latitude/Longitude		Issue No.
	Start	End						Start	End	Photo
1	0.02	0.02	Earthen Levee	Encroachments	LS	PO	Fences Inspector Comments: The land owner has installed the fence without PERMIT, I met with owner 10-16-2009. An application is being prepared for submittal todote. Photos were taken.	38.347517 ° -121.535943 °	38.347517 ° -121.535943 °	23 Y
2	0.03	0.03	Earthen Levee	Vegetation	LS	A	Control annual grass and weeds on the levee slopes and easements.	° °	° °	6 Y
3	0.03	0.03	Earthen Levee	Vegetation	WS	A	Control annual grass and weeds on the levee slopes and easements.	° °	° °	7 Y
4	0.26	0.26	Earthen Levee	Vegetation	LS	C	Remove the wild growth other than native grasses from the levee slopes.	38.346450 ° -121.540260 °	38.346450 ° -121.540260 °	1
5	0.26	0.26	Earthen Levee	Vegetation	WS	C	Remove the wild growth other than native grasses from the levee slopes.	38.346450 ° -121.540260 °	38.346450 ° -121.540260 °	2
6	0.43	0.43	Earthen Levee	Trim / Thin Trees	LS	C	Tree stumps.	38.345653 ° -121.542942 °	38.345653 ° -121.542942 °	3
7	0.55	1.78	Earthen Levee	Animal Control	LS	M	Exterminate rodents and backfill and compact or grout burrows.	38.345637 ° -121.545270 °	38.337432 ° -121.564027 °	4
8	0.79	0.83	Earthen Levee	Animal Control	LS	M	No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.	38.344608 ° -121.549855 °	38.344403 ° -121.550523 °	5
9	1.74	1.83	Earthen Levee	Encroachments	LS	PO	Landscaping	38.337702 ° -121.563618 °	38.336855 ° -121.564545 °	13

**\* Location**

LS : Landside  
WS : Waterside  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
PO : Partially Obstructing  
CO : Completely Obstructing  
N : Not Inspected/Rated  
C : Corrected  
W : Watch/Monitor

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2011**

**Reclamation District No. 0755 Randall**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	1.86	03/30/2011 03/30/2011	Herman Phillips

Levee Mile Report Line	1
Start Levee Mile	0.02
End Levee Mile	0.02
Location	Land Side
Category	Earthen Levee
Item	Encroachments

This is the gate Mr. Hemley has installed without a Permit.

phillips\_s\_20110228\_120.jpg



Levee Mile Report Line	1
Start Levee Mile	0.02
End Levee Mile	0.02
Location	Land Side
Category	Earthen Levee
Item	Encroachments

Hemley's gate

phillips\_s\_20110228\_121.jpg



Levee Mile Report Line	2
Start Levee Mile	0.03
End Levee Mile	0.03
Location	Land Side
Category	Earthen Levee
Item	Vegetation

Landside levee mile 0.03 looking downstream in RD 755. Photo taken 03-30,-2011.

phillips\_s\_20110330\_219.jpg



**\* Location**

LS : Landside  
WS : Waterside  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable

PO : Partially Obstructing  
CO : Completely Obstructing  
N : Not Inspected/Rated

C : Corrected  
W : Watch/Monitor

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2011**

**Reclamation District No. 0755 Randall**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	1.86	03/30/2011 03/30/2011	Herman Phillips

Levee Mile Report Line	3
Start Levee Mile	0.03
End Levee Mile	0.03
Location	Water Side
Category	Earthen Levee
Item	Vegetation

Looking downstream from levee mile 0.03 RD 755. Photo taken 03-30-2011.

phillips\_s\_20110330\_220.jpg



**\* Location**

LS : Landside  
WS : Waterside  
CR : Crown

**\*\* Rating**

A : Acceptable      PO : Partially Obstructing      C : Corrected  
M : Minimally Acceptable      CO : Completely Obstructing      W : Watch/Monitor  
U : Unacceptable      N : Not Inspected/Rated