

**Flood Control Project Maintenance
Levee Inspections**
LMA District Cover Sheet
Spring 2019 Levee Inspection Results

Reclamation District No. 0755 Randall

	Spring (March - May)	Summer ** (June - August)	Fall (September - November)	Winter ** (December - February)
† Overall LMA Rating (Fall Only)				

** Non-receipt of Summer or Winter Inspection
Reports may effect overall annual rating.

† SPRING INSPECTIONS: Overall maintenance ratings are not determined for the spring inspection results. Individual maintenance deficiencies are rated using the same criteria in the spring and in the fall.

FALL INSPECTIONS: The overall maintenance rating shown above is based on operation and maintenance deficiencies identified within the attached unit inspection reports. This rating is not intended to be an indication of risk.

Comments

**Flood Control Project Maintenance
Levee Inspections**

Unit Cover Sheet

Spring 2019 Levee Inspection Results

Reclamation District No. 0755 Randall

Waterway			Bank	Unit Miles
Unit No. 01 Sacramento River			Left	1.83
	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - February)
Unit Maintenance Rating (Fall Only)				
Date of Inspection	3/15/2019 - 3/15/2019			
DWR Inspector	David Julian			
Accompanied By				

Summer & Winter Inspections

The Local Maintaining Agency (LMA) is responsible for summer and winter inspections. The LMA is required to submit a report regarding summer and winter inspections to the California Department of Water Resources (DWR).

DWR must be informed on the:

- a) completion of the inspection
- b) any changes other than the results of normal maintenance
- c) corrections to deficiencies noted in this report

If additional items are noted, further documentation of those items must also be submitted.

The LMA should submit this information to DWR using the LMA web application tool available at:

<http://cdec.water.ca.gov/lma.html>

If the LMA is unable to submit information on this webpage, please contact DWR for assistance.

The LMA should submit the information and any associated documentation by September 30 for summer inspections and March 31 for winter inspections.

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2019

Reclamation District No. 0755 Randall

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	1.83	03/15/2019 03/15/2019	David Julian

LM Start		Rating **	M	Issue No.	14
LM End		Issue Type +	Ma	Location *	
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Flood Preparedness & Training				
DWR ID	DWR_RD0755_01_f_2014_14				
Comment Code					
Inspector Comment					
This district has a knowledge of how to conduct a flood fight but has not taken the class recently.					

No Photos

LM Start		Rating **	A	Issue No.	15
LM End		Issue Type +	Ma	Location *	
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Emergency Supplies & Equipment				
DWR ID	DWR_RD0755_01_f_2014_15				
Comment Code					
Inspector Comment					
District maintains supply of sand bags and gets other supplies from other districts.					

No Photos

LM Start		Rating **	A	Issue No.	16
LM End		Issue Type +	Ma	Location *	
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Operations & Maintenance Manuals				
DWR ID	DWR_RD0755_01_f_2014_16				
Comment Code					
Inspector Comment					
MBK Engineering mailed a copy of the O/M Manul to the RD President in spring of 2017.					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
----------------------------------------------------------------------------------------------	------------------------------------------------------------------------------------	-------------------------------------------------------------------------------------	-------------------------------------------------------------------------------------------------------------

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2019

Reclamation District No. 0755 Randall

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	1.83	03/15/2019 03/15/2019	David Julian

LM Start	0.00	Rating **	M	Issue No.	11
LM End	0.17	Issue Type +	Ma	Location *	CR
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.347123 °	38.346773 °
				-121.537572 °	-121.538687 °
DWR ID	DWR_RD0755_01_s_2017_11				
Comment Code					
V9 : Keep the crown roadway free of vegetation.					
Inspector Comment					
Crown vegetation should be mowed to allow inspection.					

Photo 1 of 1 : SP_2019_RD0755_177_11_20190311_00001.jpg



Crown vegetation should be reduced.

LM Start	0.17	Rating **	M	Issue No.	20
LM End	0.85	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.346757 °	38.344390 °
				-121.538675 °	-121.550762 °
DWR ID	DWR_RD0755_01_f_2016_20				
Comment Code					
V2 : Remove the wild growth other than native grasses from the levee slopes.					
Inspector Comment					
The vegetation should be removed/managed to allow inspection of lanside slope and toe.					

Photo 1 of 2 : SP_2019_RD0755_177_20_20190311_00008.jpg



View looking downstream at vegetation on the land sideslope (October 2018).

LM Start	0.17	Rating **	M	Issue No.	20 (cont)
LM End	0.85	Issue Type +	Ma	Location *	LS

Photo 2 of 2 : SP_2019_RD0755_177_20_20190311_00009.jpg



RD 755 looking downstream from levee mile 0.17-0.59.

*** Location**
LS : Land Side N/A : Not Applicable
WS : Water Side
CR : Crown

**** Rating**
A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type
Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2019

Reclamation District No. 0755 Randall

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	1.83	03/15/2019 03/15/2019	David Julian

LM Start	0.17	Rating **	M	Issue No.	19
LM End	1.84	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.346757 °	38.336409 °
				-121.538675 °	-121.564813 °
DWR ID	DWR_RD0755_01_f_2016_19				
Comment Code					
V2 : Remove the wild growth other than native grasses from the levee slopes.					
Inspector Comment					
The tall weeds on the waterside slope should be removed/managed to allow inspection. Large cactus (Century Plants) at LM 1.07 should also be removed.					

Photo 1 of 2 : SP_2019_RD0755_177_19_20190311_00006.jpg



View looking upstream at vegetation on the waterside slope (October 2018)

LM Start	0.17	Rating **	M	Issue No.	19 (cont)
LM End	1.84	Issue Type +	Ma	Location *	WS

Photo 2 of 2 : SP_2019_RD0755_177_19_20190311_00007.jpg



RD 755 Levee mile 0.17-1.12 waterside looking downstream.

LM Start	0.21	Rating **	M	Issue No.	10
LM End	0.21	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Slope Stability			38.346428 °	38.346428 °
				-121.539400 °	-121.539400 °
DWR ID	DWR_RD0755_01_s_2019_10				
Comment Code					
S1 : Repair slope instability.					
Inspector Comment					
There is a 2" seperation between roadway and levee on the landside shoulder.					

Photo 1 of 1 : SP_2019_RD0755_177_10_20190320_00049.jpg



View looking upstream at small slip on the landside shoulder (Spring 2019).

* Location		** Rating		+ Issue Type	
LS : Land Side	N/A : Not Applicable	A : Acceptable	N : Not Inspected/Rated	Ma : Maintenance Deficiency	
WS : Water Side		M : Minimally Acceptable	C : Corrected	Ob : Design & System Obsolescence	
CR : Crown		U : Unacceptable	A/W : Acceptable but Monitor & Maintain	En : Enforcement	

Reclamation District No. 0755 Randall

No Photos

A photograph showing a shoreline with a grassy bank on the left, a pile of rocks and bare branches in the foreground, and a body of water extending to a distant treeline under a clear blue sky.Page 4 of 27

Reclamation District No. 0755 Randall

A photograph showing a shoreline with a rocky beach in the foreground. A large, light-colored piece of driftwood lies horizontally across the rocks. To the left is a body of water, and to the right is a grassy bank with some small plants. The background shows a line of trees under a clear sky.

* Location	** Rating	+ Issue Type
LS : Land Side N/A : Not Applicable	A : Acceptable N : Not Inspected/Rated	Ma : Maintenance Deficiency
WS : Water Side	M : Minimally Acceptable C : Corrected	Ob : Design & System Obsolescence
CR : Crown	U : Unacceptable AWW : Acceptable but Monitor & Maintain	En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2019

Reclamation District No. 0755 Randall

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	1.83	03/15/2019 03/15/2019	David Julian

LM Start	0.43	Rating **	M	Issue No.	4
LM End	1.77	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			38.345593 °	38.337197 °
				-121.543263 °	-121.564147 °
DWR ID	DWR_RD0755_01_f_2014_4				
Comment Code					
A1 : Exterminate rodents and backfill and compact or grout burrows.					
Inspector Comment					
Evidence of active rodents on landside slope near the walnut trees. No bait stations were observed.					

No Photos

LM Start	0.43	Rating **	M	Issue No.	35	
LM End	0.43	Issue Type +	En	Location *		
Category	Supplemental			GPS Latitude/Longitude		
				Start	End	
Item	DWR UCIP Field Study			38.345640 °	38.345640 °	
				-121.543277 °	-121.543277 °	
DWR ID	18849					
Comment Code						
Inspector Comment						
FS_ID:17123 DS_ID:18849 EP_NO: 4302 Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: FBC about 2 feet.Power conduit also through the levee.Wet ground on pump site/location. May need investigation about wet ground. FIELD_STRUCT_DESC: 8-inch coated steel irrigation discharge pipe through the levee, 2 feet below the crown. Pump, electrical box, and control valve on the waterside (WS) slope. Siphon breaker on the landside (LS) slope. Service pole at the LS toe. (Plans for placing an 8-inch irrigation pipe and pump authorized under Permit No. 4302, 1963 - E. C. Hemly). [Additional Reference(s): DWR Levee Log, 2005, referenced as 4 feet below the crown]. FS Date: 8/6/2013						

Photo 1 of 3 : UCIP_SP_2019_17123_29242.jpg



WS view: overview of pump and pipe.

* Location		** Rating		+ Issue Type	
LS : Land Side	N/A : Not Applicable	A : Acceptable	N : Not Inspected/Rated	Ma : Maintenance Deficiency	
WS : Water Side		M : Minimally Acceptable	C : Corrected	Ob : Design & System Obsolescence	
CR : Crown		U : Unacceptable	A/W : Acceptable but Monitor & Maintain	En : Enforcement	

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2019

Reclamation District No. 0755 Randall

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	1.83	03/15/2019 03/15/2019	David Julian

LM Start	0.43	Rating **	M	Issue No.	35 (cont)	
LM End	0.43	Issue Type +	En	Location *		
Category	Supplemental			GPS Latitude/Longitude		
				Start		End
Item	DWR UCIP Field Study			38.345640 °		38.345640 °
				-121.543277 °		-121.543277 °
DWR ID	18849					
Comment Code						
Inspector Comment						
FS_ID:17123 DS_ID:18849 EP_NO: 4302 Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: FBC about 2 feet.Power conduit also through the levee.Wet ground on pump site/location. May need investigation about wet ground. FIELD_STRUCT_DESC: 8-inch coated steel irrigation discharge pipe through the levee, 2 feet below the crown. Pump, electrical box, and control valve on the waterside (WS) slope. Siphon breaker on the landside (LS) slope. Service pole at the LS toe. (Plans for placing an 8-inch irrigation pipe and pump authorized under Permit No. 4302, 1963 - E. C. Hemly). [Additional Reference(s): DWR Levee Log, 2005, referenced as 4 feet below the crown]. FS Date: 8/6/2013						

Photo 2 of 3 : UCIP_SP_2019_17123_29241.jpg



WS view: steel pipe and power conduit.

LM Start	0.43	Rating **	M	Issue No.	35 (cont)
LM End	0.43	Issue Type +	En	Location *	

Photo 3 of 3 : UCIP_SP_2019_17123_29240.jpg



WS view: pump, power switch box, butterfly valve and pipe.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
----------------------------------------------------------------------------------------------	--	---------------------------------------------------------------------------------------------------------------------------------------------------------------------------	--	-------------------------------------------------------------------------------------------------------------

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2019

Reclamation District No. 0755 Randall

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	1.83	03/15/2019 03/15/2019	David Julian

LM Start	0.50	Rating **	M	Issue No.	17
LM End	0.53	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			38.345652 °	38.345618 °
				-121.544482 °	-121.545122 °
DWR ID	DWR_RD0755_01_f_2018_17				
Comment Code					
T1 : Trim trees to at least five feet above ground level.					
Inspector Comment					

No Photos

LM Start	0.68	Rating **	M	Issue No.	36
LM End	0.68	Issue Type +	En	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			38.345113 °	38.345113 °
				-121.547789 °	-121.547789 °
DWR ID	18851				
Comment Code					
Inspector Comment					
FS_ID:41634 DS_ID:18851 EP_NO: 7357 Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: An abandoned 12-in steel pipe lying on LS levee slope should be removed.A buried concrete headwall found on LS levee slope should be checked for any pipe or connection. FIELD_STRUCT_DESC: 2 of 2: 8-inch pipe sleeved through a 16-inch irrigation discharge pipe of an unknown material through the levee, 4.2 feet below the crown. Pump on the waterside (WS). (Plans to install an additional pump on an existing stand and to connect the discharge pipe to the existing pipe through the levee authorized under Permit No. 7357, 1971 - Green and Keown Farms, Inc). [Additional Reference(s): DWR Levee Log, 2005, 14-inch outer pipe referenced]. FS Date: 8/6/2013					

Photo 1 of 3 : UCIP_SP_2019_41634_29087.jpg



WS view: pump structure on the stream, conduit, pipes, and walkway.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
----------------------------------------------------------------------------------------------	--	---------------------------------------------------------------------------------------------------------------------------------------------------------------------------	--	-------------------------------------------------------------------------------------------------------------

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2019

Reclamation District No. 0755 Randall

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	1.83	03/15/2019 03/15/2019	David Julian

LM Start	0.68	Rating **	M	Issue No.	36 (cont)	
LM End	0.68	Issue Type +	En	Location *		
Category	Supplemental			GPS Latitude/Longitude		
				Start	End	
Item	DWR UCIP Field Study			38.345113	°	38.345113
				-121.547789	°	-121.547789
DWR ID	18851					
Comment Code						
Inspector Comment						
FS_ID:41634 DS_ID:18851 EP_NO: 7357 Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: An abandoned 12-in steel pipe lying on LS levee slope should be removed.A buried concrete headwall found on LS levee slope should be checked for any pipe or connection. FIELD_STRUCT_DESC: 2 of 2: 8-inch pipe sleeved through a 16-inch irrigation discharge pipe of an unknown material through the levee, 4.2 feet below the crown. Pump on the waterside (WS). (Plans to install an additional pump on an existing stand and to connect the discharge pipe to the existing pipe through the levee authorized under Permit No. 7357, 1971 - Green and Keown Farms, Inc). [Additional Reference(s): DWR Levee Log, 2005, 14-inch outer pipe referenced]. FS Date: 8/6/2013						

LM Start	0.68	Rating **	M	Issue No.	36 (cont)
LM End	0.68	Issue Type +	En	Location *	

Photo 2 of 3 : UCIP_SP_2019_41634_29086.jpg



WS view: view towards levee crown from pump structure.

Photo 3 of 3 : UCIP_SP_2019_41634_29085.jpg



WS view: pump mounted on pump station/deck.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
----------------------------------------------------------------------------------------------	--	---------------------------------------------------------------------------------------------------------------------------------------------------------------------------	--	-------------------------------------------------------------------------------------------------------------

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2019

Reclamation District No. 0755 Randall

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	1.83	03/15/2019 03/15/2019	David Julian

LM Start	0.69	Rating **	M	Issue No.	26
LM End	0.69	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			38.345103 °	38.345103 °
				-121.547918 °	-121.547918 °
DWR ID	DWR_RD0755_01_f_2018_26				
Comment Code					
T1 : Trim trees to at least five feet above ground level.					
Inspector Comment					

No Photos

LM Start	0.69	Rating **	M	Issue No.	27
LM End	0.69	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			38.345070 °	38.345070 °
				-121.547985 °	-121.547985 °
DWR ID	DWR_RD0755_01_f_2018_27				
Comment Code					
GA : Garbage					
Inspector Comment					
Remove chair from the landside shoulder.					

Photo 1 of 1 : SP_2019_RD0755_177_27_20190311_00017.jpg



Chair on the waterside (October 2018).

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable N : Not Inspected/Rated M : Minimally Acceptable C : Corrected U : Unacceptable A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
----------------------------------------------------------------------------------------------	--	---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------	--	-------------------------------------------------------------------------------------------------------------

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2019

Reclamation District No. 0755 Randall

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	1.83	03/15/2019 03/15/2019	David Julian

LM Start	0.70	Rating **	A/W	Issue No.	37
LM End	0.70	Issue Type +	Ma	Location *	
Category	Supplemental		GPS Latitude/Longitude		
			Start	End	
Item	DWR UCIP LMA Responsibility		38.345057 °	38.345057 °	
			-121.548050 °	-121.548050 °	
DWR ID	18852				

Comment Code

Inspector Comment

FS_ID:17145
DS_ID:18852
EP_NO: 11222
Repair Type: No Action Needed
Crossing Status: Found
UCIP Comments: It was working during field survey. A pump found 150 ft from the levee. Not sure whether the pump belong to this drainage system.
FIELD_STRUCT_DESC: *ABANDONED* 16-inch steel drainage pipe sleeved through a 24-inch steel drainage pipe through the levee, invert elevation 8 feet below the crown. (Retention of a 12-inch drainage pipe sleeved through a 24-inch pipe through the levee, 8 feet below the crown, authorized under Automatic Board Order (ABO) issued as Permit No. 11222, 1975 - Green McKeown, Inc). [Additional Reference(s): DWR Levee Log, 2005, 12-inch inner pipe referenced. USACE Sacramento O&M Manual 111, May 1959, (RM 35.89)].
FS Date: 8/6/2013

LM Start	0.70	Rating **	A/W	Issue No.	37 (cont)
LM End	0.70	Issue Type +	Ma	Location *	

Photo 1 of 3 : UCIP_SP_2019_17145_29292.jpg



WS view: pipe and siphon breaker on levee slope

Photo 2 of 3 : UCIP_SP_2019_17145_29293.jpg



WS view: 16-inch pipe sleeved through 24-inch pipe.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
----------------------------------------------------------------------------------------------	--	---------------------------------------------------------------------------------------------------------------------------------------------------------------------------	--	-------------------------------------------------------------------------------------------------------------

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2019

Reclamation District No. 0755 Randall

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	1.83	03/15/2019 03/15/2019	David Julian

LM Start	0.70	Rating **	A/W	Issue No.	37 (cont)	
LM End	0.70	Issue Type +	Ma	Location *		
Category	Supplemental			GPS Latitude/Longitude		
				Start	End	
Item	DWR UCIP LMA Responsibility			38.345057 °	38.345057 °	
				-121.548050 °	-121.548050 °	
DWR ID	18852					
Comment Code						
Inspector Comment						
FS_ID:17145 DS_ID:18852 EP_NO: 11222 Repair Type: No Action Needed Crossing Status: Found UCIP Comments: It was working during field survey. A pump found 150 ft from the levee. Not sure whether the pump belong to this drainage system. FIELD_STRUCT_DESC: *ABANDONED* 16-inch steel drainage pipe sleeved through a 24-inch steel drainage pipe through the levee, invert elevation 8 feet below the crown. (Retention of a 12-inch drainage pipe sleeved through a 24-inch pipe through the levee, 8 feet below the crown, authorized under Automatic Board Order (ABO) issued as Permit No. 11222, 1975 - Green McKeown, Inc). [Additional Reference(s): DWR Levee Log, 2005, 12-inch inner pipe referenced. USACE Sacramento O&M Manual 111, May 1959, (RM 35.89)]. FS Date: 8/6/2013						

Photo 3 of 3 : UCIP_SP_2019_17145_29295.jpg



WS view: 16-inch drainage pipe on levee slope.

LM Start	0.70	Rating **	M	Issue No.	38	
LM End	0.70	Issue Type +	En	Location *		
Category	Supplemental			GPS Latitude/Longitude		
				Start	End	
Item	DWR UCIP Field Study			38.345036 °	38.345036 °	
				-121.548141 °	-121.548141 °	
DWR ID	18854					
Comment Code						
Inspector Comment						
FS_ID:17049						
DS_ID:18854						
EP_NO: 1716						
Repair Type: Non-Urgent						
Crossing Status: Found						
UCIP Comments: Not found- a 4-inch pipe on waterward shoulder but a 2-inch GI pipe found on landside slope.						
FIELD_STRUCT_DESC: *ABANDONED* 18-inch drainage pipe of an unknown material through the levee, invert elevation 4.5 feet below the crown. (Plans for the replacement of an existing pipe through the levee authorized under Permit No. 1716, 1952 - Reclamation District No. 755 [RD0755]). [Additional Reference(s): DWR Levee Log, 2005. USACE Sacramento O&M Manual 111, May 1959, (RM 35.88)].						
FS Date: 8/6/2013						

Photo 1 of 3 : UCIP_SP_2019_17049_29119.jpg



LS view: concrete headwall and 2-inch conduit (left)

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable N : Not Inspected/Rated M : Minimally Acceptable C : Corrected U : Unacceptable A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
----------------------------------------------------------------------------------------------	--	---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------	--	-------------------------------------------------------------------------------------------------------------

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2019

Reclamation District No. 0755 Randall

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	1.83	03/15/2019 03/15/2019	David Julian

LM Start	0.70	Rating **	M	Issue No.	38 (cont)	
LM End	0.70	Issue Type +	En	Location *		
Category	Supplemental			GPS Latitude/Longitude		
				Start	End	
Item	DWR UCIP Field Study			38.345036 °	38.345036 °	
				-121.548141 °	-121.548141 °	
DWR ID	18854					
Comment Code						
Inspector Comment						
FS_ID:17049						
DS_ID:18854						
EP_NO: 1716						
Repair Type: Non-Urgent						
Crossing Status: Found						
UCIP Comments: Not found- a 4-inch pipe on waterward shoulder but a 2-inch GI pipe found on landside slope.						
FIELD_STRUCT_DESC: *ABANDONED* 18-inch drainage pipe of an unknown material through the levee, invert elevation 4.5 feet below the crown. (Plans for the replacement of an existing pipe through the levee authorized under Permit No. 1716, 1952 - Reclamation District No. 755 [RD0755]). [Additional Reference(s): DWR Levee Log, 2005. USACE Sacramento O&M Manual 111, May 1959, (RM 35.88)].						
FS Date: 8/6/2013						

LM Start	0.70	Rating **	M	Issue No.	38 (cont)
LM End	0.70	Issue Type +	En	Location *	

Photo 2 of 3 : UCIP_SP_2019_17049_29121.jpg



LS view: 18-inch abandoned pipe on levee slope

Photo 3 of 3 : UCIP_SP_2019_17049_29122.jpg



LS view: exposed/daylight 18-inch abandoned pipe on levee slope

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
----------------------------------------------------------------------------------------------	------------------------------------------------------------------------------------	-------------------------------------------------------------------------------------	-------------------------------------------------------------------------------------------------------------

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2019

Reclamation District No. 0755 Randall

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	1.83	03/15/2019 03/15/2019	David Julian

LM Start	0.93	Rating **	M	Issue No.	39
LM End	0.93	Issue Type +	En	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			38.344103 °	38.344103 °
				-121.552119 °	-121.552119 °
DWR ID	18855				
Comment Code					
Inspector Comment					
FS_ID:17063 DS_ID:18855 EP_NO: 11225 Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: Abandoned pipe and pump.Service pole, power box lying on LS slope. FIELD_STRUCT_DESC: *ABANDONED* 10-inch irrigation discharge pipe of an unknown material and a 1-inch electrical conduit through the levee, invert elevation 5.6 feet below the crown. Pump on a pile structure with a walkway to the pump. Abandoned service pole on the landside (LS) slope. (Retention of a 10-inch pipe through the levee, 5.6 feet below the crown, pump on a pile structure with a walkway to the pump, and a service pole on the LS slope Automatic Board Order (ABO) issued as Permit No. 11225, 1975 - Helen D. Wilson). [Additional Reference(s): DWR Levee Log, 2005. USACE Sacramento O&M Manual 111, May 1959, (RM 35.66)]. FS Date: 8/6/2013					

LM Start	0.93	Rating **	M	Issue No.	39 (cont)
LM End	0.93	Issue Type +	En	Location *	

Photo 1 of 3 : UCIP_SP_2019_17063_29148.jpg



WS view: overview of pipe and pump structure.

Photo 2 of 3 : UCIP_SP_2019_17063_29147.jpg



WS view: an abandoned pump

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable		N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement	
----------------------------------------------------------------------------------------------	--	------------------------------------------------------------------------------------	--	-------------------------------------------------------------------------------------	--	-------------------------------------------------------------------------------------------------------------	--

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2019

Reclamation District No. 0755 Randall

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	1.83	03/15/2019 03/15/2019	David Julian

LM Start	0.93	Rating **	M	Issue No.	39 (cont)
LM End	0.93	Issue Type +	En	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			38.344103 °	38.344103 °
				-121.552119 °	-121.552119 °
DWR ID	18855				
Comment Code					
Inspector Comment					
FS_ID:17063 DS_ID:18855 EP_NO: 11225 Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: Abandoned pipe and pump.Service pole, power box lying on LS slope. FIELD_STRUCT_DESC: *ABANDONED* 10-inch irrigation discharge pipe of an unknown material and a 1-inch electrical conduit through the levee, invert elevation 5.6 feet below the crown. Pump on a pile structure with a walkway to the pump. Abandoned service pole on the landside (LS) slope. (Retention of a 10-inch pipe through the levee, 5.6 feet below the crown, pump on a pile structure with a walkway to the pump, and a service pole on the LS slope Automatic Board Order (ABO) issued as Permit No. 11225, 1975 - Helen D. Wilson). [Additional Reference(s): DWR Levee Log, 2005. USACE Sacramento O&M Manual 111, May 1959, (RM 35.66)]. FS Date: 8/6/2013					

Photo 3 of 3 : UCIP_SP_2019_17063_29146.jpg



WS view: abandoned and discontinued vertical intake pipe

LM Start	0.99	Rating **	M	Issue No.	29
LM End	0.99	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			38.343835 °	38.343835 °
				-121.553162 °	-121.553162 °
DWR ID	DWR_RD0755_01_f_2018_29				
Comment Code					
T1 : Trim trees to at least five feet above ground level.					
Inspector Comment					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable		N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement	
----------------------------------------------------------------------------------------------	--	------------------------------------------------------------------------------------	--	-------------------------------------------------------------------------------------	--	-------------------------------------------------------------------------------------------------------------	--

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2019

Reclamation District No. 0755 Randall

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	1.83	03/15/2019 03/15/2019	David Julian

LM Start	1.04	Rating **	M	Issue No.	40	
LM End	1.04	Issue Type +	En	Location *		
Category	Supplemental			GPS Latitude/Longitude		
				Start	End	
Item	DWR UCIP Field Study			38.343625 °	38.343625 °	
				-121.554145 °	-121.554145 °	
DWR ID	18856					
Comment Code						
Inspector Comment						
FS_ID:46764						
DS_ID:18856						
EP_NO: N/A						
Repair Type: Non-Urgent						
Crossing Status: Found						
UCIP Comments: Needs to be properly abandoned.						
FIELD_STRUCT_DESC: *ABANDONED* 12-inch pipe of an unknown material or purpose through the levee, invert elevation 5 feet below the crown. Siphon breaker on the waterside (WS). Pipe not found on the landside (LS). (Wilson). [Additional Reference(s): DWR Levee Log, 2005. USACE Sacramento O&M Manual 111, May 1959, (RM 35.55)].						
FS Date: 8/6/2013						

Photo 1 of 3 : UCIP_SP_2019_46764_29158.jpg



WS view: overview of steel pipe with siphon breaker on levee slope

LM Start	1.04	Rating **	M	Issue No.	40 (cont)
LM End	1.04	Issue Type +	En	Location *	

Photo 2 of 3 : UCIP_SP_2019_46764_29157.jpg



WS view: steel pipe with siphon breaker on levee slope

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
----------------------------------------------------------------------------------------------	---------------------------------------------------------------------------------------------------------------------------------------------------------------------------	-------------------------------------------------------------------------------------------------------------

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2019

Reclamation District No. 0755 Randall

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	1.83	03/15/2019 03/15/2019	David Julian

LM Start	1.04	Rating **	M	Issue No.	40 (cont)	
LM End	1.04	Issue Type +	En	Location *		
Category	Supplemental			GPS Latitude/Longitude		
				Start	End	
Item	DWR UCIP Field Study			38.343625 °	38.343625 °	
				-121.554145 °	-121.554145 °	
DWR ID	18856					
Comment Code						
Inspector Comment						
FS_ID:46764						
DS_ID:18856						
EP_NO: N/A						
Repair Type: Non-Urgent						
Crossing Status: Found						
UCIP Comments: Needs to be properly abandoned.						
FIELD_STRUCT_DESC: *ABANDONED* 12-inch pipe of an unknown material or purpose through the levee, invert elevation 5 feet below the crown. Siphon breaker on the waterside (WS). Pipe not found on the landside (LS). (Wilson). [Additional Reference(s): DWR Levee Log, 2005. USACE Sacramento O&M Manual 111, May 1959, (RM 35.55)].						
FS Date: 8/6/2013						

Photo 3 of 3 : UCIP_SP_2019_46764_29159.jpg



LS view: no pipe and pump found on LS.

LM Start	1.05	Rating **	M	Issue No.	23
LM End	1.08	Issue Type +	En	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.343595 °	38.343487 °
				-121.554238 °	-121.554768 °
DWR ID	DWR_RD0755_01_s_2017_23				
Comment Code					
V6 : Landscaping					
Inspector Comment					
Ground vegetation, shrubs and trees should be maintained to allow inspection and access to landside slope and toe.					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
----------------------------------------------------------------------------------------------	------------------------------------------------------------------------------------	-------------------------------------------------------------------------------------	-------------------------------------------------------------------------------------------------------------

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2019

Reclamation District No. 0755 Randall

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	1.83	03/15/2019 03/15/2019	David Julian

LM Start	1.06	Rating **	M	Issue No.	31
LM End	1.06	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			38.343542 °	38.343542 °
				-121.554487 °	-121.554487 °
DWR ID	DWR_RD0755_01_s_2019_31				
Comment Code					
T1 : Trim trees to at least five feet above ground level.					
Inspector Comment					
Trees are blocking visibility down waterside slope.					

Photo 1 of 1 : SP_2019_RD0755_177_31_20190320_00048.jpg



View of tree at the top of the waterside shoulder (Spring 2019).

LM Start	1.06	Rating **	M	Issue No.	12
LM End	1.06	Issue Type +	En	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.343543 °	38.343543 °
				-121.554523 °	-121.554523 °
DWR ID	DWR_RD0755_01_s_2018_12				
Comment Code					
V6 : Landscaping					
Inspector Comment					
Remove cactus on waterside slope.					

Photo 1 of 1 : SP_2019_RD0755_177_12_20190320_00047.jpg



View of cactus at the top of the waterside slope (Spring 2019).

LM Start	1.10	Rating **	M	Issue No.	30
LM End	1.10	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			38.343373 °	38.343373 °
				-121.555188 °	-121.555188 °
DWR ID	DWR_RD0755_01_f_2018_30				
Comment Code					
T1 : Trim trees to at least five feet above ground level.					
Inspector Comment					

No Photos

* Location		** Rating		+ Issue Type	
LS : Land Side	N/A : Not Applicable	A : Acceptable	N : Not Inspected/Rated	Ma : Maintenance Deficiency	
WS : Water Side		M : Minimally Acceptable	C : Corrected	Ob : Design & System Obsolescence	
CR : Crown		U : Unacceptable	A/W : Acceptable but Monitor & Maintain	En : Enforcement	

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2019

Reclamation District No. 0755 Randall

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	1.83	03/15/2019 03/15/2019	David Julian

LM Start	1.12	Rating **	M	Issue No.	28
LM End	1.42	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.343300 °	38.341237 °
				-121.555507 °	-121.560113 °
DWR ID	DWR_RD0755_01_s_2017_28				
Comment Code					
V1 : Control annual grass and weeds on the levee slopes and easements.					
Inspector Comment					
Remove vegetation from the landside slope.					

Photo 1 of 1 : SP_2019_RD0755_177_28_20190311_00018.jpg



View looking upstream at vegetation on the landside slope (October 2018).

LM Start	1.12	Rating **	M	Issue No.	41
LM End	1.12	Issue Type +	En	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			38.343305 °	38.343305 °
				-121.555538 °	-121.555538 °
DWR ID	18857				
Comment Code					
Inspector Comment					
FS_ID:17144 DS_ID:18857 EP_NO: 11219 Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: - requires cleaning of siphon breaker box. FIELD_STRUCT_DESC: 8-inch irrigation discharge pipe of an unknown material through the levee, invert elevation 5.7 feet below the crown. Siphon breaker in a corrugated metal pipe (CMP) riser on the landside (LS) shoulder. Power pole on the LS. Pump and power box in a pump house on the waterside (WS) slope. Electrical conduit through the levee at the same location. (Retention of an 8-inch pipe through the levee, 5.7 feet below the crown, and a pump in a pump house on the WS slope authorized under Automatic Board Order (ABO) issued as Permit No. 11219, 1975 - David J. Jr and Bonnie Elliott). [Additional Reference(s): DWR Levee Log, 2005. USACE Sacramento O&M Manual 111, May 1959, (RM 35.47)]. FS Date: 8/6/2013					

Photo 1 of 3 : UCIP_SP_2019_17144_29288.jpg



WS view: pump house on levee slope.

* Location	** Rating	+ Issue Type
LS : Land Side WS : Water Side CR : Crown	A : Acceptable M : Minimally Acceptable U : Unacceptable	Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2019

Reclamation District No. 0755 Randall

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	1.83	03/15/2019 03/15/2019	David Julian

LM Start	1.12	Rating **	M	Issue No.	41 (cont)	
LM End	1.12	Issue Type +	En	Location *		
Category	Supplemental			GPS Latitude/Longitude		
				Start	End	
Item	DWR UCIP Field Study			38.343305°	38.343305°	
				-121.555538°	-121.555538°	
DWR ID	18857					
Comment Code						
Inspector Comment						
FS_ID:17144 DS_ID:18857 EP_NO: 11219 Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: - requires cleaning of siphon breaker box. FIELD_STRUCT_DESC: 8-inch irrigation discharge pipe of an unknown material through the levee, invert elevation 5.7 feet below the crown. Siphon breaker in a corrugated metal pipe (CMP) riser on the landside (LS) shoulder. Power pole on the LS. Pump and power box in a pump house on the waterside (WS) slope. Electrical conduit through the levee at the same location. (Retention of an 8-inch pipe through the levee, 5.7 feet below the crown, and a pump in a pump house on the WS slope authorized under Automatic Board Order (ABO) issued as Permit No. 11219, 1975 - David J. Jr and Bonnie Elliott). [Additional Reference(s): DWR Levee Log, 2005. USACE Sacramento O&M Manual 111, May 1959, (RM 35.47)]. FS Date: 8/6/2013						

LM Start	1.12	Rating **	M	Issue No.	41 (cont)
LM End	1.12	Issue Type +	En	Location *	

Photo 2 of 3 : UCIP_SP_2019_17144_29287.jpg



WS view: pipe daylight from pump house.

Photo 3 of 3 : UCIP_SP_2019_17144_29286.jpg



WS view: pumps, butterfly valve and pipe inside pump house.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable		N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement	
----------------------------------------------------------------------------------------------	--	------------------------------------------------------------------------------------	--	-------------------------------------------------------------------------------------	--	-------------------------------------------------------------------------------------------------------------	--

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2019

Reclamation District No. 0755 Randall

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	1.83	03/15/2019 03/15/2019	David Julian

LM Start	1.23	Rating **	A/W	Issue No.	22 (cont)
LM End	1.29	Issue Type +	Ma	Location *	WS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	2017 Storm Damage			38.342992 °	38.342633 °
				-121.557572 °	-121.558622 °
DWR ID	DWR_RD0755_01_f_2017_22				
Comment Code					
Inspector Comment					
Levee Evaluation Comments					
Description:The damage consists of erosion of the lower waterside levee slope and bank approximately 322 feet in length along the east (left) bank of the Sacramento River. See attached pages for photos.					
Site location T06N R04E Section 29.					
Site ID No:328					
Site Designation:LMA-155					
Repair Type: Erosion					
Rating:Area of Concern					
Field Date:7/13/2017					
Notes: Could not access most of the lower portion of the slope because of vegetation, but there was rip rap just downstream of the site. Looked like it may have been missing on part of the site. Erosion looked like it may be 1/2 the length reported. Crown is a paved road					

Photo 3 of 3 : SP_2019_RD0755_177_22_20190311_00012.jpg



LM Start	1.30	Rating **	M	Issue No.	32
LM End	1.43	Issue Type +	En	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			38.342412 °	38.341108 °
				-121.558688 °	-121.560220 °
DWR ID	DWR_RD0755_01_s_2019_32				
Comment Code					
CR : Crops					
Inspector Comment					
Orchard trees are on landside slope.					

Photo 1 of 1 : SP_2019_RD0755_177_32_20190320_00044.jpg



View looking upstream at orchard trees on the base of the landside slope (Spring 2019).

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable N : Not Inspected/Rated M : Minimally Acceptable C : Corrected U : Unacceptable A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
----------------------------------------------------------------------------------------------	--	---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------	--	-------------------------------------------------------------------------------------------------------------

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2019

Reclamation District No. 0755 Randall

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	1.83	03/15/2019 03/15/2019	David Julian

LM Start	1.42	Rating **	M	Issue No.	34
LM End	1.42	Issue Type +	Ma	Location *	CR
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			38.341205 °	38.341205 °
				-121.560122 °	-121.560122 °
DWR ID	DWR_RD0755_01_s_2019_34				
Comment Code					
A1 : Exterminate rodents and backfill and compact or grout burrows.					
Inspector Comment					
Multiple rodent holes are on the crown, including one that was 2' deep.					

Photo 1 of 2 : SP_2019_RD0755_177_34_20190320_00045.jpg



View of 2 foot deep rodent hole on the landside of the crown (Spring 2019).

LM Start	1.42	Rating **	M	Issue No.	34 (cont)
LM End	1.42	Issue Type +	Ma	Location *	CR

Photo 2 of 2 : SP_2019_RD0755_177_34_20190320_00046.jpg



Measuring tape showing rodent hole as being 2 feet deep on the landside of the crown (Spring 2019).

LM Start	1.58	Rating **	M	Issue No.	33
LM End	1.72	Issue Type +	En	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			38.339360 °	38.337767 °
				-121.561855 °	-121.563602 °
DWR ID	DWR_RD0755_01_s_2019_33				
Comment Code					
CR : Crops					
Inspector Comment					
Trees are on the landside slope.					

Photo 1 of 1 : SP_2019_RD0755_177_33_20190320_00043.jpg



View looking upstream at orchard trees at the landside toe (Spring 2019).

*** Location**

LS : Land Side N/A : Not Applicable
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable N : Not Inspected/Rated
M : Minimally Acceptable C : Corrected
U : Unacceptable A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2019

Reclamation District No. 0755 Randall

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	1.83	03/15/2019 03/15/2019	David Julian

LM Start	1.59	Rating **	M	Issue No.	13
LM End	1.73	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.339210 °	38.337755 °
				-121.562058 °	-121.563666 °
DWR ID	DWR_RD0755_01_f _ 2018_13				
Comment Code					
V2 : Remove the wild growth other than native grasses from the levee slopes.					
Inspector Comment					

Photo 1 of 1 : SP_2019_RD0755_177_13_20190311_00002.jpg



Vegetation on landside should be maintained to allow inspection and access to slope and toe.

LM Start	1.64	Rating **	M	Issue No.	42
LM End	1.64	Issue Type +	En	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			38.338715 °	38.338715 °
				-121.562560 °	-121.562560 °
DWR ID	18858				
Comment Code					
Inspector Comment					
FS_ID:17143 DS_ID:18858 EP_NO: 11219 Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: - Pump and walkway seem abandoned.- Power line is not connected with pump.- A pump house like structure found on LS levee toe. FIELD_STRUCT_DESC: 16-inch irrigation discharge pipe of an unknown material through the levee, invert elevation 8.5 feet below the crown. Pump on a pile structure in the river. Walkway to the pump. Siphon breaker and power pole on the landside (LS) slope. Electrical conduit through the levee at the same location. (Retention of a 14-inch pipe through the levee, 8.5 feet below the crown, a pump on a pile structure in the river, a walkway to the pump, and a siphon breaker on the LS slope authorized under Automatic Board Order (ABO) issued as Permit No. 11219, 1975 - David J. Jr and Bonnie Elliott). [Additional Reference(s): DWR Levee Log, 2005, 14-inch pipe referenced. USACE Sacramento O&M Manual 111, May 1959, (RM 35.02), 14-inch pipe referenced, incorrectly referenced in Reclamation District No. 551 (RD0551)]. FS Date: 8/6/2013					

Photo 1 of 3 : UCIP_SP_2019_17143_29282.jpg



WS view: Overview of walkway, pump structure, and pipe.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable N : Not Inspected/Rated M : Minimally Acceptable C : Corrected U : Unacceptable A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
----------------------------------------------------------------------------------------------	--	---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------	--	-------------------------------------------------------------------------------------------------------------

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2019

Reclamation District No. 0755 Randall

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	1.83	03/15/2019 03/15/2019	David Julian

LM Start	1.64	Rating **	M	Issue No.	42 (cont)	
LM End	1.64	Issue Type +	En	Location *		
Category	Supplemental			GPS Latitude/Longitude		
				Start	End	
Item	DWR UCIP Field Study			38.338715 °	38.338715 °	
				-121.562560 °	-121.562560 °	
DWR ID	18858					
Comment Code						
Inspector Comment						
FS_ID:17143 DS_ID:18858 EP_NO: 11219 Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: - Pump and walkway seem abandoned.- Power line is not connected with pump.- A pump house like structure found on LS levee toe. FIELD_STRUCT_DESC: 16-inch irrigation discharge pipe of an unknown material through the levee, invert elevation 8.5 feet below the crown. Pump on a pile structure in the river. Walkway to the pump. Siphon breaker and power pole on the landside (LS) slope. Electrical conduit through the levee at the same location. (Retention of a 14-inch pipe through the levee, 8.5 feet below the crown, a pump on a pile structure in the river, a walkway to the pump, and a siphon breaker on the LS slope authorized under Automatic Board Order (ABO) issued as Permit No. 11219, 1975 - David J. Jr and Bonnie Elliott). [Additional Reference(s): DWR Levee Log, 2005, 14-inch pipe referenced. USACE Sacramento O&M Manual 111, May 1959, (RM 35.02), 14-inch pipe referenced, incorrectly referenced in Reclamation District No. 551 (RD0551)]. FS Date: 8/6/2013						

LM Start	1.64	Rating **	M	Issue No.	42 (cont)
LM End	1.64	Issue Type +	En	Location *	

Photo 2 of 3 : UCIP_SP_2019_17143_29281.jpg



WS view: Abandoned walkway and pump structure

Photo 3 of 3 : UCIP_SP_2019_17143_29280.jpg



WS view: Pipe and butterfly/gate valve on levee slope.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
----------------------------------------------------------------------------------------------	--	---------------------------------------------------------------------------------------------------------------------------------------------------------------------------	--	-------------------------------------------------------------------------------------------------------------

Reclamation District No. 0755 Randall

Landscaping on landside should be maintained to allow inspection and access to levee slope and toe.

A photograph showing a rocky shoreline with sparse, dry vegetation. In the foreground, there are several green, fern-like plants and some dry, brownish grasses. The ground is covered with small, light-colored rocks and pebbles. In the background, a body of water is visible, with a dark, silty or muddy appearance. The water's surface is slightly rippled. The overall scene suggests a coastal or estuarine environment.Page 26 of 27

