

**Flood Control Project Maintenance  
Levee Inspections**

**Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2014**

**Reclamation District No. 0755 Randall**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	1.83	10/29/2014 10/29/2014	Herman Phillips

LM Start		Rating **	M	Issue No.	<b>14</b>
LM End		Issue Type +	Ma	Location *	LS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Flood Preparedness & Training			°	°
DWR ID	DWR_RD0755_01_f_2014_14				
Action/Comments					
Inspector Comments: This district has a knowledge of how to conduct a flood fight but has not taken the class recently.					

No Photos

LM Start		Rating **	M	Issue No.	<b>15</b>
LM End		Issue Type +	Ma	Location *	LS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Emergency Supplies & Equipment			°	°
DWR ID	DWR_RD0755_01_f_2014_15				
Action/Comments					
Inspector Comments: The emergency supplies was not observed during the inspection.					

No Photos

LM Start		Rating **	M	Issue No.	<b>16</b>
LM End		Issue Type +	Ma	Location *	LS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Operations & Maintenance Manuals			°	°
DWR ID	DWR_RD0755_01_f_2014_16				
Action/Comments					
Inspector Comments: The engineer for the district has a copy of the O&M Manual but the LMA should also have a copy.					

No Photos

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable	<b>N : Not Inspected/Rated</b> C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	--	---

**Flood Control Project Maintenance  
Levee Inspections**

**Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2014**

**Reclamation District No. 0755 Randall**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	1.83	10/29/2014 10/29/2014	Herman Phillips

LM Start	<b>0.18</b>	Rating **	U	Issue No.	<b>2</b>
LM End	<b>0.59</b>	Issue Type +	Ma	Location *	WS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Vegetation		38.346768 °	38.345555 °	
			-121.538667 °	-121.545965 °	
DWR ID	DWR_RD0755_01_f_2014_2				
Action/Comments					
Control annual grass and weeds on the levee slopes and easements. Inspector Comments: Control the wild growth on the waterside levee slope.					

Photo 1 of 1 : FA\_2014\_RD0755\_177\_2\_20141124\_00003.jpg



Looking downstream from levee mile 0.18 along the waterside at unwanted tall weeds blocking the view of the waterside slope.

LM Start	<b>0.18</b>	Rating **	A	Issue No.	<b>1</b>
LM End	<b>0.64</b>	Issue Type +	Ma	Location *	LS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Vegetation		38.346768 °	38.345355 °	
			-121.538667 °	-121.546755 °	
DWR ID	DWR_RD0755_01_f_2014_1				
Action/Comments					
Control annual grass and weeds on the levee slopes and easements.					

No Photos

LM Start	<b>0.45</b>	Rating **	M	Issue No.	<b>3</b>
LM End	<b>0.45</b>	Issue Type +	Ma	Location *	LS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Erosion / Bank Caving		38.345593 °	38.345593 °	
			-121.543263 °	-121.543263 °	
DWR ID	DWR_RD0755_01_f_2014_3				
Action/Comments					
Note and monitor erosion site.					

No Photos

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable	<b>N : Not Inspected/Rated</b> C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	--	---

**Flood Control Project Maintenance  
Levee Inspections**

**Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2014**

**Reclamation District No. 0755 Randall**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	1.83	10/29/2014 10/29/2014	Herman Phillips

LM Start	<b>0.45</b>	Rating **	M	Issue No.	<b>4</b>
LM End	<b>1.80</b>	Issue Type +	Ma	Location *	LS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Animal Control		38.345593 °	38.337197 °	
			-121.543263 °	-121.564147 °	
DWR ID	DWR_RD0755_01_f_2014_4				
Action/Comments					
Exterminate rodents and backfill and compact or grout burrows.					

No Photos

LM Start	<b>0.52</b>	Rating **	M	Issue No.	<b>12</b>
LM End	<b>1.85</b>	Issue Type +	Ma	Location *	WS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Vegetation		38.345520 °	38.336715 °	
			-121.546223 °	-121.564750 °	
DWR ID	DWR_RD0755_01_f_2014_12				
Action/Comments					
Control annual grass and weeds on the levee slopes and easements.					

No Photos

LM Start	<b>0.64</b>	Rating **	U	Issue No.	<b>11</b>
LM End	<b>0.92</b>	Issue Type +	Ma	Location *	LS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Vegetation		38.345383 °	38.344197 °	
			-121.546740 °	-121.551710 °	
DWR ID	DWR_RD0755_01_f_2014_11				
Action/Comments					
Control annual grass and weeds on the levee slopes and easements. Inspector Comments: Remove the unwanted tall weeds from the levee section.					

Photo 1 of 1 : FA\_2014\_RD0755\_177\_11\_20141124\_00002.jpg



Looking downstream from levee mile 0.64 at unwanted tall weeds on the landside levee shoulder and slope.

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

**Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2014**

**Reclamation District No. 0755 Randall**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	1.83	10/29/2014 10/29/2014	Herman Phillips

LM Start	<b>1.11</b>	Rating **	<b>N</b>	Issue No.	<b>6</b>
LM End	<b>1.11</b>	Issue Type +	<b>Ma</b>	Location *	<b>LS</b>
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Trim / Thin Trees		38.343405 °	38.343405 °	
			-121.555052 °	-121.555052 °	
DWR ID	DWR_RD0755_01_f_2014_6				
Action/Comments					
Tree stumps.					

No Photos

LM Start	<b>1.13</b>	Rating **	<b>U</b>	Issue No.	<b>13</b>
LM End	<b>1.43</b>	Issue Type +	<b>Ma</b>	Location *	<b>WS</b>
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Vegetation		38.343427 °	38.341390 °	
			-121.555405 °	-121.560013 °	
DWR ID	DWR_RD0755_01_f_2014_13				
Action/Comments					
Control annual grass and weeds on the levee slopes and easements. Inspector Comments: Control the wild weed growth on the water side levee slope.					

No Photos

LM Start	<b>1.14</b>	Rating **	<b>U</b>	Issue No.	<b>7</b>
LM End	<b>1.26</b>	Issue Type +	<b>Ma</b>	Location *	<b>LS</b>
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Vegetation		38.343302 °	38.342810 °	
			-121.555538 °	-121.557687 °	
DWR ID	DWR_RD0755_01_f_2014_7				
Action/Comments					
Control annual grass and weeds on the levee slopes and easements. Inspector Comments: Remove tall weeds from the landside levee slope.					

Photo 1 of 1 : FA\_2014\_RD0755\_177\_7\_20141124\_00004.jpg



Tall weeds on slope and toe landside.

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable	<b>N : Not Inspected/Rated</b> <b>C : Corrected</b> <b>A/W : Acceptable but Monitor &amp; Maintain</b>	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	--	---

**Flood Control Project Maintenance  
Levee Inspections**

**Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2014**

**Reclamation District No. 0755 Randall**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	1.83	10/29/2014 10/29/2014	Herman Phillips

LM Start	<b>1.30</b>	Rating **	M	Issue No.	<b>8</b>
LM End	<b>1.80</b>	Issue Type +	Ma	Location *	LS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Vegetation		38.342622 °	38.337230 °	
			-121.558235 °	-121.564127 °	
DWR ID	DWR_RD0755_01_f_2014_8				
Action/Comments					
Control annual grass and weeds on the levee slopes and easements.					

No Photos

LM Start	<b>1.45</b>	Rating **	A	Issue No.	<b>9</b>
LM End	<b>1.77</b>	Issue Type +	Ma	Location *	LS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Vegetation		38.341093 °	38.337538 °	
			-121.560263 °	-121.563855 °	
DWR ID	DWR_RD0755_01_f_2014_9				
Action/Comments					
Control annual grass and weeds on the levee slopes and easements.					

No Photos

LM Start	<b>1.59</b>	Rating **	M	Issue No.	<b>17</b>
LM End	<b>1.70</b>	Issue Type +	Ma	Location *	WS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Vegetation				
DWR ID	DWR_RD0755_01_f_2014_17				
Action/Comments					
Control annual grass and weeds on the levee slopes and easements.					

No Photos

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

