

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2015

Reclamation District No. 0755 Randall

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	1.83	04/16/2015 04/16/2015	Herman Phillips

LM Start		Rating **	M	Issue No.	14
LM End		Issue Type +	Ma	Location *	WS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Flood Preparedness & Training			°	°
				°	°
DWR ID	DWR_RD0755_01_f_2014_14				
Action/Comments					
Inspector Comments: This district has a knowledge of how to conduct a flood fight but has not taken the class recently.					

No Photos

LM Start		Rating **	M	Issue No.	15
LM End		Issue Type +	Ma	Location *	WS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Emergency Supplies & Equipment			°	°
				°	°
DWR ID	DWR_RD0755_01_f_2014_15				
Action/Comments					
Inspector Comments: The emergency supplies were not observed during the inspection.					

No Photos

LM Start		Rating **	M	Issue No.	16
LM End		Issue Type +	Ma	Location *	WS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Operations & Maintenance Manuals			°	°
				°	°
DWR ID	DWR_RD0755_01_f_2014_16				
Action/Comments					
Inspector Comments: The engineer for the district has a copy of the O&M Manual but the LMA should also have a copy.					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable N : Not Inspected/Rated M : Minimally Acceptable C : Corrected U : Unacceptable A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2015

Reclamation District No. 0755 Randall

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	1.83	04/16/2015 04/16/2015	Herman Phillips

LM Start	0.17	Rating **	U	Issue No.	2
LM End	0.62	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.346768 °	38.345415 °
				-121.538667 °	-121.546663 °
DWR ID	DWR_RD0755_01_f_2014_2				
Action/Comments					
Control annual grass and weeds on the levee slopes and easements. Inspector Comments: Control the wild growth on the waterside levee slope.					

Photo 1 of 1 : SP_2015_RD0755_177_2_20150601_00011.jpg



Looking downstream along the waterside shoulder at tall snap grass and other weeds on the slope.

LM Start	0.26	Rating **	M	Issue No.	20
LM End	0.36	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.346257 °	38.345823 °
				-121.540223 °	-121.542050 °
DWR ID	DWR_RD0755_01_s_2015_20				
Action/Comments					
Control annual grass and weeds on the levee slopes and easements. Inspector Comments: Control the snap grasses on the landside levee section.					

No Photos

LM Start	0.43	Rating **	M	Issue No.	3
LM End	0.43	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Erosion / Bank Caving			38.345593 °	38.345593 °
				-121.543263 °	-121.543263 °
DWR ID	DWR_RD0755_01_f_2014_3				
Action/Comments					
Note and monitor erosion site.					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable N : Not Inspected/Rated M : Minimally Acceptable C : Corrected U : Unacceptable A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2015

Reclamation District No. 0755 Randall

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	1.83	04/16/2015 04/16/2015	Herman Phillips

LM Start	0.43	Rating **	M	Issue No.	4
LM End	1.77	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			38.345593 °	38.337197 °
				-121.543263 °	-121.564147 °
DWR ID	DWR_RD0755_01_f_2014_4				
Action/Comments					
Exterminate rodents and backfill and compact or grout burrows.					

No Photos

LM Start	0.62	Rating **	U	Issue No.	11
LM End	0.90	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.345383 °	38.344197 °
				-121.546740 °	-121.551710 °
DWR ID	DWR_RD0755_01_f_2014_11				
Action/Comments					
Control annual grass and weeds on the levee slopes and easements. Inspector Comments: Remove the unwanted tall weeds from the levee section.					

Photo 1 of 1 : SP_2015_RD0755_177_11_20150601_00012.jpg



Looking downstream at tall weeds on the landside levee shoulder and slope.

LM Start	0.64	Rating **	U	Issue No.	22
LM End	0.87	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.345315 °	38.344330 °
				-121.547092 °	-121.551032 °
DWR ID	DWR_RD0755_01_s_2015_22				
Action/Comments					
Control annual grass and weeds on the levee slopes and easements. Inspector Comments: Snap grasses on waterward levee section unacceptable growth.					

Photo 1 of 1 : SP_2015_RD0755_177_22_20150601_00010.jpg



Looking downstream at tall snap grasses covering the waterward levee slope.

* Location		** Rating		+ Issue Type	
LS : Land Side	N/A : Not Applicable	A : Acceptable	N : Not Inspected/Rated	Ma : Maintenance Deficiency	
WS : Water Side		M : Minimally Acceptable	C : Corrected	Ob : Design & System Obsolescence	
CR : Crown		U : Unacceptable	A/W : Acceptable but Monitor & Maintain	En : Enforcement	

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2015

Reclamation District No. 0755 Randall

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	1.83	04/16/2015 04/16/2015	Herman Phillips

LM Start	1.09	Rating **	N	Issue No.	6
LM End	1.09	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			38.343405 °	38.343405 °
				-121.555052 °	-121.555052 °
DWR ID	DWR_RD0755_01_f_2014_6				
Action/Comments					
Tree stumps.					

No Photos

LM Start	1.11	Rating **	U	Issue No.	25
LM End	1.57	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.343418 °	38.339530 °
				-121.555315 °	-121.561800 °
DWR ID	DWR_RD0755_01_s_2015_25				
Action/Comments					
Control annual grass and weeds on the levee slopes and easements. Inspector Comments: Control the wild growth on the waterside levee slope.					

Photo 1 of 1 : SP_2015_RD0755_177_25_20150601_00009.jpg



Looking downstream from the waterside shoulder at unacceptable tall weeds covering the waterward slope.

LM Start	1.12	Rating **	C	Issue No.	7
LM End	1.24	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.343302 °	38.342810 °
				-121.555538 °	-121.557687 °
DWR ID	DWR_RD0755_01_f_2014_7				
Action/Comments					
Control annual grass and weeds on the levee slopes and easements. Inspector Comments: Remove tall weeds from the landside levee slope.					

No Photos

* Location		** Rating		+ Issue Type	
LS : Land Side	N/A : Not Applicable	A : Acceptable	N : Not Inspected/Rated	Ma : Maintenance Deficiency	
WS : Water Side		M : Minimally Acceptable	C : Corrected	Ob : Design & System Obsolescence	
CR : Crown		U : Unacceptable	A/W : Acceptable but Monitor & Maintain	En : Enforcement	

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2015

Reclamation District No. 0755 Randall

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	1.83	04/16/2015 04/16/2015	Herman Phillips

LM Start	1.27	Rating **	A	Issue No.	8
LM End	1.77	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.342622 °	38.337230 °
				-121.558235 °	-121.564127 °
DWR ID	DWR_RD0755_01_f_2014_8				
Action/Comments					
Control annual grass and weeds on the levee slopes and easements.					

No Photos

LM Start	1.63	Rating **	M	Issue No.	26
LM End	1.81	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.338812 °	38.336708 °
				-121.562452 °	-121.564643 °
DWR ID	DWR_RD0755_01_s_2015_26				
Action/Comments					
Remove the wild growth other than native grasses from the levee slopes.					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable N : Not Inspected/Rated M : Minimally Acceptable C : Corrected U : Unacceptable A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---