

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2021

Reclamation District No. 0755 Randall

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	1.83	04/08/2021 04/08/2021	David Julian

LM Start		Rating **	M	Issue No.	14
LM End		Issue Type +	Ma	Location *	
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Flood Preparedness & Training			°	°
				°	°
DWR ID	DWR_RD0755_01_f_2014_14				
Comment Code					
Inspector Comment					
This district has a knowledge of how to conduct a flood fight but has not taken the class recently.					

No Photos

LM Start		Rating **	A	Issue No.	15
LM End		Issue Type +	Ma	Location *	
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Emergency Supplies & Equipment			°	°
				°	°
DWR ID	DWR_RD0755_01_f_2014_15				
Comment Code					
Inspector Comment					
District maintains supply of sand bags and gets other supplies from other districts.					

No Photos

LM Start		Rating **	A	Issue No.	16
LM End		Issue Type +	Ma	Location *	
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Operations & Maintenance Manuals			°	°
				°	°
DWR ID	DWR_RD0755_01_f_2014_16				
Comment Code					
Inspector Comment					
MBK Engineering mailed a copy of the O/M Manual to the RD President in spring of 2017.					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2021

Reclamation District No. 0755 Randall

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	1.83	04/08/2021 04/08/2021	David Julian

LM Start	0.07	Rating **	M	Issue No.	42
LM End	0.15	Issue Type +	Ma	Location *	CR
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.347353 °	38.346885 °
				-121.537034 °	-121.538322 °
DWR ID	DWR_RD0755_01_s_2021_42				
Comment Code					
V9 : Keep the crown roadway free of vegetation.					
Inspector Comment					

No Photos

LM Start	0.07	Rating **	M	Issue No.	19
LM End	1.73	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.347353 °	38.337654 °
				-121.537034 °	-121.563779 °
DWR ID	DWR_RD0755_01_f_2016_19				
Comment Code					
V1 : Control annual grass and weeds on the levee slopes and easements.					
Inspector Comment					
Large cactus (Century Plants) at LM 1.07 should also be removed.					

Photo 1 of 1 : SP_2021_RD0755_177_19_20210408_00080.jpg



View looking downstream at vegetation on the waterside slope (Spring 2021).

LM Start	0.20	Rating **	M	Issue No.	4
LM End	0.92	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			38.346500 °	38.344130 °
				-121.539146 °	-121.552038 °
DWR ID	DWR_RD0755_01_f_2014_4				
Comment Code					
A3 : No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.					
Inspector Comment					
Evidence of active rodents on landside slope near the walnut trees. No bait stations were observed.					

Photo 1 of 2 : SP_2021_RD0755_177_4_20210301_00001.jpg



View looking downstream at fresh animal hole on the landside slope (Spring 2020).

* Location		** Rating		+ Issue Type	
LS : Land Side	N/A : Not Applicable	A : Acceptable	N : Not Inspected/Rated	Ma : Maintenance Deficiency	
WS : Water Side		M : Minimally Acceptable	C : Corrected	Ob : Design & System Obsolescence	
CR : Crown		U : Unacceptable	A/W : Acceptable but Monitor & Maintain	En : Enforcement	

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2021

Reclamation District No. 0755 Randall

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	1.83	04/08/2021 04/08/2021	David Julian

LM Start	0.28	Rating **	U	Issue No.	18
LM End	0.28	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Erosion / Bank Caving			38.346249 °	38.346331 °
				-121.540542 °	-121.540664 °
DWR ID	DWR_RD0755_01_s _ 2020_18				
Comment Code					
E2 : Schedule repair of erosion site prior to the next inspection.					
Inspector Comment					
This was a 2017 Storm Damage site. Damage consists of erosion of the lower waterside levee slope and bank approximately 27 feet in length. Site ID No:327 Site Designation:LMA-154 3/25/2020 Field Notes: Erosion is significant. At least 1' into waterside slope. No riprap present.					

Photo 1 of 1 : SP_2021_RD0755_177_18_20210301_00006.jpg



View looking upstream and slightly up at erosion into the waterside slope (Spring 2020).

LM Start	0.50	Rating **	M	Issue No.	17
LM End	0.53	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			38.345652 °	38.345618 °
				-121.544482 °	-121.545122 °
DWR ID	DWR_RD0755_01_f _ 2018_17				
Comment Code					
T1 : Trim trees to at least five feet above ground level.					
Inspector Comment					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2021

Reclamation District No. 0755 Randall

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	1.83	04/08/2021 04/08/2021	David Julian

LM Start	0.69	Rating **	M	Issue No.	26
LM End	0.69	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			38.345103 °	38.345103 °
				-121.547918 °	-121.547918 °
DWR ID	DWR_RD0755_01_f_2018_26				
Comment Code					
T1 : Trim trees to at least five feet above ground level.					
Inspector Comment					

No Photos

LM Start	0.70	Rating **	M	Issue No.	27	
LM End	0.70	Issue Type +	Ma	Location *		
Category	Supplemental			GPS Latitude/Longitude		
				Start		End
Item	DWR UCIP LMA Responsibility			38.345057 °	38.345057 °	
				-121.548050 °	-121.548050 °	
DWR ID	18852					
Comment Code						
Inspector Comment						
FS_ID:57038						
DS_ID:18852						
EP_NO: 11222						
Repair Type: Non-Urgent						
Crossing Status: Found						
UCIP Comments: 05/26/2020 Record updated from No Action Needed to Non-Urgent. No permit has been identified authorizing pipe. Pipe was running during site visit pumping water to the waterside. (O.Yakimov - DWR UCIP)						
08/06/2013 It was working during field survey. A pump found 150 ft from the levee. Not sure whether the pump belong to this drainage system.						
FIELD_STRUCT_DESC: 16-inch steel drainage pipe sleeved through a 24-inch steel drainage pipe through the levee, invert elevation 8 feet below the crown. Air vent installed on the pipe on WS slope. Concrete headwall on LS. (12-inch pipe sleeved through 24-inch pipe-inch pipe [HLM 0.71] authorized under Automatic Board Order (ABO) issued as Permit No. 11222, 1975 - Green McKeown, Inc). [Additional Reference(s): DWR Levee Log, 2005 (HLM 0.71), referenced as 12-inch pipe through 24-inch pipe. USACE Sacramento O&M Manual, Unit 111, May 1959, Revised 29 December 2016, (RM 35.89), listed as 24-inch pipe].						
FS Date: 5/26/2020 3:00:07 PM						

Photo 1 of 3 : UCIP_SP_2021_57038_84440.jpg



Top of Levee: View of levee crown looking downstream

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2021

Reclamation District No. 0755 Randall

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	1.83	04/08/2021 04/08/2021	David Julian

LM Start	0.70	Rating **	M	Issue No.	27 (cont)
LM End	0.70	Issue Type +	Ma	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP LMA Responsibility			38.345057 °	38.345057 °
				-121.548050 °	-121.548050 °
DWR ID	18852				

Photo 2 of 3 : UCIP_SP_2021_57038_84442.jpg



Water-Side: View of levee slope looking from crown

LM Start	0.70	Rating **	M	Issue No.	27 (cont)
LM End	0.70	Issue Type +	Ma	Location *	

Photo 3 of 3 : UCIP_SP_2021_57038_84443.jpg



Water-Side: Pipe and air release valve on levee slope

LM Start	0.70	Rating **	M	Issue No.	43
LM End	0.70	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			38.345083 °	38.345083 °
				-121.548068 °	-121.548068 °
DWR ID	DWR_RD0755_01_s_2021_43				
Comment Code					
GA : Garbage					
Inspector Comment					
Remove discarded mattresses.					

Photo 1 of 1 : SP_2021_RD0755_177_43_20210408_00082.jpg



View of discarded mattress on the landside hinge (Spring 2021).

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2021

Reclamation District No. 0755 Randall

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	1.83	04/08/2021 04/08/2021	David Julian

LM Start	0.79	Rating **	M	Issue No.	45
LM End	0.79	Issue Type +	Ma	Location *	LS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Trim / Thin Trees		38.344612 °	38.344612 °	
			-121.549752 °	-121.549752 °	
DWR ID	DWR_RD0755_01_f_2019_45				
Comment Code					
T1 : Trim trees to at least five feet above ground level.					
Inspector Comment					

No Photos

LM Start	0.85	Rating **	M	Issue No.	46
LM End	0.85	Issue Type +	Ma	Location *	LS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Trim / Thin Trees		38.344414 °	38.344414 °	
			-121.550812 °	-121.550812 °	
DWR ID	DWR_RD0755_01_s_2021_46				
Comment Code					
T2 : Thin trees to allow visibility of the ground and room to flood fight.					
Inspector Comment					

No Photos

LM Start	0.89	Rating **	M	Issue No.	51
LM End	0.89	Issue Type +	Ma	Location *	LS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Trim / Thin Trees		38.344253 °	38.344253 °	
			-121.551435 °	-121.551435 °	
DWR ID	DWR_RD0755_01_f_2020_51				
Comment Code					
T1 : Trim trees to at least five feet above ground level.					
Inspector Comment					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2021

Reclamation District No. 0755 Randall

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	1.83	04/08/2021 04/08/2021	David Julian

LM Start	0.91	Rating **	C	Issue No.	52
LM End	0.91	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			38.344198 °	38.344198 °
				-121.551805 °	-121.551805 °
DWR ID	DWR_RD0755_01_f_2020_52				
Comment Code					
T1 : Trim trees to at least five feet above ground level.					
Inspector Comment					

No Photos

LM Start	0.99	Rating **	U	Issue No.	53
LM End	0.99	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			38.343850 °	38.343850 °
				-121.553150 °	-121.553150 °
DWR ID	DWR_RD0755_01_f_2020_53				
Comment Code					
T1 : Trim trees to at least five feet above ground level.					
Inspector Comment					

Photo 1 of 1 : SP_2021_RD0755_177_53_20210301_00023.jpg



View of thick trees on the landside slope (Fall 2020).

LM Start	1.06	Rating **	M	Issue No.	31
LM End	1.06	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			38.343542 °	38.343542 °
				-121.554487 °	-121.554487 °
DWR ID	DWR_RD0755_01_s_2019_31				
Comment Code					
T1 : Trim trees to at least five feet above ground level.					
Inspector Comment					
Trees are blocking visibility down waterside slope.					

Photo 1 of 1 : SP_2021_RD0755_177_31_20210301_00016.jpg



View of tree at the top of the waterside shoulder (Spring 2019).

*** Location**

LS : Land Side N/A : Not Applicable
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable N : Not Inspected/Rated
M : Minimally Acceptable C : Corrected
U : Unacceptable A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2021

Reclamation District No. 0755 Randall

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	1.83	04/08/2021 04/08/2021	David Julian

LM Start	1.10	Rating **	M	Issue No.	47
LM End	1.10	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			38.343422 °	38.343422 °
				-121.555217 °	-121.555217 °
DWR ID	DWR_RD0755_01_s_2021_47				
Comment Code					
T2 : Thin trees to allow visibility of the ground and room to flood fight.					
Inspector Comment					

No Photos

LM Start	1.11	Rating **	M	Issue No.	54
LM End	1.76	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.343345 °	38.337423 °
				-121.555430 °	-121.564028 °
DWR ID	DWR_RD0755_01_f_2020_54				
Comment Code					
V1 : Control annual grass and weeds on the levee slopes and easements.					
Inspector Comment					

Photo 1 of 1 : SP_2021_RD0755_177_54_20210301_00024.jpg



View looking downstream at annual vegetation on the landside slope (Fall 2020).

LM Start	1.18	Rating **	M	Issue No.	28
LM End	1.18	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			38.343072 °	38.343072 °
				-121.556532 °	-121.556532 °
DWR ID	DWR_RD0755_01_f_2019_28				
Comment Code					
T2 : Thin trees to allow visibility of the ground and room to flood fight.					
Inspector Comment					

Photo 1 of 1 : SP_2021_RD0755_177_28_20210301_00015.jpg



View looking downstream at tree on the waterside slope (Spring 2020).

*** Location**
LS : Land Side N/A : Not Applicable
WS : Water Side
CR : Crown

**** Rating**
A : Acceptable N : Not Inspected/Rated
M : Minimally Acceptable C : Corrected
U : Unacceptable A/W : Acceptable but Monitor & Maintain

+ Issue Type
Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2021

Reclamation District No. 0755 Randall

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	1.83	04/08/2021 04/08/2021	David Julian

LM Start	1.23	Rating **	A/W	Issue No.	22
LM End	1.29	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Erosion / Bank Caving			38.342992 °	38.342633 °
				-121.557572 °	-121.558622 °
DWR ID	LMA-155				
Comment Code					
E1 : Note and monitor erosion site.					
Inspector Comment					
This was a 2017 Storm Damage site. Damage consists of erosion of the lower waterside levee slope and bank approximately 322 feet in length. Site ID No:328 Site Designation:LMA-155 6/18/2020 Field Notes: Erosion is into berm and not prism.					

Photo 1 of 1 : SP_2021_RD0755_177_22_20210301_00009.jpg



LM Start	1.28	Rating **	M	Issue No.	48
LM End	1.28	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			38.342602 °	38.342602 °
				-121.558360 °	-121.558360 °
DWR ID	DWR_RD0755_01_s_2021_48				
Comment Code					
T2 : Thin trees to allow visibility of the ground and room to flood fight.					
Inspector Comment					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2021

Reclamation District No. 0755 Randall

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	1.83	04/08/2021 04/08/2021	David Julian

LM Start	1.39	Rating **	M	Issue No.	41
LM End	1.39	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			38.341510 °	38.341510 °
				-121.559892 °	-121.559892 °
DWR ID	DWR_RD0755_01_f_2019_41				
Comment Code					
T2 : Thin trees to allow visibility of the ground and room to flood fight.					
Inspector Comment					

No Photos

LM Start	1.53	Rating **	U	Issue No.	36
LM End	1.53	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			38.339867 °	38.339867 °
				-121.561397 °	-121.561397 °
DWR ID	DWR_RD0755_01_f_2019_36				
Comment Code					
T2 : Thin trees to allow visibility of the ground and room to flood fight.					
Inspector Comment					

Photo 1 of 1 : SP_2021_RD0755_177_36_20210301_00019.jpg



View looking downstream at thick trees on the waterside slope (Fall 2019).

LM Start	1.61	Rating **	U	Issue No.	37
LM End	1.61	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			38.339030 °	38.339030 °
				-121.562232 °	-121.562232 °
DWR ID	DWR_RD0755_01_f_2019_37				
Comment Code					
T2 : Thin trees to allow visibility of the ground and room to flood fight.					
Inspector Comment					

Photo 1 of 1 : SP_2021_RD0755_177_37_20210408_00083.jpg



View looking downstream at thick tree on the waterside slope (Spring 2021).

*** Location**
LS : Land Side N/A : Not Applicable
WS : Water Side
CR : Crown

**** Rating**
A : Acceptable N : Not Inspected/Rated
M : Minimally Acceptable C : Corrected
U : Unacceptable A/W : Acceptable but Monitor & Maintain

+ Issue Type
Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2021

Reclamation District No. 0755 Randall

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	1.83	04/08/2021 04/08/2021	David Julian

LM Start	1.73	Rating **	A/W	Issue No.	24
LM End	1.81	Issue Type +	Ma	Location *	WS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	2017 Storm Damage			38.337758 °	38.336789 °
				-121.563856 °	-121.564739 °
DWR ID	LMA-156				
Comment Code					
Inspector Comment					
Planned For Repair.					
Levee Evaluation Comments					
Description:The damage consists of erosion of the lower waterside levee slope and bank approximately 424 feet in length along the east (left) bank of the Sacramento River. See attached pages for photos.					
Site location T06N R04E Section 29.					
Site ID No:329					
Site Designation:LMA-156					
Repair Type: Erosion					
Rating:Serious					
Field Date:7/13/2017					
Notes: Crown is a paved road. Large LS berm on part. Good visibility here. Serious because erosion cut into prism significantly for a long distance and soils are very sandy here and WS slope is very steep.					

LM Start	1.73	Rating **	A/W	Issue No.	24 (cont)
LM End	1.81	Issue Type +	Ma	Location *	WS

Photo 1 of 3 : SP_2021_RD0755_177_24_20210301_00011.jpg



Photo 2 of 3 : SP_2021_RD0755_177_24_20210301_00012.jpg

*** Location**

LS : Land Side N/A : Not Applicable
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable N : Not Inspected/Rated
M : Minimally Acceptable C : Corrected
U : Unacceptable A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2021

Reclamation District No. 0755 Randall

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	1.83	04/08/2021 04/08/2021	David Julian

LM Start	1.73	Rating **	A/W	Issue No.	24 (cont)
LM End	1.81	Issue Type +	Ma	Location *	WS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	2017 Storm Damage			38.337758 °	38.336789 °
				-121.563856 °	-121.564739 °
DWR ID	LMA-156				

Photo 3 of 3 : SP_2021_RD0755_177_24_20210301_00013.jpg



LM Start	1.81	Rating **	M	Issue No.	12
LM End	1.81	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			38.336812 °	38.336812 °
				-121.564551 °	-121.564551 °
DWR ID	DWR_RD0755_01_s_2020_12				
Comment Code					
T1 : Trim trees to at least five feet above ground level.					
Inspector Comment					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---