

**Flood Control Project Maintenance
Levee Inspections
LMA District Cover Sheet
Spring 2011 Levee Inspection Results**

Reclamation District No. 0765 Glide

	Spring (March - May)	Summer ** (June - August)	Fall (September - November)	Winter ** (December - February)
* Overall LMA Rating (Fall Only)				

** Non-receipt of Summer or Winter Inspection Reports may effect overall annual rating.

* **SPRING INSPECTIONS:** Overall maintenance ratings are not determined for the spring inspection results. Individual maintenance deficiencies are rated using the same criteria in the spring and in the fall.

FALL INSPECTIONS: The overall maintenance rating shown above is based on operation and maintenance deficiencies identified within the attached unit inspection reports.

Comments

**Flood Control Project Maintenance
Levee Inspections**

Unit Cover Sheet

Spring 2011 Levee Inspection Results

Reclamation District No. 0765 Glide

Waterway	Bank	Unit Miles
Unit No. 01 Sacramento River	Right	1.74

	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - February)
Unit Maintenance Rating (Fall Only)				
Date of Inspection	3/3/2011 - 3/3/2011			
DWR Inspector	Richard Willoughby			
Accompanied By	Dave Chestnut RD765			

Check one:

During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.

During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

Comments

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :

DWR Summer/Winter Inspection Reports
3310 El Camino Avenue, Suite 200
Sacramento, CA 95821-9000

X _____ Date

Signature of LMA Representative

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2011

Reclamation District No. 0765 Glide

Waterway			Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River			Right	1.74	03/03/2011 03/03/2011	Richard Willoughby

LMR No.	Levee Mile		Category	Item	Location	Rating	Action/Comment	GPS Latitude/Longitude		Issue No. Photo
	Start	End						Start	End	
1	0.00	0.11	Earthen Levee	Encroachments	LS	CO	Fences	38.502962 ° -121.560112 °	38.501373 ° -121.560402 °	12
2	0.03	1.74	Earthen Levee	Vegetation	WS	M	Control annual grass and weeds on the levee slopes and easements.	38.502503 ° -121.560050 °	38.480087 ° -121.549413 °	6
3	0.05	0.05	Earthen Levee	Trim / Thin Trees	LS	M	Trim trees to at least five feet above ground level.	38.502253 ° -121.560192 °	38.502253 ° -121.560192 °	3
4	0.09	1.72	Earthen Levee	Vegetation	LS	M	Control annual grass and weeds on the levee slopes and easements.	38.501692 ° -121.560305 °	38.480305 ° -121.549498 °	25
5	0.12	0.19	Earthen Levee	Trim / Thin Trees	LS	M	Trim and thin trees to allow visibility of the ground and room to flood fight.	38.501215 ° -121.560432 °	38.500271 ° -121.560434 °	28 Y
6	0.14	0.14	Earthen Levee	Vegetation	LS	M	Elderberries are blocking visibility and flood fight capability.	38.500928 ° -121.560431 °	38.500928 ° -121.560431 °	22
7	0.19	0.35	Earthen Levee	Trim / Thin Trees	LS	M	Trim trees to at least five feet above ground level.	38.500343 ° -121.560507 °	38.498032 ° -121.560337 °	14
8	0.25	0.28	Earthen Levee	Trim / Thin Trees	WS	U	Thin trees to allow visibility of the ground and room to flood fight.	38.499405 ° -121.560445 °	38.499042 ° -121.560430 °	11 Y
9	0.32	0.32	Earthen Levee	Trim / Thin Trees	WS	M	Trim trees to at least five feet above ground level.	38.498453 ° -121.560360 °	38.498453 ° -121.560360 °	23
10	0.41	0.41	Earthen Levee	Trim / Thin Trees	LS	M	Trim trees to at least five feet above ground level.	38.497196 ° -121.560147 °	38.497196 ° -121.560147 °	21
11	0.41	0.52	Earthen Levee	Trim / Thin Trees	WS	M	Trim trees to at least five feet above ground level.	38.497125 ° -121.560087 °	38.495648 ° -121.559391 °	24
12	0.43	0.47	Earthen Levee	Trim / Thin Trees	LS	M	Trim and thin trees to allow visibility of the ground and room to flood fight.	38.496792 ° -121.560026 °	38.496321 ° -121.559842 °	32
13	0.48	0.50	Earthen Levee	Vegetation	LS	U	Remove the wild growth other than native grasses from the levee slopes.	38.496217 ° -121.559788 °	38.495855 ° -121.559586 °	33 Y
14	0.54	0.54	Earthen Levee	Trim / Thin Trees	LS	M	Trim trees to at least five feet above ground level.	38.495347 ° -121.559291 °	38.495347 ° -121.559291 °	34
15	0.57	0.60	Earthen Levee	Trim / Thin Trees	WS	M	Trim trees to at least five feet above ground level.	38.495035 ° -121.559027 °	38.494642 ° -121.558697 °	10
16	0.62	0.65	Earthen Levee	Trim / Thin Trees	LS	M	Trim trees to at least five feet above ground level.	38.494468 ° -121.558577 °	38.494037 ° -121.558192 °	16
17	0.65	0.65	Earthen Levee	Trim / Thin Trees	WS	M	Trim trees to at least five feet above ground level.	38.494097 ° -121.558192 °	38.494097 ° -121.558192 °	19
18	0.66	0.66	Earthen Levee	Trim / Thin Trees	WS	M	Trim trees to at least five feet above ground level.	38.493917 ° -121.558041 °	38.493917 ° -121.558041 °	18
19	0.69	0.69	Earthen Levee	Trim / Thin Trees	LS	M	Trim trees to at least five feet above ground level.	38.493596 ° -121.557832 °	38.493596 ° -121.557832 °	35

* Location LS : Landside WS : Waterside CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected/Rated C : Corrected W : Watch/Monitor
--------------------------------------------------------------------	------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2011

Reclamation District No. 0765 Glide

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	1.74	03/03/2011 03/03/2011	Richard Willoughby

LMR No.	Levee Mile		Category	Item	Location	Rating	Action/Comment	GPS Latitude/Longitude		Issue No. Photo
	Start	End						Start	End	
20	0.71	0.71	Earthen Levee	Trim / Thin Trees	WS	M	Trim trees to at least five feet above ground level.	38.493392 ° -121.557640 °	38.493392 ° -121.557640 °	15
21	0.78	0.81	Earthen Levee	Trim / Thin Trees	LS	M	Trim and thin trees to allow visibility of the ground and room to flood fight.	38.492392 ° -121.557026 °	38.492034 ° -121.556820 °	36
22	0.87	1.03	Earthen Levee	Trim / Thin Trees	LS	U	Trim trees to at least five feet above ground level.	38.491283 ° -121.556360 °	38.489149 ° -121.555121 °	17 Y
23	0.99	1.05	Earthen Levee	Trim / Thin Trees	WS	M	Thin trees to allow visibility of the ground and room to flood fight.	38.489705 ° -121.555385 °	38.488990 ° -121.554993 °	8 Y
24	1.08	1.08	Earthen Levee	Trim / Thin Trees	LS	U	Trim and thin trees to allow visibility of the ground and room to flood fight.	38.488503 ° -121.554757 °	38.488503 ° -121.554757 °	37 Y
25	1.10	1.16	Earthen Levee	Trim / Thin Trees	LS	M	Trim trees to at least five feet above ground level.	38.488279 ° -121.554615 °	38.487465 ° -121.554117 °	38
26	1.15	1.15	Earthen Levee	Vegetation	LS	M	Remove the wild growth other than native grasses from the levee slopes.	38.487653 ° -121.554248 °	38.487653 ° -121.554248 °	39 Y
27	1.16	1.16	Earthen Levee	Trim / Thin Trees	WS	M	Trim trees to at least five feet above ground level.	38.487473 ° -121.554080 °	38.487473 ° -121.554080 °	9
28	1.19	1.22	Earthen Levee	Encroachments	LS	CO	Buildings	38.487127 ° -121.553910 °	38.486702 ° -121.553652 °	43 Y
29	1.32	1.32	Earthen Levee	Trim / Thin Trees	LS	M	Trim trees to at least five feet above ground level.	38.485280 ° -121.552860 °	38.485280 ° -121.552860 °	26
30	1.36	1.36	Earthen Levee	Trim / Thin Trees	WS	U	Trim trees to at least five feet above ground level.	38.484877 ° -121.552540 °	38.484877 ° -121.552540 °	7 Y
31	1.41	1.41	Earthen Levee	Trim / Thin Trees	WS	M	Trim trees to at least five feet above ground level.	38.484316 ° -121.552115 °	38.484316 ° -121.552115 °	4
32	1.44	1.47	Earthen Levee	Trim / Thin Trees	WS	M	Thin trees to allow visibility of the ground and room to flood fight.	38.483925 ° -121.551845 °	38.483530 ° -121.551587 °	5 Y
33	1.50	1.50	Earthen Levee	Trim / Thin Trees	LS	M	Trim trees to at least five feet above ground level.	38.483170 ° -121.551367 °	38.483170 ° -121.551367 °	42
34	1.54	1.60	Earthen Levee	Vegetation	LS	M	Remove the wild growth other than native grasses from the levee slopes.	38.482627 ° -121.551038 °	38.481810 ° -121.550538 °	20
35	1.54	1.54	Earthen Levee	Vegetation	LS	U	Remove the wild growth other than native grasses from the levee slopes.	38.482590 ° -121.551020 °	38.482590 ° -121.551020 °	29 Y
36	1.60	1.67	Earthen Levee	Trim / Thin Trees	WS	M	Trim trees to at least five feet above ground level.	38.480913 ° -121.549677 °	38.480993 ° -121.549738 °	2 Y
37	1.60	1.60	Earthen Levee	Vegetation	WS	M	Remove the wild growth other than native grasses from the levee slopes.	38.481841 ° -121.550438 °	38.482028 ° -121.550512 °	31
38	1.69	1.69	Earthen Levee	Encroachments	WS	M	Garbage	38.480770 ° -121.549514 °	38.480895 ° -121.549556 °	30 Y

* Location LS : Landside WS : Waterside CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected/Rated C : Corrected W : Watch/Monitor
--------------------------------------------------------------------	------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2011

Reclamation District No. 0765 Glide

Waterway			Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River			Right	1.74	03/03/2011 03/03/2011	Richard Willoughby

LMR No.	Levee Mile		Category	Item	* Location	** Rating	Action/Comment	GPS Latitude/Longitude		Issue No. Photo
	Start	End						Start	End	
39	1.70	1.70	Earthen Levee	Encroachments	WS	M	Prunings	38.480632 ° -121.549543 °	38.480632 ° -121.549543 °	13 Y
40	1.70	1.73	Earthen Levee	Trim / Thin Trees	WS	M	Trim trees to at least five feet above ground level.	38.480602 ° -121.549523 °	38.480257 ° -121.549458 °	1 Y

* Location LS : Landside WS : Waterside CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected/Rated C : Corrected W : Watch/Monitor
--------------------------------------------------------------------	------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2011

Reclamation District No. 0765 Glide

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	1.74	03/03/2011 03/03/2011	Richard Willoughby

Levee Mile Report Line	5
Start Levee Mile	0.12
End Levee Mile	0.19
Location	Land Side
Category	Earthen Levee
Item	Trim / Thin Trees
Looking west at trees on landside toe.	
richard_s_20110215_310.jpg	



Levee Mile Report Line	5
Start Levee Mile	0.12
End Levee Mile	0.19
Location	Land Side
Category	Earthen Levee
Item	Trim / Thin Trees
Looking downstream (south) at trees on landside slope & toe.	
richard_s_20110215_311.jpg	



Levee Mile Report Line	8
Start Levee Mile	0.25
End Levee Mile	0.28
Location	Water Side
Category	Earthen Levee
Item	Trim / Thin Trees
Looking northeast at overgrown trees on waterside slope.	
richard_s_20110215_305.jpg	



<p>* Location</p> <p>LS : Landside WS : Waterside CR : Crown</p>	<p>** Rating</p> <p>A : Acceptable M : Minimally Acceptable U : Unacceptable</p>	<p>PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected/Rated</p>	<p>C : Corrected W : Watch/Monitor</p>
---------------------------------------------------------------------------------	-------------------------------------------------------------------------------------------------	-----------------------------------------------------------------------------------------------	--------------------------------------------

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2011

Reclamation District No. 0765 Glide

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	1.74	03/03/2011 03/03/2011	Richard Willoughby

Levee Mile Report Line	8
Start Levee Mile	0.25
End Levee Mile	0.28
Location	Water Side
Category	Earthen Levee
Item	Trim / Thin Trees
Looking north at dense trees on waterside slope from fall 2010 inspection.	
richard_s_20110215_306.jpg	



Levee Mile Report Line	8
Start Levee Mile	0.25
End Levee Mile	0.28
Location	Water Side
Category	Earthen Levee
Item	Trim / Thin Trees
Looking upstream (north) at dense vegetation and trees from 2011 spring inspection.	
richard_s_20110304_432.jpg	



Levee Mile Report Line	13
Start Levee Mile	0.48
End Levee Mile	0.50
Location	Land Side
Category	Earthen Levee
Item	Vegetation
Looking northwest at trees on landside toe from 2010 fall inspection.	
richard_s_20110215_317.jpg	



* Location LS : Landside WS : Waterside CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected/Rated	C : Corrected W : Watch/Monitor
--------------------------------------------------------------------	------------------------------------------------------------------------------------	--------------------------------------------------------------------------------------	------------------------------------

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2011

Reclamation District No. 0765 Glide

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	1.74	03/03/2011 03/03/2011	Richard Willoughby

Levee Mile Report Line	13
Start Levee Mile	0.48
End Levee Mile	0.50
Location	Land Side
Category	Earthen Levee
Item	Vegetation

Looking downstream (south) at trees on landside slope & toe.

richard_s_20110215_318.jpg



Levee Mile Report Line	13
Start Levee Mile	0.48
End Levee Mile	0.50
Location	Land Side
Category	Earthen Levee
Item	Vegetation

Looking downstream (southwest) at dense vegetation on landside slope.

richard_s_20110304_433.jpg



Levee Mile Report Line	13
Start Levee Mile	0.48
End Levee Mile	0.50
Location	Land Side
Category	Earthen Levee
Item	Vegetation

Looking upstream (northwest) at dense vegetation on landside slope.

richard_s_20110304_434.jpg



<p>* Location</p> <p>LS : Landside WS : Waterside CR : Crown</p>	<p>** Rating</p> <p>A : Acceptable M : Minimally Acceptable U : Unacceptable</p>	<p>PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected/Rated</p>	<p>C : Corrected W : Watch/Monitor</p>
---------------------------------------------------------------------------------	-------------------------------------------------------------------------------------------------	-----------------------------------------------------------------------------------------------	--------------------------------------------

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2011

Reclamation District No. 0765 Glide

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	1.74	03/03/2011 03/03/2011	Richard Willoughby

Levee Mile Report Line	22
Start Levee Mile	0.87
End Levee Mile	1.03
Location	Land Side
Category	Earthen Levee
Item	Trim / Thin Trees
Looking downstream (south) at dense trees on landside slope and toe.	
richard_s_20110304_435.jpg	



Levee Mile Report Line	22
Start Levee Mile	0.87
End Levee Mile	1.03
Location	Land Side
Category	Earthen Levee
Item	Trim / Thin Trees
Looking upstream (north) at dense trees on landside slope and toe.	
richard_s_20110304_436.jpg	



Levee Mile Report Line	23
Start Levee Mile	0.99
End Levee Mile	1.05
Location	Water Side
Category	Earthen Levee
Item	Trim / Thin Trees
Looking upstream (northeast) at dense vegetation on waterside slope.	
richard_s_20110304_430.jpg	



<p>* Location</p> <p>LS : Landside WS : Waterside CR : Crown</p>	<p>** Rating</p> <p>A : Acceptable M : Minimally Acceptable U : Unacceptable</p>	<p>PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected/Rated</p>	<p>C : Corrected W : Watch/Monitor</p>
---------------------------------------------------------------------------------	-------------------------------------------------------------------------------------------------	-----------------------------------------------------------------------------------------------	--------------------------------------------

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2011

Reclamation District No. 0765 Glide

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	1.74	03/03/2011 03/03/2011	Richard Willoughby

Levee Mile Report Line	23
Start Levee Mile	0.99
End Levee Mile	1.05
Location	Water Side
Category	Earthen Levee
Item	Trim / Thin Trees
Looking upstream (north) dense vegetation and trees on waterside shoulder and slope.	
richard_s_20110304_431.jpg	



Levee Mile Report Line	24
Start Levee Mile	1.08
End Levee Mile	1.08
Location	Land Side
Category	Earthen Levee
Item	Trim / Thin Trees
Looking downstream (south) at trees on landside slope & toe from 2010 fall inspection.	
richard_s_20110215_319.jpg	



Levee Mile Report Line	24
Start Levee Mile	1.08
End Levee Mile	1.08
Location	Land Side
Category	Earthen Levee
Item	Trim / Thin Trees
Looking west at trees on landside slope & toe.	
richard_s_20110215_320.jpg	



<p>* Location</p> <p>LS : Landside WS : Waterside CR : Crown</p>	<p>** Rating</p> <p>A : Acceptable M : Minimally Acceptable U : Unacceptable</p>	<p>PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected/Rated</p>	<p>C : Corrected W : Watch/Monitor</p>
---------------------------------------------------------------------------------	-------------------------------------------------------------------------------------------------	-----------------------------------------------------------------------------------------------	--------------------------------------------

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2011

Reclamation District No. 0765 Glide

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	1.74	03/03/2011 03/03/2011	Richard Willoughby

Levee Mile Report Line	24
Start Levee Mile	1.08
End Levee Mile	1.08
Location	Land Side
Category	Earthen Levee
Item	Trim / Thin Trees
Looking downstream (southwest) at dense trees on landside slope and toe.	
richard_s_20110304_438.jpg	



Levee Mile Report Line	26
Start Levee Mile	1.15
End Levee Mile	1.15
Location	Land Side
Category	Earthen Levee
Item	Vegetation
Looking downstream (southwest) at wild roses on landside slope & toe.	
richard_s_20110215_321.jpg	



Levee Mile Report Line	28
Start Levee Mile	1.19
End Levee Mile	1.22
Location	Land Side
Category	Earthen Levee
Item	Encroachments
Looking northwest at buildings along landside toe.	
richard_s_20110215_322.jpg	



<p>* Location</p> <p>LS : Landside WS : Waterside CR : Crown</p>	<p>** Rating</p> <p>A : Acceptable M : Minimally Acceptable U : Unacceptable</p>	<p>PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected/Rated</p>	<p>C : Corrected W : Watch/Monitor</p>
---------------------------------------------------------------------------------	-------------------------------------------------------------------------------------------------	-----------------------------------------------------------------------------------------------	--------------------------------------------

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2011

Reclamation District No. 0765 Glide

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	1.74	03/03/2011 03/03/2011	Richard Willoughby

Levee Mile Report Line	30
Start Levee Mile	1.36
End Levee Mile	1.36
Location	Water Side
Category	Earthen Levee
Item	Trim / Thin Trees
Looking upstream (north) at dense vegetation on waterside slope.	
richard_s_20110304_429.jpg	



Levee Mile Report Line	32
Start Levee Mile	1.44
End Levee Mile	1.47
Location	Water Side
Category	Earthen Levee
Item	Trim / Thin Trees
Looking upstream (north) at dense trees on waterside slope.	
richard_s_20110304_428.jpg	



Levee Mile Report Line	35
Start Levee Mile	1.54
End Levee Mile	1.54
Location	Land Side
Category	Earthen Levee
Item	Vegetation
Looking downstream (southwest) at trees, vines & wildroses on landside slope & toe from 2010 fall inspection	
richard_s_20110215_312.jpg	



<p>* Location</p> <p>LS : Landside WS : Waterside CR : Crown</p>	<p>** Rating</p> <p>A : Acceptable M : Minimally Acceptable U : Unacceptable</p>	<p>PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected/Rated</p>	<p>C : Corrected W : Watch/Monitor</p>
---------------------------------------------------------------------------------	-------------------------------------------------------------------------------------------------	-----------------------------------------------------------------------------------------------	--------------------------------------------

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2011

Reclamation District No. 0765 Glide

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	1.74	03/03/2011 03/03/2011	Richard Willoughby

Levee Mile Report Line	35
Start Levee Mile	1.54
End Levee Mile	1.54
Location	Land Side
Category	Earthen Levee
Item	Vegetation
Looking downstream (south) at trees, vines & wildroses on landside slope & toe.	
richard_s_20110215_313.jpg	



Levee Mile Report Line	35
Start Levee Mile	1.54
End Levee Mile	1.54
Location	Land Side
Category	Earthen Levee
Item	Vegetation
Looking downstream (south) at dense vegetation on landside slope and toe.	
richard_s_20110304_437.jpg	



Levee Mile Report Line	36
Start Levee Mile	1.60
End Levee Mile	1.67
Location	Water Side
Category	Earthen Levee
Item	Trim / Thin Trees
Looking south at dense trees on waterside slope.	
richard_s_20110304_426.jpg	



<p>* Location</p> <p>LS : Landside WS : Waterside CR : Crown</p>	<p>** Rating</p> <p>A : Acceptable M : Minimally Acceptable U : Unacceptable</p>	<p>PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected/Rated</p>	<p>C : Corrected W : Watch/Monitor</p>
---------------------------------------------------------------------------------	-------------------------------------------------------------------------------------------------	-----------------------------------------------------------------------------------------------	--------------------------------------------

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2011

Reclamation District No. 0765 Glide

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	1.74	03/03/2011 03/03/2011	Richard Willoughby

Levee Mile Report Line	36
Start Levee Mile	1.60
End Levee Mile	1.67
Location	Water Side
Category	Earthen Levee
Item	Trim / Thin Trees
Looking east at dense vegetation on waterside slope.	
richard_s_20110304_427.jpg	



Levee Mile Report Line	38
Start Levee Mile	1.69
End Levee Mile	1.69
Location	Water Side
Category	Earthen Levee
Item	Encroachments
Looking northeast at garbage on waterside slope.	
richard_s_20110304_425.jpg	



Levee Mile Report Line	39
Start Levee Mile	1.70
End Levee Mile	1.70
Location	Water Side
Category	Earthen Levee
Item	Encroachments
Looking southeast at pruning piles on waterside shoulder & slope.	
richard_s_20110304_424.jpg	



* Location LS : Landside WS : Waterside CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected/Rated	C : Corrected W : Watch/Monitor
--------------------------------------------------------------------	------------------------------------------------------------------------------------	--------------------------------------------------------------------------------------	------------------------------------

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2011

Reclamation District No. 0765 Glide

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	1.74	03/03/2011 03/03/2011	Richard Willoughby

Levee Mile Report Line	40
Start Levee Mile	1.70
End Levee Mile	1.73
Location	Water Side
Category	Earthen Levee
Item	Trim / Thin Trees
Looking upstream (north) at trees on waterside slope.	
richard_s_20110215_296.jpg	



Levee Mile Report Line	40
Start Levee Mile	1.70
End Levee Mile	1.73
Location	Water Side
Category	Earthen Levee
Item	Trim / Thin Trees
Looking east at trees on waterside slope.	
richard_s_20110215_297.jpg	



* Location LS : Landside WS : Waterside CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected/Rated	C : Corrected W : Watch/Monitor
--------------------------------------------------------------------	------------------------------------------------------------------------------------	--------------------------------------------------------------------------------------	------------------------------------