

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2014

Reclamation District No. 0765 Glide

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	1.72	10/27/2014 10/27/2014	Richard Willoughby

LM Start		Rating **	M	Issue No.	18		
LM End		Issue Type +	Ma	Location *	N/A		
Category	Earthen Levee			GPS Latitude/Longitude			
				Start		End	
Item	Emergency Supplies & Equipment				°		°
					°		°
DWR ID	DWR_RD0765_01_s_2013_18						
Action/Comments							
Inspector Comments: The LMA did not have an adequate supply of flood fight materials.							

No Photos

LM Start		Rating **	A	Issue No.	44
LM End		Issue Type +	Ma	Location *	N/A
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Operations & Maintenance Manuals				°
					°
DWR ID	DWR_RD0765_01_s_2012_44				
Action/Comments					
Inspector Comments: LMA has copy of O&M manual on file in office.					

No Photos

LM Start		Rating **	M	Issue No.	46
LM End		Issue Type +	Ma	Location *	N/A
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Flood Preparedness & Training				°
					°
DWR ID	DWR_RD0765_01_s_2012_46				
Action/Comments					
Inspector Comments: LMA does not have a written flood preparedness plan. Also LMA staff has not been involved in flood training for several years.					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

Reclamation District No. 0765 Glide

Reclamation District No. 0765 Glide

Photo 2 of 2 : FA_2014_RD0765_211_28_20141020_00037.jpg

A large, leafless tree with a thick trunk and many bare branches stands in a lush green field. The tree is the central focus, with its branches spreading out in various directions. The field is covered in tall, vibrant green grass. In the background, a line of trees and a small building with a red roof are visible under a clear blue sky.

No Photos

Photo 1 of 1 : FA_2014_RD0765_211_22_20141020_00033.jpg

A photograph showing a grassy embankment or roadside area. In the foreground, there is a patch of green grass and some gravel. Behind the grass, there is a dense thicket of bare, brown shrubs and trees. The background shows a clear blue sky and a few more trees. A utility pole is visible on the right side of the image.

* Location	** Rating	+ Issue Type
LS : Land Side N/A : Not Applicable	A : Acceptable N : Not Inspected/Rated	Ma : Maintenance Deficiency
WS : Water Side	M : Minimally Acceptable C : Corrected	Ob : Design & System Obsolescence
CR : Crown	U : Unacceptable A/W : Acceptable but Monitor & Maintain	En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2014

Reclamation District No. 0765 Glide

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	1.72	10/27/2014 10/27/2014	Richard Willoughby

LM Start	0.19	Rating **	M	Issue No.	14
LM End	0.35	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			38.500343 °	38.498032 °
				-121.560507 °	-121.560337 °
DWR ID	DWR_RD0765_01_s_2012_14				
Action/Comments					
Trim trees to at least five feet above ground level.					

No Photos

LM Start	0.21	Rating **	A/W	Issue No.	25
LM End	0.21	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			38.500018 °	38.500018 °
				-121.560457 °	-121.560457 °
DWR ID	DWR_RD0765_01_s_2012_25				
Action/Comments					
Trim trees to at least five feet above ground level.					

No Photos

LM Start	0.24	Rating **	M	Issue No.	49
LM End	0.24	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.499530 °	38.499530 °
				-121.560490 °	-121.560490 °
DWR ID	DWR_RD0765_01_s_2013_49				
Action/Comments					
Remove the wild growth other than native grasses from the levee slopes.					
Inspector Comments: Wild berryvines on landside slope.					

Photo 1 of 1 : FA_2014_RD0765_211_49_20141020_00057.jpg



Looking at wild berryvines or wild roses on landside slope and toe.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2014

Reclamation District No. 0765 Glide

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	1.72	10/27/2014 10/27/2014	Richard Willoughby

LM Start	0.25	Rating **	A/W	Issue No.	11
LM End	0.28	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			38.499405 °	38.499042 °
				-121.560445 °	-121.560430 °
DWR ID	DWR_RD0765_01_s_2012_11				
Action/Comments					
Thin trees to allow visibility of the ground and room to flood fight.					

Photo 1 of 5 : FA_2014_RD0765_211_11_20141020_00015.jpg



Looking northeast at overgrown trees on waterside slope.

LM Start	0.25	Rating **	A/W	Issue No.	11 (cont)
LM End	0.28	Issue Type +	Ma	Location *	WS

Photo 2 of 5 : FA_2014_RD0765_211_11_20141020_00016.jpg



Looking north at dense trees on waterside slope from fall 2010 inspection.

LM Start	0.25	Rating **	A/W	Issue No.	11 (cont)
LM End	0.28	Issue Type +	Ma	Location *	WS

Photo 3 of 5 : FA_2014_RD0765_211_11_20141020_00017.jpg



Looking south (downstream) at dense trees on landside slope and shoulder. (Spring 2013)

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable N : Not Inspected/Rated M : Minimally Acceptable C : Corrected U : Unacceptable A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement	
--	--	---	--	---	--

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2014

Reclamation District No. 0765 Glide

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	1.72	10/27/2014 10/27/2014	Richard Willoughby

LM Start	0.25	Rating **	A/W	Issue No.	11 (cont)	
LM End	0.28	Issue Type +	Ma	Location *	WS	
Category	Earthen Levee			GPS Latitude/Longitude		
				Start		End
Item	Trim / Thin Trees			38.499405 °		38.499042 °
				-121.560445 °		-121.560430 °
DWR ID	DWR_RD0765_01_s_2012_11					
Action/Comments						
Thin trees to allow visibility of the ground and room to flood fight.						

Photo 4 of 5 : FA_2014_RD0765_211_11_20141020_00018.jpg



Looking north (upstream) at dense trees on landside slope and shoulder. (Spring 2013)

LM Start	0.25	Rating **	A/W	Issue No.	11 (cont)
LM End	0.28	Issue Type +	Ma	Location *	WS

Photo 5 of 5 : FA_2014_RD0765_211_11_20141020_00019.jpg



Looking upstream (north) at dense vegetation and trees from 2011 spring inspection.

LM Start	0.31	Rating **	A/W	Issue No.	31
LM End	0.31	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.498516 °	38.498516 °
				-121.560463 °	-121.560463 °
DWR ID	DWR_RD0765_01_f_2012_31				
Action/Comments					
Remove the wild growth other than native grasses from the levee slopes.					
Inspector Comments: Wild berryvines on landside toe.					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable N : Not Inspected/Rated M : Minimally Acceptable C : Corrected U : Unacceptable A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

Reclamation District No. 0765 Glide

Looking north (upstream) at untrimmed trees on waterside shoulder and slope.

No Photos

Looking north (upstream) at untrimmed trees on waterward slope.

Page 7 of 30

Reclamation District No. 0765 Glide

Page 8 of 30

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2014

Reclamation District No. 0765 Glide

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	1.72	10/27/2014 10/27/2014	Richard Willoughby

LM Start	0.47	Rating **	A/W	Issue No.	55 (cont)
LM End	0.47	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			38.496235 °	38.496235 °
				-121.559796 °	-121.559796 °
DWR ID	DWR_RD0765_01_f_2013_55				
Action/Comments					
Garbage					
Inspector Comments: Trash dumped on landside slope.					

Photo 2 of 2 : FA_2014_RD0765_211_55_20141020_00064.jpg



Looking west at garbage on landside slope.

LM Start	0.48	Rating **	M	Issue No.	33
LM End	0.50	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.496217 °	38.495855 °
				-121.559788 °	-121.559586 °
DWR ID	DWR_RD0765_01_s_2012_33				
Action/Comments					
Remove the wild growth other than native grasses from the levee slopes.					
Inspector Comments: District removed some of the wild growth on landside slope and toe.					

Photo 1 of 5 : FA_2014_RD0765_211_33_20141020_00044.jpg



Looking northwest at trees on landside toe from 2010 fall inspection.

LM Start	0.48	Rating **	M	Issue No.	33 (cont)
LM End	0.50	Issue Type +	Ma	Location *	LS

Photo 2 of 5 : FA_2014_RD0765_211_33_20141020_00045.jpg



Looking downstream (south) at trees on landside slope & toe.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable N : Not Inspected/Rated M : Minimally Acceptable C : Corrected U : Unacceptable A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement	
--	--	---	--	---	--

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2014

Reclamation District No. 0765 Glide

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	1.72	10/27/2014 10/27/2014	Richard Willoughby

LM Start	0.48	Rating **	M	Issue No.	33 (cont)
LM End	0.50	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.496217 °	38.495855 °
				-121.559788 °	-121.559586 °
DWR ID	DWR_RD0765_01_s_2012_33				
Action/Comments					
Remove the wild growth other than native grasses from the levee slopes.					
Inspector Comments: District removed some of the wild growth on landside slope and toe.					

LM Start	0.48	Rating **	M	Issue No.	33 (cont)
LM End	0.50	Issue Type +	Ma	Location *	LS

LM Start	0.48	Rating **	M	Issue No.	33 (cont)
LM End	0.50	Issue Type +	Ma	Location *	LS

Photo 3 of 5 : FA_2014_RD0765_211_33_20141020_00046.jpg



Looking southwest at dense vegetation on landside slope and toe.

Photo 4 of 5 : FA_2014_RD0765_211_33_20141020_00047.jpg



Looking upstream (northwest) at dense vegetation on landside slope.

Photo 5 of 5 : FA_2014_RD0765_211_33_20141020_00048.jpg



Looking downstream (southwest) at dense vegetation on landside slope.

*** Location**

LS : Land Side N/A : Not Applicable
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable N : Not Inspected/Rated
M : Minimally Acceptable C : Corrected
U : Unacceptable A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2014

Reclamation District No. 0765 Glide

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	1.72	10/27/2014 10/27/2014	Richard Willoughby

LM Start	0.54	Rating **	A/W	Issue No.	34
LM End	0.64	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			38.495347 °	38.494204 °
				-121.559291 °	-121.558313 °
DWR ID	DWR_RD0765_01_s_2012_34				
Action/Comments					
Trim trees to at least five feet above ground level.					

No Photos

LM Start	0.57	Rating **	A/W	Issue No.	10
LM End	0.60	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			38.495035 °	38.494642 °
				-121.559027 °	-121.558697 °
DWR ID	DWR_RD0765_01_s_2012_10				
Action/Comments					
Trim trees to at least five feet above ground level.					

No Photos

LM Start	0.69	Rating **	A/W	Issue No.	35
LM End	0.73	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			38.493596 °	38.493077 °
				-121.557832 °	-121.557451 °
DWR ID	DWR_RD0765_01_s_2012_35				
Action/Comments					
Trim trees to at least five feet above ground level.					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2014

Reclamation District No. 0765 Glide

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	1.72	10/27/2014 10/27/2014	Richard Willoughby

LM Start	0.71	Rating **	A/W	Issue No.	15
LM End	0.71	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			38.493392 °	38.494171 °
				-121.557640 °	-121.558253 °
DWR ID	DWR_RD0765_01_s_2012_15				
Action/Comments					
Trim trees to at least five feet above ground level.					

No Photos

LM Start	0.76	Rating **	M	Issue No.	50
LM End	0.80	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.492713 °	38.492176 °
				-121.557224 °	-121.556893 °
DWR ID	DWR_RD0765_01_s_2013_50				
Action/Comments					
Remove the wild growth other than native grasses from the levee slopes.					

Photo 1 of 1 : FA_2014_RD0765_211_50_20141020_00058.jpg



Looking northwest at vegetation on landside slope.

LM Start	0.78	Rating **	A/W	Issue No.	36
LM End	0.81	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			38.492392 °	38.492034 °
				-121.557026 °	-121.556820 °
DWR ID	DWR_RD0765_01_s_2012_36				
Action/Comments					
Trim and thin trees to allow visibility of the ground and room to flood fight.					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2014

Reclamation District No. 0765 Glide

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	1.72	10/27/2014 10/27/2014	Richard Willoughby

LM Start	0.87	Rating **	A/W	Issue No.	17
LM End	0.99	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			38.491283 °	38.489771 °
				-121.556360 °	-121.555451 °
DWR ID	DWR_RD0765_01_s_2012_17				
Action/Comments					
Trim trees to at least five feet above ground level.					

LM Start	0.87	Rating **	A/W	Issue No.	17 (cont)
LM End	0.99	Issue Type +	Ma	Location *	LS

LM Start	0.87	Rating **	A/W	Issue No.	17 (cont)
LM End	0.99	Issue Type +	Ma	Location *	LS

Photo 1 of 6 : FA_2014_RD0765_211_17_20141020_00024.jpg



Looking downstream (south) at dense trees on landside slope and toe.

Photo 2 of 6 : FA_2014_RD0765_211_17_20141020_00025.jpg



Looking upstream (north) at dense trees on landside slope and toe.

Photo 3 of 6 : FA_2014_RD0765_211_17_20141020_00026.jpg



Looking south at trimmed trees and vegetation on landside slope and toe.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	--	---

Reclamation District No. 0765 Glide

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	1.72	10/27/2014 10/27/2014	Richard Willoughby

LM Start	0.87	Rating **	A/W	Issue No.	17 (cont)
LM End	0.99	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			38.491283 °	38.489771 °
				-121.556360 °	-121.555451 °
DWR ID	DWR_RD0765_01_s_2012_17				
Action/Comments					
Trim trees to at least five feet above ground level.					

LM Start	0.87	Rating **	A/W	Issue No.	17 (cont)
LM End	0.99	Issue Type +	Ma	Location *	LS

LM Start	0.87	Rating **	A/W	Issue No.	17 (cont)
LM End	0.99	Issue Type +	Ma	Location *	LS

Looking southwest at dense trees on landside slope and toe spring 2012.

Looking southwest at dense vegetation on landward slope.

A photograph showing a paved road that curves to the right. The road is bordered on the right by a dense line of green trees and bushes. On the left side of the road, a white car is visible in the distance. The sky is blue with some clouds.

Looking south at dense trees on landside shoulder and slope.
(November 2011)

* Location	** Rating	+ Issue Type
LS : Land Side N/A : Not Applicable	A : Acceptable N : Not Inspected/Rated	Ma : Maintenance Deficiency
WS : Water Side	M : Minimally Acceptable C : Corrected	Ob : Design & System Obsolescence
CR : Crown	U : Unacceptable A/W : Acceptable but Monitor & Maintain	En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**


Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2014

Reclamation District No. 0765 Glide

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	1.72	10/27/2014 10/27/2014	Richard Willoughby

LM Start	0.97	Rating **	M	Issue No.	81
LM End	0.97	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.489962 °	38.489962 °
				-121.555573 °	-121.555573 °
DWR ID	DWR_RD0765_01_s_2012_81				
Action/Comments					
Remove the wild growth other than native grasses from the levee slopes.					
Inspector Comments: Dense berryvines on landside slope.					

Photo 1 of 5 : FA_2014_RD0765_211_81_20141020_00069.jpg



Looking west at dense berryvines and wildroses on landside shoulder and slope. (November 2011)

LM Start	0.97	Rating **	M	Issue No.	81 (cont)
LM End	0.97	Issue Type +	Ma	Location *	LS

Photo 2 of 5 : FA_2014_RD0765_211_81_20141020_00070.jpg



Looking northwest at vines on landside toe spring 2012.

LM Start	0.97	Rating **	M	Issue No.	81 (cont)
LM End	0.97	Issue Type +	Ma	Location *	LS

Photo 3 of 5 : FA_2014_RD0765_211_81_20141020_00071.jpg



Looking northwest at trimmed trees and vegetation on landside slope and toe.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	--	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2014

Reclamation District No. 0765 Glide

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	1.72	10/27/2014 10/27/2014	Richard Willoughby

LM Start	0.97	Rating **	M	Issue No.	81 (cont)	
LM End	0.97	Issue Type +	Ma	Location *	LS	
Category	Earthen Levee			GPS Latitude/Longitude		
				Start		End
Item	Vegetation			38.489962 °		38.489962 °
				-121.555573 °		-121.555573 °
DWR ID	DWR_RD0765_01_s_2012_81					
Action/Comments						
Remove the wild growth other than native grasses from the levee slopes.						
Inspector Comments: Dense berryvines on landside slope.						

Photo 4 of 5 : FA_2014_RD0765_211_81_20141020_00072.jpg



Looking southwest at trimmed trees and vegetation on landside slope and toe.

LM Start	0.97	Rating **	M	Issue No.	81 (cont)
LM End	0.97	Issue Type +	Ma	Location *	LS

Photo 5 of 5 : FA_2014_RD0765_211_81_20141020_00073.jpg



Looking west at trimmed trees on landward slope.

LM Start	0.99	Rating **	A/W	Issue No.	6
LM End	1.15	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			38.489664 °	38.487617 °
				-121.555370 °	-121.554200 °
DWR ID	DWR_RD0765_01_f_2012_6				
Action/Comments					
Trim trees to at least five feet above ground level.					

Photo 1 of 2 : FA_2014_RD0765_211_6_20141020_00007.jpg



Looking south (downstream) at untrimmed trees on waterward slope.

*** Location**

LS : Land Side N/A : Not Applicable
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable N : Not Inspected/Rated
M : Minimally Acceptable C : Corrected
U : Unacceptable A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2014

Reclamation District No. 0765 Glide

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	1.72	10/27/2014 10/27/2014	Richard Willoughby

LM Start	0.99	Rating **	A/W	Issue No.	6 (cont)	
LM End	1.15	Issue Type +	Ma	Location *	WS	
Category	Earthen Levee			GPS Latitude/Longitude		
				Start		End
Item	Trim / Thin Trees			38.489664 °	38.487617 °	
				-121.555370 °	-121.554200 °	
DWR ID	DWR_RD0765_01_f_2012_6					
Action/Comments						
Trim trees to at least five feet above ground level.						

Photo 2 of 2 : FA_2014_RD0765_211_6_20141020_00008.jpg



Looking north (upstream) at untrimmed trees on waterward slope.

LM Start	1.02	Rating **	A/W	Issue No.	40
LM End	1.02	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.489283 °	38.489283 °
				-121.555223 °	-121.555223 °
DWR ID	DWR_RD0765_01_s_2012_40				
Action/Comments					
Trees / Woody Vegetation					
Inspector Comments: Fig trees on landside slope					

Photo 1 of 1 : FA_2014_RD0765_211_40_20141020_00053.jpg



Looking southwest at fig trees and other trees on landside slope and toe.

LM Start	1.05	Rating **	M	Issue No.	58
LM End	1.05	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			38.488903 °	38.488903 °
				-121.554921 °	-121.554921 °
DWR ID	DWR_RD0765_01_f_2014_58				
Action/Comments					
Prunings					
Inspector Comments: Prunings on waterward shoulder.					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2014

Reclamation District No. 0765 Glide

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	1.72	10/27/2014 10/27/2014	Richard Willoughby

LM Start	1.08	Rating **	A/W	Issue No.	37
LM End	1.08	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			38.488503 °	38.488503 °
				-121.554757 °	-121.554757 °
DWR ID	DWR_RD0765_01_s_2012_37				
Action/Comments					
Trim and thin trees to allow visibility of the ground and room to flood fight.					

Photo 1 of 4 : FA_2014_RD0765_211_37_20141020_00049.jpg



Looking downstream (south) at trees on landside slope & toe from 2010 fall inspection.

LM Start	1.08	Rating **	A/W	Issue No.	37 (cont)
LM End	1.08	Issue Type +	Ma	Location *	LS

Photo 2 of 4 : FA_2014_RD0765_211_37_20141020_00050.jpg



Looking southwest at trees on landward slope.

LM Start	1.08	Rating **	A/W	Issue No.	37 (cont)
LM End	1.08	Issue Type +	Ma	Location *	LS

Photo 3 of 4 : FA_2014_RD0765_211_37_20141020_00051.jpg



Looking downstream (southwest) at dense trees on landside slope and toe.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable N : Not Inspected/Rated M : Minimally Acceptable C : Corrected U : Unacceptable A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement	
--	--	---	--	---	--

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2014

Reclamation District No. 0765 Glide

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	1.72	10/27/2014 10/27/2014	Richard Willoughby

LM Start	1.08	Rating **	A/W	Issue No.	37 (cont)
LM End	1.08	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			38.488503 °	38.488503 °
				-121.554757 °	-121.554757 °
DWR ID	DWR_RD0765_01_s_2012_37				
Action/Comments					
Trim and thin trees to allow visibility of the ground and room to flood fight.					

Photo 4 of 4 : FA_2014_RD0765_211_37_20141020_00052.jpg



Looking west at trees on landside slope & toe.

LM Start	1.10	Rating **	M	Issue No.	38
LM End	1.16	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			38.488279 °	38.487465 °
				-121.554615 °	-121.554117 °
DWR ID	DWR_RD0765_01_s_2012_38				
Action/Comments					
Trim trees to at least five feet above ground level.					

No Photos

LM Start	1.15	Rating **	A/W	Issue No.	48
LM End	1.15	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.487645 °	38.487645 °
				-121.554233 °	-121.554233 °
DWR ID	DWR_RD0765_01_f_2012_48				
Action/Comments					
Remove the wild growth other than native grasses from the levee slopes.					
Inspector Comments: Wild berryvines at landside toe.					

Photo 1 of 1 : FA_2014_RD0765_211_48_20141020_00056.jpg



Looking southwest at dense vegetation on landside slope and toe.

*** Location**

LS : Land Side N/A : Not Applicable
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable N : Not Inspected/Rated
M : Minimally Acceptable C : Corrected
U : Unacceptable A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2014

Reclamation District No. 0765 Glide

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	1.72	10/27/2014 10/27/2014	Richard Willoughby

LM Start	1.16	Rating **	A/W	Issue No.	9
LM End	1.16	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			38.487473 °	38.487473 °
				-121.554080 °	-121.554080 °
DWR ID	DWR_RD0765_01_s_2012_9				
Action/Comments					
Trim trees to at least five feet above ground level.					

No Photos

LM Start	1.31	Rating **	M	Issue No.	26
LM End	1.31	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			38.485561 °	38.485561 °
				-121.553031 °	-121.553031 °
DWR ID	DWR_RD0765_01_s_2012_26				
Action/Comments					
Trim trees to at least five feet above ground level.					

No Photos

LM Start	1.36	Rating **	A/W	Issue No.	7
LM End	1.36	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.484877 °	38.484877 °
				-121.552540 °	-121.552540 °
DWR ID	DWR_RD0765_01_s_2012_7				
Action/Comments					
Remove the wild growth other than native grasses from the levee slopes.					

Photo 1 of 2 : FA_2014_RD0765_211_7_20141020_00009.jpg



Looking southeast at dense vegetation on waterside slope. (Fall Inspection 2012)

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable N : Not Inspected/Rated M : Minimally Acceptable C : Corrected U : Unacceptable A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2014

Reclamation District No. 0765 Glide

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	1.72	10/27/2014 10/27/2014	Richard Willoughby

LM Start	1.36	Rating **	A/W	Issue No.	7 (cont)	
LM End	1.36	Issue Type +	Ma	Location *	WS	
Category	Earthen Levee			GPS Latitude/Longitude		
				Start		End
Item	Vegetation			38.484877 °		38.484877 °
				-121.552540 °		-121.552540 °
DWR ID	DWR_RD0765_01_s_2012_7					
Action/Comments						
Remove the wild growth other than native grasses from the levee slopes.						

Photo 2 of 2 : FA_2014_RD0765_211_7_20141020_00010.jpg



Looking upstream (north) at dense vegetation on waterside slope.

LM Start	1.41	Rating **	A/W	Issue No.	4
LM End	1.41	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			38.484316 °	38.484316 °
				-121.552115 °	-121.552115 °
DWR ID	DWR_RD0765_01_s_2012_4				
Action/Comments					
Trim trees to at least five feet above ground level.					


Photo 1 of 1 : FA_2014_RD0765_211_4_20141020_00004.jpg



Looking north at untrimmed trees on waterward slope.

LM Start	1.44	Rating **	A/W	Issue No.	5
LM End	1.47	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			38.483925 °	38.483530 °
				-121.551845 °	-121.551587 °
DWR ID	DWR_RD0765_01_s_2012_5				
Action/Comments					
Thin trees to allow visibility of the ground and room to flood fight.					

Photo 1 of 2 : FA_2014_RD0765_211_5_20141020_00005.jpg



Looking north at dense vegetation on waterside slope. (Fall Inspection 2012)

*** Location**

LS : Land Side N/A : Not Applicable
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable N : Not Inspected/Rated
M : Minimally Acceptable C : Corrected
U : Unacceptable A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2014

Reclamation District No. 0765 Glide

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	1.72	10/27/2014 10/27/2014	Richard Willoughby

LM Start	1.44	Rating **	A/W	Issue No.	5 (cont)	
LM End	1.47	Issue Type +	Ma	Location *	WS	
Category	Earthen Levee			GPS Latitude/Longitude		
				Start		End
Item	Trim / Thin Trees			38.483925 °		38.483530 °
				-121.551845 °		-121.551587 °
DWR ID	DWR_RD0765_01_s_2012_5					
Action/Comments						
Thin trees to allow visibility of the ground and room to flood fight.						

Photo 2 of 2 : FA_2014_RD0765_211_5_20141020_00006.jpg



Looking upstream (north) at dense trees on waterside slope.

LM Start	1.46	Rating **	A/W	Issue No.	41
LM End	1.46	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			38.483640 °	38.483640 °
				-121.551727 °	-121.551727 °
DWR ID	DWR_RD0765_01_s_2012_41				
Action/Comments					
Trim trees to at least five feet above ground level.					

No Photos

LM Start	1.48	Rating **	C	Issue No.	19
LM End	1.48	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Slope Stability			38.483353 °	38.483353 °
				-121.551457 °	-121.551457 °
DWR ID	DWR_RD0765_01_f_2013_19				
Action/Comments					
Repair the levee slope damaged by vehicle traffic and prevent access where possible.					
Inspector Comments: Slope damage caused by tractor.					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable N : Not Inspected/Rated M : Minimally Acceptable C : Corrected U : Unacceptable A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2014

Reclamation District No. 0765 Glide

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	1.72	10/27/2014 10/27/2014	Richard Willoughby

LM Start	1.50	Rating **	A/W	Issue No.	42
LM End	1.51	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			38.483170 °	38.482965 °
				-121.551367 °	-121.551265 °
DWR ID	DWR_RD0765_01_s_2012_42				
Action/Comments					
Trim trees to at least five feet above ground level.					

No Photos

LM Start	1.52	Rating **	A/W	Issue No.	1
LM End	1.73	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.482893 °	38.480257 °
				-121.551121 °	-121.549458 °
DWR ID	DWR_RD0765_01_s_2012_1				
Action/Comments					
Remove the wild growth other than native grasses from the levee slopes.					

Photo 1 of 2 : FA_2014_RD0765_211_1_20141020_00001.jpg



Looking north at vegetation on waterward slope.

LM Start	1.52	Rating **	A/W	Issue No.	1 (cont)
LM End	1.73	Issue Type +	Ma	Location *	WS

Photo 2 of 2 : FA_2014_RD0765_211_1_20141020_00002.jpg



Looking southeast at vegetation on waterward slope.

*** Location**

LS : Land Side N/A : Not Applicable
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable N : Not Inspected/Rated
M : Minimally Acceptable C : Corrected
U : Unacceptable A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

Reclamation District No. 0765 Glide

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	1.72	10/27/2014 10/27/2014	Richard Willoughby

LM Start	1.54	Rating **	M	Issue No.	29 (cont)
LM End	1.64	Issue Type +	Ma	Location *	N/A
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.482665 °	38.481421 °
				-121.551036 °	-121.550207 °
DWR ID	DWR_RD0765_01_s _ 2012_29				
Action/Comments					
Remove the wild growth other than native grasses from the levee slopes.					
Inspector Comments: Dense berryvines and dense trees on landward slope. The LMA removed a sizeable amount of vines, but some still remain.					

LM Start	1.54	Rating **	M	Issue No.	29 (cont)
LM End	1.64	Issue Type +	Ma	Location *	N/A

A photograph of a roadside area. On the left is a paved road with a white line. To the right of the road is a grassy shoulder with some dry brush. A utility pole with a meter is visible. In the background, there is a field and trees under an overcast sky.

LM Start	1.54	Rating **	M	Issue No.	29 (cont)
LM End	1.64	Issue Type +	Ma	Location *	N/A

Looking southwest at vegetation on landside slope.

* Location	** Rating	+ Issue Type
LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	A : Acceptable N : Not Inspected/Rated M : Minimally Acceptable C : Corrected U : Unacceptable A/W : Acceptable but Monitor & Maintain	Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2014

Reclamation District No. 0765 Glide

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	1.72	10/27/2014 10/27/2014	Richard Willoughby

LM Start	1.56	Rating **	C	Issue No.	59
LM End	1.56	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			38.482402 °	38.482402 °
				-121.550867 °	-121.550867 °
DWR ID	DWR_RD0765_01_f_2013_59				
Action/Comments					
Prunings					

No Photos

LM Start	1.56	Rating **	C	Issue No.	8
LM End	1.56	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Erosion / Bank Caving			38.482414 °	38.482414 °
				-121.550804 °	-121.550804 °
DWR ID	DWR_RD0765_01_f_2013_8				
Action/Comments					
Schedule repair of erosion site prior to the next inspection. Inspector Comments: Erosion located around metal walkway on waterward shoulder and slope.					

No Photos

LM Start	1.57	Rating **	C	Issue No.	62
LM End	1.57	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments				°
					°
DWR ID	DWR_RD0765_01_s_2014_62				
Action/Comments					
Garbage					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

Reclamation District No. 0765 Glide

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2014

Reclamation District No. 0765 Glide

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	1.72	10/27/2014 10/27/2014	Richard Willoughby

LM Start	1.71	Rating **	A/W	Issue No.	52 (cont)
LM End	1.72	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			38.480519 °	38.480164 °
				-121.549513 °	-121.549445 °
DWR ID	DWR_RD0765_01_s_2013_52				
Action/Comments					
Trim trees to at least five feet above ground level.					

Photo 2 of 2 : FA_2014_RD0765_211_52_20141020_00060.jpg



Looking north (upstream) at dense trees on landside slope.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---