

**Flood Control Project Maintenance
Levee Inspections**

Fall 2008 Levee Maintenance Deficiency Summary Report

Overall LMA & Unit Ratings, including Boat Survey Erosion

Sacramento River Basin

RD0784	Overall LMA Rating	Total LMA Miles				
Reclamation District No. 0784	A	35.20				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments PO Miles CO Miles	
Vegetation	0.71		0.71	2.02%		
Encroachments					0.44	0.01
Erosion / Bank Caving	0.03		0.03	0.09%		
<i>LMA Totals:</i>	0.74	0.00	0.74	2.10%	0.44	0.01
Unit No. 01 Yuba River	Overall Unit Rating	Total Unit Miles				
	A	2.20				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments PO Miles CO Miles	
Encroachments					0.02	
<i>Unit Totals:</i>	0.00	0.00	0.00	0.00%	0.02	0.00
Unit No. 02 Feather River	Overall Unit Rating	Total Unit Miles				
	A	13.60				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments PO Miles CO Miles	
Encroachments					0.28	0.01
<i>Unit Totals:</i>	0.00	0.00	0.00	0.00%	0.28	0.01
Unit No. 03 Bear River	Overall Unit Rating	Total Unit Miles				
	A	4.70				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments PO Miles CO Miles	
Encroachments					0.01	
<i>Unit Totals:</i>	0.00	0.00	0.00	0.00%	0.01	0.00
Unit No. 04 Interceptor Canal	Overall Unit Rating	Total Unit Miles				
	M	6.30				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments PO Miles CO Miles	
Vegetation	0.71		0.71	11.27%		
<i>Unit Totals:</i>	0.71	0.00	0.71	11.27%	0.00	0.00
Unit No. 05 Interceptor Canal	Overall Unit Rating	Total Unit Miles				
	A	4.20				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments PO Miles CO Miles	
Erosion / Bank Caving	0.01		0.01	0.24%		
<i>Unit Totals:</i>	0.01	0.00	0.01	0.24%	0.00	0.00
Unit No. 06 South Dry Creek	Overall Unit Rating	Total Unit Miles				
	A	0.30				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments PO Miles CO Miles	
No Items						
<i>Unit Totals:</i>	0.00	0.00	0.00	0.00%	0.00	0.00

**Flood Control Project Maintenance
Levee Inspections**

Fall 2008 Levee Maintenance Deficiency Summary Report

Overall LMA & Unit Ratings, including Boat Survey Erosion

Sacramento River Basin (cont.)

Unit No. 07 Yuba River	Overall Unit Rating	Total Unit Miles				
	A	3.90				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
Encroachments					0.13	
Erosion / Bank Caving	0.02		0.02	0.51%		
<i>Unit Totals:</i>	0.02	0.00	0.02	0.51%	0.13	0.00

Unit No. 08 Three Rivers	Overall Unit Rating	Total Unit Miles				
	A					
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
No Items						
<i>Unit Totals:</i>	0.00	0.00	0.00	0.00%	0.00	0.00

**Flood Control Project Maintenance
Levee Inspections**
LMA District Cover Sheet
Fall 2008 Levee Inspection Results

Reclamation District No. 0784

	Spring (March - May)	Summer ** (June - August)	Fall (September - November)	Winter ** (December - February)
* Overall LMA Rating (Fall Only)			A	

** Non-receipt of Summer or Winter Inspection Reports may effect overall annual rating.

* **SPRING INSPECTIONS:** Overall maintenance ratings are not determined for the spring inspection results. Individual maintenance deficiencies are rated using the same criteria in the spring and in the fall.

FALL INSPECTIONS: The overall maintenance rating shown above is based on operation and maintenance deficiencies identified within the attached unit inspection reports.

Comments

**Flood Control Project Maintenance
Levee Inspections
Unit Cover Sheet
Fall 2008 Levee Inspection Results
Reclamation District No. 0784**

Waterway		Bank	Unit Miles
Unit No. 01 Yuba River		Left	2.20

	Spring (March - May)	Summer (June - August)	Fall (September - November)	Winter (December - February)
Date of Inspection	4/3/2008		9/24/2008	
DWR Inspector	Clay Thomas		Clay Thomas	
Accompanied By				
Unit Maintenance Rating (Fall Only)			A	

Check one:

During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.

During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

Comments

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :
 DWR Summer/Winter Inspection Reports
 3310 El Camino Avenue, Room LL-30
 Sacramento, CA 95821-9000.

X _____
 Signature of LMA Representative Date

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2008

Reclamation District No. 0784

Waterway				Bank	Unit Miles	Inspection Date	Inspector
Unit No. 01 Yuba River				Left	2.20	09/24/2008	Clay Thomas

LMR Line	Levee Mile		Category	Item	* Location	** Rating	Action/Comment	GPS Latitude/Longitude		Photo	Issue
	Start	End						Start	End		
1	2.03	2.03	Earthen Levee	Encroachments	CR PO	Equipment	Inspector Comments: segment 3 levee repair in process	39.128159 °	39.128159 °		1
								-121.587086 °	-121.587086 °		
2	2.13	2.13	Earthen Levee	Encroachments	CR PO	Equipment	Inspector Comments: levee repair	39.127028 °	39.127028 °		2
								-121.588046 °	-121.588046 °		

<p>* Location</p> <p>LS : Land Side WS : Water Side CR : Crown</p>	<p>** Rating</p> <p>A : Acceptable M : Minimally Acceptable U : Unacceptable</p> <p>PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected</p>
---	---

**Flood Control Project Maintenance
Levee Inspections
Unit Cover Sheet
Fall 2008 Levee Inspection Results
Reclamation District No. 0784**

Waterway		Bank	Unit Miles
Unit No. 02 Feather River		Left	13.60

	Spring (March - May)	Summer (June - August)	Fall (September - November)	Winter (December - February)
Date of Inspection	4/8/2008		9/24/2008	
DWR Inspector	Clay Thomas		Clay Thomas	
Accompanied By				
Unit Maintenance Rating (Fall Only)			A	

Check one:

During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.

During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

Comments

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to : DWR Summer/Winter Inspection Reports
3310 El Camino Avenue, Room LL-30
Sacramento, CA 95821-9000.

X _____
Signature of LMA Representative Date

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2008

Reclamation District No. 0784

Waterway				Bank	Unit Miles	Inspection Date	Inspector
Unit No. 02 Feather River				Left	13.60	09/24/2008	Clay Thomas

LMR Line	Levee Mile		Category	Item	* Location	** Rating	Action/Comment	GPS Latitude/Longitude		Photo	Issue
	Start	End						Start	End		
1	0.00	0.00	Earthen Levee	Encroachments	CR	CO	Inspector Comments: This levee ends at approximate l/m 12.80, levee changed when set back levee was built.	°	°		5
2	2.16	2.44	Earthen Levee	Encroachments	CR	PO	Equipment Inspector Comments: levee in repair process	39.098473 ° -121.586031 °	39.094577 ° -121.584758 °		6
3	9.26	9.26	Earthen Levee	Encroachments	CR	A	Inspector Comments: levee repair in process, levee degraded for pipe installation, pipe in place	39.005863 ° -121.578064 °	39.005863 ° -121.578064 °		7

<p>* Location</p> <p>LS : Land Side WS : Water Side CR : Crown</p>	<p>** Rating</p> <p>A : Acceptable M : Minimally Acceptable U : Unacceptable</p> <p>PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected</p>
---	---

**Flood Control Project Maintenance
Levee Inspections
Unit Cover Sheet
Fall 2008 Levee Inspection Results
Reclamation District No. 0784**

Waterway		Bank	Unit Miles
Unit No. 03 Bear River		Right	4.70

	Spring (March - May)	Summer (June - August)	Fall (September - November)	Winter (December - February)
Date of Inspection	4/8/2008		9/24/2008	
DWR Inspector	Clay Thomas		Clay Thomas	
Accompanied By				
Unit Maintenance Rating (Fall Only)			A	

Check one:

During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.

During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

Comments

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :
 DWR Summer/Winter Inspection Reports
 3310 El Camino Avenue, Room LL-30
 Sacramento, CA 95821-9000.

X _____
 Signature of LMA Representative Date

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2008

Reclamation District No. 0784

Waterway			Bank	Unit Miles	Inspection Date	Inspector
Unit No. 03 Bear River			Right	4.70	09/24/2008	Clay Thomas

LMR Line	Levee Mile		Category	Item	* Location	** Rating	Action/Comment	GPS Latitude/Longitude		Photo	Issue
	Start	End						Start	End		
1	2.82	2.82	Earthen Levee	Encroachments	CR PO	Equipment	Inspector Comments: hwy 70 new bridge construction	38.974003 °	38.974003 °		4
								-121.541910 °	-121.541910 °		

<p>* Location</p> <p>LS : Land Side WS : Water Side CR : Crown</p>	<p>** Rating</p> <p>A : Acceptable M : Minimally Acceptable U : Unacceptable</p> <p>PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected</p>
---	---

**Flood Control Project Maintenance
Levee Inspections
Unit Cover Sheet
Fall 2008 Levee Inspection Results
Reclamation District No. 0784**

Waterway		Bank	Unit Miles
Unit No. 04 Interceptor Canal		Left	6.30

	Spring (March - May)	Summer (June - August)	Fall (September - November)	Winter (December - February)
Date of Inspection	4/9/2008		9/24/2008	
DWR Inspector	Clay Thomas		Clay Thomas	
Accompanied By				
Unit Maintenance Rating (Fall Only)			M	

Check one:

During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.

During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

Comments

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :
 DWR Summer/Winter Inspection Reports
 3310 El Camino Avenue, Room LL-30
 Sacramento, CA 95821-9000.

X _____
 Signature of LMA Representative Date

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2008

Reclamation District No. 0784

Waterway			Bank	Unit Miles	Inspection Date	Inspector
Unit No. 04 Interceptor Canal			Left	6.30	09/24/2008	Clay Thomas

LMR Line	Levee Mile		Category	Item	* Location	** Rating	Action/Comment	GPS Latitude/Longitude		Photo	Issue
	Start	End						Start	End		
1	4.88	5.59	Earthen Levee	Vegetation	LS	M	Control annual grass and weeds on the levee slopes and easements.	39.044807 °	39.055144 °		1
								-121.542415 °	-121.542506 °		

<p>* Location</p> <p>LS : Land Side WS : Water Side CR : Crown</p>	<p>** Rating</p> <p>A : Acceptable M : Minimally Acceptable U : Unacceptable</p> <p>PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected</p>
---	---

**Flood Control Project Maintenance
Levee Inspections
Unit Cover Sheet
Fall 2008 Levee Inspection Results
Reclamation District No. 0784**

Waterway		Bank	Unit Miles
Unit No. 05 Interceptor Canal		Left	4.20

	Spring (March - May)	Summer (June - August)	Fall (September - November)	Winter (December - February)
Date of Inspection	4/9/2008		9/24/2008	
DWR Inspector	Clay Thomas		Clay Thomas	
Accompanied By				
Unit Maintenance Rating (Fall Only)			A	

Check one:

During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.

During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

Comments

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :
 DWR Summer/Winter Inspection Reports
 3310 El Camino Avenue, Room LL-30
 Sacramento, CA 95821-9000.

X _____
 Signature of LMA Representative Date

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2008

Reclamation District No. 0784

Waterway			Bank	Unit Miles	Inspection Date	Inspector
Unit No. 05 Interceptor Canal			Left	4.20	09/24/2008	Clay Thomas

LMR Line	Levee Mile		Category	Item	* Location	** Rating	Action/Comment	GPS Latitude/Longitude		Photo	Issue
	Start	End						Start	End		
1	3.79	3.79	Earthen Levee	Erosion / Bank Caving	WS	M	Note and monitor erosion site.	39.019236 ° -121.516381 °	39.019236 ° -121.516381 °		6

<p>* Location</p> <p>LS : Land Side WS : Water Side CR : Crown</p>	<p>** Rating</p> <p>A : Acceptable M : Minimally Acceptable U : Unacceptable</p> <p>PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected</p>
---	---

**Flood Control Project Maintenance
Levee Inspections
Unit Cover Sheet
Fall 2008 Levee Inspection Results
Reclamation District No. 0784**

Waterway		Bank	Unit Miles
Unit No. 06 South Dry Creek		Right	0.30

	Spring (March - May)	Summer (June - August)	Fall (September - November)	Winter (December - February)
Date of Inspection	4/22/2008		9/24/2008	
DWR Inspector	Clay Thomas		Clay Thomas	
Accompanied By				
Unit Maintenance Rating (Fall Only)			A	

Check one:

During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.

During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

Comments

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :
 DWR Summer/Winter Inspection Reports
 3310 El Camino Avenue, Room LL-30
 Sacramento, CA 95821-9000.

X _____
 Signature of LMA Representative Date

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2008

Reclamation District No. 0784

Waterway			Bank	Unit Miles	Inspection Date	Inspector
Unit No. 06 South Dry Creek			Right	0.30	09/24/2008	Clay Thomas

LMR Line	Levee Mile		Category	Item	Location *	Rating **	Action/Comment	GPS Latitude/Longitude		Photo	Issue
	Start	End						Start	End		
1								°	°		
								°	°		

<p>* Location</p> <p>LS : Land Side WS : Water Side CR : Crown</p>	<p>** Rating</p> <p>A : Acceptable PO : Partially Obstructing M : Minimally Acceptable CO : Completely Obstructing U : Unacceptable N : Not Inspected</p>
---	---

**Flood Control Project Maintenance
Levee Inspections
Unit Cover Sheet
Fall 2008 Levee Inspection Results
Reclamation District No. 0784**

Waterway		Bank	Unit Miles
Unit No. 07 Yuba River		Left	3.90

	Spring (March - May)	Summer (June - August)	Fall (September - November)	Winter (December - February)
Date of Inspection	4/3/2008		9/24/2008	
DWR Inspector	Clay Thomas		Clay Thomas	
Accompanied By				
Unit Maintenance Rating (Fall Only)			A	

Check one:

During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.

During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

Comments

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :
 DWR Summer/Winter Inspection Reports
 3310 El Camino Avenue, Room LL-30
 Sacramento, CA 95821-9000.

X _____
 Signature of LMA Representative Date

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2008

Reclamation District No. 0784

Waterway				Bank	Unit Miles	Inspection Date	Inspector			
Unit No. 07 Yuba River				Left	3.90	09/24/2008	Clay Thomas			
LMR Line	Levee Mile		Category	Item	* Location	** Rating	GPS Latitude/Longitude		Photo	Issue
	Start	End					Start	End		
1	0.01	0.01	Earthen Levee	Encroachments	CR	A	39.134758 ° -121.552040 °	39.134758 ° -121.552040 °		8
Inspector Comments: this is 0.00 of unit 7.										
2	2.16	2.28	Earthen Levee	Encroachments	WS	PO	Equipment	° °	° °	3
3	2.79	2.79	Earthen Levee	Encroachments	CR	PO	Inspector Comments: l/m 1.79 to 3.91 is a patrol road, l/m 1.79 at locator mile 2.79	39.144676 ° -121.523826 °	39.144676 ° -121.523826 °	7
4	3.29	3.29	Earthen Levee	Erosion / Bank Caving	WS	M	Note and monitor erosion site. Inspector Comments: ck levee locator, l/m 3.30, tool has this as l/m 5.23, levee is 3.91 total	39.160679 ° -121.504872 °	39.160679 ° -121.504872 °	5
5	3.30	3.30	Earthen Levee	Erosion / Bank Caving	WS	M	Note and monitor erosion site.	° °	° °	4
6	3.52	3.52	Earthen Levee	Encroachments	WS	A	Inspector Comments: l/m 2.28, locator has it at 3.52	39.150060 ° -121.517740 °	39.150060 ° -121.517740 °	6

<p>* Location</p> <p>LS : Land Side WS : Water Side CR : Crown</p>	<p>** Rating</p> <p>A : Acceptable M : Minimally Acceptable U : Unacceptable</p> <p>PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected</p>
---	---

**Flood Control Project Maintenance
Levee Inspections
Unit Cover Sheet
Fall 2008 Levee Inspection Results
Reclamation District No. 0784**

Waterway		Bank	Unit Miles
Unit No. 08 Three Rivers			

	Spring (March - May)	Summer (June - August)	Fall (September - November)	Winter (December - February)
Date of Inspection	5/19/2008		9/24/2008	
DWR Inspector	Clay Thomas		Clay Thomas	
Accompanied By				
Unit Maintenance Rating (Fall Only)			A	

Check one:

During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.

During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

Comments

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :
 DWR Summer/Winter Inspection Reports
 3310 El Camino Avenue, Room LL-30
 Sacramento, CA 95821-9000.

X _____
 Signature of LMA Representative Date

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2008

Reclamation District No. 0784

Waterway				Bank	Unit Miles	Inspection Date	Inspector
Unit No. 08 Three Rivers						09/24/2008	Clay Thomas

LMR Line	Levee Mile		Category	Item	Location *	Rating **	Action/Comment	GPS Latitude/Longitude		Photo	Issue
	Start	End						Start	End		
1								o	o		
								o	o		

<p>* Location</p> <p>LS : Land Side WS : Water Side CR : Crown</p>	<p>** Rating</p> <p>A : Acceptable PO : Partially Obstructing M : Minimally Acceptable CO : Completely Obstructing U : Unacceptable N : Not Inspected</p>
---	---