

**Flood Control Project Maintenance
Levee Inspections**

Fall 2011 Levee Maintenance Deficiency Summary Report

Overall LMA & Unit Ratings, including USACE Erosion Survey

Sacramento River Basin

RD0784	Overall LMA Rating	Total LMA Miles				
Reclamation District No. 0784 Plumas Lake	A	44.16				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments PO Miles CO Miles	
<i>Earthen Levee</i>						
Vegetation	0.93		0.93	2.11%		
Encroachments					1.69	0.02
<i>Supplemental</i>						
USACE Erosion Survey	0.35		0.35	0.79%		
<i>LMA Totals:</i>	1.28	0.00	1.28	2.90%	1.69	0.02
Unit No. 01 Yuba River LB	Overall Unit Rating	Total Unit Miles				
RD0784	A	2.22				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments PO Miles CO Miles	
<i>Earthen Levee</i>						
Encroachments					0.08	
<i>Unit Totals:</i>	0.00	0.00	0.00	0.00%	0.08	0.00
Unit No. 02 Feather River LB	Overall Unit Rating	Total Unit Miles				
RD0784	A	13.64				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments PO Miles CO Miles	
<i>Earthen Levee</i>						
Encroachments						0.01
<i>Supplemental</i>						
USACE Erosion Survey	0.33		0.33	2.42%		
<i>Unit Totals:</i>	0.33	0.00	0.33	2.42%	0.00	0.01
Unit No. 03 Bear River RB	Overall Unit Rating	Total Unit Miles				
RD0784	A	4.73				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments PO Miles CO Miles	
<i>Earthen Levee</i>						
Encroachments					0.01	
<i>Supplemental</i>						
USACE Erosion Survey	0.01		0.01	0.21%		
<i>Unit Totals:</i>	0.01	0.00	0.01	0.21%	0.01	0.00
Unit No. 04 Interceptor Canal RB	Overall Unit Rating	Total Unit Miles				
RD0784	A	6.35				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments PO Miles CO Miles	
No Items						
<i>Unit Totals:</i>	0.00	0.00	0.00	0.00%	0.00	0.00

**Flood Control Project Maintenance
Levee Inspections**

Fall 2011 Levee Maintenance Deficiency Summary Report

Overall LMA & Unit Ratings, including USACE Erosion Survey

Sacramento River Basin (cont.)

Unit No. 05 Interceptor Canal LB		Overall Unit Rating	Total Unit Miles				
RD0784		U	4.20				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments		
					PO Miles	CO Miles	
<i>Earthen Levee</i>							
Vegetation	0.93		0.93	22.14%			
Encroachments					1.60		
<i>Unit Totals:</i>	0.93	0.00	0.93	22.14%	1.60	0.00	
Unit No. 06 South Dry Creek RB		Overall Unit Rating	Total Unit Miles				
RD0784		A	1.50				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments		
					PO Miles	CO Miles	
No Items							
<i>Unit Totals:</i>	0.00	0.00	0.00	0.00%	0.00	0.00	
Unit No. 07 Yuba River LB		Overall Unit Rating	Total Unit Miles				
RD0784		A	3.91				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments		
					PO Miles	CO Miles	
<i>Earthen Levee</i>							
Encroachments						0.01	
<i>Supplemental</i>							
USACE Erosion Survey	0.01		0.01	0.26%			
<i>Unit Totals:</i>	0.01	0.00	0.01	0.26%	0.00	0.01	
Unit No. 08 Three Rivers RB		Overall Unit Rating	Total Unit Miles				
RD0784		A	1.88				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments		
					PO Miles	CO Miles	
No Items							
<i>Unit Totals:</i>	0.00	0.00	0.00	0.00%	0.00	0.00	
Unit No. 09 Feather River, TRLIA Setback Levee LB		Overall Unit Rating	Total Unit Miles				
RD0784		A	5.73				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments		
					PO Miles	CO Miles	
No Items							
<i>Unit Totals:</i>	0.00	0.00	0.00	0.00%	0.00	0.00	

**Flood Control Project Maintenance
Levee Inspections
LMA District Cover Sheet
Fall 2011 Levee Inspection Results**

Reclamation District No. 0784 Plumas Lake

	Spring (March - May)	Summer ** (June - August)	Fall (September - November)	Winter ** (December - February)
* Overall LMA Rating (Fall Only)			A	

** Non-receipt of Summer or Winter Inspection Reports may effect overall annual rating.

* **SPRING INSPECTIONS:** Overall maintenance ratings are not determined for the spring inspection results. Individual maintenance deficiencies are rated using the same criteria in the spring and in the fall.

FALL INSPECTIONS: The overall maintenance rating shown above is based on operation and maintenance deficiencies identified within the attached unit inspection reports.

Comments

**Flood Control Project Maintenance
Levee Inspections**

Unit Cover Sheet

Fall 2011 Levee Inspection Results

Reclamation District No. 0784 Plumas Lake

Waterway	Bank	Unit Miles
Unit No. 01 Yuba River	Left	2.22

	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - February)
Unit Maintenance Rating (Fall Only)			A	
Date of Inspection	3/17/2011 - 3/17/2011		10/25/2011 - 10/26/2011	
DWR Inspector	Clay Thomas		Clay Thomas	
Accompanied By	Steve Fordice RD-784		Steve Fordice RD-784	

Check one:

During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.

During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

Comments

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :

DWR Summer/Winter Inspection Reports
3310 El Camino Avenue, Suite 200
Sacramento, CA 95821-9000

X _____ Date

Signature of LMA Representative

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2011

Reclamation District No. 0784 Plumas Lake

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Yuba River	Left	2.22	10/25/2011 10/26/2011	Clay Thomas

LMIR No.	Levee Mile		Category	Item	Location *	Rating **	Action/Comment	GPS Latitude/Longitude		Issue No. Photo
	Start	End						Start	End	
1	0.00	2.19	Earthen Levee	Vegetation	LS	A	Remove the wild growth other than native grasses from the levee slopes.	39.134555 ° -121.552577 °	39.126153 ° -121.588552 °	52 Y
2	0.00	2.19	Earthen Levee	Vegetation	WS	A	Remove the wild growth other than native grasses from the levee slopes.	39.134556 ° -121.552577 °	39.126152 ° -121.588551 °	53 Y
3	1.79	1.87	Earthen Levee	Encroachments	LS	PO	Landscaping	39.129849 ° -121.583793 °	39.129858 ° -121.585183 °	4

<p>* Location LS : Land Side WS : Water Side CR : Crown</p>	<p>** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable</p>	<p>PO : Partially Obstructing CO : Completely Obstructing W : Watch/Monitor</p>	<p>N : Not Inspected, see Inspector Comment C : Corrected</p>
---	---	---	--

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2011

Reclamation District No. 0784 Plumas Lake

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Yuba River	Left	2.22	10/25/2011 10/26/2011	Clay Thomas

Levee Mile Report Line	1
Start Levee Mile	0.00
End Levee Mile	2.19
Location	Land Side
Category	Earthen Levee
Item	Vegetation

This photo shows the landside vegetation at levee mile 2.20.

cathom_f_20111130_980.jpg



Levee Mile Report Line	2
Start Levee Mile	0.00
End Levee Mile	2.19
Location	Water Side
Category	Earthen Levee
Item	Vegetation

This photo shows the waterside vegetation at levee mile 2.20.

cathom_f_20111130_981.jpg



<p>* Location LS : Land Side WS : Water Side CR : Crown</p>	<p>** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable</p>	<p>PO : Partially Obstructing CO : Completely Obstructing W : Watch/Monitor</p>	<p>N : Not Inspected, see Inspector Comment C : Corrected</p>
---	---	---	--

**Flood Control Project Maintenance
Levee Inspections**

Unit Cover Sheet

Fall 2011 Levee Inspection Results

Reclamation District No. 0784 Plumas Lake

Waterway	Bank	Unit Miles
Unit No. 02 Feather River	Left	13.64

	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - February)
Unit Maintenance Rating (Fall Only)			A	
Date of Inspection	3/17/2011 - 3/17/2011		10/25/2011 - 10/25/2011	
DWR Inspector	Clay Thomas		Clay Thomas	
Accompanied By				

Check one:

During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.

During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

Comments

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :

DWR Summer/Winter Inspection Reports
3310 El Camino Avenue, Suite 200
Sacramento, CA 95821-9000

X

Signature of LMA Representative

Date

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2011

Reclamation District No. 0784 Plumas Lake

Waterway		Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Feather River		Left	13.64	10/25/2011 10/25/2011	Clay Thomas

LMIR No.	Levee Mile		Category	Item	Location *	Rating **	Action/Comment	GPS Latitude/Longitude		Issue No. Photo
	Start	End						Start	End	
1	0.06	12.77	Earthen Levee	Vegetation	WS	A	Remove the wild growth other than native grasses from the levee slopes.	39.124912 ° -121.588497 °	38.955775 ° -121.575092 °	62 Y
2	0.06	12.77	Earthen Levee	Vegetation	LS	A	Remove the wild growth other than native grasses from the levee slopes.	39.124910 ° -121.588590 °	39.952740 ° -121.557405 °	61 Y
3	8.90	9.23	Supplemental	USACE Erosion Survey	WS	M	Inspector Comments: 2003 - Bank is near vertical. Identified as a Potentially Critical site. 2004 - Eddy flow off downstream end of Modesto formation eroding the fluvial sediments. 2005 - Some new slumping. Actively eroding but berm width is greater than 50 ft. 2006 - Downgraded to regular erosion site. Still actively eroding. Large old rotational failures in high bank on the downstream end. 2008 - Removed from inventory due to wide berm width does not meet criteria for an erosion site. 2010 - Added back to the inventory after 10 ft of bank erosion in the winter 2009 storm. Steep vertical face. 2011: Bank has retreated an additional 2.5 ft from last year. New tree popouts and erosion throughout the site. [2011 Site ID: FHR_17-8_L]	39.009366 ° -121.579766 °	39.004549 ° -121.579143 °	2 Y
4	9.40	9.40	Earthen Levee	Encroachments	LS CO	Buildings		39.003905 ° -121.578774 °	39.003905 ° -121.578774 °	1 Y

<p>* Location LS : Land Side WS : Water Side CR : Crown</p>	<p>** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable</p>	<p>PO : Partially Obstructing CO : Completely Obstructing W : Watch/Monitor</p>	<p>N : Not Inspected, see Inspector Comment C : Corrected</p>
---	---	---	--

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2011

Reclamation District No. 0784 Plumas Lake

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Feather River	Left	13.64	10/25/2011 10/25/2011	Clay Thomas

Levee Mile Report Line	1
Start Levee Mile	0.06
End Levee Mile	12.77
Location	Water Side
Category	Earthen Levee
Item	Vegetation

This photo shows the waterside vegetation at levee mile 12.77, looking upstream.

cathom_f_20111101_976.jpg



Levee Mile Report Line	2
Start Levee Mile	0.06
End Levee Mile	12.77
Location	Land Side
Category	Earthen Levee
Item	Vegetation

This photo shows the landside vegetation at levee mile 12.77, looking upstream.

cathom_f_20111101_977.jpg



Levee Mile Report Line	3
Start Levee Mile	8.90
End Levee Mile	9.23
Location	Water Side
Category	Supplemental
Item	USACE Erosion Survey

USACE 2011 Photo #1

USACE2011_FHR_17-8_L_1.jpg



<p>* Location</p> <p>LS : Land Side WS : Water Side CR : Crown</p>	<p>** Rating</p> <p>A : Acceptable M : Minimally Acceptable U : Unacceptable</p>	<p>PO : Partially Obstructing CO : Completely Obstructing W : Watch/Monitor</p>	<p>N : Not Inspected, see Inspector Comment C : Corrected</p>
---	---	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2011

Reclamation District No. 0784 Plumas Lake

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Feather River	Left	13.64	10/25/2011 10/25/2011	Clay Thomas

Levee Mile Report Line	3
Start Levee Mile	8.90
End Levee Mile	9.23
Location	Water Side
Category	Supplemental
Item	USACE Erosion Survey
USACE 2011 Photo #2	
USACE2011_FHR_17-8_L_2.jpg	



Levee Mile Report Line	3
Start Levee Mile	8.90
End Levee Mile	9.23
Location	Water Side
Category	Supplemental
Item	USACE Erosion Survey
USACE 2011 Photo #3	
USACE2011_FHR_17-8_L_3.jpg	



Levee Mile Report Line	3
Start Levee Mile	8.90
End Levee Mile	9.23
Location	Water Side
Category	Supplemental
Item	USACE Erosion Survey
USACE 2011 Photo #4	
USACE2011_FHR_17-8_L_4.jpg	



* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	PO : Partially Obstructing CO : Completely Obstructing W : Watch/Monitor	N : Not Inspected, see Inspector Comment C : Corrected
--	--	--	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2011

Reclamation District No. 0784 Plumas Lake

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Feather River	Left	13.64	10/25/2011 10/25/2011	Clay Thomas

Levee Mile Report Line	3
Start Levee Mile	8.90
End Levee Mile	9.23
Location	Water Side
Category	Supplemental
Item	USACE Erosion Survey
USACE 2011 Photo #5	
USACE2011_FHR_17-8_L_5.jpg	



Levee Mile Report Line	3
Start Levee Mile	8.90
End Levee Mile	9.23
Location	Water Side
Category	Supplemental
Item	USACE Erosion Survey
USACE 2011 Photo #6	
USACE2011_FHR_17-8_L_6.jpg	



Levee Mile Report Line	3
Start Levee Mile	8.90
End Levee Mile	9.23
Location	Water Side
Category	Supplemental
Item	USACE Erosion Survey
USACE 2011 Photo #7	
USACE2011_FHR_17-8_L_7.jpg	



* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	PO : Partially Obstructing CO : Completely Obstructing W : Watch/Monitor	N : Not Inspected, see Inspector Comment C : Corrected
--	--	--	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2011

Reclamation District No. 0784 Plumas Lake

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Feather River	Left	13.64	10/25/2011 10/25/2011	Clay Thomas

Levee Mile Report Line	3
Start Levee Mile	8.90
End Levee Mile	9.23
Location	Water Side
Category	Supplemental
Item	USACE Erosion Survey
USACE 2011 Photo #8	
USACE2011_FHR_17-8_L_8.jpg	



Levee Mile Report Line	4
Start Levee Mile	9.40
End Levee Mile	9.40
Location	Land Side
Category	Earthen Levee
Item	Encroachments
Levee mile 9.40, looking at a building that is encroaching on the levee toe.	
cathom_f_20110929_138.jpg	



<p>* Location</p> <p>LS : Land Side WS : Water Side CR : Crown</p>	<p>** Rating</p> <p>A : Acceptable PO : Partially Obstructing N : Not Inspected, see Inspector Comment C : Corrected M : Minimally Acceptable CO : Completely Obstructing U : Unacceptable W : Watch/Monitor</p>
---	--

**Flood Control Project Maintenance
Levee Inspections**

Unit Cover Sheet

Fall 2011 Levee Inspection Results

Reclamation District No. 0784 Plumas Lake

Waterway	Bank	Unit Miles
Unit No. 03 Bear River	Right	4.73

	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - February)
Unit Maintenance Rating (Fall Only)			A	
Date of Inspection	3/17/2011 - 4/20/2011		10/25/2011 - 10/26/2011	
DWR Inspector	Clay Thomas		Clay Thomas	
Accompanied By	Steve Fordice		Steve Fordice	

Check one:

During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.

During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

Comments

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :

DWR Summer/Winter Inspection Reports
3310 El Camino Avenue, Suite 200
Sacramento, CA 95821-9000

X

Signature of LMA Representative

Date

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2011

Reclamation District No. 0784 Plumas Lake

Waterway						Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 Bear River						Right	4.73	10/25/2011 10/26/2011	Clay Thomas

LMIR No.	Levee Mile		Category	Item	Location *	Rating **	Action/Comment	GPS Latitude/Longitude		Issue No. Photo
	Start	End						Start	End	
1	2.46	4.70	Earthen Levee	Vegetation	LS	A	Remove the wild growth other than native grasses from the levee slopes.	38.970970 ° -121.547270 °	38.985355 ° -121.510867 °	80 Y
2	2.46	4.70	Earthen Levee	Vegetation	WS	A	Remove the wild growth other than native grasses from the levee slopes.	38.970970 ° -121.547273 °	38.985361 ° -121.510863 °	81 Y
3	2.82	2.82	Earthen Levee	Encroachments	CR	PO	Equipment Inspector Comments: hwy 70 new bridge construction	38.974003 ° -121.541910 °	38.974003 ° -121.541910 °	4
4	4.22	4.23	Supplemental	USACE Erosion Survey	WS	M	Inspector Comments: 2009 - Small site which could be repaired with maintenance. Erosion into the levee toe, rock has stated to fail. 2011: No observed change. [2011 Site ID: BER_4-9_R]	38.981400 ° -121.515848 °	38.981271 ° -121.515999 °	1

<p>* Location LS : Land Side WS : Water Side CR : Crown</p>	<p>** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable</p>	<p>PO : Partially Obstructing CO : Completely Obstructing W : Watch/Monitor</p>	<p>N : Not Inspected, see Inspector Comment C : Corrected</p>
---	---	---	--

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2011

Reclamation District No. 0784 Plumas Lake

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 Bear River	Right	4.73	10/25/2011 10/26/2011	Clay Thomas

Levee Mile Report Line	1
Start Levee Mile	2.46
End Levee Mile	4.70
Location	Land Side
Category	Earthen Levee
Item	Vegetation

This photo shows the landside vegetation at levee mile 3.19, looking downstream.

cathom_f_20111101_972.jpg



Levee Mile Report Line	2
Start Levee Mile	2.46
End Levee Mile	4.70
Location	Water Side
Category	Earthen Levee
Item	Vegetation

This photo shows the waterside vegetation at levee mile 3.19, looking downstream.

cathom_f_20111101_973.jpg



<p>* Location</p> <p>LS : Land Side WS : Water Side CR : Crown</p>	<p>** Rating</p> <p>A : Acceptable PO : Partially Obstructing N : Not Inspected, see Inspector Comment C : Corrected M : Minimally Acceptable CO : Completely Obstructing U : Unacceptable W : Watch/Monitor</p>
---	--

**Flood Control Project Maintenance
Levee Inspections**

Unit Cover Sheet

Fall 2011 Levee Inspection Results

Reclamation District No. 0784 Plumas Lake

Waterway		Bank	Unit Miles
Unit No. 04 Interceptor Canal		Right	6.35

	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - February)
Unit Maintenance Rating (Fall Only)			A	
Date of Inspection	3/17/2011 - 3/17/2011		10/25/2011 - 10/25/2011	
DWR Inspector	Clay Thomas		Clay Thomas	
Accompanied By	Steve Fordice		Steve Fordice	

Check one:

- During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.
- During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.
- (In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

Comments

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :
 DWR Summer/Winter Inspection Reports
 3310 El Camino Avenue, Suite 200
 Sacramento, CA 95821-9000

X _____ Date

Signature of LMA Representative

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2011

Reclamation District No. 0784 Plumas Lake

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 04 Interceptor Canal	Right	6.35	10/25/2011 10/25/2011	Clay Thomas

LMIR No.	Levee Mile		Category	Item	Location *	Rating **	Action/Comment	GPS Latitude/Longitude		Issue No. Photo
	Start	End						Start	End	
1	0.02	6.34	Earthen Levee	Vegetation	WS	A	Remove the wild growth other than native grasses from the levee slopes.	38.975045 ° -121.535077 °	39.059295 ° -121.551074 °	51 Y
2	0.02	6.34	Earthen Levee	Vegetation	LS	A	Remove the wild growth other than native grasses from the levee slopes.	38.975045 ° -121.535077 °	39.059299 ° -121.551074 °	50 Y
3	4.31	4.43	Earthen Levee	Erosion / Bank Caving	CR	W	Note and monitor erosion site.	39.036594 ° -121.542377 °	39.038493 ° -121.542380 °	4 Y

<p>* Location</p> <p>LS : Land Side WS : Water Side CR : Crown</p>	<p>** Rating</p> <p>A : Acceptable PO : Partially Obstructing N : Not Inspected, see Inspector Comment C : Corrected M : Minimally Acceptable CO : Completely Obstructing U : Unacceptable W : Watch/Monitor</p>
---	--

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2011

Reclamation District No. 0784 Plumas Lake

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 04 Interceptor Canal	Right	6.35	10/25/2011 10/25/2011	Clay Thomas

Levee Mile Report Line	1
Start Levee Mile	0.02
End Levee Mile	6.34
Location	Water Side
Category	Earthen Levee
Item	Vegetation
<p>This photo shows the waterside vegetation at levee mile 4.82, looking downstream.</p>	
<p>cathom_f_20111031_971.jpg</p>	



Levee Mile Report Line	2
Start Levee Mile	0.02
End Levee Mile	6.34
Location	Land Side
Category	Earthen Levee
Item	Vegetation
<p>This photo shows the landside vegetation at levee mile 4.82, looking downstream.</p>	
<p>cathom_f_20111031_970.jpg</p>	



Levee Mile Report Line	3
Start Levee Mile	4.31
End Levee Mile	4.43
Location	Crown
Category	Earthen Levee
Item	Erosion / Bank Caving
<p>Levee mile 4.31, looking at a crack near the landside shoulder with a temporary repair.</p>	
<p>cathom_f_20110929_351.jpg</p>	



<p>* Location LS : Land Side WS : Water Side CR : Crown</p>	<p>** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable</p>	<p>PO : Partially Obstructing CO : Completely Obstructing W : Watch/Monitor</p>	<p>N : Not Inspected, see Inspector Comment C : Corrected</p>
---	---	---	--

**Flood Control Project Maintenance
Levee Inspections**

Unit Cover Sheet

Fall 2011 Levee Inspection Results

Reclamation District No. 0784 Plumas Lake

Waterway		Bank	Unit Miles
Unit No. 05 Interceptor Canal		Left	4.20

	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - February)
Unit Maintenance Rating (Fall Only)			U	
Date of Inspection	4/20/2011 - 4/20/2011		10/26/2011 - 10/26/2011	
DWR Inspector	Clay Thomas		Clay Thomas	
Accompanied By	Steve Fordice RD 784		Steve Fordice RD 784	

Check one:

During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.

During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

Comments

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :

DWR Summer/Winter Inspection Reports
3310 El Camino Avenue, Suite 200
Sacramento, CA 95821-9000

X

Signature of LMA Representative

Date

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2011

Reclamation District No. 0784 Plumas Lake

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 05 Interceptor Canal	Left	4.20	10/26/2011 10/26/2011	Clay Thomas

LMIR No.	Levee Mile		Category	Item	* Location	** Rating	Action/Comment	GPS Latitude/Longitude		Issue No. Photo
	Start	End						Start	End	
1	0.04	0.04	Earthen Levee	Vegetation	LS	C	Remove the wild growth other than native grasses from the levee slopes.	38.975168 ° -121.532805 °	38.975168 ° -121.532805 °	84
2	0.04	0.04	Earthen Levee	Vegetation	WS	C	Remove the wild growth other than native grasses from the levee slopes.	38.975168 ° -121.532805 °	38.975168 ° -121.532805 °	85
3	1.08	1.72	Earthen Levee	Encroachments	LS	PO	Agricultural Ditch	38.989955 ° -121.535672 °	38.999068 ° -121.537462 °	10
4	2.10	3.06	Earthen Levee	Encroachments	LS	PO	Agricultural Ditch	39.004562 ° -121.538482 °	39.015593 ° -121.528533 °	9
5	3.89	4.20	Earthen Levee	Vegetation	WS	M	Remove the wild growth other than native grasses from the levee slopes.	39.019567 ° -121.514560 °	39.020545 ° -121.509080 °	86 Y
6	3.89	4.20	Earthen Levee	Vegetation	CR	M	Remove the wild growth other than native grasses from the levee slopes.	39.019567 ° -121.514562 °	39.020545 ° -121.509078 °	82 Y
7	3.89	4.20	Earthen Levee	Vegetation	LS	M	Remove the wild growth other than native grasses from the levee slopes.	39.019566 ° -121.514560 °	39.020545 ° -121.509078 °	83 Y
8	4.19	4.19	Earthen Levee	Vegetation	LS	C	Control annual grass and weeds on the levee slopes and easements.	39.020545 ° -121.509079 °	39.020545 ° -121.509080 °	81

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable PO : Partially Obstructing CO : Completely Obstructing W : Watch/Monitor N : Not Inspected, see Inspector Comment C : Corrected
--	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2011

Reclamation District No. 0784 Plumas Lake

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 05 Interceptor Canal	Left	4.20	10/26/2011 10/26/2011	Clay Thomas

Levee Mile Report Line	5
Start Levee Mile	3.89
End Levee Mile	4.20
Location	Water Side
Category	Earthen Levee
Item	Vegetation

This photo shows the waterside vegetation at levee mile 4.20.

cathom_f_20111130_984.jpg



Levee Mile Report Line	6
Start Levee Mile	3.89
End Levee Mile	4.20
Location	Crown
Category	Earthen Levee
Item	Vegetation

This photo shows the crown vegetation at levee mile 4.20.

cathom_f_20111130_982.jpg



Levee Mile Report Line	7
Start Levee Mile	3.89
End Levee Mile	4.20
Location	Land Side
Category	Earthen Levee
Item	Vegetation

This photo shows the landside vegetation at levee mile 4.20.

cathom_f_20111130_983.jpg



<p>* Location LS : Land Side WS : Water Side CR : Crown</p>	<p>** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable</p>	<p>PO : Partially Obstructing CO : Completely Obstructing W : Watch/Monitor</p>	<p>N : Not Inspected, see Inspector Comment C : Corrected</p>
---	---	---	--

**Flood Control Project Maintenance
Levee Inspections**

Unit Cover Sheet

Fall 2011 Levee Inspection Results

Reclamation District No. 0784 Plumas Lake

Waterway	Bank	Unit Miles
Unit No. 06 South Dry Creek	Right	1.50

	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - February)
Unit Maintenance Rating (Fall Only)			A	
Date of Inspection	4/20/2011 - 4/20/2011		10/26/2011 - 10/26/2011	
DWR Inspector	Clay Thomas		Clay Thomas	
Accompanied By				

Check one:

- During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.
- During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

Comments

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :

DWR Summer/Winter Inspection Reports
3310 El Camino Avenue, Suite 200
Sacramento, CA 95821-9000

X

Signature of LMA Representative

Date

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2011

Reclamation District No. 0784 Plumas Lake

Waterway				Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 06 South Dry Creek				Right	1.50	10/26/2011 10/26/2011	Clay Thomas

LMIR No.	Levee Mile		Category	Item	* Location	** Rating	Action/Comment	GPS Latitude/Longitude		Issue No. Photo
	Start	End						Start	End	
1	0.01	0.23	Earthen Levee	Vegetation	LS	A	Remove the wild growth other than native grasses from the levee slopes.	38.985630 ° -121.510310 °	38.987390 ° -121.506920 °	84 Y
2	0.01	0.24	Earthen Levee	Vegetation	WS	A	Remove the wild growth other than native grasses from the levee slopes.	38.985630 ° -121.510310 °	38.987536 ° -121.506719 °	85 Y

<p>* Location LS : Land Side WS : Water Side CR : Crown</p>	<p>** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable</p>	<p>PO : Partially Obstructing CO : Completely Obstructing W : Watch/Monitor</p>	<p>N : Not Inspected, see Inspector Comment C : Corrected</p>
---	---	---	--

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2011

Reclamation District No. 0784 Plumas Lake

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 06 South Dry Creek	Right	1.50	10/26/2011 10/26/2011	Clay Thomas

Levee Mile Report Line	1
Start Levee Mile	0.01
End Levee Mile	0.23
Location	Land Side
Category	Earthen Levee
Item	Vegetation

This photo shows the landside vegetation at levee mile 0.24.

cathom_f_20111130_985.jpg



Levee Mile Report Line	2
Start Levee Mile	0.01
End Levee Mile	0.24
Location	Water Side
Category	Earthen Levee
Item	Vegetation

This photo shows the waterside vegetation at levee mile 0.24.

cathom_f_20111130_986.jpg



<p>* Location</p> <p>LS : Land Side WS : Water Side CR : Crown</p>	<p>** Rating</p> <p>A : Acceptable PO : Partially Obstructing N : Not Inspected, see Inspector Comment C : Corrected M : Minimally Acceptable CO : Completely Obstructing U : Unacceptable W : Watch/Monitor</p>
---	--

**Flood Control Project Maintenance
Levee Inspections**

Unit Cover Sheet

Fall 2011 Levee Inspection Results

Reclamation District No. 0784 Plumas Lake

Waterway	Bank	Unit Miles
Unit No. 07 Yuba River	Left	3.91

	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - February)
Unit Maintenance Rating (Fall Only)			A	
Date of Inspection	3/17/2011 - 3/17/2011		10/25/2011 - 10/25/2011	
DWR Inspector	Clay Thomas		Clay Thomas	
Accompanied By				

Check one:

During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.

During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

Comments

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :

DWR Summer/Winter Inspection Reports
3310 El Camino Avenue, Suite 200
Sacramento, CA 95821-9000

X

Signature of LMA Representative

Date

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2011

Reclamation District No. 0784 Plumas Lake

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 07 Yuba River	Left	3.91	10/25/2011 10/25/2011	Clay Thomas

LMIR No.	Levee Mile		Category	Item	* Location	** Rating	Action/Comment	GPS Latitude/Longitude		Issue No. Photo
	Start	End						Start	End	
1	1.72	1.72	Earthen Levee	Encroachments	CR	A	Equipment Inspector Comments: This levee was not inspected, the levee is under repair.	39.144820 ° -121.523600 °	39.144820 ° -121.523600 °	80 Y
2	2.18	2.18	Earthen Levee	Encroachments	WS	CO	Buildings	39.149330 ° -121.518550 °	39.149330 ° -121.518550 °	4 Y
3	2.28	2.28	Supplemental	USACE Erosion Survey	WS	M	Inspector Comments: 2006 - Land owner has removed levee toe and lower slope during plowing and cultivation activities resulting in high, near vertical face at levee toe and exposure of levee core. 2007 - Levee is set back a ways from the channel. 2011: Site currently being repaired under the Upper Yuba Levee Improvement Project by the Three Levees District. [2011 Site ID: YUB_2-3_L]	39.150442 ° -121.517481 °	39.153613 ° -121.513920 °	1

<p>* Location LS : Land Side WS : Water Side CR : Crown</p>	<p>** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable PO : Partially Obstructing CO : Completely Obstructing W : Watch/Monitor N : Not Inspected, see Inspector Comment C : Corrected</p>
--	--

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2011

Reclamation District No. 0784 Plumas Lake

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 07 Yuba River	Left	3.91	10/25/2011 10/25/2011	Clay Thomas

Levee Mile Report Line	1
Start Levee Mile	1.72
End Levee Mile	1.72
Location	Crown
Category	Earthen Levee
Item	Encroachments
This photo is looking upstream from levee mile 1.72.	
cathom_f_20111202_037.jpg	



Levee Mile Report Line	1
Start Levee Mile	1.72
End Levee Mile	1.72
Location	Crown
Category	Earthen Levee
Item	Encroachments
This photo is looking downstream from levee mile 1.72.	
cathom_f_20111202_038.jpg	



Levee Mile Report Line	2
Start Levee Mile	2.18
End Levee Mile	2.18
Location	Water Side
Category	Earthen Levee
Item	Encroachments
Water side buildings and equipment levee mile 2.18.	
cathom_f_20110929_679.jpg	



* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	PO : Partially Obstructing CO : Completely Obstructing W : Watch/Monitor	N : Not Inspected, see Inspector Comment C : Corrected
--	--	--	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2011

Reclamation District No. 0784 Plumas Lake

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 07 Yuba River	Left	3.91	10/25/2011 10/25/2011	Clay Thomas

Levee Mile Report Line	2
Start Levee Mile	2.18
End Levee Mile	2.18
Location	Water Side
Category	Earthen Levee
Item	Encroachments
Water side buildings and equipment levee mile 2.18.	
cathom_f_20110929_680.jpg	



<p>* Location</p> <p>LS : Land Side WS : Water Side CR : Crown</p>	<p>** Rating</p> <p>A : Acceptable PO : Partially Obstructing N : Not Inspected, see Inspector Comment C : Corrected M : Minimally Acceptable CO : Completely Obstructing U : Unacceptable W : Watch/Monitor</p>
---	--

**Flood Control Project Maintenance
Levee Inspections**

Unit Cover Sheet

Fall 2011 Levee Inspection Results

Reclamation District No. 0784 Plumas Lake

Waterway		Bank	Unit Miles
Unit No. 08 Three Rivers		Right	1.88

	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - February)
Unit Maintenance Rating (Fall Only)			A	
Date of Inspection	6/7/2011 - 6/7/2011		10/25/2011 - 10/25/2011	
DWR Inspector	Clay Thomas		Clay Thomas	
Accompanied By				

Check one:

During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.

During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

Comments

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :

DWR Summer/Winter Inspection Reports
3310 El Camino Avenue, Suite 200
Sacramento, CA 95821-9000

X _____ Date

Signature of LMA Representative

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2011

Reclamation District No. 0784 Plumas Lake

Waterway				Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 08 Three Rivers				Right	1.88	10/25/2011 10/25/2011	Clay Thomas

LMIR No.	Levee Mile		Category	Item	Location *	Rating **	Action/Comment	GPS Latitude/Longitude		Issue No. Photo
	Start	End						Start	End	
1	0.00	1.85	Earthen Levee	Vegetation	WS	A	Remove the wild growth other than native grasses from the levee slopes.	38.955522 ° -121.573999 °	38.970459 ° -121.547641 °	6 Y
2	0.00	1.85	Earthen Levee	Vegetation	LS	A	Remove the wild growth other than native grasses from the levee slopes.	38.955522 ° -121.573999 °	38.970459 ° -121.547640 °	7 Y

<p>* Location LS : Land Side WS : Water Side CR : Crown</p>	<p>** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable</p>	<p>PO : Partially Obstructing CO : Completely Obstructing W : Watch/Monitor</p>	<p>N : Not Inspected, see Inspector Comment C : Corrected</p>
---	---	---	--

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2011

Reclamation District No. 0784 Plumas Lake

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 08 Three Rivers	Right	1.88	10/25/2011 10/25/2011	Clay Thomas

Levee Mile Report Line	1
Start Levee Mile	0.00
End Levee Mile	1.85
Location	Water Side
Category	Earthen Levee
Item	Vegetation

This photo shows the waterside vegetation at levee mile 1.85, looking downstream.

cathom_f_20111101_975.jpg



Levee Mile Report Line	2
Start Levee Mile	0.00
End Levee Mile	1.85
Location	Land Side
Category	Earthen Levee
Item	Vegetation

This photo shows the landside vegetation at levee mile 1.85, looking downstream.

cathom_f_20111101_974.jpg



*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable PO : Partially Obstructing N : Not Inspected, see Inspector Comment C : Corrected
M : Minimally Acceptable CO : Completely Obstructing
U : Unacceptable W : Watch/Monitor

**Flood Control Project Maintenance
Levee Inspections**

Unit Cover Sheet

Fall 2011 Levee Inspection Results

Reclamation District No. 0784 Plumas Lake

Waterway	Bank	Unit Miles
Unit No. 09 Feather River, TRLIA Setback Levee	Left	5.73

	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - February)
Unit Maintenance Rating (Fall Only)			A	
Date of Inspection	6/7/2011 - 6/7/2011		10/25/2011 - 10/25/2011	
DWR Inspector	Clay Thomas		Clay Thomas	
Accompanied By				

Check one:

During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.

During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

Comments

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :

DWR Summer/Winter Inspection Reports
3310 El Camino Avenue, Suite 200
Sacramento, CA 95821-9000

X _____ Date

Signature of LMA Representative

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2011

Reclamation District No. 0784 Plumas Lake

Waterway				Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 09 Feather River, TRLIA Setback Levee				Left	5.73	10/25/2011 10/25/2011	Clay Thomas

LMIR No.	Levee Mile		Category	Item	* Location	** Rating	Action/Comment	GPS Latitude/Longitude		Issue No. Photo
	Start	End						Start	End	
1	0.02	4.00	Earthen Levee	Vegetation	WS	A	Remove the wild growth other than native grasses from the levee slopes.	39.090041 ° -121.584808 °	39.032986 ° -121.590631 °	18 Y
2	0.02	4.00	Earthen Levee	Vegetation	LS	A	Remove the wild growth other than native grasses from the levee slopes.	39.090041 ° -121.584808 °	39.032977 ° -121.590628 °	17 Y

<p>* Location LS : Land Side WS : Water Side CR : Crown</p>	<p>** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable</p>	<p>PO : Partially Obstructing CO : Completely Obstructing W : Watch/Monitor</p>	<p>N : Not Inspected, see Inspector Comment C : Corrected</p>
---	---	---	--

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2011

Reclamation District No. 0784 Plumas Lake

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 09 Feather River, TRLIA Setback Levee	Left	5.73	10/25/2011 10/25/2011	Clay Thomas

Levee Mile Report Line	1
Start Levee Mile	0.02
End Levee Mile	4.00
Location	Water Side
Category	Earthen Levee
Item	Vegetation

This photo shows the waterside vegetation at levee mile 4.00.

cathom_f_20111130_978.jpg



Levee Mile Report Line	2
Start Levee Mile	0.02
End Levee Mile	4.00
Location	Land Side
Category	Earthen Levee
Item	Vegetation

This photo shows the landside vegetation at levee mile 4.00.

cathom_f_20111130_979.jpg



<p>* Location</p> <p>LS : Land Side WS : Water Side CR : Crown</p>	<p>** Rating</p> <p>A : Acceptable PO : Partially Obstructing N : Not Inspected, see Inspector Comment C : Corrected M : Minimally Acceptable CO : Completely Obstructing U : Unacceptable W : Watch/Monitor</p>
---	--