

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2016

Reclamation District No. 0784 Plumas Lake

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Yuba River	Left	2.21	11/01/2016 11/01/2016	Sterling York

LM Start	0.00	Rating **	A	Issue No.	4
LM End	0.00	Issue Type +	Ma	Location *	CR
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Operations & Maintenance Manuals			°	°
DWR ID	DWR_RD0784_01_s _ 2013_4				
Comment Code					
Inspector Comment					
O&M manuals are located at the district office.					

No Photos

LM Start	0.00	Rating **	A	Issue No.	5
LM End	0.00	Issue Type +	Ma	Location *	CR
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Emergency Supplies & Equipment			°	°
DWR ID	DWR_RD0784_01_s _ 2013_5				
Comment Code					
Inspector Comment					
RD 784 participates with the neighboring districts to strategically place flood fight supplies around the local districts for fast response. They also have a shipping container at their district office, and three containers at another district full of flood fight supplies.					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2016

Reclamation District No. 0784 Plumas Lake

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Yuba River	Left	2.21	11/01/2016 11/01/2016	Sterling York

LM Start	0.00	Rating **	A	Issue No.	6		
LM End	0.00	Issue Type +	Ma	Location *	CR		
Category	Earthen Levee			GPS Latitude/Longitude			
				Start		End	
Item	Flood Preparedness & Training				°		°
					°		°
DWR ID	DWR_RD0784_01_s_2013_6						
Comment Code							
Inspector Comment							
RD 784 and its employees host and participate in a Flood Fight class put on by DWR every fall in their district.							

No Photos

LM Start	0.04	Rating **	A	Issue No.	2
LM End	2.20	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			39.134450 °	39.125874 °
				-121.552671 °	-121.588644 °
DWR ID	DWR_RD0784_01_f_2016_2				
Comment Code					
V1 : Control annual grass and weeds on the levee slopes and easements.					
Inspector Comment					
Well maintained annual vegetation. Fall 2016.					

Photo 1 of 1 : FA_2016_RD0784_178_2_20161103_00006.jpg



View of waterside looking downstream of well maintained annual vegetation. Fall 2016.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2016

Reclamation District No. 0784 Plumas Lake

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Yuba River	Left	2.21	11/01/2016 11/01/2016	Sterling York

LM Start	0.04	Rating **	A	Issue No.	3
LM End	2.20	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			39.134450°	39.125874°
				-121.552672°	-121.588644°
DWR ID	DWR_RD0784_01_f _ 2016_3				
Comment Code					
V1 : Control annual grass and weeds on the levee slopes and easements.					
Inspector Comment					
Well maintained annual vegetation. Fall 2016.					

Photo 1 of 1 : FA_2016_RD0784_178_3_20161103_00007.jpg



View of landside looking downstream of well maintained annual vegetation. Fall 2016.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2016

Reclamation District No. 0784 Plumas Lake

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02A Feather River	Left	2.54	11/01/2016 11/01/2016	Sterling York

LM Start	0.01	Rating **	A	Issue No.	1
LM End	2.53	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			39.125763 °	39.090425 °
				-121.588667 °	-121.584694 °
DWR ID	DWR_RD0784_02A_f_2016_1				
Comment Code					
V1 : Control annual grass and weeds on the levee slopes and easements.					
Inspector Comment					
Well maintained annual vegetation. Fall 2016.					

Photo 1 of 2 : FA_2016_RD0784_531_1_20161103_00005.jpg



First view looking downstream of landside well maintained annual vegetation. Fall 2016.

LM Start	0.01	Rating **	A	Issue No.	1 (cont)
LM End	2.53	Issue Type +	Ma	Location *	LS

Photo 2 of 2 : FA_2016_RD0784_531_1_20161117_00007.jpg



Second view looking downstream on waterside of well maintained annual vegetation. Fall 2016.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement	
--	--	---	--	---	--

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2016

Reclamation District No. 0784 Plumas Lake

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02A Feather River	Left	2.54	11/01/2016 11/01/2016	Sterling York

LM Start	0.01	Rating **	A	Issue No.	2
LM End	2.53	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			39.125763 °	39.090425 °
				-121.588667 °	-121.584695 °
DWR ID	DWR_RD0784_02A_f_2016_2				
Comment Code					
V1 : Control annual grass and weeds on the levee slopes and easements.					
Inspector Comment					
Well maintained annual vegetation. Fall 2016.					

Photo 1 of 2 : FA_2016_RD0784_531_2_20161103_00003.jpg



First view of waterside looking downstream of well maintained annual vegetation. Fall 2016.

LM Start	0.01	Rating **	A	Issue No.	2 (cont)
LM End	2.53	Issue Type +	Ma	Location *	WS

Photo 2 of 2 : FA_2016_RD0784_531_2_20161103_00004.jpg



Second view of waterside looking downstream of well maintained annual vegetation. Fall 2016.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	--	---

Reclamation District No. 0784 Plumas Lake

Page 1 of 2

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2016

Reclamation District No. 0784 Plumas Lake

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02B Feather River	Left	3.95	11/01/2016 11/01/2016	Sterling York

LM Start	9.00	Rating **	A	Issue No.	3
LM End	12.80	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			39.009547 °	38.955539 °
				-121.578825 °	-121.574623 °
DWR ID	DWR_RD0784_02B_f _ 2016_3				
Comment Code					
V1 : Control annual grass and weeds on the levee slopes and easements.					
Inspector Comment					
Well maintained annual vegetation. Fall 2016.					

Photo 1 of 1 : FA_2016_RD0784_532_3_20161103_00007.jpg



View of landside looking downstream of landside well maintained annual vegetation. Fall 2016.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

Reclamation District No. 0784 Plumas Lake

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03A Bear River	Right	0.78	11/01/2016 11/01/2016	Sterling York

LM Start	2.43	Rating **	A	Issue No.	3
LM End	3.20	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.970576 °	38.974682 °
				-121.547586 °	-121.535308 °
DWR ID	DWR_RD0784_03A_f _ 2016_3				
Comment Code					
V1 : Control annual grass and weeds on the levee slopes and easements.					
Inspector Comment					
Well maintained annual vegetation. Fall 2016.					

Photo 1 of 1 : FA_2016_RD0784_533_3_20161103_00002.jpg



View of waterside looking upstream at well maintained annual vegetation. Fall 2016.

LM Start	2.43	Rating **	A	Issue No.	1
LM End	3.20	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.970576 °	38.974682 °
				-121.547585 °	-121.535308 °
DWR ID	DWR_RD0784_03A_f _ 2016_1				
Comment Code					
V1 : Control annual grass and weeds on the levee slopes and easements.					
Inspector Comment					
Well maintained annual vegetation. Fall 2016.					

Photo 1 of 1 : FA_2016_RD0784_533_1_20161103_00003.jpg



View of landside looking upstream of landside well maintained annual vegetation. Fall 2016.

* Location	** Rating	+ Issue Type
LS : Land Side N/A : Not Applicable	A : Acceptable N : Not Inspected/Rated	Ma : Maintenance Deficiency
WS : Water Side	M : Minimally Acceptable C : Corrected	Ob : Design & System Obsolescence
CR : Crown	U : Unacceptable A/W : Acceptable but Monitor & Maintain	En : Enforcement

Reclamation District No. 0784 Plumas Lake

View of landside looking upstream of landside well maintained annual vegetation. Fall 2016.

View of waterside looking upstream at well maintained annual vegetation. Fall 2016.

Page 1 of 1

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2016

Reclamation District No. 0784 Plumas Lake

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 04 Interceptor Canal	Right	6.33	11/01/2016 11/01/2016	Sterling York

LM Start	0.00	Rating **	A	Issue No.	3
LM End	6.31	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.974774 °	39.059304 °
				-121.535090 °	-121.551040 °
DWR ID	DWR_RD0784_04_f _ 2016_3				
Comment Code					
V1 : Control annual grass and weeds on the levee slopes and easements.					
Inspector Comment					
Well maintained annual vegetation. Fall 2016.					

Photo 1 of 1 : FA_2016_RD0784_181_3_20161103_00007.jpg



View of landside looking upstream of landside well maintained annual vegetation. Fall 2016.

LM Start	0.00	Rating **	A	Issue No.	4
LM End	6.31	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.974774 °	39.059304 °
				-121.535089 °	-121.551040 °
DWR ID	DWR_RD0784_04_f_2016_4				
Comment Code					
V1 : Control annual grass and weeds on the levee slopes and easements.					
Inspector Comment					
Well maintained annual vegetation. Fall 2016.					

Photo 1 of 1 : FA_2016_RD0784_181_4_20161103_00008.jpg



View of waterside looking upstream at well maintained annual vegetation. Fall 2016.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2016

Reclamation District No. 0784 Plumas Lake

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 04 Interceptor Canal	Right	6.33	11/01/2016 11/01/2016	Sterling York

LM Start	3.60	Rating **	A	Issue No.	5
LM End	5.84	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Slope Stability			39.026503 °	39.058462 °
				-121.542349 °	-121.543125 °
DWR ID	DWR_RD0784_04_f _ 2016_5				
Comment Code					
S1 : Repair slope instability.					
Inspector Comment					
This section of levee on the landside is under construction with Permit Number 19020-1 to construct a stability berm and all weather access road. Fall 2016.					

Photo 1 of 2 : FA_2016_RD0784_181_5_20161103_00009.jpg



View of landside looking upstream. This section of levee on the landside is under construction with Permit Number 19020-1 to construct a stability berm and all weather access road. Fall 2016.

LM Start	3.60	Rating **	A	Issue No.	5 (cont)
LM End	5.84	Issue Type +	Ma	Location *	LS

Photo 2 of 2 : FA_2016_RD0784_181_5_20161103_00010.jpg



Second view of landside looking upstream. This section of levee on the landside is under construction with Permit Number 19020-1 to construct a stability berm and all weather access road. Fall 2016.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2016

Reclamation District No. 0784 Plumas Lake

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 05 Interceptor Canal	Left	4.19	11/01/2016 11/01/2016	Sterling York

LM Start	0.01	Rating **	A	Issue No.	8
LM End	4.19	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.974573 °	39.020574 °
				-121.532567 °	-121.509096 °
DWR ID	DWR_RD0784_05_f_2016_8				
Comment Code					
V1 : Control annual grass and weeds on the levee slopes and easements.					
Inspector Comment					
Well maintained annual vegetation. Fall 2016.					

Photo 1 of 1 : FA_2016_RD0784_182_8_20161103_00023.jpg



View of landside looking downstream of landside well maintained annual vegetation. Fall 2016.

LM Start	0.01	Rating **	A	Issue No.	12
LM End	4.19	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.974573 °	39.020574 °
				-121.532567 °	-121.509096 °
DWR ID	DWR_RD0784_05_f_2016_12				
Comment Code					
V1 : Control annual grass and weeds on the levee slopes and easements.					
Inspector Comment					
Well maintained annual vegetation. Fall 2016.					

Photo 1 of 1 : FA_2016_RD0784_182_12_20161103_00022.jpg



View of waterside looking downstream at well maintained annual vegetation. Fall 2016.

*** Location**
LS : Land Side N/A : Not Applicable
WS : Water Side
CR : Crown

**** Rating**
A : Acceptable N : Not Inspected/Rated
M : Minimally Acceptable C : Corrected
U : Unacceptable A/W : Acceptable but Monitor & Maintain

+ Issue Type
Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

Reclamation District No. 0784 Plumas Lake

View of landside looking upstream of landside well maintained annual vegetation. Fall 2016.

View of waterside looking upstream at well maintained annual vegetation. Fall 2016.

Page 1 of 1

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2016

Reclamation District No. 0784 Plumas Lake

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 07 Yuba River	Left	3.82	11/01/2016 11/01/2016	Sterling York

LM Start	0.12	Rating **	A	Issue No.	2
LM End	3.81	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			39.135137°	39.165505°
				-121.550129°	-121.495615°
DWR ID	DWR_RD0784_07_f_2016_2				
Comment Code					
V1 : Control annual grass and weeds on the levee slopes and easements.					
Inspector Comment					
Well maintained annual vegetation. Fall 2016.					

Photo 1 of 1 : FA_2016_RD0784_184_2_20161103_00005.jpg



View of landside looking downstream of landside well maintained annual vegetation. Fall 2016.

LM Start	0.12	Rating **	A	Issue No.	3
LM End	3.81	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			39.135138°	39.165505°
				-121.550129°	-121.495615°
DWR ID	DWR_RD0784_07_f_2016_3				
Comment Code					
V1 : Control annual grass and weeds on the levee slopes and easements.					
Inspector Comment					
Well maintained annual vegetation. Fall 2016.					

Photo 1 of 1 : FA_2016_RD0784_184_3_20161103_00004.jpg



View of waterside looking downstream at well maintained annual vegetation. Fall 2016.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2016

Reclamation District No. 0784 Plumas Lake

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 08 Three Rivers	Right	1.93	11/01/2016 11/01/2016	Sterling York

LM Start	0.02	Rating **	A	Issue No.	2
LM End	1.93	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.955540°	38.970544°
				-121.574624°	-121.547607°
DWR ID	DWR_RD0784_08_f_2016_2				
Comment Code					
V1 : Control annual grass and weeds on the levee slopes and easements.					
Inspector Comment					
Well maintained annual vegetation. Fall 2016.					

Photo 1 of 1 : FA_2016_RD0784_437_2_20161103_00002.jpg



View of waterside looking upstream at well maintained annual vegetation. Fall 2016.

LM Start	0.02	Rating **	A	Issue No.	1
LM End	1.93	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.955539 °	38.970544 °
				-121.574623 °	-121.547607 °
DWR ID	DWR_RD0784_08_f_2016_1				
Comment Code					
V1 : Control annual grass and weeds on the levee slopes and easements.					
Inspector Comment					
Well maintained annual vegetation. Fall 2016.					

Photo 1 of 1 : FA_2016_RD0784_437_1_20161103_00001.jpg



View of landside looking upstream of landside well maintained annual vegetation. Fall 2016.

* Location
LS : Land Side N/A : Not Applicable
WS : Water Side
CR : Crown

** Rating
A : Acceptable N : Not Inspected/Rated
M : Minimally Acceptable C : Corrected
U : Unacceptable A/W : Acceptable but Monitor & Maintain

+ Issue Type
Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

