

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2015

Reclamation District No. 0784 Plumas Lake

| Waterway | Bank | Unit Miles | Inspection Start/End | Inspector |
|------------------------|------|------------|--------------------------|------------------|
| Unit No. 01 Yuba River | Left | 2.21 | 03/25/2015 03/25/2015 | Michael Pitta |

| | | | | | |
|---|----------------------------------|--------------|----|------------------------|-----|
| LM Start | 0.00 | Rating ** | A | Issue No. | 4 |
| LM End | 0.00 | Issue Type + | Ma | Location * | CR |
| Category | Earthen Levee | | | GPS Latitude/Longitude | |
| | | | | Start | End |
| Item | Operations & Maintenance Manuals | | | | ° |
| | | | | | ° |
| DWR ID | DWR_RD0784_01_s _ 2013_4 | | | | |
| Action/Comments | | | | | |
| Inspector Comments: O&M manuals are located at the district office. | | | | | |

No Photos

| | | | | | |
|---|--------------------------------|--------------|----|------------------------|-----|
| LM Start | 0.00 | Rating ** | A | Issue No. | 5 |
| LM End | 0.00 | Issue Type + | Ma | Location * | CR |
| Category | Earthen Levee | | | GPS Latitude/Longitude | |
| | | | | Start | End |
| Item | Emergency Supplies & Equipment | | | | ° |
| | | | | | ° |
| DWR ID | DWR_RD0784_01_s _ 2013_5 | | | | |
| Action/Comments | | | | | |
| Inspector Comments: RD 784 participates with the neighboring districts to strategically place flood fight supplies around the local districts for fast response. They also have a shipping container at their district office, and three containers at another district full of flood fight supplies. | | | | | |

No Photos

| | | | | | |
|--|-------------------------------|--------------|----|------------------------|-----|
| LM Start | 0.00 | Rating ** | A | Issue No. | 6 |
| LM End | 0.00 | Issue Type + | Ma | Location * | CR |
| Category | Earthen Levee | | | GPS Latitude/Longitude | |
| | | | | Start | End |
| Item | Flood Preparedness & Training | | | | ° |
| | | | | | ° |
| DWR ID | DWR_RD0784_01_s _ 2013_6 | | | | |
| Action/Comments | | | | | |
| Inspector Comments: RD 784 and its employees host and participate in a Flood Fight class put on by DWR every fall in their district. | | | | | |

No Photos

| | | | | |
|--|--|---|--|---|
| * Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown | | ** Rating A : Acceptable N : Not Inspected/Rated M : Minimally Acceptable C : Corrected U : Unacceptable A/W : Acceptable but Monitor & Maintain | | + Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement |
|--|--|---|--|---|

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2015

Reclamation District No. 0784 Plumas Lake

| Waterway | Bank | Unit Miles | Inspection Start/End | Inspector |
|------------------------|------|------------|--------------------------|------------------|
| Unit No. 01 Yuba River | Left | 2.21 | 03/25/2015 03/25/2015 | Michael Pitta |

| | | | | | |
|---|--------------------------|--------------|----|------------------------|---------------|
| LM Start | 0.04 | Rating ** | A | Issue No. | 7 |
| LM End | 0.04 | Issue Type + | Ma | Location * | WS |
| Category | Earthen Levee | | | GPS Latitude/Longitude | |
| | | | | Start | End |
| Item | Vegetation | | | 39.134403 ° | 39.134403 ° |
| | | | | -121.552673 ° | -121.552673 ° |
| DWR ID | DWR_RD0784_01_s _ 2015_7 | | | | |
| Action/Comments | | | | | |
| Control annual grass and weeds on the levee slopes and easements. | | | | | |

No Photos

| | | | | | |
|---|--------------------------|--------------|----|------------------------|---------------|
| LM Start | 0.04 | Rating ** | A | Issue No. | 3 |
| LM End | 0.05 | Issue Type + | Ma | Location * | LS |
| Category | Earthen Levee | | | GPS Latitude/Longitude | |
| | | | | Start | End |
| Item | Vegetation | | | 39.134403 ° | 39.134340 ° |
| | | | | -121.552673 ° | -121.552725 ° |
| DWR ID | DWR_RD0784_01_s _ 2015_3 | | | | |
| Action/Comments | | | | | |
| Control annual grass and weeds on the levee slopes and easements. | | | | | |

Photo 1 of 1 : SP_2015_RD0784_178_3_20150330_00004.jpg



Left bank landside, facing downstream.

| | | | | | |
|--|--------------------------|--------------|----|------------------------|-------------|
| LM Start | 1.28 | Rating ** | M | Issue No. | 2 |
| LM End | 1.28 | Issue Type + | Ma | Location * | WS |
| Category | Earthen Levee | | | GPS Latitude/Longitude | |
| | | | | Start | End |
| Item | Vegetation | | | 39.129783 ° | 39.129783 |
| | | | | -121.574384 ° | -121.574384 |
| DWR ID | DWR_RD0784_01_s _ 2012_2 | | | | |
| Action/Comments | | | | | |
| Elderberries are blocking visibility and flood fight capability. | | | | | |

Photo 1 of 1 : SP_2015_RD0784_178_2_20150325_00001.jpg



W/S slope vegetation, Elderberry.

| | | | | |
|--|--|---|--|---|
| * Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown | | ** Rating A : Acceptable N : Not Inspected/Rated M : Minimally Acceptable C : Corrected U : Unacceptable A/W : Acceptable but Monitor & Maintain | | + Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement |
|--|--|---|--|---|

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2015

Reclamation District No. 0784 Plumas Lake

| Waterway | Bank | Unit Miles | Inspection Start/End | Inspector |
|----------------------------|------|------------|--------------------------|------------------|
| Unit No. 02A Feather River | Left | 2.54 | 03/25/2015 03/25/2015 | Michael Pitta |

| | | | | | |
|---|-------------------------|--------------|----|------------------------|-------------|
| LM Start | 0.04 | Rating ** | A | Issue No. | 2 |
| LM End | 0.04 | Issue Type + | Ma | Location * | LS |
| Category | Earthen Levee | | | GPS Latitude/Longitude | |
| | | | | Start | End |
| Item | Vegetation | | | 39.125198 ° | 39.125198 |
| | | | | -121.588575 ° | -121.588575 |
| DWR ID | DWR_RD0784_02A_s_2015_2 | | | | |
| Action/Comments | | | | | |
| Control annual grass and weeds on the levee slopes and easements. | | | | | |

Photo 1 of 1 : SP_2015_RD0784_531_2_20150330_00002.jpg



Left bank land side, facing downstream.

| | | | | | |
|---|-------------------------|--------------|----|------------------------|---------------|
| LM Start | 0.04 | Rating ** | A | Issue No. | 4 |
| LM End | 0.04 | Issue Type + | Ma | Location * | WS |
| Category | Earthen Levee | | | GPS Latitude/Longitude | |
| | | | | Start | End |
| Item | Vegetation | | | 39.125198 ° | 39.125198 ° |
| | | | | -121.588575 ° | -121.588575 ° |
| DWR ID | DWR_RD0784_02A_s_2015_4 | | | | |
| Action/Comments | | | | | |
| Control annual grass and weeds on the levee slopes and easements. | | | | | |

No Photos

| | | | | |
|--|--|---|--|---|
| * Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown | | ** Rating A : Acceptable N : Not Inspected/Rated M : Minimally Acceptable C : Corrected U : Unacceptable A/W : Acceptable but Monitor & Maintain | | + Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement |
|--|--|---|--|---|

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2015

Reclamation District No. 0784 Plumas Lake

| Waterway | Bank | Unit Miles | Inspection Start/End | Inspector |
|----------------------------|------|------------|--------------------------|------------------|
| Unit No. 02B Feather River | Left | 3.95 | 03/25/2015 03/25/2015 | Michael Pitta |

| | | | | | |
|----------|-------------------------|--------------|----|------------------------|---------------|
| LM Start | 8.96 | Rating ** | M | Issue No. | 7 |
| LM End | 9.36 | Issue Type + | Ma | Location * | WS |
| Category | Supplemental | | | GPS Latitude/Longitude | |
| | | | | Start | End |
| Item | USACE Erosion Survey | | | 39.009366 ° | 39.004549 ° |
| | | | | -121.579766 ° | -121.579143 ° |
| DWR ID | DWR_RD0784_02A_f_2014_3 | | | | |

Action/Comments

Inspector Comments: 2003 - Bank is near vertical. Identified as a Potentially Critical site. 2004 - Eddy flow off downstream end of Modesto formation eroding the fluvial sediments. 2005 - Some new slumping. Actively eroding but berm width is greater than 50 ft. 2006 - Downgraded to regular erosion site. Still actively eroding. Large old rotational failures in high bank on the downstream end. 2008 - Removed from inventory due to wide berm width does not meet criteria for an erosion site. 2010 - Added back to the inventory after 10 ft of bank erosion in the winter 2009 storm. Steep vertical face. 2011 - Bank has retreated an additional 2.5 ft from last year. New tree popouts and erosion throughout the site. 2012 - Site continues to worsen with new tree popouts and many sections of new erosion. 2013: No observed changes. [2013 Site ID: FHR_17-8_L]

Photo 1 of 1 : SP_2015_RD0784_532_7_20150325_00003.jpg



USACE 2013 Photo #1

| | | | | | |
|----------|-------------------------|--------------|----|------------------------|---------------|
| LM Start | 8.97 | Rating ** | M | Issue No. | 2 |
| LM End | 8.97 | Issue Type + | Ma | Location * | LS |
| Category | Earthen Levee | | | GPS Latitude/Longitude | |
| | | | | Start | End |
| Item | Vegetation | | | 39.009813 ° | 39.009813 ° |
| | | | | -121.579082 ° | -121.579082 ° |
| DWR ID | DWR RD0784 02B s 2015 2 | | | | |

Action/Comments

Control annual grass and weeds on the levee slopes and easements.

No Photos

| | | | | |
|--|--|---|--|---|
| * Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown | | ** Rating A : Acceptable N : Not Inspected/Rated M : Minimally Acceptable C : Corrected U : Unacceptable A/W : Acceptable but Monitor & Maintain | | + Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement |
|--|--|---|--|---|

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2015

Reclamation District No. 0784 Plumas Lake

| Waterway | Bank | Unit Miles | Inspection Start/End | Inspector |
|----------------------------|------|------------|--------------------------|------------------|
| Unit No. 02B Feather River | Left | 3.95 | 03/25/2015 03/25/2015 | Michael Pitta |

| | | | | | |
|---|---------------------------|--------------|----|------------------------|---------------|
| LM Start | 8.97 | Rating ** | M | Issue No. | 3 |
| LM End | 8.97 | Issue Type + | Ma | Location * | WS |
| Category | Earthen Levee | | | GPS Latitude/Longitude | |
| | | | | Start | End |
| Item | Vegetation | | | 39.009813 ° | 39.009813 ° |
| | | | | -121.579082 ° | -121.579082 ° |
| DWR ID | DWR_RD0784_02B_s _ 2015_3 | | | | |
| Action/Comments | | | | | |
| Control annual grass and weeds on the levee slopes and easements. | | | | | |

Photo 1 of 1 : SP_2015_RD0784_532_3_20150330_00002.jpg



Waterside facing downstream

| | | | | |
|--|--|---|--|---|
| * Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown | | ** Rating A : Acceptable N : Not Inspected/Rated M : Minimally Acceptable C : Corrected U : Unacceptable A/W : Acceptable but Monitor & Maintain | | + Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement |
|--|--|---|--|---|

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2015

Reclamation District No. 0784 Plumas Lake

| Waterway | Bank | Unit Miles | Inspection Start/End | Inspector |
|-------------------------|-------|------------|--------------------------|------------------|
| Unit No. 03A Bear River | Right | 0.78 | 03/25/2015 03/26/2015 | Michael Pitta |

| | | | | | |
|---|--------------------------|--------------|-----|------------------------|---------------|
| LM Start | 2.52 | Rating ** | A/W | Issue No. | 4 |
| LM End | 2.52 | Issue Type + | Ma | Location * | WS |
| Category | Earthen Levee | | | GPS Latitude/Longitude | |
| | | | | Start | End |
| Item | Vegetation | | | 38.971682 ° | 38.971682 ° |
| | | | | -121.546682 ° | -121.546682 ° |
| DWR ID | DWR_RD0784_03_s _ 2015_4 | | | | |
| Action/Comments | | | | | |
| Control annual grass and weeds on the levee slopes and easements. | | | | | |

Photo 1 of 1 : SP_2015_RD0784_180_4_20150429_00002.jpg



View of the vegetation on the waterside of the levee facing upstream.

| | | | | | |
|---|--------------------------|--------------|----|------------------------|---------------|
| LM Start | 2.52 | Rating ** | A | Issue No. | 5 |
| LM End | 2.52 | Issue Type + | Ma | Location * | LS |
| Category | Earthen Levee | | | GPS Latitude/Longitude | |
| | | | | Start | End |
| Item | Vegetation | | | 38.971682 ° | 38.971682 ° |
| | | | | -121.546682 ° | -121.546682 ° |
| DWR ID | DWR_RD0784_03_s _ 2015_5 | | | | |
| Action/Comments | | | | | |
| Control annual grass and weeds on the levee slopes and easements. | | | | | |

No Photos

| | | | | |
|--|--|---|--|---|
| * Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown | | ** Rating A : Acceptable N : Not Inspected/Rated M : Minimally Acceptable C : Corrected U : Unacceptable A/W : Acceptable but Monitor & Maintain | | + Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement |
|--|--|---|--|---|

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2015

Reclamation District No. 0784 Plumas Lake

| Waterway | Bank | Unit Miles | Inspection Start/End | Inspector |
|-------------------------|-------|------------|--------------------------|------------------|
| Unit No. 03B Bear River | Right | 1.49 | 03/26/2015 03/26/2015 | Michael Pitta |

| | | | | | |
|---|--------------------------|--------------|----|------------------------|---------------|
| LM Start | 3.41 | Rating ** | M | Issue No. | 6 |
| LM End | 4.83 | Issue Type + | Ma | Location * | WS |
| Category | Earthen Levee | | | GPS Latitude/Longitude | |
| | | | | Start | End |
| Item | Vegetation | | | 38.974255 ° | 38.985490 ° |
| | | | | -121.531433 ° | -121.510663 ° |
| DWR ID | DWR_RD0784_03_s _ 2015_6 | | | | |
| Action/Comments | | | | | |
| Control annual grass and weeds on the levee slopes and easements. | | | | | |

No Photos

| | | | | | |
|---|--------------------------|--------------|----|------------------------|---------------|
| LM Start | 3.73 | Rating ** | M | Issue No. | 7 |
| LM End | 4.83 | Issue Type + | Ma | Location * | LS |
| Category | Earthen Levee | | | GPS Latitude/Longitude | |
| | | | | Start | End |
| Item | Vegetation | | | 38.974797 ° | 38.985490 ° |
| | | | | -121.525840 ° | -121.510663 ° |
| DWR ID | DWR_RD0784_03_s _ 2015_7 | | | | |
| Action/Comments | | | | | |
| Control annual grass and weeds on the levee slopes and easements. | | | | | |

No Photos

| | | | | | |
|--|---------------------------|--------------|----|------------------------|---------------|
| LM Start | 4.31 | Rating ** | M | Issue No. | 3 |
| LM End | 4.32 | Issue Type + | Ma | Location * | WS |
| Category | Supplemental | | | GPS Latitude/Longitude | |
| | | | | Start | End |
| Item | USACE Erosion Survey | | | 38.981400 ° | 38.981271 ° |
| | | | | -121.515848 ° | -121.515999 ° |
| DWR ID | DWR_RD0784_03A_f _ 2014_3 | | | | |
| Action/Comments | | | | | |
| Inspector Comments: 2009 - Small site which could be repaired with maintenance. Erosion into the levee toe, rock has started to fail. 2013: No observed changes. [2013 Site ID: BER_4-9_R] | | | | | |

No Photos

| | | | | |
|--|--|---|--|---|
| * Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown | | ** Rating A : Acceptable N : Not Inspected/Rated M : Minimally Acceptable C : Corrected U : Unacceptable A/W : Acceptable but Monitor & Maintain | | + Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement |
|--|--|---|--|---|

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2015

Reclamation District No. 0784 Plumas Lake

| Waterway | Bank | Unit Miles | Inspection Start/End | Inspector |
|-------------------------------|-------|------------|--------------------------|------------------|
| Unit No. 04 Interceptor Canal | Right | 6.33 | 03/25/2015 03/26/2015 | Michael Pitta |

| | | | | | |
|---|------------------------|--------------|----|------------------------|---------------|
| LM Start | 0.01 | Rating ** | A | Issue No. | 3 |
| LM End | 0.01 | Issue Type + | Ma | Location * | LS |
| Category | Earthen Levee | | | GPS Latitude/Longitude | |
| | | | | Start | End |
| Item | Vegetation | | | 38.974838 ° | 38.974838 ° |
| | | | | -121.535062 ° | -121.535062 ° |
| DWR ID | DWR_RD0784_04_s_2015_3 | | | | |
| Action/Comments | | | | | |
| Control annual grass and weeds on the levee slopes and easements. | | | | | |

No Photos

| | | | | | |
|---|------------------------|--------------|----|------------------------|---------------|
| LM Start | 0.01 | Rating ** | A | Issue No. | 4 |
| LM End | 0.01 | Issue Type + | Ma | Location * | WS |
| Category | Earthen Levee | | | GPS Latitude/Longitude | |
| | | | | Start | End |
| Item | Vegetation | | | 38.974838 ° | 38.974838 ° |
| | | | | -121.535062 ° | -121.535062 ° |
| DWR ID | DWR_RD0784_04_s_2015_4 | | | | |
| Action/Comments | | | | | |
| Control annual grass and weeds on the levee slopes and easements. | | | | | |

No Photos

| | | | | | |
|---|------------------------|--------------|-----|------------------------|---------------|
| LM Start | 5.10 | Rating ** | A/W | Issue No. | 5 |
| LM End | 5.57 | Issue Type + | Ma | Location * | LS |
| Category | Earthen Levee | | | GPS Latitude/Longitude | |
| | | | | Start | End |
| Item | Vegetation | | | 39.048223 ° | 39.048223 ° |
| | | | | -121.542410 ° | -121.542410 ° |
| DWR ID | DWR_RD0784_04_s_2015_5 | | | | |
| Action/Comments | | | | | |
| Control annual grass and weeds on the levee slopes and easements. | | | | | |

Photo 1 of 1 : SP_2015_RD0784_181_5_20150429_00004.jpg



View of the vegetation on the landside of the levee facing upstream.

| | | | | |
|--|--|---|--|---|
| * Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown | | ** Rating A : Acceptable N : Not Inspected/Rated M : Minimally Acceptable C : Corrected U : Unacceptable A/W : Acceptable but Monitor & Maintain | | + Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement |
|--|--|---|--|---|

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2015

Reclamation District No. 0784 Plumas Lake

| Waterway | Bank | Unit Miles | Inspection Start/End | Inspector |
|-------------------------------|-------|------------|--------------------------|------------------|
| Unit No. 04 Interceptor Canal | Right | 6.33 | 03/25/2015 03/26/2015 | Michael Pitta |

| | | | | | |
|---|--------------------------|--------------|----|------------------------|---------------|
| LM Start | 5.94 | Rating ** | M | Issue No. | 7 |
| LM End | 6.23 | Issue Type + | Ma | Location * | LS |
| Category | Earthen Levee | | | GPS Latitude/Longitude | |
| | | | | Start | End |
| Item | Vegetation | | | 39.058635 ° | 39.058517 ° |
| | | | | -121.544995 ° | -121.550295 ° |
| DWR ID | DWR_RD0784_04_s _ 2015_7 | | | | |
| Action/Comments | | | | | |
| Control annual grass and weeds on the levee slopes and easements. | | | | | |

Photo 1 of 1 : SP_2015_RD0784_181_7_20150330_00003.jpg



Landside facing upstream

| | | | | |
|--|--|---|--|---|
| * Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown | | ** Rating A : Acceptable N : Not Inspected/Rated M : Minimally Acceptable C : Corrected U : Unacceptable A/W : Acceptable but Monitor & Maintain | | + Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement |
|--|--|---|--|---|

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2015

Reclamation District No. 0784 Plumas Lake

| Waterway | Bank | Unit Miles | Inspection Start/End | Inspector |
|-------------------------------|------|------------|--------------------------|------------------|
| Unit No. 05 Interceptor Canal | Left | 4.19 | 03/26/2015 03/26/2015 | Michael Pitta |

| | | | | | |
|---|-------------------------|--------------|----|------------------------|---------------|
| LM Start | 0.01 | Rating ** | M | Issue No. | 14 |
| LM End | 0.54 | Issue Type + | Ma | Location * | WS |
| Category | Earthen Levee | | | GPS Latitude/Longitude | |
| | | | | Start | End |
| Item | Vegetation | | | 38.974490 ° | 38.982137 ° |
| | | | | -121.532510 ° | -121.534167 ° |
| DWR ID | DWR_RD0784_05_s_2015_14 | | | | |
| Action/Comments | | | | | |
| Control annual grass and weeds on the levee slopes and easements. | | | | | |

No Photos

| | | | | | |
|---|-------------------------|--------------|----|------------------------|---------------|
| LM Start | 0.06 | Rating ** | M | Issue No. | 13 |
| LM End | 0.54 | Issue Type + | Ma | Location * | LS |
| Category | Earthen Levee | | | GPS Latitude/Longitude | |
| | | | | Start | End |
| Item | Vegetation | | | 38.975202 ° | 38.982137 ° |
| | | | | -121.532810 ° | -121.534167 ° |
| DWR ID | DWR_RD0784_05_s_2015_13 | | | | |
| Action/Comments | | | | | |
| Control annual grass and weeds on the levee slopes and easements. | | | | | |

Photo 1 of 1 : SP_2015_RD0784_182_13_20150330_00004.jpg



Landside facing downstream

| | | | | | |
|---|-------------------------|--------------|-----|------------------------|---------------|
| LM Start | 0.54 | Rating ** | A/W | Issue No. | 11 |
| LM End | 4.14 | Issue Type + | Ma | Location * | LS |
| Category | Earthen Levee | | | GPS Latitude/Longitude | |
| | | | | Start | End |
| Item | Vegetation | | | 38.982137 ° | 39.020460 ° |
| | | | | -121.534167 ° | -121.510012 ° |
| DWR ID | DWR_RD0784_05_s_2015_11 | | | | |
| Action/Comments | | | | | |
| Control annual grass and weeds on the levee slopes and easements. | | | | | |

Photo 1 of 1 : SP_2015_RD0784_182_11_20150330_00003.jpg



Landside facing downstream

| | | | | |
|--|--|---|--|---|
| * Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown | | ** Rating A : Acceptable N : Not Inspected/Rated M : Minimally Acceptable C : Corrected U : Unacceptable A/W : Acceptable but Monitor & Maintain | | + Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement |
|--|--|---|--|---|

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2015

Reclamation District No. 0784 Plumas Lake

| Waterway | Bank | Unit Miles | Inspection Start/End | Inspector |
|-------------------------------|------|------------|--------------------------|------------------|
| Unit No. 05 Interceptor Canal | Left | 4.19 | 03/26/2015 03/26/2015 | Michael Pitta |

| | | | | | |
|---|---------------------------|--------------|-----|------------------------|---------------|
| LM Start | 0.54 | Rating ** | A/W | Issue No. | 12 |
| LM End | 4.14 | Issue Type + | Ma | Location * | WS |
| Category | Earthen Levee | | | GPS Latitude/Longitude | |
| | | | | Start | End |
| Item | Vegetation | | | 38.982137 ° | 39.020460 ° |
| | | | | -121.534167 ° | -121.510012 ° |
| DWR ID | DWR_RD0784_05_s _ 2015_12 | | | | |
| Action/Comments | | | | | |
| Control annual grass and weeds on the levee slopes and easements. | | | | | |

No Photos

| | | | | |
|--|--|---|--|---|
| * Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown | | ** Rating A : Acceptable N : Not Inspected/Rated M : Minimally Acceptable C : Corrected U : Unacceptable A/W : Acceptable but Monitor & Maintain | | + Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement |
|--|--|---|--|---|

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2015

Reclamation District No. 0784 Plumas Lake

| Waterway | Bank | Unit Miles | Inspection Start/End | Inspector |
|-----------------------------|-------|------------|--------------------------|------------------|
| Unit No. 06 South Dry Creek | Right | 0.25 | 03/26/2015 03/26/2015 | Michael Pitta |

| | | | | | |
|---|--------------------------|--------------|----|------------------------|---------------|
| LM Start | 0.00 | Rating ** | M | Issue No. | 8 |
| LM End | 0.25 | Issue Type + | Ma | Location * | WS |
| Category | Earthen Levee | | | GPS Latitude/Longitude | |
| | | | | Start | End |
| Item | Vegetation | | | 38.985647 ° | 38.987603 ° |
| | | | | -121.510458 ° | -121.506583 ° |
| DWR ID | DWR_RD0784_06_s _ 2015_8 | | | | |
| Action/Comments | | | | | |
| Control annual grass and weeds on the levee slopes and easements. | | | | | |

No Photos

| | | | | | |
|---|--------------------------|--------------|----|------------------------|---------------|
| LM Start | 0.00 | Rating ** | M | Issue No. | 9 |
| LM End | 0.25 | Issue Type + | Ma | Location * | LS |
| Category | Earthen Levee | | | GPS Latitude/Longitude | |
| | | | | Start | End |
| Item | Vegetation | | | 38.985647 ° | 38.987603 ° |
| | | | | -121.510458 ° | -121.506583 ° |
| DWR ID | DWR_RD0784_06_s _ 2015_9 | | | | |
| Action/Comments | | | | | |
| Control annual grass and weeds on the levee slopes and easements. | | | | | |

Photo 1 of 1 : SP_2015_RD0784_183_9_20150330_00004.jpg



Landside facing upstream

| | | | | |
|--|--|---|--|---|
| * Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown | | ** Rating A : Acceptable N : Not Inspected/Rated M : Minimally Acceptable C : Corrected U : Unacceptable A/W : Acceptable but Monitor & Maintain | | + Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement |
|--|--|---|--|---|

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2015

Reclamation District No. 0784 Plumas Lake

| Waterway | Bank | Unit Miles | Inspection Start/End | Inspector |
|------------------------|------|------------|--------------------------|------------------|
| Unit No. 07 Yuba River | Left | 3.82 | 03/25/2015 03/25/2015 | Michael Pitta |

| | | | | | |
|---|--------------------------|--------------|-----|------------------------|---------------|
| LM Start | 0.00 | Rating ** | A/W | Issue No. | 2 |
| LM End | 3.73 | Issue Type + | Ma | Location * | LS |
| Category | Earthen Levee | | | GPS Latitude/Longitude | |
| | | | | Start | End |
| Item | Vegetation | | | | ° 39.164987 |
| | | | | | ° -121.496795 |
| DWR ID | DWR_RD0784_07_s _ 2015_2 | | | | |
| Action/Comments | | | | | |
| Control annual grass and weeds on the levee slopes and easements. | | | | | |

No Photos

| | | | | | |
|---|--------------------------|--------------|-----|------------------------|---------------|
| LM Start | 0.00 | Rating ** | A/W | Issue No. | 3 |
| LM End | 3.73 | Issue Type + | Ma | Location * | WS |
| Category | Earthen Levee | | | GPS Latitude/Longitude | |
| | | | | Start | End |
| Item | Vegetation | | | 39.134403 ° | 39.164987 ° |
| | | | | -121.552673 ° | -121.496795 ° |
| DWR ID | DWR_RD0784_07_s _ 2015_3 | | | | |
| Action/Comments | | | | | |
| Control annual grass and weeds on the levee slopes and easements. | | | | | |

Photo 1 of 1 : SP_2015_RD0784_184_3_20150330_00002.jpg



Left bank waterside, facing upstream.

| | | | | |
|--|--|---|--|---|
| * Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown | | ** Rating A : Acceptable N : Not Inspected/Rated M : Minimally Acceptable C : Corrected U : Unacceptable A/W : Acceptable but Monitor & Maintain | | + Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement |
|--|--|---|--|---|

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2015

Reclamation District No. 0784 Plumas Lake

| Waterway | Bank | Unit Miles | Inspection Start/End | Inspector |
|--------------------------|-------|------------|--------------------------|------------------|
| Unit No. 08 Three Rivers | Right | 1.93 | 03/25/2015 03/25/2015 | Michael Pitta |

| | | | | | |
|---|------------------------|--------------|----|------------------------|---------------|
| LM Start | 0.05 | Rating ** | A | Issue No. | 1 |
| LM End | 0.05 | Issue Type + | Ma | Location * | LS |
| Category | Earthen Levee | | | GPS Latitude/Longitude | |
| | | | | Start | End |
| Item | Vegetation | | | 38.955502 ° | 38.955502 ° |
| | | | | -121.574117 ° | -121.574117 ° |
| DWR ID | DWR_RD0784_08_s_2015_1 | | | | |
| Action/Comments | | | | | |
| Control annual grass and weeds on the levee slopes and easements. | | | | | |

No Photos

| | | | | | |
|---|------------------------|--------------|----|------------------------|---------------|
| LM Start | 0.05 | Rating ** | A | Issue No. | 2 |
| LM End | 0.05 | Issue Type + | Ma | Location * | WS |
| Category | Earthen Levee | | | GPS Latitude/Longitude | |
| | | | | Start | End |
| Item | Vegetation | | | 38.955502 ° | 38.955502 ° |
| | | | | -121.574117 ° | -121.574117 ° |
| DWR ID | DWR_RD0784_08_s_2015_2 | | | | |
| Action/Comments | | | | | |
| Control annual grass and weeds on the levee slopes and easements. | | | | | |

Photo 1 of 1 : SP_2015_RD0784_437_2_20150330_00002.jpg



Waterside facing downstream

| | | | | |
|--|--|---|--|---|
| * Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown | | ** Rating A : Acceptable N : Not Inspected/Rated M : Minimally Acceptable C : Corrected U : Unacceptable A/W : Acceptable but Monitor & Maintain | | + Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement |
|--|--|---|--|---|

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2015

Reclamation District No. 0784 Plumas Lake

| Waterway | Bank | Unit Miles | Inspection Start/End | Inspector |
|---------------------------|------|------------|--------------------------|------------------|
| Unit No. 09 Feather River | Left | 5.71 | 03/25/2015 03/25/2015 | Michael Pitta |

| | | | | | |
|---|--------------------------|--------------|----|------------------------|---------------|
| LM Start | 0.21 | Rating ** | A | Issue No. | 1 |
| LM End | 0.21 | Issue Type + | Ma | Location * | LS |
| Category | Earthen Levee | | | GPS Latitude/Longitude | |
| | | | | Start | End |
| Item | Vegetation | | | 39.087308 ° | 39.087308 ° |
| | | | | -121.585417 ° | -121.585417 ° |
| DWR ID | DWR_RD0784_09_s _ 2015_1 | | | | |
| Action/Comments | | | | | |
| Control annual grass and weeds on the levee slopes and easements. | | | | | |

Photo 1 of 1 : SP_2015_RD0784_530_1_20150330_00002.jpg



Landside facing downstream

| | | | | | |
|---|--------------------------|--------------|----|------------------------|---------------|
| LM Start | 0.21 | Rating ** | A | Issue No. | 4 |
| LM End | 0.21 | Issue Type + | Ma | Location * | WS |
| Category | Earthen Levee | | | GPS Latitude/Longitude | |
| | | | | Start | End |
| Item | Vegetation | | | 39.087308 ° | 39.087308 ° |
| | | | | -121.585417 ° | -121.585417 ° |
| DWR ID | DWR_RD0784_09_s _ 2015_4 | | | | |
| Action/Comments | | | | | |
| Control annual grass and weeds on the levee slopes and easements. | | | | | |

No Photos

| | | | | |
|--|--|---|--|---|
| * Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown | | ** Rating A : Acceptable N : Not Inspected/Rated M : Minimally Acceptable C : Corrected U : Unacceptable A/W : Acceptable but Monitor & Maintain | | + Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement |
|--|--|---|--|---|