

**Flood Control Project Maintenance  
Levee Inspections**

## Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2015

### Reclamation District No. 0787 Fair

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Colusa Basin Drain	Left	4.45	04/23/2015 04/23/2015	Jai Lor

LM Start		Rating **	A	Issue No.	7
LM End		Issue Type +	Ma	Location *	N/A
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Emergency Supplies & Equipment			°	°
				°	°
DWR ID	DWR_RD0787_01_s _ 2013_7				
Action/Comments					
Inspector Comments: RD 787 shares flood resources with RD 108 with a stockpile of flood response materials.					

No Photos

LM Start		Rating **	A	Issue No.	8
LM End		Issue Type +	Ma	Location *	N/A
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Operations & Maintenance Manuals			°	°
				°	°
DWR ID	DWR_RD0787_01_s _ 2013_8				
Action/Comments					
Inspector Comments: RD 787 is current with Owner's, O&M manuals.					

No Photos

LM Start		Rating **	M	Issue No.	10
LM End		Issue Type +	Ma	Location *	N/A
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Flood Preparedness & Training			°	°
				°	°
DWR ID	DWR_RD0787_01_s _ 2012_10				
Action/Comments					
Inspector Comments: RD 787 works jointly with RD 108 on training and flood response.					

No Photos

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

## Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2015

### Reclamation District No. 0787 Fair

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Colusa Basin Drain	Left	4.45	04/23/2015 04/23/2015	Jai Lor

LM Start	0.01	Rating **	M	Issue No.	4
LM End	4.42	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.799561 °	38.822437 °
				-121.725530 °	-121.795560 °
DWR ID	DWR_RD0787_01_s_2015_4				
Action/Comments					
Control annual grass and weeds on the levee slopes and easements.					

Photo 1 of 1 : SP\_2015\_RD0787\_212\_4\_20150423\_00009.jpg



View of the vegetation on the landward side of the levee looking upstream. Spring 2015.

LM Start	0.01	Rating **	M	Issue No.	6
LM End	4.42	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.799561 °	38.822441 °
				-121.725530 °	-121.795567 °
DWR ID	DWR_RD0787_01_s_2015_6				
Action/Comments					
Control annual grass and weeds on the levee slopes and easements.					

No Photos

LM Start	0.39	Rating **	M	Issue No.	1
LM End	0.50	Issue Type +	Ma	Location *	WS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	USACE Erosion Survey			38.795931 °	38.795268 °
				-121.730627 °	-121.732566 °
DWR ID	DWR_RD0787_01_f_2014_1				
Action/Comments					
Inspector Comments: 2011 - Large scallops throughout the entire reach. Toe scour due to tree pop-outs, resulting in a steepening slope. The reduced resistive forces plus clay levee may increase the loading. Additional erosion due to human use. 2013: Site is part of the extended inventory, last inspected 2011. [2013 Site ID: CBD_0-5_L]					

No Photos

* Location		** Rating		+ Issue Type	
LS : Land Side	N/A : Not Applicable	A : Acceptable	N : Not Inspected/Rated	Ma : Maintenance Deficiency	
WS : Water Side		M : Minimally Acceptable	C : Corrected	Ob : Design & System Obsolescence	
CR : Crown		U : Unacceptable	A/W : Acceptable but Monitor & Maintain	En : Enforcement	

**Flood Control Project Maintenance  
Levee Inspections**

## Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2015

### Reclamation District No. 0787 Fair

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Colusa Basin Drain	Left	4.45	04/23/2015 04/23/2015	Jai Lor

LM Start	0.67	Rating **	M	Issue No.	2
LM End	0.85	Issue Type +	Ma	Location *	WS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	USACE Erosion Survey			38.795486 °	38.796225 °
				-121.735647 °	-121.738902 °
DWR ID	DWR_RD0787_01_f_2014_2				
Action/Comments					
Inspector Comments: 2011 - Large scallops throughout the entire reach. Toe scour due to tree pop-outs, resulting in a steepening slope. The reduced resistive forces plus clay levee may increase the loading. 2013: Site is part of the extended inventory, last inspected 2011. [2013 Site ID: CBD_0-9_L]					

No Photos

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown		<b>** Rating</b> A : Acceptable                      N : Not Inspected/Rated M : Minimally Acceptable        C : Corrected U : Unacceptable                  A/W : Acceptable but Monitor & Maintain		<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---