

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2023

Reclamation District No. 0900 West Sacramento

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	7.70	10/17/2023 10/17/2023	Marvin Marshall

LM Start	0.00	Rating **	A	Issue No.	6
LM End	0.00	Issue Type +	Ma	Location *	N/A
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Operations & Maintenance Manuals			°	°
				°	°
DWR ID	DWR_RD0900_01_f_2018_6				
Comment Code					
OM : O&M Manuals					
Inspector Comment					
This LMA has the updated O&M manuals for the district.					

No Photos

LM Start	0.00	Rating **	A	Issue No.	12
LM End	0.00	Issue Type +	Ma	Location *	N/A
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Emergency Supplies & Equipment			38.580931°	38.580931°
				-121.509693°	-121.509693°
DWR ID	DWR_RD0900_01_s_2013_12				
Comment Code					
ES : Emergency Supplies & Equipment					
Inspector Comment					
This LMA has an adequate amount of sandbags, sand, and various flood fight supplies in their possession.					

No Photos

LM Start	0.00	Rating **	A	Issue No.	16
LM End	0.00	Issue Type +	Ma	Location *	N/A
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Flood Preparedness & Training			°	°
				°	°
DWR ID	DWR_RD0900_01_s_2013_16				
Comment Code					
FP : Flood Preparedness & Training					
Inspector Comment					
The LMA attended November 2023 Flood Fighting Methods Training.					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2023

Reclamation District No. 0900 West Sacramento

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	7.70	10/17/2023 10/17/2023	Marvin Marshall

LM Start	0.50	Rating **	M	Issue No.	21
LM End	0.50	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			38.574733°	38.574733°
				-121.514061°	-121.514061°
DWR ID	DWR_RD0900_01_s_2023_21				
Comment Code					
T2 : Tree or limb.					
Inspector Comment					
Remove fallen limbs/trees from the crown/WS shoulder.					

Photo 1 of 1 : FA_2023_RD0900_230_21_20230905_00001.jpg



Logs on the WS shoulder. Spring 2023

LM Start	0.84	Rating **	A/W	Issue No.	39
LM End	0.84	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Erosion / Bank Caving			38.571150°	38.571150°
				-121.518137°	-121.518137°
DWR ID	DWR_RD0900_01_s_2020_39				
Comment Code					
E1 : Note and monitor erosion site.					
Inspector Comment					
The site is on private land and not accessible for inspection.					

No Photos

LM Start	6.89	Rating **	M	Issue No.	15
LM End	6.89	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			38.514900°	38.514900°
				-121.552500°	-121.552500°
DWR ID	DWR_RD0900_01_f_2023_15				
Comment Code					
A1 : Exterminate rodents and backfill and compact or grout burrows.					
Inspector Comment					
Exterminate rodents and fill burrows.					

Photo 1 of 1 : FA_2023_RD0900_230_15_20231017_00035.jpg



Burrows on the LS berm. Fall 2023

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable		N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement	
--	--	--	--	---	--	---	--

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2023

Reclamation District No. 0900 West Sacramento

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Yolo Bypass	Left	5.26	10/17/2023 10/17/2023	Marvin Marshall

LM Start	5.09	Rating **	U	Issue No.	3
LM End	5.09	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Slope Stability			38.514355°	38.514355°
				-121.582165°	-121.582165°
DWR ID	DWR_RD0900_02_s_2023_3				
Comment Code					
S1 : Repair slope instability.					
Inspector Comment					
Fall 2023: USACE has visited the site for PL 84-99 repair. PGE has relocated pole.					
Spring 2023:Levee slip at power pole. Scarp ~50' long, 5' vertical face, 10' separation. LMA has placed raincoat.					

Photo 1 of 1 : FA_2023_RD0900_231_3_20231017_00022.jpg



Slope slip on the LS. Fall 2023

LM Start	5.24	Rating **	U	Issue No.	18
LM End	5.24	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Slope Stability			38.512197°	38.512197°
				-121.582143°	-121.582143°
DWR ID	DWR_RD0900_02_f_2020_18				
Comment Code					
S1 : Repair slope instability.					
Inspector Comment					
Fall 2023: USACE has visited the site for PL 84-99 repair.					
Spring 2023: Slope slip, ~50 long, 4' vertical face, 5' seperation					

Photo 1 of 1 : FA_2023_RD0900_231_18_20231017_00023.jpg



Slope slip on the LS. Fall 2023

* Location LS: Land Side N/A: Not Applicable WS: Water Side CR: Crown	** Rating A: Acceptable M: Minimally Acceptable U: Unacceptable	N: Not Inspected/Rated C: Corrected A/W: Acceptable but Monitor & Maintain	+ Issue Type Ma: Maintenance Deficiency Ob: Design & System Obsolescence En: Enforcement
--	---	---	--