

**Flood Control Project Maintenance
Levee Inspections**
LMA District Cover Sheet
Spring 2008 Levee Inspection Results

Reclamation District No. 0999

	Spring (March - May)	Summer ** (June - August)	Fall (September - November)	Winter ** (December - February)
* Overall LMA Rating (Fall Only)				

** Non-receipt of Summer or Winter Inspection Reports may effect overall annual rating.

* **SPRING INSPECTIONS:** Overall maintenance ratings are not determined for the spring inspection results. Individual maintenance deficiencies are rated using the same criteria in the spring and in the fall.

FALL INSPECTIONS: The overall maintenance rating shown above is based on operation and maintenance deficiencies identified within the attached unit inspection reports.

Comments

**Flood Control Project Maintenance
Levee Inspections
Unit Cover Sheet
Spring 2008 Levee Inspection Results
Reclamation District No. 0999**

Waterway		Bank	Unit Miles
Unit No. 01 Yolo Bypass		Left	15.40

	Spring (March - May)	Summer (June - August)	Fall (September - November)	Winter (December - February)
Date of Inspection	3/5/2008			
DWR Inspector	Richard Willoughby			
Accompanied By				
Unit Maintenance Rating (Fall Only)				

Check one:

During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.

During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

Comments

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :

DWR Summer/Winter Inspection Reports
3310 El Camino Avenue, Room LL-30
Sacramento, CA 95821-9000.

X _____
Signature of LMA Representative Date

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2008

Reclamation District No. 0999

Waterway			Bank	Unit Miles	Inspection Date	Inspector
Unit No. 01 Yolo Bypass			Left	15.40	03/05/2008	Richard Willoughby

LMR Line	Levee Mile		Category	Item	Location*	Rating**	Action/Comment	GPS Latitude/Longitude		Photo	Issue
	Start	End						Start	End		
1	0.12	15.43	Earthen Levee	Vegetation	LS	M	Control annual grass and weeds on the levee slopes and easements.	38.503642 ° -121.582082 °	38.290360 ° -121.644795 °		2
2	0.12	15.43	Earthen Levee	Vegetation	WS	M	Control annual grass and weeds on the levee slopes and easements.	38.503637 ° -121.582080 °	38.290360 ° -121.644772 °		3
3	1.75	1.77	Earthen Levee	Trim / Thin Trees	WS	M	Trim trees to at least five feet above ground level.	38.480082 ° -121.580930 °	38.479788 ° -121.580918 °		4
4	1.78	1.78	Earthen Levee	Encroachments	LS	M	Material Inspector Comments: Material should be removed or spread out along slope.	38.479647 ° -121.580905 °	38.479647 ° -121.580905 °	Y	5
5	1.90	1.96	Earthen Levee	Trim / Thin Trees	LS	M	Trim trees to at least five feet above ground level.	38.477867 ° -121.580702 °	38.476985 ° -121.580640 °		6
6	2.15	2.15	Earthen Levee	Trim / Thin Trees	WS	M	Trim trees to at least five feet above ground level.	38.474258 ° -121.580528 °	38.474258 ° -121.580528 °		7
7	2.20	2.21	Earthen Levee	Trim / Thin Trees	WS	M	Thin trees to allow visibility of the ground and room to flood fight.	38.473542 ° -121.580793 °	38.473417 ° -121.580885 °		8
8	4.15	4.21	Earthen Levee	Encroachments	WS	M	Prunings	38.447017 ° -121.593338 °	38.446288 ° -121.593657 °		9
9	4.17	4.18	Earthen Levee	Encroachments	LS	M	Prunings	38.446787 ° -121.593433 °	38.446653 ° -121.593492 °		10
10	4.24	4.28	Earthen Levee	Trim / Thin Trees	LS	M	Thin trees to allow visibility of the ground and room to flood fight.	38.445842 ° -121.593857 °	38.445268 ° -121.594118 °		11
11	4.57	4.61	Earthen Levee	Encroachments	WS	M	Prunings Inspector Comments: Firewood & Pruning shoulder & slope.	38.441270 ° -121.595962 °	38.440775 ° -121.596188 °	Y	12
12	4.69	4.69	Earthen Levee	Encroachments	WS	M	Prunings	38.439677 ° -121.596702 °	38.439677 ° -121.596702 °	Y	13
13	4.85	4.85	Earthen Levee	Encroachments	WS	M	Firewood	38.437515 ° -121.597637 °	38.437515 ° -121.597637 °		14
14	5.31	5.31	Earthen Levee	Encroachments	WS	M	Tree or limb	38.431230 ° -121.600562 °	38.431230 ° -121.600562 °	Y	15
15	6.43	6.43	Earthen Levee	Encroachments	LS	M	Tree or limb	38.416000 ° -121.607635 °	38.416000 ° -121.607635 °	Y	16
16	6.55	6.60	Earthen Levee	Trim / Thin Trees	LS	M	Trim trees to at least five feet above ground level.	38.414300 ° -121.608450 °	38.413698 ° -121.608762 °		17
17	6.55	6.60	Earthen Levee	Encroachments	LS	M	Prunings	38.414367 ° -121.608430 °	38.413698 ° -121.608762 °		18
18	9.02	9.31	Earthen Levee	Crown Surface / Depressions / Rutting	CR	M	Regrade the crown roadway for proper drainage.	38.380632 ° -121.624165 °	38.376718 ° -121.625955 °		19
19	9.77	9.96	Earthen Levee	Encroachments	LS	PO	Fences Inspector Comments: Fence at landside shoulder	38.370502 ° -121.628975 °	38.367903 ° -121.630017 °		20

<p>* Location</p> <p>LS : Land Side WS : Water Side CR : Crown</p>	<p>** Rating</p> <p>A : Acceptable M : Minimally Acceptable U : Unacceptable</p> <p>PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected</p>
---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2008

Reclamation District No. 0999

Waterway				Bank	Unit Miles	Inspection Date	Inspector				
Unit No. 01 Yolo Bypass				Left	15.40	03/05/2008	Richard Willoughby				
LMR Line	Levee Mile		Category	Item	Location*	Rating**	Action/Comment	GPS Latitude/Longitude		Photo	Issue
	Start	End						Start	End		
20	9.88	9.88	Earthen Levee	Trim / Thin Trees	WS	M	Trim trees to at least five feet above ground level.	38.368912 ° -121.629563 °	38.368912 ° -121.629563 °	Y	21
21	9.96	10.59	Earthen Levee	Encroachments	LS	M	Tree or limb	38.367903 ° -121.630017 °	38.359297 ° -121.634258 °		22
22	10.83	11.07	Earthen Levee	Trim / Thin Trees	WS	M	Trim trees to at least five feet above ground level.	38.356077 ° -121.635598 °	38.352640 ° -121.637078 °		23
23	10.87	10.92	Earthen Levee	Encroachments	LS	M	Tree or limb	38.355450 ° -121.635867 °	38.354703 ° -121.636160 °		24
24	13.23	13.47	Earthen Levee	Crown Surface / Depressions / Rutting	CR	M	Regrade the crown roadway for proper drainage.	38.322215 ° -121.644983 °	38.318720 ° -121.644955 °		25

<p>* Location</p> <p>LS : Land Side WS : Water Side CR : Crown</p>	<p>** Rating</p> <p>A : Acceptable M : Minimally Acceptable U : Unacceptable</p> <p>PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected</p>
---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2008

Reclamation District No. 0999

Waterway	Bank	Unit Miles	Inspection Date	Inspector
Unit No. 01 Yolo Bypass	Left	15.40	03/05/2008	Richard Willoughby

Levee Mile Report Line	4
Start Levee Mile	1.78
End Levee Mile	1.78
Location	
Category	Earthen Levee
Item	Encroachments
Material pile on waterside shoulder at LM 1.78	



Levee Mile Report Line	11
Start Levee Mile	4.57
End Levee Mile	4.61
Location	
Category	Earthen Levee
Item	Encroachments
Pruning & Firewood pile along waterside shoulder and slope at LM 1.56	



Levee Mile Report Line	12
Start Levee Mile	4.69
End Levee Mile	4.69
Location	
Category	Earthen Levee
Item	Encroachments
Prunings at waterward toe	



<p>* Location</p> <p>LS : Land Side WS : Water Side CR : Crown</p>	<p>** Rating</p> <p>A : Acceptable M : Minimally Acceptable U : Unacceptable</p>	<p>PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected</p>
---	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2008

Reclamation District No. 0999

Waterway	Bank	Unit Miles	Inspection Date	Inspector
Unit No. 01 Yolo Bypass	Left	15.40	03/05/2008	Richard Willoughby

Levee Mile Report Line	14
Start Levee Mile	5.31
End Levee Mile	5.31
Location	
Category	Earthen Levee
Item	Encroachments
Tree limb at waterward toe LM 5.31	



Levee Mile Report Line	15
Start Levee Mile	6.43
End Levee Mile	6.43
Location	
Category	Earthen Levee
Item	Encroachments
Down tree limbs on landward toe LM 6.43	



Levee Mile Report Line	20
Start Levee Mile	9.88
End Levee Mile	9.88
Location	
Category	Earthen Levee
Item	Trim / Thin Trees
Overgrown tree on waterward slope at LM 9.88	



* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected
--	--	--

**Flood Control Project Maintenance
Levee Inspections
Unit Cover Sheet
Spring 2008 Levee Inspection Results
Reclamation District No. 0999**

Waterway		Bank	Unit Miles
Unit No. 02 Miner Slough		Right	2.30

	Spring (March - May)	Summer (June - August)	Fall (September - November)	Winter (December - February)
Date of Inspection	3/5/2008			
DWR Inspector	Richard Willoughby			
Accompanied By				
Unit Maintenance Rating (Fall Only)				

Check one:

During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.

During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

Comments

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :

DWR Summer/Winter Inspection Reports
3310 El Camino Avenue, Room LL-30
Sacramento, CA 95821-9000.

X _____
Signature of LMA Representative Date

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2008

Reclamation District No. 0999

Waterway				Bank	Unit Miles	Inspection Date	Inspector
Unit No. 02 Miner Slough				Right	2.30	03/05/2008	Richard Willoughby

LMR Line	Levee Mile		Category	Item	Location*	Rating**	Action/Comment	GPS Latitude/Longitude		Photo	Issue
	Start	End						Start	End		
1	0.02	2.32	Earthen Levee	Vegetation	LS	M	Control annual grass and weeds on the levee slopes and easements.	38.290370 ° -121.644400 °	38.286780 ° -121.605877 °		2
2	0.02	2.32	Earthen Levee	Vegetation	WS	M	Control annual grass and weeds on the levee slopes and easements.	38.290377 ° -121.644420 °	38.286790 ° -121.605882 °		3
3	0.03	0.06	Earthen Levee	Encroachments	WS	PO	Landscaping	38.290382 ° -121.644335 °	38.290502 ° -121.643745 °		1
4	0.46	0.48	Earthen Levee	Vegetation	WS	M	Remove the wild growth other than native grasses from the levee slopes.	38.291538 ° -121.636622 °	38.291475 ° -121.636282 °		4
5	1.16	1.19	Earthen Levee	Encroachments	LS	M	Prunings	38.291180 ° -121.624657 °	38.291280 ° -121.624107 °		5
6	1.66	1.67	Earthen Levee	Trim / Thin Trees	WS	M	Thin trees to allow visibility of the ground and room to flood fight.	38.290312 ° -121.615638 °	38.290265 ° -121.615473 °		6
7	1.72	1.74	Earthen Levee	Trim / Thin Trees	WS	M	Trim trees to at least five feet above ground level.	38.289927 ° -121.614735 °	38.289740 ° -121.614497 °		7
8	1.72	1.75	Earthen Levee	Vegetation	LS	M	Elderberries are blocking visibility and flood fight capability.	38.289895 ° -121.614688 °	38.289595 ° -121.614337 °		8
9	1.77	1.80	Earthen Levee	Vegetation	WS	M	Remove the wild growth other than native grasses from the levee slopes.	38.289388 ° -121.614093 °	38.289057 ° -121.613660 °		9
10	1.81	1.87	Earthen Levee	Vegetation	LS	M	Remove the wild growth other than native grasses from the levee slopes.	38.289038 ° -121.613632 °	38.288780 ° -121.612485 °		10
11	1.95	1.95	Earthen Levee	Trim / Thin Trees	WS	M	Trim trees to at least five feet above ground level.	38.288735 ° -121.611128 °	38.288735 ° -121.611128 °		11

<p>* Location</p> <p>LS : Land Side WS : Water Side CR : Crown</p>	<p>** Rating</p> <p>A : Acceptable M : Minimally Acceptable U : Unacceptable</p> <p>PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected</p>
---	---

**Flood Control Project Maintenance
Levee Inspections
Unit Cover Sheet
Spring 2008 Levee Inspection Results
Reclamation District No. 0999**

Waterway		Bank	Unit Miles
Unit No. 03 Sutter Slough		Right	3.80

	Spring (March - May)	Summer (June - August)	Fall (September - November)	Winter (December - February)
Date of Inspection	3/5/2008			
DWR Inspector	Richard Willoughby			
Accompanied By				
Unit Maintenance Rating (Fall Only)				

Check one:

During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.

During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

Comments

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :

DWR Summer/Winter Inspection Reports
3310 El Camino Avenue, Room LL-30
Sacramento, CA 95821-9000.

X _____
Signature of LMA Representative Date

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2008

Reclamation District No. 0999

Waterway				Bank	Unit Miles	Inspection Date	Inspector
Unit No. 03 Sutter Slough				Right	3.80	03/05/2008	Richard Willoughby

LMR Line	Levee Mile		Category	Item	Location*	Rating**	Action/Comment	GPS Latitude/Longitude		Photo	Issue
	Start	End						Start	End		
1	0.01	0.03	Earthen Levee	Encroachments	WS	M	Prunings	38.286937 ° -121.605745 °	38.287145 ° -121.605573 °		2
2	0.01	3.74	Earthen Levee	Vegetation	LS	M	Control annual grass and weeds on the levee slopes and easements. Inspector Comments: Control on waterside also.	38.286907 ° -121.605765 °	38.332248 ° -121.584663 °		1
3	0.03	0.04	Earthen Levee	Trim / Thin Trees	LS	M	Trim trees to at least five feet above ground level.	38.287145 ° -121.605572 °	38.287267 ° -121.605478 °		4
4	0.04	0.05	Earthen Levee	Encroachments	LS	PO	Landscaping	38.287267 ° -121.605477 °	38.287395 ° -121.605378 °		5
5	0.11	0.15	Earthen Levee	Vegetation	WS	M	Remove the wild growth other than native grasses from the levee slopes.	38.288172 ° -121.604962 °	38.288745 ° -121.604695 °		6
6	0.44	0.44	Earthen Levee	Vegetation	WS	M	Remove the wild growth other than native grasses from the levee slopes.	38.292748 ° -121.604972 °	38.292748 ° -121.604972 °		7
7	0.64	0.64	Earthen Levee	Vegetation	LS	M	Elderberries are blocking visibility and flood fight capability.	38.295618 ° -121.605923 °	38.295618 ° -121.605923 °		8
8	0.67	0.69	Earthen Levee	Vegetation	WS	M	Remove the wild growth other than native grasses from the levee slopes.	38.296007 ° -121.605900 °	38.296328 ° -121.605798 °		9
9	0.92	0.92	Earthen Levee	Encroachments	LS	M	Prunings	38.299165 ° -121.603740 °	38.299165 ° -121.603740 °		10
10	1.35	1.54	Earthen Levee	Trim / Thin Trees	WS	M	Thin trees to allow visibility of the ground and room to flood fight.	38.304193 ° -121.600482 °	38.306502 ° -121.598877 °		11
11	1.59	1.62	Earthen Levee	Encroachments	WS	M	Material	38.307073 ° -121.598247 °	38.307492 ° -121.598122 °		12
12	2.02	2.10	Earthen Levee	Vegetation	LS	M	Remove the wild growth other than native grasses from the levee slopes.	38.311888 ° -121.596442 °	38.312592 ° -121.595280 °		13
13	2.11	2.11	Earthen Levee	Vegetation	WS	M	Remove the wild growth other than native grasses from the levee slopes.	38.312695 ° -121.595120 °	38.312695 ° -121.595120 °		14
14	2.65	2.72	Earthen Levee	Trim / Thin Trees	WS	M	Trim and thin trees to allow visibility of the ground and room to flood fight.	38.319402 ° -121.590748 °	38.320342 ° -121.590735 °		15
15	2.70	2.72	Earthen Levee	Encroachments	LS	PO	Landscaping	38.320105 ° -121.590765 °	38.320340 ° -121.590730 °		16
16	2.87	2.88	Earthen Levee	Trim / Thin Trees	WS	M	Trim trees to at least five feet above ground level.	38.322397 ° -121.590903 °	38.322595 ° -121.590837 °		17
17	2.90	2.96	Earthen Levee	Trim / Thin Trees	LS	M	Trim and thin trees to allow visibility of the ground and room to flood fight.	38.322765 ° -121.590775 °	38.323472 ° -121.590072 °		18
18	3.02	3.14	Earthen Levee	Trim / Thin Trees	LS	M	Trim and thin trees to allow visibility of the ground and room to flood fight.	38.323762 ° -121.589173 °	38.324410 ° -121.587055 °		19
19	3.18	3.21	Earthen Levee	Vegetation	LS	M	Remove the wild growth other than native grasses from the levee slopes.	38.324842 ° -121.586692 °	38.325352 ° -121.586383 °		20

<p>* Location</p> <p>LS : Land Side WS : Water Side CR : Crown</p>	<p>** Rating</p> <p>A : Acceptable M : Minimally Acceptable U : Unacceptable</p> <p>PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected</p>
---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2008

Reclamation District No. 0999

Waterway				Bank	Unit Miles	Inspection Date	Inspector
Unit No. 03 Sutter Slough				Right	3.80	03/05/2008	Richard Willoughby

LMR Line	Levee Mile		Category	Item	Location*	Rating**	Action/Comment	GPS Latitude/Longitude		Photo	Issue
	Start	End						Start	End		
20	3.64	3.67	Earthen Levee	Trim / Thin Trees	WS	M	Trim trees to at least five feet above ground level.	38.331162 ° -121.585785 °	38.331465 ° -121.585490 °		21
21	3.72	3.72	Earthen Levee	Encroachments	LS	PO	Landscaping	38.332035 ° -121.584800 °	38.332035 ° -121.584800 °		22

<p>* Location</p> <p>LS : Land Side WS : Water Side CR : Crown</p>	<p>** Rating</p> <p>A : Acceptable M : Minimally Acceptable U : Unacceptable</p> <p>PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected</p>
---	---

**Flood Control Project Maintenance
Levee Inspections
Unit Cover Sheet
Spring 2008 Levee Inspection Results
Reclamation District No. 0999**

Waterway		Bank	Unit Miles
Unit No. 04 Sacramento River		Right	1.20

	Spring (March - May)	Summer (June - August)	Fall (September - November)	Winter (December - February)
Date of Inspection	3/3/2008			
DWR Inspector	Richard Willoughby			
Accompanied By				
Unit Maintenance Rating (Fall Only)				

Check one:

During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.

During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

Comments

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :
 DWR Summer/Winter Inspection Reports
 3310 El Camino Avenue, Room LL-30
 Sacramento, CA 95821-9000.

X _____
 Signature of LMA Representative Date

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2008

Reclamation District No. 0999

Waterway				Bank	Unit Miles	Inspection Date	Inspector
Unit No. 04 Sacramento River				Right	1.20	03/03/2008	Richard Willoughby

LMR Line	Levee Mile		Category	Item	Location*	Rating**	Action/Comment	GPS Latitude/Longitude		Photo	Issue
	Start	End						Start	End		
1	0.01	0.05	Earthen Levee	Trim / Thin Trees	WS	M	Trim trees to at least five feet above ground level.	38.414198 ° -121.523082 °	38.414703 ° -121.523477 °		15
2	0.01	1.17	Earthen Levee	Vegetation	LS	M	Control annual grass and weeds on the levee slopes and easements.	38.414173 ° -121.523140 °	38.428973 ° -121.533040 °		1
3	0.04	0.04	Earthen Levee	Trim / Thin Trees	LS	M	Trim trees to at least five feet above ground level.	38.414568 ° -121.523437 °	38.414568 ° -121.523437 °		14
4	0.05	0.11	Earthen Levee	Encroachments	LS	PO	Fences	38.414672 ° -121.523527 °	38.415468 ° -121.524037 °	Y	13
5	0.06	1.16	Earthen Levee	Vegetation	WS	M	Control annual grass and weeds on the levee slopes and easements.	38.414802 ° -121.523535 °	38.428920 ° -121.532903 °		16
6	0.11	0.12	Earthen Levee	Vegetation	WS	U		38.415425 ° -121.523900 °	38.415667 ° -121.524018 °		17
7	0.20	0.21	Earthen Levee	Vegetation	WS	U		38.416642 ° -121.524630 °	38.416817 ° -121.524757 °		18
8	0.24	0.26	Earthen Levee	Trim / Thin Trees	WS	M	Trim trees to at least five feet above ground level.	38.417113 ° -121.524990 °	38.417347 ° -121.525195 °		19
9	0.31	0.35	Earthen Levee	Encroachments	LS	PO	Landscaping	38.418002 ° -121.525712 °	38.418470 ° -121.526002 °		12
10	0.37	0.48	Earthen Levee	Encroachments	LS	PO	Landscaping	38.418838 ° -121.526225 °	38.420237 ° -121.527193 °		11
11	0.37	0.50	Earthen Levee	Trim / Thin Trees	LS	U	Trim trees to at least five feet above ground level.	38.418838 ° -121.526225 °	38.420447 ° -121.527380 °		10
12	0.58	0.59	Earthen Levee	Vegetation	LS	M		38.421438 ° -121.528087 °	38.421607 ° -121.528198 °		9
13	0.62	0.64	Earthen Levee	Trim / Thin Trees	LS	M	Trim trees to at least five feet above ground level.	38.421963 ° -121.528452 °	38.422165 ° -121.528605 °		8
14	0.67	0.69	Earthen Levee	Trim / Thin Trees	LS	M	Trim trees to at least five feet above ground level.	38.422517 ° -121.528858 °	38.422842 ° -121.529107 °		7
15	0.70	0.72	Earthen Levee	Vegetation	WS	U		38.423010 ° -121.529162 °	38.423245 ° -121.529308 °		20
16	0.71	0.87	Earthen Levee	Trim / Thin Trees	LS	M	Trim trees to at least five feet above ground level.	38.423035 ° -121.529255 °	38.425140 ° -121.530742 °		6
17	0.71	0.91	Earthen Levee	Encroachments	LS	PO	Fences	38.423035 ° -121.529253 °	38.425645 ° -121.531083 °		5
18	0.91	0.91	Earthen Levee	Trim / Thin Trees	LS	U	Trim trees to at least five feet above ground level.	38.425665 ° -121.531090 °	38.425665 ° -121.531090 °		4
19	0.99	1.01	Earthen Levee	Vegetation	LS	U		38.426682 ° -121.531738 °	38.426910 ° -121.531858 °		3

<p>* Location</p> <p>LS : Land Side WS : Water Side CR : Crown</p>	<p>** Rating</p> <p>A : Acceptable M : Minimally Acceptable U : Unacceptable</p> <p>PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected</p>
---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2008

Reclamation District No. 0999

Waterway				Bank	Unit Miles	Inspection Date	Inspector
Unit No. 04 Sacramento River				Right	1.20	03/03/2008	Richard Willoughby

LMR Line	Levee Mile		Category	Item	Location *	Rating **	Action/Comment	GPS Latitude/Longitude		Photo	Issue
	Start	End						Start	End		
20	1.02	1.02	Earthen Levee	Trim / Thin Trees	LS	M	Thin trees to allow visibility of the ground and room to flood fight.	38.427088 °	38.427088 °		2
								-121.531962 °	-121.531962 °		

<p>* Location</p> <p>LS : Land Side WS : Water Side CR : Crown</p>	<p>** Rating</p> <p>A : Acceptable PO : Partially Obstructing M : Minimally Acceptable CO : Completely Obstructing U : Unacceptable N : Not Inspected</p>
---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2008

Reclamation District No. 0999

Waterway	Bank	Unit Miles	Inspection Date	Inspector
Unit No. 04 Sacramento River	Right	1.20	03/03/2008	Richard Willoughby

Levee Mile Report Line	4
Start Levee Mile	0.05
End Levee Mile	0.11
Location	
Category	Earthen Levee
Item	Encroachments
Cyclone fence along landside shoulder at LM 0.05 -0.11	



<p>* Location</p> <p>LS : Land Side WS : Water Side CR : Crown</p>	<p>** Rating</p> <p>A : Acceptable PO : Partially Obstructing M : Minimally Acceptable CO : Completely Obstructing U : Unacceptable N : Not Inspected</p>
---	---

**Flood Control Project Maintenance
Levee Inspections
Unit Cover Sheet
Spring 2008 Levee Inspection Results
Reclamation District No. 0999**

Waterway		Bank	Unit Miles
Unit No. 05 Elk Slough		Right	9.70

	Spring (March - May)	Summer (June - August)	Fall (September - November)	Winter (December - February)
Date of Inspection	3/5/2008			
DWR Inspector	Richard Willoughby			
Accompanied By				
Unit Maintenance Rating (Fall Only)				

Check one:

During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.

During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

Comments

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :

DWR Summer/Winter Inspection Reports
3310 El Camino Avenue, Room LL-30
Sacramento, CA 95821-9000.

X _____
Signature of LMA Representative Date

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2008

Reclamation District No. 0999

Waterway				Bank	Unit Miles	Inspection Date	Inspector
Unit No. 05 Elk Slough				Right	9.70	03/05/2008	Richard Willoughby

LMR Line	Levee Mile		Category	Item	Location*	Rating**	Action/Comment	GPS Latitude/Longitude		Photo	Issue
	Start	End						Start	End		
1	0.01	9.65	Earthen Levee	Vegetation	WS	M	Control annual grass and weeds on the levee slopes and easements.	38.332473 ° -121.584593 °	38.414168 ° -121.523322 °		1
2	0.05	9.65	Earthen Levee	Vegetation	LS	M	Control annual grass and weeds on the levee slopes and easements.	38.333003 ° -121.584475 °	38.414137 ° -121.523357 °		2
3	0.19	0.22	Earthen Levee	Trim / Thin Trees	WS	M	Trim trees to at least five feet above ground level.	38.334960 ° -121.584047 °	38.335428 ° -121.583845 °		3
4	0.40	0.47	Earthen Levee	Trim / Thin Trees	LS	M	Trim trees to at least five feet above ground level.	38.337693 ° -121.582395 °	38.338643 ° -121.582160 °		4
5	0.41	0.41	Earthen Levee	Trim / Thin Trees	WS	M	Trim trees to at least five feet above ground level.	38.337870 ° -121.582350 °	38.337870 ° -121.582350 °		5
6	0.53	0.53	Earthen Levee	Trim / Thin Trees	LS	M	Trim trees to at least five feet above ground level.	38.339545 ° -121.582033 °	38.339545 ° -121.582033 °		6
7	0.57	0.64	Earthen Levee	Trim / Thin Trees	LS	M	Thin trees to allow visibility of the ground and room to flood fight.	38.340070 ° -121.581980 °	38.341058 ° -121.581615 °		7
8	0.69	0.69	Earthen Levee	Encroachments	WS	M	Tree or limb	38.341712 ° -121.581435 °	38.341712 ° -121.581435 °		8
9	0.72	0.74	Earthen Levee	Trim / Thin Trees	LS	U	Trim trees to at least five feet above ground level.	38.342180 ° -121.581230 °	38.342537 ° -121.581263 °		9
10	0.78	0.94	Earthen Levee	Trim / Thin Trees	WS	U	Trim and thin trees to allow visibility of the ground and room to flood fight.	38.343058 ° -121.581263 °	38.345210 ° -121.580713 °		10
11	0.84	0.94	Earthen Levee	Encroachments	LS	PO	Landscaping	38.343825 ° -121.581133 °	38.345215 ° -121.580728 °	Y	11
12	0.95	0.98	Earthen Levee	Trim / Thin Trees	LS	M	Trim trees to at least five feet above ground level.	38.345383 ° -121.580663 °	38.345750 ° -121.580473 °		12
13	0.95	1.09	Earthen Levee	Vegetation	WS	M	Remove the wild growth other than native grasses from the levee slopes.	38.345402 ° -121.580655 °	38.347133 ° -121.579573 °		13
14	1.11	1.15	Earthen Levee	Trim / Thin Trees	LS	M	Trim trees to at least five feet above ground level.	38.347427 ° -121.579395 °	38.347863 ° -121.579113 °		14
15	1.20	1.24	Earthen Levee	Trim / Thin Trees	LS	M	Trim trees to at least five feet above ground level.	38.348237 ° -121.578440 °	38.348328 ° -121.577735 °		15
16	1.39	1.42	Earthen Levee	Vegetation	WS	U	Remove the wild growth other than native grasses from the levee slopes.	38.348190 ° -121.575008 °	38.348128 ° -121.574390 °		16
17	1.43	1.48	Earthen Levee	Vegetation	LS	M	Remove the wild growth other than native grasses from the levee slopes.	38.348105 ° -121.574160 °	38.348335 ° -121.573298 °		17
18	1.51	1.88	Earthen Levee	Trim / Thin Trees	LS	M	Trim and thin trees to allow visibility of the ground and room to flood fight.	38.348670 ° -121.573320 °	38.353852 ° -121.573570 °		18
19	1.54	1.88	Earthen Levee	Animal Control	WS	M	Exterminate rodents and backfill and compact or grout burrows.	38.349152 ° -121.573493 °	38.353877 ° -121.573545 °		19

<p>* Location</p> <p>LS : Land Side WS : Water Side CR : Crown</p>	<p>** Rating</p> <p>A : Acceptable M : Minimally Acceptable U : Unacceptable</p> <p>PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected</p>
---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2008

Reclamation District No. 0999

Waterway				Bank	Unit Miles	Inspection Date	Inspector
Unit No. 05 Elk Slough				Right	9.70	03/05/2008	Richard Willoughby

LMR Line	Levee Mile		Category	Item	Location*	Rating**	Action/Comment	GPS Latitude/Longitude		Photo	Issue
	Start	End						Start	End		
20	1.59	1.65	Earthen Levee	Trim / Thin Trees	WS	M	Trim trees to at least five feet above ground level.	38.349835 ° -121.573643 °	38.350717 ° -121.573887 °		20
21	1.75	1.81	Earthen Levee	Trim / Thin Trees	WS	M	Trim trees to at least five feet above ground level.	38.352088 ° -121.574052 °	38.352968 ° -121.574008 °		21
22	1.97	1.97	Earthen Levee	Encroachments	WS	M	Material Inspector Comments: Concrete rubble should be removed or broken up and spread out at waterward toe.	38.354888 ° -121.572540 °	38.354888 ° -121.572540 °	Y	22
23	2.12	2.14	Earthen Levee	Trim / Thin Trees	LS	M	Trim trees to at least five feet above ground level.	38.355640 ° -121.570208 °	38.355630 ° -121.569977 °		23
24	2.20	2.22	Earthen Levee	Trim / Thin Trees	LS	M	Trim and thin trees to allow visibility of the ground and room to flood fight.	38.355402 ° -121.568893 °	38.355282 ° -121.568547 °		24
25	2.33	2.34	Earthen Levee	Vegetation	WS	M	Remove the wild growth other than native grasses from the levee slopes.	38.354525 ° -121.566905 °	38.354490 ° -121.566658 °		25
26	2.46	2.49	Earthen Levee	Vegetation	WS	M	Remove the wild growth other than native grasses from the levee slopes.	38.355267 ° -121.564727 °	38.355572 ° -121.564305 °		26
27	2.66	2.76	Earthen Levee	Vegetation	WS	M	Remove the wild growth other than native grasses from the levee slopes.	38.357465 ° -121.562405 °	38.358913 ° -121.562285 °		27
28	2.90	2.91	Earthen Levee	Vegetation	WS	M	Remove the wild growth other than native grasses from the levee slopes.	38.360757 ° -121.562970 °	38.360937 ° -121.563090 °		28
29	2.93	3.19	Earthen Levee	Trim / Thin Trees	LS	U	Trim and thin trees to allow visibility of the ground and room to flood fight.	38.361268 ° -121.563263 °	38.364373 ° -121.561947 °		29
30	3.04	3.10	Earthen Levee	Trim / Thin Trees	WS	M	Trim and thin trees to allow visibility of the ground and room to flood fight.	38.362813 ° -121.563332 °	38.363498 ° -121.563030 °		30
31	3.19	3.24	Earthen Levee	Encroachments	LS	PO	Landscaping	38.364392 ° -121.561882 °	38.364597 ° -121.561087 °	Y	31
32	3.24	3.31	Earthen Levee	Encroachments	WS	M	Prunings	38.364585 ° -121.561047 °	38.364503 ° -121.559880 °		32
33	3.29	3.37	Earthen Levee	Trim / Thin Trees	LS	M	Trim trees to at least five feet above ground level.	38.364552 ° -121.560137 °	38.364225 ° -121.558852 °		33
34	3.41	3.64	Earthen Levee	Encroachments	WS	M	Tree or limb	38.364050 ° -121.558150 °	38.366028 ° -121.556843 °		34
35	3.44	3.47	Earthen Levee	Trim / Thin Trees	LS	M	Trim trees to at least five feet above ground level.	38.363923 ° -121.557608 °	38.363822 ° -121.557108 °		35
36	3.57	3.64	Earthen Levee	Vegetation	WS	U	Remove the wild growth other than native grasses from the levee slopes.	38.364973 ° -121.556530 °	38.366027 ° -121.556847 °		36
37	3.75	3.82	Earthen Levee	Encroachments	WS	M	Tree or limb	38.367482 ° -121.556542 °	38.367977 ° -121.555443 °		37
38	3.94	3.98	Earthen Levee	Encroachments	WS	M	Tree or limb	38.368260 ° -121.553313 °	38.368462 ° -121.552620 °		38

<p>* Location</p> <p>LS : Land Side WS : Water Side CR : Crown</p>	<p>** Rating</p> <p>A : Acceptable M : Minimally Acceptable U : Unacceptable</p> <p>PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected</p>
---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2008

Reclamation District No. 0999

Waterway				Bank	Unit Miles	Inspection Date	Inspector				
Unit No. 05 Elk Slough				Right	9.70	03/05/2008	Richard Willoughby				
LMR Line	Levee Mile		Category	Item	Location*	Rating**	Action/Comment	GPS Latitude/Longitude		Photo	Issue
	Start	End						Start	End		
39	3.96	3.96	Earthen Levee	Encroachments	LS	M	Garbage	38.368318 ° -121.552938 °	38.368318 ° -121.552938 °	Y	39
40	4.00	4.03	Earthen Levee	Vegetation	WS	M	Remove the wild growth other than native grasses from the levee slopes.	38.368727 ° -121.552467 °	38.369197 ° -121.552595 °		40
41	4.05	4.14	Earthen Levee	Trim / Thin Trees	WS	M	Trim and thin trees to allow visibility of the ground and room to flood fight.	38.369440 ° -121.552747 °	38.370492 ° -121.553437 °		41
42	4.11	4.11	Earthen Levee	Trim / Thin Trees	LS	M	Trim trees to at least five feet above ground level.	38.370130 ° -121.553220 °	38.370130 ° -121.553220 °		42
43	4.31	4.32	Earthen Levee	Encroachments	WS	M	Prunings	38.372615 ° -121.552398 °	38.372852 ° -121.552267 °	Y	43
44	4.38	4.41	Earthen Levee	Encroachments	LS	CO	Landscaping	38.373625 ° -121.551787 °	38.373907 ° -121.551607 °	Y	44
45	4.43	4.47	Earthen Levee	Trim / Thin Trees	WS	U	Trim and thin trees to allow visibility of the ground and room to flood fight.	38.374160 ° -121.551408 °	38.374683 ° -121.550827 °		45
46	4.51	4.53	Earthen Levee	Trim / Thin Trees	LS	M	Trim trees to at least five feet above ground level.	38.374945 ° -121.550287 °	38.375020 ° -121.549945 °		46
47	4.55	4.68	Earthen Levee	Trim / Thin Trees	LS	U	Trim and thin trees to allow visibility of the ground and room to flood fight.	38.375072 ° -121.549547 °	38.375188 ° -121.547203 °		47
48	4.55	4.70	Earthen Levee	Vegetation	WS	M	Remove the wild growth other than native grasses from the levee slopes.	38.375073 ° -121.549538 °	38.375283 ° -121.546807 °		48
49	4.60	4.81	Earthen Levee	Animal Control	LS	M	Exterminate rodents and backfill and compact or grout burrows.	38.375050 ° -121.548717 °	38.375912 ° -121.544982 °		49
50	4.71	4.74	Earthen Levee	Encroachments	WS	M	Prunings	38.375330 ° -121.546613 °	38.375417 ° -121.546143 °		50
51	4.72	4.72	Earthen Levee	Encroachments	LS	M	Prunings	38.375373 ° -121.546422 °	38.375373 ° -121.546422 °	Y	51
52	4.75	4.86	Earthen Levee	Trim / Thin Trees	LS	M	Trim trees to at least five feet above ground level.	38.375418 ° -121.546043 °	38.376395 ° -121.544387 °		52
53	4.77	4.82	Earthen Levee	Vegetation	WS	U	Remove the wild growth other than native grasses from the levee slopes.	38.375560 ° -121.545680 °	38.375940 ° -121.544950 °		53
54	4.89	4.89	Earthen Levee	Trim / Thin Trees	LS	M	Trim trees over roadway to at least 12 feet above ground level.	38.376717 ° -121.544017 °	38.376717 ° -121.544017 °		54
55	4.90	4.92	Earthen Levee	Vegetation	WS	U	Remove the wild growth other than native grasses from the levee slopes.	38.376785 ° -121.543935 °	38.377060 ° -121.543635 °		55
56	5.18	5.21	Earthen Levee	Encroachments	LS	M	Garbage Inspector Comments: Garbage & Prunings	38.379965 ° -121.541018 °	38.380403 ° -121.541115 °	Y	56
57	5.26	5.26	Earthen Levee	Encroachments	LS	M	Equipment	38.380903 ° -121.541618 °	38.380903 ° -121.541618 °	Y	57

<p>* Location</p> <p>LS : Land Side WS : Water Side CR : Crown</p>	<p>** Rating</p> <p>A : Acceptable M : Minimally Acceptable U : Unacceptable</p> <p>PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected</p>
---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2008

Reclamation District No. 0999

Waterway				Bank	Unit Miles	Inspection Date	Inspector
Unit No. 05 Elk Slough				Right	9.70	03/05/2008	Richard Willoughby

LMR Line	Levee Mile		Category	Item	Location*	Rating**	Action/Comment	GPS Latitude/Longitude		Photo	Issue
	Start	End						Start	End		
58	5.58	5.61	Earthen Levee	Vegetation	WS	U	Remove the wild growth other than native grasses from the levee slopes.	38.382647 ° -121.546665 °	38.383095 ° -121.546833 °		58
59	5.93	6.13	Earthen Levee	Animal Control	WS	M	Exterminate rodents and backfill and compact or grout burrows.	38.384877 ° -121.542110 °	38.387015 ° -121.541578 °		59
60	6.20	6.34	Earthen Levee	Trim / Thin Trees	LS	M	Trim and thin trees to allow visibility of the ground and room to flood fight.	38.387825 ° -121.542335 °	38.389775 ° -121.542687 °		60
61	6.25	6.34	Earthen Levee	Vegetation	WS	U	Remove the wild growth other than native grasses from the levee slopes.	38.388507 ° -121.542832 °	38.389773 ° -121.542687 °		61
62	6.59	6.62	Earthen Levee	Vegetation	WS	M	Remove the wild growth other than native grasses from the levee slopes.	38.391887 ° -121.539185 °	38.392308 ° -121.538912 °		62
63	7.24	7.24	Earthen Levee	Trim / Thin Trees	WS	M	Trim trees to at least five feet above ground level.	38.399503 ° -121.536375 °	38.399503 ° -121.536375 °		63
64	7.44	7.57	Earthen Levee	Trim / Thin Trees	WS	M	Trim trees to at least five feet above ground level.	38.401882 ° -121.538397 °	38.403390 ° -121.539768 °		64
65	7.64	7.72	Earthen Levee	Trim / Thin Trees	WS	U	Trim and thin trees to allow visibility of the ground and room to flood fight.	38.403870 ° -121.540978 °	38.404358 ° -121.542300 °		65
66	7.65	7.72	Earthen Levee	Encroachments	LS	CO	Landscaping	38.403895 ° -121.541113 °	38.404360 ° -121.542298 °	Y	66
67	8.32	8.32	Earthen Levee	Vegetation	WS	U	Remove the wild growth other than native grasses from the levee slopes.	38.409875 ° -121.539388 °	38.409877 ° -121.539388 °		67
68	8.33	8.45	Earthen Levee	Trim / Thin Trees	WS	M	Trim and thin trees to allow visibility of the ground and room to flood fight.	38.409892 ° -121.539165 °	38.409445 ° -121.536982 °		68
69	8.45	9.61	Earthen Levee	Animal Control	LS	M	Exterminate rodents and backfill and compact or grout burrows.	38.409445 ° -121.536980 °	38.413717 ° -121.523813 °		69
70	8.51	8.51	Earthen Levee	Encroachments	LS	M	Prunings	38.408962 ° -121.535947 °	38.408962 ° -121.535947 °	Y	70
71	8.64	8.68	Earthen Levee	Vegetation	WS	M	Remove the wild growth other than native grasses from the levee slopes.	38.408955 ° -121.534020 °	38.409460 ° -121.533497 °		71
72	8.71	8.71	Earthen Levee	Encroachments	WS	M	Prunings	38.409743 ° -121.533210 °	38.409743 ° -121.533210 °		72
73	9.16	9.16	Earthen Levee	Trim / Thin Trees	LS	M	Trim and thin trees to allow visibility of the ground and room to flood fight.	38.415010 ° -121.529730 °	38.415010 ° -121.529730 °		73
74	9.20	9.58	Earthen Levee	Trim / Thin Trees	LS	U	Trim and thin trees to allow visibility of the ground and room to flood fight.	38.415528 ° -121.529390 °	38.413537 ° -121.524167 °		74
75	9.20	9.61	Earthen Levee	Trim / Thin Trees	WS	M	Trim trees to at least five feet above ground level.	38.415528 ° -121.529390 °	38.413717 ° -121.523813 °		75

<p>* Location</p> <p>LS : Land Side WS : Water Side CR : Crown</p>	<p>** Rating</p> <p>A : Acceptable M : Minimally Acceptable U : Unacceptable</p> <p>PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected</p>
---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2008

Reclamation District No. 0999

Waterway	Bank	Unit Miles	Inspection Date	Inspector
Unit No. 05 Elk Slough	Right	9.70	03/05/2008	Richard Willoughby

Levee Mile Report Line	11
Start Levee Mile	0.84
End Levee Mile	0.94
Location	
Category	Earthen Levee
Item	Encroachments
View of landscaping (Ivy) blocking view of landside slope from LM 0.84 to 0.94	



Levee Mile Report Line	11
Start Levee Mile	0.84
End Levee Mile	0.94
Location	
Category	Earthen Levee
Item	Encroachments
View of landscaping (Ivy) looking upstream from LM 0.84 to 0.94	



Levee Mile Report Line	22
Start Levee Mile	1.97
End Levee Mile	1.97
Location	
Category	Earthen Levee
Item	Encroachments
Concrete rubble on waterside sholder at LM 1.97	



<p>* Location</p> <p>LS : Land Side WS : Water Side CR : Crown</p>	<p>** Rating</p> <p>A : Acceptable M : Minimally Acceptable U : Unacceptable</p>	<p>PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected</p>
---	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2008

Reclamation District No. 0999

Waterway	Bank	Unit Miles	Inspection Date	Inspector
Unit No. 05 Elk Slough	Right	9.70	03/05/2008	Richard Willoughby

Levee Mile Report Line	31
Start Levee Mile	3.19
End Levee Mile	3.24
Location	
Category	Earthen Levee
Item	Encroachments
Looking downstream of landscaping blocking view of landside slope from LM 3.19 to 3.24	



Levee Mile Report Line	39
Start Levee Mile	3.96
End Levee Mile	3.96
Location	
Category	Earthen Levee
Item	Encroachments
Garbage piles on landside toe at LM 3.96	



Levee Mile Report Line	43
Start Levee Mile	4.31
End Levee Mile	4.32
Location	
Category	Earthen Levee
Item	Encroachments
Pruning piles on waterward shoulder from LM 4.31 to 4.32	



<p>* Location</p> <p>LS : Land Side WS : Water Side CR : Crown</p>	<p>** Rating</p> <p>A : Acceptable M : Minimally Acceptable U : Unacceptable</p>	<p>PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected</p>
---	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2008

Reclamation District No. 0999

Waterway	Bank	Unit Miles	Inspection Date	Inspector
Unit No. 05 Elk Slough	Right	9.70	03/05/2008	Richard Willoughby

Levee Mile Report Line	44
Start Levee Mile	4.38
End Levee Mile	4.41
Location	
Category	Earthen Levee
Item	Encroachments
Overgrown landscaping on landside slope blocking view of slope from LM 4.38 to 4.41	



Levee Mile Report Line	51
Start Levee Mile	4.72
End Levee Mile	4.72
Location	
Category	Earthen Levee
Item	Encroachments
Prunings and firewood on landside shoulder at LM 4.72	



Levee Mile Report Line	56
Start Levee Mile	5.18
End Levee Mile	5.21
Location	
Category	Earthen Levee
Item	Encroachments
Garbage and Prunings on landside slope from LM 5.18 to 5.21	



<p>* Location</p> <p>LS : Land Side WS : Water Side CR : Crown</p>	<p>** Rating</p> <p>A : Acceptable M : Minimally Acceptable U : Unacceptable</p>	<p>PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected</p>
---	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2008

Reclamation District No. 0999

Waterway	Bank	Unit Miles	Inspection Date	Inspector
Unit No. 05 Elk Slough	Right	9.70	03/05/2008	Richard Willoughby

Levee Mile Report Line	57
Start Levee Mile	5.26
End Levee Mile	5.26
Location	
Category	Earthen Levee
Item	Encroachments
Farm equipment on landside slope at LM 5.26	



Levee Mile Report Line	66
Start Levee Mile	7.65
End Levee Mile	7.72
Location	
Category	Earthen Levee
Item	Encroachments
Landscaping on landside slope blocking view of slope from LM 7.65 to 7.72	



Levee Mile Report Line	70
Start Levee Mile	8.51
End Levee Mile	8.51
Location	
Category	Earthen Levee
Item	Encroachments
Prunings and firewood on waterside and landside shoulder at LM 8.51	



<p>* Location</p> <p>LS : Land Side WS : Water Side CR : Crown</p>	<p>** Rating</p> <p>A : Acceptable M : Minimally Acceptable U : Unacceptable</p>	<p>PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected</p>
---	---	---