

**Flood Control Project Maintenance
Levee Inspections
LMA District Cover Sheet
Spring 2008 Levee Inspection Results**

Reclamation District No. 1001

	Spring (March - May)	Summer ** (June - August)	Fall (September - November)	Winter ** (December - February)
* Overall LMA Rating (Fall Only)				

** Non-receipt of Summer or Winter Inspection Reports may effect overall annual rating.

* **SPRING INSPECTIONS:** Overall maintenance ratings are not determined for the spring inspection results. Individual maintenance deficiencies are rated using the same criteria in the spring and in the fall.

FALL INSPECTIONS: The overall maintenance rating shown above is based on operation and maintenance deficiencies identified within the attached unit inspection reports.

Comments

**Flood Control Project Maintenance
Levee Inspections
Unit Cover Sheet
Spring 2008 Levee Inspection Results
Reclamation District No. 1001**

Waterway		Bank	Unit Miles
Unit No. 01 Yankee Slough		Right	4.20

	Spring (March - May)	Summer (June - August)	Fall (September - November)	Winter (December - February)
Date of Inspection	3/20/2008			
DWR Inspector	Clay Thomas			
Accompanied By				
Unit Maintenance Rating (Fall Only)				

Check one:

During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.

During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

Comments

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :

DWR Summer/Winter Inspection Reports
3310 El Camino Avenue, Room LL-30
Sacramento, CA 95821-9000.

X _____
Signature of LMA Representative Date

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2008

Reclamation District No. 1001

Waterway				Bank	Unit Miles	Inspection Date	Inspector
Unit No. 01 Yankee Slough				Right	4.20	03/20/2008	Clay Thomas

LMR Line	Levee Mile		Category	Item	Location*	Rating**	Action/Comment	GPS Latitude/Longitude		Photo	Issue
	Start	End						Start	End		
1	0.44	2.45	Earthen Levee	Vegetation	WS	M	Control annual grass and weeds on the levee slopes and easements.	38.975797 ° -121.475527 °	38.968482 ° -121.509442 °		8
2	0.60	0.60	Earthen Levee	Encroachments	LS	M	Prunings	38.975105 ° -121.478247 °	38.975105 ° -121.478247 °		18
3	0.93	0.93	Earthen Levee	Encroachments	LS	M	Prunings	38.974670 ° -121.484230 °	38.974670 ° -121.484230 °		16
4	0.96	1.10	Earthen Levee	Encroachments	LS	CO	Landscaping	38.974535 ° -121.484722 °	38.973837 ° -121.487105 °		15
5	1.31	1.31	Earthen Levee	Encroachments	LS	M	Prunings	38.972670 ° -121.490550 °	38.972670 ° -121.490550 °		14
6	1.54	1.54	Earthen Levee	Encroachments	LS	M	Debris	38.970683 ° -121.493833 °	38.970683 ° -121.493833 °		13
7	1.61	1.61	Earthen Levee	Encroachments	LS	M	Debris	38.970510 ° -121.495195 °	38.970510 ° -121.495195 °		12
8	1.83	1.83	Earthen Levee	Slope Stability	LS	M	Repair slope instability.	38.971082 ° -121.499118 °	38.971082 ° -121.499118 °		11
9	1.86	2.26	Earthen Levee	Vegetation	LS	M	Control annual grass and weeds on the levee slopes and easements.	38.971098 ° -121.499747 °	38.969265 ° -121.506130 °		9
10	2.03	2.03	Earthen Levee	Encroachments	LS	M	Prunings	38.971150 ° -121.502780 °	38.971150 ° -121.502780 °		10
11	2.79	3.88	Earthen Levee	Vegetation	LS	M	Control annual grass and weeds on the levee slopes and easements.	38.968640 ° -121.515730 °	38.966768 ° -121.533397 °		2
12	2.79	4.16	Earthen Levee	Vegetation	WS	M	Control annual grass and weeds on the levee slopes and easements.	38.968662 ° -121.515745 °	38.970613 ° -121.534445 °		1
13	2.83	2.83	Earthen Levee	Encroachments	LS	M	Debris	38.968285 ° -121.516330 °	38.968285 ° -121.516330 °		7
14	3.01	3.01	Earthen Levee	Encroachments	LS	M	Prunings	38.966612 ° -121.518898 °	38.966612 ° -121.518898 °		6
15	3.16	3.22	Earthen Levee	Encroachments	LS	PO	Landscaping	38.965663 ° -121.521023 °	38.965705 ° -121.522098 °		5
16	3.20	3.24	Earthen Levee	Encroachments	LS	M	Debris	38.965688 ° -121.521800 °	38.965720 ° -121.522550 °		4
17	3.35	3.35	Earthen Levee	Encroachments	LS	M	Debris	38.965585 ° -121.524458 °	38.965585 ° -121.524458 °		3

<p>* Location</p> <p>LS : Land Side WS : Water Side CR : Crown</p>	<p>** Rating</p> <p>A : Acceptable M : Minimally Acceptable U : Unacceptable</p> <p>PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected</p>
---	---

**Flood Control Project Maintenance
Levee Inspections
Unit Cover Sheet
Spring 2008 Levee Inspection Results
Reclamation District No. 1001**

Waterway		Bank	Unit Miles
Unit No. 02 Yankee Slough		Left	3.70

	Spring (March - May)	Summer (June - August)	Fall (September - November)	Winter (December - February)
Date of Inspection	3/20/2008			
DWR Inspector	Clay Thomas			
Accompanied By				
Unit Maintenance Rating (Fall Only)				

Check one:

During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.

During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

Comments

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :
 DWR Summer/Winter Inspection Reports
 3310 El Camino Avenue, Room LL-30
 Sacramento, CA 95821-9000.

X _____
 Signature of LMA Representative Date

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2008

Reclamation District No. 1001

Waterway				Bank	Unit Miles	Inspection Date	Inspector				
Unit No. 02 Yankee Slough				Left	3.70	03/20/2008	Clay Thomas				
LMR Line	Levee Mile		Category	Item	Location*	Rating**	Action/Comment	GPS Latitude/Longitude		Photo	Issue
	Start	End						Start	End		
1	0.00	3.66	Earthen Levee	Vegetation	WS	M	Control annual grass and weeds on the levee slopes and easements.	38.970632 ° -121.474048 °	° °		2
2	0.00	3.66	Earthen Levee	Vegetation	LS	M	Control annual grass and weeds on the levee slopes and easements.	38.970627 ° -121.474042 °	° °		1
3	0.08	0.08	Earthen Levee	Encroachments	LS	M	Prunings	38.971837 ° -121.474000 °	38.971837 ° -121.474000 °		3
4	0.24	0.33	Earthen Levee	Encroachments	LS	M	Prunings	38.973947 ° -121.475518 °	38.974555 ° -121.477083 °		4
5	0.52	0.52	Earthen Levee	Encroachments	LS	M	Debris	38.974325 ° -121.480495 °	38.974325 ° -121.480495 °		5
6	0.65	0.65	Earthen Levee	Encroachments	LS	M	Debris	38.974287 ° -121.483035 °	38.974287 ° -121.483035 °		6
7	0.81	0.81	Earthen Levee	Encroachments	LS	M	Debris	38.973605 ° -121.485728 °	38.973605 ° -121.485728 °		7
8	1.24	1.24	Earthen Levee	Encroachments	LS	M	Prunings	38.970720 ° -121.492475 °	38.970720 ° -121.492475 °		8
9	1.74	1.74	Earthen Levee	Encroachments	LS	PO	Equipment	38.970320 ° -121.501348 °	38.970320 ° -121.501348 °		9
10	1.77	1.77	Earthen Levee	Encroachments	LS	CO	Landscaping	38.970353 ° -121.501935 °	38.970353 ° -121.501935 °		10
11	1.78	1.78	Earthen Levee	Encroachments	LS	CO	Buildings	38.970347 ° -121.502027 °	38.970347 ° -121.502027 °		11
12	1.79	1.81	Earthen Levee	Encroachments	LS	PO	Landscaping	38.970347 ° -121.502177 °	38.970327 ° -121.502618 °		12

<p>* Location</p> <p>LS : Land Side WS : Water Side CR : Crown</p>	<p>** Rating</p> <p>A : Acceptable M : Minimally Acceptable U : Unacceptable</p> <p>PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected</p>
---	---

**Flood Control Project Maintenance
Levee Inspections
Unit Cover Sheet
Spring 2008 Levee Inspection Results
Reclamation District No. 1001**

Waterway		Bank	Unit Miles
Unit No. 03 Bear River		Left	12.60

	Spring (March - May)	Summer (June - August)	Fall (September - November)	Winter (December - February)
Date of Inspection	3/20/2008			
DWR Inspector	Clay Thomas			
Accompanied By				
Unit Maintenance Rating (Fall Only)				

Check one:

During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.

During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

Comments

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :

DWR Summer/Winter Inspection Reports
3310 El Camino Avenue, Room LL-30
Sacramento, CA 95821-9000.

X _____
Signature of LMA Representative Date

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2008

Reclamation District No. 1001

Waterway				Bank	Unit Miles	Inspection Date	Inspector
Unit No. 03 Bear River				Left	12.60	03/20/2008	Clay Thomas

LMR Line	Levee Mile		Category	Item	Location*	Rating**	Action/Comment	GPS Latitude/Longitude		Photo	Issue
	Start	End						Start	End		
1	0.00	12.60	Earthen Levee	Vegetation	LS	M	Control annual grass and weeds on the levee slopes and easements.	39.006470 ° -121.374963 °	38.941572 ° -121.567373 °		1
2	0.00	12.60	Earthen Levee	Vegetation	WS	M	Control annual grass and weeds on the levee slopes and easements.	39.006482 ° -121.374973 °	38.941578 ° -121.567372 °		2
3	0.65	0.65	Earthen Levee	Slope Stability	LS	M	Repair the levee slope damaged by vehicle traffic and prevent access where possible.	39.006343 ° -121.386813 °	39.006343 ° -121.386813 °		3
4	1.47	1.47	Earthen Levee	Slope Stability	CR	M	Repair slope instability.	39.002848 ° -121.400285 °	39.002848 ° -121.400285 °		4
5	4.11	4.11	Earthen Levee	Encroachments	LS	M	Prunings	38.991475 ° -121.444728 °	38.991475 ° -121.444728 °		5
6	4.51	4.54	Earthen Levee	Encroachments	LS	M	Debris	38.991918 ° -121.452003 °	38.991865 ° -121.452612 °		6
7	4.76	4.76	Earthen Levee	Encroachments	LS	M	Debris	38.991295 ° -121.456553 °	38.991295 ° -121.456553 °		7
8	5.45	5.45	Earthen Levee	Encroachments	LS	M	Firewood	38.986713 ° -121.468257 °	38.986713 ° -121.468257 °		8
9	6.15	6.23	Earthen Levee	Encroachments	LS	M	Firewood	38.984788 ° -121.480868 °	38.984632 ° -121.482345 °		9
10	6.62	6.62	Earthen Levee	Encroachments	LS	M	Firewood	38.983927 ° -121.489528 °	38.983927 ° -121.489528 °		11
11	6.73	6.73	Earthen Levee	Encroachments	LS	M	Prunings	38.983545 ° -121.491485 °	38.983545 ° -121.491485 °		12
12	6.88	6.96	Earthen Levee	Encroachments	LS	M	Prunings	38.983423 ° -121.494277 °	38.983277 ° -121.495640 °		13
13	7.12	7.12	Earthen Levee	Encroachments	LS	M	Prunings	38.982925 ° -121.498590 °	38.982925 ° -121.498590 °		14
14	7.38	7.38	Earthen Levee	Vegetation	LS	M	Remove the wild growth other than native grasses from the levee slopes.	38.982512 ° -121.503423 °	38.982512 ° -121.503423 °		15
15	7.54	7.54	Earthen Levee	Encroachments	LS	M	Debris	38.982095 ° -121.506367 °	38.982095 ° -121.506367 °		16
16	7.71	7.71	Earthen Levee	Encroachments	LS	M	Prunings	38.980960 ° -121.509018 °	38.980960 ° -121.509018 °		17
17	8.21	8.21	Earthen Levee	Encroachments	LS	M	Prunings	38.975700 ° -121.515462 °	38.975700 ° -121.515462 °		18
18	10.08	10.12	Earthen Levee	Rip Rap Revetments	WS	A	Inspector Comments: site repaired	38.969135 ° -121.543610 °	38.968437 ° -121.543580 °		19
19	10.52	10.65	Earthen Levee	Vegetation	LS	M	Remove the wild growth other than native grasses from the levee slopes.	38.963130 ° -121.545647 °	38.961328 ° -121.546653 °		20

<p>* Location</p> <p>LS : Land Side WS : Water Side CR : Crown</p>	<p>** Rating</p> <p>A : Acceptable M : Minimally Acceptable U : Unacceptable</p> <p>PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected</p>
---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2008

Reclamation District No. 1001

Waterway				Bank	Unit Miles	Inspection Date	Inspector				
Unit No. 03 Bear River				Left	12.60	03/20/2008	Clay Thomas				
LMR Line	Levee Mile		Category	Item	Location*	Rating**	Action/Comment	GPS Latitude/Longitude		Photo	Issue
	Start	End						Start	End		
20	10.80	11.02	Earthen Levee	Erosion / Bank Caving	WS	A	Note and monitor erosion site. Inspector Comments: erosion site repaired	38.959202 ° -121.546982 °	38.956317 ° -121.548058 °		21
21	11.29	11.32	Earthen Levee	Vegetation	LS	M	Remove the wild growth other than native grasses from the levee slopes.	38.953367 ° -121.551428 °	38.953025 ° -121.551808 °		22
22	11.38	11.38	Earthen Levee	Vegetation	LS	M	Remove the wild growth other than native grasses from the levee slopes.	38.952475 ° -121.552477 °	38.952475 ° -121.552477 °		23
23	11.65	11.86	Earthen Levee	Erosion / Bank Caving	WS	A	Note and monitor erosion site. Inspector Comments: site repaired	38.951298 ° -121.556855 °	38.950982 ° -121.560720 °		24
24	11.90	11.90	Earthen Levee	Vegetation	WS	M	Remove the wild growth other than native grasses from the levee slopes.	38.950528 ° -121.561178 °	38.950528 ° -121.561178 °		25
25	12.15	12.15	Earthen Levee	Encroachments	LS	M	Prunings	38.947422 ° -121.563420 °	38.947422 ° -121.563420 °		26
26	12.24	12.24	Earthen Levee	Vegetation	LS	M	Remove the wild growth other than native grasses from the levee slopes.	38.946248 ° -121.564220 °	38.946248 ° -121.564220 °		27

<p>* Location</p> <p>LS : Land Side WS : Water Side CR : Crown</p>	<p>** Rating</p> <p>A : Acceptable M : Minimally Acceptable U : Unacceptable</p> <p>PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected</p>
---	---

**Flood Control Project Maintenance
Levee Inspections
Unit Cover Sheet
Spring 2008 Levee Inspection Results
Reclamation District No. 1001**

Waterway		Bank	Unit Miles
Unit No. 04 Feather River		Left	13.30

	Spring (March - May)	Summer (June - August)	Fall (September - November)	Winter (December - February)
Date of Inspection	3/27/2008			
DWR Inspector	Clay Thomas			
Accompanied By				
Unit Maintenance Rating (Fall Only)				

Check one:

During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.

During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

Comments

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :
 DWR Summer/Winter Inspection Reports
 3310 El Camino Avenue, Room LL-30
 Sacramento, CA 95821-9000.

X _____
 Signature of LMA Representative Date

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2008

Reclamation District No. 1001

Waterway				Bank	Unit Miles	Inspection Date	Inspector
Unit No. 04 Feather River				Left	13.30	03/27/2008	Clay Thomas

LMR Line	Levee Mile		Category	Item	Location*	Rating**	Action/Comment	GPS Latitude/Longitude		Photo	Issue
	Start	End						Start	End		
1	0.01	13.34	Earthen Levee	Vegetation	WS	M	Control annual grass and weeds on the levee slopes and easements.	38.941457 ° -121.567415 °	38.781032 ° -121.605815 °		2
2	0.01	13.34	Earthen Levee	Vegetation	LS	M	Control annual grass and weeds on the levee slopes and easements.	38.941457 ° -121.567417 °	38.781027 ° -121.605815 °		1
3	0.14	0.44	Earthen Levee	Vegetation	LS	M	Remove the wild growth other than native grasses from the levee slopes.	38.939520 ° -121.567830 °	38.935363 ° -121.567005 °		3
4	0.57	0.65	Earthen Levee	Vegetation	LS	M	Remove the wild growth other than native grasses from the levee slopes.	38.933415 ° -121.567152 °	38.932337 ° -121.567095 °		4
5	0.65	0.76	Earthen Levee	Trim / Thin Trees	LS	M	Trim trees to at least five feet above ground level.	38.932337 ° -121.567095 °	38.930785 ° -121.567350 °		5
6	0.95	0.99	Earthen Levee	Vegetation	WS	M	Remove the wild growth other than native grasses from the levee slopes.	38.928170 ° -121.568167 °	38.927610 ° -121.568112 °		6
7	1.25	1.37	Earthen Levee	Vegetation	LS	M	Remove the wild growth other than native grasses from the levee slopes.	38.923933 ° -121.568608 °	38.922135 ° -121.568857 °		7
8	1.49	1.72	Earthen Levee	Vegetation	LS	M	Remove the wild growth other than native grasses from the levee slopes.	38.920422 ° -121.569138 °	38.917197 ° -121.569750 °		8
9	1.75	1.95	Earthen Levee	Vegetation	LS	M	Remove the wild growth other than native grasses from the levee slopes.	38.916907 ° -121.570013 °	38.914683 ° -121.572403 °		9
10	2.14	2.14	Earthen Levee	Vegetation	LS	M	Remove the wild growth other than native grasses from the levee slopes.	38.912007 ° -121.573242 °	38.912007 ° -121.573242 °		10
11	2.26	2.26	Earthen Levee	Vegetation	LS	M	Remove the wild growth other than native grasses from the levee slopes.	38.910580 ° -121.574238 °	38.910580 ° -121.574238 °		11
12	2.85	2.85	Earthen Levee	Vegetation	LS	M	Remove the wild growth other than native grasses from the levee slopes.	38.903948 ° -121.580242 °	38.903948 ° -121.580242 °		12
13	2.88	2.88	Earthen Levee	Vegetation	LS	M	Remove the wild growth other than native grasses from the levee slopes.	38.903550 ° -121.580517 °	38.903550 ° -121.580517 °		13
14	5.50	5.50	Earthen Levee	Vegetation	LS	M	Remove the wild growth other than native grasses from the levee slopes.	38.878478 ° -121.612255 °	38.878478 ° -121.612255 °		14
15	6.19	6.19	Earthen Levee	Vegetation	LS	M	Remove the wild growth other than native grasses from the levee slopes.	38.869520 ° -121.617577 °	38.869520 ° -121.617577 °		15
16	6.41	6.41	Earthen Levee	Vegetation	LS	M	Remove the wild growth other than native grasses from the levee slopes.	38.866585 ° -121.619150 °	38.866585 ° -121.619150 °		16
17	6.48	6.48	Earthen Levee	Encroachments	LS	PO	Landscaping	38.865653 ° -121.619742 °	38.865653 ° -121.619742 °		17
18	6.64	6.64	Earthen Levee	Vegetation	LS	M	Remove the wild growth other than native grasses from the levee slopes.	38.863700 ° -121.621198 °	38.863700 ° -121.621198 °		18
19	6.66	6.66	Earthen Levee	Encroachments	LS	M	Prunings	38.863385 ° -121.621342 °	38.863385 ° -121.621342 °		19

<p>* Location LS : Land Side WS : Water Side CR : Crown</p>	<p>** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected</p>
---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2008

Reclamation District No. 1001

Waterway				Bank	Unit Miles	Inspection Date	Inspector				
Unit No. 04 Feather River				Left	13.30	03/27/2008	Clay Thomas				
LMR Line	Levee Mile		Category	Item	Location*	Rating**	Action/Comment	GPS Latitude/Longitude		Photo	Issue
	Start	End						Start	End		
20	8.72	8.72	Earthen Levee	Vegetation	LS	M	Remove the wild growth other than native grasses from the levee slopes.	38.835698 ° -121.634070 °	38.835698 ° -121.634070 °		20
21	9.74	9.74	Earthen Levee	Encroachments	WS	PO	Landscaping	38.833088 ° -121.635103 °	38.833088 ° -121.635103 °		21
22	11.15	11.15	Earthen Levee	Vegetation	LS	M	Remove the wild growth other than native grasses from the levee slopes.	38.802508 ° -121.632862 °	38.802508 ° -121.632862 °		22
23	11.32	11.32	Earthen Levee	Vegetation	LS	M	Remove the wild growth other than native grasses from the levee slopes.	38.800112 ° -121.632242 °	38.800112 ° -121.632242 °		23
24	12.40	12.40	Earthen Levee	Vegetation	LS	M	Remove the wild growth other than native grasses from the levee slopes.	38.787355 ° -121.621165 °	38.787355 ° -121.621165 °		24
25	12.57	12.57	Earthen Levee	Encroachments	LS	CO	Buildings	38.786073 ° -121.618522 °	38.786073 ° -121.618522 °		25
26	12.74	13.22	Earthen Levee	Vegetation	LS	M	Remove the wild growth other than native grasses from the levee slopes.	38.784513 ° -121.616045 °	38.781862 ° -121.607855 °		26

<p>* Location</p> <p>LS : Land Side WS : Water Side CR : Crown</p>	<p>** Rating</p> <p>A : Acceptable M : Minimally Acceptable U : Unacceptable</p> <p>PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected</p>
---	---

**Flood Control Project Maintenance
Levee Inspections
Unit Cover Sheet
Spring 2008 Levee Inspection Results
Reclamation District No. 1001**

Waterway		Bank	Unit Miles
Unit No. 05 Natomas Cross Canal		Right	5.40

	Spring (March - May)	Summer (June - August)	Fall (September - November)	Winter (December - February)
Date of Inspection	4/1/2008			
DWR Inspector	Clay Thomas			
Accompanied By				
Unit Maintenance Rating (Fall Only)				

Check one:

During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.

During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

Comments

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :

DWR Summer/Winter Inspection Reports
3310 El Camino Avenue, Room LL-30
Sacramento, CA 95821-9000.

X _____
Signature of LMA Representative Date

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2008

Reclamation District No. 1001

Waterway				Bank	Unit Miles	Inspection Date	Inspector
Unit No. 05 Natomas Cross Canal				Right	5.40	04/01/2008	Clay Thomas

LMR Line	Levee Mile		Category	Item	Location*	Rating**	Action/Comment	GPS Latitude/Longitude		Photo	Issue
	Start	End						Start	End		
1	0.04	5.43	Earthen Levee	Vegetation	WS	M	Control annual grass and weeds on the levee slopes and easements.	38.781682 ° -121.605083 °	38.830877 ° -121.529853 °		2
2	0.04	5.43	Earthen Levee	Vegetation	LS	M	Control annual grass and weeds on the levee slopes and easements.	38.781110 ° -121.605320 °	38.830873 ° -121.529852 °		1
3	0.83	0.83	Earthen Levee	Encroachments	WS	CO	Buildings	38.790830 ° -121.596973 °	38.790830 ° -121.596973 °		3

<p>* Location</p> <p>LS : Land Side WS : Water Side CR : Crown</p>	<p>** Rating</p> <p>A : Acceptable M : Minimally Acceptable U : Unacceptable</p> <p>PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected</p>
---	---

**Flood Control Project Maintenance
Levee Inspections
Unit Cover Sheet
Spring 2008 Levee Inspection Results
Reclamation District No. 1001**

Waterway		Bank	Unit Miles
Unit No. 06 East Side Canal		Right	4.80

	Spring (March - May)	Summer (June - August)	Fall (September - November)	Winter (December - February)
Date of Inspection	4/1/2008			
DWR Inspector	Clay Thomas			
Accompanied By				
Unit Maintenance Rating (Fall Only)				

Check one:

During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.

During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

Comments

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :
 DWR Summer/Winter Inspection Reports
 3310 El Camino Avenue, Room LL-30
 Sacramento, CA 95821-9000.

X _____
 Signature of LMA Representative Date

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2008

Reclamation District No. 1001

Waterway			Bank	Unit Miles	Inspection Date	Inspector
Unit No. 06 East Side Canal			Right	4.80	04/01/2008	Clay Thomas

LMR Line	Levee Mile		Category	Item	Location*	Rating**	Action/Comment	GPS Latitude/Longitude		Photo	Issue
	Start	End						Start	End		
1	0.01	4.74	Earthen Levee	Vegetation	LS	M	Control annual grass and weeds on the levee slopes and easements.	38.831060 ° -121.529538 °	38.896345 ° -121.520385 °		1
2	0.01	4.74	Earthen Levee	Vegetation	WS	M	Control annual grass and weeds on the levee slopes and easements.	38.831063 ° -121.529535 °	38.896342 ° -121.520382 °		2
3	1.45	1.45	Earthen Levee	Encroachments	WS	PO	Equipment	38.851272 ° -121.524357 °	38.851272 ° -121.524357 °		3
4	3.29	3.29	Interior Drainage & Piping Systems	Sluice / Slide Gates	WS	M		38.877680 ° -121.524760 °	38.877680 ° -121.524760 °		4

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected