

**Flood Control Project Maintenance
Levee Inspections**

Fall 2015 Levee Maintenance Deficiency Summary Report

Overall LMA & Unit Ratings, including USACE Erosion Survey

Sacramento River Basin

RD1500 Reclamation District No. 1500 Sutter Basin	Overall LMA Rating	Total LMA Miles	* Overall LMA Threshold Percent is less than 10.00%; however, U Rated Miles are present, so the Overall LMA Rating is M instead of A.					
	M *	53.87						
Rated Item	Maintenance Deficiency				Enforcement		Design & System Obsolescence	
	M Miles	U Miles	M + 4U Miles	Threshold %	M Miles	U Miles	M Miles	U Miles
<i>Earthen Levee</i>								
Vegetation					0.09	0.01		
Trim / Thin Trees	0.03	0.01	0.07	0.13%				
Encroachments	0.14		0.14	0.26%	4.21			
Animal Control	0.05		0.05	0.09%				
Slope Stability	0.01		0.01	0.02%				
Erosion / Bank Caving	0.02		0.02	0.04%				
<i>Supplemental</i>								
2015 USACE Erosion Survey, DRAFT	3.23		3.23	6.00%				
DWR UCIP Field Study					0.44	0.06		
<i>LMA Totals:</i>	3.48	0.01	3.52	6.53% *	4.74	0.07	0.00	0.00
Unit No. 01 Sacramento River LB								
RD1500	Overall Unit Rating	Total Unit Miles						
	M	33.15						
Rated Item	Maintenance Deficiency				Enforcement		Design & System Obsolescence	
	M Miles	U Miles	M + 4U Miles	Threshold %	M Miles	U Miles	M Miles	U Miles
<i>Earthen Levee</i>								
Vegetation					0.09	0.01		
Trim / Thin Trees	0.03	0.01	0.07	0.21%				
Encroachments	0.12		0.12	0.36%	4.21			
Animal Control	0.05		0.05	0.15%				
Slope Stability	0.01		0.01	0.03%				
Erosion / Bank Caving	0.02		0.02	0.06%				
<i>Supplemental</i>								
2015 USACE Erosion Survey, DRAFT	3.23		3.23	9.75%				
DWR UCIP Field Study					0.44	0.06		
<i>Unit Totals:</i>	3.46	0.01	3.50	10.56%	4.74	0.07	0.00	0.00
Unit No. 02 Sutter Bypass RB								
RD1500	Overall Unit Rating	Total Unit Miles						
	A	20.72						
Rated Item	Maintenance Deficiency				Enforcement		Design & System Obsolescence	
	M Miles	U Miles	M + 4U Miles	Threshold %	M Miles	U Miles	M Miles	U Miles
<i>Earthen Levee</i>								
Encroachments	0.02		0.02	0.10%				
<i>Unit Totals:</i>	0.02	0.00	0.02	0.10%	0.00	0.00	0.00	0.00

**Flood Control Project Maintenance
Levee Inspections**
LMA District Cover Sheet
Fall 2015 Levee Inspection Results

Reclamation District No. 1500 Sutter Basin

	Spring (March - May)	Summer ** (June - August)	Fall (September - November)	Winter ** (December - February)
* Overall LMA Rating (Fall Only)			M	

** Non-receipt of Summer or Winter Inspection Reports may effect overall annual rating.

* **SPRING INSPECTIONS:** Overall maintenance ratings are not determined for the spring inspection results. Individual maintenance deficiencies are rated using the same criteria in the spring and in the fall.

FALL INSPECTIONS: The overall maintenance rating shown above is based on operation and maintenance deficiencies identified within the attached unit inspection reports. This rating is not intended to be an indication of risk.

Comments

**Flood Control Project Maintenance
Levee Inspections**

Unit Cover Sheet

Fall 2015 Levee Inspection Results

Reclamation District No. 1500 Sutter Basin

Waterway		Bank	Unit Miles	
Unit No. 01 Sacramento River		Left	33.15	
	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - February)
Unit Maintenance Rating (Fall Only)			M	
Date of Inspection	05/13/2015 - 05/14/2015		10/20/2015 - 10/21/2015	
DWR Inspector	Jai Lor		Jai Lor	
Accompanied By				

Summer & Winter Inspections

The Local Maintaining Agency (LMA) is responsible for summer and winter inspections. The LMA is required to submit a report regarding summer and winter inspections to the California Department of Water Resources (DWR).

DWR must be informed on the:

- a) completion of the inspection
- b) any changes other than the results of normal maintenance
- c) corrections to deficiencies noted in this report

If additional items are noted, further documentation of those items must also be submitted.

The LMA should submit this information to DWR using the LMA web application tool available at:

<http://cdec.water.ca.gov/lma.html>

If the LMA is unable to submit information on this webpage, please contact DWR for assistance.

The LMA should submit the information and any associated documentation by September 30 for summer inspections and March 31 for winter inspections.

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2015

Reclamation District No. 1500 Sutter Basin

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	33.15	10/20/2015 10/21/2015	Jai Lor

LM Start		Rating **	A	Issue No.	9
LM End		Issue Type +	Ma	Location *	N/A
Category	Earthen Levee		GPS Latitude/Longitude		
			Start		End
Item	Operations & Maintenance Manuals			o	o
DWR ID	DWR_RD1500_01_s_2013_9				
Action/Comments					
Inspector Comments: RD 1500 has their O&M Manual.					

No Photos

LM Start		Rating **	A	Issue No.	55
LM End		Issue Type +	Ma	Location *	N/A
Category	Earthen Levee		GPS Latitude/Longitude		
			Start		End
Item	Emergency Supplies & Equipment			o	o
DWR ID	DWR_RD1500_01_s_2013_55				
Action/Comments					
Inspector Comments: RD 1500 maintains a stockpile of flood response material.					

No Photos

LM Start		Rating **	A	Issue No.	61
LM End		Issue Type +	Ma	Location *	N/A
Category	Earthen Levee		GPS Latitude/Longitude		
			Start		End
Item	Flood Preparedness & Training			o	o
DWR ID	DWR_RD1500_01_s_2013_61				
Action/Comments					
Inspector Comments: RD 1500 is current with it's flood response plans and training.					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2015

Reclamation District No. 1500 Sutter Basin

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	33.15	10/20/2015 10/21/2015	Jai Lor

LM Start	0.02	Rating **	C	Issue No.	1681
LM End	0.02	Issue Type +	Ma	Location *	N/A
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			38.761057 °	38.761057 °
				-121.675021 °	-121.675021 °
DWR ID	DWR_RD1500_01_s_2015_1681				
Action/Comments					
Exterminate rodents and backfill and compact or grout burrows.					

No Photos

LM Start	0.20	Rating **	C	Issue No.	2535
LM End	0.20	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			38.761728 °	38.761728 °
				-121.677991 °	-121.677991 °
DWR ID	DWR_RD1500_01_s_2015_2535				
Action/Comments					
No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.					

No Photos

LM Start	0.23	Rating **	C	Issue No.	2536
LM End	0.23	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			38.762233 °	38.762233 °
				-121.678326 °	-121.678326 °
DWR ID	DWR_RD1500_01_s_2015_2536				
Action/Comments					
No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2015

Reclamation District No. 1500 Sutter Basin

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	33.15	10/20/2015 10/21/2015	Jai Lor

LM Start	0.31	Rating **	C	Issue No.	2538
LM End	0.31	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			38.763141 °	38.763141 °
				-121.678949 °	-121.678949 °
DWR ID	DWR_RD1500_01_s_2015_2538				
Action/Comments					
No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.					

No Photos

LM Start	0.31	Rating **	C	Issue No.	2540
LM End	0.31	Issue Type +	Ma	Location *	CR
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			38.763154 °	38.763154 °
				-121.678967 °	-121.678967 °
DWR ID	DWR_RD1500_01_s_2015_2540				
Action/Comments					
Exterminate rodents and backfill and compact or grout burrows.					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2015

Reclamation District No. 1500 Sutter Basin

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	33.15	10/20/2015 10/21/2015	Jai Lor

LM Start	0.31	Rating **	M	Issue No.	2551
LM End	0.31	Issue Type +	En	Location *	CR
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			38.763210 °	38.763210 °
				-121.679017 °	-121.679017 °
DWR ID					
Action/Comments					
Inspector Comments: FS_ID:28183 DS_ID:20032 EP_NO: 1566A FS_HLM: 0.32 Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: - soil erosion around headwall on waterside.- pump was removed.- overhead powerline. FIELD_STRUCT_DESC: 10-inch steel irrigation pipe through levee, 5.0 feet below crown. Pump and switch panel on waterside berm. Service pole on waterward shoulder. Siphon breaker on landward slope. A 3-foot by 4-foot concrete distribution box at landward toe (App. No. 1566A White) O&M Manual Sac 128, March 1960. FS Date: 01/09/2014					

Photo 1 of 3 : UCIP_FA_2015_2967.jpg



LS view: open steel pipe in concrete distribution box on levee toe.

LM Start	0.31	Rating **	M	Issue No.	2551 (cont)
LM End	0.31	Issue Type +	En	Location *	CR

Photo 2 of 3 : UCIP_FA_2015_2968.jpg



LS view: pressure breaker (bottom) in steel pipe riser and concrete distribution box on levee toe.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2015

Reclamation District No. 1500 Sutter Basin

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	33.15	10/20/2015 10/21/2015	Jai Lor

LM Start	0.50	Rating **	C	Issue No.	1336
LM End	0.50	Issue Type +	En	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			38.764497 °	38.764497 °
				-121.681925 °	-121.681925 °
DWR ID	DWR_RD1500_01_s_2014_1336				
Action/Comments					
Prunings					

No Photos

LM Start	0.51	Rating **	C	Issue No.	2542
LM End	0.51	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			38.764514 °	38.764514 °
				-121.682210 °	-121.682210 °
DWR ID	DWR_RD1500_01_s_2015_2542				
Action/Comments					
No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.					

No Photos

LM Start	0.56	Rating **	A/W	Issue No.	72
LM End	0.82	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.764462 °	38.764638 °
				-121.683167 °	-121.687690 °
DWR ID	DWR_RD1500_01_s_2012_72				
Action/Comments					
Environmental Requirements.					

Photo 1 of 2 : FA_2015_RD1500_189_72_20150914_00049.jpg



A view of the revegetation site.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2015

Reclamation District No. 1500 Sutter Basin

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	33.15	10/20/2015 10/21/2015	Jai Lor

LM Start	0.56	Rating **	A/W	Issue No.	72 (cont)
LM End	0.82	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.764462 °	38.764638 °
				-121.683167 °	-121.687690 °
DWR ID	DWR_RD1500_01_s_2012_72				
Action/Comments					
Environmental Requirements.					

Photo 2 of 2 : FA_2015_RD1500_189_72_20150914_00050.jpg



A revegetation site waterside toe, photo taken spring 2012.

LM Start	0.63	Rating **	A/W	Issue No.	76
LM End	1.05	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Slope Stability			38.764305 °	38.766827 °
				-121.684396 °	-121.690884 °
DWR ID	DWR_RD1500_01_s_2013_76				
Action/Comments					
Repair slope instability. Inspector Comments: Seepage berm was damaged last fall in prep for the agricultural field and needs to be restored by the land owner. A field investigation report was made. The seepage berm is scheduled to be repaired before next flood season.					

Photo 1 of 2 : FA_2015_RD1500_189_76_20150914_00053.jpg



Damage to the seepage berm during the flood season needs to be repaired, Spring 2013

LM Start	0.63	Rating **	A/W	Issue No.	76 (cont)
LM End	1.05	Issue Type +	Ma	Location *	LS

Photo 2 of 2 : FA_2015_RD1500_189_76_20150914_00054.jpg



The damage to the seepage berm has been repaired and needs to be monitored. Spring 2014

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	--	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2015

Reclamation District No. 1500 Sutter Basin

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	33.15	10/20/2015 10/21/2015	Jai Lor

LM Start	1.29	Rating **	M	Issue No.	2552
LM End	1.29	Issue Type +	En	Location *	LS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			38.769697 °	38.769697 °
				-121.691024 °	-121.691024 °
DWR ID					
Action/Comments					
Inspector Comments: FS_ID:28903 DS_ID:20094 EP_NO: 10080 FS_HLM: 1.305 Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: Pump removed from concrete pad and kept inside pump house (may be for storage purpose) on waterside. A 8-inch steel pipe inside 14-inch pipe. FIELD_STRUCT_DESC: 14-inch steel irrigation pipe through levee, 5.2 feet below crown. Pump on river bank. Butterfly valve on waterward side. Concrete stairway on waterward slope. 1-3/4-inch galvanized iron waterline with tap exposed on landward slope 3.4 feet below crown. 4 foot by 5.1 foot concrete distribution box at landward toe. 1-1/4-inch conduit through levee, 2.0 feet below crown. (ABO No. 10080 - Yturralde) FS Date: 01/09/2014					

Photo 1 of 3 : UCIP_FA_2015_3270.jpg



WS view: pump removed from pipe and stored in pump house.

LM Start	1.29	Rating **	M	Issue No.	2552 (cont)
LM End	1.29	Issue Type +	En	Location *	LS

Photo 2 of 3 : UCIP_FA_2015_3271.jpg



WS view: U type headwall and 8-inch pipe sleeved into 14-inch steel pipe. Pump was removed from the pipe.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	--	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2015

Reclamation District No. 1500 Sutter Basin

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	33.15	10/20/2015 10/21/2015	Jai Lor

LM Start	1.29	Rating **	M	Issue No.	2552 (cont)
LM End	1.29	Issue Type +	En	Location *	LS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			38.769697 °	38.769697 °
				-121.691024 °	-121.691024 °
DWR ID					
Action/Comments					
Inspector Comments: FS_ID:28903 DS_ID:20094 EP_NO: 10080 FS_HLM: 1.305 Repair Type: Non-Urgent Crossing Status: Found					

Photo 3 of 3 : UCIP_FA_2015_3272.jpg



WS view: pipe (left), pump house/store, and concrete steps.

LM Start	1.29	Rating **	M	Issue No.	2553
LM End	1.29	Issue Type +	En	Location *	LS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			38.769698 °	38.769698 °
				-121.691023 °	-121.691023 °
DWR ID					
Action/Comments					
Inspector Comments: FS_ID:28905 DS_ID:20095 EP_NO: 10080 FS_HLM: 1.305 Repair Type: Non-Urgent Crossing Status: Not Found UCIP Comments: - an electrical conduit for the pump- 1-3/4-inch galvanized iron waterline with tap exposed on landward slope 3.4 feet below crown not found. Included in Record No. 20094. FIELD_STRUCT_DESC: 2 of 2: 14-inch steel irrigation pipe through levee, 5.2 feet below crown. Pump in CM pump house on waterward slope. Butterfly valve on waterward side. Concrete stairway on waterward slope. A 4 foot by 5 foot concrete distribution box at landside toe. A 1-1/4-inch conduit through levee, 2.0 feet below crown. (ABO No. 10080 - Yturalde) FS Date: 01/09/2014					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2015

Reclamation District No. 1500 Sutter Basin

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	33.15	10/20/2015 10/21/2015	Jai Lor

LM Start	1.32	Rating **	M	Issue No.	4
LM End	1.32	Issue Type +	En	Location *	N/A
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Vegetation		38.770003 °	38.770003 °	
			-121.690607 °	-121.690607 °	
DWR ID	DWR_RD1500_01_s_2012_4				
Action/Comments					
Landscaping Inspector Comments: Retaining wall built into the levee.					

Photo 1 of 1 : FA_2015_RD1500_189_4_20150914_00004.jpg



Landscape with retaining wall that is in the USACE as-builts Fall 2013

LM Start	1.34	Rating **	M	Issue No.	6
LM End	1.95	Issue Type +	Ma	Location *	WS
Category	Supplemental		GPS Latitude/Longitude		
			Start	End	
Item	2015 USACE Erosion Survey, DRAFT		38.770390 °	38.777282 °	
			-121.690553 °	-121.685841 °	
DWR ID					
Action/Comments					
Inspector Comments: 2006 - New erosion upstream, new bank failures near levee but still fairly wide berm in most places. 2008 - Large berm, questionable as to if it should remain in the inventory. 2010 - Minor new erosion, old cobble starting to fail. 2011 - Cobble continues to unravel and additional slumping. 2012 - Minor new erosion at bank mid point. 2013 - Minor new erosion. 2015: No observed changes. [2015 Site ID: SAC_86-3_L]					

Photo 1 of 1 : USACE2013A_SAC_86-3_L_2.jpg



USACE 2013 Photo #1

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable N : Not Inspected/Rated M : Minimally Acceptable C : Corrected U : Unacceptable A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
---	--	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2015

Reclamation District No. 1500 Sutter Basin

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	33.15	10/20/2015 10/21/2015	Jai Lor

LM Start	1.63	Rating **	M	Issue No.	2554
LM End	1.63	Issue Type +	En	Location *	WS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			38.772862 °	38.772862 °
				-121.686453 °	-121.686453 °
DWR ID					
Action/Comments					
Inspector Comments: FS_ID:28204 DS_ID:20033 EP_NO: N/A FS_HLM: 1.64 Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: - pump removed- erosion around pump station.- overhead electrical line. FIELD_STRUCT_DESC: 10-inch diameter steel irrigation pipeline through levee, 10.0 feet below crown. Pump and gate valve on bank. Service pole and switch panel on waterward shoulder. Pipe crosses irrigation ditch and discharges into steel distribution box on the field. FS Date: 01/09/2014					

Photo 1 of 3 : UCIP_FA_2015_2990.jpg



LS view: pipe crosses irrigation ditch. Steel distribution box across irrigation ditch.

LM Start	1.63	Rating **	M	Issue No.	2554 (cont)
LM End	1.63	Issue Type +	En	Location *	WS

Photo 2 of 3 : UCIP_FA_2015_2991.jpg



WS view: pump (removed) and inlet pipe on river bank.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
---	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2015

Reclamation District No. 1500 Sutter Basin

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	33.15	10/20/2015 10/21/2015	Jai Lor

LM Start	1.63	Rating **	M	Issue No.	2554 (cont)
LM End	1.63	Issue Type +	En	Location *	WS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			38.772862 °	38.772862 °
				-121.686453 °	-121.686453 °
DWR ID					
Action/Comments					
Inspector Comments: FS_ID:28204 DS_ID:20033 EP_NO: N/A FS_HLM: 1.64 Repair Type: Non-Urgent Crossing Status: Found					

Photo 3 of 3 : UCIP_FA_2015_2992.jpg



WS view: Service pole with control panel on levee shoulder.

LM Start	1.96	Rating **	M	Issue No.	2555
LM End	1.96	Issue Type +	En	Location *	WS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			38.777433 °	38.777433 °
				-121.685348 °	-121.685348 °
DWR ID					
Action/Comments					
Inspector Comments: FS_ID:28263 DS_ID:20034 EP_NO: 16146 FS_HLM: 1.973 Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: - pump removed- overhead powerline- pile structure abandoned- levee slope erosion due to leaky siphon breaker on landside. FIELD_STRUCT_DESC: 12-inch diameter steel pipe through levee, 12.0 feet below crown. Pump mounted on river bank, butterfly valve on waterward side. Power pole with one anchor on waterside slope. Pump discharges into 5 foot by 5 foot concrete distribution box (damaged) across the irrigation ditch on the landside. (Cat. I Furlan) (App. No. 16146) O&M Manual Sac 128, March 1960. FS Date: 01/09/2014					

Photo 1 of 3 : UCIP_FA_2015_3052.jpg



LS view: discharge pipe crossing irrigation ditch.

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	--	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2015

Reclamation District No. 1500 Sutter Basin

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	33.15	10/20/2015 10/21/2015	Jai Lor

LM Start	1.96	Rating **	M	Issue No.	2555 (cont)
LM End	1.96	Issue Type +	En	Location *	WS
Category	Supplemental			GPS Latitude/Longitude	
	Item		Start	End	
DWR UCIP Field Study			38.777433 °	38.777433 °	
DWR ID			-121.685348 °	-121.685348 °	
Action/Comments					
Inspector Comments: FS_ID:28263 DS_ID:20034 EP_NO: 16146 FS_HLM: 1.973 Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: - pump removed- overhead powerline- pile structure abandoned- levee slope erosion due to leaky siphon breaker on landside. FIELD_STRUCT_DESC: 12-inch diameter steel pipe through levee, 12.0 feet below crown. Pump mounted on river bank, butterfly valve on waterward side. Power pole with one anchor on waterside slope. Pump discharges into 5 foot by 5 foot concrete distribution box (damaged) across the irrigation ditch on the landside. (Cat. I Furlan) (App. No. 16146) O&M Manual Sac 128, March 1960. FS Date: 01/09/2014					

Photo 2 of 3 : UCIP_FA_2015_3053.jpg



LS view: siphon breaker in CMP riser. Levee slope erosion due to leaky siphon breaker.

LM Start	1.96	Rating **	M	Issue No.	2555 (cont)
LM End	1.96	Issue Type +	En	Location *	WS

Photo 3 of 3 : UCIP_FA_2015_3054.jpg



WS view: Pump (removed and plywood plated), pipe, and gate valve in CMP riser on river bank.

* Location	** Rating	+ Issue Type
LS : Land Side WS : Water Side CR : Crown	A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain
N/A : Not Applicable		Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2015

Reclamation District No. 1500 Sutter Basin

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	33.15	10/20/2015 10/21/2015	Jai Lor

LM Start	2.30	Rating **	M	Issue No.	2
LM End	2.52	Issue Type +	Ma	Location *	WS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	2015 USACE Erosion Survey, DRAFT			38.781962 °	38.784936 °
				-121.688033 °	-121.690033 °
DWR ID					
Action/Comments					
Inspector Comments: 2010 - The upstream end of the repair site at 87.0. Repair did not extend far enough upstream. 2011 - New erosion pockets. 2012 - Minor new erosion at toe. 2013 - Minor new erosion. 2015: Significant new toe erosion. [2015 Site ID: SAC_87-1_L]					

Photo 1 of 1 : USACE2013A_SAC_87-1_L_3.jpg



USACE 2013 Photo #1

LM Start	2.38	Rating **	M	Issue No.	2556
LM End	2.38	Issue Type +	En	Location *	WS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			38.783184 °	38.783184 °
				-121.688136 °	-121.688136 °
DWR ID					
Action/Comments					
Inspector Comments: FS_ID:28264 DS_ID:20035 EP_NO: 10029 FS_HLM: 2.402 Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: - pump removed- outlet plugged- looks abandoned. Found abandoned pipe parts on levee slope and berm.- overhead powerline FIELD_STRUCT_DESC: Abandoned 12-inch steel irrigation pipe through levee, 11.0-feet below crown. Two metal cutoff walls installed. Pump on bank during irrigation season. Gate valve at waterward toe. Discharges into 2.5x2.5 foot concrete distribution box on landward side of irrigation ditch. (ABO No. 10029 - Anderson). O&M Manual Sac 128, March 1960. FS Date: 01/09/2014					

Photo 1 of 3 : UCIP_FA_2015_3055.jpg



LS view: plugged discharge pipe with air vent across irrigation ditch on landside.

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	+ Issue Type N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	--	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2015

Reclamation District No. 1500 Sutter Basin

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	33.15	10/20/2015 10/21/2015	Jai Lor

LM Start	2.38	Rating **	M	Issue No.	2556 (cont)
LM End	2.38	Issue Type +	En	Location *	WS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			38.783184 °	38.783184 °
				-121.688136 °	-121.688136 °
DWR ID					
Action/Comments					
Inspector Comments: FS_ID:28264 DS_ID:20035 EP_NO: 10029 FS_HLM: 2.402 Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: - pump removed- outlet plugged- looks abandoned. Found abandoned pipe parts on levee slope and berm.- overhead powerline FIELD_STRUCT_DESC: Abandoned 12-inch steel irrigation pipe through levee, 11.0-feet below crown. Two metal cutoff walls installed. Pump on bank during irrigation season. Gate valve at waterward toe. Discharges into 2.5x2.5 foot concrete distribution box on landward side of irrigation ditch. (ABO No. 10029 - Anderson). O&M Manual Sac 128, March 1960. FS Date: 01/09/2014					

Photo 2 of 3 : UCIP_FA_2015_3056.jpg



LS view: discharge pipe crossing irrigation ditch on landside.

LM Start	2.38	Rating **	M	Issue No.	2556 (cont)
LM End	2.38	Issue Type +	En	Location *	WS

Photo 3 of 3 : UCIP_FA_2015_3057.jpg



WS view: steel pipe, gate valve, and pump (removed) on river bank. Looks abandoned.

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	--	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2015

Reclamation District No. 1500 Sutter Basin

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	33.15	10/20/2015 10/21/2015	Jai Lor

LM Start	2.54	Rating **	M	Issue No.	963
LM End	3.79	Issue Type +	En	Location *	LS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Encroachments		38.785351 °	38.797174 °	
			-121.689075 °	-121.693045 °	
DWR ID	DWR_RD1500_01_s_2012_963				
Action/Comments					
Ditch					

Photo 1 of 1 : FA_2015_RD1500_189_963_20150914_00067.jpg



Agricultural ditch, photo was taken in spring 2010.

LM Start	3.95	Rating **	M	Issue No.	7
LM End	3.95	Issue Type +	En	Location *	LS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Encroachments		38.797607 °	38.797607 °	
			-121.695862 °	-121.695862 °	
DWR ID	DWR_RD1500_01_s_2012_7				
Action/Comments					
Building					

Photo 1 of 2 : FA_2015_RD1500_189_7_20150914_00005.jpg



A small building is encroaching into the landside levee toe.

LM Start	3.95	Rating **	M	Issue No.	7 (cont)
LM End	3.95	Issue Type +	En	Location *	LS

Photo 2 of 2 : FA_2015_RD1500_189_7_20150914_00006.jpg



Chicken coupes have been added along the toe of the levee. Spring 2014

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2015

Reclamation District No. 1500 Sutter Basin

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	33.15	10/20/2015 10/21/2015	Jai Lor

LM Start	3.96	Rating **	M	Issue No.	8
LM End	3.96	Issue Type +	En	Location *	LS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Vegetation		38.797827 °	38.797827 °	
			-121.695985 °	-121.695985 °	
DWR ID	DWR_RD1500_01_s_2012_8				
Action/Comments					
Landscaping					

Photo 1 of 1 : FA_2015_RD1500_189_8_20150914_00007.jpg



The landscape is planted into the encroachment zone within 15' of the toe.

LM Start	4.01	Rating **	M	Issue No.	2557
LM End	4.01	Issue Type +	En	Location *	LS
Category	Supplemental		GPS Latitude/Longitude		
			Start	End	
Item	DWR UCIP Field Study		38.798436 °	38.798436 °	
			-121.696280 °	-121.696280 °	
DWR ID					
Action/Comments					
Inspector Comments: FS_ID:28272 DS_ID:20037 EP_NO: 3638 FS_HLM: 4.04 Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: - No protection for pressure breaker. FIELD_STRUCT_DESC: 12-inch steel irrigation pipe through levee, 2.4 feet below crown. Slant pump on berm. Pressure breaker on landward slope. Service pole at landward toe. Discharges into 36-inch diameter concrete standpipe on landside. (App. No. 3638 - J. Waters) FS Date: 01/09/2014					

Photo 1 of 3 : UCIP_FA_2015_3240.jpg



LS view: pressure breaker without protection on levee slope.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2015

Reclamation District No. 1500 Sutter Basin

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	33.15	10/20/2015 10/21/2015	Jai Lor

LM Start	4.01	Rating **	M	Issue No.	2557 (cont)
LM End	4.01	Issue Type +	En	Location *	LS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			38.798436 °	38.798436 °
				-121.696280 °	-121.696280 °
DWR ID					
Action/Comments					
Inspector Comments: FS_ID:28272 DS_ID:20037 EP_NO: 3638 FS_HLM: 4.04 Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: - No protection for pressure breaker. FIELD_STRUCT_DESC: 12-inch steel irrigation pipe through levee, 2.4 feet below crown. Slant pump on berm. Pressure breaker on landward slope. Service pole at landward toe. Discharges into 36-inch diameter concrete standpipe on landside. (App. No. 3638 - J. Waters) FS Date: 01/09/2014					

Photo 2 of 3 : UCIP_FA_2015_3241.jpg



WS view: slant pump on steel frame on levee berm.

LM Start	4.01	Rating **	M	Issue No.	2557 (cont)
LM End	4.01	Issue Type +	En	Location *	LS

Photo 3 of 3 : UCIP_FA_2015_3242.jpg



LS view: power pole and concrete standpipe on levee toe.

* Location	** Rating	+ Issue Type
LS : Land Side WS : Water Side CR : Crown	A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain
N/A : Not Applicable		Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2015

Reclamation District No. 1500 Sutter Basin

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	33.15	10/20/2015 10/21/2015	Jai Lor

LM Start	4.02	Rating **	M	Issue No.	54
LM End	4.12	Issue Type +	En	Location *	LS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Encroachments		38.798572 °	38.800080 °	
			-121.696392 °	-121.696653 °	
DWR ID	DWR_RD1500_01_s_2012_54				
Action/Comments					
Ditch					

Photo 1 of 1 : FA_2015_RD1500_189_54_20150914_00045.jpg



An agricultural ditch runs along the toe of the levee, photo taken spring 2012.

LM Start	4.16	Rating **	M	Issue No.	11
LM End	4.16	Issue Type +	En	Location *	LS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Encroachments		38.800548 °	38.800548 °	
			-121.696751 °	-121.696751 °	
DWR ID	DWR_RD1500_01_s_2012_11				
Action/Comments					
Building					

Photo 1 of 1 : FA_2015_RD1500_189_11_20150914_00009.jpg



The equipment shed encroaches into the toe of the levee.

LM Start	4.60	Rating **	M	Issue No.	12
LM End	4.60	Issue Type +	En	Location *	LS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Vegetation		38.803585 °	38.803585 °	
			-121.702910 °	-121.702910 °	
DWR ID	DWR_RD1500_01_s_2012_12				
Action/Comments					
Landscaping					

Photo 1 of 1 : FA_2015_RD1500_189_12_20150914_00010.jpg



The landscape is planted within the encroachment area of 15'.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2015

Reclamation District No. 1500 Sutter Basin

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	33.15	10/20/2015 10/21/2015	Jai Lor

LM Start	4.68	Rating **	M	Issue No.	2558
LM End	4.68	Issue Type +	En	Location *	LS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			38.803025 °	38.803025 °
				-121.704091 °	-121.704091 °
DWR ID					

Action/Comments

Inspector Comments: FS_ID:28912
 DS_ID:20040
 EP_NO: 5031
 FS_HLM: 4.713
 Repair Type: Non-Urgent
 Crossing Status: Found
 UCIP Comments: New butterfly valve in CMP riser on waterside slope. New pipe and pump. Needs cleaning and clearing of siphon breaker in CMP on landside. An abandoned 5x5 foot concrete distribution box on landside. Abandoned pipe found on both sides of the levee.
 FIELD_STRUCT_DESC: 12-inch diameter steel irrigation pipe through levee at slight angle, 4.2 feet below crown. A 2-inch diameter conduit through levee, 2.0 feet below crown. Slant pump on steel platform on berm. (App. No. 5031-Knox.) Discharges into irrigation ditch and an abandoned 5x5 foot concrete distribution box on landside. Pipe originally installed in 1950 under App. No. 1466 By Estate of Caroline L. Knox reinstalled by USCE, in 1958; O&M Manual Sac 128, March 1960. FS Date: 01/09/2014

Photo 1 of 3 : UCIP_FA_2015_0609.jpg



WS view: new butterfly valve in CMP on levee shoulder.

LM Start	4.68	Rating **	M	Issue No.	2558 (cont)
LM End	4.68	Issue Type +	En	Location *	LS

Photo 2 of 3 : UCIP_FA_2015_0610.jpg



LS view: obstructed siphon breaker in CMP riser.

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	--	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2015

Reclamation District No. 1500 Sutter Basin

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	33.15	10/20/2015 10/21/2015	Jai Lor

LM Start	4.68	Rating **	M	Issue No.	2558 (cont)
LM End	4.68	Issue Type +	En	Location *	LS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			38.803025 °	38.803025 °
				-121.704091 °	-121.704091 °
DWR ID					
Action/Comments					
Inspector Comments: FS_ID:28912 DS_ID:20040 EP_NO: 5031 FS_HLM: 4.713 Repair Type: Non-Urgent Crossing Status: Found					

Photo 3 of 3 : UCIP_FA_2015_0611.jpg



WS view: slant pump and switch panel in shed on levee berm.

LM Start	4.68	Rating **	M	Issue No.	107
LM End	4.68	Issue Type +	En	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			38.802986 °	38.802986 °
				-121.704134 °	-121.704134 °
DWR ID	DWR_RD1500_01_f_2015_107				
Action/Comments					
Pipe Inspector Comments: Seems like owner is trying to fix the conduit next to the pipe.					

Photo 1 of 3 : FA_2015_RD1500_189_107_20151026_00139.jpg



View of the pipe exposure on the waterward side of the levee looking upstream. Fall 2015.

LM Start	4.68	Rating **	M	Issue No.	107 (cont)
LM End	4.68	Issue Type +	En	Location *	WS

Photo 2 of 3 : FA_2015_RD1500_189_107_20151026_00140.jpg



A close-up view of the exposed pipe. Fall 2015.

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
N/A : Not Applicable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2015

Reclamation District No. 1500 Sutter Basin

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	33.15	10/20/2015 10/21/2015	Jai Lor

LM Start	4.68	Rating **	M	Issue No.	107 (cont)
LM End	4.68	Issue Type +	En	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			38.802986 °	38.802986 °
				-121.704134 °	-121.704134 °
DWR ID	DWR_RD1500_01_f_2015_107				
Action/Comments					
Pipe Inspector Comments: Seems like owner is trying to fix the conduit next to the pipe.					

Photo 3 of 3 : FA_2015_RD1500_189_107_20151026_00141.jpg



There is a hole on the culvert next to the pipe. Fall 2015.

LM Start	5.14	Rating **	M	Issue No.	108
LM End	5.14	Issue Type +	En	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			38.801962 °	38.801962 °
				-121.712118 °	-121.712118 °
DWR ID	DWR_RD1500_01_f_2015_108				
Action/Comments					
Equipment					

Photo 1 of 1 : FA_2015_RD1500_189_108_20151026_00142.jpg



View of the equipment on the landward side of the levee looking upstream. Fall 2015.

LM Start	5.17	Rating **	A/W	Issue No.	1340
LM End	5.17	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.802164 °	38.802164 °
				-121.712560 °	-121.712560 °
DWR ID	DWR_RD1500_01_s_2014_1340				
Action/Comments					
Trees / Woody Vegetation					

Photo 1 of 1 : FA_2015_RD1500_189_1340_20150914_00076.jpg



Monitor tree that may pose a future threat to the integrity of the levee. Spring 2014

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2015

Reclamation District No. 1500 Sutter Basin

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	33.15	10/20/2015 10/21/2015	Jai Lor

LM Start	5.19	Rating **	M	Issue No.	2559
LM End	5.19	Issue Type +	En	Location *	LS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			38.802322 °	38.802322 °
				-121.712908 °	-121.712908 °
DWR ID					
Action/Comments					
Inspector Comments: FS_ID:28913 DS_ID:20041 EP_NO: 10056 FS_HLM: 5.23 Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: Depression on landside levee slope around siphon breaker due to leakage. Siphon breaker needs protection. FIELD_STRUCT_DESC: 18-inch steel irrigation pipe through levee, 4.0 feet below crown. 1 1/2-inch conduit through levee, 20 ft below crown. Slant pump in CM pump house on waterside. Wooden steps on waterside slope. Siphon breaker on landside slope. A 5 ft x 5 ft Concrete distribution box at landward toe. (ABO No. 10056 - Leiser) O&M Manual Sac 128, March 1960. FS Date: 01/09/2014					

Photo 1 of 3 : UCIP_FA_2015_0612.jpg



LS view: leaky and obstructed siphon breaker. Depression around siphon breaker due to leakage.

LM Start	5.19	Rating **	M	Issue No.	2559 (cont)
LM End	5.19	Issue Type +	En	Location *	LS

Photo 2 of 3 : UCIP_FA_2015_0613.jpg



LS view: depression on landside levee slope around siphon breaker due to leakage. Concrete distribution box (top) on levee toe.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable N : Not Inspected/Rated M : Minimally Acceptable C : Corrected U : Unacceptable A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
---	--	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2015

Reclamation District No. 1500 Sutter Basin

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	33.15	10/20/2015 10/21/2015	Jai Lor

LM Start	5.19	Rating **	M	Issue No.	2559 (cont)
LM End	5.19	Issue Type +	En	Location *	LS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			38.802322 °	38.802322 °
				-121.712908 °	-121.712908 °
DWR ID					
Action/Comments					
Inspector Comments: FS_ID:28913 DS_ID:20041 EP_NO: 10056 FS_HLM: 5.23 Repair Type: Non-Urgent Crossing Status: Found					

Photo 3 of 3 : UCIP_FA_2015_0614.jpg



WS view: wooden steps to pump house on levee berm.

LM Start	5.26	Rating **	M	Issue No.	1341
LM End	5.26	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			38.802827 °	38.802827 °
				-121.714043 °	-121.714043 °
DWR ID	DWR_RD1500_01_s_2014_1341				
Action/Comments					
Trim trees to at least five feet above ground level.					

Photo 1 of 1 : FA_2015_RD1500_189_1341_20150914_00077.jpg



Trees need to be trimmed up to at least 5' they are blocking the visibility. Spring 2014

LM Start	5.26	Rating **	C	Issue No.	1342
LM End	5.26	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			38.802826 °	38.802826 °
				-121.714044 °	-121.714044 °
DWR ID	DWR_RD1500_01_s_2014_1342				
Action/Comments					
Exterminate rodents and backfill and compact or grout burrows.					

No Photos

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2015

Reclamation District No. 1500 Sutter Basin

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	33.15	10/20/2015 10/21/2015	Jai Lor

LM Start	5.34	Rating **	M	Issue No.	14
LM End	5.34	Issue Type +	En	Location *	LS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Vegetation		38.803240 °	38.803240 °	
			-121.715402 °	-121.715402 °	
DWR ID	DWR_RD1500_01_s_2012_14				
Action/Comments					
Landscaping					

Photo 1 of 1 : FA_2015_RD1500_189_14_20151026_00143.jpg



View of the landscape on the landward side of the levee looking upstream. Fall 2015.

LM Start	5.61	Rating **	M	Issue No.	52
LM End	5.69	Issue Type +	En	Location *	WS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Encroachments		38.803005 °	38.803238 °	
			-121.720380 °	-121.71847 °	
DWR ID	DWR_RD1500_01_s_2012_52				
Action/Comments					
Building Inspector Comments: Sting Rayz Beach Boardwalk Marina on the waterside berm.					

Photo 1 of 2 : FA_2015_RD1500_189_52_20150914_00042.jpg



String Rayzs RV park, Fall 2013

LM Start	5.61	Rating **	M	Issue No.	52 (cont)
LM End	5.69	Issue Type +	En	Location *	WS

Photo 2 of 2 : FA_2015_RD1500_189_52_20150914_00043.jpg



String Rayzs, Fall 2013

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2015

Reclamation District No. 1500 Sutter Basin

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	33.15	10/20/2015 10/21/2015	Jai Lor

LM Start	6.48	Rating **	M	Issue No.	2560
LM End	6.48	Issue Type +	En	Location *	WS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			38.814501 °	38.814501 °
				-121.723040 °	-121.723040 °
DWR ID					
Action/Comments					
Inspector Comments: FS_ID:28286 DS_ID:20044 EP_NO: 10074 FS_HLM: 6.53 Repair Type: Non-Urgent Crossing Status: Found					

Photo 1 of 2 : UCIP_FA_2015_3383.jpg



LS view: a capped pipe on levee toe. It is not clear whether this pipe is connected to the CMP riser on waterside.

LM Start	6.48	Rating **	M	Issue No.	2560 (cont)
LM End	6.48	Issue Type +	En	Location *	WS

Photo 2 of 2 : UCIP_FA_2015_3384.jpg



WS view: CMP riser with slide gate and slant pump on steel platform on levee berm.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
---	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2015

Reclamation District No. 1500 Sutter Basin

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	33.15	10/20/2015 10/21/2015	Jai Lor

LM Start	7.15	Rating **	M	Issue No.	217
LM End	7.15	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			38.824119 °	38.824119 °
				-121.722776 °	-121.722776 °
DWR ID	DWR_RD1500_01_s_2012_217				
Action/Comments					
Trim trees to at least five feet above ground level.					

Photo 1 of 1 : FA_2015_RD1500_189_217_20150914_00064.jpg



Trees need to be trimmed to the height of 5 feet to see the slope.

LM Start	7.15	Rating **	M	Issue No.	2561
LM End	7.15	Issue Type +	En	Location *	LS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			38.824208 °	38.824208 °
				-121.722793 °	-121.722793 °
DWR ID					
Action/Comments					
Inspector Comments: FS_ID:28923 DS_ID:20047 EP_NO: 10048 FS_HLM: 7.22 Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: An abandoned pipe. Highly deteriorated pipe on river bank. Needs proper abandonment. Not found- Siphon breaker at landward levee toe. FIELD_STRUCT_DESC: Abandoned 10-inch diameter irrigation pipe through levee, 4.5 feet below crown. A 1-inch conduit through levee, 4.5 feet below crown. A pump in metal shed on bank. Gate valve on waterside end. Service pole and 24-inch Concrete standpipe at landside toe. Installed by USCE, 1958 (ABO. No. 10048-King) O&M Manual Sac 128, March 1960. FS Date: 01/09/2014					

Photo 1 of 3 : UCIP_FA_2015_0615.jpg



LS view: service pole and switch board on levee toe. No other apurtenances found on landside.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable N : Not Inspected/Rated M : Minimally Acceptable C : Corrected U : Unacceptable A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
---	--	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2015

Reclamation District No. 1500 Sutter Basin

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	33.15	10/20/2015 10/21/2015	Jai Lor

LM Start	7.15	Rating **	M	Issue No.	2561 (cont)
LM End	7.15	Issue Type +	En	Location *	LS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			38.824208 °	38.824208 °
				-121.722793 °	-121.722793 °
DWR ID					
Action/Comments					
Inspector Comments: FS_ID:28923 DS_ID:20047 EP_NO: 10048 FS_HLM: 7.22 Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: An abandoned pipe. Highly deteriorated pipe on river bank. Needs proper abandonment. Not found- Siphon breaker at landward levee toe. FIELD_STRUCT_DESC: Abandoned 10-inch diameter irrigation pipe through levee, 4.5 feet below crown. A 1-inch conduit through levee, 4.5 feet below crown. A pump in metal shed on bank. Gate valve on waterside end. Service pole and 24-inch Concrete standpipe at landside toe. Installed by USCE, 1958 (ABO. No. 10048-King) O&M Manual Sac 128, March 1960. FS Date: 01/09/2014					

Photo 2 of 3 : UCIP_FA_2015_0616.jpg



WS view: deteorated and abandoned steel pipe on river bank.

LM Start	7.15	Rating **	M	Issue No.	2561 (cont)
LM End	7.15	Issue Type +	En	Location *	LS

Photo 3 of 3 : UCIP_FA_2015_0617.jpg



WS view: dilapidated and abandoned CM pump house on berm. Pipe and gate valve also on berm.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2015

Reclamation District No. 1500 Sutter Basin

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	33.15	10/20/2015 10/21/2015	Jai Lor

LM Start	7.20	Rating **	A/W	Issue No.	1343
LM End	7.20	Issue Type +	Ma	Location *	LS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Vegetation		38.824900 °	38.824900 °	
			-121.722851 °	-121.722851 °	
DWR ID	DWR_RD1500_01_s_2014_1343				
Action/Comments					
Trees / Woody Vegetation					

Photo 1 of 1 : FA_2015_RD1500_189_1343_20150914_00079.jpg



Monitor tree that may pose a future threat to the integrity of the levee. Spring 2014

LM Start	7.49	Rating **	M	Issue No.	16
LM End	7.49	Issue Type +	Ma	Location *	LS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Encroachments		38.828975 °	38.828975 °	
			-121.724265 °	-121.724265 °	
DWR ID	DWR_RD1500_01_s_2012_16				
Action/Comments					
Equipment					

Photo 1 of 1 : FA_2015_RD1500_189_16_20150914_00013.jpg



Equipment along landside toe. Photo was taken in spring 2010.

LM Start	7.60	Rating **	M	Issue No.	17
LM End	7.60	Issue Type +	En	Location *	LS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Vegetation		38.830260 °	38.830260 °	
			-121.725357 °	-121.725357 °	
DWR ID	DWR_RD1500_01_s_2012_17				
Action/Comments					
Landscaping					

Photo 1 of 2 : FA_2015_RD1500_189_17_20150914_00014.jpg



Landscape shrubs, photo taken in spring 2010.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

Flood Control Project Maintenance
Levee Inspections

Levee Inspection Report By Mile - Fall 2015

Reclamation District No. 1500 Sutter Basin

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	33.15	10/20/2015 10/21/2015	Jai Lor

LM Start	7.72	Rating **	U	Issue No.	2562 (cont)
LM End	7.72	Issue Type +	En	Location *	LS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			38.831638 °	38.831638 °
				-121.726580 °	-121.726580 °
DWR ID					

Action/Comments

Inspector Comments: FS_ID:42935
DS_ID:20049
EP_NO: 8147
FS_HLM: 7.78
Repair Type: Urgent
Crossing Status: Found
UCIP Comments: Not found- slide gate in 48-inch corrugated metal riser at waterside toe.Repair works under way. Contact LMA for repair works information.Sign of leaky pipe and siphon breaker. This needs detailed investigation.
FIELD_STRUCT_DESC: 12-inch steel irrigation pipe through levee, 4.8 feet below crown. Slant pump mounted on steel structure at the edge of berm. A 4 X 4 foot concrete distribution box at landward toe. (App. No. 8147 - Driver)
FS Date: 01/10/2014

Photo 2 of 2 : UCIP_FA_2015_2932.jpg



WS view: slant pump on steel platform on end of berm.

LM Start	7.96	Rating **	M	Issue No.	2563
LM End	7.96	Issue Type +	En	Location *	LS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			38.834260 °	38.834260 °
				-121.729566 °	-121.729566 °
DWR ID					

Action/Comments

Inspector Comments: FS_ID:28323
DS_ID:20051
EP_NO: 13882
FS_HLM: 8.04
Repair Type: Non-Urgent
Crossing Status: Found
UCIP Comments: Power pole on landside. 2-inch conduit through the levee. Service box on waterside. Concrete pad on waterside. Not found- Concrete distribution box on landward side; not found- gate valve on waterside.Need proper abandonment.Pipe visible on river bank, waterside levee slope and landside field.
FIELD_STRUCT_DESC: Abandoned 6-inch diameter steel irrigation pipe and electric conduit through levee, 4.9 feet below crown. 1-1/2 conduit through levee, 4.0 feet below crown. Service pole at landward levee toe. (ABO. No. 10062-Moroni, App. No. 13882)
FS Date: 01/10/2014

Photo 1 of 3 : UCIP_FA_2015_3083.jpg



LS view: outlet steel pipe across the residential road off the levee toe on field.

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	Issue Type N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	--	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2015

Reclamation District No. 1500 Sutter Basin

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	33.15	10/20/2015 10/21/2015	Jai Lor

LM Start	7.96	Rating **	M	Issue No.	2563 (cont)
LM End	7.96	Issue Type +	En	Location *	LS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			38.834260 °	38.834260 °
				-121.729566 °	-121.729566 °
DWR ID					
Action/Comments					
Inspector Comments: FS_ID:28323 DS_ID:20051 EP_NO: 13882 FS_HLM: 8.04 Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: Power pole on landside. 2-inch conduit through the levee. Service box on waterside. Concrete pad on waterside. Not found- Concrete distribution box on landward side; not found- gate valve on waterside. Need proper abandonment. Pipe visible on river bank, waterside levee slope and landside field. FIELD_STRUCT_DESC: Abandoned 6-inch diameter steel irrigation pipe and electric conduit through levee, 4.9 feet below crown. 1-1/2 conduit through levee, 4.0 feet below crown. Service pole at landward levee toe. (ABO. No. 10062-Moroni, App. No. 13882) FS Date: 01/10/2014					

Photo 2 of 3 : UCIP_FA_2015_3084.jpg



WS view: abandoned steel pipe exposed on river bank.

LM Start	7.96	Rating **	M	Issue No.	2563 (cont)
LM End	7.96	Issue Type +	En	Location *	LS

Photo 3 of 3 : UCIP_FA_2015_3085.jpg



WS view: CMP with air vent (right), concrete pad (left), and switch panel (left) on levee slope.

* Location	** Rating	+ Issue Type
LS : Land Side WS : Water Side CR : Crown N/A : Not Applicable	A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2015

Reclamation District No. 1500 Sutter Basin

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	33.15	10/20/2015 10/21/2015	Jai Lor

LM Start	8.33	Rating **	M	Issue No.	3
LM End	8.47	Issue Type +	Ma	Location *	WS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	2015 USACE Erosion Survey, DRAFT			38.839546 °	38.840347 °
				-121.729591 °	-121.726857 °
DWR ID					
Action/Comments					
Inspector Comments: 1997 - Damage to cobble revetment on top left bank and toe damage. 2004 - Site is pretty minor. 2010 - Cobbles continue to deteriorate. 2011 - Minor new erosion at the toe. 2013 - Might be able to shorten due to deposition. 2015: Site shortened, downstream end has plenty of berm and deposited material, well vegetated. [2015 Site ID: SAC_92-8_L]					

Photo 1 of 1 : USACE2013A_SAC_92-8_L_2.jpg



USACE 2013 Photo #1

LM Start	8.35	Rating **	M	Issue No.	2564
LM End	8.35	Issue Type +	En	Location *	WS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			38.839446 °	38.839446 °
				-121.728901 °	-121.728901 °
DWR ID					
Action/Comments					
Inspector Comments: FS_ID:28324 DS_ID:20053 EP_NO: 10064 FS_HLM: 8.421 Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: Looks abandoned as service pole not found. May need proper abandonment. FIELD_STRUCT_DESC: 2 foot by 2 foot concrete box culvert through levee, 13.0 feet below crown. Pump on 6 foot diameter concrete pump well on berm. Slide gate in 42-inch CM riser on waterward slope. 4.5 foot by 6 foot concrete distribution box at landward toe. (ABO No. 10064 - Nix) FS Date: 01/10/2014					

Photo 1 of 3 : UCIP_FA_2015_3086.jpg



LS view: concrete distribution box on levee toe.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable N : Not Inspected/Rated M : Minimally Acceptable C : Corrected U : Unacceptable A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
---	--	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2015

Reclamation District No. 1500 Sutter Basin

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	33.15	10/20/2015 10/21/2015	Jai Lor

LM Start	8.35	Rating **	M	Issue No.	2564 (cont)
LM End	8.35	Issue Type +	En	Location *	WS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			38.839446 °	38.839446 °
				-121.728901 °	-121.728901 °
DWR ID					
Action/Comments					
Inspector Comments: FS_ID:28324 DS_ID:20053 EP_NO: 10064 FS_HLM: 8.421 Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: Looks abandoned as service pole not found. May need proper abandonment. FIELD_STRUCT_DESC: 2 foot by 2 foot concrete box culvert through levee, 13.0 feet below crown. Pump on 6 foot diameter concrete pump well on berm. Slide gate in 42-inch CM riser on waterward slope. 4.5 foot by 6 foot concrete distribution box at landward toe. (ABO No. 10064 - Nix) FS Date: 01/10/2014					

Photo 2 of 3 : UCIP_FA_2015_3087.jpg



WS view: vertical pump on concrete sump on levee berm. Looks abandoned.

LM Start	8.35	Rating **	M	Issue No.	2564 (cont)
LM End	8.35	Issue Type +	En	Location *	WS

Photo 3 of 3 : UCIP_FA_2015_3088.jpg



WS view: slide gate in CMP riser on levee slope. Looks abandoned.

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	--	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2015

Reclamation District No. 1500 Sutter Basin

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	33.15	10/20/2015 10/21/2015	Jai Lor

LM Start	8.67	Rating **	M	Issue No.	2565
LM End	8.67	Issue Type +	En	Location *	WS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			38.842218 °	38.842218 °
				-121.725728 °	-121.725728 °
DWR ID					
Action/Comments					
Inspector Comments: FS_ID:28343 DS_ID:20054 EP_NO: 5518 FS_HLM: 8.743 Repair Type: Non-Urgent Crossing Status: Found					

Photo 1 of 3 : UCIP_FA_2015_3089.jpg



LS view: concrete distribution box on landside toe.

LM Start	8.67	Rating **	M	Issue No.	2565 (cont)
LM End	8.67	Issue Type +	En	Location *	WS

Photo 2 of 3 : UCIP_FA_2015_3259.jpg



WS view: pipe, pump (removed and capped with plywood), and gate valve on river bank.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2015

Reclamation District No. 1500 Sutter Basin

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	33.15	10/20/2015 10/21/2015	Jai Lor

LM Start	8.67	Rating **	M	Issue No.	2565 (cont)
LM End	8.67	Issue Type +	En	Location *	WS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			38.842218 °	38.842218 °
				-121.725728 °	-121.725728 °
DWR ID					
Action/Comments					
Inspector Comments: FS_ID:28343 DS_ID:20054 EP_NO: 5518 FS_HLM: 8.743 Repair Type: Non-Urgent Crossing Status: Found					

Photo 3 of 3 : UCIP_FA_2015_3260.jpg



WS view: U type concrete headwall, pipe, and pump on river bank.

LM Start	8.72	Rating **	M	Issue No.	18
LM End	8.72	Issue Type +	En	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			38.842673 °	38.842673 °
				-121.726442 °	-121.726442 °
DWR ID	DWR_RD1500_01_s_2012_18				
Action/Comments					
Building					

Photo 1 of 1 : FA_2015_RD1500_189_18_20150914_00016.jpg



The corner of the building has encroached into the toe.

LM Start	8.79	Rating **	M	Issue No.	109
LM End	8.79	Issue Type +	En	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			38.843481 °	38.843481 °
				-121.727256 °	-121.727256 °
DWR ID	DWR_RD1500_01_f_2015_109				
Action/Comments					
Debris Inspector Comments: Abandoned pipe is embedded into levee slope.					

Photo 1 of 1 : FA_2015_RD1500_189_109_20151026_00144.jpg



View of the abandoned pipe on the landward side of the levee looking upstream. Fall 2015.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
---	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2015

Reclamation District No. 1500 Sutter Basin

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	33.15	10/20/2015 10/21/2015	Jai Lor

LM Start	8.92	Rating **	A/W	Issue No.	1344
LM End	8.92	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.845076 °	38.845076 °
				-121.728301 °	-121.728301 °
DWR ID	DWR_RD1500_01_s_2014_1344				
Action/Comments					
Trees / Woody Vegetation					

Photo 1 of 3 : FA_2015_RD1500_189_1344_20150914_00080.jpg



The walnut tree at the toe has fallen. The roots are exposed and the branches are holding it up. Spring 2014

LM Start	8.92	Rating **	A/W	Issue No.	1344 (cont)
LM End	8.92	Issue Type +	Ma	Location *	LS

Photo 2 of 3 : FA_2015_RD1500_189_1344_20151026_00145.jpg



The walnut tree has been trimmed but still remains at the landward toe of the levee. Fall 2015.

LM Start	8.92	Rating **	A/W	Issue No.	1344 (cont)
LM End	8.92	Issue Type +	Ma	Location *	LS

Photo 3 of 3 : FA_2015_RD1500_189_1344_20151026_00146.jpg



Perspective view of the walnut tree on the landward side of the levee looking downstream. Fall 2015.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2015

Reclamation District No. 1500 Sutter Basin

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	33.15	10/20/2015 10/21/2015	Jai Lor

LM Start	8.95	Rating **	M	Issue No.	2566
LM End	8.95	Issue Type +	En	Location *	LS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			38.845578 °	38.845578 °
				-121.728406 °	-121.728406 °
DWR ID					
Action/Comments					
Inspector Comments: FS_ID:28363 DS_ID:20055 EP_NO: 8503 FS_HLM: 9.03 Repair Type: Non-Urgent Crossing Status: Found					

Photo 1 of 3 : UCIP_FA_2015_3261.jpg



LS view: pipe end capped with steel plate on levee toe. Looks abandoned.

LM Start	8.95	Rating **	M	Issue No.	2566 (cont)
LM End	8.95	Issue Type +	En	Location *	LS

Photo 2 of 3 : UCIP_FA_2015_3262.jpg



WS view: inlet steel pipe with gate valve on river bank.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2015

Reclamation District No. 1500 Sutter Basin

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	33.15	10/20/2015 10/21/2015	Jai Lor

LM Start	8.95	Rating **	M	Issue No.	2566 (cont)
LM End	8.95	Issue Type +	En	Location *	LS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			38.845578 °	38.845578 °
				-121.728406 °	-121.728406 °
DWR ID					
Action/Comments					
Inspector Comments: FS_ID:28363 DS_ID:20055 EP_NO: 8503 FS_HLM: 9.03 Repair Type: Non-Urgent Crossing Status: Found					

Photo 3 of 3 : UCIP_FA_2015_3263.jpg



WS view: siphon breaker in CMP riser on levee slope.

LM Start	9.13	Rating **	M	Issue No.	2567
LM End	9.13	Issue Type +	En	Location *	LS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			38.847841 °	38.847841 °
				-121.727172 °	-121.727172 °
DWR ID					
Action/Comments					
Inspector Comments: FS_ID:28364 DS_ID:20056 EP_NO: 5598 FS_HLM: 9.2 Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: Not found- Wood headwall 18 ft from landward toe. Not found- Flap gate on landward side.No outlet structure found. Only a capped pipe found, but not sure whether it is connected to the crossing. FIELD_STRUCT_DESC: 12-inch steel irrigation pipe through levee, 4.8 feet below crown. Electrical conduit through levee, 4.8 feet below crown. Slant pump on steel structure. Siphon breaker in landward shoulder. Service pole on landside toe. Discharges into field. Installed 1967. (App. No. 5598 & 8505 - James) FS Date: 01/10/2014					

Photo 1 of 3 : UCIP_FA_2015_1220.jpg



WS view: slant pump on steel platform on levee berm. Excessive oil leak from the pump.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2015

Reclamation District No. 1500 Sutter Basin

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	33.15	10/20/2015 10/21/2015	Jai Lor

LM Start	9.13	Rating **	M	Issue No.	2567 (cont)
LM End	9.13	Issue Type +	En	Location *	LS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			38.847841 °	38.847841 °
				-121.727172 °	-121.727172 °
DWR ID					
Action/Comments					
Inspector Comments: FS_ID:28364 DS_ID:20056 EP_NO: 5598 FS_HLM: 9.2 Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: Not found- Wood headwall 18 ft from landward toe. Not found- Flap gate on landward side.No outlet structure found. Only a capped pipe found, but not sure whether it is connected to the crossing. FIELD_STRUCT_DESC: 12-inch steel irrigation pipe through levee, 4.8 feet below crown. Electrical conduit through levee, 4.8 feet below crown. Slant pump on steel structure. Siphon breaker in landward shoulder. Service pole on landside toe. Discharges into field. Installed 1967. (App. No. 5598 & 8505 - James) FS Date: 01/10/2014					

Photo 2 of 3 : UCIP_FA_2015_1221.jpg



LS view: air vent in steel pipe riser on levee slope.

Photo 3 of 3 : UCIP_FA_2015_3264.jpg



LS view: capped outlet pipe on levee toe.

LM Start	9.13	Rating **	M	Issue No.	2567 (cont)
LM End	9.13	Issue Type +	En	Location *	LS

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable N : Not Inspected/Rated M : Minimally Acceptable C : Corrected U : Unacceptable A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
---	--	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2015

Reclamation District No. 1500 Sutter Basin

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	33.15	10/20/2015 10/21/2015	Jai Lor

LM Start	9.28	Rating **	M	Issue No.	111
LM End	9.28	Issue Type +	En	Location *	WS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Encroachments		38.849171 °	38.849171 °	
			-121.724840 °	-121.724840 °	
DWR ID	DWR_RD1500_01_f_2015_111				
Action/Comments					
Debris					

Photo 1 of 1 : FA_2015_RD1500_189_111_20151026_00147.jpg



The couch is on the berm of the waterward side of the levee. Fall 2015.

LM Start	9.40	Rating **	A/W	Issue No.	74
LM End	9.63	Issue Type +	Ma	Location *	WS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Vegetation		38.850267 °	38.853222 °	
			-121.723275 °	-121.724062 °	
DWR ID	DWR_RD1500_01_s_2012_74				
Action/Comments					
Environmental Requirements.					

Photo 1 of 2 : FA_2015_RD1500_189_74_20150914_00051.jpg



A revegetation site on the waterside bank with sprinklers installed.

LM Start	9.40	Rating **	A/W	Issue No.	74 (cont)
LM End	9.63	Issue Type +	Ma	Location *	WS

Photo 2 of 2 : FA_2015_RD1500_189_74_20150914_00052.jpg



Another revegetation site photo taken spring 2012.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	--	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2015

Reclamation District No. 1500 Sutter Basin

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	33.15	10/20/2015 10/21/2015	Jai Lor

LM Start	9.66	Rating **	M	Issue No.	2568
LM End	9.66	Issue Type +	En	Location *	WS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			38.853364 °	38.853364 °
				-121.724617 °	-121.724617 °
DWR ID					
Action/Comments					
Inspector Comments: FS_ID:28365 DS_ID:20057 EP_NO: N/A FS_HLM: 9.74 Repair Type: Non-Urgent Crossing Status: Found					

Photo 1 of 3 : UCIP_FA_2015_1222.jpg



LS view: U type concrete headwall, pipe, gate valve, and pump (removed and plugged with plywood) on river bank.

LM Start	9.66	Rating **	M	Issue No.	2568 (cont)
LM End	9.66	Issue Type +	En	Location *	WS

Photo 2 of 3 : UCIP_FA_2015_1223.jpg



WS view: siphon breaker obstructed by dumped-trash in CMP riser.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2015

Reclamation District No. 1500 Sutter Basin

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	33.15	10/20/2015 10/21/2015	Jai Lor

LM Start	9.66	Rating **	M	Issue No.	2568 (cont)
LM End	9.66	Issue Type +	En	Location *	WS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			38.853364 °	38.853364 °
				-121.724617 °	-121.724617 °
DWR ID					
Action/Comments					
Inspector Comments: FS_ID:28365 DS_ID:20057 EP_NO: N/A FS_HLM: 9.74 Repair Type: Non-Urgent Crossing Status: Found					

Photo 3 of 3 : UCIP_FA_2015_1224.jpg



WS view: CMP riser with siphon breaker on levee slope.

LM Start	10.12	Rating **	M	Issue No.	2569
LM End	10.12	Issue Type +	En	Location *	WS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			38.857853 °	38.857853 °
				-121.728222 °	-121.728222 °
DWR ID					
Action/Comments					
Inspector Comments: FS_ID:28366 DS_ID:20058 EP_NO: 10068 FS_HLM: 10.205 Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: Surface erosion along pipe alignment on landside. 30-inch concrete pipe in CMP riser on waterside. 30-inch x 24-inch concrete culvert on landside. FIELD_STRUCT_DESC: A 2 foot by 2.5 foot concrete box culvert through levee, 13.0 feet below crown. A pump on river bank, power pole and switch panel on waterside berm. Concrete surge box with slide gate on waterside berm. Concrete distribution box at landward toe. (ABO. No. 10068-Reel) O&M Manual Sac 128, March 1960. FS Date: 01/10/2014					

Photo 1 of 3 : UCIP_FA_2015_1225.jpg



WS view: pipe and pump with appurtenances on river bank. Pump removed and plugged with plywood.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable N : Not Inspected/Rated M : Minimally Acceptable C : Corrected U : Unacceptable A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
---	--	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2015

Reclamation District No. 1500 Sutter Basin

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	33.15	10/20/2015 10/21/2015	Jai Lor

LM Start	10.12	Rating **	M	Issue No.	2569 (cont)
LM End	10.12	Issue Type +	En	Location *	WS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			38.857853 °	38.857853 °
				-121.728222 °	-121.728222 °
DWR ID					
Action/Comments					
Inspector Comments: FS_ID:28366 DS_ID:20058 EP_NO: 10068 FS_HLM: 10.205 Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: Surface erosion along pipe alignment on landside. 30-inch concrete pipe in CMP riser on waterside. 30-inch x 24-inch concrete culvert on landside. FIELD_STRUCT_DESC: A 2 foot by 2.5 foot concrete box culvert through levee, 13.0 feet below crown. A pump on river bank, power pole and switch panel on waterside berm. Concrete surge box with slide gate on waterside berm. Concrete distribution box at landward toe. (ABO. No. 10068-Reel) O&M Manual Sac 128, March 1960. FS Date: 01/10/2014					

Photo 2 of 3 : UCIP_FA_2015_3334.jpg



LS view: surface erosion along pipe alignment on landside.

LM Start	10.12	Rating **	M	Issue No.	2569 (cont)
LM End	10.12	Issue Type +	En	Location *	WS

Photo 3 of 3 : UCIP_FA_2015_3335.jpg



WS view: service pole and concrete surge box with slide gate on berm.

* Location	** Rating	+ Issue Type
LS : Land Side WS : Water Side CR : Crown	A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain
N/A : Not Applicable		Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2015

Reclamation District No. 1500 Sutter Basin

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	33.15	10/20/2015 10/21/2015	Jai Lor

LM Start	10.54	Rating **	M	Issue No.	112
LM End	10.54	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			38.861027 °	38.861027 °
				-121.734094 °	-121.734094 °
DWR ID	DWR_RD1500_01_f_2015_112				
Action/Comments					
Trim trees to at least five feet above ground level.					

Photo 1 of 1 : FA_2015_RD1500_189_112_20151026_00148.jpg



View of the trees on the landward side of the levee looking upstream. Fall 2015.

LM Start	10.70	Rating **	M	Issue No.	2570
LM End	10.70	Issue Type +	En	Location *	LS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			38.861550 °	38.861550 °
				-121.737006 °	-121.737006 °
DWR ID					
Action/Comments					
Inspector Comments: FS_ID:28925 DS_ID:20059 EP_NO: N/A FS_HLM: 10.79 Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: Pump removed. Obstructed siphon breaker in CMP riser on landside. FIELD_STRUCT_DESC: A 12-inch diameter steel irrigation pipe through levee, 4.3 feet below crown. A 1-1/2 conduit through levee. 2.0 feet below crown. Pump on river bank, siphon breaker on landside shoulder. A 8x6 ft. concrete distribution box and service pole at landside toe. O&M Manual Sac 128, March 1960. FS Date: 01/10/2014					

Photo 1 of 3 : UCIP_FA_2015_2933.jpg



LS view: obstructed siphon breaker in CMP riser (bottom) on levee slope.

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	--	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2015

Reclamation District No. 1500 Sutter Basin

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	33.15	10/20/2015 10/21/2015	Jai Lor

LM Start	10.70	Rating **	M	Issue No.	2570 (cont)
LM End	10.70	Issue Type +	En	Location *	LS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			38.861550 °	38.861550 °
				-121.737006 °	-121.737006 °
DWR ID					
Action/Comments					
Inspector Comments: FS_ID:28925 DS_ID:20059 EP_NO: N/A FS_HLM: 10.79 Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: Pump removed. Obstructed siphon breaker in CMP riser on landside. FIELD_STRUCT_DESC: A 12-inch diameter steel irrigation pipe through levee, 4.3 feet below crown. A 1-1/2 conduit through levee. 2.0 feet below crown. Pump on river bank, siphon breaker on landside shoulder. A 8x6 ft. concrete distribution box and service pole at landside toe. O&M Manual Sac 128, March 1960. FS Date: 01/10/2014					

Photo 2 of 3 : UCIP_FA_2015_2934.jpg



LS view: siphon breaker in CMP riser (bottom) on levee slope and concrete distribution box (top) on levee toe.

LM Start	10.70	Rating **	M	Issue No.	2570 (cont)
LM End	10.70	Issue Type +	En	Location *	LS

Photo 3 of 3 : UCIP_FA_2015_2935.jpg



WS view: pipe, pump (removed and plugged with plywood), headwall, and appurtenances on river bank.

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	--	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2015

Reclamation District No. 1500 Sutter Basin

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	33.15	10/20/2015 10/21/2015	Jai Lor

LM Start	11.23	Rating **	M	Issue No.	113
LM End	11.23	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Erosion / Bank Caving			38.865598 °	38.865598 °
				-121.745196 °	-121.745196 °
DWR ID	DWR_RD1500_01_f_2015_113				
Action/Comments					
Schedule repair of erosion site prior to the next inspection.					

Photo 1 of 1 : FA_2015_RD1500_189_113_20151026_00149.jpg



View of the erosion on the landward side of the levee looking upstream. Fall 2015.

LM Start	11.23	Rating **	C	Issue No.	2548
LM End	11.23	Issue Type +	En	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			38.865649 °	38.865649 °
				-121.745255 °	-121.745255 °
DWR ID	DWR_RD1500_01_s_2015_2548				
Action/Comments					
Pipe Inspector Comments: Owner is applying for a permit for an existing pipe. This issue was given an NOV on April 15, 2015.					

No Photos

LM Start	11.24	Rating **	U	Issue No.	2571
LM End	11.24	Issue Type +	En	Location *	WS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			38.865649 °	38.865649 °
				-121.745279 °	-121.745279 °
DWR ID					
Action/Comments					
Inspector Comments: FS_ID:44406 DS_ID:20060 EP_NO: N/A FS_HLM: 11.34 Repair Type: Urgent Crossing Status: Found					

Photo 1 of 3 : UCIP_FA_2015_3336.jpg



LS view: siphon breaker in CMP riser on levee slope and concrete distribution box on levee toe (top0).

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	--	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2015

Reclamation District No. 1500 Sutter Basin

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	33.15	10/20/2015 10/21/2015	Jai Lor

LM Start	11.24	Rating **	U	Issue No.	2571 (cont)
LM End	11.24	Issue Type +	En	Location *	WS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			38.865649 °	38.865649 °
				-121.745279 °	-121.745279 °
DWR ID					
Action/Comments					
Inspector Comments: FS_ID:44406 DS_ID:20060 EP_NO: N/A FS_HLM: 11.34 Repair Type: Urgent Crossing Status: Found UCIP Comments: Pump removed.10-inch pipe joined to 14-inch pipe.Wet, some vegetations, and subsidence along pipe alignment on landside. This needs detailed investigation. FIELD_STRUCT_DESC: 14-inch diameter steel irrigation pipe through levee. 4.7 feet below crown. Pump and gate valve on concrete platform on bank. Switch control house and service pole on shoulder. Siphon breaker on landside slope. Concrete distribution box on landward side. O&M Manual Sac 128, March 1960, ABO No. 10068. FS Date: 01/10/2014					

Photo 2 of 3 : UCIP_FA_2015_3337.jpg



LS view: wet, some vegetations, and subsidence along pipe alignment on landside.

LM Start	11.24	Rating **	U	Issue No.	2571 (cont)
LM End	11.24	Issue Type +	En	Location *	WS

Photo 3 of 3 : UCIP_FA_2015_3338.jpg



WS view: pipe, pump (removed and plugged with plywood plate), and appurtenances on river bank.

* Location	** Rating	+ Issue Type
LS : Land Side WS : Water Side CR : Crown	A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain
N/A : Not Applicable		Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2015

Reclamation District No. 1500 Sutter Basin

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	33.15	10/20/2015 10/21/2015	Jai Lor

LM Start	11.33	Rating **	M	Issue No.	20
LM End	11.33	Issue Type +	En	Location *	LS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Vegetation		38.866762 °	38.866762 °	
			-121.746125 °	-121.746125 °	
DWR ID	DWR_RD1500_01_s_2012_20				
Action/Comments					
Landscaping					

Photo 1 of 1 : FA_2015_RD1500_189_20_20151026_00150.jpg



View of the landscaping on the landward side of the levee looking upstream. Fall 2015.

LM Start	11.45	Rating **	U	Issue No.	2572
LM End	11.45	Issue Type +	En	Location *	LS
Category	Supplemental		GPS Latitude/Longitude		
			Start	End	
Item	DWR UCIP Field Study		38.868544 °	38.868544 °	
			-121.746471 °	-121.746471 °	
DWR ID					
Action/Comments					
Inspector Comments: FS_ID:43085 DS_ID:20061 EP_NO: 10041 FS_HLM: 11.56 Repair Type: Urgent Crossing Status: Found UCIP Comments: Depressions on both sides of the levee slope. It needs more investigation. Pump removed. FIELD_STRUCT_DESC: 8-inch steel irrigation pipe through levee, 4.0 feet below crown. Pump and gate valve on concrete pump platform on bank. Corrugated metal switch house on waterside. Service pole on waterside shoulder. 8 foot by 6 foot I.D. concrete distribution box on landside. Overhead power line. Pole at landward toe. (ABO No. 10041 - Duffy) O&M Manual Sac 128, March 1960. FS Date: 01/10/2014					

Photo 1 of 3 : UCIP_FA_2015_0608.jpg



LS view: concrete distribution box on levee toe. Exposed pipe and depression (top) visible on levee slope.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable N : Not Inspected/Rated M : Minimally Acceptable C : Corrected U : Unacceptable A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
---	--	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2015

Reclamation District No. 1500 Sutter Basin

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	33.15	10/20/2015 10/21/2015	Jai Lor

LM Start	11.45	Rating **	U	Issue No.	2572 (cont)
LM End	11.45	Issue Type +	En	Location *	LS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			38.868544 °	38.868544 °
				-121.746471 °	-121.746471 °
DWR ID					

Action/Comments
 Inspector Comments: FS_ID:43085
 DS_ID:20061
 EP_NO: 10041
 FS_HLM: 11.56
 Repair Type: Urgent
 Crossing Status: Found
 UCIP Comments: Depressions on both sides of the levee slope. It needs more investigation. Pump removed.
 FIELD_STRUCT_DESC: 8-inch steel irrigation pipe through levee, 4.0 feet below crown. Pump and gate valve on concrete pump platform on bank. Corrugated metal switch house on waterside. Service pole on waterside shoulder. 8 foot by 6 foot I.D. concrete distribution box on landside. Overhead power line. Pole at landward toe. (ABO No. 10041 - Duffy) O&M Manual Sac 128, March 1960.
 FS Date: 01/10/2014

Photo 2 of 3 : UCIP_FA_2015_2915.jpg



LS view: depressions along the pipe alignment on levee slope. It needs detailed investigation.

LM Start	11.45	Rating **	U	Issue No.	2572 (cont)
LM End	11.45	Issue Type +	En	Location *	LS

Photo 3 of 3 : UCIP_FA_2015_2916.jpg



WS view: pipe, pump (removed), headwall, and appurtenances on river bank.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	--	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2015

Reclamation District No. 1500 Sutter Basin

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	33.15	10/20/2015 10/21/2015	Jai Lor

LM Start	11.45	Rating **	M	Issue No.	114
LM End	11.45	Issue Type +	En	Location *	LS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Encroachments		38.868577 °	38.868577 °	
			-121.746487 °	-121.746487 °	
DWR ID	DWR_RD1500_01_f_2015_114				
Action/Comments					
Stairway Inspector Comments: There is erosion at the toe of the levee where the concrete box is located.					

Photo 1 of 3 : FA_2015_RD1500_189_114_20151026_00155.jpg



Perspective view of the concrete box on the landward side of the levee looking upstream. Fall 2015.

LM Start	11.45	Rating **	M	Issue No.	114 (cont)
LM End	11.45	Issue Type +	En	Location *	LS

Photo 2 of 3 : FA_2015_RD1500_189_114_20151026_00152.jpg



There is erosion at the levee toe around the concrete box. There are also stairs leading down the slope. Fall 2015.

LM Start	11.45	Rating **	M	Issue No.	114 (cont)
LM End	11.45	Issue Type +	En	Location *	LS

Photo 3 of 3 : FA_2015_RD1500_189_114_20151026_00156.jpg



There is slight erosion on the waterward side of the levee where the pipe seems to run through the levee. Fall 2015.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2015

Reclamation District No. 1500 Sutter Basin

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	33.15	10/20/2015 10/21/2015	Jai Lor

LM Start	11.80	Rating **	M	Issue No.	19
LM End	11.98	Issue Type +	Ma	Location *	WS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	2015 USACE Erosion Survey, DRAFT			38.871853 °	38.870581 °
				-121.749330 °	-121.752059 °
DWR ID					
Action/Comments					
Inspector Comments: 1997 - No toe on the large upstream rubble (mix of broken concrete, bricks, rock, and steal) - should be replaced. Oversized bank. 2001 - New slump at the downstream end. 2003 - Some minor bank retreat at the downstream end. 2004 - Some new retreat at the downstream end. 2006 - Some new erosion, mainly on the steep slope and scarps. (Pumping station is not part of the erosion					

No Photos

LM Start	11.82	Rating **	A/W	Issue No.	115
LM End	11.82	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Erosion / Bank Caving			38.872124 °	38.872124 °
				-121.749720 °	-121.749720 °
DWR ID	DWR_RD1500_01_f_2015_115				
Action/Comments					
Note and monitor erosion site. Inspector Comments: Erosion site is on the edge of the river.					

Photo 1 of 2 : FA_2015_RD1500_189_115_20151026_00157.jpg



View of the erosion at the edge of the waterward berm looking upstream. Fall 2015.

LM Start	11.82	Rating **	A/W	Issue No.	115 (cont)
LM End	11.82	Issue Type +	Ma	Location *	WS

Photo 2 of 2 : FA_2015_RD1500_189_115_20151026_00158.jpg



View of the erosion at the edge of the river looking downstream. Fall 2015.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable N : Not Inspected/Rated M : Minimally Acceptable C : Corrected U : Unacceptable A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
---	--	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2015

Reclamation District No. 1500 Sutter Basin

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	33.15	10/20/2015 10/21/2015	Jai Lor

LM Start	11.82	Rating **	C	Issue No.	219
LM End	11.82	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			38.872220 °	38.872220 °
				-121.749785 °	-121.749785 °
DWR ID	DWR_RD1500_01_s_2012_219				
Action/Comments					
Debris					

No Photos

LM Start	11.93	Rating **	C	Issue No.	1346
LM End	11.93	Issue Type +	En	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			38.871375 °	38.871375 °
				-121.751541 °	-121.751541 °
DWR ID	DWR_RD1500_01_s_2014_1346				
Action/Comments					
Debris					

No Photos

LM Start	11.99	Rating **	A/W	Issue No.	1
LM End	12.26	Issue Type +	Ma	Location *	WS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	2015 USACE Erosion Survey, DRAFT			38.870474 °	38.869139 °
				-121.752237 °	-121.757108 °
DWR ID					
Action/Comments					
Inspector Comments: 2000 - Vertical Modesto Formation bank with mass failure. 2003 - Upstream end has some new bank retreat. 2004 - Upstream end is worse. 2006 - Some new erosion, mainly on the steep slope and scarps. (Pumping station is not part of the erosion site.) 2010 - Some new erosion and deposition at upstream end, definite encroachments. 2011 - Minor new erosion at the toe. 2015: Site removed, sufficient berm width. [2015 Site ID: SAC_96-2_L]					

Photo 1 of 1 : USACE2013A_SAC_96-2_L_11.jpg



USACE 2013 Photo #1

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable N : Not Inspected/Rated M : Minimally Acceptable C : Corrected U : Unacceptable A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
---	--	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2015

Reclamation District No. 1500 Sutter Basin

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	33.15	10/20/2015 10/21/2015	Jai Lor

LM Start	11.99	Rating **	M	Issue No.	116
LM End	11.99	Issue Type +	En	Location *	WS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Encroachments		38.870840 °	38.870840 °	
			-121.752594 °	-121.752594 °	
DWR ID	DWR_RD1500_01_f_2015_116				
Action/Comments					
Garbage					


Photo 1 of 1 : FA_2015_RD1500_189_116_20151026_00159.jpg



View of the debris on the waterward side of the levee. Fall 2015.

LM Start	12.00	Rating **	M	Issue No.	2573
LM End	12.00	Issue Type +	En	Location *	WS
Category	Supplemental		GPS Latitude/Longitude		
			Start	End	
Item	DWR UCIP Field Study		38.870780 °	38.870780 °	
			-121.752630 °	-121.752630 °	
DWR ID					
Action/Comments					
Inspector Comments: FS_ID:41744 DS_ID:20008 EP_NO: N/A FS_HLM: 12.115 Repair Type: Non-Urgent Crossing Status: Indicator Found UCIP Comments: An abandoned pump house on waterside and a 72-inch corrugated metal pipe on landside. The pipe discharges into irrigation ditch (canal). Water was flowing during the field visit. Needs to verify from LMA whether this pipe is through the levee or not. FIELD_STRUCT_DESC: 1 of 2: Two 4 foot and 3.5 foot concrete culverts through levee, 17 feet below the crown, pump on WS. FS Date: 01/10/2014					

Photo 1 of 3 : UCIP_FA_2015_3224.jpg



Sketch of Utility Crossing @HLM 12.115

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable N : Not Inspected/Rated M : Minimally Acceptable C : Corrected U : Unacceptable A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
---	--	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2015

Reclamation District No. 1500 Sutter Basin

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	33.15	10/20/2015 10/21/2015	Jai Lor

LM Start	12.00	Rating **	M	Issue No.	2573 (cont)
LM End	12.00	Issue Type +	En	Location *	WS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			38.870780 °	38.870780 °
				-121.752630 °	-121.752630 °
DWR ID					

Action/Comments

Inspector Comments: FS_ID:41744
 DS_ID:20008
 EP_NO: N/A
 FS_HLM: 12.115
 Repair Type: Non-Urgent
 Crossing Status: Indicator Found
 UCIP Comments: An abandoned pump house on waterside and a 72-inch corrugated metal pipe on landside. The pipe discharges into irrigation ditch (canal). Water was flowing during the field visit. Needs to verify from LMA whether this pipe is through the levee or not.
 FIELD_STRUCT_DESC: 1 of 2: Two 4 foot and 3.5 foot concrete culverts through levee, 17 feet below the crown, pump on WS.
 FS Date: 01/10/2014

LM Start	12.00	Rating **	M	Issue No.	2573 (cont)
LM End	12.00	Issue Type +	En	Location *	WS

Photo 2 of 3 : UCIP_FA_2015_3225.jpg



LS view: overview of irrigation ditch on toe of levee.

Photo 3 of 3 : UCIP_FA_2015_3226.jpg



WS view: abandoned concrete pump house. No pump and pipe found.

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	--	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2015

Reclamation District No. 1500 Sutter Basin

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	33.15	10/20/2015 10/21/2015	Jai Lor

LM Start	12.19	Rating **	A/W	Issue No.	50
LM End	12.19	Issue Type +	Ma	Location *	WS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Erosion / Bank Caving		38.869700 °	38.869700 °	
			-121.755945 °	-121.755945 °	
DWR ID	DWR_RD1500_01_s_2012_50				
Action/Comments					
Note and monitor erosion site. Inspector Comments: The levee has a wide berm at this location.					

Photo 1 of 2 : FA_2015_RD1500_189_50_20151026_00161.jpg



LM Start	12.19	Rating **	A/W	Issue No.	50 (cont)
LM End	12.19	Issue Type +	Ma	Location *	WS

Photo 2 of 2 : FA_2015_RD1500_189_50_20151026_00160.jpg



View of the erosion site along the embankment looking downstream. Fall 2015.

LM Start	12.43	Rating **	M	Issue No.	24
LM End	12.53	Issue Type +	Ma	Location *	LS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Encroachments		38.868717 °	38.867492 °	
			-121.760133 °	-121.760903 °	
DWR ID	DWR_RD1500_01_s_2012_24				
Action/Comments					
Equipment					

Photo 1 of 1 : FA_2015_RD1500_189_24_20151026_00162.jpg



View of the equipment on the landward side of the levee looking upstream. Fall 2015.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable N : Not Inspected/Rated M : Minimally Acceptable C : Corrected U : Unacceptable A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
---	--	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2015

Reclamation District No. 1500 Sutter Basin

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	33.15	10/20/2015 10/21/2015	Jai Lor

LM Start	12.50	Rating **	M	Issue No.	117
LM End	12.50	Issue Type +	Ma	Location *	WS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Animal Control		38.867902 °	38.867902 °	
			-121.760631 °	-121.760631 °	
DWR ID	DWR_RD1500_01_f_2015_117				
Action/Comments					
No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.					

Photo 1 of 1 : FA_2015_RD1500_189_117_20151026_00163.jpg



View of the rodent hole on the waterward side of the levee looking upstream. Fall 2015.

LM Start	12.55	Rating **	M	Issue No.	2574
LM End	12.55	Issue Type +	En	Location *	WS
Category	Supplemental		GPS Latitude/Longitude		
			Start	End	
Item	DWR UCIP Field Study		38.867254 °	38.867254 °	
			-121.761212 °	-121.761212 °	
DWR ID					
Action/Comments					
Inspector Comments: FS_ID:28463 DS_ID:20063 EP_NO: N/A FS_HLM: 12.677 Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: Needs proper abandonment. FIELD_STRUCT_DESC: Abandoned 18-inch Corrugated Metal drainpipe through levee, 15.0 feet below crown. Slide gate in 4 foot by 4 foot concrete box at waterward toe. Concrete box at landward toe. Pipe across overflow area to river. O&M Manual Sac 128, March 1960. FS Date: 01/10/2014					

Photo 1 of 3 : UCIP_FA_2015_3027.jpg



LS view: silted CMP in concrete intake box on levee toe.

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2015

Reclamation District No. 1500 Sutter Basin

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	33.15	10/20/2015 10/21/2015	Jai Lor

LM Start	12.55	Rating **	M	Issue No.	2574 (cont)
LM End	12.55	Issue Type +	En	Location *	WS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			38.867254 °	38.867254 °
				-121.761212 °	-121.761212 °
DWR ID					
Action/Comments					
Inspector Comments: FS_ID:28463 DS_ID:20063 EP_NO: N/A FS_HLM: 12.677 Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: Needs proper abandonment. FIELD_STRUCT_DESC: Abandoned 18-inch Corrugated Metal drainpipe through levee, 15.0 feet below crown. Slide gate in 4 foot by 4 foot concrete box at waterward toe. Concrete box at landward toe. Pipe across overflow area to river. O&M Manual Sac 128, March 1960. FS Date: 01/10/2014					

Photo 2 of 3 : UCIP_FA_2015_3028.jpg



LS view: concrete intake box on levee toe.

Photo 3 of 3 : UCIP_FA_2015_3029.jpg



WS view: slide gate (left) in concrete box at levee toe. Slide gate and the box mostly buried.

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	--	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2015

Reclamation District No. 1500 Sutter Basin

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	33.15	10/20/2015 10/21/2015	Jai Lor

LM Start	12.57	Rating **	M	Issue No.	118
LM End	12.57	Issue Type +	Ma	Location *	WS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Erosion / Bank Caving		38.867108 °	38.867108 °	
			-121.761498 °	-121.761498 °	
DWR ID	DWR_RD1500_01_f_2015_118				
Action/Comments					
Schedule repair of erosion site prior to the next inspection.					

Photo 1 of 1 : FA_2015_RD1500_189_118_20151026_00164.jpg



View of the erosion on the waterward side of the levee looking upstream. Fall 2015.

LM Start	12.81	Rating **	A/W	Issue No.	25
LM End	12.81	Issue Type +	Ma	Location *	CR
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Encroachments		38.865127 °	38.865127 °	
			-121.765157 °	-121.765157 °	
DWR ID	DWR_RD1500_01_s_2012_25				
Action/Comments					
Equipment					

Photo 1 of 1 : FA_2015_RD1500_189_25_20151026_00165.jpg



View of the equipment on the crown of the levee looking upstream. Fall 2015.

LM Start	13.01	Rating **	M	Issue No.	26
LM End	13.01	Issue Type +	En	Location *	LS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Encroachments		38.863438 °	38.863438 °	
			-121.768212 °	-121.768212 °	
DWR ID	DWR_RD1500_01_s_2012_26				
Action/Comments					
Building					

Photo 1 of 1 : FA_2015_RD1500_189_26_20150914_00024.jpg



The building's backside was built into the toe of the levee.

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2015

Reclamation District No. 1500 Sutter Basin

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	33.15	10/20/2015 10/21/2015	Jai Lor

LM Start	13.05	Rating **	M	Issue No.	992
LM End	13.05	Issue Type +	Ma	Location *	LS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Encroachments		38.863081 °	38.863081 °	
			-121.768781 °	-121.768781 °	
DWR ID	DWR_RD1500_01_s_2012_992				
Action/Comments					
Equipment Inspector Comments: There are equipment and tires at this location.					

Photo 1 of 1 : FA_2015_RD1500_189_992_20150914_00074.jpg



Next to the building there are tires and axles stored at the toe.

LM Start	13.78	Rating **	M	Issue No.	119
LM End	13.78	Issue Type +	En	Location *	CR
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Encroachments		38.859715 °	38.859715 °	
			-121.780817 °	-121.780817 °	
DWR ID	DWR_RD1500_01_f_2015_119				
Action/Comments					
Equipment					

Photo 1 of 1 : FA_2015_RD1500_189_119_20151026_00166.jpg



View of the equipment on the crown of the levee looking upstream. Fall 2015.

LM Start	13.84	Rating **	M	Issue No.	120
LM End	13.84	Issue Type +	En	Location *	CR
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Encroachments		38.859005 °	38.859005 °	
			-121.781440 °	-121.781440 °	
DWR ID	DWR_RD1500_01_f_2015_120				
Action/Comments					
Building					

Photo 1 of 1 : FA_2015_RD1500_189_120_20151026_00167.jpg



View of the beehives on the crown of the levee looking upstream. Fall 2015.

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
N/A : Not Applicable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2015

Reclamation District No. 1500 Sutter Basin

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	33.15	10/20/2015 10/21/2015	Jai Lor

LM Start	13.96	Rating **	A/W	Issue No.	28
LM End	13.96	Issue Type +	Ma	Location *	WS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Encroachments		38.857625 °	38.857625 °	
			-121.782832 °	-121.782832 °	
DWR ID	DWR_RD1500_01_s_2012_28				
Action/Comments					
Equipment					

Photo 1 of 1 : FA_2015_RD1500_189_28_20151026_00168.jpg



View of the equipment on the waterward side of the levee looking upstream. Fall 2015.

LM Start	13.98	Rating **	M	Issue No.	10
LM End	14.26	Issue Type +	Ma	Location *	WS
Category	Supplemental		GPS Latitude/Longitude		
			Start	End	
Item	2015 USACE Erosion Survey, DRAFT		38.857239 °	38.861899 °	
			-121.783771 °	-121.784057 °	
DWR ID					
Action/Comments					
Inspector Comments: 1997 - Intermittent toe failure of the hand placed riprap; failure of toe materials. 2015: No observed changes. [2015 Site ID: SAC_99-0_L]					

Photo 1 of 1 : USACE2013A_SAC_99-0_L_1.jpg



USACE 2013 Photo #1

LM Start	14.18	Rating **	C	Issue No.	89
LM End	14.18	Issue Type +	Ma	Location *	LS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Animal Control		38.860452 °	38.860452 °	
			-121.783294 °	-121.783294 °	
DWR ID	DWR_RD1500_01_s_2013_89				
Action/Comments					
Exterminate rodents and backfill and compact or grout burrows.					

No Photos

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	--	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2015

Reclamation District No. 1500 Sutter Basin

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	33.15	10/20/2015 10/21/2015	Jai Lor

LM Start	14.21	Rating **	M	Issue No.	30
LM End	14.21	Issue Type +	En	Location *	LS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Encroachments		38.860848 °	38.860848 °	
			-121.783307 °	-121.783307 °	
DWR ID	DWR_RD1500_01_s_2012_30				
Action/Comments					
Building Inspector Comments: Concrete stemwall into levee embankment.					

Photo 1 of 1 : FA_2015_RD1500_189_30_20151026_00169.jpg



View of the building on the landward side of the levee looking upstream. Fall 2015.

LM Start	14.25	Rating **	M	Issue No.	31
LM End	14.25	Issue Type +	En	Location *	LS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Vegetation		38.861513 °	38.861513 °	
			-121.783588 °	-121.783588 °	
DWR ID	DWR_RD1500_01_s_2012_31				
Action/Comments					
Landscaping					

Photo 1 of 1 : FA_2015_RD1500_189_31_20151026_00170.jpg



View of the landscaping on the landward side of the levee looking upstream. Fall 2015.

LM Start	14.27	Rating **	U	Issue No.	77
LM End	14.27	Issue Type +	Ma	Location *	LS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Trim / Thin Trees		38.861793 °	38.861793 °	
			-121.783703 °	-121.783703 °	
DWR ID	DWR_RD1500_01_s_2012_77				
Action/Comments					
Trim and thin trees to allow visibility of the ground and room to flood fight.					

Photo 1 of 1 : FA_2015_RD1500_189_77_20151026_00171.jpg



View of the trees on the landward side of the levee looking upstream. Blocking visibility. Fall 2015.

* Location		** Rating		+ Issue Type	
LS : Land Side	N/A : Not Applicable	A : Acceptable	N : Not Inspected/Rated	Ma : Maintenance Deficiency	
WS : Water Side		M : Minimally Acceptable	C : Corrected	Ob : Design & System Obsolescence	
CR : Crown		U : Unacceptable	A/W : Acceptable but Monitor & Maintain	En : Enforcement	

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2015

Reclamation District No. 1500 Sutter Basin

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	33.15	10/20/2015 10/21/2015	Jai Lor

LM Start	14.71	Rating **	M	Issue No.	969
LM End	15.76	Issue Type +	En	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			38.865473 °	38.871752 °
				-121.789413 °	-121.804257 °
DWR ID	DWR_RD1500_01_s_2012_969				
Action/Comments					
Ditch Inspector Comments: Ditch is at the levee toe.					

Photo 1 of 1 : FA_2015_RD1500_189_969_20151026_00172.jpg



View of the ditch on the landward side of the levee looking upstream. Fall 2015.

LM Start	15.11	Rating **	M	Issue No.	21
LM End	15.11	Issue Type +	En	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			38.866827 °	38.866827 °
				-121.794020 °	-121.794020 °
DWR ID	DWR_RD1500_01_s_2012_21				
Action/Comments					
Debris Inspector Comments: A pile of rip rap and concrete needs to be removed.					

Photo 1 of 1 : FA_2015_RD1500_189_21_20151026_00173.jpg



View of the concrete debris on the waterward side of the levee. Fall 2015.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2015

Reclamation District No. 1500 Sutter Basin

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	33.15	10/20/2015 10/21/2015	Jai Lor

LM Start	15.11	Rating **	M	Issue No.	2575
LM End	15.11	Issue Type +	En	Location *	WS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			38.866841 °	38.866841 °
				-121.794047 °	-121.794047 °
DWR ID					
Action/Comments					
Inspector Comments: FS_ID:28486 DS_ID:20010 EP_NO: 10037 FS_HLM: 15.27 Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: Water treatment plant on landside. Working during field visit. Not found- Flap Gate in 6.5 foot by 7.0 foot O.D. concrete distribution box at landward toe. FIELD_STRUCT_DESC: 22-inch concrete encased steel irrigation pipe through levee, 17.5 feet below crown. 1.5 -inch conduit through levee, 6.0 feet below crown. Slant pump on river bank. Gate valve in CMP riser on waterside. A 6.5 foot by 7.0 foot O.D. concrete distribution box at landward toe. (ABO. No. 10037 - Clauss) O&M Manual Sac 128, March 1960. FS Date: 01/10/2014					

Photo 1 of 3 : UCIP_FA_2015_3068.jpg



LS view: concrete distribution box on levee toe. Water filtration plant off the levee toe.

LM Start	15.11	Rating **	M	Issue No.	2575 (cont)
LM End	15.11	Issue Type +	En	Location *	WS

Photo 2 of 3 : UCIP_FA_2015_3069.jpg



WS view: oil leaking slant pump on steel platform.

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	--	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2015

Reclamation District No. 1500 Sutter Basin

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	33.15	10/20/2015 10/21/2015	Jai Lor

LM Start	15.11	Rating **	M	Issue No.	2575 (cont)
LM End	15.11	Issue Type +	En	Location *	WS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			38.866841 °	38.866841 °
				-121.794047 °	-121.794047 °
DWR ID					
Action/Comments					
Inspector Comments: FS_ID:28486 DS_ID:20010 EP_NO: 10037 FS_HLM: 15.27 Repair Type: Non-Urgent Crossing Status: Found					

Photo 3 of 3 : UCIP_FA_2015_3070.jpg



WS view: CMP riser with gate valve and slant pump on steel platform.

LM Start	15.27	Rating **	M	Issue No.	110
LM End	15.27	Issue Type +	En	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			38.868244 °	38.868244 °
				-121.796220 °	-121.796220 °
DWR ID	DWR_RD1500_01_f_2014_110				
Action/Comments					
Debris					

Photo 1 of 1 : FA_2015_RD1500_189_110_20151026_00174.jpg



View of the debris on the waterward side of the levee. The abandoned pipe has been removed. Fall 2015.

LM Start	15.78	Rating **	A/W	Issue No.	32
LM End	15.78	Issue Type +	En	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			38.871960 °	38.871960 °
				-121.804440 °	-121.804440 °
DWR ID	DWR_RD1500_01_s_2012_32				
Action/Comments					
Equipment					

Photo 1 of 1 : FA_2015_RD1500_189_32_20151026_00175.jpg



View of the equipment on the waterward side of the levee looking upstream. Fall 2015.

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
N/A : Not Applicable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2015

Reclamation District No. 1500 Sutter Basin

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	33.15	10/20/2015 10/21/2015	Jai Lor

LM Start	16.20	Rating **	C	Issue No.	78
LM End	16.20	Issue Type +	En	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			38.874623 °	38.874623 °
				-121.811272 °	-121.811272 °
DWR ID	DWR_RD1500_01_s_2012_78				
Action/Comments					
Equipment					

No Photos

LM Start	16.30	Rating **	U	Issue No.	33
LM End	16.30	Issue Type +	En	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.875873 °	38.875873 °
				-121.812410 °	-121.812410 °
DWR ID	DWR_RD1500_01_s_2012_33				
Action/Comments					
Landscaping Inspector Comments: There is landscaping, including oleanders and other shrubs at this location.					

Photo 1 of 1 : FA_2015_RD1500_189_33_20151026_00176.jpg



View of the shrubs on the landward side of the levee looking upstream. Fall 2015.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable N : Not Inspected/Rated M : Minimally Acceptable C : Corrected U : Unacceptable A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
---	--	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2015

Reclamation District No. 1500 Sutter Basin

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	33.15	10/20/2015 10/21/2015	Jai Lor

LM Start	16.97	Rating **	M	Issue No.	2576
LM End	16.97	Issue Type +	En	Location *	LS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			38.885098 °	38.885098 °
				-121.812884 °	-121.812884 °
DWR ID					

Action/Comments
 Inspector Comments: FS_ID:28489
 DS_ID:20081
 EP_NO: 8510
 FS_HLM: 17.155
 Repair Type: Non-Urgent
 Crossing Status: Found
 UCIP Comments: Pipe not visible on river bank. Cleaning and clearing require around slide gates. May be abandoned.
 FIELD_STRUCT_DESC: 24-inch CM irrigation pipe through levee, 15.0 feet below crown. Slide gate in 36-inch CM riser on waterward slope. Slide gate on concrete "U" headwall an irrigation ditch at landward toe.
 (App No. 8510, 11/1972 - Clauss) O&M Manual Sac 128, March 1960.
 FS Date: 01/14/2014

Photo 1 of 3 : UCIP_FA_2015_3090.jpg



LS view: U type concrete headwall with slide gate on levee toe.

LM Start	16.97	Rating **	M	Issue No.	2576 (cont)
LM End	16.97	Issue Type +	En	Location *	LS

Photo 2 of 3 : UCIP_FA_2015_3091.jpg



WS view: cleaning and clearing require around slide gate in CMP riser.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	--	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2015

Reclamation District No. 1500 Sutter Basin

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	33.15	10/20/2015 10/21/2015	Jai Lor

LM Start	16.97	Rating **	M	Issue No.	2576 (cont)
LM End	16.97	Issue Type +	En	Location *	LS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			38.885098 °	38.885098 °
				-121.812884 °	-121.812884 °
DWR ID					
Action/Comments					
Inspector Comments: FS_ID:28489 DS_ID:20081 EP_NO: 8510 FS_HLM: 17.155 Repair Type: Non-Urgent Crossing Status: Found					

Photo 3 of 3 : UCIP_FA_2015_3092.jpg



WS view: CMP riser with slide gate on levee slope.

LM Start	17.27	Rating **	M	Issue No.	2577
LM End	17.27	Issue Type +	En	Location *	LS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			38.887377 °	38.887377 °
				-121.808219 °	-121.808219 °
DWR ID					
Action/Comments					
Inspector Comments: FS_ID:28490 DS_ID:20066 EP_NO: 1739 FS_HLM: 17.456 Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: Most of the pipe exposed on levee slope. Pipe leakage repaired recently. Siphon breaker requires protection. FIELD_STRUCT_DESC: 20-inch welded steel irrigation pipe through levee, 5.5 feet below crown. Slant pump mounted on steel structure on waterside. Siphon breaker on landward slope. Discharges into concrete distribution box at landward toe. (App. No. 1739 - Clauss) (RM 102.50) O&M Manual Sac 128, March 1960 FS Date: 01/14/2014					

Photo 1 of 3 : UCIP_FA_2015_3093.jpg



LS view: exposed pipe on levee slope, and concrete distribution box on levee toe.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2015

Reclamation District No. 1500 Sutter Basin

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	33.15	10/20/2015 10/21/2015	Jai Lor

LM Start	17.27	Rating **	M	Issue No.	2577 (cont)
LM End	17.27	Issue Type +	En	Location *	LS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			38.887377 °	38.887377 °
				-121.808219 °	-121.808219 °
DWR ID					
Action/Comments					
Inspector Comments: FS_ID:28490 DS_ID:20066 EP_NO: 1739 FS_HLM: 17.456 Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: Most of the pipe exposed on levee slope. Pipe leakage repaired recently. Siphon breaker requires protection. FIELD_STRUCT_DESC: 20-inch welded steel irrigation pipe through levee, 5.5 feet below crown. Slant pump mounted on steel structure on waterside. Siphon breaker on landward slope. Discharges into concrete distribution box at landward toe. (App. No. 1739 - Clauss) (RM 102.50) O&M Manual Sac 128, March 1960 FS Date: 01/14/2014					

Photo 2 of 3 : UCIP_FA_2015_3094.jpg



LS view: siphon breaker (bottom) without protection, exposed pipe on levee slope, and distribution box on levee toe.

LM Start	17.27	Rating **	M	Issue No.	2577 (cont)
LM End	17.27	Issue Type +	En	Location *	LS

Photo 3 of 3 : UCIP_FA_2015_3095.jpg



WS view: slant pump on steel platform on levee berm.

* Location	** Rating	+ Issue Type
LS : Land Side WS : Water Side CR : Crown	A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain
N/A : Not Applicable		Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2015

Reclamation District No. 1500 Sutter Basin

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	33.15	10/20/2015 10/21/2015	Jai Lor

LM Start	17.34	Rating **	M	Issue No.	121
LM End	17.34	Issue Type +	En	Location *	WS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Encroachments		38.888137 °	38.888137 °	
			-121.807273 °	-121.807273 °	
DWR ID	DWR_RD1500_01_f_2015_121				
Action/Comments					
Pipe Inspector Comments: Pipe is causing the erosion on the berm of the levee.					

Photo 1 of 3 : FA_2015_RD1500_189_121_20151026_00179.jpg



Perspective view of the pump on the waterward side of the levee looking upstream. Fall 2015.

LM Start	17.34	Rating **	M	Issue No.	121 (cont)
LM End	17.34	Issue Type +	En	Location *	WS

Photo 2 of 3 : FA_2015_RD1500_189_121_20151026_00177.jpg



There is erosion underneath the pipe on the waterward berm area. Fall 2015.

LM Start	17.34	Rating **	M	Issue No.	121 (cont)
LM End	17.34	Issue Type +	En	Location *	WS

Photo 3 of 3 : FA_2015_RD1500_189_121_20151026_00178.jpg



The concrete for the base stand has been exposed due to erosion.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2015

Reclamation District No. 1500 Sutter Basin

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	33.15	10/20/2015 10/21/2015	Jai Lor

LM Start	17.63	Rating **	M	Issue No.	122
LM End	17.66	Issue Type +	En	Location *	WS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Encroachments		38.891795 °	38.892291 °	
			-121.804829 °	-121.804734 °	
DWR ID	DWR_RD1500_01_f_2015_122				
Action/Comments					
Prunings					

Photo 1 of 1 : FA_2015_RD1500_189_122_20151026_00180.jpg



View of the prunings on the waterward side of the levee looking upstream. Fall 2015.

LM Start	18.29	Rating **	A/W	Issue No.	51
LM End	18.29	Issue Type +	Ma	Location *	WS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Erosion / Bank Caving		38.900873 °	38.900873 °	
			-121.802680 °	-121.802680 °	
DWR ID	DWR_RD1500_01_s_2012_51				
Action/Comments					
Note and monitor erosion site.					

Photo 1 of 2 : FA_2015_RD1500_189_51_20151026_00182.jpg



Looking downstream at the embankment erosion. Fall 2015.

LM Start	18.29	Rating **	A/W	Issue No.	51 (cont)
LM End	18.29	Issue Type +	Ma	Location *	WS

Photo 2 of 2 : FA_2015_RD1500_189_51_20151026_00181.jpg



Looking upstream at the same embankment erosion. Fall 2015.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2015

Reclamation District No. 1500 Sutter Basin

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	33.15	10/20/2015 10/21/2015	Jai Lor

LM Start	18.38	Rating **	M	Issue No.	13
LM End	19.06	Issue Type +	Ma	Location *	WS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	2015 USACE Erosion Survey, DRAFT			38.901337 °	38.902721 °
				-121.801175 °	-121.790677 °
DWR ID					
Action/Comments					
Inspector Comments: 1997 - Pocket failures of cobble revetment toe; scallops of rock loss along the bank; irregular bankline developing. 2001 - Small scallops in the toe of the berm. 2005 - Still multiple erosion pockets in the toe. 2006 - Two new small slumps. 2011 - Old cobble continue to fail causing minor slumping. 2012 - Portions of site appears to be stabilizing. 2015: No observed changes. [2015 Site ID:					

Photo 1 of 1 : USACE2013A_SAC_104-0_L_11.jpg



USACE 2013 Photo #1

LM Start	18.40	Rating **	M	Issue No.	2578
LM End	18.40	Issue Type +	En	Location *	WS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			38.900885 °	38.900885 °
				-121.800999 °	-121.800999 °
DWR ID					
Action/Comments					
Inspector Comments: FS_ID:28505 DS_ID:20068 EP_NO: 2425 FS_HLM: 18.56 Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: Concrete pad on both sides of the levee shoulders. Oil leaks from pump set. FIELD_STRUCT_DESC: 14-inch steel irrigation pipe through levee, 3.0 feet below crown. Slant pump in Corrugated metal pump house on steel structure on bank. Meter pole on slope. Siphon breaker on landward shoulder. Discharges into 36-inch concrete standpipe at landward toe. (App. No. 2425 - Hiatt). O&M Manual Sac 128, March 1960. FS Date: 01/14/2014					

Photo 1 of 3 : UCIP_FA_2015_1226.jpg



LS view: siphon breaker (left) on exposed steel pipe on levee slope. Concrete pad (right) on levee shoulder.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable N : Not Inspected/Rated M : Minimally Acceptable C : Corrected U : Unacceptable A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
---	--	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2015

Reclamation District No. 1500 Sutter Basin

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	33.15	10/20/2015 10/21/2015	Jai Lor

LM Start	18.40	Rating **	M	Issue No.	2578 (cont)
LM End	18.40	Issue Type +	En	Location *	WS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			38.900885 °	38.900885 °
				-121.800999 °	-121.800999 °
DWR ID					

Action/Comments

Inspector Comments: FS_ID:28505
 DS_ID:20068
 EP_NO: 2425
 FS_HLM: 18.56
 Repair Type: Non-Urgent
 Crossing Status: Found
 UCIP Comments: Concrete pad on both sides of the levee shoulders. Oil leaks from pump set.
 FIELD_STRUCT_DESC: 14-inch steel irrigation pipe through levee, 3.0 feet below crown. Slant pump in Corrugated metal pump house on steel structure on bank. Meter pole on slope. Siphon breaker on landward shoulder. Discharges into 36-inch concrete standpipe at landward toe.
 (App. No. 2425 - Hiatt). O&M Manual Sac 128, March 1960.
 FS Date: 01/14/2014

Photo 2 of 3 : UCIP_FA_2015_1227.jpg



LS view: siphon breaker (bottom) on exposed steel pipe on levee slope and steel stand pipe (top) on levee toe.

LM Start	18.40	Rating **	M	Issue No.	2578 (cont)
LM End	18.40	Issue Type +	En	Location *	WS

Photo 3 of 3 : UCIP_FA_2015_1228.jpg



WS view: slant pump in CM shed on levee berm. Oil leaks from the pump.

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	--	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2015

Reclamation District No. 1500 Sutter Basin

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	33.15	10/20/2015 10/21/2015	Jai Lor

LM Start	18.98	Rating **	M	Issue No.	36
LM End	18.98	Issue Type +	En	Location *	LS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Encroachments		38.901570 °	38.901570 °	
			-121.791235 °	-121.791235 °	
DWR ID	DWR_RD1500_01_s_2012_36				
Action/Comments					
Building Inspector Comments: Concrete retaining wall toe of landside levee. Permit #10065					

Photo 1 of 2 : FA_2015_RD1500_189_36_20150914_00032.jpg



Building and wall into levee with landscape, photo taken in spring 2010.

LM Start	18.98	Rating **	M	Issue No.	36 (cont)
LM End	18.98	Issue Type +	En	Location *	LS

Photo 2 of 2 : FA_2015_RD1500_189_36_20151026_00183.jpg



View of the building on the landward side of the levee looking upstream. Fall 2015.

LM Start	19.01	Rating **	M	Issue No.	37
LM End	19.01	Issue Type +	En	Location *	LS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Vegetation		38.901965 °	38.901965 °	
			-121.790993 °	-121.790993 °	
DWR ID	DWR_RD1500_01_s_2012_37				
Action/Comments					
Landscaping Inspector Comments: Concrete retaining wall along toe of landside levee. Permit #10065					

Photo 1 of 2 : FA_2015_RD1500_189_37_20150914_00033.jpg



The groundcover is on the levee slope above the concrete retaining wall. The groundcover is irrigated.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
---	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2015

Reclamation District No. 1500 Sutter Basin

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	33.15	10/20/2015 10/21/2015	Jai Lor

LM Start	19.01	Rating **	M	Issue No.	37 (cont)
LM End	19.01	Issue Type +	En	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.901965 °	38.901965 °
				-121.790993 °	-121.790993 °
DWR ID	DWR_RD1500_01_s_2012_37				
Action/Comments					
Landscaping Inspector Comments: Concrete retaining wall along toe of landside levee. Permit #10065					

Photo 2 of 2 : FA_2015_RD1500_189_37_20151026_00184.jpg



View of the groundcover on the landward side of the levee looking upstream. Fall 2015.

LM Start	19.16	Rating **	M	Issue No.	5
LM End	19.47	Issue Type +	Ma	Location *	WS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	2015 USACE Erosion Survey, DRAFT			38.904041 °	38.906697 °
				-121.790298 °	-121.792796 °
DWR ID					
Action/Comments					
Inspector Comments: 1997 - Cobbles eroded off the clay materials; not much evidence of erosion on the toe; cobble loss on the toe. 2011 - Some minor new erosion. 2015: No observed changes. [2015 Site ID: SAC_104-5_L]					

Photo 1 of 1 : USACE2013A_SAC_104-5_L_3.jpg



USACE 2013 Photo #1

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

Flood Control Project Maintenance
Levee Inspections

Levee Inspection Report By Mile - Fall 2015

Reclamation District No. 1500 Sutter Basin

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	33.15	10/20/2015 10/21/2015	Jai Lor

LM Start	19.23	Rating **	M	Issue No.	2579
LM End	19.23	Issue Type +	En	Location *	WS
Category	Supplemental		GPS Latitude/Longitude		
			Start	End	
Item	DWR UCIP Field Study		38.905029 °	38.905029 °	
			-121.790076 °	-121.790076 °	
DWR ID					
Action/Comments					
Inspector Comments: FS_ID:28506 DS_ID:20087 EP_NO: 550 FS_HLM: 19.44 Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: Surface erosion on landside slope.Oil leaks from the pump. FIELD_STRUCT_DESC: 14-inch steel irrigation pipe through levee, 4.8 feet below crown. Slant pump and gate valve in CM pump house on steel structure on berm. Water meter installed on pipe on the waterward slope. Concrete distribution box on landward side. (App. No. 550 - Hiatt) O&M Manual Sac 128, March 1960. New permit no. 17648GM- Van Ruiten Bros- June 24, 2003. FS Date: 01/14/2014					

Photo 1 of 3 : UCIP_FA_2015_1229.jpg



LS view: concrete distribution box on levee toe.

LM Start	19.23	Rating **	M	Issue No.	2579 (cont)
LM End	19.23	Issue Type +	En	Location *	WS

Photo 2 of 3 : UCIP_FA_2015_1230.jpg



LS view: surface erosion on landside levee slope.

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	--	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2015

Reclamation District No. 1500 Sutter Basin

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	33.15	10/20/2015 10/21/2015	Jai Lor

LM Start	19.23	Rating **	M	Issue No.	2579 (cont)
LM End	19.23	Issue Type +	En	Location *	WS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			38.905029 °	38.905029 °
				-121.790076 °	-121.790076 °
DWR ID					
Action/Comments					
Inspector Comments: FS_ID:28506 DS_ID:20087 EP_NO: 550 FS_HLM: 19.44 Repair Type: Non-Urgent Crossing Status: Found					

Photo 3 of 3 : UCIP_FA_2015_1231.jpg



WS view: slant pump in CM shed on levee berm. Oil leaks from the pump.

LM Start	19.47	Rating **	M	Issue No.	2580
LM End	19.47	Issue Type +	En	Location *	WS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			38.907033 °	38.907033 °
				-121.792943 °	-121.792943 °
DWR ID					
Action/Comments					
Inspector Comments: FS_ID:28524 DS_ID:20004 EP_NO: 15681 FS_HLM: 19.688 Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: Obstructed siphon breakers on landside. Two 3-inch conduit through the levee. Service box on pump platform. Pumping plant was working during the field visit. FIELD_STRUCT_DESC: 1 of 2: Two slant pumps supported by steel piling on the riverbank. 16 and 18-inches steel pipelines, asphalt coated inside and out and wrapped with asphalt saturated felt through the levee section to a concrete discharge box located landward of the landward levee toe. Pipes 1.5 feet below the crown. Siphon breakers in steel pipe risers on levee slope. (App. No. 15681) FS Date: 01/14/2014					

Photo 1 of 3 : UCIP_FA_2015_3344.jpg



LS view: concrete distribution box on levee toe.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2015

Reclamation District No. 1500 Sutter Basin

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	33.15	10/20/2015 10/21/2015	Jai Lor

LM Start	19.47	Rating **	M	Issue No.	2580 (cont)
LM End	19.47	Issue Type +	En	Location *	WS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			38.907033 °	38.907033 °
				-121.792943 °	-121.792943 °
DWR ID					
Action/Comments					
Inspector Comments: FS_ID:28524 DS_ID:20004 EP_NO: 15681 FS_HLM: 19.688 Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: Obstructed siphon breakers on landside. Two 3-inch conduit through the levee. Service box on pump platform. Pumping plant was working during the field visit. FIELD_STRUCT_DESC: 1 of 2: Two slant pumps supported by steel piling on the riverbank. 16 and 18-inches steel pipelines, asphalt coated inside and out and wrapped with asphalt saturated felt through the levee section to a concrete discharge box located landward of the landward levee toe. Pipes 1.5 feet below the crown. Siphon breakers in steel pipe risers on levee slope. (App. No. 15681) FS Date: 01/14/2014					

Photo 2 of 3 : UCIP_FA_2015_3345.jpg



LS view: siphon breakers in steel pipe risers (bottom) on levee slope and concrete distribution (top) box on levee toe.

LM Start	19.47	Rating **	M	Issue No.	2580 (cont)
LM End	19.47	Issue Type +	En	Location *	WS

Photo 3 of 3 : UCIP_FA_2015_3346.jpg



WS view: pipe, walkway, slant pump, and steel platform on levee berm.

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	--	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2015

Reclamation District No. 1500 Sutter Basin

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	33.15	10/20/2015 10/21/2015	Jai Lor

LM Start	19.47	Rating **	M	Issue No.	2581
LM End	19.47	Issue Type +	En	Location *	WS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			38.907028 °	38.907028 °
				-121.792959 °	-121.792959 °
DWR ID					
Action/Comments					
Inspector Comments: FS_ID:28927 DS_ID:20022 EP_NO: 15681 FS_HLM: 19.6881 Repair Type: Non-Urgent Crossing Status: Found					

Photo 1 of 3 : UCIP_FA_2015_2936.jpg



LS view: concrete distribution box on levee toe.

LM Start	19.47	Rating **	M	Issue No.	2581 (cont)
LM End	19.47	Issue Type +	En	Location *	WS

Photo 2 of 3 : UCIP_FA_2015_2937.jpg



LS view: siphon breakers in steel pipe risers (bottom) on levee slope and concrete distribution (top) box on levee toe.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	--	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2015

Reclamation District No. 1500 Sutter Basin

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	33.15	10/20/2015 10/21/2015	Jai Lor

LM Start	19.47	Rating **	M	Issue No.	2581 (cont)
LM End	19.47	Issue Type +	En	Location *	WS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			38.907028 °	38.907028 °
				-121.792959 °	-121.792959 °
DWR ID					
Action/Comments					
Inspector Comments: FS_ID:28927 DS_ID:20022 EP_NO: 15681 FS_HLM: 19.6881 Repair Type: Non-Urgent Crossing Status: Found					

Photo 3 of 3 : UCIP_FA_2015_2938.jpg



WS view: pipe, walkway, slant pump, and steel platform on levee berm.

LM Start	19.56	Rating **	M	Issue No.	2549
LM End	19.56	Issue Type +	En	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			38.906565 °	38.906565 °
				-121.794472 °	-121.794472 °
DWR ID	DWR_RD1500_01_s_2015_2549				
Action/Comments					
Equipment					

Photo 1 of 1 : FA_2015_RD1500_189_2549_20150914_00090.jpg



View of the equipment on the waterward side of the levee looking upstream. Spring 2015.

LM Start	19.62	Rating **	M	Issue No.	2550
LM End	19.62	Issue Type +	En	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			38.906375 °	38.906375 °
				-121.795611 °	-121.795611 °
DWR ID	DWR_RD1500_01_s_2015_2550				
Action/Comments					
Prunings					

No Photos

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---

Flood Control Project Maintenance
Levee Inspections

Levee Inspection Report By Mile - Fall 2015

Reclamation District No. 1500 Sutter Basin

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	33.15	10/20/2015 10/21/2015	Jai Lor

LM Start	20.57	Rating **	M	Issue No.	2582
LM End	20.57	Issue Type +	En	Location *	WS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			38.910005 °	38.910005 °
				-121.811376 °	-121.811376 °
DWR ID					
Action/Comments					
Inspector Comments: FS_ID:41800 DS_ID:20069 EP_NO: 16605 FS_HLM: 20.795 Repair Type: Non-Urgent Crossing Status: Indicator Found UCIP Comments: Verify pipe has been abandoned properly. Culvert and pipe not found. A crossing tag plate on waterside shoulder. An abandoned pump house on river bank at the bend of the river (ab 250 ft from the levee). A concrete pad found on waterside levee toe. A ditch from pump house to concrete pad. 3- 1-inch stand pipes on landside. FIELD_STRUCT_DESC: 3 foot by 2 foot concrete culvert through levee, 21.0 feet below crown. Two corrugated metal cutoff walls. Piezometer at landward toe. (AB0 No. 1005) To abandon a 30-inch diameter gravity feed concrete pipeline through the left bank levee on the Sacramento River. (App. No. 16605). O&M Manual Sac 128, March 1960. FS Date: 01/14/2014					

Photo 1 of 3 : UCIP_FA_2015_2939.jpg



LS view: three 1" standpipes (may be piezometers) on levee toe.

LM Start	20.57	Rating **	M	Issue No.	2582 (cont)
LM End	20.57	Issue Type +	En	Location *	WS

Photo 2 of 3 : UCIP_FA_2015_3347.jpg



WS view: abandoned pump house on river bank at the bend of the river (ab 250 ft from the levee).

* Location		** Rating		+ Issue Type	
LS : Land Side	N/A : Not Applicable	A : Acceptable	N : Not Inspected/Rated	Ma : Maintenance Deficiency	
WS : Water Side		M : Minimally Acceptable	C : Corrected	Ob : Design & System Obsolescence	
CR : Crown		U : Unacceptable	A/W : Acceptable but Monitor & Maintain	En : Enforcement	

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2015

Reclamation District No. 1500 Sutter Basin

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	33.15	10/20/2015 10/21/2015	Jai Lor

LM Start	20.57	Rating **	M	Issue No.	2582 (cont)
LM End	20.57	Issue Type +	En	Location *	WS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			38.910005 °	38.910005 °
				-121.811376 °	-121.811376 °
DWR ID					
Action/Comments					
Inspector Comments: FS_ID:41800 DS_ID:20069 EP_NO: 16605 FS_HLM: 20.795 Repair Type: Non-Urgent Crossing Status: Indicator Found					

Photo 3 of 3 : UCIP_FA_2015_3348.jpg



WS view: a concrete pad on waterside levee toe.

LM Start	20.63	Rating **	C	Issue No.	975
LM End	21.16	Issue Type +	En	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			38.910177 °	38.913267 °
				-121.810352 °	-121.803142 °
DWR ID	DWR_RD1500_01_s_2012_975				
Action/Comments					
Ditch					

No Photos

LM Start	21.06	Rating **	M	Issue No.	101
LM End	21.06	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			38.911910 °	38.911910 °
				-121.803666 °	-121.803666 °
DWR ID	DWR_RD1500_01_f_2015_101				
Action/Comments					
No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.					

Photo 1 of 1 : FA_2015_RD1500_189_101_20151026_00133.jpg



View of the rodent hole on the landward side of the levee looking upstream. Fall 2015.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable N : Not Inspected/Rated M : Minimally Acceptable C : Corrected U : Unacceptable A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
---	--	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2015

Reclamation District No. 1500 Sutter Basin

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	33.15	10/20/2015 10/21/2015	Jai Lor

LM Start	21.26	Rating **	M	Issue No.	2583
LM End	21.26	Issue Type +	En	Location *	LS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			38.914659 °	38.914659 °
				-121.803609 °	-121.803609 °
DWR ID					

Action/Comments

Inspector Comments: FS_ID:28527
 DS_ID:20070
 EP_NO: 11959A
 FS_HLM: 21.495
 Repair Type: Non-Urgent
 Crossing Status: Found
 UCIP Comments: Siphon breaker (obstructed) in CMP on landside slope. Power pole on landside toe.
 FIELD_STRUCT_DESC: 10-inch steel pipe through levee, 3.0 feet below crown with slant pump on steel platform. Siphon breaker (obstructed) in CMP on landside slope. A 6 foot by 6 foot concrete distribution box on landward side. (App. No. 11959A - Van Ruiten) O&M Manual Sac 128, March 1960.
 FS Date: 01/14/2014

Photo 1 of 3 : UCIP_FA_2015_0619.jpg



LS view: obstructed siphon breaker in CMP riser on levee slope.

LM Start	21.26	Rating **	M	Issue No.	2583 (cont)
LM End	21.26	Issue Type +	En	Location *	LS

Photo 2 of 3 : UCIP_FA_2015_2917.jpg



LS view: siphon breaker in CMP riser on levee slope (bottom) and concrete distribution box (top) on levee toe.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
---	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2015

Reclamation District No. 1500 Sutter Basin

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	33.15	10/20/2015 10/21/2015	Jai Lor

LM Start	21.26	Rating **	M	Issue No.	2583 (cont)
LM End	21.26	Issue Type +	En	Location *	LS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			38.914659 °	38.914659 °
				-121.803609 °	-121.803609 °
DWR ID					
Action/Comments					
Inspector Comments: FS_ID:28527 DS_ID:20070 EP_NO: 11959A FS_HLM: 21.495 Repair Type: Non-Urgent Crossing Status: Found					

Photo 3 of 3 : UCIP_FA_2015_2918.jpg



WS view: slant pump on steel platform on levee berm.

LM Start	21.58	Rating **	M	Issue No.	2584
LM End	21.58	Issue Type +	En	Location *	LS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			38.916180 °	38.916180 °
				-121.808904 °	-121.808904 °
DWR ID					
Action/Comments					
Inspector Comments: FS_ID:28528 DS_ID:20071 EP_NO: 10063 FS_HLM: 21.828 Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: Water leaks near pump. Obstructed siphon breaker in CMP on landside. Plant was working during field visit. FIELD_STRUCT_DESC: 16-inch steel irrigation pipe through levee 6.3 feet below crown. 1-1/2-inch conduit through levee, 6.5 feet below crown. Slant pump and gate valve on berm. Siphon breaker in 24-inch corrugated metal riser on landward slope. CMP standpipe on landside toe. Power pole and one anchor at landward toe. (ABO. No. 10063, 11/1974 - Nelson) O&M Manual Sac 128, March 1960. FS Date: 01/14/2014					

Photo 1 of 3 : UCIP_FA_2015_2919.jpg



LS view: siphon breaker in CMP riser on levee slope (bottom) and CMP stand pipe (top) on levee toe.

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	--	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2015

Reclamation District No. 1500 Sutter Basin

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	33.15	10/20/2015 10/21/2015	Jai Lor

LM Start	21.91	Rating **	M	Issue No.	2585
LM End	21.91	Issue Type +	En	Location *	LS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			38.916606 °	38.916606 °
				-121.814881 °	-121.814881 °
DWR ID					
Action/Comments					
Inspector Comments: FS_ID:28543 DS_ID:20083 EP_NO: 10851 FS_HLM: 22.159 Repair Type: Non-Urgent Crossing Status: Found					

Photo 1 of 3 : UCIP_FA_2015_2994.jpg



LS view: siphon breaker in CMP riser on levee slope (bottom) and CMP stand pipe (top) on the levee toe.

LM Start	21.91	Rating **	M	Issue No.	2585 (cont)
LM End	21.91	Issue Type +	En	Location *	LS

Photo 2 of 3 : UCIP_FA_2015_2995.jpg



WS view: slant pipe and gate valve at the end of levee berm.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2015

Reclamation District No. 1500 Sutter Basin

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	33.15	10/20/2015 10/21/2015	Jai Lor

LM Start	21.91	Rating **	M	Issue No.	2585 (cont)
LM End	21.91	Issue Type +	En	Location *	LS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			38.916606 °	38.916606 °
				-121.814881 °	-121.814881 °
DWR ID					
Action/Comments					
Inspector Comments: FS_ID:28543 DS_ID:20083 EP_NO: 10851 FS_HLM: 22.159 Repair Type: Non-Urgent Crossing Status: Found					

Photo 3 of 3 : UCIP_FA_2015_2996.jpg



WS view: slant pump on steel platform on levee berm.

LM Start	22.73	Rating **	M	Issue No.	2586
LM End	22.73	Issue Type +	En	Location *	LS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			38.919717 °	38.919717 °
				-121.829113 °	-121.829113 °
DWR ID					
Action/Comments					
Inspector Comments: FS_ID:28583 DS_ID:19995 EP_NO: 10851 FS_HLM: 22.991 Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: Exposed conduit on both slopes of the levee. Plant was working during field visit. Water was leaking from pipe joint near pump. Obstructed siphon breaker in CMP. FIELD_STRUCT_DESC: 14-inch steel irrigation pipe through levee, 6.2 feet below crown. Pump and gate valve on steel platform. Switch panel on berm. Siphon breaker in 24-inch CM riser on landward shoulder. Discharges into 36-inch CM standpipe at landward toe. 2-inch conduit through levee, 5.0 feet below crown. Service pole at landward toe. Pumping plant No. 2. (App. No. 10851, 2895 - Van Ruiten) FS Date: 01/14/2014					

Photo 1 of 3 : UCIP_FA_2015_3031.jpg



LS view: siphon breaker in CMP riser on levee slope (bottom) and CMP stand pipe (top) on levee toe.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2015

Reclamation District No. 1500 Sutter Basin

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	33.15	10/20/2015 10/21/2015	Jai Lor

LM Start	22.73	Rating **	M	Issue No.	2586 (cont)
LM End	22.73	Issue Type +	En	Location *	LS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			38.919717 °	38.919717 °
				-121.829113 °	-121.829113 °
DWR ID					
Action/Comments					
Inspector Comments: FS_ID:28583 DS_ID:19995 EP_NO: 10851 FS_HLM: 22.991 Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: Exposed conduit on both slopes of the levee. Plant was working during field visit. Water was leaking from pipe joint near pump. Obstructed siphon breaker in CMP. FIELD_STRUCT_DESC: 14-inch steel irrigation pipe through levee, 6.2 feet below crown. Pump and gate valve on steel platform. Switch panel on berm. Siphon breaker in 24-inch CM riser on landward shoulder. Discharges into 36-inch CM standpipe at landward toe. 2-inch conduit through levee, 5.0 feet below crown. Service pole at landward toe. Pumping plant No. 2. (App. No. 10851, 2895 - Van Ruiten) FS Date: 01/14/2014					

Photo 2 of 3 : UCIP_FA_2015_3032.jpg



WS view: gate valve beneath slant pipe on levee berm. Water leaking from this pipe (marked).

LM Start	22.73	Rating **	M	Issue No.	2586 (cont)
LM End	22.73	Issue Type +	En	Location *	LS

Photo 3 of 3 : UCIP_FA_2015_3033.jpg



WS view: slant pump on steel platform on levee berm.

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	--	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2015

Reclamation District No. 1500 Sutter Basin

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	33.15	10/20/2015 10/21/2015	Jai Lor

LM Start	23.42	Rating **	C	Issue No.	1349
LM End	23.67	Issue Type +	En	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			38.927290 °	38.930442 °
				-121.836912 °	-121.834905 °
DWR ID	DWR_RD1500_01_s_2014_1349				
Action/Comments					
Ditch					

No Photos

LM Start	23.65	Rating **	M	Issue No.	2587
LM End	23.65	Issue Type +	En	Location *	LS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			38.930242 °	38.930242 °
				-121.834956 °	-121.834956 °
DWR ID					
Action/Comments					
Inspector Comments: FS_ID:28586 DS_ID:20072 EP_NO: 2895 FS_HLM: 23.927 Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: Most of the pipe exposed on levee slopes. Leaky pump. Obstructed siphon breaker. Not found- Concrete headwall at landward toe. FIELD_STRUCT_DESC: 14-inch steel irrigation pipe through levee, 6.5 feet below crown. 1-1/2 inch conduit through levee, 4.0 feet below crown. Slant pump and control panel on steel structure on berm. Siphon breaker in 24-inch corrugated metal riser on landward shoulder. 36-inch CM standpipe at landward toe. Service pole at landward toe. Pumping- Plant No. 1. (App. No. 2895 - Van Ruiten) O&M Manual Sac 128, March 1960. FS Date: 01/14/2014					

Photo 1 of 3 : UCIP_FA_2015_3073.jpg



LS view: obstructed siphon breaker in CMP riser on levee slope.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2015

Reclamation District No. 1500 Sutter Basin

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	33.15	10/20/2015 10/21/2015	Jai Lor

LM Start	23.65	Rating **	M	Issue No.	2587 (cont)	
LM End	23.65	Issue Type +	En	Location *	LS	
Category	Supplemental			GPS Latitude/Longitude		
			Start	End		
Item	DWR UCIP Field Study			38.930242 °	38.930242 °	
				-121.834956 °	-121.834956 °	
DWR ID						
Action/Comments						
Inspector Comments: FS_ID:28586 DS_ID:20072 EP_NO: 2895 FS_HLM: 23.927 Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: Most of the pipe exposed on levee slopes. Leaky pump. Obstructed siphon breaker. Not found- Concrete headwall at landward toe. FIELD_STRUCT_DESC: 14-inch steel irrigation pipe through levee, 6.5 feet below crown. 1-1/2 inch conduit through levee, 4.0 feet below crown. Slant pump and control panel on steel structure on berm. Siphon breaker in 24-inch corrugated metal riser on landward shoulder. 36-inch CM standpipe at landward toe. Service pole at landward toe. Pumping- Plant No. 1. (App. No. 2895 - Van Ruiten) O&M Manual Sac 128, March 1960. FS Date: 01/14/2014						

Photo 2 of 3 : UCIP_FA_2015_3074.jpg



LS view: siphon breaker in CMP riser on levee slope (bottom) and CM standpipe (top) on levee toe.

LM Start	23.65	Rating **	M	Issue No.	2587 (cont)
LM End	23.65	Issue Type +	En	Location *	LS

Photo 3 of 3 : UCIP_FA_2015_3075.jpg



WS view: slant pump on steel platform on levee berm. Oil leaks from the pump (marked). Exposed pipe on the berm.

* Location	** Rating	+ Issue Type
LS : Land Side WS : Water Side CR : Crown	A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain
N/A : Not Applicable		Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2015

Reclamation District No. 1500 Sutter Basin

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	33.15	10/20/2015 10/21/2015	Jai Lor

LM Start	23.77	Rating **	M	Issue No.	42
LM End	23.77	Issue Type +	En	Location *	LS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Encroachments		38.931838 °	38.931838 °	
			-121.834437 °	-121.834437 °	
DWR ID	DWR_RD1500_01_s_2012_42				
Action/Comments					
Building Inspector Comments: Some equipment at landside toe.					

Photo 1 of 1 : FA_2015_RD1500_189_42_20151026_00134.jpg



View of the barn and equipment on the landward side of the levee looking downstream. Fall 2015.

LM Start	24.16	Rating **	M	Issue No.	979
LM End	24.31	Issue Type +	En	Location *	LS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Encroachments		38.936282 °	38.938430 °	
			-121.830192 °	-121.829359 °	
DWR ID	DWR_RD1500_01_s_2012_979				
Action/Comments					
Ditch					

Photo 1 of 2 : FA_2015_RD1500_189_979_20150914_00070.jpg



Agricultural ditch, photo taken in spring 2010.

LM Start	24.16	Rating **	M	Issue No.	979 (cont)
LM End	24.31	Issue Type +	En	Location *	LS

Photo 2 of 2 : FA_2015_RD1500_189_979_20150914_00071.jpg



Agricultural ditch runs along the toe of the levee. Spring 2014

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable N : Not Inspected/Rated M : Minimally Acceptable C : Corrected U : Unacceptable A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
---	--	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2015

Reclamation District No. 1500 Sutter Basin

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	33.15	10/20/2015 10/21/2015	Jai Lor

LM Start	24.31	Rating **	M	Issue No.	2588
LM End	24.31	Issue Type +	En	Location *	LS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			38.938431 °	38.938431 °
				-121.829350 °	-121.829350 °
DWR ID					
Action/Comments					
Inspector Comments: FS_ID:28603 DS_ID:24757 EP_NO: 10057 FS_HLM: 24.598 Repair Type: Non-Urgent Crossing Status: Found					

Photo 1 of 3 : UCIP_FA_2015_3076.jpg



LS view: siphon breaker in CMP riser on levee slope (bottom) and concrete distribution box (top) on levee toe.

LM Start	24.31	Rating **	M	Issue No.	2588 (cont)
LM End	24.31	Issue Type +	En	Location *	LS

Photo 2 of 3 : UCIP_FA_2015_3102.jpg



WS view: leaky pipe near pump platform. Pipe leaks from the joint.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2015

Reclamation District No. 1500 Sutter Basin

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	33.15	10/20/2015 10/21/2015	Jai Lor

LM Start	24.31	Rating **	M	Issue No.	2588 (cont)
LM End	24.31	Issue Type +	En	Location *	LS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			38.938431 °	38.938431 °
				-121.829350 °	-121.829350 °
DWR ID					
Action/Comments					
Inspector Comments: FS_ID:28603 DS_ID:24757 EP_NO: 10057 FS_HLM: 24.598 Repair Type: Non-Urgent Crossing Status: Found					

Photo 3 of 3 : UCIP_FA_2015_3103.jpg



WS view: slant pump on steel platform at levee berm. Walkway, exposed pipe, and gate valve on the berm.

LM Start	24.76	Rating **	M	Issue No.	102
LM End	24.76	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			38.942846 °	38.942846 °
				-121.834838 °	-121.834838 °
DWR ID	DWR_RD1500_01_f_ 2015_102				
Action/Comments					
No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.					

No Photos

LM Start	24.88	Rating **	M	Issue No.	69
LM End	24.88	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			38.944340 °	38.944340 °
				-121.835790 °	-121.835790 °
DWR ID	DWR_RD1500_01_f_ 2013_69				
Action/Comments					
Exterminate rodents and backfill and compact or grout burrows.					

Photo 1 of 2 : FA_2015_RD1500_189_69_20150914_00047.jpg



Multiple rodent burrows on landside slope. Fall 2013

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	--	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2015

Reclamation District No. 1500 Sutter Basin

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	33.15	10/20/2015 10/21/2015	Jai Lor

LM Start	24.88	Rating **	M	Issue No.	69 (cont)
LM End	24.88	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			38.944340 °	38.944340 °
				-121.835790 °	-121.835790 °
DWR ID	DWR_RD1500_01_f_2013_69				
Action/Comments					
Exterminate rodents and backfill and compact or grout burrows.					

Photo 2 of 2 : FA_2015_RD1500_189_69_20150914_00048.jpg



A rodent burrow on the landside Fall 2013

LM Start	25.49	Rating **	M	Issue No.	2589
LM End	25.49	Issue Type +	En	Location *	LS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			38.952803 °	38.952803 °
				-121.837618 °	-121.837618 °
DWR ID					
Action/Comments					
Inspector Comments: FS_ID:41728 DS_ID:20074 EP_NO: 8765 FS_HLM: 25.79 Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: Buried Concrete headwall on landside toe. Should verify pipe has been properly abandoned.Utility tag plate on waterside shoulder.No pipe found. FIELD_STRUCT_DESC: Abandoned 4 foot by 4 foot reinforced concrete pipe through levee, 10 feet below the crown. App. No. 8765 has been approved to sleeve a 20-inch pipe through existing pipe from a new pumping facility. (App. No. 8765 & 9175 - Lewis) O&M Manual Sac 128, March 1960. FS Date: 01/15/2014					

Photo 1 of 2 : UCIP_FA_2015_3104.jpg



LS view: concrete headwall on landside toe. No pipe found.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable N : Not Inspected/Rated M : Minimally Acceptable C : Corrected U : Unacceptable A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
---	--	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2015

Reclamation District No. 1500 Sutter Basin

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	33.15	10/20/2015 10/21/2015	Jai Lor

LM Start	25.49	Rating **	M	Issue No.	2589 (cont)	
LM End	25.49	Issue Type +	En	Location *	LS	
Category	Supplemental			GPS Latitude/Longitude		
			Start	End		
Item	DWR UCIP Field Study			38.952803 °	38.952803 °	
				-121.837618 °	-121.837618 °	
DWR ID						
Action/Comments						
Inspector Comments: FS_ID:41728 DS_ID:20074 EP_NO: 8765 FS_HLM: 25.79 Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: Burried Concrete headwall on landside toe. Should verify pipe has been properly abandoned. Utility tag plate on waterside shoulder. No pipe found. FIELD_STRUCT_DESC: Abandoned 4 foot by 4 foot reinforced concrete pipe through levee, 10 feet below the crown. App. No. 8765 has been approved to sleeve a 20-inch pipe through existing pipe from a new pumping facility. (App. No. 8765 & 9175 - Lewis) O&M Manual Sac 128, March 1960. FS Date: 01/15/2014						

Photo 2 of 2 : UCIP_FA_2015_3105.jpg



WS view: utility tag plate on waterside shoulder. No pipe found.

LM Start	25.76	Rating **	M	Issue No.	103	
LM End	25.76	Issue Type +	En	Location *	LS	
Category	Earthen Levee			GPS Latitude/Longitude		
			Start	End		
Item	Encroachments			38.956183 °	38.956183 °	
				-121.836347 °	-121.836347 °	
DWR ID	DWR_RD1500_01_f_2015_103					
Action/Comments						
Prunings						

Photo 1 of 1 : FA_2015_RD1500_189_103_20151026_00135.jpg



View of the prunings on the landward toe of the levee looking upstream. Fall 2015.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2015

Reclamation District No. 1500 Sutter Basin

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	33.15	10/20/2015 10/21/2015	Jai Lor

LM Start	26.52	Rating **	M	Issue No.	2590
LM End	26.52	Issue Type +	En	Location *	LS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			38.964915 °	38.964915 °
				-121.833675 °	-121.833675 °
DWR ID					
Action/Comments					
Inspector Comments: FS_ID:28629 DS_ID:20014 EP_NO: 10057 FS_HLM: 26.838 Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: May need proper abandonment. FIELD_STRUCT_DESC: Abandoned 24-inch pipe through levee, 7.1 feet below the crown, slant pump on WS. O&M Manual Sac 128, March 1960. (ABO No. 10057) FS Date: 01/15/2014					

Photo 1 of 2 : UCIP_FA_2015_3267.jpg



LS view: abandoned CMP risers on levee toe.

LM Start	26.52	Rating **	M	Issue No.	2590 (cont)
LM End	26.52	Issue Type +	En	Location *	LS

Photo 2 of 2 : UCIP_FA_2015_3268.jpg



WS view: abandoned 24" and 30" steel pipe on river bank.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2015

Reclamation District No. 1500 Sutter Basin

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	33.15	10/20/2015 10/21/2015	Jai Lor

LM Start	26.52	Rating **	M	Issue No.	2591
LM End	26.52	Issue Type +	En	Location *	LS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			38.964931 °	38.964931 °
				-121.833682 °	-121.833682 °
DWR ID					
Action/Comments					
Inspector Comments: FS_ID:28628 DS_ID:20013 EP_NO: 10057 FS_HLM: 26.84 Repair Type: Non-Urgent Crossing Status: Found					

Photo 1 of 2 : UCIP_FA_2015_3265.jpg



LS view: abandoned CMP risers on levee toe.

LM Start	26.52	Rating **	M	Issue No.	2591 (cont)
LM End	26.52	Issue Type +	En	Location *	LS

Photo 2 of 2 : UCIP_FA_2015_3266.jpg



WS view: abandoned 24" and 30" steel pipe on river bank.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2015

Reclamation District No. 1500 Sutter Basin

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	33.15	10/20/2015 10/21/2015	Jai Lor

LM Start	26.74	Rating **	M	Issue No.	2592
LM End	26.74	Issue Type +	En	Location *	LS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			38.968093 °	38.968093 °
				-121.833708 °	-121.833708 °
DWR ID					
Action/Comments					
Inspector Comments: FS_ID:28631 DS_ID:20015 EP_NO: 10052 FS_HLM: 27.064 Repair Type: Non-Urgent Crossing Status: Found					

Photo 1 of 3 : UCIP_FA_2015_3349.jpg



LS view: siphon breaker in CMP riser on levee slope (bottom) and concrete distribution box on levee toe.

LM Start	26.74	Rating **	M	Issue No.	2592 (cont)
LM End	26.74	Issue Type +	En	Location *	LS

Photo 2 of 3 : UCIP_FA_2015_3350.jpg



WS view: slant pump and gate valves on wooden platform at levee berm. Wooden walkway to the pump.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2015

Reclamation District No. 1500 Sutter Basin

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	33.15	10/20/2015 10/21/2015	Jai Lor

LM Start	26.74	Rating **	M	Issue No.	2592 (cont)
LM End	26.74	Issue Type +	En	Location *	LS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			38.968093 °	38.968093 °
				-121.833708 °	-121.833708 °
DWR ID					
Action/Comments					
Inspector Comments: FS_ID:28631 DS_ID:20015 EP_NO: 10052 FS_HLM: 27.064 Repair Type: Non-Urgent Crossing Status: Found					

Photo 3 of 3 : UCIP_FA_2015_3351.jpg



LS view: obstructed siphon breaker in CMP riser on levee slope.

LM Start	27.29	Rating **	M	Issue No.	983
LM End	27.44	Issue Type +	En	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			38.972440 °	38.972848 °
				-121.825892 °	-121.823098 °
DWR ID	DWR_RD1500_01_s_2015_983				
Action/Comments					
Ditch					

Photo 1 of 2 : FA_2015_RD1500_189_983_20150914_00072.jpg



Agricultural ditch, photo taken in spring 2010.

LM Start	27.29	Rating **	M	Issue No.	983 (cont)
LM End	27.44	Issue Type +	En	Location *	LS

Photo 2 of 2 : FA_2015_RD1500_189_983_20150914_00073.jpg



The agricultural ditch runs along the toe of the levee. Spring 2014

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2015

Reclamation District No. 1500 Sutter Basin

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	33.15	10/20/2015 10/21/2015	Jai Lor

LM Start	28.22	Rating **	M	Issue No.	38
LM End	29.23	Issue Type +	En	Location *	LS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Encroachments		38.983081 °	38.988512 °	
			-121.819924 °	-121.806463 °	
DWR ID	DWR_RD1500_01_s_2012_38				
Action/Comments					
Ditch					

Photo 1 of 2 : FA_2015_RD1500_189_38_20150914_00034.jpg



The agricultural ditch runs along the toe of the levee, photo taken spring 2012.

LM Start	28.22	Rating **	M	Issue No.	38 (cont)
LM End	29.23	Issue Type +	En	Location *	LS

Photo 2 of 2 : FA_2015_RD1500_189_38_20150914_00035.jpg



A current view of the agricultural ditch along the toe. Spring 2014

LM Start	28.95	Rating **	A/W	Issue No.	84
LM End	29.17	Issue Type +	Ma	Location *	WS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Vegetation		38.988078 °	38.988595 °	
			-121.811692 °	-121.807532 °	
DWR ID	DWR_RD1500_01_s_2012_84				
Action/Comments					
Environmental Requirements.					

Photo 1 of 2 : FA_2015_RD1500_189_84_20150914_00059.jpg



A photo of the revegetation site.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2015

Reclamation District No. 1500 Sutter Basin

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	33.15	10/20/2015 10/21/2015	Jai Lor

LM Start	28.95	Rating **	A/W	Issue No.	84 (cont)
LM End	29.17	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.988078 °	38.988595 °
				-121.811692 °	-121.807532 °
DWR ID	DWR_RD1500_01_s_2012_84				
Action/Comments					
Environmental Requirements.					

Photo 2 of 2 : FA_2015_RD1500_189_84_20150914_00060.jpg



Another revegetation site on the waterside berm, photo taken spring 2012.

LM Start	29.91	Rating **	U	Issue No.	2593
LM End	29.91	Issue Type +	En	Location *	WS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			38.993006 °	38.993006 °
				-121.796025 °	-121.796025 °
DWR ID					
Action/Comments					
Inspector Comments: FS_ID:42929 DS_ID:20113 EP_NO: 10054 FS_HLM: 30.289 Repair Type: Urgent Crossing Status: Found UCIP Comments: Levee slope erosion due to leakage from siphon breaker. Water leaking from pipe near distribution box on landside levee toe. Overhead powerline. FIELD_STRUCT_DESC: 2 of 2: 16-inch steel irrigation pipe through levee, 5.0 feet below crown. Siphon breaker in 24-inch CM riser on landward shoulder. 20-inch steel irrigation pipe through levee, 5.0 feet below crown. Siphon breaker in 24-inch CM riser on landward shoulder. Slant pumps in CM pump house mounted on steel pile structure on the berm 4 foot by 7 foot concrete inspection box for Hersey-Sparling water meter on berm in front of pump house. Flap gates in 9.7 foot by 10.6 foot O.D. concrete distribution box at landward toe. (ABO No. 10054 - Larner) O&M Manual Sac 128, March 1960. FS Date: 01/15/2014					

Photo 1 of 3 : UCIP_FA_2015_2965.jpg



LS view: CMPs with leaky siphon breakers. Slope erosion and excessive vegetation on levee slope.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2015

Reclamation District No. 1500 Sutter Basin

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	33.15	10/20/2015 10/21/2015	Jai Lor

LM Start	29.91	Rating **	U	Issue No.	2593 (cont)
LM End	29.91	Issue Type +	En	Location *	WS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			38.993006 °	38.993006 °
				-121.796025 °	-121.796025 °
DWR ID					
Action/Comments					
Inspector Comments: FS_ID:42929 DS_ID:20113 EP_NO: 10054 FS_HLM: 30.289 Repair Type: Urgent Crossing Status: Found UCIP Comments: Levee slope erosion due to leakage from siphon breaker. Water leaking from pipe near distribution box on landside levee toe. Overhead powerline. FIELD_STRUCT_DESC: 2 of 2: 16-inch steel irrigation pipe through levee, 5.0 feet below crown. Siphon breaker in 24-inch CM riser on landward shoulder. 20-inch steel irrigation pipe through levee, 5.0 feet below crown. Siphon breaker in 24-inch CM riser on landward shoulder. Slant pumps in CM pump house mounted on steel pile structure on the berm 4 foot by 7 foot concrete inspection box for Hersey-Sparling water meter on berm in front of pump house. Flap gates in 9.7 foot by 10.6 foot O.D. concrete distribution box at landward toe. (ABO No. 10054 - Larner) O&M Manual Sac 128, March 1960. FS Date: 01/15/2014					

Photo 2 of 3 : UCIP_FA_2015_2966.jpg



WS view: two slant pumps on wooden platform on levee berm.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2015

Reclamation District No. 1500 Sutter Basin

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	33.15	10/20/2015 10/21/2015	Jai Lor

LM Start	29.91	Rating **	U	Issue No.	2593 (cont)
LM End	29.91	Issue Type +	En	Location *	WS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			38.993006 °	38.993006 °
				-121.796025 °	-121.796025 °
DWR ID					
Action/Comments					
Inspector Comments: FS_ID:42929 DS_ID:20113 EP_NO: 10054 FS_HLM: 30.289 Repair Type: Urgent Crossing Status: Found UCIP Comments: Levee slope erosion due to leakage from siphon breaker. Water leaking from pipe near distribution box on landside levee toe. Overhead powerline. FIELD_STRUCT_DESC: 2 of 2: 16-inch steel irrigation pipe through levee, 5.0 feet below crown. Siphon breaker in 24-inch CM riser on landward shoulder. 20-inch steel irrigation pipe through levee, 5.0 feet below crown. Siphon breaker in 24-inch CM riser on landward shoulder. Slant pumps in CM pump house mounted on steel pile structure on the berm 4 foot by 7 foot concrete inspection box for Hersey-Sparling water meter on berm in front of pump house. Flap gates in 9.7 foot by 10.6 foot O.D. concrete distribution box at landward toe. (ABO No. 10054 - Larner) O&M Manual Sac 128, March 1960. FS Date: 01/15/2014					

Photo 3 of 3 : UCIP_FA_2015_3396.jpg



LS view: siphon breakers in CMP riser on levee slope and distribution box on levee toe.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2015

Reclamation District No. 1500 Sutter Basin

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	33.15	10/20/2015 10/21/2015	Jai Lor

LM Start	29.91	Rating **	U	Issue No.	2594
LM End	29.91	Issue Type +	En	Location *	WS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			38.993006 °	38.993006 °
				-121.796025 °	-121.796025 °
DWR ID					

Photo 1 of 3 : UCIP_FA_2015_3393.jpg



Action/Comments

Inspector Comments: FS_ID:42930
 DS_ID:20084
 EP_NO: 10054
 FS_HLM: 30.28
 Repair Type: Urgent
 Crossing Status: Found
 UCIP Comments: Levee slope erosion due to leakage from siphon breaker. Water leaking from pipe near distribution box on landside levee toe. Overhead powerline.
 FIELD_STRUCT_DESC: 1 of 2: 20-inch steel irrigation pipe through levee, 5.0 feet below crown. Siphon breaker in 24-inch CM riser on landward slope. Another 16-inch steel irrigation pipe through levee, 5.0 feet below crown. Siphon breaker in 24-inch CM riser on landward shoulder. Slant pumps in CM pump house mounted on steel pile structure on the berm. A 4 foot by 7 foot concrete inspection box for Hersey-Sparling water meter on berm in front of pump house. Flap gates in 9.7 foot by 10.6 foot O.D. concrete distribution box at landward toe. (ABO No. 10054 - Larner) O&M Manual Sac 128, March 1960.
 FS Date: 01/15/2014

LS view: obstructed and leaky siphon breaker in CMP riser on levee slope.

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	--	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2015

Reclamation District No. 1500 Sutter Basin

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	33.15	10/20/2015 10/21/2015	Jai Lor

LM Start	29.91	Rating **	U	Issue No.	2594 (cont)
LM End	29.91	Issue Type +	En	Location *	WS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			38.993006 °	38.993006 °
				-121.796025 °	-121.796025 °
DWR ID					

Photo 2 of 3 : UCIP_FA_2015_3394.jpg



Action/Comments

Inspector Comments: FS_ID:42930
 DS_ID:20084
 EP_NO: 10054
 FS_HLM: 30.28
 Repair Type: Urgent
 Crossing Status: Found
 UCIP Comments: Levee slope erosion due to leakage from siphon breaker. Water leaking from pipe near distribution box on landside levee toe. Overhead powerline.
 FIELD_STRUCT_DESC: 1 of 2: 20-inch steel irrigation pipe through levee, 5.0 feet below crown. Siphon breaker in 24-inch CM riser on landward slope. Another 16-inch steel irrigation pipe through levee, 5.0 feet below crown. Siphon breaker in 24-inch CM riser on landward shoulder. Slant pumps in CM pump house mounted on steel pile structure on the berm. A 4 foot by 7 foot concrete inspection box for Hersey-Sparling water meter on berm in front of pump house. Flap gates in 9.7 foot by 10.6 foot O.D. concrete distribution box at landward toe. (ABO No. 10054 - Larner) O&M Manual Sac 128, March 1960.
 FS Date: 01/15/2014

LS view: siphon breakers in CMP riser on levee slope and distribution box on levee toe.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
---	--	--	---

**Flood Control Project Maintenance
Levee Inspections**


Levee Inspection Report By Mile - Fall 2015

Reclamation District No. 1500 Sutter Basin

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	33.15	10/20/2015 10/21/2015	Jai Lor

LM Start	29.91	Rating **	U	Issue No.	2594 (cont)
LM End	29.91	Issue Type +	En	Location *	WS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			38.993006 °	38.993006 °
				-121.796025 °	-121.796025 °
DWR ID					
Action/Comments					
Inspector Comments: FS_ID:42930 DS_ID:20084 EP_NO: 10054 FS_HLM: 30.28 Repair Type: Urgent Crossing Status: Found UCIP Comments: Levee slope erosion due to leakage from siphon breaker. Water leaking from pipe near distribution box on landside levee toe. Overhead powerline. FIELD_STRUCT_DESC: 1 of 2: 20-inch steel irrigation pipe through levee, 5.0 feet below crown. Siphon breaker in 24-inch CM riser on landward slope. Another 16-inch steel irrigation pipe through levee, 5.0 feet below crown. Siphon breaker in 24-inch CM riser on landward shoulder. Slant pumps in CM pump house mounted on steel pile structure on the berm. A 4 foot by 7 foot concrete inspection box for Hersey-Sparling water meter on berm in front of pump house. Flap gates in 9.7 foot by 10.6 foot O.D. concrete distribution box at landward toe. (ABO No. 10054 - Larner) O&M Manual Sac 128, March 1960. FS Date: 01/15/2014					

Photo 3 of 3 : UCIP_FA_2015_3395.jpg



WS view: slant pumps and control boxes on steel platform at levee berm.

LM Start	30.07	Rating **	U	Issue No.	2595
LM End	30.07	Issue Type +	En	Location *	WS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			38.994988 °	38.994988 °
				-121.794484 °	-121.794484 °
DWR ID					
Action/Comments					
Inspector Comments: FS_ID:28163 DS_ID:20107 EP_NO: 6169 FS_HLM: 30.452 Repair Type: Urgent Crossing Status: Found UCIP Comments: Leaky pump and excessive vegetation observed along pipe alignment on waterside slope of the levee. It needs more investigations. May have new permit for slant pump. FIELD_STRUCT_DESC: 30-inch reinforced concrete encased steel irrigation pipe through levee, 15.5 feet below crown. Slant pump and switch panel on steel pile structure at edge of berm. Slide gate in 2.5 foot by 3.5 foot I.D. concrete box on berm. 6 foot by 8 foot concrete distribution box at landward toe. 2-inch conduit through levee, 2.5 feet below crown. (App. No. 6169 - Butler) Pipe through levee was initially installed in 1952. O&M Manual Sac 128, March 1960. FS Date: 01/15/2014					

Photo 1 of 3 : UCIP_FA_2015_3341.jpg



WS view: excessive vegetation along pipe alignment on levee slope.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2015

Reclamation District No. 1500 Sutter Basin

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	33.15	10/20/2015 10/21/2015	Jai Lor

LM Start	30.07	Rating **	U	Issue No.	2595 (cont)
LM End	30.07	Issue Type +	En	Location *	WS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			38.994988 °	38.994988 °
DWR ID				-121.794484 °	-121.794484 °
Action/Comments					
Inspector Comments: FS_ID:28163 DS_ID:20107 EP_NO: 6169 FS_HLM: 30.452 Repair Type: Urgent Crossing Status: Found UCIP Comments: Leaky pump and excessive vegetation observed along pipe alignment on waterside slope of the levee. It needs more investigations. May have new permit for slant pump. FIELD_STRUCT_DESC: 30-inch reinforced concrete encased steel irrigation pipe through levee, 15.5 feet below crown. Slant pump and switch panel on steel pile structure at edge of berm. Slide gate in 2.5 foot by 3.5 foot I.D. concrete box on berm. 6 foot by 8 foot concrete distribution box at landward toe. 2-inch conduit through levee, 2.5 feet below crown. (App. No. 6169 - Butler) Pipe through levee was initially installed in 1952. O&M Manual Sac 128, March 1960. FS Date: 01/15/2014					

Photo 2 of 3 : UCIP_FA_2015_3342.jpg



WS view: concrete surge box with slide gate on levee berm.

LM Start	30.07	Rating **	U	Issue No.	2595 (cont)
LM End	30.07	Issue Type +	En	Location *	WS

Photo 3 of 3 : UCIP_FA_2015_3343.jpg



WS view: leaky slant pump on levee berm.

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	--	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2015

Reclamation District No. 1500 Sutter Basin

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	33.15	10/20/2015 10/21/2015	Jai Lor

LM Start	30.21	Rating **	M	Issue No.	45
LM End	30.21	Issue Type +	En	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.996980 °	38.996980 °
				-121.794723 °	-121.794723 °
DWR ID	DWR_RD1500_01_s_2012_45				
Action/Comments					
Landscaping					

Photo 1 of 1 : FA_2015_RD1500_189_45_20150914_00037.jpg



The groundcover in the landscape makes it hard to see the levee slope.

LM Start	30.60	Rating **	M	Issue No.	22
LM End	30.75	Issue Type +	Ma	Location *	WS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	2015 USACE Erosion Survey, DRAFT			38.999745 °	39.001413 °
				-121.800898 °	-121.802889 °
DWR ID					
Action/Comments					
Inspector Comments: 2000 - Eroding, vertical berm slope over a vertical cohesive toe; slow erosion but getting close to the toe. 2002 - Erosion is getting close to the levee, still eroding with some new small slumps. 2004 - Some minor new erosion. 2006 - Some new erosion, cleaned off older scars and slump faces. 2008 - New, small, partial rotational failure. 2011 - Some new minor erosion. 2015: No observed changes. [2015 Site ID: SAC_116-0_L]					

Photo 1 of 1 : USACE2013A_SAC_116-0_L_4.jpg



USACE 2013 Photo #1

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2015

Reclamation District No. 1500 Sutter Basin

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	33.15	10/20/2015 10/21/2015	Jai Lor

LM Start	30.87	Rating **	M	Issue No.	2596
LM End	30.87	Issue Type +	En	Location *	WS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			39.002960 °	39.002960 °
				-121.803736 °	-121.803736 °
DWR ID					

Action/Comments

Inspector Comments: FS_ID:28144
 DS_ID:20000
 EP_NO: 15916
 FS_HLM: 31.261
 Repair Type: Non-Urgent
 Crossing Status: Found
 UCIP Comments: Surface erosion due to leaky pressure breaker on landside slope.
 FIELD_STRUCT_DESC: 18-inch steel irrigation pipe through levee. Siphon breaker in 24-inch CM riser on landward slope. Discharges into 6 foot by 8 foot I.D. concrete distribution box at landward toe. (App. No. 15916 - Butler) 18-inch replaced original 12-inch pipe (10034 - Butler)
 FS Date: 01/15/2014

LM Start	30.87	Rating **	M	Issue No.	2596 (cont)
LM End	30.87	Issue Type +	En	Location *	WS

Photo 1 of 2 : UCIP_FA_2015_3339.jpg



LS view: obstructed and leaked pressure breaker in CMP on levee slope.

Photo 2 of 2 : UCIP_FA_2015_3340.jpg



WS view: pump in CM pump house on levee shoulder. Looks abandoned.

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
N/A : Not Applicable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2015

Reclamation District No. 1500 Sutter Basin

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	33.15	10/20/2015 10/21/2015	Jai Lor

LM Start	30.94	Rating **	M	Issue No.	15
LM End	31.60	Issue Type +	Ma	Location *	WS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	2015 USACE Erosion Survey, DRAFT			39.003301 °	39.006072 °
				-121.805024 °	-121.815926 °
DWR ID					
Action/Comments					
Inspector Comments: 2003 - New sedimentation and some new small toe scallops at the upstream end; downstream end has some new erosion. 2004 - Some new erosion at the toe and upper bank and some small new rotational failures (mainly minor, except at the downstream end). 2007 - Some new slumps. 2009 - Some new scallops and site was extended upstream. 2010 - New deposition along					

Photo 1 of 1 : USACE2013A_SAC_116-5_L_10.jpg



USACE 2013 Photo #1

LM Start	31.53	Rating **	A/W	Issue No.	86
LM End	31.53	Issue Type +	En	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Underseepage Relief Wells			39.006722 °	39.006722 °
				-121.814752 °	-121.814752 °
DWR ID	DWR_RD1500_01_s_2012_86				
Action/Comments					

Photo 1 of 1 : FA_2015_RD1500_189_86_20150914_00061.jpg



The control unit for pizometers installed in 2012, photo taken spring 2012.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2015

Reclamation District No. 1500 Sutter Basin

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	33.15	10/20/2015 10/21/2015	Jai Lor

LM Start	31.61	Rating **	M	Issue No.	2597
LM End	31.61	Issue Type +	En	Location *	WS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			39.006484 °	39.006484 °
				-121.816168 °	-121.816168 °
DWR ID					
Action/Comments					
Inspector Comments: FS_ID:28143 DS_ID:20077 EP_NO: 9657 FS_HLM: 32.018 Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: Looks abandoned. May need proper abandonment. Overhead power line. FIELD_STRUCT_DESC: Abandoned 20-inch diameter steel pipe through levee, 15.0 feet below crown. Pump on elevated structure. Slide gate in riser, concrete surge box on waterward slope. Switch panel on berm. (App. Nos. 13536 & 13941 - Niechen 10/82) Discharges into 36-inch I.D. concrete standpipe on landward side. (App. No. 9657 ABO No. 10030 - Bell) O&M Manual Sac 128, March 1960. FS Date: 01/15/2014					

Photo 1 of 3 : UCIP_FA_2015_3297.jpg



LS view: concrete standpipe on levee toe.

LM Start	31.61	Rating **	M	Issue No.	2597 (cont)
LM End	31.61	Issue Type +	En	Location *	WS

Photo 2 of 3 : UCIP_FA_2015_3298.jpg



WS view: abandoned walkway, pipe, and pump on river bank.

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	--	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2015

Reclamation District No. 1500 Sutter Basin

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	33.15	10/20/2015 10/21/2015	Jai Lor

LM Start	31.61	Rating **	M	Issue No.	2597 (cont)
LM End	31.61	Issue Type +	En	Location *	WS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			39.006484 °	39.006484 °
				-121.816168 °	-121.816168 °
DWR ID					
Action/Comments					
Inspector Comments: FS_ID:28143 DS_ID:20077 EP_NO: 9657 FS_HLM: 32.018 Repair Type: Non-Urgent Crossing Status: Found					

Photo 3 of 3 : UCIP_FA_2015_3299.jpg



WS view: concrete surge box on levee slope.

LM Start	32.42	Rating **	M	Issue No.	60
LM End	32.58	Issue Type +	En	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			39.013720 °	39.015640 °
				-121.825038 °	-121.823397 °
DWR ID	DWR_RD1500_01_s_2012_60				
Action/Comments					
Ditch					

Photo 1 of 1 : FA_2015_RD1500_189_60_20150914_00046.jpg



Older, unused agricultural ditch. Tree stump needs to be removed.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	--	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2015

Reclamation District No. 1500 Sutter Basin

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	33.15	10/20/2015 10/21/2015	Jai Lor

LM Start	32.55	Rating **	M	Issue No.	2598
LM End	32.55	Issue Type +	En	Location *	LS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			39.015277 °	39.015277 °
				-121.823735 °	-121.823735 °
DWR ID					
Action/Comments					
Inspector Comments: FS_ID:28943 DS_ID:20018 EP_NO: N/A FS_HLM: 32.969 Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: Pipe leaks near pump through a hole in the pipe. Needs repair. An electric conduit through the levee. Concrete distribution box on landside levee toe. Slide gate in CMP on waterside slope. FIELD_STRUCT_DESC: 30-inch pipe and electric conduit through levee, 14.3 feet below the crown, Pump and headwall on waterside. Slide gate in CMP on waterside slope. Electric control box on waterside. Concrete distribution box on landside levee toe. O&M Manual Sac 128, March 1960. FS Date: 01/15/2014					

Photo 1 of 3 : UCIP_FA_2015_3458.jpg



LS view: steel pipe in concrete distribution box on levee toe.

LM Start	32.55	Rating **	M	Issue No.	2598 (cont)
LM End	32.55	Issue Type +	En	Location *	LS

Photo 2 of 3 : UCIP_FA_2015_3459.jpg



WS view: pump on river bank protected by concrete headwall. Leaky pipe near pump.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2015

Reclamation District No. 1500 Sutter Basin

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	33.15	10/20/2015 10/21/2015	Jai Lor

LM Start	32.55	Rating **	M	Issue No.	2598 (cont)
LM End	32.55	Issue Type +	En	Location *	LS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			39.015277 °	39.015277 °
				-121.823735 °	-121.823735 °
DWR ID					
Action/Comments					
Inspector Comments: FS_ID:28943 DS_ID:20018 EP_NO: N/A FS_HLM: 32.969 Repair Type: Non-Urgent Crossing Status: Found					

Photo 3 of 3 : UCIP_FA_2015_3460.jpg



WS view: power control panel and CMP riser with slide gate on levee slope.

LM Start	32.84	Rating **	M	Issue No.	104
LM End	32.84	Issue Type +	En	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			39.018848 °	39.018848 °
				-121.820761 °	-121.820761 °
DWR ID	DWR_RD1500_01_f_2015_104				
Action/Comments					
Debris					

Photo 1 of 1 : FA_2015_RD1500_189_104_20151026_00136.jpg



View of the abandoned pipe on the waterward side of the levee looking upstream. Fall 2015.

LM Start	32.96	Rating **	M	Issue No.	46
LM End	32.96	Issue Type +	En	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			39.020550 °	39.020550 °
				-121.820315 °	-121.820315 °
DWR ID	DWR_RD1500_01_s_2012_46				
Action/Comments					
Building					

Photo 1 of 1 : FA_2015_RD1500_189_46_20150914_00038.jpg



The building is within the easement of the levee toe.

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	--	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2015

Reclamation District No. 1500 Sutter Basin

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	33.15	10/20/2015 10/21/2015	Jai Lor

LM Start	33.13	Rating **	M	Issue No.	2599 (cont)
LM End	33.13	Issue Type +	En	Location *	LS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			39.022938 °	39.022938 °
				-121.820717 °	-121.820717 °
DWR ID					
Action/Comments					
Inspector Comments: FS_ID:28953 DS_ID:20080 EP_NO: 5617 FS_HLM: 33.563 Repair Type: Non-Urgent Crossing Status: Found					

Photo 3 of 3 : UCIP_FA_2015_3484.jpg



WS view: slant pumps on steel platform in shed on berm.

LM Start	33.13	Rating **	M	Issue No.	2600
LM End	33.13	Issue Type +	En	Location *	LS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			39.022956 °	39.022956 °
				-121.820716 °	-121.820716 °
DWR ID					
Action/Comments					
Inspector Comments: FS_ID:28952 DS_ID:24758 EP_NO: N/A FS_HLM: 33.564 Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: Not found- slide gate in 54 inch corrugated metal riser on waterside berm.Two 16-inch steel pipes (looks new). Leaky pipe near pump.Plant was working during field visit.Needs more info from LMA. There may be a new permit. FIELD_STRUCT_DESC: 2 of 2. Two 16-inch steel irrigation pipe through the levee. Two slant pumps on steel platform and under the shed. Two air vents on waterside levee shoulder. Two pipes with gate valves discharge water into irrigation ditch. Service pole on landside toe. Previously only a 30-inch steel pipe through the levee and slide gate in CMP riser on waterside. FS Date: 01/15/2014					

Photo 1 of 3 : UCIP_FA_2015_3461.jpg



WS view: oil and water leakage from pipe near pump.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable N : Not Inspected/Rated M : Minimally Acceptable C : Corrected U : Unacceptable A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
---	--	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2015

Reclamation District No. 1500 Sutter Basin

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	33.15	10/20/2015 10/21/2015	Jai Lor

LM Start	33.13	Rating **	M	Issue No.	2600 (cont)
LM End	33.13	Issue Type +	En	Location *	LS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			39.022956 °	39.022956 °
				-121.820716 °	-121.820716 °
DWR ID					
Action/Comments					
Inspector Comments: FS_ID:28952 DS_ID:24758 EP_NO: N/A FS_HLM: 33.564 Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: Not found- slide gate in 54 inch corrugated metal riser on waterside berm.Two 16-inch steel pipes (looks new). Leaky pipe near pump.Plant was working during field visit.Needs more info from LMA. There may be a new permit. FIELD_STRUCT_DESC: 2 of 2. Two 16-inch steel irrigation pipe through the levee. Two slant pumps on steel platform and under the shed. Two air vents on waterside levee shoulder. Two pipes with gate valves discharge water into irrigation ditch. Service pole on landside toe. Previously only a 30-inch steel pipe through the levee and slide gate in CMP riser on waterside. FS Date: 01/15/2014					

Photo 2 of 3 : UCIP_FA_2015_3462.jpg



WS view: two slant pumps on steel platform at waterside berm.

LM Start	33.13	Rating **	M	Issue No.	2600 (cont)
LM End	33.13	Issue Type +	En	Location *	LS

Photo 3 of 3 : UCIP_FA_2015_3463.jpg



WS view: pump platform and shed on levee berm.

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	--	---

**Flood Control Project Maintenance
Levee Inspections**

Unit Cover Sheet

Fall 2015 Levee Inspection Results

Reclamation District No. 1500 Sutter Basin

Waterway		Bank	Unit Miles	
Unit No. 02 Sutter Bypass		Right	20.72	
	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - February)
Unit Maintenance Rating (Fall Only)			A	
Date of Inspection	05/14/2015 - 05/14/2015		10/20/2015 - 10/20/2015	
DWR Inspector	Jai Lor		Jai Lor	
Accompanied By				

Summer & Winter Inspections

The Local Maintaining Agency (LMA) is responsible for summer and winter inspections. The LMA is required to submit a report regarding summer and winter inspections to the California Department of Water Resources (DWR).

DWR must be informed on the:

- a) completion of the inspection
- b) any changes other than the results of normal maintenance
- c) corrections to deficiencies noted in this report

If additional items are noted, further documentation of those items must also be submitted.

The LMA should submit this information to DWR using the LMA web application tool available at:

<http://cdec.water.ca.gov/lma.html>

If the LMA is unable to submit information on this webpage, please contact DWR for assistance.

The LMA should submit the information and any associated documentation by September 30 for summer inspections and March 31 for winter inspections.

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2015

Reclamation District No. 1500 Sutter Basin

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Sutter Bypass	Right	20.72	10/20/2015 10/20/2015	Jai Lor

LM Start	0.00	Rating **	M	Issue No.	12
LM End	0.00	Issue Type +	Ma	Location *	WS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Encroachments		38.761121 °	38.761121 °	
			-121.674592 °	-121.674592 °	
DWR ID	DWR_RD1500_02_s_2012_12				
Action/Comments					
Equipment					

Photo 1 of 2 : FA_2015_RD1500_190_12_20150914_00005.jpg



Farm equipment is parked on the levee slope. Photo fall 2012.

LM Start	0.00	Rating **	M	Issue No.	12 (cont)
LM End	0.00	Issue Type +	Ma	Location *	WS

Photo 2 of 2 : FA_2015_RD1500_190_12_20150914_00006.jpg



Farm equipment is on the levee crown. Spring 2014

LM Start	0.16	Rating **	C	Issue No.	302
LM End	1.85	Issue Type +	Ma	Location *	CR
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Vegetation		38.762750 °	38.782985 °	
			-121.672501 °	-121.655599 °	
DWR ID	DWR_RD1500_02_s_2014_302				
Action/Comments					
Keep the crown roadway free of vegetation.					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2015

Reclamation District No. 1500 Sutter Basin

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Sutter Bypass	Right	20.72	10/20/2015 10/20/2015	Jai Lor

LM Start	2.03	Rating **	C	Issue No.	587
LM End	3.12	Issue Type +	Ma	Location *	CR
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Vegetation		38.785438 °	38.800998 °	
			-121.654603 °	-121.656246 °	
DWR ID	DWR_RD1500_02_s_2015_587				
Action/Comments					
Keep the crown roadway free of vegetation.					

No Photos

LM Start	14.13	Rating **	A/W	Issue No.	4
LM End	14.13	Issue Type +	Ma	Location *	LS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Underseepage Relief Wells		38.947582 °	38.947582 °	
			-121.669740 °	-121.669740 °	
DWR ID	DWR_RD1500_02_s_2012_4				
Action/Comments					

Photo 1 of 1 : FA_2015_RD1500_190_4_20151026_00018.jpg



View of the relief well at historical boil 12. Fall 2015.

LM Start	14.31	Rating **	C	Issue No.	10
LM End	14.31	Issue Type +	Ma	Location *	LS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Underseepage Relief Wells		38.949640 °	38.949640 °	
			-121.671947 °	-121.671947 °	
DWR ID	DWR_RD1500_02_s_2012_10				
Action/Comments					
Inspector Comments: Fall 2013, work has been done on the seepage well. Unsure if it operates properly. Spring 2014 unable to find may have been removed. Fall 2015 well has been removed and grouted. A slurry wall has been placed on the waterward side.					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2015

Reclamation District No. 1500 Sutter Basin

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Sutter Bypass	Right	20.72	10/20/2015 10/20/2015	Jai Lor

LM Start	18.19	Rating **	C	Issue No.	584
LM End	18.19	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			38.987247 °	38.987247 °
				-121.725271 °	-121.725271 °
DWR ID	DWR_RD1500_02_s_2015_584				
Action/Comments					
Tree or limb Inspector Comments: A tree broke and fell onto the waterward side of the levee.					

No Photos

LM Start	18.41	Rating **	A/W	Issue No.	15
LM End	18.41	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Underseepage Relief Wells			38.989813 °	38.989813 °
				-121.727763 °	-121.727763 °
DWR ID	DWR_RD1500_02_s_2015_15				
Action/Comments					

Photo 1 of 1 : FA_2015_RD1500_190_15_20151026_00014.jpg



View of the toe drainage at the landward toe berm. Fall 2015.

LM Start	18.60	Rating **	M	Issue No.	1
LM End	18.60	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			38.992105 °	38.992105 °
				-121.729615 °	-121.729615 °
DWR ID	DWR_RD1500_02_f_2015_1				
Action/Comments					
Tree or limb					

Photo 1 of 1 : FA_2015_RD1500_190_1_20151026_00013.jpg



View of the fallen tree on the waterward side of the levee looking downstream. Fall 2015.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable N : Not Inspected/Rated M : Minimally Acceptable C : Corrected U : Unacceptable A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
---	--	---