

**Flood Control Project Maintenance
Levee Inspections**
LMA District Cover Sheet
Spring 2009 Levee Inspection Results

Reclamation District No. 1500

	Spring (March - May)	Summer ** (June - August)	Fall (September - November)	Winter ** (December - February)
* Overall LMA Rating (Fall Only)				

** Non-receipt of Summer or Winter Inspection Reports may effect overall annual rating.

* **SPRING INSPECTIONS:** Overall maintenance ratings are not determined for the spring inspection results. Individual maintenance deficiencies are rated using the same criteria in the spring and in the fall.

FALL INSPECTIONS: The overall maintenance rating shown above is based on operation and maintenance deficiencies identified within the attached unit inspection reports.

Comments

**Flood Control Project Maintenance
Levee Inspections
Unit Cover Sheet
Spring 2009 Levee Inspection Results
Reclamation District No. 1500**

Waterway		Bank	Unit Miles
Unit No. 01 Sacramento River		Left	33.60

	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - February)
Unit Maintenance Rating (Fall Only)				
Date of Inspection	4/6/2009 - 4/6/2009			
DWR Inspector	John Williamson			
Accompanied By				

Check one:

During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.

During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

Comments

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :

DWR Summer/Winter Inspection Reports
3310 El Camino Avenue, Room LL-30
Sacramento, CA 95821-9000.

X _____
Signature of LMA Representative Date

**Flood Control Project Maintenance
Levee Inspections
Levee Inspection Report By Mile - Spring 2009**

Reclamation District No. 1500

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	33.60	04/06/2009 04/06/2009	John Williamson

LMR Line	Levee Mile		Category	Item	Location *	Rating **	Action/Comment	GPS Latitude/Longitude		Photo	Issue
	Start	End						Start	End		
1	0.03	0.03	Earthen Levee	Animal Control	LS	M	Exterminate rodents and backfill and compact or grout burrows.	38.761042 ° -121.675018 °	38.761042 ° -121.675018 °		959
2	0.51	0.51	Earthen Levee	Animal Control	LS	M	Exterminate rodents and backfill and compact or grout burrows.	38.764484 ° -121.681848 °	38.764484 ° -121.681848 °		960
3	1.31	1.31	Earthen Levee	Encroachments	WS	PO	Buildings Inspector Comments: pump house	38.769712 ° -121.691055 °	38.769712 ° -121.691055 °		3
4	1.34	1.34	Earthen Levee	Encroachments	LS	PO	Landscaping	38.769983 ° -121.690610 °	38.769983 ° -121.690610 °		4
5	1.45	1.45	Earthen Levee	Encroachments	WS	M	Prunings	38.770871 ° -121.688879 °	38.770871 ° -121.688879 °		961
6	2.23	3.85	Earthen Levee	Vegetation	WS	M	Control annual grass and weeds on the levee slopes and easements.	38.780867 ° -121.686911 °	38.797184 ° -121.693460 °		962
7	2.57	3.83	Earthen Levee	Encroachments	LS	PO	Agricultural Ditch	38.785351 ° -121.689075 °	38.797174 ° -121.693045 °	Y	963
8	2.60	3.63	Earthen Levee	Crown Surface / Depressions / Rutting	CR	M	Keep the crown roadway free of vegetation.	38.785684 ° -121.688634 °	38.796300 ° -121.689733 °		964
9	2.63	3.85	Earthen Levee	Vegetation	LS	M	Control annual grass and weeds on the levee slopes and easements.	38.785835 ° -121.688198 °	38.797185 ° -121.693460 °		965
10	3.73	3.73	Earthen Levee	Encroachments	WS	PO	Buildings	38.797139 ° -121.691137 °	38.797139 ° -121.691137 °		6
11	3.99	3.99	Earthen Levee	Encroachments	LS	PO	Buildings	38.797597 ° -121.695775 °	38.797597 ° -121.695775 °		7
12	4.01	4.01	Earthen Levee	Encroachments	LS	PO	Landscaping	38.797827 ° -121.695985 °	38.797827 ° -121.695985 °		8
13	4.03	4.03	Earthen Levee	Encroachments	WS	PO	Buildings Inspector Comments: pump house concrete building	38.798048 ° -121.696148 °	38.798048 ° -121.696148 °		9
14	4.03	4.03	Earthen Levee	Encroachments	LS	PO	Buildings	38.798048 ° -121.696150 °	38.798048 ° -121.696150 °		10
15	4.07	4.17	Earthen Levee	Encroachments	LS	PO	Agricultural Ditch	38.798641 ° -121.696344 °	38.800108 ° -121.696635 °	Y	966
16	4.20	4.20	Earthen Levee	Encroachments	LS	PO	Buildings	38.800550 ° -121.696752 °	38.800550 ° -121.696752 °		11
17	4.65	4.65	Earthen Levee	Encroachments	LS	PO	Landscaping	38.803632 ° -121.702770 °	38.803632 ° -121.702770 °		12

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected C : Corrected
--	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2009

Reclamation District No. 1500

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	33.60	04/06/2009 04/06/2009	John Williamson

LMR Line	Levee Mile		Category	Item	Location	Rating	Action/Comment	GPS Latitude/Longitude		Photo	Issue
	Start	End						Start	End		
18	5.24	5.24	Earthen Levee	Encroachments	WS	PO	Buildings Inspector Comments: pump house	38.802328 ° -121.712920 °	38.802328 ° -121.712920 °		13
19	5.39	5.39	Earthen Levee	Encroachments	LS	CO	Landscaping	38.803273 ° -121.715325 °	38.803273 ° -121.715325 °		14
20	5.67	5.75	Earthen Levee	Encroachments	WS	PO	Buildings Inspector Comments: String Rayz Beach Boardwalk Marina waterside berm	38.803005 ° -121.720380 °	38.803238 ° -121.721847 °		52
21	5.75	15.00	Earthen Levee	Vegetation	LS	M	Control annual grass and weeds on the levee slopes and easements.	38.803231 ° -121.721755 °	38.864105 ° -121.791412 °		967
22	5.75	15.00	Earthen Levee	Vegetation	WS	M	Control annual grass and weeds on the levee slopes and easements.	38.803231 ° -121.721755 °	38.864102 ° -121.791412 °		968
23	7.57	7.57	Earthen Levee	Encroachments	LS	PO	Equipment	38.828975 ° -121.724265 °	38.828975 ° -121.724265 °		16
24	7.68	7.68	Earthen Levee	Encroachments	LS	PO	Landscaping	38.830200 ° -121.725268 °	38.830200 ° -121.725268 °		17
25	8.36	8.55	Boat Survey	Boat Survey Erosion	LS	M	Inspector Comments: none	38.840416 ° -121.726865 °	38.838826 ° -121.730175 °		954
26	8.82	8.82	Earthen Levee	Encroachments	LS	PO	Buildings	38.842715 ° -121.726353 °	38.842715 ° -121.726353 °		18
27	11.42	11.42	Earthen Levee	Encroachments	LS	PO	Landscaping	38.866555 ° -121.746017 °	38.866555 ° -121.746017 °		20
28	11.93	11.93	Earthen Levee	Erosion / Bank Caving	WS	M	Note and monitor erosion site.	38.871972 ° -121.749765 °	38.871972 ° -121.749765 °		55
29	12.15	12.15	Earthen Levee	Encroachments	WS	PO	Buildings	38.870562 ° -121.753335 °	38.870562 ° -121.753335 °		23
30	12.31	12.31	Earthen Levee	Erosion / Bank Caving	WS	M	Note and monitor erosion site. Inspector Comments: wide berm	38.869700 ° -121.755945 °	38.869700 ° -121.755945 °		50
31	12.55	12.55	Earthen Levee	Encroachments	LS	PO	Equipment	38.868717 ° -121.760133 °	38.868717 ° -121.760133 °		24
32	12.93	12.93	Earthen Levee	Encroachments	CR	PO	Equipment	38.865127 ° -121.765157 °	38.865127 ° -121.765157 °		25
33	13.12	13.12	Earthen Levee	Encroachments	LS	CO	Buildings	38.863547 ° -121.767937 °	38.863547 ° -121.767937 °		26
34	14.09	14.09	Earthen Levee	Encroachments	WS	M	Firewood	38.857683 ° -121.782652 °	38.857683 ° -121.782652 °		27

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected C : Corrected
--	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2009

Reclamation District No. 1500

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	33.60	04/06/2009 04/06/2009	John Williamson

LMR Line	Levee Mile		Category	Item	Location	Rating	Action/Comment	GPS Latitude/Longitude		Photo	Issue
	Start	End						Start	End		
35	14.13	14.13	Earthen Levee	Encroachments	WS	PO	Equipment	38.857792 ° -121.783265 °	38.857792 ° -121.783265 °		28
36	14.13	14.43	Boat Survey	Boat Survey Erosion	WS	M	Inspector Comments: wide berm	38.861888 ° -121.784083 °	38.857441 ° -121.783918 °		955
37	14.35	14.35	Earthen Levee	Encroachments	LS	CO	Buildings	38.860848 ° -121.783307 °	38.860848 ° -121.783307 °		30
38	14.39	14.39	Earthen Levee	Encroachments	LS	CO	Landscaping	38.861513 ° -121.783588 °	38.861513 ° -121.783588 °		31
39	14.86	15.93	Earthen Levee	Encroachments	LS	PO	Agricultural Ditch	38.865473 ° -121.789413 °	38.871752 ° -121.804257 °	Y	969
40	15.94	15.94	Earthen Levee	Encroachments	WS	PO	Equipment	38.871960 ° -121.804440 °	38.871960 ° -121.804440 °		32
41	16.47	16.47	Earthen Levee	Encroachments	LS	CO	Landscaping	38.875788 ° -121.812268 °	38.875788 ° -121.812268 °		33
42	16.53	16.53	Earthen Levee	Encroachments	LS	M	Debris	38.876545 ° -121.812963 °	38.876545 ° -121.812963 °		53
43	16.54	16.54	Earthen Levee	Animal Control	LS	M	Exterminate rodents and backfill and compact or grout burrows.	38.876668 ° -121.812937 °	38.876668 ° -121.812937 °		970
44	16.61	18.27	Earthen Levee	Vegetation	WS	M	Control annual grass and weeds on the levee slopes and easements.	38.877552 ° -121.813492 °	38.897710 ° -121.802158 °		971
45	16.86	17.45	Earthen Levee	Encroachments	LS	PO	Agricultural Ditch	38.881092 ° -121.813713 °	38.887335 ° -121.808187 °	Y	972
46	17.08	18.27	Earthen Levee	Vegetation	LS	M	Control annual grass and weeds on the levee slopes and easements.	38.884175 ° -121.813517 °	38.897707 ° -121.802157 °		973
47	18.21	18.21	Earthen Levee	Encroachments	LS	C	Prunings	38.896933 ° -121.802515 °	38.896933 ° -121.802515 °		35
48	18.51	18.51	Earthen Levee	Erosion / Bank Caving	WS	M	Note and monitor erosion site.	38.901140 ° -121.802750 °	38.901140 ° -121.802750 °		51
49	19.19	19.19	Earthen Levee	Encroachments	LS	PO	Buildings	38.901570 ° -121.791235 °	38.901570 ° -121.791235 °		36
50	19.22	19.22	Earthen Levee	Encroachments	LS	PO	Landscaping	38.901942 ° -121.790937 °	38.901942 ° -121.790937 °		37
51	20.78	21.20	Earthen Levee	Crown Surface / Depressions / Rutting	CR	M	Keep the crown roadway free of vegetation.	38.909800 ° -121.811583 °	38.910683 ° -121.804588 °		974

*** Location**
 LS : Land Side
 WS : Water Side
 CR : Crown

**** Rating**
 A : Acceptable
 M : Minimally Acceptable
 U : Unacceptable
 PO : Partially Obstructing
 CO : Completely Obstructing
 N : Not Inspected
 C : Corrected

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2009

Reclamation District No. 1500

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	33.60	04/06/2009 04/06/2009	John Williamson

LMR Line	Levee Mile		Category	Item	Location	Rating	Action/Comment	GPS Latitude/Longitude		Photo	Issue
	Start	End						Start	End		
52	20.86	21.40	Earthen Levee	Encroachments	LS	PO	Agricultural Ditch	38.910177 ° -121.810352 °	38.913267 ° -121.803142 °		Y 975
53	23.69	25.29	Earthen Levee	Vegetation	LS	M	Control annual grass and weeds on the levee slopes and easements.	38.927240 ° -121.836932 °	38.946028 ° -121.835795 °		976
54	23.70	25.29	Earthen Levee	Vegetation	WS	M	Control annual grass and weeds on the levee slopes and easements.	38.927325 ° -121.836907 °	38.946028 ° -121.835797 °		977
55	23.94	24.78	Earthen Levee	Crown Surface / Depressions / Rutting	CR	M	Keep the crown roadway free of vegetation.	38.930435 ° -121.834778 °	38.940718 ° -121.830637 °		978
56	24.04	24.04	Earthen Levee	Encroachments	LS	PO	Buildings	38.931838 ° -121.834437 °	38.931838 ° -121.834437 °		42
57	24.44	24.78	Earthen Levee	Encroachments	LS	PO	Agricultural Ditch	38.936282 ° -121.830192 °	38.940712 ° -121.830650 °		Y 979
58	24.64	24.64	Earthen Levee	Encroachments	LS	M	Prunings	38.938957 ° -121.829282 °	38.938957 ° -121.829282 °		980
59	25.76	26.54	Earthen Levee	Encroachments	LS	PO	Agricultural Ditch	38.952500 ° -121.837247 °	38.961135 ° -121.830902 °		Y 981
60	26.84	27.07	Earthen Levee	Encroachments	LS	PO	Agricultural Ditch	38.964850 ° -121.833595 °	38.968083 ° -121.833593 °		Y 982
61	26.93	26.93	Earthen Levee	Animal Control	LS	C	No rodents visible, but rodent burrows visible; need to backfill and compact or grout borrows.	38.966175 ° -121.833909 °	38.966175 ° -121.833909 °		54
62	27.63	27.78	Earthen Levee	Encroachments	LS	PO	Agricultural Ditch	38.972440 ° -121.825892 °	38.972848 ° -121.823098 °		Y 983
63	28.12	29.60	Earthen Levee	Encroachments	LS	PO	Agricultural Ditch	38.976513 ° -121.819652 °	38.988433 ° -121.806403 °		984
64	30.60	30.60	Earthen Levee	Encroachments	LS	PO	Landscaping	38.996980 ° -121.794723 °	38.996980 ° -121.794723 °		45
65	31.34	31.81	Boat Survey	Boat Survey Erosion	LS	U	Inspector Comments: beaver holes, tension cracks, slumping; wide berm area all along over 30' wide	39.006221 ° -121.812458 °	39.003293 ° -121.805031 °		957
66	31.35	31.37	Earthen Levee	Erosion / Bank Caving	WS	M	Note and monitor erosion site. Inspector Comments: this is my eroision site rated m not u	39.003850 ° -121.804550 °	39.004000 ° -121.805200 °		49
67	33.33	33.33	Earthen Levee	Encroachments	LS	PO	Buildings	39.019722 ° -121.820345 °	39.019722 ° -121.820345 °		46

*** Location**
LS : Land Side
WS : Water Side
CR : Crown

**** Rating**
A : Acceptable PO : Partially Obstructing C : Corrected
M : Minimally Acceptable CO : Completely Obstructing
U : Unacceptable N : Not Inspected

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2009

Reclamation District No. 1500

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	33.60	04/06/2009 04/06/2009	John Williamson

LMR Line	Levee Mile		Category	Item	Location*	Rating**	Action/Comment	GPS Latitude/Longitude		Photo	Issue
	Start	End						Start	End		
68	33.41	33.41	Earthen Levee	Encroachments	WS	PO	Buildings Inspector Comments: Pumping Plant Intake structure	39.020875 ° -121.820273 °	39.020875 ° -121.820273 °		48
69	33.41	33.41	Earthen Levee	Encroachments	LS	PO	Buildings	39.020875 ° -121.820272 °	39.020875 ° -121.820272 °		47

*** Location**
 LS : Land Side
 WS : Water Side
 CR : Crown

**** Rating**
 A : Acceptable PO : Partially Obstructing C : Corrected
 M : Minimally Acceptable CO : Completely Obstructing
 U : Unacceptable N : Not Inspected

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2009

Reclamation District No. 1500

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	33.60	04/06/2009 04/06/2009	John Williamson

Levee Mile Report Line	7
Start Levee Mile	2.57
End Levee Mile	3.83
Location	Land Side
Category	Earthen Levee
Item	Encroachments
ag. ditch	



Levee Mile Report Line	15
Start Levee Mile	4.07
End Levee Mile	4.17
Location	Land Side
Category	Earthen Levee
Item	Encroachments
ag. ditch	



Levee Mile Report Line	39
Start Levee Mile	14.86
End Levee Mile	15.93
Location	Land Side
Category	Earthen Levee
Item	Encroachments
ag. ditch	



* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected	C : Corrected
--	--	--	---------------

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2009

Reclamation District No. 1500

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	33.60	04/06/2009 04/06/2009	John Williamson

Levee Mile Report Line	45
Start Levee Mile	16.86
End Levee Mile	17.45
Location	Land Side
Category	Earthen Levee
Item	Encroachments
ag. ditch	



Levee Mile Report Line	52
Start Levee Mile	20.86
End Levee Mile	21.40
Location	Land Side
Category	Earthen Levee
Item	Encroachments
ag. ditch	



Levee Mile Report Line	57
Start Levee Mile	24.44
End Levee Mile	24.78
Location	Land Side
Category	Earthen Levee
Item	Encroachments
ag. ditch	



*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected
C : Corrected

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2009

Reclamation District No. 1500

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	33.60	04/06/2009 04/06/2009	John Williamson

Levee Mile Report Line	59
Start Levee Mile	25.76
End Levee Mile	26.54
Location	Land Side
Category	Earthen Levee
Item	Encroachments
ag. ditch	



Levee Mile Report Line	60
Start Levee Mile	26.84
End Levee Mile	27.07
Location	Land Side
Category	Earthen Levee
Item	Encroachments
ag. ditch	



Levee Mile Report Line	62
Start Levee Mile	27.63
End Levee Mile	27.78
Location	Land Side
Category	Earthen Levee
Item	Encroachments
ag. ditch	



*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable PO : Partially Obstructing C : Corrected
M : Minimally Acceptable CO : Completely Obstructing
U : Unacceptable N : Not Inspected

**Flood Control Project Maintenance
Levee Inspections
Unit Cover Sheet
Spring 2009 Levee Inspection Results
Reclamation District No. 1500**

Waterway		Bank	Unit Miles
Unit No. 02 Sutter Bypass		Right	20.80

	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - February)
Unit Maintenance Rating (Fall Only)				
Date of Inspection	4/7/2009 - 4/7/2009			
DWR Inspector	John Williamson			
Accompanied By				

Check one:

During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.

During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

Comments

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :

DWR Summer/Winter Inspection Reports
3310 El Camino Avenue, Room LL-30
Sacramento, CA 95821-9000.

X _____
Signature of LMA Representative Date

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2009

Reclamation District No. 1500

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Sutter Bypass	Right	20.80	04/07/2009 04/07/2009	John Williamson

LMR Line	Levee Mile		Category	Item	Location *	Rating **	Action/Comment	GPS Latitude/Longitude		Photo	Issue
	Start	End						Start	End		
1	0.01	0.01	Earthen Levee	Encroachments	WS	PO	Equipment	38.760845 ° -121.674640 °	38.760845 ° -121.674640 °		12
2	0.02	20.77	Earthen Levee	Vegetation	WS	M	Control annual grass and weeds on the levee slopes and easements.	38.761370 ° -121.674267 °	39.021328 ° -121.741130 °		14
3	0.02	20.77	Earthen Levee	Vegetation	LS	M	Control annual grass and weeds on the levee slopes and easements.	38.761370 ° -121.674265 °	39.021329 ° -121.741131 °		13
4	3.66	3.66	Earthen Levee	Animal Control	LS	C	No rodents visible, but rodent burrows visible; need to backfill and compact or grout borrows. Inspector Comments: Many gopher mounds through out the levee landside and waterside squirrels holes are present	38.808312 ° -121.658783 °	38.808312 ° -121.658783 °		6
5	4.04	4.04	Earthen Levee	Animal Control	LS	C	No rodents visible, but rodent burrows visible; need to backfill and compact or grout borrows.	38.813395 ° -121.661108 °	38.813395 ° -121.661108 °		7
6	5.73	5.73	Earthen Levee	Animal Control	LS	C	Exterminate rodents and backfill and compact or grout burrows. Inspector Comments: squirrel holes landside gopher mounds on both side of levee	38.837038 ° -121.658945 °	38.837038 ° -121.658945 °		8
7	7.35	7.35	Earthen Levee	Animal Control	LS	C	No rodents visible, but rodent burrows visible; need to backfill and compact or grout borrows.	38.859313 ° -121.650180 °	38.859313 ° -121.650180 °		9
8	9.39	9.39	Earthen Levee	Animal Control	LS	C	No rodents visible, but rodent burrows visible; need to backfill and compact or grout borrows.	38.885933 ° -121.635660 °	38.885933 ° -121.635660 °		10
9	14.70	14.70	Earthen Levee	Animal Control	WS	C	No rodents visible, but rodent burrows visible; need to backfill and compact or grout borrows.	38.952803 ° -121.675358 °	38.952803 ° -121.675358 °		11

*** Location**
LS : Land Side
WS : Water Side
CR : Crown

**** Rating**
A : Acceptable PO : Partially Obstructing C : Corrected
M : Minimally Acceptable CO : Completely Obstructing
U : Unacceptable N : Not Inspected