

**Flood Control Project Maintenance  
Levee Inspections**  
**LMA District Cover Sheet**  
**Spring 2009 Levee Inspection Results**

**Reclamation District No. 2035**

|                                  | Spring<br>(March - May) | Summer **<br>(June - August) | Fall<br>(September - November) | Winter **<br>(December - February) |
|----------------------------------|-------------------------|------------------------------|--------------------------------|------------------------------------|
| * Overall LMA Rating (Fall Only) |                         |                              |                                |                                    |

\*\* Non-receipt of Summer or Winter Inspection Reports may effect overall annual rating.

\*

SPRING INSPECTIONS: Overall maintenance ratings are not determined for the spring inspection results. Individual maintenance deficiencies are rated using the same criteria in the spring and in the fall.

FALL INSPECTIONS: The overall maintenance rating shown above is based on operation and maintenance deficiencies identified within the attached unit inspection reports.

Comments

|  |
|--|
|  |
|  |
|  |
|  |
|  |
|  |
|  |
|  |

**Flood Control Project Maintenance  
Levee Inspections**

**Unit Cover Sheet**

**Spring 2009 Levee Inspection Results**

**Reclamation District No. 2035**

| Waterway                               |  | Bank  | Unit Miles |
|--|--|-------|------------|
| Unit No. 01 Cache Creek Settling Basin |  | Right | 2.00       |

|  | Spring<br>(March - May) | Summer<br>(June - August) | (September - November)<br>Fall | Winter<br>(December - February) |
|--|-------------------------|---------------------------|--------------------------------|---------------------------------|
| Unit Maintenance Rating<br>(Fall Only) |                         |                           |                                |                                 |
| Date of Inspection                     | 3/16/2009 - 3/16/2009   |                           |                                |                                 |
| DWR Inspector                          | Clay Thomas             |                           |                                |                                 |
| Accompanied By                         |                         |                           |                                |                                 |

Check one:

- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.
- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

**Comments**

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :

DWR Summer/Winter Inspection Reports  
3310 El Camino Avenue, Room LL-30  
Sacramento, CA 95821-9000.

**X**

Signature of LMA Representative

Date

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2009**

**Reclamation District No. 2035**

| Waterway                               | Bank  | Unit Miles | Inspection Start/End     | Inspector      |
|--|-------|------------|--------------------------|----------------|
| Unit No. 01 Cache Creek Settling Basin | Right | 2.00       | 03/16/2009<br>03/16/2009 | Clay<br>Thomas |

| LMR Line | Levee Mile |     | Category | Item | Location<br>* | Rating<br>** | Action/Comment           | GPS Latitude/Longitude |     | Photo | Issue |
|----------|------------|-----|----------|------|---------------|--------------|--------------------------|------------------------|-----|-------|-------|
|          | Start      | End |          |      |               |              |                          | Start                  | End |       |       |
| 1        |            |     |          |      |               |              | No issues were reported. | °                      | °   |       |       |
|          |            |     |          |      |               |              |                          | °                      | °   |       |       |

**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable      PO : Partially Obstructing      C : Corrected  
M : Minimally Acceptable      CO : Completely Obstructing  
U : Unacceptable      N : Not Inspected

**Flood Control Project Maintenance  
Levee Inspections**

**Unit Cover Sheet**

**Spring 2009 Levee Inspection Results**

**Reclamation District No. 2035**

|                         |  |       |            |
|-------------------------|--|-------|------------|
| Waterway                |  | Bank  | Unit Miles |
| Unit No. 02 Yolo Bypass |  | Right | 7.60       |

|  |                         |                           |                                |                                 |
|--|-------------------------|---------------------------|--------------------------------|---------------------------------|
|  | Spring<br>(March - May) | Summer<br>(June - August) | (September - November)<br>Fall | Winter<br>(December - February) |
| Unit Maintenance Rating<br>(Fall Only) |                         |                           |                                |                                 |
| Date of Inspection                     | 3/16/2009 - 3/16/2009   |                           |                                |                                 |
| DWR Inspector                          | Clay Thomas             |                           |                                |                                 |
| Accompanied By                         |                         |                           |                                |                                 |

Check one:

- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.
- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

## Comments

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :

DWR Summer/Winter Inspection Reports  
3310 El Camino Avenue, Room LL-30  
Sacramento, CA 95821-9000.

X

Signature of LMA Representative

Date

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2009**

**Reclamation District No. 2035**

| Waterway                | Bank  | Unit Miles | Inspection Start/End     | Inspector      |
|-------------------------|-------|------------|--------------------------|----------------|
| Unit No. 02 Yolo Bypass | Right | 7.60       | 03/16/2009<br>03/16/2009 | Clay<br>Thomas |

| LMR Line | Levee Mile |      | Category      | Item                | Location<br>* | Rating<br>** | Action/Comment                               | GPS Latitude/Longitude       |                              | Photo | Issue |
|----------|------------|------|---------------|---------------------|---------------|--------------|--|------------------------------|------------------------------|-------|-------|
|          | Start      | End  |               |                     |               |              |  | Start                        | End                          |       |       |
| 1        | 0.28       | 0.36 | Boat Survey   | Boat Survey Erosion | LS            | M            | Inspector Comments: tension cracks, slumping | 38.673229 °<br>-121.671733 ° | 38.672069 °<br>-121.671516 ° | Y     | 976   |
| 2        | 1.97       | 2.02 | Boat Survey   | Boat Survey Erosion | LS            | M            | Inspector Comments: tension cracks, slumping | 38.648881 °<br>-121.666653 ° | 38.648178 °<br>-121.666385 ° | Y     | 977   |
| 3        | 2.23       | 4.01 | Earthen Levee | Encroachments       | LS            | PO           | Agricultural Ditch                           | 38.645470 °<br>-121.665573 ° | 38.623062 °<br>-121.648925 ° |       | 979   |
| 4        | 4.08       | 4.39 | Boat Survey   | Boat Survey Erosion | LS            | M            | Inspector Comments: tension cracks, slumping | 38.622189 °<br>-121.648277 ° | 38.618267 °<br>-121.645371 ° | Y     | 978   |

**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
PO : Partially Obstructing  
CO : Completely Obstructing  
N : Not Inspected  
C : Corrected

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2009**

**Reclamation District No. 2035**

| Waterway                | Bank  | Unit Miles | Inspection Start/End     | Inspector   |
|-------------------------|-------|------------|--------------------------|-------------|
| Unit No. 02 Yolo Bypass | Right | 7.60       | 03/16/2009<br>03/16/2009 | Clay Thomas |

|   |                     |
|---|---------------------|
| Levee Mile Report Line  | 1                   |
| Start Levee Mile  | 0.28                |
| End Levee Mile  | 0.36                |
| Location  |                     |
| Category  | Boat Survey         |
| Item  | Boat Survey Erosion |
| N 38.67201, W -121.67157. L/M 0.36. Looking up stream, I-5 overpass in the background |                     |



|   |                     |
|---|---------------------|
| Levee Mile Report Line                                | 2                   |
| Start Levee Mile                                      | 1.97                |
| End Levee Mile  | 2.02                |
| Location  |                     |
| Category  | Boat Survey         |
| Item  | Boat Survey Erosion |
| N 38.64862, W -121.66668. L/M 2.20. Looking up stream |                     |



|  |                     |
|--|---------------------|
| Levee Mile Report Line                                 | 4                   |
| Start Levee Mile                                       | 4.08                |
| End Levee Mile   | 4.39                |
| Location   |                     |
| Category   | Boat Survey         |
| Item   | Boat Survey Erosion |
| N 38.61902, W -121.64595. L/M 4.39. Looking up stream. |                     |

**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable

PO : Partially Obstructing  
CO : Completely Obstructing  
N : Not Inspected

C : Corrected

**Flood Control Project Maintenance  
Levee Inspections**

**Unit Cover Sheet**

**Spring 2009 Levee Inspection Results**

**Reclamation District No. 2035**

| Waterway                         |  | Bank | Unit Miles |
|----------------------------------|--|------|------------|
| Unit No. 03 Willow Slough Bypass |  | Left | 2.50       |

|  | Spring<br>(March - May) | Summer<br>(June - August) | (September - November)<br>Fall | Winter<br>(December - February) |
|--|-------------------------|---------------------------|--------------------------------|---------------------------------|
| Unit Maintenance Rating<br>(Fall Only) |                         |                           |                                |                                 |
| Date of Inspection                     | 3/16/2009 - 3/16/2009   |                           |                                |                                 |
| DWR Inspector                          | Clay Thomas             |                           |                                |                                 |
| Accompanied By                         |                         |                           |                                |                                 |

Check one:

- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.
- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

## Comments

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :

DWR Summer/Winter Inspection Reports  
3310 El Camino Avenue, Room LL-30  
Sacramento, CA 95821-9000.

X

Signature of LMA Representative

Date

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2009**

**Reclamation District No. 2035**

| Waterway                         | Bank | Unit Miles | Inspection Start/End     | Inspector      |
|----------------------------------|------|------------|--------------------------|----------------|
| Unit No. 03 Willow Slough Bypass | Left | 2.50       | 03/16/2009<br>03/16/2009 | Clay<br>Thomas |

| LMR Line | Levee Mile |      | Category         | Item                   | Location<br>* | Rating<br>** | Action/Comment           | GPS Latitude/Longitude       |                              | Photo | Issue |
|----------|------------|------|------------------|------------------------|---------------|--------------|--------------------------|------------------------------|------------------------------|-------|-------|
|          | Start      | End  |                  |                        |               |              |                          | Start                        | End                          |       |       |
| 1        | 0.08       | 2.09 | Earthen<br>Levee | Encroachments          | LS            | PO           | Agricultural Ditch       | 38.575615 °<br>-121.636680 ° | 38.590877 °<br>-121.657538 ° |       | 973   |
| 2        | 2.20       | 2.49 | Boat<br>Survey   | Boat Survey<br>Erosion | LS            | M            | Inspector Comments: none | 38.590784 °<br>-121.664910 ° | 38.590890 °<br>-121.659671 ° | Y     | 972   |

**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable      PO : Partially Obstructing      C : Corrected  
M : Minimally Acceptable      CO : Completely Obstructing  
U : Unacceptable      N : Not Inspected



**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2009**

**Reclamation District No. 2035**

| Waterway                         | Bank | Unit Miles | Inspection Start/End     | Inspector      |
|----------------------------------|------|------------|--------------------------|----------------|
| Unit No. 03 Willow Slough Bypass | Left | 2.50       | 03/16/2009<br>03/16/2009 | Clay<br>Thomas |

|  |                     |
|--|---------------------|
| Levee Mile Report Line   | 2                   |
| Start Levee Mile   | 2.20                |
| End Levee Mile   | 2.49                |
| Location   |                     |
| Category   | Boat Survey         |
| Item   | Boat Survey Erosion |
| N 38.59086, W -121.65882. L/M 2.20 Looking up stream Willow Slough |                     |

**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable      PO : Partially Obstructing      C : Corrected  
M : Minimally Acceptable      CO : Completely Obstructing  
U : Unacceptable      N : Not Inspected