

**Flood Control Project Maintenance  
Levee Inspections**

**Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2020**

**Reclamation District No. 2035 Conaway**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Cache Creek Settling Basin	Right	2.01	04/01/2020 04/01/2020	Zach Jojola

LM Start	<b>0.00</b>	Rating **	A	Issue No.	<b>3</b>
LM End	<b>0.00</b>	Issue Type +	Ma	Location *	CR
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Operations & Maintenance Manuals			°	°
				°	°
DWR ID	DWR_RD2035_01_s_2013_3				
Comment Code					
Inspector Comment					
The LMA stated that they keep a copy of the O&M manuals on hand at the district office.					

No Photos

LM Start	<b>0.00</b>	Rating **	A	Issue No.	<b>4</b>
LM End	<b>0.00</b>	Issue Type +	Ma	Location *	CR
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Emergency Supplies & Equipment			°	°
				°	°
DWR ID	DWR_RD2035_01_s_2013_4				
Comment Code					
Inspector Comment					
The district has emergency supplies and equipment on hand at their district office.					

No Photos

LM Start	<b>0.00</b>	Rating **	A	Issue No.	<b>5</b>
LM End	<b>0.00</b>	Issue Type +	Ma	Location *	CR
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Flood Preparedness & Training			°	°
				°	°
DWR ID	DWR_RD2035_01_s_2013_5				
Comment Code					
Inspector Comment					
The LMA is current with flood fight training.					

No Photos

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
----------------------------------------------------------------------------------------------	------------------------------------------------------------------------------------	-------------------------------------------------------------------------------------	-------------------------------------------------------------------------------------------------------------

**Flood Control Project Maintenance  
Levee Inspections**

**Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2020**

**Reclamation District No. 2035 Conaway**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Cache Creek Settling Basin	Right	2.01	04/01/2020 04/01/2020	Zach Jojola

LM Start	0.02	Rating **	A/W	Issue No.	20	
LM End	0.02	Issue Type +	Ma	Location *		
Category	Supplemental			GPS Latitude/Longitude		
				Start	End	
Item	DWR UCIP LMA Responsibility			38.677377 °	38.677377 °	
				-121.709487 °	-121.709487 °	
DWR ID	17814					
Comment Code						
Inspector Comment						
DS_ID:17814 FS_ID:56049 EP_NO: 10127 Repair Type: No Action Needed Crossing Status: Found UCIP Comments: 08/16/2019 Pending update... record will be updated in 2020. (O. Magana - DWR UCIP) FIELD_STRUCT_DESC: 42-inch concrete encased corrugated metal drainage pipe through the levee, 10 feet below the crown. Flap gate on the waterside (WS) end. Grouted spillway on the WS. Pipe exposed on the landside (LS). (36-inch pipe [HLM 0.02] authorized under Automatic Board Order (ABO) issued as Permit No. 10127, 1974 - City of Woodland, Department of Public Works). [Additional Reference(s): DWR Levee Log, 1990. USACE Sacramento O&M Manual 126, November 1961, (HLM 0.01), listed as 5.5 feet below the crown]. FS Date: 8/16/2019 12:20:00 PM						

LM Start	<b>0.02</b>	Rating **	A/W	Issue No.	<b>20 (cont)</b>
LM End	<b>0.02</b>	Issue Type +	Ma	Location *	

Photo 1 of 3 : UCIP\_SP\_2020\_56049\_18109.jpg



Flap gate and spillway on WS toe.

Photo 2 of 3 : UCIP\_SP\_2020\_56049\_18108.jpg



Flap gate and spillway on WS toe.

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
----------------------------------------------------------------------------------------------	------------------------------------------------------------------------------------	-------------------------------------------------------------------------------------	-------------------------------------------------------------------------------------------------------------

**Flood Control Project Maintenance  
Levee Inspections**

## Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2020

### Reclamation District No. 2035 Conaway

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Cache Creek Settling Basin	Right	2.01	04/01/2020 04/01/2020	Zach Jojola

LM Start	<b>0.02</b>	Rating **	A/W	Issue No.	<b>20 (cont)</b>
LM End	<b>0.02</b>	Issue Type +	Ma	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP LMA Responsibility			38.677377 °	38.677377 °
				-121.709487 °	-121.709487 °
DWR ID	17814				

Photo 3 of 3 : UCIP\_SP\_2020\_56049\_18107.jpg



Concrete encased pipe on LS toe.

LM Start	0.03	Rating **	M	Issue No.	14
LM End	0.36	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.677362 °	38.677327 °
				-121.709411 °	-121.703284 °
DWR ID	DWR_RD2035_01_s_2020_14				
Comment Code					
V1 : Control annual grass and weeds on the levee slopes and easements.					
Inspector Comment					

No Photos

LM Start	0.03	Rating **	M	Issue No.	15
LM End	0.36	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.677362 °	38.677327 °
				-121.709411 °	-121.703284 °
DWR ID	DWR_RD2035_01_s_2020_15				
Comment Code					
V1 : Control annual grass and weeds on the levee slopes and easements.					
Inspector Comment					

No Photos

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
----------------------------------------------------------------------------------------------	------------------------------------------------------------------------------------	-------------------------------------------------------------------------------------	-------------------------------------------------------------------------------------------------------------

**Flood Control Project Maintenance  
Levee Inspections**

**Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2020**

**Reclamation District No. 2035 Conaway**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Cache Creek Settling Basin	Right	2.01	04/01/2020 04/01/2020	Zach Jojola

LM Start	<b>0.03</b>	Rating **	M	Issue No.	<b>16</b>
LM End	<b>0.36</b>	Issue Type +	Ma	Location *	CR
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Vegetation		38.677362 °	38.677327 °	
			-121.709411 °	-121.703284 °	
DWR ID	DWR_RD2035_01_s _ 2020_16				
Comment Code					
V1 : Control annual grass and weeds on the levee slopes and easements.					
Inspector Comment					

No Photos

LM Start	<b>0.30</b>	Rating **	M	Issue No.	<b>17</b>
LM End	<b>0.30</b>	Issue Type +	Ma	Location *	CR
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Crown Surface / Depressions / Rutting		38.677340 °	38.677340 °	
			-121.704287 °	-121.704287 °	
DWR ID	DWR_RD2035_01_s _ 2020_17				
Comment Code					
C2 : Repair depressions or ruts in the crown or slope.					
Inspector Comment					
Tire ruts on the crown.					

No Photos

LM Start	<b>0.82</b>	Rating **	M	Issue No.	<b>18</b>
LM End	<b>0.82</b>	Issue Type +	Ma	Location *	CR
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Crown Surface / Depressions / Rutting		38.677305 °	38.677305 °	
			-121.694817 °	-121.694817 °	
DWR ID	DWR_RD2035_01_s _ 2020_18				
Comment Code					
C2 : Repair depressions or ruts in the crown or slope.					
Inspector Comment					
Tire ruts on the crown.					

No Photos

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
----------------------------------------------------------------------------------------------	------------------------------------------------------------------------------------	-------------------------------------------------------------------------------------	-------------------------------------------------------------------------------------------------------------

**Flood Control Project Maintenance  
Levee Inspections**

## Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2020

### Reclamation District No. 2035 Conaway

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Cache Creek Settling Basin	Right	2.01	04/01/2020 04/01/2020	Zach Jojola

LM Start	<b>0.85</b>	Rating **	M	Issue No.	<b>12</b>
LM End	<b>1.93</b>	Issue Type +	Ma	Location *	LS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Vegetation		38.677283 °	38.677176 °	
			-121.694091 °	-121.674258 °	
DWR ID	DWR_RD2035_01_s _ 2020_12				
Comment Code					
V1 : Control annual grass and weeds on the levee slopes and easements.					
Inspector Comment					

No Photos

LM Start	<b>1.10</b>	Rating **	M	Issue No.	<b>13</b>
LM End	<b>1.93</b>	Issue Type +	Ma	Location *	WS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Vegetation		38.677257 °	38.677175 °	
			-121.689510 °	-121.674258 °	
DWR ID	DWR_RD2035_01_s _ 2020_13				
Comment Code					
V1 : Control annual grass and weeds on the levee slopes and easements.					
Inspector Comment					

No Photos

LM Start	<b>1.10</b>	Rating **	M	Issue No.	<b>11</b>
LM End	<b>2.00</b>	Issue Type +	Ma	Location *	CR
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Vegetation		38.677257 °	38.677172 °	
			-121.689510 °	-121.672922 °	
DWR ID	DWR_RD2035_01_s _ 2020_11				
Comment Code					
V1 : Control annual grass and weeds on the levee slopes and easements.					
Inspector Comment					

No Photos

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
----------------------------------------------------------------------------------------------	------------------------------------------------------------------------------------	-------------------------------------------------------------------------------------	-------------------------------------------------------------------------------------------------------------

**Flood Control Project Maintenance  
Levee Inspections**

**Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2020**

**Reclamation District No. 2035 Conaway**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Cache Creek Settling Basin	Right	2.01	04/01/2020 04/01/2020	Zach Jojola

LM Start	1.93	Rating **	U	Issue No.	10
LM End	2.00	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.677176 °	38.677172 °
				-121.674258 °	-121.672922 °
DWR ID	DWR_RD2035_01_s_2020_10				
Comment Code					
V1 : Control annual grass and weeds on the levee slopes and easements.					
Inspector Comment					

Photo 1 of 1 : SP\_2020\_RD2035\_238\_10\_20200401\_00013.jpg



View of dense vegetation on the waterside slope. Spring 2020.

LM Start	1.93	Rating **	U	Issue No.	9
LM End	2.00	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.677176 °	38.677172 °
				-121.674258 °	-121.672921 °
DWR ID	DWR_RD2035_01_s_2020_9				
Comment Code					
V1 : Control annual grass and weeds on the levee slopes and easements.					
Inspector Comment					

Photo 1 of 1 : SP\_2020\_RD2035\_238\_9\_20200401\_00014.jpg



View of dense vegetation on the landside slope. Spring 2020.

**\* Location**  
LS : Land Side    N/A : Not Applicable  
WS : Water Side  
CR : Crown

**\*\* Rating**  
A : Acceptable                      N : Not Inspected/Rated  
M : Minimally Acceptable        C : Corrected  
U : Unacceptable                  A/W : Acceptable but Monitor & Maintain

**+ Issue Type**  
Ma : Maintenance Deficiency  
Ob : Design & System Obsolescence  
En : Enforcement

**Flood Control Project Maintenance  
Levee Inspections**

## Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2020

### Reclamation District No. 2035 Conaway

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Yolo Bypass	Right	7.63	04/01/2020 04/01/2020	Zach Jojola

LM Start	0.38	Rating **	U	Issue No.	980
LM End	0.38	Issue Type +	Ma	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP LMA Responsibility			38.671813 °	38.671813 °
				-121.671581 °	-121.671581 °
DWR ID	17822				
Comment Code					
Inspector Comment					
DS_ID:17822 FS_ID:56053 EP_NO: N/A Repair Type: Urgent Crossing Status: Found UCIP Comments: 08/16/2019 Pending update... record will be updated in 2020. (O. Magana - DWR UCIP)10/30/2018 Same as last inspection. Flap gate on the WS was submerged at the time of the inspection. Erosion is still present behind the headwall. Sink hole/burrow activity was observed along the concrete box located on the LS. Recommend internal inspection of the pipe section through levee to determine the condition of the pipe through the levee. Crossing remains Urgent due to signs of pipe leakage on LS. (O. Magana - DWR UCIP)09/14/2016 - Flap gate on the WS was submerged at time of inspection. LS headwall at the pumping plant has exposed rebar. There is still erosion present behind the headwall. However, water was present making it difficult to determine if it is getting worse. As-built drawings were requested from LMA consultant representative. (T. Hatch/UCIP)04/02/2013 - Flap gate broken in half on WS toe. Some erosion at headwalls on pumping plant. (W. Wylie/UCIP) FIELD_STRUCT_DESC: 44-inch corrugated metal drainage pipe through the levee, 22 feet below the crown. Pump on platform in drainage ditch at the landside (LS) toe. Slide gate and flap gates in a 5-foot by 9-foot concrete box. Flap gate on the waterside (WS) toe. 8-inch vent/standpipe at the WS toe. [Additional Reference(s): DWR Levee Log, 1990. USACE Sacramento O&M Manual 121, May 1959, (HLM 0.4) (4-foot by 4-foot concrete culvert listed)]. FS Date: 8/16/2019 12:25:00 PM					

Photo 1 of 3 : UCIP\_SP\_2020\_56053\_18202.jpg



Pumping plant off LS toe.

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
----------------------------------------------------------------------------------------------	---------------------------------------------------------------------------------------------------------------------------------------------------------------------------	-------------------------------------------------------------------------------------------------------------

**Flood Control Project Maintenance  
Levee Inspections**

## Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2020

### Reclamation District No. 2035 Conaway

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Yolo Bypass	Right	7.63	04/01/2020 04/01/2020	Zach Jojola

LM Start	<b>0.38</b>	Rating **	U	Issue No.	<b>980 (cont)</b>
LM End	<b>0.38</b>	Issue Type +	Ma	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP LMA Responsibility			38.671813 °	38.671813 °
				-121.671581 °	-121.671581 °
DWR ID	17822				

Photo 2 of 3 : UCIP\_SP\_2020\_56053\_18201.jpg



Pipe and flap gate with vent riser on WS toe.

LM Start	<b>0.38</b>	Rating **	U	Issue No.	<b>980 (cont)</b>
LM End	<b>0.38</b>	Issue Type +	Ma	Location *	

Photo 3 of 3 : UCIP\_SP\_2020\_56053\_18200.jpg



Broken flap gate at WS toe.

LM Start	1.20	Rating **	A/W	Issue No.	11
LM End	1.24	Issue Type +	Ma	Location *	WS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	2017 USACE Erosion Survey			38.660050 °	38.659465 °
				-121.669028 °	-121.668940 °
DWR ID	DWR_RD2035_02_f_2018_11				
Comment Code					
Inspector Comment					
2017 Site ID: YOL 1.2 R					
Status: Eroding					
2017 Field Notes: Small amount of toe erosion.					
Site History: 2011 - Small sections of slumping, likely from wind wave.					

No Photos

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable	<b>N : Not Inspected/Rated</b> C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
----------------------------------------------------------------------------------------------	------------------------------------------------------------------------------------	--------------------------------------------------------------------------------------------	-------------------------------------------------------------------------------------------------------------

**Flood Control Project Maintenance  
Levee Inspections**

**Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2020**

**Reclamation District No. 2035 Conaway**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Yolo Bypass	Right	7.63	04/01/2020 04/01/2020	Zach Jojola

LM Start	1.98	Rating **	A/W	Issue No.	12
LM End	2.03	Issue Type +	Ma	Location *	WS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	2017 USACE Erosion Survey			38.648881 °	38.648178 °
				-121.666653 °	-121.666385 °
DWR ID	DWR_RD2035_02_f_2018_12				
Comment Code					
Inspector Comment					
2017 Site ID: YOL 2.0 R					
Status: Eroding					
2017 Field Notes: Toe continues to erode.					
Site History: 2006 - Wave wash erosion and some saturation slumping occurring. Tension/separation cracks evident in fine grained levee slope materials. 2011 - Small sections of slumping lower bank, just downstream of bank rock. 2016 - New cracks observed a the mid-slope.					

No Photos

LM Start	2.15	Rating **	A/W	Issue No.	982	
LM End	2.15	Issue Type +	Ma	Location *		
Category	Supplemental			GPS Latitude/Longitude		
				Start	End	
Item	DWR UCIP LMA Responsibility			38.646445 °	38.646445 °	
				-121.666423 °	-121.666423 °	
DWR ID	17833					
Comment Code						
Inspector Comment						
DS_ID:17833						
FS_ID:10933						
EP_NO: N/A						
Repair Type: No Action Needed						
Crossing Status: Found						
UCIP Comments:						
FIELD_STRUCT_DESC: 1 of 2: 60-inch drainage pipe of an unknown material through the levee, 26 feet below the crown. Concrete well and gate structure on the waterside (WS) slope. [Additional Reference(s): DWR Levee Log, 1990. USACE Sacramento O&M Manual 121, May 1959, (HLM 2.3) (6-foot by 6-foot concrete culvert listed)].						
FS Date: 4/2/2013						

Photo 1 of 3 : UCIP\_SP\_2020\_10933\_18226.jpg



Slide gates in concrete vault on WS slope.

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
----------------------------------------------------------------------------------------------	---------------------------------------------------------------------------------------------------------------------------------------------------------------------------	-------------------------------------------------------------------------------------------------------------

**Flood Control Project Maintenance  
Levee Inspections**

## Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2020

### Reclamation District No. 2035 Conaway

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Yolo Bypass	Right	7.63	04/01/2020 04/01/2020	Zach Jojola

LM Start	<b>2.15</b>	Rating **	A/W	Issue No.	<b>982 (cont)</b>
LM End	<b>2.15</b>	Issue Type +	Ma	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP LMA Responsibility			38.646445 °	38.646445 °
				-121.666423 °	-121.666423 °
DWR ID	17833				

Photo 2 of 3 : UCIP\_SP\_2020\_10933\_18225.jpg



LS at intake.

LM Start	<b>2.15</b>	Rating **	A/W	Issue No.	<b>982 (cont)</b>
LM End	<b>2.15</b>	Issue Type +	Ma	Location *	

Photo 3 of 3 : UCIP\_SP\_2020\_10933\_18224.jpg



Outlet on WS toe.

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown		<b>** Rating</b> A : Acceptable                      N : Not Inspected/Rated M : Minimally Acceptable        C : Corrected U : Unacceptable                  A/W : Acceptable but Monitor & Maintain		<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
----------------------------------------------------------------------------------------------	--	---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------	--	-------------------------------------------------------------------------------------------------------------

**Flood Control Project Maintenance  
Levee Inspections**

**Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2020**

**Reclamation District No. 2035 Conaway**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Yolo Bypass	Right	7.63	04/01/2020 04/01/2020	Zach Jojola

LM Start	2.15	Rating **	A/W	Issue No.	983	
LM End	2.15	Issue Type +	Ma	Location *		
Category	Supplemental			GPS Latitude/Longitude		
				Start		End
Item	DWR UCIP LMA Responsibility			38.646425 °		38.646425 °
				-121.666421 °		-121.666421 °
DWR ID	17877					
Comment Code						
Inspector Comment						
DS_ID:17877 FS_ID:10934 EP_NO: N/A Repair Type: No Action Needed Crossing Status: Found UCIP Comments: FIELD_STRUCT_DESC: 2 of 2: 60-inch drainage pipe of an unknown material through the levee, 26 feet below the crown. Concrete well and gate structure on the waterside (WS) slope. Concrete headwalls on both ends. [Additional Reference(s): DWR Levee Log, 1990. USACE Sacramento O&M Manual 121, May 1959, (HLM 2.3) (6-foot by 6-foot concrete culvert listed)]. FS Date: 4/2/2013						

Photo 1 of 3 : UCIP\_SP\_2020\_10934\_18230.jpg



Slide gates in concrete vault on WS slope.

LM Start	<b>2.15</b>	Rating **	A/W	Issue No.	<b>983 (cont)</b>
LM End	<b>2.15</b>	Issue Type +	Ma	Location *	

Photo 2 of 3 : UCIP\_SP\_2020\_10934\_18229.jpg



Intake at channel on LS toe.

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
----------------------------------------------------------------------------------------------	------------------------------------------------------------------------------------	-------------------------------------------------------------------------------------	-------------------------------------------------------------------------------------------------------------

**Flood Control Project Maintenance  
Levee Inspections**

## Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2020

### Reclamation District No. 2035 Conaway

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Yolo Bypass	Right	7.63	04/01/2020 04/01/2020	Zach Jojola

LM Start	2.15	Rating **	A/W	Issue No.	983 (cont)	
LM End	2.15	Issue Type +	Ma	Location *		
Category	Supplemental			GPS Latitude/Longitude		
				Start		End
Item	DWR UCIP LMA Responsibility			38.646425 °		38.646425 °
				-121.666421 °		-121.666421 °
DWR ID	17877					

Photo 3 of 3 : UCIP\_SP\_2020\_10934\_18228.jpg



Concrete headwall on WS toe.

LM Start	2.26	Rating **	A/W	Issue No.	13
LM End	2.60	Issue Type +	Ma	Location *	WS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	2017 USACE Erosion Survey			38.645319 °	38.640997 °
				-121.665089 °	-121.661878 °
DWR ID	DWR_RD2035_02_f_2018_13				
Comment Code					
Inspector Comment					
2017 Site ID: YOL 2.3 R					
Status: Eroding					
2017 Field Notes: Minor new toe erosion.					
Site History: 2011 - Erosion from wind waves along entire length of the levee toe. Several sections of slumping bank along the toe. 2016 - Fresh cracks observed.					

No Photos

LM Start	2.61	Rating **	A/W	Issue No.	17
LM End	2.61	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			38.640880 °	38.640880 °
				-121.662058 °	-121.662058 °
DWR ID	DWR_RD2035_02_s_2020_17				
Comment Code					
A3 : No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.					
Inspector Comment					
Small rodent holes near waterside toe. Recommend monitoring.					

Photo 1 of 1 : SP\_2020\_RD2035\_239\_17\_20200401\_00029.jpg



View of rodent hole near waterside toe. Spring 2020.

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown		<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable		N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement	
----------------------------------------------------------------------------------------------	--	------------------------------------------------------------------------------------	--	-------------------------------------------------------------------------------------	--	-------------------------------------------------------------------------------------------------------------	--

**Flood Control Project Maintenance  
Levee Inspections**

## Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2020

### Reclamation District No. 2035 Conaway

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Yolo Bypass	Right	7.63	04/01/2020 04/01/2020	Zach Jojola

LM Start	2.78	Rating **	A/W	Issue No.	14
LM End	3.26	Issue Type +	Ma	Location *	WS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	2017 USACE Erosion Survey			38.638731 °	38.632783 °
				-121.660247 °	-121.655864 °
DWR ID	DWR_RD2035_02_f_2018_14				
Comment Code					
Inspector Comment					
2017 Site ID: YOL 2.8 R					
Status: Eroding					
2017 Field Notes: Erosion creeps further into levee toe.					
Site History: 2011 - Wave wash erosion and several sections of slumping bank along the toe.					

No Photos

LM Start	2.91	Rating **	M	Issue No.	9
LM End	2.91	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Erosion / Bank Caving			38.637048 °	38.637048 °
				-121.659227 °	-121.659227 °
DWR ID	DWR_RD2035_02_f_2019_9				
Comment Code					
E2 : Schedule repair of erosion site prior to the next inspection.					
Inspector Comment					
Appears to be a 15' wide section of bank caving near the waterside toe. Recommend repairing.					

Photo 1 of 1 : SP\_2020\_RD2035\_239\_9\_20200228\_00001.jpg



View of bank caving on the waterside slope. Fall 2019.

LM Start	3.42	Rating **	M	Issue No.	18
LM End	3.42	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Erosion / Bank Caving			38.630657 °	38.630657 °
				-121.654502 °	-121.654502 °
DWR ID	DWR_RD2035_02_s_2020_18				
Comment Code					
E2 : Schedule repair of erosion site prior to the next inspection.					
Inspector Comment					
Erosion at the waterside toe.					

No Photos

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
----------------------------------------------------------------------------------------------	------------------------------------------------------------------------------------	-------------------------------------------------------------------------------------	-------------------------------------------------------------------------------------------------------------

**Flood Control Project Maintenance  
Levee Inspections**

## Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2020

### Reclamation District No. 2035 Conaway

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Yolo Bypass	Right	7.63	04/01/2020 04/01/2020	Zach Jojola

LM Start	3.70	Rating **	M	Issue No.	15
LM End	3.99	Issue Type +	Ma	Location *	WS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	2017 USACE Erosion Survey			38.627145 °	38.623533 °
				-121.651820 °	-121.649176 °
DWR ID	DWR_RD2035_02_f_2018_15				
Comment Code					
Inspector Comment					
2017 Site ID: YOL 3.5 R					
Status: Eroding New					
2017 Field Notes: Unable to view due to access issues.					
Site History: 2016 - Erosion observed at levee toe.					

No Photos

LM Start	4.09	Rating **	A/W	Issue No.	16
LM End	4.41	Issue Type +	Ma	Location *	WS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	2017 USACE Erosion Survey			38.622224 °	38.618302 °
				-121.648201 °	-121.645296 °
DWR ID	DWR_RD2035_02_f_2018_16				
Comment Code					
Inspector Comment					
2017 Site ID: YOL 4.2 R					
Status: Eroding					
2017 Field Notes: Unable to view due to access issues					
Site History: 2006 - Wave wash erosion and some saturation slumping occurring. Several small scallops present in lower levee slope/toe due to saturation slumping. Tension/separation cracks evident in fine-grained levee slope materials. 2011 - Small pockets of erosion throughout the site. Site formerly called 3.8.					

No Photos

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
----------------------------------------------------------------------------------------------	------------------------------------------------------------------------------------	-------------------------------------------------------------------------------------	-------------------------------------------------------------------------------------------------------------

**Flood Control Project Maintenance  
Levee Inspections**

## Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2020

### Reclamation District No. 2035 Conaway

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Yolo Bypass	Right	7.63	04/01/2020 04/01/2020	Zach Jojola

LM Start	<b>6.35</b>	Rating **	C	Issue No.	<b>31</b>
LM End	<b>6.38</b>	Issue Type +	Ma	Location *	LS
Category	Supplemental		GPS Latitude/Longitude		
			Start	End	
Item	2017 Storm Damage		38.592840 °	38.592390 °	
			-121.631340 °	-121.631320 °	
DWR ID	RD 2035-08				
Comment Code					
Inspector Comment					
Repaired as of inspection date.  Levee Evaluation Comments Description: Site ID No:195 Site Designation:RD 2035-08 Repair Type: Erosion Rating:Critical Field Date:7/13/2017 Notes: long longitudinal cracks on the crown.					

No Photos

LM Start	<b>7.43</b>	Rating **	M	Issue No.	<b>19</b>
LM End	<b>7.60</b>	Issue Type +	Ma	Location *	LS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Vegetation		38.577406 °	38.575472 °	
			-121.633256 °	-121.635076 °	
DWR ID	DWR_RD2035_02_s_2020_19				
Comment Code					
V1 : Control annual grass and weeds on the levee slopes and easements.					
Inspector Comment					

No Photos

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
----------------------------------------------------------------------------------------------	------------------------------------------------------------------------------------	-------------------------------------------------------------------------------------	-------------------------------------------------------------------------------------------------------------

**Flood Control Project Maintenance  
Levee Inspections**

**Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2020**

**Reclamation District No. 2035 Conaway**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Yolo Bypass	Right	7.63	04/01/2020 04/01/2020	Zach Jojola

LM Start	<b>7.43</b>	Rating **	M	Issue No.	<b>20</b>
LM End	<b>7.60</b>	Issue Type +	Ma	Location *	WS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Vegetation		38.577406°	38.575470°	
			-121.633256°	-121.635079°	
DWR ID	DWR_RD2035_02_s_2020_20				
Comment Code					
V1 : Control annual grass and weeds on the levee slopes and easements.					
Inspector Comment					

No Photos

**\* Location**  
 LS : Land Side    N/A : Not Applicable  
 WS : Water Side  
 CR : Crown

**\*\* Rating**  
 A : Acceptable                      N : Not Inspected/Rated  
 M : Minimally Acceptable        C : Corrected  
 U : Unacceptable                  A/W : Acceptable but Monitor & Maintain

**+ Issue Type**  
 Ma : Maintenance Deficiency  
 Ob : Design & System Obsolescence  
 En : Enforcement

**Flood Control Project Maintenance  
Levee Inspections**

**Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2020**

**Reclamation District No. 2035 Conaway**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 Willow Slough Bypass	Left	2.51	04/01/2020 04/01/2020	Zach Jojola

LM Start	0.06	Rating **	M	Issue No.	6
LM End	0.68	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.575647 °	38.579261 °
				-121.636700 °	-121.645196 °
DWR ID	DWR_RD2035_03_s_2020_6				
Comment Code					
V1 : Control annual grass and weeds on the levee slopes and easements.					
Inspector Comment					

No Photos

LM Start	0.06	Rating **	M	Issue No.	7
LM End	0.68	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.575648 °	38.579261 °
				-121.636700 °	-121.645196 °
DWR ID	DWR_RD2035_03_s_2020_7				
Comment Code					
V1 : Control annual grass and weeds on the levee slopes and easements.					
Inspector Comment					

Photo 1 of 1 : SP\_2020\_RD2035\_240\_7\_20200401\_00014.jpg



View of vegetation on the waterside slope. Spring 2020.

LM Start	1.03	Rating **	M	Issue No.	8
LM End	1.42	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.584320 °	38.589808 °
				-121.645089 °	-121.645666 °
DWR ID	DWR_RD2035_03_s_2020_8				
Comment Code					
V1 : Control annual grass and weeds on the levee slopes and easements.					
Inspector Comment					

No Photos

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
----------------------------------------------------------------------------------------------	------------------------------------------------------------------------------------	-------------------------------------------------------------------------------------	-------------------------------------------------------------------------------------------------------------

**Flood Control Project Maintenance  
Levee Inspections**

**Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2020**

**Reclamation District No. 2035 Conaway**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 Willow Slough Bypass	Left	2.51	04/01/2020 04/01/2020	Zach Jojola

LM Start	1.03	Rating **	M	Issue No.	9
LM End	1.75	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.584321 °	38.591172 °
				-121.645089 °	-121.651084 °
DWR ID	DWR_RD2035_03_s_2020_9				
Comment Code					
V1 : Control annual grass and weeds on the levee slopes and easements.					
Inspector Comment					

No Photos

LM Start	1.39	Rating **	M	Issue No.	975
LM End	1.39	Issue Type +	Ma	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP LMA Responsibility			38.589425 °	38.589425 °
				-121.645359 °	-121.645359 °
DWR ID	17836				
Comment Code					
Inspector Comment					
DS_ID:17836 FS_ID:41128 EP_NO: N/A Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: 04/03/2013 Need to clear vegetation and debris from WS at outlet. (W. Wylie - DWR UCIP) FIELD_STRUCT_DESC: 36-inch corrugated metal drainage pipe through the levee, 17.5 feet below the crown. Flap gate on the waterside (WS) end. Slide gate and concrete headwall on the landside (LS) end. [Additional Reference(s): DWR Levee Log, 1990. USACE Sacramento O&M Manual 120, June 1952, (Station 327+75)]. FS Date: 4/3/2013					

Photo 1 of 3 : UCIP\_SP\_2020\_41128\_18348.jpg



Slide gate and headwall in canal at LS toe.

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
----------------------------------------------------------------------------------------------	------------------------------------------------------------------------------------	-------------------------------------------------------------------------------------	-------------------------------------------------------------------------------------------------------------

**Flood Control Project Maintenance  
Levee Inspections**

**Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2020**

**Reclamation District No. 2035 Conaway**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 Willow Slough Bypass	Left	2.51	04/01/2020 04/01/2020	Zach Jojola

LM Start	1.39	Rating **	M	Issue No.	975 (cont)	
LM End	1.39	Issue Type +	Ma	Location *		
Category	Supplemental			GPS Latitude/Longitude		
				Start	End	
Item	DWR UCIP LMA Responsibility			38.589425 °	38.589425 °	
				-121.645359 °	-121.645359 °	
DWR ID	17836					

Photo 2 of 3 : UCIP\_SP\_2020\_41128\_18347.jpg



Slide gate and headwall in canal at LS toe.

LM Start	<b>1.39</b>	Rating **	M	Issue No.	<b>975 (cont)</b>
LM End	<b>1.39</b>	Issue Type +	Ma	Location *	

Photo 3 of 3 : UCIP\_SP\_2020\_41128\_18346.jpg



Vegetated area blocks access to WS of pipe.

LM Start	1.50	Rating **	M	Issue No.	10
LM End	1.70	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.590625 °	38.591202 °
				-121.646648 °	-121.650265 °
DWR ID	DWR_RD2035_03_s_2020_10				
Comment Code					
V1 : Control annual grass and weeds on the levee slopes and easements.					
Inspector Comment					

No Photos

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable	<b>N : Not Inspected/Rated</b> C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
----------------------------------------------------------------------------------------------	------------------------------------------------------------------------------------	--------------------------------------------------------------------------------------------	-------------------------------------------------------------------------------------------------------------

**Flood Control Project Maintenance  
Levee Inspections**

**Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2020**

**Reclamation District No. 2035 Conaway**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 Willow Slough Bypass	Left	2.51	04/01/2020 04/01/2020	Zach Jojola

LM Start	<b>2.17</b>	Rating **	M	Issue No.	<b>976</b>
LM End	<b>2.17</b>	Issue Type +	Ma	Location *	
Category	Supplemental		GPS Latitude/Longitude		
			Start	End	
Item	DWR UCIP LMA Responsibility		38.590934 °	38.590934 °	
			-121.658940 °	-121.658940 °	
DWR ID	17837				

**Comment Code**

**Inspector Comment**

DS\_ID:17837  
 FS\_ID:11011  
 EP\_NO: N/A  
 Repair Type: Non-Urgent  
 Crossing Status: Found  
 UCIP Comments: 04/03/2013 Debris and vegetation partially blocking inlet and outlet at both toes. (W. Wylie - DWR UCIP)  
 FIELD\_STRUCT\_DESC: 48-inch corrugated metal drainage pipe through the levee, 19 feet below the crown. Slide gates on both ends.  
 [Additional Reference(s): DWR Levee Log, 1990. USACE Sacramento O&M Manual 120, June 1952, (Station 290+37)].  
 FS Date: 4/3/2013

LM Start	<b>2.17</b>	Rating **	M	Issue No.	<b>976 (cont)</b>
LM End	<b>2.17</b>	Issue Type +	Ma	Location *	

Photo 1 of 2 : UCIP\_SP\_2020\_11011\_18354.jpg



Slide gate at WS toe showing excessive vegetation.

Photo 2 of 2 : UCIP\_SP\_2020\_11011\_18353.jpg



Slide gate at LS toe showing excessive vegetation.

**\* Location**  
 LS : Land Side    N/A : Not Applicable  
 WS : Water Side  
 CR : Crown

**\*\* Rating**  
 A : Acceptable                      N : Not Inspected/Rated  
 M : Minimally Acceptable        C : Corrected  
 U : Unacceptable                  A/W : Acceptable but Monitor & Maintain

**+ Issue Type**  
 Ma : Maintenance Deficiency  
 Ob : Design & System Obsolescence  
 En : Enforcement

**Flood Control Project Maintenance  
Levee Inspections**

**Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2020**

**Reclamation District No. 2035 Conaway**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 Willow Slough Bypass	Left	2.51	04/01/2020 04/01/2020	Zach Jojola

LM Start	2.19	Rating **	M	Issue No.	977
LM End	2.19	Issue Type +	Ma	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP LMA Responsibility			38.590909 °	38.590909 °
				-121.659311 °	-121.659311 °
DWR ID	17838				
Comment Code					
Inspector Comment					
DS_ID:17838 FS_ID:11012 EP_NO: N/A Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: 04/03/2013 Debris and vegetation partially blocking both ends of pipe. (W. Wylie - DWR UCIP) FIELD_STRUCT_DESC: 36-inch corrugated metal drainage pipe through the levee, 18 feet below the crown. Slide gate on the landside (LS) toe. Combination flap and slide gate on the waterside (WS) toe. [Additional Reference(s): DWR Levee Log, 1990. USACE Sacramento O&M Manual 120, June 1952, (Station 289+33)]. FS Date: 4/3/2013					

LM Start	<b>2.19</b>	Rating **	M	Issue No.	<b>977 (cont)</b>
LM End	<b>2.19</b>	Issue Type +	Ma	Location *	

Photo 1 of 3 : UCIP\_SP\_2020\_11012\_18357.jpg



Combination flap and slide gate on WS toe. With excessive vegetation

Photo 2 of 3 : UCIP\_SP\_2020\_11012\_18356.jpg



Headwall at bottom of fenceline on LS toe

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
----------------------------------------------------------------------------------------------	------------------------------------------------------------------------------------	-------------------------------------------------------------------------------------	-------------------------------------------------------------------------------------------------------------

**Flood Control Project Maintenance  
Levee Inspections**

**Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2020**

**Reclamation District No. 2035 Conaway**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 Willow Slough Bypass	Left	2.51	04/01/2020 04/01/2020	Zach Jojola

LM Start	<b>2.19</b>	Rating **	M	Issue No.	<b>977 (cont)</b>
LM End	<b>2.19</b>	Issue Type +	Ma	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP LMA Responsibility			38.590909 °	38.590909 °
				-121.659311 °	-121.659311 °
DWR ID	17838				

Photo 3 of 3 : UCIP\_SP\_2020\_11012\_18355.jpg



Headwall and pipe on LS toe.

LM Start	2.21	Rating **	M	Issue No.	11
LM End	2.51	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.590896 °	38.590788 °
				-121.659610 °	-121.665157 °
DWR ID	DWR_RD2035_03_s_2020_11				
Comment Code					
V1 : Control annual grass and weeds on the levee slopes and easements.					
Inspector Comment					

No Photos

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
----------------------------------------------------------------------------------------------	------------------------------------------------------------------------------------	-------------------------------------------------------------------------------------	-------------------------------------------------------------------------------------------------------------