

**Flood Control Project Maintenance  
Levee Inspections**

**Fall 2011 Levee Maintenance Deficiency Summary Report**

**Overall LMA & Unit Ratings, including USACE Erosion Survey**

**Sacramento River Basin**

<b>RD2060</b>		Overall LMA Rating	Total LMA Miles				
<b>Reclamation District No. 2060 Hastings</b>		<b>A</b>	<b>15.67</b>				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments		
					PO Miles	CO Miles	
<i>Earthen Levee</i>							
Erosion / Bank Caving	0.01		0.01	0.06%			
Repair Gates	0.01		0.01	0.06%			
<i>Supplemental</i>							
USACE Erosion Survey	0.63		0.63	4.02%			
<i>LMA Totals:</i>	0.65	0.00	0.65	4.15%	0.00	0.00	

  

<b>Unit No. 01 Lindsey Slough LB</b>		Overall Unit Rating	Total Unit Miles				
RD2060		<b>A</b>	<b>6.94</b>				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments		
					PO Miles	CO Miles	
<i>Earthen Levee</i>							
Erosion / Bank Caving	0.01		0.01	0.14%			
Repair Gates	0.01		0.01	0.14%			
<i>Supplemental</i>							
USACE Erosion Survey	0.02		0.02	0.29%			
<i>Unit Totals:</i>	0.04	0.00	0.04	0.58%	0.00	0.00	

  

<b>Unit No. 02 Ulatis Creek RB</b>		Overall Unit Rating	Total Unit Miles				
RD2060		<b>A</b>	<b>3.70</b>				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments		
					PO Miles	CO Miles	
No Items							
<i>Unit Totals:</i>	0.00	0.00	0.00	0.00%	0.00	0.00	

  

<b>Unit No. 03 Cache Slough RB</b>		Overall Unit Rating	Total Unit Miles				
RD2060		<b>M</b>	<b>5.03</b>				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments		
					PO Miles	CO Miles	
<i>Supplemental</i>							
USACE Erosion Survey	0.61		0.61	12.13%			
<i>Unit Totals:</i>	0.61	0.00	0.61	12.13%	0.00	0.00	

**Flood Control Project Maintenance  
Levee Inspections  
LMA District Cover Sheet  
Fall 2011 Levee Inspection Results**

**Reclamation District No. 2060 Hastings**

	Spring (March - May)	Summer ** (June - August)	Fall (September - November)	Winter ** (December - February)
* Overall LMA Rating (Fall Only)			<b>A</b>	

\*\* Non-receipt of Summer or Winter Inspection Reports may effect overall annual rating.

\* **SPRING INSPECTIONS:** Overall maintenance ratings are not determined for the spring inspection results. Individual maintenance deficiencies are rated using the same criteria in the spring and in the fall.

**FALL INSPECTIONS:** The overall maintenance rating shown above is based on operation and maintenance deficiencies identified within the attached unit inspection reports.

Comments


**Flood Control Project Maintenance  
Levee Inspections**

**Unit Cover Sheet**

**Fall 2011 Levee Inspection Results**

**Reclamation District No. 2060 Hastings**

Waterway	Bank	Unit Miles
Unit No. 01 Lindsey Slough	Left	6.94

	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - February)
Unit Maintenance Rating (Fall Only)			<b>A</b>	
Date of Inspection	3/8/2011 - 3/8/2011		10/13/2011 - 10/13/2011	
DWR Inspector	Herman Phillips		Herman Phillips	
Accompanied By	Mark Boyd RD 2060		Mr. Mark Boyd RD 2060 Hastings Tract	

Check one:

During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.

During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

**Comments**

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :  
 DWR Summer/Winter Inspection Reports  
 3310 El Camino Avenue, Suite 200  
 Sacramento, CA 95821-9000


**X** \_\_\_\_\_ Date

Signature of LMA Representative

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Fall 2011**

**Reclamation District No. 2060 Hastings**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Lindsey Slough	Left	6.94	10/13/2011 10/13/2011	Herman Phillips

LMIR No.	Levee Mile		Category	Item	Location *	Rating **	Action/Comment	GPS Latitude/Longitude		Issue No. Photo
	Start	End						Start	End	
1	0.00	0.00	Earthen Levee	Vegetation	LS	A	Remove the wild growth other than native grasses from the levee slopes. Inspector Comments: RD 2060 has done a great job maintaining the levees.	38.247554 ° -121.696222 °	38.247554 ° -121.696220 °	2 Y
2	0.01	0.03	Earthen Levee	Trim / Thin Trees	WS	C	Trim trees to at least five feet above ground level.	38.247368 ° -121.696743 °	38.247328 ° -121.697022 °	1
3	0.03	0.03	Earthen Levee	Vegetation	WS	A	Remove the wild growth other than native grasses from the levee slopes.	38.247278 ° -121.697098 °	38.247278 ° -121.697098 °	3 Y
4	0.56	0.57	Earthen Levee	Erosion / Bank Caving	WS	M	Note and monitor erosion site. Inspector Comments: District has placed some more rock in this area, they will place more later. 3-08,2011 viewed the erosion site, this site is still active. District say that they will make repairs end of April or May 2011.	38.248630 ° -121.706403 °	38.248617 ° -121.706667 °	14
5	1.70	1.70	Supplemental	USACE Erosion Survey	WS	M	Inspector Comments: 2011: Multiple erosion pockets. Deep cracks throughout site could lead to further bank failure. [2011 Site ID: LDS_1-9_L]	38.256535 ° -121.724753 °	38.257517 ° -121.724823 °	4 Y
6	2.34	2.34	Supplemental	USACE Erosion Survey	WS	M	Inspector Comments: 2011: Two erosion pockets from rotational failures. Very soft soil. [2011 Site ID: LDS_2-4_L]	38.257224 ° -121.731953 °	38.257319 ° -121.732423 °	5 Y
7	5.07	5.07	Earthen Levee	Repair Gates	CR	M		38.263157 ° -121.771543 °	38.263157 ° -121.771543 °	6

<p><b>* Location</b></p> <p>LS : Land Side WS : Water Side CR : Crown</p>	<p><b>** Rating</b></p> <p>A : Acceptable      PO : Partially Obstructing      N : Not Inspected, see Inspector Comment      C : Corrected M : Minimally Acceptable      CO : Completely Obstructing U : Unacceptable      W : Watch/Monitor</p>
---	--

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Fall 2011**

**Reclamation District No. 2060 Hastings**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Lindsey Slough	Left	6.94	10/13/2011 10/13/2011	Herman Phillips

Levee Mile Report Line	1
Start Levee Mile	0.00
End Levee Mile	0.00
Location	Land Side
Category	Earthen Levee
Item	Vegetation
Standing on landside Unit 1 RD 2060 looking downstream L/M 0.00. Photo taken 10-13-2011.	
phillips_f_20111013_011.jpg	



Levee Mile Report Line	3
Start Levee Mile	0.03
End Levee Mile	0.03
Location	Water Side
Category	Earthen Levee
Item	Vegetation
Standing on waterside Unit 1 RD 2060 L/M 0.03 looking downstream. Photo taken 10-13-2011.	
phillips_f_20111013_012.jpg	



Levee Mile Report Line	5
Start Levee Mile	1.70
End Levee Mile	1.70
Location	Water Side
Category	Supplemental
Item	USACE Erosion Survey
USACE 2011 Photo #1	
USACE2011_LDS_1-9_L_1.jpg	



<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable	PO : Partially Obstructing CO : Completely Obstructing W : Watch/Monitor	N : Not Inspected, see Inspector Comment C : Corrected
--	--	--	---

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Fall 2011**

**Reclamation District No. 2060 Hastings**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Lindsey Slough	Left	6.94	10/13/2011 10/13/2011	Herman Phillips

Levee Mile Report Line	5
Start Levee Mile	1.70
End Levee Mile	1.70
Location	Water Side
Category	Supplemental
Item	USACE Erosion Survey
USACE 2011 Photo #2	
USACE2011_LDS_1-9_L_2.jpg	



Levee Mile Report Line	5
Start Levee Mile	1.70
End Levee Mile	1.70
Location	Water Side
Category	Supplemental
Item	USACE Erosion Survey
USACE 2011 Photo #3	
USACE2011_LDS_1-9_L_3.jpg	



Levee Mile Report Line	6
Start Levee Mile	2.34
End Levee Mile	2.34
Location	Water Side
Category	Supplemental
Item	USACE Erosion Survey
USACE 2011 Photo #1	
USACE2011_LDS_2-4_L_1.jpg	



<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable	PO : Partially Obstructing CO : Completely Obstructing W : Watch/Monitor	N : Not Inspected, see Inspector Comment C : Corrected
--	--	--	---

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Fall 2011**

**Reclamation District No. 2060 Hastings**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Lindsey Slough	Left	6.94	10/13/2011 10/13/2011	Herman Phillips

Levee Mile Report Line	6
Start Levee Mile	2.34
End Levee Mile	2.34
Location	Water Side
Category	Supplemental
Item	USACE Erosion Survey
USACE 2011 Photo #2	
USACE2011_LDS_2-4_L_2.jpg	



Levee Mile Report Line	6
Start Levee Mile	2.34
End Levee Mile	2.34
Location	Water Side
Category	Supplemental
Item	USACE Erosion Survey
USACE 2011 Photo #3	
USACE2011_LDS_2-4_L_3.jpg	



<p><b>* Location</b></p> <p>LS : Land Side WS : Water Side CR : Crown</p>	<p><b>** Rating</b></p> <p>A : Acceptable      PO : Partially Obstructing      N : Not Inspected, see Inspector Comment      C : Corrected M : Minimally Acceptable      CO : Completely Obstructing U : Unacceptable      W : Watch/Monitor</p>
---	--

**Flood Control Project Maintenance  
Levee Inspections**

**Unit Cover Sheet**

**Fall 2011 Levee Inspection Results**

**Reclamation District No. 2060 Hastings**

Waterway	Bank	Unit Miles
Unit No. 02 Ulatis Creek	Right	3.70

	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - February)
Unit Maintenance Rating (Fall Only)			<b>A</b>	
Date of Inspection	3/8/2011 - 3/8/2011		10/13/2011 - 10/13/2011	
DWR Inspector	Herman Phillips		Herman Phillips	
Accompanied By	Mark Boyd RD 2060		Mr. Mark Boyd RD 2060 Hasting Tract	

Check one:

During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.

During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

**Comments**

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :

DWR Summer/Winter Inspection Reports  
3310 El Camino Avenue, Suite 200  
Sacramento, CA 95821-9000


**X** \_\_\_\_\_ Date

Signature of LMA Representative

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Fall 2011**

**Reclamation District No. 2060 Hastings**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Ulatis Creek	Right	3.70	10/13/2011 10/13/2011	Herman Phillips

LMIR No.	Levee Mile		Category	Item	Location	Rating	Action/Comment	GPS Latitude/Longitude		Issue No. Photo
	Start	End						Start	End	
1	0.00	0.00	Earthen Levee	Vegetation	LS	A	Remove the wild growth other than native grasses from the levee slopes. Inspector Comments: Unit 2 is well maintained, no problems.	38.276269 ° -121.795888 °	38.276269 ° -121.795888 °	1 Y
2	0.00	0.00	Earthen Levee	Vegetation	WS	A	Remove the wild growth other than native grasses from the levee slopes.	38.276269 ° -121.795888 °	38.276269 ° -121.795888 °	2 Y

<p><b>* Location</b></p> <p>LS : Land Side WS : Water Side CR : Crown</p>	<p><b>** Rating</b></p> <p>A : Acceptable      PO : Partially Obstructing      N : Not Inspected, see Inspector Comment      C : Corrected M : Minimally Acceptable      CO : Completely Obstructing U : Unacceptable      W : Watch/Monitor</p>
---	--

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Fall 2011**

**Reclamation District No. 2060 Hastings**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Ulatis Creek	Right	3.70	10/13/2011 10/13/2011	Herman Phillips

Levee Mile Report Line	1
Start Levee Mile	0.00
End Levee Mile	0.00
Location	Land Side
Category	Earthen Levee
Item	Vegetation
Standing on waterward shoulder of RD 2060 looking downstream from L/M 0.00. This photo was taken 10-13-2011.	
phillips_f_20111013_013.jpg	



Levee Mile Report Line	2
Start Levee Mile	0.00
End Levee Mile	0.00
Location	Water Side
Category	Earthen Levee
Item	Vegetation
Standing on landward side of Unit 2 looking downstream from L/M 0.00 RD 2060. Photo taken 10-13-2011.	
phillips_f_20111013_014.jpg	



<p><b>* Location</b></p> <p>LS : Land Side WS : Water Side CR : Crown</p>	<p><b>** Rating</b></p> <p>A : Acceptable      PO : Partially Obstructing      N : Not Inspected, see Inspector Comment      C : Corrected M : Minimally Acceptable      CO : Completely Obstructing U : Unacceptable      W : Watch/Monitor</p>
---	--

**Flood Control Project Maintenance  
Levee Inspections**

**Unit Cover Sheet**

**Fall 2011 Levee Inspection Results**

**Reclamation District No. 2060 Hastings**

Waterway	Bank	Unit Miles
Unit No. 03 Cache Slough	Right	5.03

	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - February)
Unit Maintenance Rating (Fall Only)			<b>M</b>	
Date of Inspection	3/8/2011 - 3/8/2011		10/13/2011 - 10/13/2011	
DWR Inspector	Herman Phillips		Herman Phillips	
Accompanied By	Mark Boyd RD 2060		Mr. Mark Boyd RD 2060 Hasting Tract	

Check one:

- During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.
- During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

**Comments**

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :

DWR Summer/Winter Inspection Reports  
3310 El Camino Avenue, Suite 200  
Sacramento, CA 95821-9000


**X**

Signature of LMA Representative

Date

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Fall 2011**

**Reclamation District No. 2060 Hastings**

Waterway				Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 Cache Slough				Right	5.03	10/13/2011 10/13/2011	Herman Phillips

LMIR No.	Levee Mile		Category	Item	Location	Rating	Action/Comment	GPS Latitude/Longitude		Issue No. Photo
	Start	End						Start	End	
1	0.00	0.00	Earthen Levee	Vegetation	WS	A	Remove the wild growth other than native grasses from the levee slopes. Inspector Comments: Both landward and waterward levee slopes looks good.	38.295814 ° -121.746896 °	38.295814 ° -121.746896 °	1 Y
2	0.00	0.00	Earthen Levee	Vegetation	LS	A	Remove the wild growth other than native grasses from the levee slopes.	38.295814 ° -121.746896 °	38.295814 ° -121.746896 °	2 Y
3	0.04	0.56	Earthen Levee	Vegetation	CR	C	Remove the wild growth other than native grasses from the levee slopes.	38.296485 ° -121.748137 °	38.291878 ° -121.741010 °	3 Y
4	1.54	1.63	Supplemental	USACE Erosion Survey	WS	M	Inspector Comments: Site added in 1997 and removed in 2003. 2005 - Put back in the inventory. 2006 - Stone repair at the middle of the site. 2011: Some rock has been placed at toe in the past year. [2011 Site ID: CHS_23-6_R]	38.288192 ° -121.724806 °	38.286418 ° -121.723168 °	4 Y
5	1.95	1.95	Supplemental	USACE Erosion Survey	WS	M	Inspector Comments: 2010 - Small maintenance site. 2011: No observed change. [2011 Site ID: CHS_23-0_R]	38.283302 ° -121.717814 °	38.284105 ° -121.718471 °	5 Y
6	2.10	2.20	Supplemental	USACE Erosion Survey	WS	M	Inspector Comments: 2007 - Geotechnical failure of midside slope and wave wash/scalloping in toe area. Stone revetment upstream and downstream of site. Similar sites are present all along the right bank downstream of this site, most could be repaired with some maintenance. 2010 - Minor new erosion. 2011: No observed change. [2011 Site ID: CHS_22-8_R]	38.282100 ° -121.716817 °	38.281510 ° -121.716319 °	8 Y
7	2.28	2.48	Supplemental	USACE Erosion Survey	WS	M	Inspector Comments: 2008 - Small scour pockets and mid-slope wave wash. 2010 - More vegetation growth, could be fixed through maintenance. 2011: site extended downstream. new erosion. [2011 Site ID: CHS_22-6_R]	38.280377 ° -121.714633 °	38.278306 ° -121.712722 °	10 Y
8	3.67	3.88	Supplemental	USACE Erosion Survey	WS	M	Inspector Comments: 2011: Several large pockets of erosion from rotational failure. Toe is slumping. [2011 Site ID: CHS_21-1_R]	38.264585 ° -121.698868 °	38.261616 ° -121.697423 °	11 Y
9	3.76	3.76	Earthen Levee	Encroachments	WS	C	Debris	38.264713 ° -121.699262 °	38.264713 ° -121.699262 °	6 Y

<p><b>* Location</b></p> <p>LS : Land Side WS : Water Side CR : Crown</p>	<p><b>** Rating</b></p> <p>A : Acceptable M : Minimally Acceptable U : Unacceptable</p>	<p>PO : Partially Obstructing CO : Completely Obstructing W : Watch/Monitor</p>	<p>N : Not Inspected, see Inspector Comment C : Corrected</p>
---	---	---	---

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Fall 2011**

**Reclamation District No. 2060 Hastings**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 Cache Slough	Right	5.03	10/13/2011 10/13/2011	Herman Phillips

Levee Mile Report Line	1
Start Levee Mile	0.00
End Levee Mile	0.00
Location	Water Side
Category	Earthen Levee
Item	Vegetation
Standing on the waterward shoulder L/M 0.00 looking downstream RD 2060 Unit 3. Photo taken 10-13-2011.	
phillips_f_20111013_015.jpg	



Levee Mile Report Line	2
Start Levee Mile	0.00
End Levee Mile	0.00
Location	Land Side
Category	Earthen Levee
Item	Vegetation
Standing on the landward shoulder looking downstream from L/M 0.00 Unit 3 RD 2060. Photo taken 10-13-2011.	
phillips_f_20111013_016.jpg	



Levee Mile Report Line	4
Start Levee Mile	1.54
End Levee Mile	1.63
Location	Water Side
Category	Supplemental
Item	USACE Erosion Survey
USACE 2011 Photo #1	
USACE2011_CHS_23-6_R_1.jpg	



<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable	PO : Partially Obstructing CO : Completely Obstructing W : Watch/Monitor	N : Not Inspected, see Inspector Comment C : Corrected
--	--	--	---

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Fall 2011**

**Reclamation District No. 2060 Hastings**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 Cache Slough	Right	5.03	10/13/2011 10/13/2011	Herman Phillips

Levee Mile Report Line	4
Start Levee Mile	1.54
End Levee Mile	1.63
Location	Water Side
Category	Supplemental
Item	USACE Erosion Survey
USACE 2011 Photo #2	
USACE2011_CHS_23-6_R_2.jpg	



Levee Mile Report Line	5
Start Levee Mile	1.95
End Levee Mile	1.95
Location	Water Side
Category	Supplemental
Item	USACE Erosion Survey
USACE 2011 Photo #1	
USACE2011_CHS_23-0_R_1.jpg	



Levee Mile Report Line	5
Start Levee Mile	1.95
End Levee Mile	1.95
Location	Water Side
Category	Supplemental
Item	USACE Erosion Survey
USACE 2011 Photo #2	
USACE2011_CHS_23-0_R_2.jpg	



<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable	PO : Partially Obstructing CO : Completely Obstructing W : Watch/Monitor	N : Not Inspected, see Inspector Comment C : Corrected
--	--	--	---

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Fall 2011**

**Reclamation District No. 2060 Hastings**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 Cache Slough	Right	5.03	10/13/2011 10/13/2011	Herman Phillips

Levee Mile Report Line	5
Start Levee Mile	1.95
End Levee Mile	1.95
Location	Water Side
Category	Supplemental
Item	USACE Erosion Survey
USACE 2011 Photo #3	
USACE2011_CHS_23-0_R_3.jpg	



Levee Mile Report Line	6
Start Levee Mile	2.10
End Levee Mile	2.20
Location	Water Side
Category	Supplemental
Item	USACE Erosion Survey
USACE 2011 Photo #1	
USACE2011_CHS_22-8_R_1.jpg	



Levee Mile Report Line	6
Start Levee Mile	2.10
End Levee Mile	2.20
Location	Water Side
Category	Supplemental
Item	USACE Erosion Survey
USACE 2011 Photo #2	
USACE2011_CHS_22-8_R_2.jpg	



<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable	PO : Partially Obstructing CO : Completely Obstructing W : Watch/Monitor	N : Not Inspected, see Inspector Comment C : Corrected
--	--	--	---

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Fall 2011**

**Reclamation District No. 2060 Hastings**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 Cache Slough	Right	5.03	10/13/2011 10/13/2011	Herman Phillips

Levee Mile Report Line	6
Start Levee Mile	2.10
End Levee Mile	2.20
Location	Water Side
Category	Supplemental
Item	USACE Erosion Survey
USACE 2011 Photo #3	
USACE2011_CHS_22-8_R_3.jpg	



Levee Mile Report Line	7
Start Levee Mile	2.28
End Levee Mile	2.48
Location	Water Side
Category	Supplemental
Item	USACE Erosion Survey
USACE 2011 Photo #1	
USACE2011_CHS_22-6_R_1.jpg	



Levee Mile Report Line	7
Start Levee Mile	2.28
End Levee Mile	2.48
Location	Water Side
Category	Supplemental
Item	USACE Erosion Survey
USACE 2011 Photo #2	
USACE2011_CHS_22-6_R_2.jpg	



<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable	PO : Partially Obstructing CO : Completely Obstructing W : Watch/Monitor	N : Not Inspected, see Inspector Comment C : Corrected
--	--	--	---

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Fall 2011**

**Reclamation District No. 2060 Hastings**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 Cache Slough	Right	5.03	10/13/2011 10/13/2011	Herman Phillips

Levee Mile Report Line	8
Start Levee Mile	3.67
End Levee Mile	3.88
Location	Water Side
Category	Supplemental
Item	USACE Erosion Survey
USACE 2011 Photo #1	
USACE2011_CHS_21-1_R_1.jpg	



Levee Mile Report Line	8
Start Levee Mile	3.67
End Levee Mile	3.88
Location	Water Side
Category	Supplemental
Item	USACE Erosion Survey
USACE 2011 Photo #2	
USACE2011_CHS_21-1_R_2.jpg	



Levee Mile Report Line	8
Start Levee Mile	3.67
End Levee Mile	3.88
Location	Water Side
Category	Supplemental
Item	USACE Erosion Survey
USACE 2011 Photo #3	
USACE2011_CHS_21-1_R_3.jpg	



<p><b>* Location</b></p> <p>LS : Land Side WS : Water Side CR : Crown</p>	<p><b>** Rating</b></p> <p>A : Acceptable M : Minimally Acceptable U : Unacceptable</p>	<p>PO : Partially Obstructing CO : Completely Obstructing W : Watch/Monitor</p>	<p>N : Not Inspected, see Inspector Comment C : Corrected</p>
---	---	---	---