

**Flood Control Project Maintenance  
Levee Inspections**

**Fall 2008 Levee Maintenance Deficiency Summary Report**

**Overall LMA & Unit Ratings, including Boat Survey Erosion**

**San Joaquin River Basin**

<b>RD2064</b>	Overall LMA Rating	Total LMA Miles				
<b>Reclamation District No. 2064</b>	<b>M</b>	<b>11.90</b>				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
Encroachments					0.06	
Animal Control	1.30		1.30	10.92%		
Erosion / Bank Caving	0.01		0.01	0.08%		
<i>LMA Totals:</i>	1.31	0.00	1.31	11.01%	0.06	0.00
<b>Unit No. 01 San Joaquin River</b>	Overall Unit Rating	Total Unit Miles				
	<b>U</b>	<b>5.70</b>				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
Animal Control	1.30		1.30	22.81%		
<i>Unit Totals:</i>	1.30	0.00	1.30	22.81%	0.00	0.00
<b>Unit No. 02 Stanislaus River</b>	Overall Unit Rating	Total Unit Miles				
	<b>A</b>	<b>6.20</b>				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
Encroachments					0.06	
Erosion / Bank Caving	0.01		0.01	0.16%		
<i>Unit Totals:</i>	0.01	0.00	0.01	0.16%	0.06	0.00

**Flood Control Project Maintenance  
Levee Inspections  
LMA District Cover Sheet  
Fall 2008 Levee Inspection Results**

**Reclamation District No. 2064**

	Spring (March - May)	Summer ** (June - August)	Fall (September - November)	Winter ** (December - February)
* Overall LMA Rating (Fall Only)			<b>M</b>	

\*\* Non-receipt of Summer or Winter Inspection Reports may effect overall annual rating.

\* **SPRING INSPECTIONS:** Overall maintenance ratings are not determined for the spring inspection results. Individual maintenance deficiencies are rated using the same criteria in the spring and in the fall.

**FALL INSPECTIONS:** The overall maintenance rating shown above is based on operation and maintenance deficiencies identified within the attached unit inspection reports.

Comments


**Flood Control Project Maintenance  
Levee Inspections  
Unit Cover Sheet  
Fall 2008 Levee Inspection Results  
Reclamation District No. 2064**

Waterway		Bank	Unit Miles
Unit No. 01 San Joaquin River		Right	5.70

	Spring (March - May)	Summer (June - August)	Fall (September - November)	Winter (December - February)
Date of Inspection	3/10/2008		10/10/2008	
DWR Inspector	Herman Phillips		Herman Phillips	
Accompanied By				
Unit Maintenance Rating (Fall Only)			<b>U</b>	

Check one:

During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.

During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

Comments

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to : DWR Summer/Winter Inspection Reports  
3310 El Camino Avenue, Room LL-30  
Sacramento, CA 95821-9000.


**X** \_\_\_\_\_  
Signature of LMA Representative Date

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Fall 2008**

**Reclamation District No. 2064**

Waterway				Bank	Unit Miles	Inspection Date	Inspector
Unit No. 01 San Joaquin River				Right	5.70	10/10/2008	Herman Phillips

  

LMR Line	Levee Mile		Category	Item	* Location	** Rating	Action/Comment	GPS Latitude/Longitude		Photo	Issue
	Start	End						Start	End		
1	2.71	4.01	Earthen Levee	Animal Control	LS	M	Exterminate rodents and backfill and compact or grout burrows.	37.684727 °	37.673140 °		24
								-121.255687 °	-121.258358 °		

<p><b>* Location</b></p> <p>LS : Land Side                  WS : Water Side                  CR : Crown</p>	<p><b>** Rating</b></p> <p>A : Acceptable      PO : Partially Obstructing                  M : Minimally Acceptable      CO : Completely Obstructing                  U : Unacceptable      N : Not Inspected</p>
---	---

**Flood Control Project Maintenance  
Levee Inspections  
Unit Cover Sheet  
Fall 2008 Levee Inspection Results  
Reclamation District No. 2064**

Waterway		Bank	Unit Miles
Unit No. 02 Stanislaus River		Right	6.20

	Spring (March - May)	Summer (June - August)	Fall (September - November)	Winter (December - February)
Date of Inspection	3/11/2008		10/10/2008	
DWR Inspector	Herman Phillips		Herman Phillips	
Accompanied By				
Unit Maintenance Rating (Fall Only)			A	

Check one:

During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.

During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

Comments

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :  
 DWR Summer/Winter Inspection Reports  
 3310 El Camino Avenue, Room LL-30  
 Sacramento, CA 95821-9000.


**X** \_\_\_\_\_  
 Signature of LMA Representative Date

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Fall 2008**

**Reclamation District No. 2064**

Waterway				Bank	Unit Miles	Inspection Date	Inspector
Unit No. 02 Stanislaus River				Right	6.20	10/10/2008	Herman Phillips

  

LMR Line	Levee Mile		Category	Item	* Location	** Rating	Action/Comment	GPS Latitude/Longitude		Photo	Issue
	Start	End						Start	End		
1	0.09	0.15	Earthen Levee	Encroachments	WS PO	Fences		37.666670 ° -121.239590 °	37.666542 ° -121.238550 °		1
2	0.88	0.88	Earthen Levee	Erosion / Bank Caving	WS	M	Note and monitor erosion site. Inspector Comments: This is a old reported site however its hqsn't been corrected yet District reported it before.	37.666283 ° -121.230253 °	37.666283 ° -121.230253 °		31

<p><b>* Location</b></p> <p>LS : Land Side WS : Water Side CR : Crown</p>	<p><b>** Rating</b></p> <p>A : Acceptable M : Minimally Acceptable U : Unacceptable</p> <p>PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected</p>
---	---