

**Flood Control Project Maintenance  
Levee Inspections**  
**LMA District Cover Sheet**  
**Spring 2009 Levee Inspection Results**

**Reclamation District No. 2064**

	Spring (March - May)	Summer ** (June - August)	Fall (September - November)	Winter ** (December - February)
* Overall LMA Rating (Fall Only)				

\*\* Non-receipt of Summer or Winter Inspection Reports may effect overall annual rating.

\* **SPRING INSPECTIONS:** Overall maintenance ratings are not determined for the spring inspection results. Individual maintenance deficiencies are rated using the same criteria in the spring and in the fall.

**FALL INSPECTIONS:** The overall maintenance rating shown above is based on operation and maintenance deficiencies identified within the attached unit inspection reports.

Comments


**Flood Control Project Maintenance  
Levee Inspections  
Unit Cover Sheet  
Spring 2009 Levee Inspection Results  
Reclamation District No. 2064**

Waterway		Bank	Unit Miles
Unit No. 01 San Joaquin River		Right	5.70

	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - February)
Unit Maintenance Rating (Fall Only)				
Date of Inspection	3/11/2009 - 3/11/2009			
DWR Inspector	Herman Phillips			
Accompanied By	Mr. Roy Boyd Reclamation District 2064			

Check one:

During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.

During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

Comments

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :

DWR Summer/Winter Inspection Reports  
3310 El Camino Avenue, Room LL-30  
Sacramento, CA 95821-9000.


**X** \_\_\_\_\_  
Signature of LMA Representative Date

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2009**

**Reclamation District No. 2064**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River	Right	5.70	03/11/2009 03/11/2009	Herman Phillips

LMR Line	Levee Mile		Category	Item	Location *	Rating **	Action/Comment	GPS Latitude/Longitude		Photo	Issue
	Start	End						Start	End		
1	2.71	4.01	Earthen Levee	Animal Control	LS	C	Exterminate rodents and backfill and compact or grout burrows. Inspector Comments: The District has increased their bait stations and has stepped up their attack on the rodents along with backfilling the existing holes. Good job.	37.684727 °	37.673140 °		24
								-121.255687 °	-121.258358 °		

**\* Location**  
 LS : Land Side  
 WS : Water Side  
 CR : Crown

**\*\* Rating**  
 A : Acceptable      PO : Partially Obstructing      C : Corrected  
 M : Minimally Acceptable      CO : Completely Obstructing  
 U : Unacceptable      N : Not Inspected

**Flood Control Project Maintenance  
Levee Inspections  
Unit Cover Sheet  
Spring 2009 Levee Inspection Results  
Reclamation District No. 2064**

Waterway		Bank	Unit Miles
Unit No. 02 Stanislaus River		Right	6.20

	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - February)
Unit Maintenance Rating (Fall Only)				
Date of Inspection	3/11/2009 - 3/11/2009			
DWR Inspector	Herman Phillips			
Accompanied By				

Check one:

During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.

During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

Comments

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :

DWR Summer/Winter Inspection Reports  
3310 El Camino Avenue, Room LL-30  
Sacramento, CA 95821-9000.


**X** \_\_\_\_\_  
Signature of LMA Representative Date

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2009**

**Reclamation District No. 2064**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Stanislaus River	Right	6.20	03/11/2009 03/11/2009	Herman Phillips

LMR Line	Levee Mile		Category	Item	Location *	Rating **	Action/Comment	GPS Latitude/Longitude		Photo	Issue
	Start	End						Start	End		
1	0.09	0.15	Earthen Levee	Encroachments	WS	C	Fences Inspector Comments: The District has sent out letters to land owner requesting that he remove the fence from within the 10-foot easement on the land side of the levee.	37.666670 ° -121.239590 °	37.666542 ° -121.238550 °		1
2	0.88	0.88	Earthen Levee	Erosion / Bank Caving	WS	M	Note and monitor erosion site. Inspector Comments: This is a old reported site however its hasn't been corrected yet District reported it before.	37.666283 ° -121.230253 °	37.666283 ° -121.230253 °		31

**\* Location**  
 LS : Land Side  
 WS : Water Side  
 CR : Crown

**\*\* Rating**  
 A : Acceptable      PO : Partially Obstructing      C : Corrected  
 M : Minimally Acceptable      CO : Completely Obstructing  
 U : Unacceptable      N : Not Inspected