

**Flood Control Project Maintenance  
Levee Inspections**

## Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2014

### Reclamation District No. 2064 River Junction

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River	Right	5.56	10/28/2014 10/28/2014	Herman Phillips

LM Start		Rating **	A	Issue No.	6		
LM End		Issue Type +	Ma	Location *	LS		
Category	Earthen Levee			GPS Latitude/Longitude			
				Start		End	
Item	Operations & Maintenance Manuals				°		°
					°		°
DWR ID	DWR_RD2064_01_f_2014_6						
Action/Comments							
Inspector Comments: District 2064 has the O&M Manual on hand.							

No Photos

LM Start		Rating **	A	Issue No.	7
LM End		Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Emergency Supplies & Equipment				°
					°
DWR ID	DWR_RD2064_01_f_2014_7				
Action/Comments					
Inspector Comments: District has an adequate supply of flood fight materials in storage.					

No Photos

LM Start		Rating **	A	Issue No.	8		
LM End		Issue Type +	Ma	Location *	LS		
Category	Earthen Levee			GPS Latitude/Longitude			
				Start		End	
Item	Flood Preparedness & Training				°		°
					°		°
DWR ID	DWR_RD2064_01_f_2014_8						
Action/Comments							
Inspector Comments: District 2064 has been trained for flood fighting.							

No Photos

**\* Location**  
 LS : Land Side    N/A : Not Applicable  
 WS : Water Side  
 CR : Crown

**\*\* Rating**  
 A : Acceptable  
 M : Minimally Acceptable  
 U : Unacceptable  
 N : Not Inspected/Rated  
 C : Corrected  
 A/W : Acceptable but Monitor & Maintain

**+ Issue Type**  
 Ma : Maintenance Deficiency  
 Ob : Design & System Obsolescence  
 En : Enforcement

**Flood Control Project Maintenance  
Levee Inspections**

**Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2014**

**Reclamation District No. 2064 River Junction**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River	Right	5.56	10/28/2014 10/28/2014	Herman Phillips

LM Start	0.09	Rating **	A	Issue No.	1
LM End	5.70	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			37.709528 °	37.667195 °
				-121.267532 °	-121.241052 °
DWR ID	DWR_RD2064_01_f_2014_1				
Action/Comments					
Control annual grass and weeds on the levee slopes and easements. Inspector Comments: District has cleaned the slopes, no unwanted vegetation.					

No Photos

LM Start	0.09	Rating **	A	Issue No.	2
LM End	5.70	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			37.709528 °	37.667195 °
				-121.267532 °	-121.241052 °
DWR ID	DWR_RD2064_01_f_2014_2				
Action/Comments					
Control annual grass and weeds on the levee slopes and easements. Inspector Comments: RD 2064 has mowed the slopes and sprayed for wild weeds.					

Photo 1 of 1 : FA\_2014\_RD2064\_313\_2\_20141104\_00001.jpg



Looking downstream from waterside slope levee mile 0.09.

LM Start	3.67	Rating **	M	Issue No.	4
LM End	3.67	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			37.675258 °	37.675258 °
				-121.263440 °	-121.263440 °
DWR ID	DWR_RD2064_01_f_2014_4				
Action/Comments					
Remove the wild growth other than native grasses from the levee slopes.					

No Photos

**\* Location**  
LS : Land Side    N/A : Not Applicable  
WS : Water Side  
CR : Crown

**\*\* Rating**  
A : Acceptable                      N : Not Inspected/Rated  
M : Minimally Acceptable        C : Corrected  
U : Unacceptable                  A/W : Acceptable but Monitor & Maintain

**+ Issue Type**  
Ma : Maintenance Deficiency  
Ob : Design & System Obsolescence  
En : Enforcement

**Flood Control Project Maintenance  
Levee Inspections**

**Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2014**

**Reclamation District No. 2064 River Junction**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River	Right	5.56	10/28/2014 10/28/2014	Herman Phillips

LM Start	5.70	Rating **	A/W	Issue No.	3
LM End	5.70	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			37.667195 °	37.667195 °
				-121.241052 °	-121.241052 °
DWR ID	DWR_RD2064_01_f_2014_3				
Action/Comments					
Control annual grass and weeds on the levee slopes and easements.					

No Photos

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
----------------------------------------------------------------------------------------------	------------------------------------------------------------------------------------	-------------------------------------------------------------------------------------	-------------------------------------------------------------------------------------------------------------

**Flood Control Project Maintenance  
Levee Inspections**

**Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2014**

**Reclamation District No. 2064 River Junction**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Stanislaus River	Right	6.08	10/28/2014 10/28/2014	Herman Phillips

LM Start	0.00	Rating **	M	Issue No.	2
LM End	6.20	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			37.667068 °	37.704049 °
				-121.240899 °	-121.181042 °
DWR ID	DWR_RD2064_02_s_2012_2				
Action/Comments					
Control annual grass and weeds on the levee slopes and easements.					

Photo 1 of 1 : FA\_2014\_RD2064\_314\_2\_20141104\_00015.jpg



Looking downstream from levee mile 0.00 at the landside slope.

LM Start	0.47	Rating **	C	Issue No.	14
LM End	0.47	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			37.664052 °	37.664052 °
				-121.234382 °	-121.234382 °
DWR ID	DWR_RD2064_02_f_2013_14				
Action/Comments					
Trim trees to at least five feet above ground level.					

No Photos

LM Start	0.69	Rating **	M	Issue No.	28
LM End	1.34	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			37.663697 °	37.670097 °
				-121.230898 °	-121.226397 °
DWR ID	DWR_RD2064_02_f_2014_28				
Action/Comments					
Remove the wild growth other than native grasses from the levee slopes.					

No Photos

**\* Location**  
 LS : Land Side    N/A : Not Applicable  
 WS : Water Side  
 CR : Crown

**\*\* Rating**  
 A : Acceptable                      N : Not Inspected/Rated  
 M : Minimally Acceptable        C : Corrected  
 U : Unacceptable                  A/W : Acceptable but Monitor & Maintain

**+ Issue Type**  
 Ma : Maintenance Deficiency  
 Ob : Design & System Obsolescence  
 En : Enforcement

**Flood Control Project Maintenance  
Levee Inspections**

**Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2014**

**Reclamation District No. 2064 River Junction**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Stanislaus River	Right	6.08	10/28/2014 10/28/2014	Herman Phillips

LM Start	2.26	Rating **	N	Issue No.	8
LM End	2.26	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			37.679930 °	37.679930 °
				-121.223220 °	-121.223220 °
DWR ID	DWR_RD2064_02_s_2012_8				
Action/Comments					
Tree stumps.					

No Photos

LM Start	2.27	Rating **	N	Issue No.	9
LM End	2.27	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			37.679988 °	37.679988 °
				-121.223340 °	-121.223340 °
DWR ID	DWR_RD2064_02_s_2012_9				
Action/Comments					
Tree stumps.					

No Photos

LM Start	2.35	Rating **	C	Issue No.	10
LM End	2.35	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			37.680025 °	37.680025 °
				-121.223783 °	-121.223783 °
DWR ID	DWR_RD2064_02_s_2012_10				
Action/Comments					
Tree stumps.					
Inspector Comments: This stump actually is off the toe waterward.					

No Photos

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
----------------------------------------------------------------------------------------------	------------------------------------------------------------------------------------	-------------------------------------------------------------------------------------	-------------------------------------------------------------------------------------------------------------

**Flood Control Project Maintenance  
Levee Inspections**

**Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2014**

**Reclamation District No. 2064 River Junction**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Stanislaus River	Right	6.08	10/28/2014 10/28/2014	Herman Phillips

LM Start	2.86	Rating **	C	Issue No.	17
LM End	2.94	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			37.685525 °	37.686269 °
				-121.219798 °	-121.218940 °
DWR ID	DWR_RD2064_02_f_2013_17				
Action/Comments					
Remove the wild growth other than native grasses from the levee slopes.					

No Photos

LM Start	3.09	Rating **	N	Issue No.	11
LM End	3.09	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			37.687722 °	37.687722 °
				-121.217045 °	-121.217045 °
DWR ID	DWR_RD2064_02_s_2012_11				
Action/Comments					
Tree stumps.					

No Photos

LM Start	4.18	Rating **	N	Issue No.	12
LM End	4.18	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			37.694172 °	37.694172 °
				-121.207255 °	-121.207255 °
DWR ID	DWR_RD2064_02_s_2012_12				
Action/Comments					
Tree stumps.					

No Photos

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
----------------------------------------------------------------------------------------------	------------------------------------------------------------------------------------	-------------------------------------------------------------------------------------	-------------------------------------------------------------------------------------------------------------