

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2016

Reclamation District No. 2064 River Junction

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River	Right	5.56	09/19/2016 09/19/2016	Herman Phillips

LM Start		Rating **	A	Issue No.	6
LM End		Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Operations & Maintenance Manuals			°	°
				°	°
DWR ID	DWR_RD2064_01_f_2014_6				
Comment Code					
Inspector Comment					
District 2064 has the O&M Manual on hand.					

No Photos

LM Start		Rating **	A	Issue No.	7
LM End		Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Emergency Supplies & Equipment			°	°
				°	°
DWR ID	DWR_RD2064_01_f_2014_7				
Comment Code					
Inspector Comment					
District has an adequate supply of flood fight materials in storage.					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2016

Reclamation District No. 2064 River Junction

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River	Right	5.56	09/19/2016 09/19/2016	Herman Phillips

LM Start		Rating **	A	Issue No.	8
LM End		Issue Type +	Ma	Location *	LS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Flood Preparedness & Training			°	°
				°	°
DWR ID	DWR_RD2064_01_f_2014_8				
Comment Code					
Inspector Comment					
District 2064 has been trained for flood fighting.					

No Photos

LM Start	0.04	Rating **	A	Issue No.	19
LM End	5.55	Issue Type +	Ma	Location *	LS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Vegetation		37.709986°	37.667210°	
			-121.267545°	-121.241020°	
DWR ID	DWR_RD2064_01_f_2016_19				
Comment Code					
V1 : Control annual grass and weeds on the levee slopes and easements.					
Inspector Comment					

Photo 1 of 1 : FA_2016_RD2064_313_19_20161102_00036.jpg



RD 2064 Looking downstream from levee mile 0.04 Unit 1 landside.

LM Start	0.51	Rating **	A	Issue No.	20
LM End	5.55	Issue Type +	Ma	Location *	WS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Vegetation		37.704590°	37.667210°	
			-121.271305°	-121.241020°	
DWR ID	DWR_RD2064_01_f_2016_20				
Comment Code					
V1 : Control annual grass and weeds on the levee slopes and easements.					
Inspector Comment					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2016

Reclamation District No. 2064 River Junction

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River	Right	5.56	09/19/2016 09/19/2016	Herman Phillips

LM Start	3.79	Rating **	M	Issue No.	27
LM End	3.79	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			37.673273 °	37.673273 °
				-121.260333 °	-121.260333 °
DWR ID	DWR_RD2064_01_f_2015_27				
Comment Code					
A1 : Exterminate rodents and backfill and compact or grout burrows.					
Inspector Comment					
Exterminate rodents and back fill the burrows.					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2016

Reclamation District No. 2064 River Junction

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Stanislaus River	Right	6.08	09/19/2016 09/19/2016	Herman Phillips

LM Start	0.36	Rating **	M	Issue No.	17
LM End	0.76	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			37.664593 °	37.664747 °
				-121.235892 °	-121.229915 °
DWR ID	DWR_RD2064_02_f_2016_17				
Comment Code					
V1 : Control annual grass and weeds on the levee slopes and easements.					
Inspector Comment					
Control the annual grasses and weeds from the landside slope.					

No Photos

LM Start	0.91	Rating **	M	Issue No.	18
LM End	1.06	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			37.666833 °	37.669035 °
				-121.230230 °	-121.229627 °
DWR ID	DWR_RD2064_02_f_2016_18				
Comment Code					
V1 : Control annual grass and weeds on the levee slopes and easements.					
Inspector Comment					
Control the annual grasses and weeds from the waterside slope.					

No Photos

LM Start	1.64	Rating **	M	Issue No.	19
LM End	2.77	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			37.671925 °	37.685022 °
				-121.221582 °	-121.220183 °
DWR ID	DWR_RD2064_02_f_2016_19				
Comment Code					
V1 : Control annual grass and weeds on the levee slopes and easements.					
Inspector Comment					
Control the annual grasses and weeds from the waterside slope.					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable N : Not Inspected/Rated M : Minimally Acceptable C : Corrected U : Unacceptable A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement	
---	--	--	--	--	--

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2016

Reclamation District No. 2064 River Junction

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Stanislaus River	Right	6.08	09/19/2016 09/19/2016	Herman Phillips

LM Start	2.10	Rating **	M	Issue No.	20
LM End	2.77	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			37.678277 °	37.685028 °
				-121.222963 °	-121.220183 °
DWR ID	DWR_RD2064_02_f_2016_20				
Comment Code					
V1 : Control annual grass and weeds on the levee slopes and easements.					
Inspector Comment					
Control the annual grasses and weeds from the landside slope.					

No Photos

LM Start	2.92	Rating **	M	Issue No.	21
LM End	3.03	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			37.686480 °	37.687837 °
				-121.218332 °	-121.217107 °
DWR ID	DWR_RD2064_02_f_2016_21				
Comment Code					
V1 : Control annual grass and weeds on the levee slopes and easements.					
Inspector Comment					

No Photos

*** Location**
 LS : Land Side N/A : Not Applicable
 WS : Water Side
 CR : Crown

**** Rating**
 A : Acceptable N : Not Inspected/Rated
 M : Minimally Acceptable C : Corrected
 U : Unacceptable A/W : Acceptable but Monitor & Maintain

+ Issue Type
 Ma : Maintenance Deficiency
 Ob : Design & System Obsolescence
 En : Enforcement