

**Flood Control Project Maintenance
Levee Inspections**
LMA District Cover Sheet
Spring 2011 Levee Inspection Results

Reclamation District No. 2068 Yolano

	Spring (March - May)	Summer ** (June - August)	Fall (September - November)	Winter ** (December - February)
* Overall LMA Rating (Fall Only)				

** Non-receipt of Summer or Winter Inspection Reports may effect overall annual rating.

* **SPRING INSPECTIONS:** Overall maintenance ratings are not determined for the spring inspection results. Individual maintenance deficiencies are rated using the same criteria in the spring and in the fall.

FALL INSPECTIONS: The overall maintenance rating shown above is based on operation and maintenance deficiencies identified within the attached unit inspection reports.

Comments

**Flood Control Project Maintenance
Levee Inspections**

Unit Cover Sheet

Spring 2011 Levee Inspection Results

Reclamation District No. 2068 Yolano

Waterway	Bank	Unit Miles
Unit No. 01 Yolo Bypass	Right	5.50

	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - February)
Unit Maintenance Rating (Fall Only)				
Date of Inspection	3/30/2011 - 3/30/2011			
DWR Inspector	Herman Phillips			
Accompanied By	Mike Hardesty RD 2068			
	Mr. Mike Hardesty			

Check one:

During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.

During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

Comments

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :

DWR Summer/Winter Inspection Reports
3310 El Camino Avenue, Suite 200
Sacramento, CA 95821-9000

X _____
Signature of LMA Representative Date

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2011

Reclamation District No. 2068 Yolano

Waterway		Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Yolo Bypass		Right	5.50	03/30/2011 03/30/2011	Herman Phillips

LMR No.	Levee Mile		Category	Item	* Location	** Rating	Action/Comment	GPS Latitude/Longitude		Issue No. Photo
	Start	End						Start	End	
1	0.07	0.07	Earthen Levee	Vegetation	LS	C	Control annual grass and weeds on the levee slopes and easements.	38.522630 ° -121.631460 °	38.522630 ° -121.631460 °	15
2	0.49	2.51	Earthen Levee	Encroachments	LS	PO	Agricultural Ditch	38.401308 ° -121.693788 °	38.372530 ° -121.693775 °	1
3	0.53	1.54	Earthen Levee	Encroachments	WS	PO	Fences	38.400897 ° -121.693767 °	38.386340 ° -121.693803 °	2
4	1.52	2.65	Earthen Levee	Encroachments	LS	PO	Agricultural Ditch	38.515262 ° -121.655535 °	38.517428 ° -121.676112 °	16
5	1.64	2.49	Earthen Levee	Vegetation	WS	C	Control annual grass and weeds on the levee slopes and easements.	38.384917 ° -121.693730 °	38.372527 ° -121.693792 °	3
6	2.01	2.47	Earthen Levee	Encroachments	WS	PO	Fences	38.379570 ° -121.693787 °	38.372822 ° -121.693782 °	4
7	2.52	5.50	Earthen Levee	Vegetation	CR	C	Control annual grass and weeds on the levee slopes and easements.	38.372188 ° -121.693917 °	38.329177 ° -121.694043 °	5
8	2.52	5.50	Earthen Levee	Vegetation	LS	C	Control annual grass and weeds on the levee slopes and easements.	38.372187 ° -121.693927 °	38.329182 ° -121.694043 °	6
9	2.52	5.50	Earthen Levee	Vegetation	WS	C	Control annual grass and weeds on the levee slopes and easements.	38.372185 ° -121.693922 °	38.329168 ° -121.694047 °	7
10	3.41	3.81	Earthen Levee	Vegetation	LS	C	Control annual grass and weeds on the levee slopes and easements.	38.359043 ° -121.694932 °	38.353543 ° -121.693918 °	10
11	3.43	5.50	Earthen Levee	Vegetation	LS	C	Control annual grass and weeds on the levee slopes and easements.	38.358985 ° -121.695057 °	38.329172 ° -121.694050 °	9
12	3.59	5.50	Earthen Levee	Encroachments	LS	PO	Agricultural Ditch	38.356235 ° -121.693893 °	38.329175 ° -121.694043 °	8
13	3.62	5.44	Earthen Levee	Encroachments	WS	PO	Agricultural Ditch	38.356292 ° -121.693918 °	38.329967 ° -121.694043 °	11

* Location LS : Landside WS : Waterside CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected/Rated C : Corrected W : Watch/Monitor
--	--

**Flood Control Project Maintenance
Levee Inspections**

Unit Cover Sheet

Spring 2011 Levee Inspection Results

Reclamation District No. 2068 Yolano

Waterway	Bank	Unit Miles
Unit No. 02 Back Levee	Left	3.23

	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - February)
Unit Maintenance Rating (Fall Only)				
Date of Inspection	3/30/2011 - 3/30/2011			
DWR Inspector	Herman Phillips			
Accompanied By	Mike Hardesty RD 2068			
	Mr.Mike Hardesty RD 2068			

Check one:

During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.

During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

Comments

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :

DWR Summer/Winter Inspection Reports
3310 El Camino Avenue, Suite 200
Sacramento, CA 95821-9000

X _____
Signature of LMA Representative Date

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2011

Reclamation District No. 2068 Yolano

Waterway			Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Back Levee			Left	3.23	03/30/2011 03/30/2011	Herman Phillips

LMR No.	Levee Mile		Category	Item	* Location	** Rating	Action/Comment	GPS Latitude/Longitude		Issue No. Photo
	Start	End						Start	End	
1	0.00	0.00	Earthen Levee	Vegetation	WS	A	Control annual grass and weeds on the levee slopes and easements.	°	°	2 Y
2	0.00	0.00	Earthen Levee	Vegetation	LS	A	Control annual grass and weeds on the levee slopes and easements.	°	°	5 Y
3	0.00	0.87	Earthen Levee	Vegetation	CR	C	Control annual grass and weeds on the levee slopes and easements.	38.358190 ° -121.740450 °	38.370783 ° -121.740152 °	3

* Location LS : Landside WS : Waterside CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected/Rated C : Corrected W : Watch/Monitor
--	--

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2011

Reclamation District No. 2068 Yolano

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Back Levee	Left	3.23	03/30/2011 03/30/2011	Herman Phillips

Levee Mile Report Line	1
Start Levee Mile	0.00
End Levee Mile	0.00
Location	Water Side
Category	Earthen Levee
Item	Vegetation
Looking downstream from levee mile 0.00 waterside of RD 2068. Photo taken 3-30-2011.	
phillips_s_20110330_226.jpg	



Levee Mile Report Line	2
Start Levee Mile	0.00
End Levee Mile	0.00
Location	Land Side
Category	Earthen Levee
Item	Vegetation
Landside looking downstream from levee mile 0.00 Unit # 2 RD 2068. Photo taken 3-30-2011.	
phillips_s_20110330_225.jpg	



<p>* Location</p> <p>LS : Landside WS : Waterside CR : Crown</p>	<p>** Rating</p> <p>A : Acceptable M : Minimally Acceptable U : Unacceptable</p>	<p>PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected/Rated</p>	<p>C : Corrected W : Watch/Monitor</p>
---	---	---	--