

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2016

Reclamation District No. 2068 Yolano

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Yolo Bypass	Right	5.48	04/06/2016 04/06/2016	Herman Phillips

LM Start		Rating **	A	Issue No.	3
LM End		Issue Type +	Ma	Location *	WS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start		End
Item	Operations & Maintenance Manuals			o	o
DWR ID	DWR_RD2068_01_f_2014_3				
Comment Code					
Inspector Comment					
RD 2068 has the O&M Manual on hand.					

No Photos

LM Start		Rating **	A	Issue No.	4
LM End		Issue Type +	Ma	Location *	WS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start		End
Item	Flood Preparedness & Training			o	o
DWR ID	DWR_RD2068_01_f_2014_4				
Comment Code					
Inspector Comment					
RD 2068 crew members are trained yearly.					

No Photos

LM Start		Rating **	A	Issue No.	5
LM End		Issue Type +	Ma	Location *	WS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start		End
Item	Emergency Supplies & Equipment			o	o
DWR ID	DWR_RD2068_01_f_2014_5				
Comment Code					
Inspector Comment					
RD 2068 has emergency supplies stored.					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2016

Reclamation District No. 2068 Yolano

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Yolo Bypass	Right	5.48	04/06/2016 04/06/2016	Herman Phillips

LM Start	0.52	Rating **	M	Issue No.	9
LM End	5.48	Issue Type +	Ma	Location *	LS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Vegetation		38.401050 °	38.329078 °	
			-121.693805 °	-121.694058 °	
DWR ID	DWR_RD2068_01_s_2016_9				
Comment Code					
V1 : Control annual grass and weeds on the levee slopes and easements.					
Inspector Comment					
The RD will have this vegetation removed from the levee slope.					

Photo 1 of 1 : SP_2016_RD2068_193_9_20160408_00001.jpg



Looking downstream from levee mile 0.52 landside levee slope.

LM Start	2.50	Rating **	M	Issue No.	11
LM End	5.48	Issue Type +	Ma	Location *	CR
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Vegetation		38.372265 °	38.329078 °	
			-121.693940 °	-121.694058 °	
DWR ID	DWR_RD2068_01_s_2016_11				
Comment Code					
V9 : Keep the crown roadway free of vegetation.					
Inspector Comment					

No Photos

LM Start	5.48	Rating **	M	Issue No.	10
LM End	5.48	Issue Type +	Ma	Location *	WS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Vegetation		38.329078 °	38.329078 °	
			-121.694058 °	-121.694058 °	
DWR ID	DWR_RD2068_01_s_2016_10				
Comment Code					
V1 : Control annual grass and weeds on the levee slopes and easements.					
Inspector Comment					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2016

Reclamation District No. 2068 Yolano

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Back Levee	Left	3.22	04/06/2016 04/06/2016	Herman Phillips

LM Start	0.02	Rating **	M	Issue No.	9
LM End	0.03	Issue Type +	Ma	Location *	WS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Vegetation		38.358465 °	38.358527 °	
			-121.740383 °	-121.740386 °	
DWR ID	DWR_RD2068_02_f_2015_9				
Comment Code					
V1 : Control annual grass and weeds on the levee slopes and easements.					
Inspector Comment					

No Photos

LM Start	0.03	Rating **	M	Issue No.	11
LM End	0.84	Issue Type +	Ma	Location *	LS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Vegetation		38.358546 °	38.370343 °	
			-121.740381 °	-121.740170 °	
DWR ID	DWR_RD2068_02_s_2016_11				
Comment Code					
V1 : Control annual grass and weeds on the levee slopes and easements.					
Inspector Comment					
RD 2068 In process of mowing the levee section during this inspection.					

Photo 1 of 1 : SP_2016_RD2068_194_11_20160408_00007.jpg



Looking downstream from levee mile 0.03 unit 2 RD 2068.

LM Start	0.03	Rating **	M	Issue No.	13
LM End	0.84	Issue Type +	Ma	Location *	CR
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Vegetation		38.358546 °	38.370343 °	
			-121.740384 °	-121.740166 °	
DWR ID	DWR_RD2068_02_s_2016_13				
Comment Code					
V9 : Keep the crown roadway free of vegetation.					
Inspector Comment					
Keep the crown roadway free of vegetation. The Crown road way must be free of vegetation and must be graveled.					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2016

Reclamation District No. 2068 Yolano

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Back Levee	Left	3.22	04/06/2016 04/06/2016	Herman Phillips

LM Start	0.04	Rating **	M	Issue No.	12
LM End	3.23	Issue Type +	Ma	Location *	WS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Vegetation		38.358733 °	38.398789 °	
			-121.740382 °	-121.715637 °	
DWR ID	DWR_RD2068_02_s_2016_12				
Comment Code					
V1 : Control annual grass and weeds on the levee slopes and easements.					
Inspector Comment					
The RD was mowing the levee section during this inspection.					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---