

**Flood Control Project Maintenance  
Levee Inspections****LMA District Cover Sheet****Spring 2011 Levee Inspection Results****Reclamation District No. 2098 Cache and Haas Slough**

	Spring (March - May)	Summer ** (June - August)	Fall (September - November)	Winter ** (December - February)
* Overall LMA Rating (Fall Only)				

\*\* Non-receipt of Summer or Winter Inspection Reports may effect overall annual rating.

\*  
SPRING INSPECTIONS: Overall maintenance ratings are not determined for the spring inspection results. Individual maintenance deficiencies are rated using the same criteria in the spring and in the fall.

FALL INSPECTIONS: The overall maintenance rating shown above is based on operation and maintenance deficiencies identified within the attached unit inspection reports.

Comments


**Flood Control Project Maintenance  
Levee Inspections**

**Unit Cover Sheet**

**Spring 2011 Levee Inspection Results**

**Reclamation District No. 2098 Cache and Haas Slough**

Waterway				Bank	Unit Miles
Unit No. 01 Yolo Bypass				Right	3.58
	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - February)	
Unit Maintenance Rating (Fall Only)					
Date of Inspection	4/20/2011 - 4/20/2011				
DWR Inspector	Herman Phillips				
Accompanied By	Mike Hardesty RD 2098				

Check one:

- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.
- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

Comments

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :

DWR Summer/Winter Inspection Reports  
3310 El Camino Avenue, Suite 200  
Sacramento, CA 95821-9000

**X**

Signature of LMA Representative

Date

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2011**

**Reclamation District No. 2098 Cache and Haas Slough**

Waterway						Bank	Unit Miles	Inspection Start/End	Inspector	
Unit No. 01 Yolo Bypass						Right	3.58	04/20/2011 04/20/2011	Herman Phillips	
LMIR No.	Levee Mile		Category	Item	* Location	** Rating	Action/Comment	GPS Latitude/Longitude		Issue No.
	Start	End						Start	End	Photo
1	0.00	0.00	Earthen Levee	Vegetation	LS	M	Control annual grass and weeds on the levee slopes and easements.	°	°	3
								°	°	Y
2	0.00	0.00	Earthen Levee	Vegetation	WS	M	Control annual grass and weeds on the levee slopes and easements.	°	°	8
								°	°	Y
3	1.16	1.54	Earthen Levee	Vegetation	LS	M	Control annual grass and weeds on the levee slopes and easements.	38.312246 ° -121.693635 °	38.306707 ° -121.693591 °	1
4	1.18	1.72	Earthen Levee	Vegetation	WS	M	Control annual grass and weeds on the levee slopes and easements.	38.311955 ° -121.693633 °	38.304084 ° -121.693621 °	2
5	5.29	5.29	Earthen Levee	Trim / Thin Trees	WS	C	Trim trees to at least five feet above ground level.	38.275745 ° -121.705738 °	38.275745 ° -121.705738 °	7

**\* Location**

LS : Landside  
WS : Waterside  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
PO : Partially Obstructing  
CO : Completely Obstructing  
N : Not Inspected/Rated  
C : Corrected  
W : Watch/Monitor

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2011**

**Reclamation District No. 2098 Cache and Haas Slough**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Yolo Bypass	Right	3.58	04/20/2011 04/20/2011	Herman Phillips

Levee Mile Report Line	1
Start Levee Mile	0.00
End Levee Mile	0.00
Location	Land Side
Category	Earthen Levee
Item	Vegetation

Looking downstream from landside of Unit 1 of RD 2098. Photo taken 4-20-2011

phillips\_s\_20110421\_263.jpg



Levee Mile Report Line	2
Start Levee Mile	0.00
End Levee Mile	0.00
Location	Water Side
Category	Earthen Levee
Item	Vegetation

Standing on waterside levee slope looking downstream of RD 2098 Unit 1. This photo was taken 4-20-2011.

phillips\_s\_20110421\_264.jpg



**\* Location**

LS : Landside  
WS : Waterside  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
PO : Partially Obstructing  
CO : Completely Obstructing  
N : Not Inspected/Rated  
C : Corrected  
W : Watch/Monitor

**Flood Control Project Maintenance  
Levee Inspections**

**Unit Cover Sheet**

**Spring 2011 Levee Inspection Results**

**Reclamation District No. 2098 Cache and Haas Slough**

Waterway	Bank	Unit Miles
Unit No. 01A Cross Levee	Right	0.55

	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - February)
Unit Maintenance Rating (Fall Only)				
Date of Inspection	4/20/2011 - 4/20/2011			
DWR Inspector	Herman Phillips			
Accompanied By	Mike Hardesty RD 2098			
	Mike Hardesty RD 2098			

Check one:

- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.
- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

Comments

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :

DWR Summer/Winter Inspection Reports  
3310 El Camino Avenue, Suite 200  
Sacramento, CA 95821-9000

**X**

Signature of LMA Representative

Date

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2011**

**Reclamation District No. 2098 Cache and Haas Slough**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01A Cross Levee	Right	0.55	04/20/2011 04/20/2011	Herman Phillips

LMR No.	Levee Mile		Category	Item	* Location	** Rating	Action/Comment	GPS Latitude/Longitude		Issue No.
	Start	End						Start	End	Photo
1	0.00	0.00	Earthen Levee	Vegetation	LS	A	Control annual grass and weeds on the levee slopes and easements.	°	°	4
								°	°	Y
2	0.00	0.00	Earthen Levee	Vegetation	WS	A	Control annual grass and weeds on the levee slopes and easements.	°	°	5
								°	°	Y

**\* Location**

LS : Landside  
WS : Waterside  
CR : Crown

**\*\* Rating**

A : Acceptable      PO : Partially Obstructing      C : Corrected  
M : Minimally Acceptable      CO : Completely Obstructing      W : Watch/Monitor  
U : Unacceptable      N : Not Inspected/Rated

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2011**

**Reclamation District No. 2098 Cache and Haas Slough**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01A Cross Levee	Right	0.55	04/20/2011 04/20/2011	Herman Phillips

Levee Mile Report Line	1
Start Levee Mile	0.00
End Levee Mile	0.00
Location	Land Side
Category	Earthen Levee
Item	Vegetation

Looking downstream at the cross levee Unit 1A RD 2098 Unit 1A Levee mile 0.00. Photo taken 4-20-2011.

phillips\_s\_20110421\_265.jpg



Levee Mile Report Line	2
Start Levee Mile	0.00
End Levee Mile	0.00
Location	Water Side
Category	Earthen Levee
Item	Vegetation

This photo shows the waterside of the cross levee Unit 1A of RD 2098 levee mile 0.00 looking downstream. Photo taken 4-20-2011.

phillips\_s\_20110421\_266.jpg



**\* Location**

LS : Landside  
WS : Waterside  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
PO : Partially Obstructing  
CO : Completely Obstructing  
N : Not Inspected/Rated  
C : Corrected  
W : Watch/Monitor

**Flood Control Project Maintenance  
Levee Inspections**

**Unit Cover Sheet**

**Spring 2011 Levee Inspection Results**

**Reclamation District No. 2098 Cache and Haas Slough**

Waterway	Bank	Unit Miles
Unit No. 02 Cache Slough	Left	2.01

	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - February)
Unit Maintenance Rating (Fall Only)				
Date of Inspection	4/20/2011 - 4/20/2011			
DWR Inspector	Herman Phillips			
Accompanied By	Mike Hardesty RD 2098			
	Mike Hardesty RD 2098			

Check one:

- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.
- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

Comments

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :

DWR Summer/Winter Inspection Reports  
3310 El Camino Avenue, Suite 200  
Sacramento, CA 95821-9000

**X**

Signature of LMA Representative

Date



**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2011**

**Reclamation District No. 2098 Cache and Haas Slough**

Waterway						Bank	Unit Miles	Inspection Start/End	Inspector	
Unit No. 02 Cache Slough						Left	2.01	04/20/2011 04/20/2011	Herman Phillips	

  

LMR No.	Levee Mile		Category	Item	* Location	** Rating	Action/Comment	GPS Latitude/Longitude		Issue No.
	Start	End						Start	End	Photo
1	5.29	5.29	Earthen Levee	Vegetation	LS	A	Control annual grass and weeds on the levee slopes and easements.	38.275571 ° -121.705698 °	38.275706 ° -121.705698 °	3 Y
2	5.56	5.58	Earthen Levee	Crown Surface / Depressions / Rutting	CR	C	Regrade the crown roadway for proper drainage.	38.278757 ° -121.708568 °	38.279072 ° -121.708967 °	1
3	5.58	6.07	Earthen Levee	Vegetation	LS	C	Control annual grass and weeds on the levee slopes and easements.	38.279075 ° -121.708967 °	38.283733 ° -121.713792 °	2

**\* Location**

LS : Landside  
WS : Waterside  
CR : Crown

**\*\* Rating**

A : Acceptable      PO : Partially Obstructing      C : Corrected  
M : Minimally Acceptable      CO : Completely Obstructing      W : Watch/Monitor  
U : Unacceptable      N : Not Inspected/Rated

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2011**

**Reclamation District No. 2098 Cache and Haas Slough**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Cache Slough	Left	2.01	04/20/2011 04/20/2011	Herman Phillips

Levee Mile Report Line	1
Start Levee Mile	5.29
End Levee Mile	5.29
Location	Land Side
Category	Earthen Levee
Item	Vegetation

Standing on landside of Unit 2 levee mile 5.29 looking downstream of the landward slope, goats are in the area eating the vegetation off the slope. Photo taken 4-20-2011.

phillips\_s\_20110421\_267.jpg



**\* Location**

LS : Landside  
WS : Waterside  
CR : Crown

**\*\* Rating**

A : Acceptable      PO : Partially Obstructing      C : Corrected  
M : Minimally Acceptable      CO : Completely Obstructing      W : Watch/Monitor  
U : Unacceptable      N : Not Inspected/Rated

**Flood Control Project Maintenance  
Levee Inspections**

**Unit Cover Sheet**

**Spring 2011 Levee Inspection Results**

**Reclamation District No. 2098 Cache and Haas Slough**

Waterway	Bank	Unit Miles
Unit No. 03 Haas Slough	Right	1.89

	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - February)
Unit Maintenance Rating (Fall Only)				
Date of Inspection	4/20/2011 - 4/20/2011			
DWR Inspector	Herman Phillips			
Accompanied By	Mike Hardesty RD 2098			
	Mike Hardesty RD 2098			

Check one:

- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.
- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

Comments

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :

DWR Summer/Winter Inspection Reports  
3310 El Camino Avenue, Suite 200  
Sacramento, CA 95821-9000

**X**

Signature of LMA Representative

Date

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2011**

**Reclamation District No. 2098 Cache and Haas Slough**

Waterway						Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 Haas Slough						Right	1.89	04/20/2011 04/20/2011	Herman Phillips

  

LMR No.	Levee Mile		Category	Item	* Location	** Rating	Action/Comment	GPS Latitude/Longitude		Issue No. Photo
	Start	End						Start	End	
1	7.10	7.15	Earthen Levee	Cracking	LS	M	Monitor and have inspected by geotechnical engineer.	38.292980 ° -121.721892 °	38.292995 ° -121.723093 °	1
2	7.27	7.27	Earthen Levee	Vegetation	LS	A	Control annual grass and weeds on the levee slopes and easements.	38.294171 ° -121.725037 °	38.294171 ° -121.725037 °	5 Y
3	7.70	7.74	Earthen Levee	Cracking	WS	M	Monitor and have inspected by geotechnical engineer.	38.298843 ° -121.728588 °	38.299450 ° -121.728463 °	2

**\* Location**

LS : Landside  
WS : Waterside  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
PO : Partially Obstructing  
CO : Completely Obstructing  
N : Not Inspected/Rated  
C : Corrected  
W : Watch/Monitor

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2011**

**Reclamation District No. 2098 Cache and Haas Slough**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 Haas Slough	Right	1.89	04/20/2011 04/20/2011	Herman Phillips

Levee Mile Report Line	2
Start Levee Mile	7.27
End Levee Mile	7.27
Location	Land Side
Category	Earthen Levee
Item	Vegetation
Waterside levee slope unit 3 starts here. 4-20-2011	
phillips_s_20110512_313.jpg	

**\* Location**

LS : Landside  
WS : Waterside  
CR : Crown

**\*\* Rating**

A : Acceptable      PO : Partially Obstructing      C : Corrected  
M : Minimally Acceptable      CO : Completely Obstructing      W : Watch/Monitor  
U : Unacceptable      N : Not Inspected/Rated

**Flood Control Project Maintenance  
Levee Inspections**

**Unit Cover Sheet**

**Spring 2011 Levee Inspection Results**

**Reclamation District No. 2098 Cache and Haas Slough**

Waterway	Bank	Unit Miles
Unit No. 04 Back Levee	Left	2.93

	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - February)
Unit Maintenance Rating (Fall Only)				
Date of Inspection	4/20/2011 - 4/20/2011			
DWR Inspector	Herman Phillips			
Accompanied By	Mike Hadesty RD 2098			
	Mike Hardesty RD 2098			

Check one:

- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.
- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

Comments

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :

DWR Summer/Winter Inspection Reports  
3310 El Camino Avenue, Suite 200  
Sacramento, CA 95821-9000

**X**

Signature of LMA Representative

Date

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2011**

**Reclamation District No. 2098 Cache and Haas Slough**

Waterway						Bank	Unit Miles	Inspection Start/End	Inspector	
Unit No. 04 Back Levee						Left	2.93	04/20/2011 04/20/2011	Herman Phillips	
LMIR No.	Levee Mile		Category	Item	* Location	** Rating	Action/Comment	GPS Latitude/Longitude		Issue No.
	Start	End						Start	End	Photo
1	9.15	9.15	Earthen Levee	Vegetation	WS	W	Control annual grass and weeds on the levee slopes and easements.	38.316093 ° -121.740144 °	38.316093 ° -121.740144 °	13 Y
2	9.80	12.11	Earthen Levee	Vegetation	WS	M	Control annual grass and weeds on the levee slopes and easements. Inspector Comments: There are two photos added to the inspection to show how the veg is over grown from the gate downstream to 9.82. The growth continues down stream to levee mile 13.11 just not as tall.	38.325060 ° -121.740077 °	38.372562 ° -121.739037 °	8 Y
3	9.81	9.81	Earthen Levee	Vegetation	WS	M	Remove the wild growth other than native grasses from the levee slopes.	38.324993 ° -121.740082 °	38.324993 ° -121.740082 °	1
4	9.81	12.11	Earthen Levee	Vegetation	LS	M	Control annual grass and weeds on the levee slopes and easements.	38.325035 ° -121.740080 °	38.372565 ° -121.739022 °	7
5	9.81	9.83	Earthen Levee	Vegetation	CR	C	Control annual grass and weeds on the levee slopes and easements.	38.325038 ° -121.740103 °	38.325372 ° -121.740030 °	9
6	10.05	10.08	Earthen Levee	Vegetation	LS	C	Control annual grass and weeds on the levee slopes and easements.	38.328213 ° -121.740588 °	38.328600 ° -121.740577 °	2
7	10.47	10.48	Earthen Levee	Vegetation	LS	M	Control annual grass and weeds on the levee slopes and easements.	38.334287 ° -121.740560 °	38.334487 ° -121.740572 °	3
8	10.57	10.58	Earthen Levee	Vegetation	LS	M	Control annual grass and weeds on the levee slopes and easements.	38.335750 ° -121.740592 °	38.335885 ° -121.740610 °	4
9	10.88	10.88	Earthen Levee	Vegetation	LS	M	Control annual grass and weeds on the levee slopes and easements.	38.340167 ° -121.740787 °	38.340303 ° -121.740788 °	5
10	10.92	10.99	Earthen Levee	Vegetation	LS	M	Control annual grass and weeds on the levee slopes and easements.	38.340850 ° -121.740798 °	38.341852 ° -121.740802 °	6
11	10.93	10.94	Earthen Levee	Trim / Thin Trees	WS	M	Trim trees to at least five feet above ground level.	38.340930 ° -121.740783 °	38.341077 ° -121.740735 °	10

**\* Location**

LS : Landside  
WS : Waterside  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
PO : Partially Obstructing  
CO : Completely Obstructing  
N : Not Inspected/Rated  
C : Corrected  
W : Watch/Monitor



**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2011**

**Reclamation District No. 2098 Cache and Haas Slough**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 04 Back Levee	Left	2.93	04/20/2011 04/20/2011	Herman Phillips

Levee Mile Report Line	1
Start Levee Mile	9.15
End Levee Mile	9.15
Location	Water Side
Category	Earthen Levee
Item	Vegetation
Standing on waterside start of unit 4 looking downstream. Photo taken 4-20-2011	
phillips_s_20110512_314.jpg	



Levee Mile Report Line	2
Start Levee Mile	9.80
End Levee Mile	12.11
Location	Water Side
Category	Earthen Levee
Item	Vegetation
Standing downstream from L/M 9.83 looking back upstream from landside. As you can see beyond the fence back up stream the live in area leaps the veg. low on levee section.	
phillips_s_20110228_165.jpg	



Levee Mile Report Line	2
Start Levee Mile	9.80
End Levee Mile	12.11
Location	Water Side
Category	Earthen Levee
Item	Vegetation
This shot shows veg on water side from the gate at levee mile 9.79 down stream to 9.84.	
phillips_s_20110228_166.jpg	

**\* Location**

LS : Landside  
WS : Waterside  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable

PO : Partially Obstructing  
CO : Completely Obstructing  
N : Not Inspected/Rated

C : Corrected  
W : Watch/Monitor