

**Flood Control Project Maintenance  
Levee Inspections**

## Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2015

### Reclamation District No. 2098 Cache and Haas Slough

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Yolo Bypass	Right	3.60	05/14/2015 05/14/2015	Herman Phillips

LM Start		Rating **	A	Issue No.	3		
LM End		Issue Type +	Ma	Location *	WS		
Category	Earthen Levee			GPS Latitude/Longitude			
				Start		End	
Item	Operations & Maintenance Manuals				°		°
					°		°
DWR ID	DWR_RD2098_01_f_2014_3						
Action/Comments							
Inspector Comments: RD 2098 has the O&M Manual on file.							

No Photos

LM Start		Rating **	A	Issue No.	4	
LM End		Issue Type +	Ma	Location *	WS	
Category	Earthen Levee			GPS Latitude/Longitude		
				Start		End
Item	Emergency Supplies & Equipment				°	°
					°	°
DWR ID	DWR_RD2098_01_f_2014_4					
Action/Comments						
Inspector Comments: RD 2098 has emergency supplies and equipment in storage.						

No Photos

LM Start		Rating **	A	Issue No.	5	
LM End		Issue Type +	Ma	Location *	WS	
Category	Earthen Levee			GPS Latitude/Longitude		
				Start		End
Item	Flood Preparedness & Training				°	°
					°	°
DWR ID	DWR_RD2098_01_f_2014_5					
Action/Comments						
Inspector Comments: RD 2098 has their team well prepared for a flood fight.						

No Photos

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

## Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2015

### Reclamation District No. 2098 Cache and Haas Slough

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Yolo Bypass	Right	3.60	05/14/2015 05/14/2015	Herman Phillips

LM Start	0.14	Rating **	A	Issue No.	10
LM End	3.58	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.327017 °	38.277623 °
				-121.694053 °	-121.696213 °
DWR ID	DWR_RD2098_01_s_2015_10				
Action/Comments					
Control annual grass and weeds on the levee slopes and easements.					

Photo 1 of 1 : SP\_2015\_RD2098\_244\_10\_20150604\_00002.jpg



Looking downstream at the waterside levee slope.

LM Start	0.14	Rating **	A	Issue No.	11
LM End	3.58	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.327010 °	38.277623 °
				-121.694055 °	-121.696213 °
DWR ID	DWR_RD2098_01_s_2015_11				
Action/Comments					
Control annual grass and weeds on the levee slopes and easements.					

Photo 1 of 1 : SP\_2015\_RD2098\_244\_11\_20150604\_00001.jpg



View looking downstream at the landside levee slope.

LM Start	0.84	Rating **	M	Issue No.	12
LM End	0.84	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Erosion / Bank Caving			38.316845 °	38.316845 °
				-121.694007 °	-121.694007 °
DWR ID	DWR_RD2098_01_s_2015_12				
Action/Comments					
Note and monitor erosion site.					

No Photos

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown		<b>** Rating</b> A : Acceptable                      N : Not Inspected/Rated M : Minimally Acceptable        C : Corrected U : Unacceptable                  A/W : Acceptable but Monitor & Maintain		<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance  
Levee Inspections**

**Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2015**

**Reclamation District No. 2098 Cache and Haas Slough**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Yolo Bypass	Right	3.60	05/14/2015 05/14/2015	Herman Phillips

LM Start	1.76	Rating **	M	Issue No.	13
LM End	1.76	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Erosion / Bank Caving			38.303590 °	38.303590 °
				-121.693613 °	-121.693613 °
DWR ID	DWR_RD2098_01_s _ 2015_13				
Action/Comments					
Note and monitor erosion site.					

No Photos

**\* Location**  
 LS : Land Side    N/A : Not Applicable  
 WS : Water Side  
 CR : Crown

**\*\* Rating**  
 A : Acceptable                      N : Not Inspected/Rated  
 M : Minimally Acceptable        C : Corrected  
 U : Unacceptable                  A/W : Acceptable but Monitor & Maintain

**+ Issue Type**  
 Ma : Maintenance Deficiency  
 Ob : Design & System Obsolescence  
 En : Enforcement

**Flood Control Project Maintenance  
Levee Inspections**

## Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2015

### Reclamation District No. 2098 Cache and Haas Slough

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01A Cross Levee	Right	0.53	05/14/2015 05/14/2015	Herman Phillips

LM Start	0.00	Rating **	A	Issue No.	2
LM End	0.53	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.277408 °	38.275722 °
				-121.696282 °	-121.705772 °
DWR ID	DWR_RD2098_01A_s_2015_2				
Action/Comments					
Control annual grass and weeds on the levee slopes and easements.					

Photo 1 of 1 : SP\_2015\_RD2098\_245\_2\_20150604\_00001.jpg



View looking at the landside slope.

LM Start	0.00	Rating **	A	Issue No.	3
LM End	0.53	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.277408 °	38.275722 °
				-121.696282 °	-121.705772 °
DWR ID	DWR_RD2098_01A_s_2015_3				
Action/Comments					
Control annual grass and weeds on the levee slopes and easements.					

No Photos

**\* Location**  
 LS : Land Side    N/A : Not Applicable  
 WS : Water Side  
 CR : Crown

**\*\* Rating**  
 A : Acceptable  
 M : Minimally Acceptable  
 U : Unacceptable  
 N : Not Inspected/Rated  
 C : Corrected  
 A/W : Acceptable but Monitor & Maintain

**+ Issue Type**  
 Ma : Maintenance Deficiency  
 Ob : Design & System Obsolescence  
 En : Enforcement

**Flood Control Project Maintenance  
Levee Inspections**

## Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2015

### Reclamation District No. 2098 Cache and Haas Slough

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Cache Slough	Left	1.89	05/14/2015 05/14/2015	Herman Phillips

LM Start	5.31	Rating **	A	Issue No.	9
LM End	6.74	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.275935 °	38.292505 °
				-121.705900 °	-121.716120 °
DWR ID	DWR_RD2098_02_s _ 2015_9				
Action/Comments					
Control annual grass and weeds on the levee slopes and easements.					

No Photos

LM Start	5.31	Rating **	A	Issue No.	11
LM End	6.74	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.275935 °	38.292505 °
				-121.705900 °	-121.716120 °
DWR ID	DWR_RD2098_02_s _ 2015_11				
Action/Comments					
Control annual grass and weeds on the levee slopes and easements.					

Photo 1 of 1 : SP\_2015\_RD2098\_246\_11\_20150604\_00003.jpg



View looking downstream at levee section.

LM Start	6.70	Rating **	C	Issue No.	10
LM End	6.70	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Slope Stability			38.292076 °	38.292076 °
				-121.715792 °	-121.715792 °
DWR ID	DWR_RD2098_02_s _ 2014_10				
Action/Comments					
Repair slope instability. Inspector Comments: RD 2098 will send out crew to inspect site and make repairs as needed.					

No Photos

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown		<b>** Rating</b> A : Acceptable                      N : Not Inspected/Rated M : Minimally Acceptable        C : Corrected U : Unacceptable                  A/W : Acceptable but Monitor & Maintain		<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance  
Levee Inspections**

## Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2015

### Reclamation District No. 2098 Cache and Haas Slough

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Cache Slough	Left	1.89	05/14/2015 05/14/2015	Herman Phillips

LM Start	6.73	Rating **	U	Issue No.	4
LM End	6.73	Issue Type +	Ma	Location *	CR
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Repair Gates			38.292428 °	38.292428 °
				-121.716062 °	-121.716062 °
DWR ID	DWR_RD2098_02_f_2013_4				
Action/Comments					
Inspector Comments: This gate is damaged and requires replacement.					

Photo 1 of 1 : SP\_2015\_RD2098\_246\_4\_20150604\_00004.jpg



View of the broken gate.

LM Start	6.84	Rating **	M	Issue No.	16
LM End	7.10	Issue Type +	Ma	Location *	CR
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.292972 °	38.293010 °
				-121.717822 °	-121.722695 °
DWR ID	DWR_RD2098_02_s_2015_16				
Action/Comments					
Keep the crown roadway free of vegetation.					

No Photos

LM Start	7.09	Rating **	U	Issue No.	17
LM End	7.15	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.292975 °	38.293008 °
				-121.722357 °	-121.723457 °
DWR ID	DWR_RD2098_02_s_2015_17				
Action/Comments					
Remove the wild growth other than native grasses from the levee slopes.					
Inspector Comments: Remove the unacceptable weeds from the landside slope.					

Photo 1 of 1 : SP\_2015\_RD2098\_246\_17\_20150604\_00008.jpg



View of unacceptable weeds on the landside levee slope.

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown		<b>** Rating</b> A : Acceptable                      N : Not Inspected/Rated M : Minimally Acceptable        C : Corrected U : Unacceptable                  A/W : Acceptable but Monitor & Maintain		<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement	
--	--	---	--	---	--

**Flood Control Project Maintenance  
Levee Inspections**

## Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2015

### Reclamation District No. 2098 Cache and Haas Slough

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Cache Slough	Left	1.89	05/14/2015 05/14/2015	Herman Phillips

LM Start	7.10	Rating **	M	Issue No.	18
LM End	7.10	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Slope Stability			38.293012 °	38.293012 °
				-121.722560 °	-121.722560 °
DWR ID	DWR_RD2098_02_s_2015_18				
Action/Comments					
Repair slope instability.					

No Photos

LM Start	7.15	Rating **	U	Issue No.	19
LM End	7.15	Issue Type +	Ma	Location *	CR
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Repair Gates			38.293008 °	38.293008 °
				-121.723457 °	-121.723457 °
DWR ID	DWR_RD2098_02_s_2015_19				
Action/Comments					
Inspector Comments: Repair the broken gate.					

Photo 1 of 2 : SP\_2015\_RD2098\_246\_19\_20150604\_00006.jpg



View of the broken gate hinge.

LM Start	<b>7.15</b>	Rating **	U	Issue No.	<b>19 (cont)</b>
LM End	<b>7.15</b>	Issue Type +	Ma	Location *	CR

Photo 2 of 2 : SP\_2015\_RD2098\_246\_19\_20150604\_00007.jpg



View of the broken gate crossing levee crown.

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown		<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable		N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement	
--	--	--	--	---	--	---	--

**Flood Control Project Maintenance  
Levee Inspections**

## Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2015

### Reclamation District No. 2098 Cache and Haas Slough

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 Haas Slough	Right	1.94	05/14/2015 05/14/2015	Herman Phillips

LM Start	7.22	Rating **	U	Issue No.	8
LM End	7.77	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.293483 °	38.300218 °
				-121.724547 °	-121.728303 °
DWR ID	DWR_RD2098_03_s_2015_8				
Action/Comments					
Remove the wild growth other than native grasses from the levee slopes.					
Inspector Comments: Remove the tall weeds from the landside slope.					

Photo 1 of 1 : SP\_2015\_RD2098\_247\_8\_20150604\_00007.jpg



View of unacceptable tall weeds on the landside levee slope.

LM Start	7.25	Rating **	U	Issue No.	10
LM End	7.60	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.293902 °	38.297882 °
				-121.724890 °	-121.728647 °
DWR ID	DWR_RD2098_03_s_2015_10				
Action/Comments					
Remove the wild growth other than native grasses from the levee slopes.					
Inspector Comments: Remove the unacceptable tall weeds from the waterside slope.					

Photo 1 of 1 : SP\_2015\_RD2098\_247\_10\_20150604\_00008.jpg



View of unacceptable tall weeds on the waterside levee shoulder and slope.

LM Start	7.33	Rating **	M	Issue No.	7
LM End	7.72	Issue Type +	Ma	Location *	WS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	USACE Erosion Survey			38.294858 °	38.299606 °
				-121.725433 °	-121.728621 °
DWR ID	DWR_RD2098_03_f_2014_7				
Action/Comments					
Inspector Comments: 2011 - Large vertical erosion pockets and bank slumping. 2013: Site is part of the extended inventory, last inspected 2011. [2013 Site ID: HAS_7-9_L] The USAC Placed rock at this site,					

No Photos

* Location LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable                      N : Not Inspected/Rated M : Minimally Acceptable        C : Corrected U : Unacceptable                  A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement	
---	--	--	--	--	--

**Flood Control Project Maintenance  
Levee Inspections**

## Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2015

### Reclamation District No. 2098 Cache and Haas Slough

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 Haas Slough	Right	1.94	05/14/2015 05/14/2015	Herman Phillips

LM Start	7.37	Rating **	M	Issue No.	6
LM End	7.51	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Slope Stability			38.295460 °	38.296799 °
				-121.725750 °	-121.727510 °
DWR ID	DWR_RD2098_03_s _ 2013_6				
Action/Comments					
Repair the levee slope damaged by foot traffic and prevent access where possible.					
Inspector Comments: This erosion is caused by the resident goats in the area. They are corralled in this location with full access to the levee.					

No Photos

LM Start	7.45	Rating **	M	Issue No.	4
LM End	7.61	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Slope Stability			38.295930 °	38.298142 °
				-121.727043 °	-121.739715 °
DWR ID	DWR_RD2098_03_s _ 2013_4				
Action/Comments					
Repair slope instability.					
Inspector Comments: There is erosion on waterside covered by tullies.					

No Photos

LM Start	7.65	Rating **	M	Issue No.	11
LM End	8.65	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.298547 °	38.310547 °
				-121.728628 °	-121.734595 °
DWR ID	DWR_RD2098_03_s _ 2015_11				
Action/Comments					
Control annual grass and weeds on the levee slopes and easements.					

No Photos

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown		<b>** Rating</b> A : Acceptable                      N : Not Inspected/Rated M : Minimally Acceptable        C : Corrected U : Unacceptable                  A/W : Acceptable but Monitor & Maintain		<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance  
Levee Inspections**

**Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2015**

**Reclamation District No. 2098 Cache and Haas Slough**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 Haas Slough	Right	1.94	05/14/2015 05/14/2015	Herman Phillips

LM Start	8.46	Rating **	U	Issue No.	19
LM End	8.69	Issue Type +	Ma	Location *	CR
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.308293 °	38.311033 °
				-121.732993 °	-121.734652 °
DWR ID	DWR_RD2098_03_s _ 2015_19				
Action/Comments					
Keep the crown roadway free of vegetation.					
Inspector Comments: Control the weeds off the crown roadway.					

Photo 1 of 1 : SP\_2015\_RD2098\_247\_19\_20150604\_00009.jpg



View of unacceptable weeds on the crown roadway.

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown		<b>** Rating</b> A : Acceptable                      N : Not Inspected/Rated M : Minimally Acceptable        C : Corrected U : Unacceptable                  A/W : Acceptable but Monitor & Maintain		<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance  
Levee Inspections**

## Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2015

### Reclamation District No. 2098 Cache and Haas Slough

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 04 Back Levee	Left	2.95	05/14/2015 05/14/2015	Herman Phillips

LM Start	9.15	Rating **	M	Issue No.	4
LM End	9.15	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.316167 °	38.316167 °
				-121.740120 °	-121.740115 °
DWR ID	DWR_RD2098_04_s _ 2014_4				
Action/Comments					
Remove the wild growth other than native grasses from the levee slopes.					

Photo 1 of 1 : SP\_2015\_RD2098\_248\_4\_20150604\_00002.jpg



View looking downstream along the landside slope.

LM Start	9.68	Rating **	M	Issue No.	8
LM End	9.73	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Erosion / Bank Caving			38.323749 °	38.324467 °
				-121.740148 °	-121.740155 °
DWR ID	DWR_RD2098_04_s _ 2014_8				
Action/Comments					
Note and monitor erosion site.					

No Photos

LM Start	9.71	Rating **	M	Issue No.	10
LM End	12.07	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.324248 °	38.358122 °
				-121.740128 °	-121.740388 °
DWR ID	DWR_RD2098_04_s _ 2015_10				
Action/Comments					
Remove the wild growth other than native grasses from the levee slopes.					

No Photos

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown		<b>** Rating</b> A : Acceptable                      N : Not Inspected/Rated M : Minimally Acceptable        C : Corrected U : Unacceptable                  A/W : Acceptable but Monitor & Maintain		<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance  
Levee Inspections**

**Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2015**

**Reclamation District No. 2098 Cache and Haas Slough**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 04 Back Levee	Left	2.95	05/14/2015 05/14/2015	Herman Phillips

LM Start	9.73	Rating **	M	Issue No.	11
LM End	12.07	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.324492 °	38.358122 °
				-121.740127 °	-121.740388 °
DWR ID	DWR_RD2098_04_s_2015_11				
Action/Comments					
Control annual grass and weeds on the levee slopes and easements.					

No Photos

LM Start	9.77	Rating **	U	Issue No.	12
LM End	9.78	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.325062 °	38.325265 °
				-121.740128 °	-121.740100 °
DWR ID	DWR_RD2098_04_s_2015_12				
Action/Comments					
Control annual grass and weeds on the levee slopes and easements. Inspector Comments: Remove the unacceptable vegetation.					

Photo 1 of 1 : SP\_2015\_RD2098\_248\_12\_20150604\_00003.jpg



View of unacceptable tall weeds on the waterside levee slope.

* Location LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement	
---	--	--	--	--	--