

**Flood Control Project Maintenance
Levee Inspections**
LMA District Cover Sheet
Spring 2010 Levee Inspection Results

Sutter Maintenance Yard East Levee Sacramento River

| | Spring (March - May) | Summer ** (June - August) | Fall (September - November) | Winter ** (December - February) |
|----------------------------------|-------------------------|------------------------------|--------------------------------|------------------------------------|
| * Overall LMA Rating (Fall Only) | | | | |

** Non-receipt of Summer or Winter Inspection Reports may effect overall annual rating.

* **SPRING INSPECTIONS:** Overall maintenance ratings are not determined for the spring inspection results. Individual maintenance deficiencies are rated using the same criteria in the spring and in the fall.

FALL INSPECTIONS: The overall maintenance rating shown above is based on operation and maintenance deficiencies identified within the attached unit inspection reports.

Comments

| |
|--|
| |
| |
| |
| |
| |
| |
| |

**Flood Control Project Maintenance
Levee Inspections**

Unit Cover Sheet

Spring 2010 Levee Inspection Results

Sutter Maintenance Yard East Levee Sacramento River

| Waterway | Bank | Unit Miles |
|------------------------------|------|------------|
| Unit No. 01 Sacramento River | Left | 20.39 |

| | Spring (March - May) | Summer (June - August) | (September - November) Fall | Winter (December - February) |
|--|--------------------------------|---------------------------|--------------------------------|---------------------------------|
| Unit Maintenance Rating (Fall Only) | | | | |
| Date of Inspection | 5/11/2010 - 5/11/2010 | | | |
| DWR Inspector | Bob Duffey | | | |
| Accompanied By | Bryan Reniff Sutter Yard | | | |
| | Karen Hull Sutter Yard | | | |
| | Joel Farias Jr. Sutter Yard | | | |

Check one:

- During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.
- During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

Comments

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :

DWR Summer/Winter Inspection Reports
3310 El Camino Avenue, Room LL-30
Sacramento, CA 95821-9000

| |
|--|
| |
| |
| |
| |
| |
| |
| |
| |

X

Signature of LMA Representative

Date

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2010

Sutter Maintenance Yard East Levee Sacramento River

| Waterway | Bank | Unit Miles | Inspection Start/End | Inspector |
|------------------------------|------|------------|--------------------------|------------|
| Unit No. 01 Sacramento River | Left | 20.39 | 05/11/2010 05/11/2010 | Bob Duffey |

| LMIR No | Levee Mile | | Category | Item | Location | Rating | Action/Comment | GPS Latitude/Longitude | | Issue No. Photo |
|---------|------------|-------|---------------|-----------------------|----------|--------|--|------------------------------|------------------------------|--------------------|
| | Start | End | | | | | | Start | End | |
| 1 | 0.08 | 0.14 | Earthen Levee | Encroachments | WS | CO | Buildings | 39.194978 ° -121.937502 ° | 39.195022 ° -121.938563 ° | 3 Y |
| 2 | 1.54 | 1.69 | Earthen Levee | Animal Control | LS | M | No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows. | 39.191057 ° -121.960547 ° | 39.189465 ° -121.962527 ° | 18 |
| 3 | 5.30 | 5.34 | Earthen Levee | Animal Control | LS | M | Exterminate rodents and backfill and compact or grout burrows. | 39.216609 ° -122.002245 ° | 39.216801 ° -122.002964 ° | 1 |
| 4 | 5.37 | 5.37 | Earthen Levee | Encroachments | LS | M | Prunings | 39.217235 ° -122.003672 ° | 39.217235 ° -122.003672 ° | 19 |
| 5 | 6.33 | 6.33 | Earthen Levee | Encroachments | LS | C | Prunings | 39.223637 ° -121.998848 ° | 39.223637 ° -121.998848 ° | 20 |
| 6 | 6.42 | 6.42 | Earthen Levee | Encroachments | LS | M | Material | 39.224982 ° -121.998600 ° | 39.225013 ° -121.998585 ° | 21 |
| 7 | 6.43 | 6.43 | Earthen Levee | Animal Control | LS | C | Exterminate rodents and backfill and compact or grout burrows. | 39.225133 ° -121.998597 ° | 39.225133 ° -121.998597 ° | 22 |
| 8 | 6.93 | 6.96 | Earthen Levee | Animal Control | LS | M | Exterminate rodents and backfill and compact or grout burrows. | 39.229842 ° -121.995837 ° | 39.230292 ° -121.995765 ° | 23 |
| 9 | 8.76 | 8.76 | Earthen Levee | Encroachments | LS | CO | Buildings | 39.252260 ° -121.997721 ° | 39.252260 ° -121.997721 ° | 2 |
| 10 | 10.27 | 10.27 | Earthen Levee | Encroachments | LS | PO | Buildings | 39.270431 ° -121.999782 ° | 39.270431 ° -121.999782 ° | 4 |
| 11 | 10.36 | 10.36 | Earthen Levee | Vegetation | LS | M | Elderberries are blocking visibility and flood fight capability. | 39.270503 ° -122.001339 ° | 39.270503 ° -122.001339 ° | 5 |
| 12 | 11.67 | 11.90 | Earthen Levee | Encroachments | LS | PO | Agricultural Ditch | 39.282064 ° -122.016517 ° | 39.285084 ° -122.014815 ° | 6 |
| 13 | 11.95 | 12.18 | Earthen Levee | Encroachments | LS | PO | Agricultural Ditch | 39.285658 ° -122.014574 ° | 39.288978 ° -122.013892 ° | 7 |
| 14 | 12.18 | 12.46 | Earthen Levee | Trim / Thin Trees | LS | M | Trim trees to at least five feet above ground level. | 39.289029 ° -122.013891 ° | 39.293124 ° -122.013467 ° | 8 |
| 15 | 12.57 | 12.57 | Earthen Levee | Trim / Thin Trees | LS | M | Thin trees to allow visibility of the ground and room to flood fight. | 39.294880 ° -122.014133 ° | 39.294880 ° -122.014133 ° | 13 Y |
| 16 | 13.18 | 13.18 | Earthen Levee | Animal Control | WS | C | Exterminate rodents and backfill and compact or grout burrows. | 39.303152 ° -122.013128 ° | 39.303152 ° -122.013128 ° | 27 |
| 17 | 13.47 | 13.66 | Earthen Levee | Erosion / Bank Caving | WS | M | Note and monitor erosion site. | 39.307448 ° -122.013037 ° | 39.310231 ° -122.012912 ° | 9 |
| 18 | 15.79 | 15.83 | Earthen Levee | Animal Control | LS | C | No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows. | 39.338152 ° -122.022677 ° | 39.338323 ° -122.022230 ° | 24 |

*** Location**
 LS : Land Side
 WS : Water Side
 CR : Crown

**** Rating**
 A : Acceptable
 M : Minimally Acceptable
 U : Unacceptable
 PO : Partially Obstructing
 CO : Completely Obstructing
 N : Not Inspected
 C : Corrected
 W : Watch/Monitor

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2010

Sutter Maintenance Yard East Levee Sacramento River

| Waterway | Bank | Unit Miles | Inspection Start/End | Inspector |
|------------------------------|------|------------|--------------------------|------------|
| Unit No. 01 Sacramento River | Left | 20.39 | 05/11/2010 05/11/2010 | Bob Duffey |

| LMIR No | Levee Mile | | Category | Item | Location * | Rating ** | Action/Comment | GPS Latitude/Longitude | | Issue No. Photo |
|---------|------------|-------|---------------|----------------|------------|-----------|--|------------------------------|------------------------------|--------------------|
| | Start | End | | | | | | Start | End | |
| 19 | 16.01 | 16.36 | Earthen Levee | Animal Control | LS | C | Exterminate rodents and backfill and compact or grout burrows. | 39.340367 ° -122.023185 ° | 39.344942 ° -122.023668 ° | 28 |
| 20 | 16.97 | 16.97 | Earthen Levee | Encroachments | LS | C | Prunings | 39.347280 ° -122.015095 ° | 39.347280 ° -122.015095 ° | 26 |
| 21 | 17.71 | 17.81 | Earthen Levee | Animal Control | LS | C | Exterminate rodents and backfill and compact or grout burrows. | 39.355107 ° -122.009207 ° | 39.356445 ° -122.008762 ° | 29 |
| 22 | 17.88 | 18.01 | Earthen Levee | Animal Control | WS | C | Exterminate rodents and backfill and compact or grout burrows. | 39.357513 ° -122.008460 ° | 39.359033 ° -122.007390 ° | 30 |
| 23 | 18.00 | 18.08 | Earthen Levee | Encroachments | LS | M | Firewood | 39.358956 ° -122.007492 ° | 39.359565 ° -122.006219 ° | 10 |
| 24 | 18.04 | 18.18 | Earthen Levee | Encroachments | LS | M | Equipment | 39.359188 ° -122.006878 ° | 39.359980 ° -122.004517 ° | 16 Y |
| 25 | 18.11 | 18.11 | Earthen Levee | Encroachments | LS | C | Prunings | 39.359718 ° -122.005793 ° | 39.359718 ° -122.005793 ° | 31 |

| | |
|--|--|
| * Location LS : Land Side WS : Water Side CR : Crown | ** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected C : Corrected W : Watch/Monitor |
|--|--|

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2010

Sutter Maintenance Yard East Levee Sacramento River

| Waterway | Bank | Unit Miles | Inspection Start/End | Inspector |
|------------------------------|------|------------|--------------------------|------------|
| Unit No. 01 Sacramento River | Left | 20.39 | 05/11/2010 05/11/2010 | Bob Duffey |

| | |
|--|---------------|
| Levee Mile Report Line | 1 |
| Start Levee Mile | 0.08 |
| End Levee Mile | 0.14 |
| Location | Water Side |
| Category | Earthen Levee |
| Item | Encroachments |
| View of a old building next to the landside toe. | |
| rduffey_s_20100622_072.jpg | |



| | |
|--|-------------------|
| Levee Mile Report Line | 15 |
| Start Levee Mile | 12.57 |
| End Levee Mile | 12.57 |
| Location | Land Side |
| Category | Earthen Levee |
| Item | Trim / Thin Trees |
| View of the trees and landscape next to the landside toe of the levee. | |
| rduffey_s_20100625_082.jpg | |



| | |
|--|---------------|
| Levee Mile Report Line | 24 |
| Start Levee Mile | 18.04 |
| End Levee Mile | 18.18 |
| Location | Land Side |
| Category | Earthen Levee |
| Item | Encroachments |
| View of the equipment and trees next to the landside toe of the levee. | |
| rduffey_s_20100625_083.jpg | |



| | | | |
|--|--|--|------------------------------------|
| * Location LS : Land Side WS : Water Side CR : Crown | ** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable | PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected | C : Corrected W : Watch/Monitor |
|--|--|--|------------------------------------|

**Flood Control Project Maintenance
Levee Inspections**

Unit Cover Sheet

Spring 2010 Levee Inspection Results

Sutter Maintenance Yard East Levee Sacramento River

| Waterway | Bank | Unit Miles |
|---------------------------|-------|------------|
| Unit No. 02 Colusa Bypass | Right | 2.20 |

| | Spring (March - May) | Summer (June - August) | (September - November) Fall | Winter (December - February) |
|--|-----------------------------|---------------------------|--------------------------------|---------------------------------|
| Unit Maintenance Rating (Fall Only) | | | | |
| Date of Inspection | 5/11/2001 - 5/11/2010 | | | |
| DWR Inspector | Bob Duffey | | | |
| Accompanied By | Bryan Reniff Sutter Yard | | | |

Check one:

During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.

During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

Comments

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :

DWR Summer/Winter Inspection Reports
3310 El Camino Avenue, Room LL-30
Sacramento, CA 95821-9000

| |
|--|
| |
| |
| |
| |
| |
| |
| |
| |

X _____ Date

Signature of LMA Representative

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2010

Sutter Maintenance Yard East Levee Sacramento River

| Waterway | | | Bank | Unit Miles | Inspection Start/End | Inspector |
|---------------------------|--|--|-------|------------|--------------------------|------------|
| Unit No. 02 Colusa Bypass | | | Right | 2.20 | 05/11/2001 05/11/2010 | Bob Duffey |

| LMIR No | Levee Mile | | Category | Item | Location * | Rating ** | Action/Comment | GPS Latitude/Longitude | | Issue No. Photo |
|---------|------------|------|---------------|------------|------------|-----------|--|------------------------------|------------------------------|--------------------|
| | Start | End | | | | | | Start | End | |
| 1 | 0.01 | 0.01 | Earthen Levee | Vegetation | LS | M | Elderberries are blocking visibility and flood fight capability. | 39.232058 ° -121.995514 ° | 39.232058 ° -121.995514 ° | 1 Y |

| | |
|---|---|
| <p>* Location</p> <p>LS : Land Side WS : Water Side CR : Crown</p> | <p>** Rating</p> <p>A : Acceptable PO : Partially Obstructing C : Corrected M : Minimally Acceptable CO : Completely Obstructing W : Watch/Monitor U : Unacceptable N : Not Inspected</p> |
|---|---|

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2010

Sutter Maintenance Yard East Levee Sacramento River

| Waterway | Bank | Unit Miles | Inspection Start/End | Inspector |
|---------------------------|-------|------------|--------------------------|------------|
| Unit No. 02 Colusa Bypass | Right | 2.20 | 05/11/2001 05/11/2010 | Bob Duffey |

| | |
|------------------------|---------------|
| Levee Mile Report Line | 1 |
| Start Levee Mile | 0.01 |
| End Levee Mile | 0.01 |
| Location | Land Side |
| Category | Earthen Levee |
| Item | Vegetation |

View of the elderberries along the landside toe of the levee.

rduffey_s_20100622_067.jpg



*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable PO : Partially Obstructing C : Corrected
M : Minimally Acceptable CO : Completely Obstructing W : Watch/Monitor
U : Unacceptable N : Not Inspected

**Flood Control Project Maintenance
Levee Inspections**

Unit Cover Sheet

Spring 2010 Levee Inspection Results

Sutter Maintenance Yard East Levee Sacramento River

| Waterway | Bank | Unit Miles |
|---------------------------|------|------------|
| Unit No. 03 Colusa Bypass | Left | 2.28 |

| | Spring (March - May) | Summer (June - August) | (September - November) Fall | Winter (December - February) |
|--|-----------------------------|---------------------------|--------------------------------|---------------------------------|
| Unit Maintenance Rating (Fall Only) | | | | |
| Date of Inspection | 5/21/2010 - 5/21/2010 | | | |
| DWR Inspector | Bob Duffey | | | |
| Accompanied By | Bryan Reniff Sutter Yard | | | |

Check one:

During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.

During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

Comments

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :

DWR Summer/Winter Inspection Reports
3310 El Camino Avenue, Room LL-30
Sacramento, CA 95821-9000

| |
|--|
| |
| |
| |
| |
| |
| |
| |
| |

X

Signature of LMA Representative

Date

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2010

Sutter Maintenance Yard East Levee Sacramento River

| Waterway | | | Bank | Unit Miles | Inspection Start/End | Inspector |
|---------------------------|--|--|------|------------|--------------------------|------------|
| Unit No. 03 Colusa Bypass | | | Left | 2.28 | 05/21/2010 05/21/2010 | Bob Duffey |

| LMIR No | Levee Mile | | Category | Item | Location * | Rating ** | Action/Comment | GPS Latitude/Longitude | | Issue No. Photo |
|---------|------------|------|---------------|------------|------------|-----------|--|------------------------------|------------------------------|--------------------|
| | Start | End | | | | | | Start | End | |
| 1 | 1.98 | 1.98 | Earthen Levee | Vegetation | LS | M | Elderberries are blocking visibility and flood fight capability. | 39.244888 ° -121.965595 ° | 39.244888 ° -121.965595 ° | 10 Y |
| 2 | 2.17 | 2.17 | Earthen Levee | Vegetation | WS | M | Elderberries are blocking visibility and flood fight capability. | 39.244838 ° -121.962072 ° | 39.244838 ° -121.962072 ° | 13 |

| | |
|--|--|
| * Location LS : Land Side WS : Water Side CR : Crown | ** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected C : Corrected W : Watch/Monitor |
|--|--|

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2010

Sutter Maintenance Yard East Levee Sacramento River

| Waterway | Bank | Unit Miles | Inspection Start/End | Inspector |
|---------------------------|------|------------|--------------------------|------------|
| Unit No. 03 Colusa Bypass | Left | 2.28 | 05/21/2010 05/21/2010 | Bob Duffey |

| | |
|---|---------------|
| Levee Mile Report Line | 1 |
| Start Levee Mile | 1.98 |
| End Levee Mile | 1.98 |
| Location | Land Side |
| Category | Earthen Levee |
| Item | Vegetation |
| View of the elderberries along the landside toe of the levee. | |
| rduffey_s_20100630_099.jpg | |



| | |
|---|---|
| <p>* Location</p> <p>LS : Land Side WS : Water Side CR : Crown</p> | <p>** Rating</p> <p>A : Acceptable PO : Partially Obstructing C : Corrected M : Minimally Acceptable CO : Completely Obstructing W : Watch/Monitor U : Unacceptable N : Not Inspected</p> |
|---|---|

**Flood Control Project Maintenance
Levee Inspections**

Unit Cover Sheet

Spring 2010 Levee Inspection Results

Sutter Maintenance Yard East Levee Sacramento River

| Waterway | Bank | Unit Miles |
|----------------------------|-------|------------|
| Unit No. 04 Moulton Bypass | Right | 0.30 |

| | Spring (March - May) | Summer (June - August) | (September - November) Fall | Winter (December - February) |
|--|--------------------------------|---------------------------|--------------------------------|---------------------------------|
| Unit Maintenance Rating (Fall Only) | | | | |
| Date of Inspection | 5/21/2010 - 5/21/2010 | | | |
| DWR Inspector | Bob Duffey | | | |
| Accompanied By | Bryan Reniff Sutter Yard | | | |
| | Karen Hull Sutter Yard | | | |
| | Joel Farias Jr. Sutter Yard | | | |

Check one:

- During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.
- During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

Comments

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :

DWR Summer/Winter Inspection Reports
3310 El Camino Avenue, Room LL-30
Sacramento, CA 95821-9000

| |
|--|
| |
| |
| |
| |
| |
| |
| |
| |

X

Signature of LMA Representative

Date

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2010

Sutter Maintenance Yard East Levee Sacramento River

| Waterway | Bank | Unit Miles | Inspection Start/End | Inspector |
|----------------------------|-------|------------|--------------------------|------------|
| Unit No. 04 Moulton Bypass | Right | 0.30 | 05/21/2010 05/21/2010 | Bob Duffey |

| LMIR No | Levee Mile | | Category | Item | Location * | Rating ** | Action/Comment | GPS Latitude/Longitude | | Issue No. Photo |
|---------|------------|------|---------------|----------------|------------|-----------|--|------------------------------|------------------------------|--------------------|
| | Start | End | | | | | | Start | End | |
| 1 | 0.02 | 0.02 | Earthen Levee | Vegetation | WS | M | Elderberries are blocking visibility and flood fight capability. | 39.338141 ° -122.021852 ° | 39.338141 ° -122.021852 ° | 2 Y |
| 2 | 0.13 | 0.13 | Earthen Levee | Animal Control | WS | C | Exterminate rodents and backfill and compact or grout burrows. | 39.337497 ° -122.019807 ° | 39.337497 ° -122.019807 ° | 1 |

| | |
|--|--|
| * Location LS : Land Side WS : Water Side CR : Crown | ** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected C : Corrected W : Watch/Monitor |
|--|--|

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2010

Sutter Maintenance Yard East Levee Sacramento River

| Waterway | Bank | Unit Miles | Inspection Start/End | Inspector |
|----------------------------|-------|------------|--------------------------|------------|
| Unit No. 04 Moulton Bypass | Right | 0.30 | 05/21/2010 05/21/2010 | Bob Duffey |

| | |
|------------------------|---------------|
| Levee Mile Report Line | 1 |
| Start Levee Mile | 0.02 |
| End Levee Mile | 0.02 |
| Location | Water Side |
| Category | Earthen Levee |
| Item | Vegetation |

View of a Elderberries bush by the waterside toe.

rduffey_s_20100622_073.jpg



| | |
|------------------------|---------------|
| Levee Mile Report Line | 1 |
| Start Levee Mile | 0.02 |
| End Levee Mile | 0.02 |
| Location | Water Side |
| Category | Earthen Levee |
| Item | Vegetation |

View of the elderberry & Oak tree by the waterside toe of the levee.

rduffey_s_20100625_084.jpg



| | | | |
|---|---|---|--|
| <p>* Location</p> <p>LS : Land Side WS : Water Side CR : Crown</p> | <p>** Rating</p> <p>A : Acceptable M : Minimally Acceptable U : Unacceptable</p> | <p>PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected</p> | <p>C : Corrected W : Watch/Monitor</p> |
|---|---|---|--|

**Flood Control Project Maintenance
Levee Inspections**

Unit Cover Sheet

Spring 2010 Levee Inspection Results

Sutter Maintenance Yard East Levee Sacramento River

| Waterway | Bank | Unit Miles |
|----------------------------|------|------------|
| Unit No. 05 Moulton Bypass | Left | 2.00 |

| | Spring (March - May) | Summer (June - August) | (September - November) Fall | Winter (December - February) |
|--|-----------------------------|---------------------------|--------------------------------|---------------------------------|
| Unit Maintenance Rating (Fall Only) | | | | |
| Date of Inspection | 5/21/2010 - 5/21/2010 | | | |
| DWR Inspector | Bob Duffey | | | |
| Accompanied By | Bryan Reniff Sutter Yard | | | |

Check one:

During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.

During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

Comments

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :

DWR Summer/Winter Inspection Reports
3310 El Camino Avenue, Room LL-30
Sacramento, CA 95821-9000

| |
|--|
| |
| |
| |
| |
| |
| |
| |
| |

X

Signature of LMA Representative

Date

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2010

Sutter Maintenance Yard East Levee Sacramento River

| Waterway | Bank | Unit Miles | Inspection Start/End | Inspector |
|----------------------------|------|------------|--------------------------|------------|
| Unit No. 05 Moulton Bypass | Left | 2.00 | 05/21/2010 05/21/2010 | Bob Duffey |

| LMIR No | Levee Mile | | Category | Item | Location * | Rating ** | Action/Comment | GPS Latitude/Longitude | | Issue No. Photo |
|---------|------------|------|---------------|----------------|------------|-----------|--|------------------------------|------------------------------|--------------------|
| | Start | End | | | | | | Start | End | |
| 1 | 0.42 | 0.45 | Earthen Levee | Animal Control | LS | C | Exterminate rodents and backfill and compact or grout burrows. | 39.342852 ° -122.015438 ° | 39.342683 ° -122.014908 ° | 1 |
| 2 | 0.94 | 0.94 | Earthen Levee | Animal Control | LS | M | No rodents visible, but rodent burrows visible; need to backfill and compact or grout borrows. | 39.339592 ° -122.006717 ° | 39.339592 ° -122.006717 ° | 4 Y |

| | |
|--|--|
| * Location LS : Land Side WS : Water Side CR : Crown | ** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected C : Corrected W : Watch/Monitor |
|--|--|

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2010

Sutter Maintenance Yard East Levee Sacramento River

| Waterway | Bank | Unit Miles | Inspection Start/End | Inspector |
|----------------------------|------|------------|--------------------------|------------|
| Unit No. 05 Moulton Bypass | Left | 2.00 | 05/21/2010 05/21/2010 | Bob Duffey |

| | |
|---|----------------|
| Levee Mile Report Line | 2 |
| Start Levee Mile | 0.94 |
| End Levee Mile | 0.94 |
| Location | Land Side |
| Category | Earthen Levee |
| Item | Animal Control |
| View of the squirrel hole on the landside slope of the levee. | |
| rduffey_s_20100625_085.jpg | |



| | |
|---|---|
| <p>* Location</p> <p>LS : Land Side WS : Water Side CR : Crown</p> | <p>** Rating</p> <p>A : Acceptable PO : Partially Obstructing C : Corrected M : Minimally Acceptable CO : Completely Obstructing W : Watch/Monitor U : Unacceptable N : Not Inspected</p> |
|---|---|