

**Flood Control Project Maintenance  
Levee Inspections**

**Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2014**

**Sacramento Maintenance Yard East Levee Yolo Bypass**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Yolo Bypass	Left	2.01	11/04/2014 11/04/2014	Clay Thomas

LM Start		Rating **	A	Issue No.	3
LM End		Issue Type +	Ma	Location *	N/A
Category	Earthen Levee		GPS Latitude/Longitude		
			Start		End
Item	Operations & Maintenance Manuals			°	
				°	
DWR ID	DWR_ST0004_01_s_2013_3				
Action/Comments					
Inspector Comments: The Sacramento Maintenance Yard has the levee manuals.					

No Photos

LM Start		Rating **	A	Issue No.	4
LM End		Issue Type +	Ma	Location *	N/A
Category	Earthen Levee		GPS Latitude/Longitude		
			Start		End
Item	Emergency Supplies & Equipment			°	
				°	
DWR ID	DWR_ST0004_01_s_2013_4				
Action/Comments					
Inspector Comments: The Sacramento Maintenance Yard maintains a stockpile of flood response material.					

No Photos

LM Start		Rating **	A	Issue No.	5
LM End		Issue Type +	Ma	Location *	N/A
Category	Earthen Levee		GPS Latitude/Longitude		
			Start		End
Item	Flood Preparedness & Training			°	
				°	
DWR ID	DWR_ST0004_01_s_2013_5				
Action/Comments					
Inspector Comments: The Sacramento Maintenance Yard has a written response plan and regular flood response training.					

No Photos

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

**Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2014**

**Sacramento Maintenance Yard East Levee Yolo Bypass**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Yolo Bypass	Left	2.01	11/04/2014 11/04/2014	Clay Thomas

LM Start	0.01	Rating **	A	Issue No.	1		
LM End	2.00	Issue Type +	Ma	Location *	LS		
Category	Earthen Levee			GPS Latitude/Longitude			
				Start		End	
Item	Vegetation				°		°
					°		°
DWR ID	DWR_ST0004_01_f_2014_1						
Action/Comments							
Control annual grass and weeds on the levee slopes and easements.							

Photo 1 of 1 : FA\_2014\_ST0004\_41\_1\_20141106\_00002.jpg



Levee mile 1.98, vegetation on levee slopes and crown. Fall 2014.

LM Start	0.01	Rating **	C	Issue No.	11
LM End	0.19	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.765295 °	38.762751 °
				-121.635085 °	-121.635422 °
DWR ID	DWR_ST0004_01_f_2013_11				
Action/Comments					
Trees / Woody Vegetation					

No Photos

**\* Location**  
 LS : Land Side    N/A : Not Applicable  
 WS : Water Side  
 CR : Crown

**\*\* Rating**  
 A : Acceptable                      N : Not Inspected/Rated  
 M : Minimally Acceptable        C : Corrected  
 U : Unacceptable                  A/W : Acceptable but Monitor & Maintain

**+ Issue Type**  
 Ma : Maintenance Deficiency  
 Ob : Design & System Obsolescence  
 En : Enforcement