

Sacramento Maintenance Yard East Levee Yolo Bypass

No Photos

No Photos

No Photos

Page 1 of 4

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2018

Sacramento Maintenance Yard East Levee Yolo Bypass

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Yolo Bypass	Left	2.01	11/07/2018 11/07/2018	Zach Jojola

LM Start	1.71	Rating **	A/W	Issue No.	6	
LM End	1.71	Issue Type +	Ma	Location *		
Category	Supplemental			GPS Latitude/Longitude		
				Start		End
Item	DWR UCIP LMA Responsibility			38.740710 °		38.740710 °
				-121.633981 °		-121.633981 °
DWR ID	838					
Comment Code						
Inspector Comment						
FS_ID:53253 DS_ID:838 EP_NO: N/A Repair Type: No Action Needed Crossing Status: Found UCIP Comments: 11/16/17 Ted Skidgel, pipe is closed on w/s and closed on L/S. Mud removed recently from WS pipes. FIELD_STRUCT_DESC: 1 of 2: 48-inch corrugated metal drainage pipe through the levee, 28.5 feet below the crown. 30-inch steel pipe sleeved through the 48-inch pipe. Slide gate in a 60-inch pipe riser on the waterside (WS) slope. [Additional Reference(s): DWR Levee Log, 1981. USACE Sacramento O&M Manual 123, August 1955, (Station 382+85)]. No permit or as-built drawing available. FS Date: 11/21/2018 8:31:59 AM						

LM Start	1.71	Rating **	A/W	Issue No.	6 (cont)
LM End	1.71	Issue Type +	Ma	Location *	

Photo 1 of 3 : UCIP_FA_2018_53253_60261.jpg



Waterside view: overview CMP standpipe and water body

Photo 2 of 3 : UCIP_FA_2018_53253_60260.jpg



Waterside view: steel pipe and concrete headwall

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
----------------------------------------------------------------------------------------------	------------------------------------------------------------------------------------	-------------------------------------------------------------------------------------	-------------------------------------------------------------------------------------------------------------

Sacramento Maintenance Yard East Levee Yolo Bypass

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2018

Sacramento Maintenance Yard East Levee Yolo Bypass

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Yolo Bypass	Left	2.01	11/07/2018 11/07/2018	Zach Jojola

LM Start	1.71	Rating **	A/W	Issue No.	7 (cont)	
LM End	1.71	Issue Type +	Ma	Location *		
Category	Supplemental			GPS Latitude/Longitude		
				Start		End
Item	DWR UCIP LMA Responsibility			38.740686 °		38.740686 °
				-121.633979 °		-121.633979 °
DWR ID	840					
Comment Code						
Inspector Comment						
FS_ID:53254 DS_ID:840 EP_NO: N/A Repair Type: No Action Needed Crossing Status: Found UCIP Comments: FIELD_STRUCT_DESC: 2 of 2: 48-inch corrugated metal drainage pipe through the levee, 28.5 feet below the crown. 30-inch steel pipe sleeved through the 48-inch pipe. Slide gate in a 60-inch pipe riser on the waterside (WS) slope. [Additional Reference(s): DWR Levee Log, 1981. USACE Sacramento O&M Manual 123, August 1955, (Station 382+85)]. No permit or as-built drawing available. FS Date: 11/21/2018 8:34:20 AM						

LM Start	1.71	Rating **	A/W	Issue No.	7 (cont)
LM End	1.71	Issue Type +	Ma	Location *	

Photo 2 of 3 : UCIP_FA_2018_53254_60268.jpg



Waterside view: mud clogged pipe, trash rack and headwall

Photo 3 of 3 : UCIP_FA_2018_53254_60267.jpg



Waterside view: overview pipes and headwall

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
----------------------------------------------------------------------------------------------	------------------------------------------------------------------------------------	-------------------------------------------------------------------------------------	-------------------------------------------------------------------------------------------------------------