

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2016

Sacramento Maintenance Yard East Levee Yolo Bypass

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Yolo Bypass	Left	2.01	03/29/2016 03/29/2016	Jai Lor

LM Start		Rating **	A	Issue No.	3
LM End		Issue Type +	Ma	Location *	N/A
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Operations & Maintenance Manuals				
DWR ID	DWR_ST0004_01_s_2013_3				
Comment Code					
Inspector Comment					
The Sacramento Maintenance Yard has the levee manuals.					

No Photos

LM Start		Rating **	A	Issue No.	4
LM End		Issue Type +	Ma	Location *	N/A
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Emergency Supplies & Equipment				
DWR ID	DWR_ST0004_01_s_2013_4				
Comment Code					
Inspector Comment					
The Sacramento Maintenance Yard maintains a stockpile of flood response material.					

No Photos

LM Start		Rating **	A	Issue No.	5
LM End		Issue Type +	Ma	Location *	N/A
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Flood Preparedness & Training				
DWR ID	DWR_ST0004_01_s_2013_5				
Comment Code					
Inspector Comment					
The Sacramento Maintenance Yard has a written response plan and regular flood response training.					

No Photos

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
N/A : Not Applicable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2016

Sacramento Maintenance Yard East Levee Yolo Bypass

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Yolo Bypass	Left	2.01	03/29/2016 03/29/2016	Jai Lor

LM Start	0.00	Rating **	M	Issue No.	1
LM End	2.02	Issue Type +	Ma	Location *	LS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Vegetation		38.765317 °	38.736192 °	
			-121.635083 °	-121.633670 °	
DWR ID	DWR_ST0004_01_s_2016_1				
Comment Code					
V1 : Control annual grass and weeds on the levee slopes and easements.					
Inspector Comment					

Photo 1 of 1 : SP_2016_ST0004_41_1_20160401_00004.jpg



View of the vegetation on the landward side of the levee looking downstream. Spring 2016.

LM Start	0.09	Rating **	M	Issue No.	2
LM End	2.02	Issue Type +	Ma	Location *	WS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Vegetation		38.764093 °	38.736192 °	
			-121.635541 °	-121.633670 °	
DWR ID	DWR_ST0004_01_s_2016_2				
Comment Code					
V1 : Control annual grass and weeds on the levee slopes and easements.					
Inspector Comment					

No Photos

LM Start	0.27	Rating **	M	Issue No.	8
LM End	2.02	Issue Type +	Ma	Location *	CR
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Crown Surface / Depressions / Rutting		38.761439 °	38.736191 °	
			-121.635400 °	-121.633670 °	
DWR ID	DWR_ST0004_01_s_2016_8				
Comment Code					
C1 : Add appropriate material and re-grade the levee to bring the crown above the design elevation.					
Inspector Comment					

Photo 1 of 1 : SP_2016_ST0004_41_8_20160401_00005.jpg



View of the crown of the levee looking upstream. Spring 2016.

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	--	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2016

Sacramento Maintenance Yard East Levee Yolo Bypass

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Yolo Bypass	Left	2.01	03/29/2016 03/29/2016	Jai Lor

LM Start	1.42	Rating **	C	Issue No.	7
LM End	1.42	Issue Type +	Ma	Location *	WS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Encroachments		38.744863 °	38.744863 °	
			-121.634251 °	-121.634251 °	
DWR ID	DWR_ST0004_01_f_2015_7				
Comment Code					
TR : Tree or limb					
Inspector Comment					
Issue has been corrected.					

No Photos

LM Start	1.65	Rating **	M	Issue No.	6
LM End	1.65	Issue Type +	Ma	Location *	LS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Animal Control		38.741579 °	38.741579 °	
			-121.634007 °	-121.634007 °	
DWR ID	DWR_ST0004_01_f_2015_6				
Comment Code					
A3 : No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.					
Inspector Comment					

Photo 1 of 1 : SP_2016_ST0004_41_6_20160304_00001.jpg



View of the rodent holes on the landward side of the levee looking upstream. Fall 2015.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---