

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2015

Sutter Maintenance Yard Wadsworth Canal

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Wadsworth Canal	Left	4.63	11/04/2015 11/04/2015	Bob Duffey

LM Start		Rating **	A	Issue No.	10		
LM End		Issue Type +	Ma	Location *	N/A		
Category	Earthen Levee			GPS Latitude/Longitude			
				Start		End	
Item	Operations & Maintenance Manuals				o		o
					o		o
DWR ID	DWR_ST0010_01_s _ 2013_10						
Action/Comments							
Inspector Comments: The LMA has the O&M manuals.							

No Photos

LM Start		Rating **	A	Issue No.	11		
LM End		Issue Type +	Ma	Location *	N/A		
Category	Earthen Levee			GPS Latitude/Longitude			
				Start		End	
Item	Emergency Supplies & Equipment				°		°
					°		°
DWR ID	DWR_ST0010_01_s _ 2013_11						
Action/Comments							
Inspector Comments: The LMA has flood fight supplies and equipment.							

No Photos

LM Start		Rating **	A	Issue No.	12	
LM End		Issue Type +	Ma	Location *	N/A	
Category	Earthen Levee			GPS Latitude/Longitude		
				Start		End
Item	Flood Preparedness & Training				°	
					°	
DWR ID	DWR_ST0010_01_s _ 2013_12					
Action/Comments						
Inspector Comments: The LMA completed flood fight training in 2014.						

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2015

Sutter Maintenance Yard Wadsworth Canal

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Wadsworth Canal	Left	4.63	11/04/2015 11/04/2015	Bob Duffey

LM Start	1.75	Rating **	M	Issue No.	7
LM End	2.39	Issue Type +	Ma	Location *	WS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	2015 USACE Erosion Survey, DRAFT			39.133887 °	39.141757 °
				-121.749526 °	-121.742939 °
DWR ID					
Action/Comments					
Inspector Comments: 2011 - Whole bank is starting to unravel, with failure from poor soils. 2015: Site is part of the extended inventory, last inspected 2011. [2015 Site ID: WAD_2-1_L]					

No Photos

LM Start	1.85	Rating **	U	Issue No.	107
LM End	1.85	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Erosion / Bank Caving			39.135110 °	39.135110 °
				-121.748230 °	-121.748230 °
DWR ID	DWR_ST0010_01_f_2013_107				
Action/Comments					
Schedule repair of erosion site prior to the next inspection.					
Inspector Comments: Repair the erosion under the abandoned pump.					

LM Start	1.85	Rating **	U	Issue No.	107 (cont)
LM End	1.85	Issue Type +	Ma	Location *	WS

Photo 1 of 2 : FA_2015_ST0010_42_107_20150910_00008.jpg



View of the erosion along both sides of the abandoned pump.

Photo 2 of 2 : FA_2015_ST0010_42_107_20150910_00009.jpg



View of the erosion along both sides of the abandoned pump.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement	
--	--	---	--	---	--

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2015

Sutter Maintenance Yard Wadsworth Canal

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Wadsworth Canal	Left	4.63	11/04/2015 11/04/2015	Bob Duffey

LM Start	1.85	Rating **	M	Issue No.	106
LM End	1.85	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			39.135110 °	39.135110 °
				-121.748229 °	-121.748229 °
DWR ID	DWR_ST0010_01_f_2013_106				
Action/Comments					
No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.					

Photo 1 of 1 : FA_2015_ST0010_42_106_20150910_00007.jpg



View of the rodent holes under the irrigation pipe.

LM Start	2.14	Rating **	A	Issue No.	20
LM End	2.14	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			39.138568 °	39.138568 °
				-121.745360 °	-121.745360 °
DWR ID	DWR_ST0010_01_f_2015_20				
Action/Comments					
Control annual grass and weeds on the levee slopes and easements. Inspector Comments: Sutter Yard burned and dragged both slopes.					

Photo 1 of 1 : FA_2015_ST0010_42_20_20151109_00010.jpg



View of no vegetation on both slopes.

LM Start	2.43	Rating **	M	Issue No.	6
LM End	3.30	Issue Type +	Ma	Location *	WS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	2015 USACE Erosion Survey, DRAFT			39.142235 °	39.153095 °
				-121.742609 °	-121.734390 °
DWR ID	DWR_ST0010_01_f_2015_6				
Action/Comments					
Inspector Comments: 2010 - Over steepened levees, some slumping, reach-wide problem. 2011 - Still a reach-wide problem. 2015: Site is part of the extended inventory, last inspected 2011. [2015 Site ID: WAD_2-4_L]					

Photo 1 of 4 : FA_2015_ST0010_42_6_20151210_00019.jpg



View of the erosion along the waterside toe.

* Location		** Rating		+ Issue Type	
LS : Land Side	N/A : Not Applicable	A : Acceptable	N : Not Inspected/Rated	Ma : Maintenance Deficiency	
WS : Water Side		M : Minimally Acceptable	C : Corrected	Ob : Design & System Obsolescence	
CR : Crown		U : Unacceptable	A/W : Acceptable but Monitor & Maintain	En : Enforcement	

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2015

Sutter Maintenance Yard Wadsworth Canal

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Wadsworth Canal	Left	4.63	11/04/2015 11/04/2015	Bob Duffey

LM Start	2.43	Rating **	M	Issue No.	6 (cont)	
LM End	3.30	Issue Type +	Ma	Location *	WS	
Category	Supplemental			GPS Latitude/Longitude		
				Start		End
Item	2015 USACE Erosion Survey, DRAFT			39.142235 °		39.153095 °
				-121.742609 °		-121.734390 °
DWR ID	DWR_ST0010_01_f_2015_6					
Action/Comments						
Inspector Comments: 2010 - Over steepened levees, some slumping, reach-wide problem. 2011 - Still a reach-wide problem. 2015: Site is part of the extended inventory, last inspected 2011. [2015 Site ID: WAD_2-4_L]						

LM Start	2.43	Rating **	M	Issue No.	6 (cont)
LM End	3.30	Issue Type +	Ma	Location *	WS

LM Start	2.43	Rating **	M	Issue No.	6 (cont)
LM End	3.30	Issue Type +	Ma	Location *	WS

Photo 2 of 4 : FA_2015_ST0010_42_6_20151210_00020.jpg



View of the erosion along the waterside toe.

Photo 3 of 4 : FA_2015_ST0010_42_6_20151210_00021.jpg



View of the erosion along the waterside toe.

Photo 4 of 4 : FA_2015_ST0010_42_6_20151210_00022.jpg



View of the erosion along the waterside toe.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement	
---	--	--	--	--	--

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2015

Sutter Maintenance Yard Wadsworth Canal

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Wadsworth Canal	Left	4.63	11/04/2015 11/04/2015	Bob Duffey

LM Start	3.53	Rating **	M	Issue No.	3
LM End	3.56	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Erosion / Bank Caving			39.156225 °	39.156639 °
				-121.732930 °	-121.732755 °
DWR ID	DWR_ST0010_01_s_2012_3				
Action/Comments					
Note and monitor erosion site.					
Inspector Comments: Monitor the erosion along the waterside toe.					

Photo 1 of 1 : FA_2015_ST0010_42_3_20151109_00011.jpg



View of the erosion along the waterside toe.

LM Start	3.65	Rating **	M	Issue No.	4
LM End	3.65	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Erosion / Bank Caving			39.157861 °	39.157861 °
				-121.732238 °	-121.732238 °
DWR ID	DWR_ST0010_01_s_2012_4				
Action/Comments					
Note and monitor erosion site.					
Inspector Comments: Monitor the erosion along the waterside toe.					

Photo 1 of 2 : FA_2015_ST0010_42_4_20150910_00003.jpg



View of the erosion along the waterside toe of the levee.

LM Start	3.65	Rating **	M	Issue No.	4 (cont)
LM End	3.65	Issue Type +	Ma	Location *	WS

Photo 2 of 2 : FA_2015_ST0010_42_4_20151109_00012.jpg



View of the erosion along the waterside toe.

* Location		** Rating		+ Issue Type	
LS : Land Side	N/A : Not Applicable	A : Acceptable	N : Not Inspected/Rated	Ma : Maintenance Deficiency	
WS : Water Side		M : Minimally Acceptable	C : Corrected	Ob : Design & System Obsolescence	
CR : Crown		U : Unacceptable	A/W : Acceptable but Monitor & Maintain	En : Enforcement	

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2015

Sutter Maintenance Yard Wadsworth Canal

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Wadsworth Canal	Left	4.63	11/04/2015 11/04/2015	Bob Duffey

LM Start	3.84	Rating **	M	Issue No.	17
LM End	3.84	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Erosion / Bank Caving			39.160442 °	39.160442 °
				-121.731067 °	-121.731067 °
DWR ID	DWR_ST0010_01_f_2014_17				
Action/Comments					
Note and monitor erosion site.					
Inspector Comments: Monitor the erosion along the waterside toe.					

Photo 1 of 1 : FA_2015_ST0010_42_17_20151109_00013.jpg



View of the erosion along the waterside toe.

LM Start	4.23	Rating **	M	Issue No.	5
LM End	4.23	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Erosion / Bank Caving			39.165845 °	39.165845 °
				-121.728877 °	-121.728877 °
DWR ID	DWR_ST0010_01_s_2012_5				
Action/Comments					
Note and monitor erosion site.					
Inspector Comments: Monitor the erosion along the waterside toe.					

Photo 1 of 2 : FA_2015_ST0010_42_5_20150910_00004.jpg



View of the erosion along the waterside toe.

LM Start	4.23	Rating **	M	Issue No.	5 (cont)
LM End	4.23	Issue Type +	Ma	Location *	WS

Photo 2 of 2 : FA_2015_ST0010_42_5_20151109_00014.jpg



View of the erosion along the waterside toe.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable N : Not Inspected/Rated M : Minimally Acceptable C : Corrected U : Unacceptable A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2015

Sutter Maintenance Yard Wadsworth Canal

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Wadsworth Canal	Right	4.60	10/16/2015 10/16/2015	Bob Duffey

LM Start	1.17	Rating **	M	Issue No.	3
LM End	1.17	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Slope Stability			39.127648 °	39.127648
				-121.756345 °	-121.756345
DWR ID	DWR_ST0010_02_s_2012_3				
Action/Comments					
Repair the levee slope damaged by vehicle traffic and prevent access where possible.					

Photo 1 of 1 : FA_2015_ST0010_43_3_20150910_00001.jpg



View of vehicle erosion along L/S slope.

LM Start	1.38	Rating **	A	Issue No.	20
LM End	1.38	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			39.130125 °	39.130125
				-121.753912 °	-121.753912
DWR ID	DWR_ST0010_02_f_2015_20				
Action/Comments					
Control annual grass and weeds on the levee slopes and easements.					
Inspector Comments: Sutter Yard burned and dragged both slopes.					

Photo 1 of 1 : FA_2015_ST0010_43_20_20151109_00012.jpg



View of no vegetation on both slopes.

LM Start	1.74	Rating **	M	Issue No.	10
LM End	2.37	Issue Type +	Ma	Location *	WS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	2015 USACE Erosion Survey, DRAFT			39.134064 °	39.141814 °
				-121.749781 °	-121.743260 °
DWR ID					
Action/Comments					
Inspector Comments: 2011 - Whole bank is starting to unravel, with failure from poor soils. 2015: Site is part of the extended inventory, last inspected 2011. [2015 Site ID: WAD_2-1_R]					

No Photos

* Location		** Rating		+ Issue Type	
LS : Land Side	N/A : Not Applicable	A : Acceptable	N : Not Inspected/Rated	Ma : Maintenance Deficiency	
WS : Water Side		M : Minimally Acceptable	C : Corrected	Ob : Design & System Obsolescence	
CR : Crown		U : Unacceptable	A/W : Acceptable but Monitor & Maintain	En : Enforcement	

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2015

Sutter Maintenance Yard Wadsworth Canal

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Wadsworth Canal	Right	4.60	10/16/2015 10/16/2015	Bob Duffey

LM Start	1.76	Rating **	A/W	Issue No.	11
LM End	1.76	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			39.134490 °	39.134490 °
				-121.749716 °	-121.749716 °
DWR ID	DWR_ST0010_02_f_2012_11				
Action/Comments					
No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows. Inspector Comments: Repair the rodent hole.					

Photo 1 of 2 : FA_2015_ST0010_43_11_20150910_00006.jpg



View of the rodent holes above the irrigation pipe.

LM Start	1.76	Rating **	A/W	Issue No.	11 (cont)
LM End	1.76	Issue Type +	Ma	Location *	LS

Photo 2 of 2 : FA_2015_ST0010_43_11_20151109_00013.jpg



View of the rodent hole above the irrigation pipe.

LM Start	2.41	Rating **	M	Issue No.	8
LM End	3.28	Issue Type +	Ma	Location *	WS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	2015 USACE Erosion Survey, DRAFT			39.142254 °	39.153150 °
				-121.742847 °	-121.734611 °
DWR ID					
Action/Comments					
Inspector Comments: 2010 - Over steepened levees, some slumping, reach-wide problem. 2011 - Still a reach-wide problem. 2015: Site is part of the extended inventory, last inspected 2011. [2015 Site ID: WAD_2-4_R]					

Photo 1 of 2 : FA_2015_ST0010_43_8_20151210_00016.jpg



View of the erosion along the landside toe.

* Location		** Rating		+ Issue Type	
LS : Land Side	N/A : Not Applicable	A : Acceptable	N : Not Inspected/Rated	Ma : Maintenance Deficiency	
WS : Water Side		M : Minimally Acceptable	C : Corrected	Ob : Design & System Obsolescence	
CR : Crown		U : Unacceptable	A/W : Acceptable but Monitor & Maintain	En : Enforcement	

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2015

Sutter Maintenance Yard Wadsworth Canal

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Wadsworth Canal	Right	4.60	10/16/2015 10/16/2015	Bob Duffey

LM Start	2.41	Rating **	M	Issue No.	8 (cont)	
LM End	3.28	Issue Type +	Ma	Location *	WS	
Category	Supplemental			GPS Latitude/Longitude		
				Start		End
Item	2015 USACE Erosion Survey, DRAFT			39.142254 °		39.153150 °
				-121.742847 °		-121.734611 °
DWR ID						
Action/Comments						
Inspector Comments: 2010 - Over steepened levees, some slumping, reach-wide problem. 2011 - Still a reach-wide problem. 2015: Site is part of the extended inventory, last inspected 2011. [2015 Site ID: WAD_2-4_R]						

Photo 2 of 2 : FA_2015_ST0010_43_8_20151210_00017.jpg



View of erosion along the waterside toe.

LM Start	3.26	Rating **	M	Issue No.	14
LM End	3.26	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Erosion / Bank Caving			39.152903 °	39.152903 °
				-121.734906 °	-121.734906 °
DWR ID	DWR_ST0010_02_s_2012_14				
Action/Comments					
Note and monitor erosion site.					
Inspector Comments: The erosion is scheduled for repair in 2015					

Photo 1 of 1 : FA_2015_ST0010_43_14_20150910_00007.jpg



View of the erosion along the W/S toe.

LM Start	3.42	Rating **	M	Issue No.	4
LM End	3.42	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Erosion / Bank Caving			39.155057 °	39.155057 °
				-121.733985 °	-121.733985 °
DWR ID	DWR_ST0010_02_s_2012_4				
Action/Comments					
Note and monitor erosion site.					
Inspector Comments: Monitor the erosion at the waterside toe.					

Photo 1 of 2 : FA_2015_ST0010_43_4_20150910_00002.jpg



View of the erosion at the waterside toe.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable N : Not Inspected/Rated M : Minimally Acceptable C : Corrected U : Unacceptable A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2015

Sutter Maintenance Yard Wadsworth Canal

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Wadsworth Canal	Right	4.60	10/16/2015 10/16/2015	Bob Duffey

LM Start	3.42	Rating **	M	Issue No.	4 (cont)
LM End	3.42	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Erosion / Bank Caving			39.155057 °	39.155057 °
				-121.733985 °	-121.733985 °
DWR ID	DWR_ST0010_02_s _ 2012_4				
Action/Comments					
Note and monitor erosion site.					
Inspector Comments: Monitor the erosion at the waterside toe.					

Photo 2 of 2 : FA_2015_ST0010_43_4_20151109_00008.jpg



View of the erosion at the waterside toe.

LM Start	3.54	Rating **	M	Issue No.	5
LM End	3.93	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Erosion / Bank Caving			39.156753 °	39.162113 °
				-121.733267 °	-121.730997 °
DWR ID	DWR_ST0010_02_s _ 2012_5				
Action/Comments					
Note and monitor erosion site.					
Inspector Comments: Monitor is the erosion at the waterside toe.					

Photo 1 of 2 : FA_2015_ST0010_43_5_20150910_00003.jpg



View of the erosion along the waterside toe.

LM Start	3.54	Rating **	M	Issue No.	5 (cont)
LM End	3.93	Issue Type +	Ma	Location *	WS

Photo 2 of 2 : FA_2015_ST0010_43_5_20151109_00009.jpg



View of erosion at the waterside toe

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement	
--	--	---	--	---	--

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2015

Sutter Maintenance Yard Wadsworth Canal

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Wadsworth Canal	Right	4.60	10/16/2015 10/16/2015	Bob Duffey

LM Start	4.41	Rating **	M	Issue No.	9
LM End	4.43	Issue Type +	Ma	Location *	WS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	2015 USACE Erosion Survey, DRAFT			39.168659 °	39.168937 °
				-121.728016 °	-121.727905 °
DWR ID					
Action/Comments					
Inspector Comments: 2011 - Small erosion pocket. 2015: Site is part of the extended inventory, last inspected 2011. [2015 Site ID: WAD_4-3_R]					

Photo 1 of 2 : FA_2015_ST0010_43_9_20151210_00018.jpg



View of the erosion along the waterside toe.

LM Start	4.41	Rating **	M	Issue No.	9 (cont)
LM End	4.43	Issue Type +	Ma	Location *	WS

Photo 2 of 2 : FA_2015_ST0010_43_9_20151210_00019.jpg



View of the erosion along the waterside toe.

LM Start	4.48	Rating **	M	Issue No.	7
LM End	4.48	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Erosion / Bank Caving			39.169670 °	39.169670 °
				-121.727787 °	-121.727787 °
DWR ID	DWR_ST0010_02_s_2012_7				
Action/Comments					
Note and monitor erosion site.					
Inspector Comments: Monitor the erosion along the waterside toe.					

Photo 1 of 2 : FA_2015_ST0010_43_7_20150910_00005.jpg



View of the erosion along the W/S toe.

* Location		** Rating		+ Issue Type	
LS : Land Side	N/A : Not Applicable	A : Acceptable	N : Not Inspected/Rated	Ma : Maintenance Deficiency	
WS : Water Side		M : Minimally Acceptable	C : Corrected	Ob : Design & System Obsolescence	
CR : Crown		U : Unacceptable	A/W : Acceptable but Monitor & Maintain	En : Enforcement	

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2015

Sutter Maintenance Yard Wadsworth Canal

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Wadsworth Canal	Right	4.60	10/16/2015 10/16/2015	Bob Duffey

LM Start	4.48	Rating **	M	Issue No.	7 (cont)	
LM End	4.48	Issue Type +	Ma	Location *	WS	
Category	Earthen Levee			GPS Latitude/Longitude		
				Start		End
Item	Erosion / Bank Caving			39.169670 °	39.169670 °	
				-121.727787 °	-121.727787 °	
DWR ID	DWR_ST0010_02_s _ 2012_7					
Action/Comments						
Note and monitor erosion site.						
Inspector Comments: Monitor the erosion along the waterside toe.						

Photo 2 of 2 : FA_2015_ST0010_43_7_20151109_00011.jpg



View of the erosion along the waterside toe.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable N : Not Inspected/Rated M : Minimally Acceptable C : Corrected U : Unacceptable A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement	
---	--	--	--	--	--