

**Flood Control Project Maintenance  
Levee Inspections**  
**LMA District Cover Sheet**  
**Spring 2013 Levee Inspection Results**

**Sacramento Maintenance Yard West Levee Yolo Bypass**

	Spring (March - May)	Summer ** (June - August)	Fall (September - November)	Winter ** (December - February)
* Overall LMA Rating (Fall Only)				

\*\* Non-receipt of Summer or Winter Inspection Reports may effect overall annual rating.

\* **SPRING INSPECTIONS:** Overall maintenance ratings are not determined for the spring inspection results. Individual maintenance deficiencies are rated using the same criteria in the spring and in the fall.

**FALL INSPECTIONS:** The overall maintenance rating shown above is based on operation and maintenance deficiencies identified within the attached unit inspection reports. This rating is not intended to be an indication of risk.

Comments


**Flood Control Project Maintenance  
Levee Inspections**

**Unit Cover Sheet**

**Spring 2013 Levee Inspection Results**

**Sacramento Maintenance Yard West Levee Yolo Bypass**

Waterway	Bank	Unit Miles
Unit No. 01 West Levee	Right	2.72

	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - February)
Unit Maintenance Rating (Fall Only)				
Date of Inspection	-			
DWR Inspector	John Williamson			
Accompanied By	Phil Carey Sacramento Maintenance Yard			
	Ted Skidgel Sacramento Maintenance Yard			

**Summer & Winter Inspections**

The Local Maintaining Agency (LMA) is responsible for summer and winter inspections. The LMA is required to submit a report regarding summer and winter inspections to the California Department of Water Resources (DWR).

DWR must be informed on the:

- a) completion of the inspection
- b) any changes other than the results of normal maintenance
- c) corrections to deficiencies noted in this report

If additional items are noted, further documentation of those items must also be submitted.

The LMA should submit this information to DWR using the LMA web application tool available at:

<http://cdec.water.ca.gov/lma.html>

If the LMA is unable to submit information on this webpage, please contact DWR for assistance.

*The LMA should submit the information and any associated documentation by September 30 for summer inspections and March 31 for winter inspections.*

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2013**

**Sacramento Maintenance Yard West Levee Yolo Bypass**

Waterway				Bank	Unit Miles	Inspection Start/End	Inspector				
Unit No. 01 West Levee				Right	2.72		John Williamson				
LMIR No.	Levee Mile		Category	Item	* Location	** Rating	Action/Comment		GPS Latitude/Longitude		Issue No.
	Start	End					Start	End	Start	End	Photo
1				Operations & Maintenance Manuals	LS	A Ma			°	°	5 Y
DWR ID: DWR_ST0011_01_s_2013_5											
2				Emergency Supplies & Equipment	LS	A Ma			°	°	6 Y
DWR ID: DWR_ST0011_01_s_2013_6											
3				Flood Preparedness & Training	LS	A Ma			°	°	7 Y
DWR ID: DWR_ST0011_01_s_2013_7											
4	0.02	2.72		Vegetation	LS	M Ma	V1 : Control annual grass and weeds on the levee slopes and easements.		38.758952 °	38.724243 °	9 Y
DWR ID: DWR_ST0011_01_s_2013_9											
5	0.02	2.72		Vegetation	WS	M Ma	V1 : Control annual grass and weeds on the levee slopes and easements.		38.758952 °	38.724243 °	10 Y
DWR ID: DWR_ST0011_01_s_2013_10											
6	0.36	0.43		Encroachments	LS	M En	DT : Ditch		38.755535 °	38.754512 °	1 Y
DWR ID: DWR_ST0011_01_s_2012_1											
7	0.93	1.63		Encroachments	LS	M En	DT : Ditch		38.747888 °	38.737688 °	8 Y
DWR ID: DWR_ST0011_01_s_2012_8											
8	2.53	2.68	Supplemental	USACE Erosion Survey	WS	M Ma	Inspector Comments: 2006 - Slow wave wash and general fluvial erosion of the toe area under river cobbles. Erosion is creating a scarp and cobble covered wave-cut bench. 2011 - Site appears better than it looked in 2006, but still eroding. 2012: Site is part of the extended inventory, last inspected 2011. [2012 Site ID: YOL_2-6_R]		38.725505 °	38.724385 °	2 Y
DWR ID: DWR_ST0011_01_s_2013_2											
9	2.63	2.70		Encroachments	LS	M En	DT : Ditch		38.724800 °	38.724230 °	4 Y
DWR ID: DWR_ST0011_01_s_2012_4											

<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2013**

**Sacramento Maintenance Yard West Levee Yolo Bypass**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 West Levee	Right	2.72		John Williamson

Levee Mile Report Line	1
Start Levee Mile	
End Levee Mile	
Location	Land Side
Category	
Item	Operations & Maintenance Manuals
The levee slope is mostly grasses. Photo fall 2012.	
johngw_s_20130221_754.jpg	



Levee Mile Report Line	4
Start Levee Mile	0.02
End Levee Mile	2.72
Location	Land Side
Category	
Item	Vegetation
The vegetation is taller than 12". Spring 2013	
johngw_s_20130408_899.JPG	



Levee Mile Report Line	5
Start Levee Mile	0.02
End Levee Mile	2.72
Location	Water Side
Category	
Item	Vegetation
The vegetation is taller than 12". Spring 2013	
johngw_s_20130408_900.JPG	



<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2013**

**Sacramento Maintenance Yard West Levee Yolo Bypass**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 West Levee	Right	2.72		John Williamson

Levee Mile Report Line	6
Start Levee Mile	0.36
End Levee Mile	0.43
Location	Land Side
Category	
Item	Encroachments
<p>The end of the agricultural ditch along the toe of the levee. Photo taken Fall 2011.</p> <p>johngw_s_20130221_749.jpg</p>	



Levee Mile Report Line	6
Start Levee Mile	0.36
End Levee Mile	0.43
Location	Land Side
Category	
Item	Encroachments
<p>This photo shows the agricultural ditch as it turns towards the levee toe. Photo taken Fall 2011.</p> <p>johngw_s_20130221_750.jpg</p>	



Levee Mile Report Line	6
Start Levee Mile	0.36
End Levee Mile	0.43
Location	Land Side
Category	
Item	Encroachments
<p>Photo taken spring 2012, agricultural ditch runs along toe of levee.</p> <p>johngw_s_20130221_751.jpg</p>	



<p><b>* Location</b></p> <p>LS : Land Side WS : Water Side CR : Crown</p>	<p><b>** Rating</b></p> <p>A : Acceptable M : Minimally Acceptable U : Unacceptable</p> <p>N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor &amp; Maintain</p>	<p><b>+ Issue Type</b></p> <p>Ma : Maintenance Deficiency Ob : Design &amp; System Obsolescence En : Enforcement</p>
---	--	--

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2013**

**Sacramento Maintenance Yard West Levee Yolo Bypass**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 West Levee	Right	2.72		John Williamson

Levee Mile Report Line	7
Start Levee Mile	0.93
End Levee Mile	1.63
Location	Land Side
Category	
Item	Encroachments
<p>The agricultural ditch runs along the toe of the levee. Spring 2013</p> <p>johngw_s_20130408_901.JPG</p>	



Levee Mile Report Line	7
Start Levee Mile	0.93
End Levee Mile	1.63
Location	Land Side
Category	
Item	Encroachments
<p>Another view of the agricultural ditch along the toe. Spring 2013</p> <p>johngw_s_20130408_902.JPG</p>	



Levee Mile Report Line	9
Start Levee Mile	2.63
End Levee Mile	2.70
Location	Land Side
Category	
Item	Encroachments
<p>The agricultural ditch runs along the toe of the levee. Spring 2013</p> <p>johngw_s_20130408_903.JPG</p>	



<p><b>* Location</b></p> <p>LS : Land Side WS : Water Side CR : Crown</p>	<p><b>** Rating</b></p> <p>A : Acceptable M : Minimally Acceptable U : Unacceptable</p> <p>N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor &amp; Maintain</p>	<p><b>+ Issue Type</b></p> <p>Ma : Maintenance Deficiency Ob : Design &amp; System Obsolescence En : Enforcement</p>
---	--	--

**Flood Control Project Maintenance  
Levee Inspections**

**Unit Cover Sheet**

**Spring 2013 Levee Inspection Results**

**Sacramento Maintenance Yard West Levee Yolo Bypass**

Waterway	Bank	Unit Miles
Unit No. 02 West Levee	Right	1.52

	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - February)
Unit Maintenance Rating (Fall Only)				
Date of Inspection	-			
DWR Inspector	John Williamson			
Accompanied By	Ted Skidgel Sacramento Maintenance Yard			

**Summer & Winter Inspections**

The Local Maintaining Agency (LMA) is responsible for summer and winter inspections. The LMA is required to submit a report regarding summer and winter inspections to the California Department of Water Resources (DWR).

DWR must be informed on the:

- a) completion of the inspection
- b) any changes other than the results of normal maintenance
- c) corrections to deficiencies noted in this report

If additional items are noted, further documentation of those items must also be submitted.

The LMA should submit this information to DWR using the LMA web application tool available at:

<http://cdec.water.ca.gov/lma.html>

If the LMA is unable to submit information on this webpage, please contact DWR for assistance.

*The LMA should submit the information and any associated documentation by September 30 for summer inspections and March 31 for winter inspections.*

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2013**

**Sacramento Maintenance Yard West Levee Yolo Bypass**

Waterway				Bank	Unit Miles	Inspection Start/End	Inspector			
Unit No. 02 West Levee				Right	1.52		John Williamson			
LMR No.	Levee Mile		Category	Item	* Location	** Rating	Action/Comment	GPS Latitude/Longitude		Issue No. Photo
	Start	End						Start	End	
1	0.00	1.52		Vegetation	LS Ma	M	V1 : Control annual grass and weeds on the levee slopes and easements.	38.718975 ° -121.664088 °	38.698650 ° -121.674116 °	1 Y
DWR ID: DWR_ST0011_02_s_2013_1										
2	0.00	1.52		Vegetation	WS Ma	M	V1 : Control annual grass and weeds on the levee slopes and easements.	38.718974 ° -121.664089 °	38.698650 ° -121.674116 °	2 Y
DWR ID: DWR_ST0011_02_s_2013_2										
3	0.01	0.01		Encroachments	WS En	M	DE : Debris	38.718893 ° -121.664095 °	38.718893 ° -121.664095 °	6 Y
DWR ID: DWR_ST0011_02_s_2013_6										
4	0.07	0.07		Encroachments	LS En	M	DE : Debris Inspector Comments: 36" concrete pipe at toe of levee	38.718087 ° -121.664462 °	38.718087 ° -121.664462 °	8 Y
DWR ID: DWR_ST0011_02_s_2012_8										
5	0.08	0.21		Encroachments	LS En	M	DT : Ditch	38.718005 ° -121.664496 °	38.716140 ° -121.665460 °	4 Y
DWR ID: DWR_ST0011_02_s_2012_4										
6	0.47	0.97		Encroachments	LS En	M	DT : Ditch	38.712813 ° -121.667349 °	38.706018 ° -121.670831 °	3 Y
DWR ID: DWR_ST0011_02_s_2012_3										
7	1.15	1.44		Encroachments	LS En	M	DT : Ditch	38.703681 ° -121.672090 °	38.699637 ° -121.674112 °	5 Y
DWR ID: DWR_ST0011_02_s_2012_5										

<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2013**

**Sacramento Maintenance Yard West Levee Yolo Bypass**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 West Levee	Right	1.52		John Williamson

Levee Mile Report Line	1
Start Levee Mile	0.00
End Levee Mile	1.52
Location	Land Side
Category	
Item	Vegetation
The vegetation is taller than 12". Spring 2013	
johngw_s_20130408_904.JPG	



Levee Mile Report Line	2
Start Levee Mile	0.00
End Levee Mile	1.52
Location	Water Side
Category	
Item	Vegetation
The vegetation is taller than 12". Spring 2013	
johngw_s_20130408_905.JPG	



Levee Mile Report Line	3
Start Levee Mile	0.01
End Levee Mile	0.01
Location	Water Side
Category	
Item	Encroachments
Pipe and debris at the toe of the waterside of the levee. Spring 2013	
johngw_s_20130408_906.JPG	



<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2013**

**Sacramento Maintenance Yard West Levee Yolo Bypass**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 West Levee	Right	1.52		John Williamson

Levee Mile Report Line	4
Start Levee Mile	0.07
End Levee Mile	0.07
Location	Land Side
Category	
Item	Encroachments
Photo taken spring 2012, concrete stand pipe laying at toe of levee.	
johngw_s_20130221_761.jpg	



Levee Mile Report Line	5
Start Levee Mile	0.08
End Levee Mile	0.21
Location	Land Side
Category	
Item	Encroachments
The agricultural ditch is at the toe of the levee. Photo fall 2012.	
johngw_s_20130221_758.jpg	



Levee Mile Report Line	6
Start Levee Mile	0.47
End Levee Mile	0.97
Location	Land Side
Category	
Item	Encroachments
The agricultural ditch is at the toe of the levee. Photo 2012.	
johngw_s_20130221_757.jpg	



<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2013**

**Sacramento Maintenance Yard West Levee Yolo Bypass**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 West Levee	Right	1.52		John Williamson

Levee Mile Report Line	7
Start Levee Mile	1.15
End Levee Mile	1.44
Location	Land Side
Category	
Item	Encroachments
<p>The agricultural ditch is at the toe of the levee. Photo fall 2012.</p>	
<p>johngw_s_20130221_759.jpg</p>	



<p><b>* Location</b></p> <p>LS : Land Side WS : Water Side CR : Crown</p>	<p><b>** Rating</b></p> <p>A : Acceptable M : Minimally Acceptable U : Unacceptable</p> <p>N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor &amp; Maintain</p>	<p><b>+ Issue Type</b></p> <p>Ma : Maintenance Deficiency Ob : Design &amp; System Obsolescence En : Enforcement</p>
---	--	--

**Flood Control Project Maintenance  
Levee Inspections**

**Unit Cover Sheet**

**Spring 2013 Levee Inspection Results**

**Sacramento Maintenance Yard West Levee Yolo Bypass**

Waterway	Bank	Unit Miles
Unit No. 03 West Levee	Right	1.48

	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - February)
Unit Maintenance Rating (Fall Only)				
Date of Inspection	-			
DWR Inspector	John Williamson			
Accompanied By	Ted Skidgel Sacramento Maintenance Yard			

**Summer & Winter Inspections**

The Local Maintaining Agency (LMA) is responsible for summer and winter inspections. The LMA is required to submit a report regarding summer and winter inspections to the California Department of Water Resources (DWR).

DWR must be informed on the:

- a) completion of the inspection
- b) any changes other than the results of normal maintenance
- c) corrections to deficiencies noted in this report

If additional items are noted, further documentation of those items must also be submitted.

The LMA should submit this information to DWR using the LMA web application tool available at:

<http://cdec.water.ca.gov/lma.html>

If the LMA is unable to submit information on this webpage, please contact DWR for assistance.

*The LMA should submit the information and any associated documentation by September 30 for summer inspections and March 31 for winter inspections.*

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2013**

**Sacramento Maintenance Yard West Levee Yolo Bypass**

Waterway				Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 West Levee				Right	1.48		John Williamson

  

LMIR No.	Levee Mile		Category	Item	* Location	+ Rating	Action/Comment	GPS Latitude/Longitude		Issue No. Photo
	Start	End						Start	End	
1	0.00	1.46		Vegetation	WS	M Ma	V1 : Control annual grass and weeds on the levee slopes and easements.	38.698595 ° -121.674112 °	38.677218 ° -121.672794 °	4 Y
DWR ID: DWR_ST0011_03_s_2013_4										
2	0.00	1.46		Vegetation	LS	M Ma	V1 : Control annual grass and weeds on the levee slopes and easements.	38.698595 ° -121.674112 °	38.677219 ° -121.672793 °	3 Y
DWR ID: DWR_ST0011_03_s_2013_3										

<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2013**

**Sacramento Maintenance Yard West Levee Yolo Bypass**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 West Levee	Right	1.48		John Williamson

Levee Mile Report Line	1
Start Levee Mile	0.00
End Levee Mile	1.46
Location	Water Side
Category	
Item	Vegetation
The vegetation is taller than 12". Spring 2013	
dpesaven_s_20130412_914.JPG	



Levee Mile Report Line	2
Start Levee Mile	0.00
End Levee Mile	1.46
Location	Land Side
Category	
Item	Vegetation
The vegetation is taller than 12". Spring 2013	
johngw_s_20130408_913.JPG	



<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

**Unit Cover Sheet**

**Spring 2013 Levee Inspection Results**

**Sacramento Maintenance Yard West Levee Yolo Bypass**

Waterway		Bank	Unit Miles
Unit No. 04 West Levee		Right	3.61

	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - February)
Unit Maintenance Rating (Fall Only)				
Date of Inspection	-			
DWR Inspector	John Williamson			
Accompanied By	Casey Lund Sacramento Maintenance Yard			

**Summer & Winter Inspections**

The Local Maintaining Agency (LMA) is responsible for summer and winter inspections. The LMA is required to submit a report regarding summer and winter inspections to the California Department of Water Resources (DWR).

DWR must be informed on the:

- a) completion of the inspection
- b) any changes other than the results of normal maintenance
- c) corrections to deficiencies noted in this report

If additional items are noted, further documentation of those items must also be submitted.

The LMA should submit this information to DWR using the LMA web application tool available at:

<http://cdec.water.ca.gov/lma.html>

If the LMA is unable to submit information on this webpage, please contact DWR for assistance.

*The LMA should submit the information and any associated documentation by September 30 for summer inspections and March 31 for winter inspections.*

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2013**

**Sacramento Maintenance Yard West Levee Yolo Bypass**

Waterway				Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 04 West Levee				Right	3.61		John Williamson

  

LMIR No.	Levee Mile		Category	Item	* Location	** Rating	Action/Comment	GPS Latitude/Longitude		Issue No. Photo
	Start	End						Start	End	
1	0.02	3.60		Vegetation	LS Ma	M	V1 : Control annual grass and weeds on the levee slopes and easements.	38.574359 ° -121.638747 °	38.523821 ° -121.631444 °	1 Y
DWR ID: DWR_ST0011_04_s_2013_1										
2	0.02	3.60		Vegetation	WS Ma	M	V1 : Control annual grass and weeds on the levee slopes and easements.	38.574359 ° -121.638747 °	38.523821 ° -121.631444 °	2 Y
DWR ID: DWR_ST0011_04_s_2013_2										
3	1.78	2.70		Encroachments	LS En	M	DT : Ditch	38.550387 ° -121.631257 °	38.536958 ° -121.631450 °	3 Y
DWR ID: DWR_ST0011_04_s_2012_3										
4	2.76	3.60		Encroachments	LS En	M	DT : Ditch	38.536100 ° -121.631425 °	38.523807 ° -121.631535 °	4 Y
DWR ID: DWR_ST0011_04_s_2012_4										

<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2013**

**Sacramento Maintenance Yard West Levee Yolo Bypass**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 04 West Levee	Right	3.61		John Williamson

Levee Mile Report Line	1
Start Levee Mile	0.02
End Levee Mile	3.60
Location	Land Side
Category	
Item	Vegetation
The vegetation is taller than 12". Spring 2013	
johngw_s_20130408_911.JPG	



Levee Mile Report Line	2
Start Levee Mile	0.02
End Levee Mile	3.60
Location	Water Side
Category	
Item	Vegetation
The vegetation is taller than 12". Spring 2013	
johngw_s_20130408_910.JPG	



Levee Mile Report Line	3
Start Levee Mile	1.78
End Levee Mile	2.70
Location	Land Side
Category	
Item	Encroachments
The argricultural ditch runs along the landside toe. Fall 2011	
johngw_s_20130221_765.jpg	



<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2013**

**Sacramento Maintenance Yard West Levee Yolo Bypass**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 04 West Levee	Right	3.61		John Williamson

Levee Mile Report Line	3
Start Levee Mile	1.78
End Levee Mile	2.70
Location	Land Side
Category	
Item	Encroachments
Photo taken spring 2012, agricultural ditch runs along toe of levee.	
johngw_s_20130221_766.jpg	



Levee Mile Report Line	4
Start Levee Mile	2.76
End Levee Mile	3.60
Location	Land Side
Category	
Item	Encroachments
The argricultural ditch runs along the toe of the landside. Fall 2011	
johngw_s_20130221_767.jpg	



Levee Mile Report Line	4
Start Levee Mile	2.76
End Levee Mile	3.60
Location	Land Side
Category	
Item	Encroachments
This view is looking to the north. Fall 2011	
johngw_s_20130221_768.jpg	



<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2013**

**Sacramento Maintenance Yard West Levee Yolo Bypass**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 04 West Levee	Right	3.61		John Williamson

Levee Mile Report Line	4
Start Levee Mile	2.76
End Levee Mile	3.60
Location	Land Side
Category	
Item	Encroachments
Photo taken spring 2012, agricultural ditch runs along toe of levee.	
johngw_s_20130221_769.jpg	



<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---