

**Flood Control Project Maintenance
Levee Inspections
LMA District Cover Sheet
Spring 2012 Levee Inspection Results**

Sacramento Maintenance Yard West Levee Yolo Bypass

	Spring (March - May)	Summer ** (June - August)	Fall (September - November)	Winter ** (December - February)
* Overall LMA Rating (Fall Only)				

** Non-receipt of Summer or Winter Inspection Reports may effect overall annual rating.

* SPRING INSPECTIONS: Overall maintenance ratings are not determined for the spring inspection results. Individual maintenance deficiencies are rated using the same criteria in the spring and in the fall.

FALL INSPECTIONS: The overall maintenance rating shown above is based on operation and maintenance deficiencies identified within the attached unit inspection reports.

Comments

**Flood Control Project Maintenance
Levee Inspections**

Unit Cover Sheet

Spring 2012 Levee Inspection Results

Sacramento Maintenance Yard West Levee Yolo Bypass

Waterway	Bank	Unit Miles
Unit No. 01 West Levee	Right	2.72

	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - February)
Unit Maintenance Rating (Fall Only)				
Date of Inspection	3/21/2012 - 3/21/2012			
DWR Inspector	John Williamson			
Accompanied By	Phil Carey Sacramento Maintenance			
	Ted Skidgel Sac maint			

Summer & Winter Inspections

The Local Maintaining Agency (LMA) is responsible for summer and winter inspections. The LMA is required to submit a report regarding summer and winter inspections to the California Department of Water Resources (DWR).

DWR must be informed on the:

- a) completion of the inspection
- b) any changes other than the results of normal maintenance
- c) corrections to deficiencies noted in this report

If additional items are noted, further documentation of those items must also be submitted.

The LMA should submit this information to DWR using the LMA web application tool available at:

<http://cdec.water.ca.gov/lma.html>

If the LMA is unable to submit information on this webpage, please contact DWR for assistance.

The LMA should submit the information and any associated documentation by September 30 for summer inspections and March 31 for winter inspections.

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2012

Sacramento Maintenance Yard West Levee Yolo Bypass

Waterway				Bank	Unit Miles	Inspection Start/End	Inspector				
Unit No. 01 West Levee				Right	2.72	03/21/2012 03/21/2012	John Williamson				
LMIR No.	Levee Mile		Category	Item	* Location	** Rating	Action/Comment		GPS Latitude/Longitude		Issue No. Photo
	Start	End					Start	End			
1			Earthen Levee	Operations & Maintenance Manuals	LS	A Ma			°	°	9
DWR ID: DWR_ST0011_01_s_2012_9											
2			Earthen Levee	Emergency Supplies & Equipment	LS	A Ma			°	°	10
DWR ID: DWR_ST0011_01_s_2012_10											
3			Earthen Levee	Flood Preparedness & Training	LS	A Ma			°	°	11
DWR ID: DWR_ST0011_01_s_2012_11											
4	0.01	2.72	Earthen Levee	Vegetation	LS	M Ma	V1 : Control annual grass and weeds on the levee slopes and easements.	38.758975 ° -121.667362 °	38.724237 ° -121.665165 °	7 Y	
DWR ID: DWR_ST0011_01_s_2012_7											
5	0.01	2.72	Earthen Levee	Vegetation	WS	M Ma	V1 : Control annual grass and weeds on the levee slopes and easements.	38.758978 ° -121.667350 °	38.724240 ° -121.665162 °	6 Y	
DWR ID: DWR_ST0011_01_s_2012_6											
6	0.36	0.43	Earthen Levee	Encroachments	LS	M En	AD : Agricultural Ditch	38.755535 ° -121.664127 °	38.754512 ° -121.663907 °	1 Y	
DWR ID: DWR_ST0011_01_s_2012_1											
7	0.93	1.63	Earthen Levee	Encroachments	LS	M En	AD : Agricultural Ditch	38.747888 ° -121.660202 °	38.737688 ° -121.660235 °	8 Y	
DWR ID: DWR_ST0011_01_s_2012_8											
8	2.53	2.68	Supplemental	USACE Erosion Survey	WS	M Ma	Inspector Comments: 2006 - Slow wave wash and general fluvial erosion of the toe area under river cobbles. Erosion is creating a scarp and cobble covered wave-cut bench. 2011: Site appears better than it looked in 2006, but still eroding. [2011 Site ID: YOL_2-6_R]	38.725505 ° -121.662041 °	38.724385 ° -121.664564 °	2 Y	
DWR ID: DWR_ST0011_01_s_2012_2											
9	2.63	2.70	Earthen Levee	Encroachments	LS	M En	AD : Agricultural Ditch	38.724800 ° -121.663710 °	38.724230 ° -121.664873 °	4 Y	
DWR ID: DWR_ST0011_01_s_2012_4											

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2012

Sacramento Maintenance Yard West Levee Yolo Bypass

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 West Levee	Right	2.72	03/21/2012 03/21/2012	John Williamson

Levee Mile Report Line	4
Start Levee Mile	0.01
End Levee Mile	2.72
Location	Land Side
Category	Earthen Levee
Item	Vegetation
Photo taken spring 2012, grasses taller than 12".	
johngw_s_20120326_578.jpg	



Levee Mile Report Line	5
Start Levee Mile	0.01
End Levee Mile	2.72
Location	Water Side
Category	Earthen Levee
Item	Vegetation
Photo taken spring 2012, grasses taller than 12".	
johngw_s_20120326_579.jpg	



Levee Mile Report Line	6
Start Levee Mile	0.36
End Levee Mile	0.43
Location	Land Side
Category	Earthen Levee
Item	Encroachments
The end of the agricultural ditch along the toe of the levee. Photo taken fall 2011.	
johngw_s_20120313_551.jpg	



* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2012

Sacramento Maintenance Yard West Levee Yolo Bypass

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 West Levee	Right	2.72	03/21/2012 03/21/2012	John Williamson

Levee Mile Report Line	6
Start Levee Mile	0.36
End Levee Mile	0.43
Location	Land Side
Category	Earthen Levee
Item	Encroachments

This photo shows the agricultural ditch as it turns towards the levee toe. Photo taken fall 2011.

johngw_s_20120313_552.jpg



Levee Mile Report Line	6
Start Levee Mile	0.36
End Levee Mile	0.43
Location	Land Side
Category	Earthen Levee
Item	Encroachments

Photo taken spring 2012, agricultural ditch runs along toe of levee.

johngw_s_20120326_580.jpg



Levee Mile Report Line	7
Start Levee Mile	0.93
End Levee Mile	1.63
Location	Land Side
Category	Earthen Levee
Item	Encroachments

A photo of the agricultural ditch along the toe. Photo taken fall 2011.

johngw_s_20120313_556.jpg



* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2012

Sacramento Maintenance Yard West Levee Yolo Bypass

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 West Levee	Right	2.72	03/21/2012 03/21/2012	John Williamson

Levee Mile Report Line	7
Start Levee Mile	0.93
End Levee Mile	1.63
Location	Land Side
Category	Earthen Levee
Item	Encroachments

This is another view of the agricultural ditch along the toe. Photo taken fall 2011.

johngw_s_20120313_557.jpg



Levee Mile Report Line	8
Start Levee Mile	2.53
End Levee Mile	2.68
Location	Water Side
Category	Supplemental
Item	USACE Erosion Survey

USACE 2011 Photo #1

johngw_s_20120313_553.jpg



Levee Mile Report Line	8
Start Levee Mile	2.53
End Levee Mile	2.68
Location	Water Side
Category	Supplemental
Item	USACE Erosion Survey

USACE 2011 Photo #2

johngw_s_20120313_554.jpg



<p>* Location</p> <p>LS : Land Side WS : Water Side CR : Crown</p>	<p>** Rating</p> <p>A : Acceptable M : Minimally Acceptable U : Unacceptable</p> <p>N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain</p>	<p>+ Issue Type</p> <p>Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement</p>
---	--	--

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2012

Sacramento Maintenance Yard West Levee Yolo Bypass

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 West Levee	Right	2.72	03/21/2012 03/21/2012	John Williamson

Levee Mile Report Line	9
Start Levee Mile	2.63
End Levee Mile	2.70
Location	Land Side
Category	Earthen Levee
Item	Encroachments
Agricultural ditch running along toe landside. 3-7-11	
johngw_s_20120313_555.jpg	



* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Unit Cover Sheet

Spring 2012 Levee Inspection Results

Sacramento Maintenance Yard West Levee Yolo Bypass

Waterway		Bank	Unit Miles
Unit No. 02 West Levee		Right	1.52

	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - February)
Unit Maintenance Rating (Fall Only)				
Date of Inspection	3/21/2012 - 3/21/2012			
DWR Inspector	John Williamson			
Accompanied By	Ted Skidgel Sac maint			

Summer & Winter Inspections

The Local Maintaining Agency (LMA) is responsible for summer and winter inspections. The LMA is required to submit a report regarding summer and winter inspections to the California Department of Water Resources (DWR).

DWR must be informed on the:

- a) completion of the inspection
- b) any changes other than the results of normal maintenance
- c) corrections to deficiencies noted in this report

If additional items are noted, further documentation of those items must also be submitted.

The LMA should submit this information to DWR using the LMA web application tool available at:

<http://cdec.water.ca.gov/lma.html>

If the LMA is unable to submit information on this webpage, please contact DWR for assistance.

The LMA should submit the information and any associated documentation by September 30 for summer inspections and March 31 for winter inspections.

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2012

Sacramento Maintenance Yard West Levee Yolo Bypass

Waterway		Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 West Levee		Right	1.52	03/21/2012 03/21/2012	John Williamson

LMIR No.	Levee Mile		Category	Item	Location	Rating	Action/Comment	GPS Latitude/Longitude		Issue No. Photo
	Start	End						Start	End	
1			Earthen Levee	Operations & Maintenance Manuals	LS	A Ma		°	°	10
DWR ID: DWR_ST0011_02_s_2012_10										
2			Earthen Levee	Emergency Supplies & Equipment	LS	A Ma		°	°	11
DWR ID: DWR_ST0011_02_s_2012_11										
3			Earthen Levee	Flood Preparedness & Training	LS	A Ma		°	°	12
DWR ID: DWR_ST0011_02_s_2012_12										
4	0.00	1.51	Earthen Levee	Vegetation	WS	M Ma	V1 : Control annual grass and weeds on the levee slopes and easements.	38.719040 ° -121.664097 °	38.698730 ° -121.674103 °	6 Y
DWR ID: DWR_ST0011_02_s_2012_6										
5	0.00	1.51	Earthen Levee	Vegetation	LS	M Ma	V1 : Control annual grass and weeds on the levee slopes and easements.	38.719035 ° -121.664102 °	38.698730 ° -121.674105 °	1 Y
DWR ID: DWR_ST0011_02_s_2012_1										
6	0.07	0.07	Earthen Levee	Encroachments	LS	M En	DE : Debris Inspector Comments: 36" concrete pipe at toe of levee	38.718087 ° -121.664462 °	38.718087 ° -121.664462 °	8 Y
DWR ID: DWR_ST0011_02_s_2012_8										
7	0.08	0.21	Earthen Levee	Encroachments	LS	M En	AD : Agricultural Ditch	38.718005 ° -121.664496 °	38.716140 ° -121.665460 °	4 Y
DWR ID: DWR_ST0011_02_s_2012_4										
8	0.47	0.97	Earthen Levee	Encroachments	LS	M En	AD : Agricultural Ditch	38.712813 ° -121.667349 °	38.706018 ° -121.670831 °	3 Y
DWR ID: DWR_ST0011_02_s_2012_3										
9	1.15	1.44	Earthen Levee	Encroachments	LS	M En	AD : Agricultural Ditch	38.703681 ° -121.672090 °	38.699637 ° -121.674112 °	5 Y
DWR ID: DWR_ST0011_02_s_2012_5										
10	1.43	1.43	Earthen Levee	Animal Control	LS	C Ma	A3 : No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.	38.699942 ° -121.674026 °	38.699942 ° -121.674026 °	2
DWR ID: DWR_ST0011_02_s_2012_2										

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2012

Sacramento Maintenance Yard West Levee Yolo Bypass

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 West Levee	Right	1.52	03/21/2012 03/21/2012	John Williamson

Levee Mile Report Line	4
Start Levee Mile	0.00
End Levee Mile	1.51
Location	Water Side
Category	Earthen Levee
Item	Vegetation
Photo taken spring 2012, grasses taller than 12".	
johngw_s_20120326_583.jpg	



Levee Mile Report Line	5
Start Levee Mile	0.00
End Levee Mile	1.51
Location	Land Side
Category	Earthen Levee
Item	Vegetation
Photo taken spring 2012, grasses taller than 12".	
johngw_s_20120326_582.jpg	



Levee Mile Report Line	6
Start Levee Mile	0.07
End Levee Mile	0.07
Location	Land Side
Category	Earthen Levee
Item	Encroachments
Photo taken spring 2012, concrete stand pipe laying at toe of levee.	
johngw_s_20120326_585.jpg	



* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2012

Sacramento Maintenance Yard West Levee Yolo Bypass

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 West Levee	Right	1.52	03/21/2012 03/21/2012	John Williamson

Levee Mile Report Line	7
Start Levee Mile	0.08
End Levee Mile	0.21
Location	Land Side
Category	Earthen Levee
Item	Encroachments
Agricultural ditch full of water runs along the toe of the levee. Photo taken fall 2011.	
johngw_s_20120313_560.jpg	



Levee Mile Report Line	8
Start Levee Mile	0.47
End Levee Mile	0.97
Location	Land Side
Category	Earthen Levee
Item	Encroachments
Agricultural ditch runs along the toe of the levee. Photo taken fall 2011.	
johngw_s_20120313_559.jpg	



Levee Mile Report Line	9
Start Levee Mile	1.15
End Levee Mile	1.44
Location	Land Side
Category	Earthen Levee
Item	Encroachments
Agricultural ditch runs along the toe of the levee. It varies in distance from toe from 1-10 feet away. Photo taken fall 2011.	
johngw_s_20120313_561.jpg	



* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Unit Cover Sheet

Spring 2012 Levee Inspection Results

Sacramento Maintenance Yard West Levee Yolo Bypass

Waterway		Bank	Unit Miles
Unit No. 03 West Levee		Right	1.48

	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - February)
Unit Maintenance Rating (Fall Only)				
Date of Inspection	3/21/2012 - 3/21/2012			
DWR Inspector	John Williamson			
Accompanied By	Ted Skidgel Sac maint			

Summer & Winter Inspections

The Local Maintaining Agency (LMA) is responsible for summer and winter inspections. The LMA is required to submit a report regarding summer and winter inspections to the California Department of Water Resources (DWR).

DWR must be informed on the:

- a) completion of the inspection
- b) any changes other than the results of normal maintenance
- c) corrections to deficiencies noted in this report

If additional items are noted, further documentation of those items must also be submitted.

The LMA should submit this information to DWR using the LMA web application tool available at:

<http://cdec.water.ca.gov/lma.html>

If the LMA is unable to submit information on this webpage, please contact DWR for assistance.

The LMA should submit the information and any associated documentation by September 30 for summer inspections and March 31 for winter inspections.

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2012

Sacramento Maintenance Yard West Levee Yolo Bypass

Waterway		Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 West Levee		Right	1.48	03/21/2012 03/21/2012	John Williamson

LMR No.	Levee Mile		Category	Item	* Location	** Rating	Action/Comment	GPS Latitude/Longitude		Issue No. Photo
	Start	End						Start	End	
1	0.02	1.41	Earthen Levee	Vegetation	WS	M Ma	V1 : Control annual grass and weeds on the levee slopes and easements. Inspector Comments: Cache weir is from LM .72-1.11 Total distance for grasses is 1.03	38.698380 ° -121.674078 °	38.678132 ° -121.672957 °	4 Y
DWR ID: DWR_ST0011_03_s_2012_4										
2	0.02	1.41	Earthen Levee	Vegetation	LS	M Ma	V1 : Control annual grass and weeds on the levee slopes and easements. Inspector Comments: Cache weir is from LM .72-1.11 Total distance for grasses is 1.03 miles.	38.698373 ° -121.674078 °	38.678147 ° -121.672965 °	3 Y
DWR ID: DWR_ST0011_03_s_2012_3										

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2012

Sacramento Maintenance Yard West Levee Yolo Bypass

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 West Levee	Right	1.48	03/21/2012 03/21/2012	John Williamson

Levee Mile Report Line	1
Start Levee Mile	0.02
End Levee Mile	1.41
Location	Water Side
Category	Earthen Levee
Item	Vegetation
Photo taken spring 2012, grasses taller than 12".	
johngw_s_20120326_588.jpg	



Levee Mile Report Line	2
Start Levee Mile	0.02
End Levee Mile	1.41
Location	Land Side
Category	Earthen Levee
Item	Vegetation
Photo taken spring 2012, grasses taller than 12".	
johngw_s_20120326_587.jpg	



* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Unit Cover Sheet

Spring 2012 Levee Inspection Results

Sacramento Maintenance Yard West Levee Yolo Bypass

Waterway		Bank	Unit Miles
Unit No. 04 West Levee		Right	3.61

	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - February)
Unit Maintenance Rating (Fall Only)				
Date of Inspection	3/22/2012 - 3/22/2012			
DWR Inspector	John Williamson			
Accompanied By	Casey Lund Sac maint.			

Summer & Winter Inspections

The Local Maintaining Agency (LMA) is responsible for summer and winter inspections. The LMA is required to submit a report regarding summer and winter inspections to the California Department of Water Resources (DWR).

DWR must be informed on the:

- a) completion of the inspection
- b) any changes other than the results of normal maintenance
- c) corrections to deficiencies noted in this report

If additional items are noted, further documentation of those items must also be submitted.

The LMA should submit this information to DWR using the LMA web application tool available at:

<http://cdec.water.ca.gov/lma.html>

If the LMA is unable to submit information on this webpage, please contact DWR for assistance.

The LMA should submit the information and any associated documentation by September 30 for summer inspections and March 31 for winter inspections.

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2012

Sacramento Maintenance Yard West Levee Yolo Bypass

Waterway				Bank	Unit Miles	Inspection Start/End	Inspector				
Unit No. 04 West Levee				Right	3.61	03/22/2012 03/22/2012	John Williamson				
LMR No.	Levee Mile		Category	Item	* Location	+ Rating	Action/Comment		GPS Latitude/Longitude		Issue No. Photo
	Start	End					Start	End			
1			Earthen Levee	Operations & Maintenance Manuals	LS	A Ma			°	°	7
DWR ID: DWR_ST0011_04_s_2012_7											
2			Earthen Levee	Emergency Supplies & Equipment	LS	A Ma			°	°	8
DWR ID: DWR_ST0011_04_s_2012_8											
3			Earthen Levee	Flood Preparedness & Training	LS	A Ma			°	°	9
DWR ID: DWR_ST0011_04_s_2012_9											
4	0.93	2.83	Earthen Levee	Vegetation	LS	M Ma	V1 : Control annual grass and weeds on the levee slopes and easements.	38.561212 ° -121.638197 °	38.535097 ° -121.631337 °	5	Y
DWR ID: DWR_ST0011_04_s_2012_5											
5	0.93	2.83	Earthen Levee	Vegetation	WS	M Ma	V1 : Control annual grass and weeds on the levee slopes and easements.	38.561208 ° -121.638198 °	38.535098 ° -121.631335 °	6	Y
DWR ID: DWR_ST0011_04_s_2012_6											
6	1.78	2.70	Earthen Levee	Encroachments	LS	M En	AD : Agricultural Ditch	38.550387 ° -121.631257 °	38.536958 ° -121.631450 °	3	Y
DWR ID: DWR_ST0011_04_s_2012_3											
7	2.76	3.60	Earthen Levee	Encroachments	LS	M En	AD : Agricultural Ditch	38.536100 ° -121.631425 °	38.523807 ° -121.631535 °	4	Y
DWR ID: DWR_ST0011_04_s_2012_4											

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2012

Sacramento Maintenance Yard West Levee Yolo Bypass

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 04 West Levee	Right	3.61	03/22/2012 03/22/2012	John Williamson

Levee Mile Report Line	4
Start Levee Mile	0.93
End Levee Mile	2.83
Location	Land Side
Category	Earthen Levee
Item	Vegetation
Photo taken spring 2012, grasses are taller than 12".	
johngw_s_20120326_606.jpg	



Levee Mile Report Line	5
Start Levee Mile	0.93
End Levee Mile	2.83
Location	Water Side
Category	Earthen Levee
Item	Vegetation
Photo taken spring 2012, grasses are taller than 12".	
johngw_s_20120326_607.jpg	



Levee Mile Report Line	6
Start Levee Mile	1.78
End Levee Mile	2.70
Location	Land Side
Category	Earthen Levee
Item	Encroachments
The argricultural ditch runs along the landside toe. Fall 2011	
johngw_s_20120313_564.jpg	



* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2012

Sacramento Maintenance Yard West Levee Yolo Bypass

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 04 West Levee	Right	3.61	03/22/2012 03/22/2012	John Williamson

Levee Mile Report Line	6
Start Levee Mile	1.78
End Levee Mile	2.70
Location	Land Side
Category	Earthen Levee
Item	Encroachments
Photo taken spring 2012, agricultural ditch runs along toe of levee.	
johngw_s_20120326_608.jpg	



Levee Mile Report Line	7
Start Levee Mile	2.76
End Levee Mile	3.60
Location	Land Side
Category	Earthen Levee
Item	Encroachments
The argricultural ditch runs along the toe of the landside. Fall 2011	
johngw_s_20120313_565.jpg	



Levee Mile Report Line	7
Start Levee Mile	2.76
End Levee Mile	3.60
Location	Land Side
Category	Earthen Levee
Item	Encroachments
This view is looking to the north. Fall 2011	
johngw_s_20120313_566.jpg	



* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2012

Sacramento Maintenance Yard West Levee Yolo Bypass

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 04 West Levee	Right	3.61	03/22/2012 03/22/2012	John Williamson

Levee Mile Report Line	7
Start Levee Mile	2.76
End Levee Mile	3.60
Location	Land Side
Category	Earthen Levee
Item	Encroachments
Photo taken spring 2012, agricultural ditch runs along toe of levee.	
johngw_s_20120326_609.jpg	



* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---