



2008 SAN JOAQUIN EROSION SURVEYS AERIAL ATLAS




Department of Water Resources
Division of Flood Management
Flood Project Integrity and Inspection Branch
May 2009





Index of San Joaquin Erosion Surveys Atlas





Department of Water Resources
 Division of Flood Management
 Flood Project Integrity and Inspection Branch

Bear Creek

- Erosion Site
- PL84-99 Rehabilitation Assistance Program Site




Plate 1


Aerial photograph taken in 2005, courtesy of the California Spatial Information Library.



Department of Water Resources
 Division of Flood Management
 Flood Project Integrity and Inspection Branch

Bear Creek

- Erosion Site
- PL84-99 Rehabilitation Assistance Program Site



Aerial photograph taken in 2005, courtesy of the California Spatial Information Library.


Plate 2



Department of Water Resources
 Division of Flood Management
 Flood Project Integrity and Inspection Branch

Bear Creek

- Erosion Site
- PL84-99 Rehabilitation Assistance Program Site



Aerial photograph taken in 2005, courtesy of the California Spatial Information Library.



Department of Water Resources
Division of Flood Management
Flood Project Integrity and Inspection Branch

Mormon Slough

- Erosion Site
- PL84-99 Rehabilitation Assistance Program Site

Aerial photograph taken in 2005, courtesy of the California Spatial Information Library.

Plate 4



Department of Water Resources
 Division of Flood Management
 Flood Project Integrity and Inspection Branch

Mormon Slough

- Erosion Site
- PL84-99 Rehabilitation Assistance Program Site




Plate 5


Aerial photograph taken in 2005, courtesy of the California Spatial Information Library.



Department of Water Resources
 Division of Flood Management
 Flood Project Integrity and Inspection Branch

San Joaquin River

- Erosion Site
- PL84-99 Rehabilitation Assistance Program Site




Aerial photograph taken in 2005, courtesy of the California Spatial Information Library.



Department of Water Resources
 Division of Flood Management
 Flood Project Integrity and Inspection Branch

San Joaquin River

- Erosion Site
- PL84-99 Rehabilitation Assistance Program Site



Aerial photograph taken in 2005, courtesy of the California Spatial Information Library.



Department of Water Resources
 Division of Flood Management
 Flood Project Integrity and Inspection Branch

San Joaquin River

- Erosion Site
- PL49-99 Rehabilitation Assistance Program Site





Plate 8

Aerial photograph taken in 2005, courtesy of the California Spatial Information Library.




Lloyd Thayer



Department of Water Resources
 Division of Flood Management
 Flood Project Integrity and Inspection Branch

French Camp Slough

- Erosion Site
- PL84-99 Rehabilitation Assistance Program Site



Aerial photograph taken in 2005, courtesy of the California Spatial Information Library.



Department of Water Resources
 Division of Flood Management
 Flood Project Integrity and Inspection Branch

San Joaquin River

- Erosion Site
- PL84-99 Rehabilitation Assistance Program Site


Aerial photograph taken in 2005, courtesy of the California Spatial Information Library.




Department of Water Resources
 Division of Flood Management
 Flood Project Integrity and Inspection Branch

San Joaquin River

- Erosion Site
- PL84-99 Rehabilitation Assistance Program Site




Aerial photograph taken in 2005, courtesy of the California Spatial Information Library.



Department of Water Resources
Division of Flood Management
Flood Project Integrity and Inspection Branch

San Joaquin River

- Erosion Site
- PL84-99 Rehabilitation Assistance Program Site




Aerial photograph taken in 2005, courtesy of the California Spatial Information Library.



Department of Water Resources
 Division of Flood Management
 Flood Project Integrity and Inspection Branch

San Joaquin River

- Erosion Site
- PL84-99 Rehabilitation Assistance Program Site




Aerial photograph taken in 2005, courtesy of the California Spatial Information Library.



Department of Water Resources
 Division of Flood Management
 Flood Project Integrity and Inspection Branch

San Joaquin River

- Erosion Site
- PL84-99 Rehabilitation Assistance Program Site




Aerial photograph taken in 2005, courtesy of the California Spatial Information Library.



Department of Water Resources
 Division of Flood Management
 Flood Project Integrity and Inspection Branch

San Joaquin River

- Erosion Site
- PL84-99 Rehabilitation Assistance Program Site




Aerial photograph taken in 2005, courtesy of the California Spatial Information Library.



Department of Water Resources
 Division of Flood Management
 Flood Project Integrity and Inspection Branch

San Joaquin River

- Erosion Site
- PL84-99 Rehabilitation Assistance Program Site



Aerial photograph taken in 2005, courtesy of the California Spatial Information Library.


Plate 16



Department of Water Resources
Division of Flood Management
Flood Project Integrity and Inspection Branch

San Joaquin River

-  Erosion Site
-  PL84-99 Rehabilitation Assistance Program Site



Aerial photograph taken in 2005, courtesy of the California Spatial Information Library.


Plate 17



Department of Water Resources
 Division of Flood Management
 Flood Project Integrity and Inspection Branch

San Joaquin River

- Erosion Site
- PL84-99 Rehabilitation Assistance Program Site



Aerial photograph taken in 2005, courtesy of the California Spatial Information Library.


Plate 18



Department of Water Resources
 Division of Flood Management
 Flood Project Integrity and Inspection Branch

San Joaquin River

- Erosion Site
- PL84-99 Rehabilitation Assistance Program Site




Aerial photograph taken in 2005, courtesy of the California Spatial Information Library.



Department of Water Resources
 Division of Flood Management
 Flood Project Integrity and Inspection Branch

San Joaquin River

- Erosion Site
- PL84-99 Rehabilitation Assistance Program Site




Aerial photograph taken in 2005, courtesy of the California Spatial Information Library.



Department of Water Resources
 Division of Flood Management
 Flood Project Integrity and Inspection Branch

San Joaquin River

- Erosion Site
- PL84-99 Rehabilitation Assistance Program Site





Department of Water Resources
 Division of Flood Management
 Flood Project Integrity and Inspection Branch

San Joaquin River

- Erosion Site
- PL84-99 Rehabilitation Assistance Program Site





Plate 22

Aerial photograph taken in 2005, courtesy of the California Spatial Information Library.



Department of Water Resources
Division of Flood Management
Flood Project Integrity and Inspection Branch

Old River

Aerial photograph taken in 2005, courtesy of the California Spatial Information Library.

Plate 23



Department of Water Resources
 Division of Flood Management
 Flood Project Integrity and Inspection Branch

Old River

- Erosion Site
- PL84-99 Rehabilitation Assistance Program Site




Plate 24


Aerial photograph taken in 2005, courtesy of the California Spatial Information Library.



Department of Water Resources
 Division of Flood Management
 Flood Project Integrity and Inspection Branch

Old River

- Erosion Site
- PL84-99 Rehabilitation Assistance Program Site



Aerial photograph taken in 2005, courtesy of the California Spatial Information Library.



Department of Water Resources
 Division of Flood Management
 Flood Project Integrity and Inspection Branch

Old River

- Erosion Site
- PL84-99 Rehabilitation Assistance Program Site




Plate 26


Aerial photograph taken in 2005, courtesy of the California Spatial Information Library.



Department of Water Resources
 Division of Flood Management
 Flood Project Integrity and Inspection Branch

Old River

- Erosion Site
- PL84-99 Rehabilitation Assistance Program Site




Aerial photograph taken in 2005, courtesy of the California Spatial Information Library.



Department of Water Resources
 Division of Flood Management
 Flood Project Integrity and Inspection Branch

Old River

- Erosion Site
- PL84-99 Rehabilitation Assistance Program Site




Aerial photograph taken in 2005, courtesy of the California Spatial Information Library.



Department of Water Resources
Division of Flood Management
Flood Project Integrity and Inspection Branch

Old River

-  Erosion Site
-  PL84-99 Rehabilitation Assistance Program Site



Aerial photograph taken in 2005, courtesy of the California Spatial Information Library.

Plate 29



Department of Water Resources
Division of Flood Management
Flood Project Integrity and Inspection Branch

San Joaquin River

- Erosion Site
- PL84-99 Rehabilitation Assistance Program Site




Plate 30

Aerial photograph taken in 2005, courtesy of the California Spatial Information Library.



Department of Water Resources
Division of Flood Management
Flood Project Integrity and Inspection Branch

Paradise Cut

- Erosion Site
- PL84-99 Rehabilitation Assistance Program Site

Aerial photograph taken in 2005, courtesy of the California Spatial Information Library.

Plate 31



Department of Water Resources
Division of Flood Management
Flood Project Integrity and Inspection Branch

Paradise Cut

- Erosion Site
- PL84-99 Rehabilitation Assistance Program Site

0 250 500 1,000 Feet

Aerial photograph taken in 2005, courtesy of the California Spatial Information Library.


Plate 32



Department of Water Resources
Division of Flood Management
Flood Project Integrity and Inspection Branch

San Joaquin River

-  Erosion Site
-  PL84-99 Rehabilitation Assistance Program Site



Aerial photograph taken in 2005, courtesy of the California Spatial Information Library.

Plate 33



Department of Water Resources
Division of Flood Management
Flood Project Integrity and Inspection Branch

San Joaquin River

-  Erosion Site
-  PL84-99 Rehabilitation Assistance Program Site

0 250 500 1,000 Feet

Aerial photograph taken in 2005, courtesy of the California Spatial Information Library.


Plate 34




Department of Water Resources
 Division of Flood Management
 Flood Project Integrity and Inspection Branch

San Joaquin River

- Erosion Site
- PL84-99 Rehabilitation Assistance Program Site



Aerial photograph taken in 2005, courtesy of the California Spatial Information Library.



Department of Water Resources
Division of Flood Management
Flood Project Integrity and Inspection Branch

San Joaquin River

- Erosion Site
- PL84-99 Rehabilitation Assistance Program Site

0 250 500 1,000 Feet

Aerial photograph taken in 2005, courtesy of the California Spatial Information Library.

Plate 36



Department of Water Resources
Division of Flood Management
Flood Project Integrity and Inspection Branch

San Joaquin River

- Erosion Site
- PL84-99 Rehabilitation Assistance Program Site





Plate 37


Aerial photograph taken in 2005, courtesy of the California Spatial Information Library.



Department of Water Resources
Division of Flood Management
Flood Project Integrity and Inspection Branch

San Joaquin River

- Erosion Site
- PL84-99 Rehabilitation Assistance Program Site



Aerial photograph taken in 2005, courtesy of the California Spatial Information Library.


Plate 38



Department of Water Resources
 Division of Flood Management
 Flood Project Integrity and Inspection Branch

San Joaquin River

- Erosion Site
- PL84-99 Rehabilitation Assistance Program Site




Aerial photograph taken in 2005, courtesy of the California Spatial Information Library.



Department of Water Resources
Division of Flood Management
Flood Project Integrity and Inspection Branch

San Joaquin River

-  Erosion Site
-  PL84-99 Rehabilitation Assistance Program Site



Aerial photograph taken in 2005, courtesy of the California Spatial Information Library.

Plate 40



Department of Water Resources
 Division of Flood Management
 Flood Project Integrity and Inspection Branch

San Joaquin River

- Erosion Site
- PL84-99 Rehabilitation Assistance Program Site




Plate 41


Aerial photograph taken in 2005, courtesy of the California Spatial Information Library.



Department of Water Resources
 Division of Flood Management
 Flood Project Integrity and Inspection Branch

Mariposa Bypass

- Erosion Site
- PL84-99 Rehabilitation Assistance Program Site




Aerial photograph taken in 2005, courtesy of the California Spatial Information Library.



Department of Water Resources
Division of Flood Management
Flood Project Integrity and Inspection Branch


Owens Creek

- Erosion Site
- PL84-99 Rehabilitation Assistance Program Site



Aerial photograph taken in 2005, courtesy of the California Spatial Information Library.


Plate 43



Department of Water Resources
 Division of Flood Management
 Flood Project Integrity and Inspection Branch

Ash Slough

- Erosion Site
- PL84-99 Rehabilitation Assistance Program Site




Aerial photograph taken in 2005, courtesy of the California Spatial Information Library.



NA 0011
Madera County

1
LM 235

Road 8




Department of Water Resources
Division of Flood Management
Flood Project Integrity and Inspection Branch

Ash Slough

- Erosion Site
- PL84-99 Rehabilitation Assistance Program Site

Aerial photograph taken in 2005, courtesy of the California Spatial Information Library.



NA 0011
Madera County

3
LM 5.37


Road 15



Department of Water Resources
Division of Flood Management
Flood Project Integrity and Inspection Branch

Fresno River

-  Erosion Site
-  PL84-99 Rehabilitation Assistance Program Site



Aerial photograph taken in 2005, courtesy of the California Spatial Information Library.


Plate 46



Department of Water Resources
 Division of Flood Management
 Flood Project Integrity and Inspection Branch

Owens Creek Diversion

- Erosion Site
- PL84-99 Rehabilitation Assistance Program Site



Aerial photograph taken in 2005, courtesy of the California Spatial Information Library.


Plate 47



Department of Water Resources
Division of Flood Management
Flood Project Integrity and Inspection Branch

San Joaquin River

- Erosion Site
- PL84-99 Rehabilitation Assistance Program Site



Aerial photograph taken in 2005, courtesy of the California Spatial Information Library.

Plate 48