

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2019

Plumas County

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 North Fork Feather River	Left	1.89	10/21/2019 10/21/2019	Sterling York

LM Start		Rating **	A	Issue No.	1
LM End		Issue Type +	Ma	Location *	N/A
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Operations & Maintenance Manuals			o	o
				o	o
DWR ID	DWR_NA0015_01_s_2013_1				
Comment Code					
Inspector Comment					
The LMA has O&M manuals in their office.					

No Photos

LM Start		Rating **	A	Issue No.	2
LM End		Issue Type +	Ma	Location *	N/A
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Emergency Supplies & Equipment			o	o
				o	o
DWR ID	DWR_NA0015_01_s_2013_2				
Comment Code					
Inspector Comment					
The LMA has flood fight supplies and equipment at their yard.					

No Photos

LM Start		Rating **	A	Issue No.	3
LM End		Issue Type +	Ma	Location *	N/A
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Flood Preparedness & Training			o	o
				o	o
DWR ID	DWR_NA0015_01_s_2013_3				
Comment Code					
Inspector Comment					
The LMA has completed flood flight training, Winter 2019.					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2019

Plumas County

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 North Fork Feather River	Left	1.89	10/21/2019 10/21/2019	Sterling York

LM Start	0.00	Rating **	A	Issue No.	5
LM End	1.86	Issue Type +	Ma	Location *	LS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Vegetation		40.273190°	40.296893°	
			-121.244775°	-121.257239°	
DWR ID	DWR_NA0015_01_f_2019_5				
Comment Code					
V1 : Control annual grass and weeds on the levee slopes and easements.					
Inspector Comment					
The annual vegetation is well maintained, Fall 2019.					

Photo 1 of 1 : FA_2019_NA0015_337_5_20191029_00007.jpg



View looking upstream landside of the well maintained annual vegetation, Fall 2019.

LM Start	0.00	Rating **	A	Issue No.	6
LM End	1.86	Issue Type +	Ma	Location *	WS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Vegetation		40.273190°	40.296896°	
			-121.244775°	-121.257236°	
DWR ID	DWR_NA0015_01_f_2019_6				
Comment Code					
V1 : Control annual grass and weeds on the levee slopes and easements.					
Inspector Comment					
The annual vegetation is well maintained, Fall 2019.					

Photo 1 of 1 : FA_2019_NA0015_337_6_20191029_00008.jpg



View looking upstream waterside of the well maintained annual vegetation, Fall 2019.

LM Start	0.54	Rating **	A/W	Issue No.	8
LM End	0.54	Issue Type +	Ma	Location *	WS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Slope Stability		40.279775°	40.279775°	
			-121.249648°	-121.249648°	
DWR ID	DWR_NA0015_01_f_2018_8				
Comment Code					
S3 : Repair the levee slope damaged by vehicle traffic and prevent access where possible.					
Inspector Comment					
The vehicle erosion on the waterside slope is not a threat to the levee slope but should be monitored, Fall 2019.					

Photo 1 of 1 : FA_2019_NA0015_337_8_20190904_00001.jpg



View of vehicle erosion on the waterside slope, Spring 2019

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2019

Plumas County

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 North Fork Feather River	Left	1.89	10/21/2019 10/21/2019	Sterling York

LM Start	1.17	Rating **	C	Issue No.	16
LM End	1.17	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			40.287722°	40.287722°
				-121.253510°	-121.253510°
DWR ID	DWR_NA0015_01_s_2017_16				
Comment Code					
TR : Tree or limb					
Inspector Comment					
The tree has been removed from the landside slope and toe, Fall 2019.					

No Photos

LM Start	1.24	Rating **	C	Issue No.	18
LM End	1.88	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			40.288744°	40.297068°
				-121.254147°	-121.257120°
DWR ID	DWR_NA0015_01_s_2018_18				
Comment Code					
V2 : Remove the wild growth other than native grasses from the levee slopes.					
Inspector Comment					
The small pine trees and vegetation have been mowed on the landside slope, Fall 2019.					

No Photos

LM Start	1.79	Rating **	C	Issue No.	19
LM End	1.88	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			40.295921°	40.297068°
				-121.257519°	-121.257120°
DWR ID	DWR_NA0015_01_s_2018_19				
Comment Code					
V2 : Remove the wild growth other than native grasses from the levee slopes.					
Inspector Comment					
The small pine trees and vegetation have been mowed on the waterside slope, Fall 2019.					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	--	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2019

Plumas County

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 North Fork Feather River	Right	1.36	10/21/2019 10/21/2019	Sterling York

LM Start	0.55	Rating **	M	Issue No.	4
LM End	0.55	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Slope Stability			40.281950 °	40.281950 °
				-121.253710 °	-121.253710 °
DWR ID	DWR_NA0015_02_s_2012_4				
Comment Code					
S3 : Repair the levee slope damaged by vehicle traffic and prevent access where possible.					
Inspector Comment					
There is no sign of slope instability but should be monitored for the next year. The access has been blocked, Fall 2019.					

Photo 1 of 1 : FA_2019_NA0015_338_4_20191029_00010.jpg



View of the undesignated vehicle access along the landside slope, there is no sign of slope instability but should be monitored for the next year, Fall 2019.

LM Start	0.55	Rating **	A/W	Issue No.	5
LM End	0.55	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Slope Stability			40.281950 °	40.281950 °
				-121.253710 °	-121.253710 °
DWR ID	DWR_NA0015_02_s_2012_5				
Comment Code					
S3 : Repair the levee slope damaged by vehicle traffic and prevent access where possible.					
Inspector Comment					
There is no sign of slope instability but should be monitored for the next year. The access has been blocked, Fall 2019.					

Photo 1 of 1 : FA_2019_NA0015_338_5_20191029_00009.jpg



View of the undesignated vehicle access along the waterside slope, there is no sign of slope instability but should be monitored for the next year, Fall 2019.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2019

Plumas County

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 North Fork Feather River	Right	1.36	10/21/2019 10/21/2019	Sterling York

LM Start	0.98	Rating **	C	Issue No.	2
LM End	1.32	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			40.276392°	40.272219°
				-121.250420°	-121.247152°
DWR ID	DWR_NA0015_02_f_2017_2				
Comment Code					
V2 : Remove the wild growth other than native grasses from the levee slopes.					
Inspector Comment					
Remove the small pine trees and vegetation from the landside slope.					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---