

**Flood Control Project Maintenance
Levee Inspections
2020 Channel Summary Report
Overall Unit and Item Ratings**

Adin Community Service District

Ash Creek

| Overall Unit Rating | Rated Item | Item Rating |
|---------------------|---|-------------|
| A | Vegetation & Obstructions | A |
| | Shoaling / Sedimentation | A |
| | Erosion / Bank Caving | A |
| | Revetments & Other Structural Appurtenances | A |
| | Encroachments | A |

Dry Creek

| Overall Unit Rating | Rated Item | Item Rating |
|---------------------|---|-------------|
| A | Vegetation & Obstructions | M |
| | Shoaling / Sedimentation | A |
| | Erosion / Bank Caving | A |
| | Revetments & Other Structural Appurtenances | N |
| | Encroachments | A |

Flood Control Project Maintenance

Unit Cover Sheet

2020 Channel Inspection Results

Adin Community Service District

| |
|-----------|
| Channel |
| Ash Creek |

| | |
|--------------------|--|
| Channel Rating | A |
| Date of Inspection | 6/25/2020 |
| DWR Inspector | Makar Sokol |
| Accompanied By | Mike Williams Adin Community Service District |

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2020

Adin Community Service District

| Channel | Channel Length | Inspection Start/End | Inspector |
|-----------|----------------|--------------------------|-------------|
| Ash Creek | 1.00 | 06/25/2020 06/25/2020 | Makar Sokol |

| Check Point / View | | | |
|-------------------------|-------------------------------------|------------|---------------|
| Main Street / Up | | | |
| Rating ** | A | Issue No. | 1 |
| Issue Type + | Ma | Location * | 41.197770 ° |
| Category | Rivers, Channels & Designated Flood | | -120.944100 ° |
| Item | Vegetation & Obstructions | | |
| DWR ID | DWR_NA0030_1_c_2012_1 | | |
| Action/Comments | | | |
| | | | |

Photo 1 of 1 : CH_2020_NA0030_1_1_20200701_00015.jpg



View of the Ash Creek upstream of the Highway 299 bridge.

| Rating ** | A | Issue No. | 7 |
|--|-------------------------------------|------------|---------------|
| Issue Type + | Ma | Location * | 41.197770 ° |
| Category | Rivers, Channels & Designated Flood | | -120.944100 ° |
| Item | Shoaling / Sedimentation | | |
| DWR ID | DWR_NA0030_1_c_2012_7 | | |
| Action/Comments | | | |
| Inspector Comments: No shoaling or sedimentation observed during the inspection. | | | |

No Photos

| Rating ** | A | Issue No. | 3 |
|-----------------|-------------------------------------|------------|---------------|
| Issue Type + | Ma | Location * | 41.197770 ° |
| Category | Rivers, Channels & Designated Flood | | -120.944100 ° |
| Item | Erosion / Bank Caving | | |
| DWR ID | DWR_NA0030_1_c_2012_3 | | |
| Action/Comments | | | |
| | | | |

No Photos

| | | |
|--|---|---|
| * Location LS : Land Side WS : Water Side CR : Crown | ** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain | + Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement |
|--|---|---|

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2020

Adin Community Service District

| Channel | Channel Length | Inspection Start/End | Inspector |
|-----------|----------------|--------------------------|-------------|
| Ash Creek | 1.00 | 06/25/2020 06/25/2020 | Makar Sokol |

| Check Point / View | | | |
|--------------------------------|-------------------------------------|--------------------|---------------|
| Main Street / Up (cont) | | | |
| Rating ** | N | Issue No. 4 | GPS Lat/Long |
| Issue Type + | Ma | Location * | 41.197770 ° |
| Category | Rivers, Channels & Designated Flood | | -120.944100 ° |
| Item | Revetments | | |
| DWR ID | DWR_NA0030_1_c_2012_4 | | |
| Action/Comments | | | |
| | | | |

No Photos

| Rating ** | A | Issue No. 5 | GPS Lat/Long |
|-----------------|-------------------------------------|--------------------|---------------|
| Issue Type + | Ma | Location * | 41.197770 ° |
| Category | Rivers, Channels & Designated Flood | | -120.944100 ° |
| Item | Encroachments | | |
| DWR ID | DWR_NA0030_1_c_2012_5 | | |
| Action/Comments | | | |
| | | | |

No Photos

| Check Point / View | | | |
|---------------------------|-------------------------------------|--------------------|---------------|
| Main Street / Down | | | |
| Rating ** | A | Issue No. 6 | GPS Lat/Long |
| Issue Type + | Ma | Location * | 41.197770 ° |
| Category | Rivers, Channels & Designated Flood | | -120.944100 ° |
| Item | Vegetation & Obstructions | | |
| DWR ID | DWR_NA0030_1_c_2012_6 | | |
| Action/Comments | | | |
| | | | |

Photo 1 of 1 : CH_2020_NA0030_1_6_20200701_00016.jpg



Downstream view of Ash Creek from the Highway 299 bridge.

| | | |
|--|---|---|
| * Location LS : Land Side WS : Water Side CR : Crown | ** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain | + Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement |
|--|---|---|

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2020

Adin Community Service District

| Channel | Channel Length | Inspection Start/End | Inspector |
|-----------|----------------|--------------------------|-------------|
| Ash Creek | 1.00 | 06/25/2020 06/25/2020 | Makar Sokol |

| Check Point / View | | | |
|--|-------------------------------------|--------------------|---------------|
| Main Street / Down (cont) | | | |
| Rating ** | A | Issue No. 2 | GPS Lat/Long |
| Issue Type + | Ma | Location * | 41.197770 ° |
| Category | Rivers, Channels & Designated Flood | | -120.944100 ° |
| Item | Shoaling / Sedimentation | | |
| DWR ID | DWR_NA0030_1_c_2012_2 | | |
| Action/Comments | | | |
| Inspector Comments: No shoaling or sedimentation observed during the inspection. | | | |

No Photos

| | | | |
|-----------------|-------------------------------------|--------------------|---------------|
| Rating ** | A | Issue No. 8 | GPS Lat/Long |
| Issue Type + | Ma | Location * | 41.197770 ° |
| Category | Rivers, Channels & Designated Flood | | -120.944100 ° |
| Item | Erosion / Bank Caving | | |
| DWR ID | DWR_NA0030_1_c_2012_8 | | |
| Action/Comments | | | |

No Photos

| | | | |
|-----------------|-------------------------------------|--------------------|---------------|
| Rating ** | N | Issue No. 9 | GPS Lat/Long |
| Issue Type + | Ma | Location * | 41.197770 ° |
| Category | Rivers, Channels & Designated Flood | | -120.944100 ° |
| Item | Revetments | | |
| DWR ID | DWR_NA0030_1_c_2012_9 | | |
| Action/Comments | | | |

No Photos

| | | |
|--|---|---|
| * Location LS : Land Side WS : Water Side CR : Crown | ** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain | + Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement |
|--|---|---|

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2020

Adin Community Service District

| Channel | Channel Length | Inspection Start/End | Inspector |
|-----------|----------------|--------------------------|-------------|
| Ash Creek | 1.00 | 06/25/2020 06/25/2020 | Makar Sokol |

| Check Point / View | | | | |
|----------------------------------|-------------------------------------|------------|----|---------------|
| Main Street / Down (cont) | | | | |
| Rating ** | A | Issue No. | 10 | GPS Lat/Long |
| Issue Type + | Ma | Location * | | 41.197770 ° |
| Category | Rivers, Channels & Designated Flood | | | -120.944100 ° |
| Item | Encroachments | | | |
| DWR ID | DWR_NA0030_1_c_2012_10 | | | |
| Action/Comments | | | | |
| | | | | |

No Photos

| Check Point / View | | | | |
|------------------------|-------------------------------------|------------|----|---------------|
| Ash Street / Up | | | | |
| Rating ** | A | Issue No. | 11 | GPS Lat/Long |
| Issue Type + | Ma | Location * | | 41.197138 ° |
| Category | Rivers, Channels & Designated Flood | | | -120.945271 ° |
| Item | Vegetation & Obstructions | | | |
| DWR ID | DWR_NA0030_1_c_2012_11 | | | |
| Action/Comments | | | | |
| | | | | |

Photo 1 of 1 : CH_2020_NA0030_1_11_20200701_00017.jpg



Upstream view of Ash Creek from the Ash Street crossing.

| Rating ** | A | Issue No. | 12 | GPS Lat/Long |
|--|-------------------------------------|------------|----|---------------|
| Issue Type + | Ma | Location * | | 41.197138 ° |
| Category | Rivers, Channels & Designated Flood | | | -120.945271 ° |
| Item | Shoaling / Sedimentation | | | |
| DWR ID | DWR_NA0030_1_c_2012_12 | | | |
| Action/Comments | | | | |
| Inspector Comments: No shoaling or sedimentation observed during the inspection. | | | | |

No Photos

| | | |
|--|---|---|
| * Location LS : Land Side WS : Water Side CR : Crown | ** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain | + Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement |
|--|---|---|

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2020

Adin Community Service District

| Channel | Channel Length | Inspection Start/End | Inspector |
|-----------|----------------|--------------------------|-------------|
| Ash Creek | 1.00 | 06/25/2020 06/25/2020 | Makar Sokol |

| Check Point / View | | | | GPS Lat/Long | No Photos |
|-------------------------------|-------------------------------------|------------|----|---------------|-----------|
| Ash Street / Up (cont) | | | | | |
| Rating ** | A | Issue No. | 13 | | |
| Issue Type + | Ma | Location * | | 41.197138 ° | |
| Category | Rivers, Channels & Designated Flood | | | -120.945271 ° | |
| Item | Erosion / Bank Caving | | | | |
| DWR ID | DWR_NA0030_1_c_2012_13 | | | | |
| Action/Comments | | | | | |
| | | | | | |

| | | | | | |
|-----------------|-------------------------------------|------------|----|---------------|-----------|
| Rating ** | N | Issue No. | 14 | GPS Lat/Long | |
| Issue Type + | Ma | Location * | | 41.197138 ° | No Photos |
| Category | Rivers, Channels & Designated Flood | | | -120.945271 ° | |
| Item | Revetments | | | | |
| DWR ID | DWR_NA0030_1_c_2012_14 | | | | |
| Action/Comments | | | | | |
| | | | | | |

| | | | | | |
|-----------------|-------------------------------------|------------|----|---------------|-----------|
| Rating ** | A | Issue No. | 15 | GPS Lat/Long | |
| Issue Type + | Ma | Location * | | 41.197138 ° | No Photos |
| Category | Rivers, Channels & Designated Flood | | | -120.945271 ° | |
| Item | Encroachments | | | | |
| DWR ID | DWR_NA0030_1_c_2012_15 | | | | |
| Action/Comments | | | | | |
| | | | | | |

| | | |
|--|---|---|
| * Location LS : Land Side WS : Water Side CR : Crown | ** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain | + Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement |
|--|---|---|

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2020

Adin Community Service District

| Channel | Channel Length | Inspection Start/End | Inspector |
|-----------|----------------|--------------------------|-------------|
| Ash Creek | 1.00 | 06/25/2020 06/25/2020 | Makar Sokol |

| Check Point / View | | | |
|--------------------------|-------------------------------------|---------------------|---------------|
| Ash Street / Down | | | |
| Rating ** | A | Issue No. 16 | GPS Lat/Long |
| Issue Type + | Ma | Location * | 41.197138 ° |
| Category | Rivers, Channels & Designated Flood | | -120.945271 ° |
| Item | Vegetation & Obstructions | | |
| DWR ID | DWR_NA0030_1_c_2012_16 | | |
| Action/Comments | | | |
| | | | |

Photo 1 of 1 : CH_2020_NA0030_1_16_20200701_00018.jpg



Downstream view of Ash Creek from the Ash Street crossing.

| Rating ** | A | Issue No. 17 | GPS Lat/Long |
|--|-------------------------------------|---------------------|---------------|
| Issue Type + | Ma | Location * | 41.197138 ° |
| Category | Rivers, Channels & Designated Flood | | -120.945271 ° |
| Item | Shoaling / Sedimentation | | |
| DWR ID | DWR_NA0030_1_c_2012_17 | | |
| Action/Comments | | | |
| Inspector Comments: No shoaling or sedimentation observed during the inspection. | | | |

No Photos

| Rating ** | M | Issue No. 18 | GPS Lat/Long |
|---|-------------------------------------|---------------------|---------------|
| Issue Type + | Ma | Location * | 41.197138 ° |
| Category | Rivers, Channels & Designated Flood | | -120.945271 ° |
| Item | Erosion / Bank Caving | | |
| DWR ID | DWR_NA0030_1_c_2012_18 | | |
| Action/Comments | | | |
| Inspector Comments: During low flows you can see the two gravel bars in channel. Monitor erosion during high flows. | | | |

Photo 1 of 1 : CH_2020_NA0030_1_18_20200701_00019.jpg



View of the gravel bars and moderate erosion on right bank.

| | | |
|--|---|---|
| * Location LS : Land Side WS : Water Side CR : Crown | ** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain | + Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement |
|--|---|---|

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2020

Adin Community Service District

| Channel | Channel Length | Inspection Start/End | Inspector |
|-----------|----------------|--------------------------|-------------|
| Ash Creek | 1.00 | 06/25/2020 06/25/2020 | Makar Sokol |

| Check Point / View | | | |
|---------------------------------|-------------------------------------|---------------------|---------------|
| Ash Street / Down (cont) | | | |
| Rating ** | A | Issue No. 19 | GPS Lat/Long |
| Issue Type + | Ma | Location * | 41.197138 ° |
| Category | Rivers, Channels & Designated Flood | | -120.945271 ° |
| Item | Revetments | | |
| DWR ID | DWR_NA0030_1_c_2012_19 | | |
| Action/Comments | | | |
| | | | |

No Photos

| Rating ** | A | Issue No. 20 | GPS Lat/Long |
|-----------------|-------------------------------------|---------------------|---------------|
| Issue Type + | Ma | Location * | 41.197138 ° |
| Category | Rivers, Channels & Designated Flood | | -120.945271 ° |
| Item | Encroachments | | |
| DWR ID | DWR_NA0030_1_c_2012_20 | | |
| Action/Comments | | | |
| | | | |

No Photos

| Check Point / View | | | |
|--|-------------------------------------|---------------------|---------------|
| Downstream limit/fish ladder & walkway / Up | | | |
| Rating ** | A | Issue No. 31 | GPS Lat/Long |
| Issue Type + | Ma | Location * | 41.192990 ° |
| Category | Rivers, Channels & Designated Flood | | -120.954530 ° |
| Item | Vegetation & Obstructions | | |
| DWR ID | DWR_NA0030_1_c_2012_31 | | |
| Action/Comments | | | |
| | | | |

Photo 1 of 1 : CH_2020_NA0030_1_31_20200701_00020.jpg



Upstream view of Ash Creek from the weir.

| | | |
|--|---|---|
| * Location LS : Land Side WS : Water Side CR : Crown | ** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain | + Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement |
|--|---|---|

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2020

Adin Community Service District

| Channel | Channel Length | Inspection Start/End | Inspector |
|-----------|----------------|--------------------------|-------------|
| Ash Creek | 1.00 | 06/25/2020 06/25/2020 | Makar Sokol |

| Check Point / View | | | |
|--|-------------------------------------|------------|---------------|
| Downstream limit/fish ladder & walkway / Up (cont) | | | |
| Rating ** | A | Issue No. | 32 |
| Issue Type + | Ma | Location * | GPS Lat/Long |
| Category | Rivers, Channels & Designated Flood | | 41.192990 ° |
| Item | Shoaling / Sedimentation | | -120.954530 ° |
| DWR ID | DWR_NA0030_1_c_2012_32 | | |
| Action/Comments | | | |
| Inspector Comments: No shoaling or sedimentation observed during the inspection. | | | |

No Photos

| | | | |
|---|-------------------------------------|------------|---------------|
| Rating ** | A | Issue No. | 33 |
| Issue Type + | Ma | Location * | GPS Lat/Long |
| Category | Rivers, Channels & Designated Flood | | 41.192990 ° |
| Item | Erosion / Bank Caving | | -120.954530 ° |
| DWR ID | DWR_NA0030_1_c_2012_33 | | |
| Action/Comments | | | |
| Inspector Comments: There is minor erosion along right side of the structure. | | | |

Photo 1 of 1 : CH_2020_NA0030_1_33_20200701_00021.jpg



View of the erosion along the right side of the weir.

| | | | |
|-----------------|-------------------------------------|------------|---------------|
| Rating ** | A | Issue No. | 34 |
| Issue Type + | Ma | Location * | GPS Lat/Long |
| Category | Rivers, Channels & Designated Flood | | 41.192990 ° |
| Item | Revetments | | -120.954530 ° |
| DWR ID | DWR_NA0030_1_c_2012_34 | | |
| Action/Comments | | | |

No Photos

| * Location |
|-----------------|
| LS : Land Side |
| WS : Water Side |
| CR : Crown |

| ** Rating | |
|--------------------------|---|
| A : Acceptable | N : Not Inspected/Rated |
| M : Minimally Acceptable | C : Corrected |
| U : Unacceptable | A/W : Acceptable but Monitor & Maintain |

| + Issue Type |
|-----------------------------------|
| Ma : Maintenance Deficiency |
| Ob : Design & System Obsolescence |
| En : Enforcement |

Flood Control Project Maintenance
Levee Inspections

Levee Inspection Report By Mile - Channel 2020

Adin Community Service District

| Channel | Channel Length | Inspection Start/End | Inspector |
|-----------|----------------|--------------------------|-------------|
| Ash Creek | 1.00 | 06/25/2020 06/25/2020 | Makar Sokol |

| Check Point / View | | | |
|---|-------------------------------------|------------|---------------|
| Downstream limit/fish ladder & walkway / Up (cont) | | | |
| Rating ** | A | Issue No. | 35 |
| Issue Type + | Ma | Location * | 41.192990 ° |
| Category | Rivers, Channels & Designated Flood | | -120.954530 ° |
| Item | Encroachments | | |
| DWR ID | DWR_NA0030_1_c_2012_35 | | |
| Action/Comments | | | |
| | | | |

No Photos

| Check Point / View | | | |
|--|-------------------------------------|------------|---------------|
| Downstream limit/fish ladder & walkway / Down | | | |
| Rating ** | A | Issue No. | 36 |
| Issue Type + | Ma | Location * | 41.192990 ° |
| Category | Rivers, Channels & Designated Flood | | -120.954530 ° |
| Item | Vegetation & Obstructions | | |
| DWR ID | DWR_NA0030_1_c_2012_36 | | |
| Action/Comments | | | |
| Inspector Comments: The channel is clear of vegetation & obstructions. | | | |

Photo 1 of 1 : CH_2020_NA0030_1_36_20200701_00022.jpg



Downstream view of Ash Creek from the weir.

| Rating ** | A | Issue No. | 37 | GPS Lat/Long |
|--|-------------------------------------|------------|---------------|--------------|
| Issue Type + | Ma | Location * | 41.192990 ° | |
| Category | Rivers, Channels & Designated Flood | | -120.954530 ° | |
| Item | Shoaling / Sedimentation | | | |
| DWR ID | DWR_NA0030_1_c_2012_37 | | | |
| Action/Comments | | | | |
| Inspector Comments: No shoaling or sedimentation observed during the inspection. | | | | |

No Photos

| * Location |
|-----------------|
| LS : Land Side |
| WS : Water Side |
| CR : Crown |

| ** Rating |
|---|
| A : Acceptable |
| M : Minimally Acceptable |
| U : Unacceptable |
| N : Not Inspected/Rated |
| C : Corrected |
| A/W : Acceptable but Monitor & Maintain |

| + Issue Type |
|-----------------------------------|
| Ma : Maintenance Deficiency |
| Ob : Design & System Obsolescence |
| En : Enforcement |

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2020

Adin Community Service District

| Channel | Channel Length | Inspection Start/End | Inspector |
|-----------|----------------|--------------------------|-------------|
| Ash Creek | 1.00 | 06/25/2020 06/25/2020 | Makar Sokol |

| Check Point / View | | | |
|---|-------------------------------------|---------------------|---------------|
| Downstream limit/fish ladder & walkway / Down (cont) | | | |
| Rating ** | A | Issue No. 38 | GPS Lat/Long |
| Issue Type + | Ma | Location * | 41.192990 ° |
| Category | Rivers, Channels & Designated Flood | | -120.954530 ° |
| Item | Erosion / Bank Caving | | |
| DWR ID | DWR_NA0030_1_c_2012_38 | | |
| Action/Comments | | | |
| | | | |

No Photos

| | | | |
|-----------------|-------------------------------------|---------------------|---------------|
| Rating ** | A | Issue No. 39 | GPS Lat/Long |
| Issue Type + | Ma | Location * | 41.192990 ° |
| Category | Rivers, Channels & Designated Flood | | -120.954530 ° |
| Item | Revetments | | |
| DWR ID | DWR_NA0030_1_c_2012_39 | | |
| Action/Comments | | | |
| | | | |

No Photos

| | | | |
|-----------------|-------------------------------------|---------------------|---------------|
| Rating ** | A | Issue No. 40 | GPS Lat/Long |
| Issue Type + | Ma | Location * | 41.192990 ° |
| Category | Rivers, Channels & Designated Flood | | -120.954530 ° |
| Item | Encroachments | | |
| DWR ID | DWR_NA0030_1_c_2012_40 | | |
| Action/Comments | | | |
| | | | |

No Photos

| | | |
|--|---|---|
| * Location LS : Land Side WS : Water Side CR : Crown | ** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain | + Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement |
|--|---|---|

Flood Control Project Maintenance

Unit Cover Sheet

2020 Channel Inspection Results

Adin Community Service District

| |
|-----------|
| Channel |
| Dry Creek |

| | |
|--------------------|--|
| Channel Rating | A |
| Date of Inspection | 6/25/2020 |
| DWR Inspector | Makar Sokol |
| Accompanied By | Mike Williams Adin Community Service District |

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2020

Adin Community Service District

| Channel | Channel Length | Inspection Start/End | Inspector |
|-----------|----------------|--------------------------|-------------|
| Dry Creek | 0.20 | 06/25/2020 06/25/2020 | Makar Sokol |

| Check Point / View | | | | |
|-------------------------|-------------------------------------|------------|---|---------------|
| Adin Street / Up | | | | |
| Rating ** | A | Issue No. | 1 | GPS Lat/Long |
| Issue Type + | Ma | Location * | | 41.195370 ° |
| Category | Rivers, Channels & Designated Flood | | | -120.943190 ° |
| Item | Vegetation & Obstructions | | | |
| DWR ID | DWR_NA0030_2_c_2012_1 | | | |
| Action/Comments | | | | |
| | | | | |

Photo 1 of 1 : CH_2020_NA0030_2_1_20200701_00009.jpg



Upstream view of the Dry Creek from Adin Street.

| Rating ** | A | Issue No. | 2 | GPS Lat/Long |
|--|-------------------------------------|------------|---|---------------|
| Issue Type + | Ma | Location * | | 41.195370 ° |
| Category | Rivers, Channels & Designated Flood | | | -120.943190 ° |
| Item | Shoaling / Sedimentation | | | |
| DWR ID | DWR_NA0030_2_c_2012_2 | | | |
| Action/Comments | | | | |
| Inspector Comments: No shoaling or sedimentation observed during the inspection. | | | | |

No Photos

| Rating ** | A | Issue No. | 3 | GPS Lat/Long |
|-----------------|-------------------------------------|------------|---|---------------|
| Issue Type + | Ma | Location * | | 41.195370 ° |
| Category | Rivers, Channels & Designated Flood | | | -120.943190 ° |
| Item | Erosion / Bank Caving | | | |
| DWR ID | DWR_NA0030_2_c_2012_3 | | | |
| Action/Comments | | | | |
| | | | | |

No Photos

| | | |
|--|---|---|
| * Location LS : Land Side WS : Water Side CR : Crown | ** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain | + Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement |
|--|---|---|

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2020

Adin Community Service District

| Channel | Channel Length | Inspection Start/End | Inspector |
|-----------|----------------|--------------------------|-------------|
| Dry Creek | 0.20 | 06/25/2020 06/25/2020 | Makar Sokol |

| Check Point / View | | | |
|--------------------------------|-------------------------------------|--------------------|---------------|
| Adin Street / Up (cont) | | | |
| Rating ** | N | Issue No. 4 | GPS Lat/Long |
| Issue Type + | Ma | Location * | 41.195370 ° |
| Category | Rivers, Channels & Designated Flood | | -120.943190 ° |
| Item | Revetments | | |
| DWR ID | DWR_NA0030_2_c_2012_4 | | |
| Action/Comments | | | |
| | | | |

No Photos

| Rating ** | A | Issue No. 5 | GPS Lat/Long |
|-----------------|-------------------------------------|--------------------|---------------|
| Issue Type + | Ma | Location * | 41.195370 ° |
| Category | Rivers, Channels & Designated Flood | | -120.943190 ° |
| Item | Encroachments | | |
| DWR ID | DWR_NA0030_2_c_2012_5 | | |
| Action/Comments | | | |
| | | | |

No Photos

| Check Point / View | | | |
|--|-------------------------------------|--------------------|---------------|
| Adin Street / Down | | | |
| Rating ** | A | Issue No. 6 | GPS Lat/Long |
| Issue Type + | Ma | Location * | 41.195370 ° |
| Category | Rivers, Channels & Designated Flood | | -120.943190 ° |
| Item | Vegetation & Obstructions | | |
| DWR ID | DWR_NA0030_2_c_2012_6 | | |
| Action/Comments | | | |
| Inspector Comments: The vegetation currently does not impede the flow. However, it should be removed before it gets too dense. | | | |

Photo 1 of 1 : CH_2020_NA0030_2_6_20200701_00010.jpg



Downstream view of Dry Creek from Adin Street.

| * Location |
|-----------------|
| LS : Land Side |
| WS : Water Side |
| CR : Crown |

| ** Rating |
|---|
| A : Acceptable |
| M : Minimally Acceptable |
| U : Unacceptable |
| N : Not Inspected/Rated |
| C : Corrected |
| A/W : Acceptable but Monitor & Maintain |

| + Issue Type |
|-----------------------------------|
| Ma : Maintenance Deficiency |
| Ob : Design & System Obsolescence |
| En : Enforcement |

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2020

Adin Community Service District

| Channel | Channel Length | Inspection Start/End | Inspector |
|-----------|----------------|--------------------------|-------------|
| Dry Creek | 0.20 | 06/25/2020 06/25/2020 | Makar Sokol |

| Check Point / View | | | |
|--|-------------------------------------|--------------------|---------------|
| Adin Street / Down (cont) | | | |
| Rating ** | A | Issue No. 7 | GPS Lat/Long |
| Issue Type + | Ma | Location * | 41.195370 ° |
| Category | Rivers, Channels & Designated Flood | | -120.943190 ° |
| Item | Shoaling / Sedimentation | | |
| DWR ID | DWR_NA0030_2_c_2012_7 | | |
| Action/Comments | | | |
| Inspector Comments: No shoaling or sedimentation observed during the inspection. | | | |

No Photos

| Rating ** | A | Issue No. 8 | GPS Lat/Long |
|-----------------|-------------------------------------|--------------------|---------------|
| Issue Type + | Ma | Location * | 41.195370 ° |
| Category | Rivers, Channels & Designated Flood | | -120.943190 ° |
| Item | Erosion / Bank Caving | | |
| DWR ID | DWR_NA0030_2_c_2012_8 | | |
| Action/Comments | | | |
| | | | |

No Photos

| Rating ** | N | Issue No. 9 | GPS Lat/Long |
|-----------------|-------------------------------------|--------------------|---------------|
| Issue Type + | Ma | Location * | 41.195370 ° |
| Category | Rivers, Channels & Designated Flood | | -120.943190 ° |
| Item | Revetments | | |
| DWR ID | DWR_NA0030_2_c_2012_9 | | |
| Action/Comments | | | |
| | | | |

No Photos

| | | |
|--|---|---|
| * Location LS : Land Side WS : Water Side CR : Crown | ** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain | + Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement |
|--|---|---|

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2020

Adin Community Service District

| Channel | Channel Length | Inspection Start/End | Inspector |
|-----------|----------------|--------------------------|-------------|
| Dry Creek | 0.20 | 06/25/2020 06/25/2020 | Makar Sokol |

| Check Point / View | | | |
|----------------------------------|-------------------------------------|------------|---------------|
| Adin Street / Down (cont) | | | |
| Rating ** | A | Issue No. | 10 |
| Issue Type + | Ma | Location * | 41.195370 ° |
| Category | Rivers, Channels & Designated Flood | | -120.943190 ° |
| Item | Encroachments | | |
| DWR ID | DWR_NA0030_2_c_2012_10 | | |
| Action/Comments | | | |
| | | | |

No Photos

| Check Point / View | | | |
|---|-------------------------------------|------------|---------------|
| Main Street / Up | | | |
| Rating ** | M | Issue No. | 11 |
| Issue Type + | Ma | Location * | 41.196350 ° |
| Category | Rivers, Channels & Designated Flood | | -120.944250 ° |
| Item | Vegetation & Obstructions | | |
| DWR ID | DWR_NA0030_2_c_2012_11 | | |
| Action/Comments | | | |
| Inspector Comments: Remove all vegetation in channel before winter. | | | |

Photo 1 of 2 : CH_2020_NA0030_2_11_20200701_00012.jpg



View of the brush at the upstream side of the Main Street bridge and culverts.

| | | |
|--|---|---|
| * Location LS : Land Side WS : Water Side CR : Crown | ** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain | + Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement |
|--|---|---|

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2020

Adin Community Service District

| Channel | Channel Length | Inspection Start/End | Inspector |
|-----------|----------------|--------------------------|-------------|
| Dry Creek | 0.20 | 06/25/2020 06/25/2020 | Makar Sokol |

Check Point / View

Main Street / Up (cont)

| Rating ** | M | Issue No. | 11 (cont) | GPS Lat/Long |
|---|-------------------------------------|------------|------------------|---------------|
| Issue Type + | Ma | Location * | | 41.196350 ° |
| Category | Rivers, Channels & Designated Flood | | | -120.944250 ° |
| Item | Vegetation & Obstructions | | | |
| DWR ID | DWR_NA0030_2_c_2012_11 | | | |
| Action/Comments | | | | |
| Inspector Comments: Remove all vegetation in channel before winter. | | | | |

Photo 2 of 2 : CH_2020_NA0030_2_11_20200701_00011.jpg



Upstream view of Dry Creek from Main Street.

| Rating ** | A | Issue No. | 12 | GPS Lat/Long |
|--|-------------------------------------|------------|-----------|---------------|
| Issue Type + | Ma | Location * | | 41.196350 ° |
| Category | Rivers, Channels & Designated Flood | | | -120.944250 ° |
| Item | Shoaling / Sedimentation | | | |
| DWR ID | DWR_NA0030_2_c_2012_12 | | | |
| Action/Comments | | | | |
| Inspector Comments: No shoaling or sedimentation observed during the inspection. | | | | |

No Photos

| Rating ** | A | Issue No. | 13 | GPS Lat/Long |
|-----------------|-------------------------------------|------------|-----------|---------------|
| Issue Type + | Ma | Location * | | 41.196350 ° |
| Category | Rivers, Channels & Designated Flood | | | -120.944250 ° |
| Item | Erosion / Bank Caving | | | |
| DWR ID | DWR_NA0030_2_c_2012_13 | | | |
| Action/Comments | | | | |
| | | | | |

No Photos

| * Location |
|-----------------|
| LS : Land Side |
| WS : Water Side |
| CR : Crown |

| ** Rating |
|---|
| A : Acceptable |
| M : Minimally Acceptable |
| U : Unacceptable |
| N : Not Inspected/Rated |
| C : Corrected |
| A/W : Acceptable but Monitor & Maintain |

| + Issue Type |
|-----------------------------------|
| Ma : Maintenance Deficiency |
| Ob : Design & System Obsolescence |
| En : Enforcement |

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2020

Adin Community Service District

| Channel | Channel Length | Inspection Start/End | Inspector |
|-----------|----------------|--------------------------|-------------|
| Dry Creek | 0.20 | 06/25/2020 06/25/2020 | Makar Sokol |

| Check Point / View | | | |
|--------------------------------|-------------------------------------|---------------------|---------------|
| Main Street / Up (cont) | | | |
| Rating ** | N | Issue No. 14 | GPS Lat/Long |
| Issue Type + | Ma | Location * | 41.196350 ° |
| Category | Rivers, Channels & Designated Flood | | -120.944250 ° |
| Item | Revetments | | |
| DWR ID | DWR_NA0030_2_c_2012_14 | | |
| Action/Comments | | | |
| | | | |

No Photos

| Rating ** | A | Issue No. 15 | GPS Lat/Long |
|-----------------|-------------------------------------|---------------------|---------------|
| Issue Type + | Ma | Location * | 41.196350 ° |
| Category | Rivers, Channels & Designated Flood | | -120.944250 ° |
| Item | Encroachments | | |
| DWR ID | DWR_NA0030_2_c_2012_15 | | |
| Action/Comments | | | |
| | | | |

No Photos

| Check Point / View | | | |
|---|-------------------------------------|---------------------|---------------|
| Main Street / Down | | | |
| Rating ** | M | Issue No. 16 | GPS Lat/Long |
| Issue Type + | Ma | Location * | 41.196350 ° |
| Category | Rivers, Channels & Designated Flood | | -120.944250 ° |
| Item | Vegetation & Obstructions | | |
| DWR ID | DWR_NA0030_2_c_2012_16 | | |
| Action/Comments | | | |
| Inspector Comments: Remove all vegetation in channel before winter. | | | |

Photo 1 of 1 : CH_2020_NA0030_2_16_20200701_00013.jpg



Downstream view of Dry Creek from Main Street.

| | | |
|--|---|---|
| * Location LS : Land Side WS : Water Side CR : Crown | ** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain | + Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement |
|--|---|---|

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2020

Adin Community Service District

| Channel | Channel Length | Inspection Start/End | Inspector |
|-----------|----------------|--------------------------|-------------|
| Dry Creek | 0.20 | 06/25/2020 06/25/2020 | Makar Sokol |

| Check Point / View | | | |
|--|-------------------------------------|---------------------|---------------|
| Main Street / Down (cont) | | | |
| Rating ** | A | Issue No. 17 | GPS Lat/Long |
| Issue Type + | Ma | Location * | 41.196350 ° |
| Category | Rivers, Channels & Designated Flood | | -120.944250 ° |
| Item | Shoaling / Sedimentation | | |
| DWR ID | DWR_NA0030_2_c_2019_17 | | |
| Action/Comments | | | |
| Inspector Comments: No shoaling or sedimentation observed during the inspection. | | | |

No Photos

| Rating ** | A | Issue No. 18 | GPS Lat/Long |
|-----------------|-------------------------------------|---------------------|---------------|
| Issue Type + | Ma | Location * | 41.196350 ° |
| Category | Rivers, Channels & Designated Flood | | -120.944250 ° |
| Item | Erosion / Bank Caving | | |
| DWR ID | DWR_NA0030_2_c_2012_18 | | |
| Action/Comments | | | |
| | | | |

No Photos

| Rating ** | N | Issue No. 19 | GPS Lat/Long |
|-----------------|-------------------------------------|---------------------|---------------|
| Issue Type + | Ma | Location * | 41.196350 ° |
| Category | Rivers, Channels & Designated Flood | | -120.944250 ° |
| Item | Revetments | | |
| DWR ID | DWR_NA0030_2_c_2012_19 | | |
| Action/Comments | | | |
| | | | |

No Photos

| | | |
|--|---|---|
| * Location LS : Land Side WS : Water Side CR : Crown | ** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain | + Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement |
|--|---|---|

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2020

Adin Community Service District

| Channel | Channel Length | Inspection Start/End | Inspector |
|-----------|----------------|--------------------------|-------------|
| Dry Creek | 0.20 | 06/25/2020 06/25/2020 | Makar Sokol |

| Check Point / View | | | |
|----------------------------------|-------------------------------------|------------|---------------|
| Main Street / Down (cont) | | | |
| Rating ** | A | Issue No. | 20 |
| Issue Type + | Ma | Location * | 41.196350 ° |
| Category | Rivers, Channels & Designated Flood | | -120.944250 ° |
| Item | Encroachments | | |
| DWR ID | DWR_NA0030_2_c_2012_20 | | |
| Action/Comments | | | |
| | | | |

No Photos

| | | |
|--|---|---|
| * Location LS : Land Side WS : Water Side CR : Crown | ** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain | + Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement |
|--|---|---|