

**Flood Control Project Maintenance
Levee Inspections**
2020 Channel Summary Report
Overall Unit and Item Ratings

DWR Sutter Maintenance Yard

Big Chico Creek

Overall Unit Rating	Rated Item	Item Rating
A	Vegetation & Obstructions	A
	Shoaling / Sedimentation	A
	Erosion / Bank Caving	A
	Revetments & Other Structural Appurtenances	A
	Encroachments	A

Lindo Channel & Sandy Gulch

Overall Unit Rating	Rated Item	Item Rating
A	Vegetation & Obstructions	M
	Shoaling / Sedimentation	A
	Erosion / Bank Caving	A
	Revetments & Other Structural Appurtenances	A
	Encroachments	A

Little Chico Creek

Overall Unit Rating	Rated Item	Item Rating
M	Vegetation & Obstructions	M
	Shoaling / Sedimentation	A
	Erosion / Bank Caving	A
	Revetments & Other Structural Appurtenances	A
	Encroachments	A

Flood Control Project Maintenance

Unit Cover Sheet

2020 Channel Inspection Results

DWR Sutter Maintenance Yard

Channel
Big Chico Creek

Channel Rating	A
Date of Inspection	7/29/2020
DWR Inspector	Brooks Weisser
Accompanied By	

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2020

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Big Chico Creek	13.00	07/29/2020 07/29/2020	Brooks Weisser

Check Point / View			
Big Chico Creek Control Structure / Up			
Rating **	A	Issue No.	1
Issue Type +	Ma	Location *	GPS Lat/Long
Category	Rivers, Channels & Designated Flood		39.761840 °
Item	Vegetation & Obstructions		-121.792590 °
DWR ID	DWR_NA0060_5_c_2012_1		
Action/Comments			
Inspector Comments: Minimal, scattered obstructions and vegetation. The flow is not impeded.			

Photo 1 of 1 : CH_2020_NA0060_5_1_20200804_00027.jpg



View of the channel from the structure facing upstream from the structure, 2020.

Rating **	A	Issue No.	2
Issue Type +	Ma	Location *	GPS Lat/Long
Category	Rivers, Channels & Designated Flood		39.761840 °
Item	Shoaling / Sedimentation		-121.792590 °
DWR ID	DWR_NA0060_5_c_2012_2		
Action/Comments			
Inspector Comments: No shoaling or sedimentation observed.			

No Photos

Rating **	A	Issue No.	3
Issue Type +	Ma	Location *	GPS Lat/Long
Category	Rivers, Channels & Designated Flood		39.761840 °
Item	Erosion / Bank Caving		-121.792590 °
DWR ID	DWR_NA0060_5_c_2012_3		
Action/Comments			
Inspector Comments: No erosion observed.			

No Photos

* Location
LS : Land Side
WS : Water Side
CR : Crown

** Rating
A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type
Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2020

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Big Chico Creek	13.00	07/29/2020 07/29/2020	Brooks Weisser

Check Point / View			
Big Chico Creek Control Structure / Up (cont)			
Rating **	A	Issue No.	4
Issue Type +	Ma	Location *	39.761840 °
Category	Rivers, Channels & Designated Flood		-121.792590 °
Item	Revetments		
DWR ID	DWR_NA0060_5_c_2012_4		
Action/Comments			
Inspector Comments: Some of the riprap is covered with vegetation. Trees and other vegetation growth should be managed/removed from riprap.			

Photo 1 of 1 : CH_2020_NA0060_5_4_20200804_00032.jpg



View of typical revetment on the upstream side of the structure, 2020.

Check Point / View			
Rating **	A	Issue No.	5
Issue Type +	Ma	Location *	39.761840 °
Category	Rivers, Channels & Designated Flood		-121.792590 °
Item	Encroachments		
DWR ID	DWR_NA0060_5_c_2012_5		
Action/Comments			
Inspector Comments: No trash, debris, excavation, structures, or other obstructions present within the project easement area.			

No Photos

* Location
LS : Land Side
WS : Water Side
CR : Crown

** Rating
A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type
Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2020

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Big Chico Creek	13.00	07/29/2020 07/29/2020	Brooks Weisser

Check Point / View			
Big Chico Creek Control Structure / Down			
Rating **	A	Issue No. 6	GPS Lat/Long
Issue Type +	Ma	Location *	39.761840 °
Category	Rivers, Channels & Designated Flood		-121.792590 °
Item	Vegetation & Obstructions		
DWR ID	DWR_NA0060_5_c_2012_6		
Action/Comments			
Inspector Comments: Minimal, scattered obstructions and vegetation. The flow is not impeded.			

Photo 1 of 1 : CH_2020_NA0060_5_6_20200804_00029.jpg



View of the downstream side of the channel from the structure, 2020

Rating **	A	Issue No. 7	GPS Lat/Long
Issue Type +	Ma	Location *	39.761840 °
Category	Rivers, Channels & Designated Flood		-121.792590 °
Item	Shoaling / Sedimentation		
DWR ID	DWR_NA0060_5_c_2012_7		
Action/Comments			
Inspector Comments: No shoaling or sedimentation observed.			

No Photos

Rating **	A	Issue No. 8	GPS Lat/Long
Issue Type +	Ma	Location *	39.761840 °
Category	Rivers, Channels & Designated Flood		-121.792590 °
Item	Erosion / Bank Caving		
DWR ID	DWR_NA0060_5_c_2012_8		
Action/Comments			
Inspector Comments: No erosion observed.			

No Photos

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2020

DWR Sutter Maintenance Yard


Channel	Channel Length	Inspection Start/End	Inspector
Big Chico Creek	13.00	07/29/2020 07/29/2020	Brooks Weisser

Check Point / View			
Big Chico Creek Control Structure / Down (cont)			
Rating **	A	Issue No.	9
Issue Type +	Ma	Location *	GPS Lat/Long
Category	Rivers, Channels & Designated Flood		39.761840 °
Item	Revetments		-121.792590 °
DWR ID	DWR_NA0060_5_c_2012_9		
Action/Comments			
Inspector Comments: Riprap is visible and appears properly maintained.			



View of the revetment downstream left bank of the channel from the structure, 2020.

Rating **	A	Issue No.	9 (cont)
Issue Type +	Ma	Location *	GPS Lat/Long
Category	Rivers, Channels & Designated Flood		39.761840 °
Item	Revetments		-121.792590 °
DWR ID	DWR_NA0060_5_c_2012_9		



View of the revetment downstream right bank of the channel from the structure, 2020.

Rating **	A	Issue No.	10
Issue Type +	Ma	Location *	GPS Lat/Long
Category	Rivers, Channels & Designated Flood		39.761840 °
Item	Encroachments		-121.792590 °
DWR ID	DWR_NA0060_5_c_2012_10		
Action/Comments			
Inspector Comments: No trash, debris, excavation, structures, or other obstructions present within the project easement area.			

No Photos

* Location
LS : Land Side
WS : Water Side
CR : Crown

** Rating
A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type
Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2020

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Big Chico Creek	13.00	07/29/2020 07/29/2020	Brooks Weisser

Check Point / View				
Manzanita Ave. / Up				
Rating **	A	Issue No.	11	GPS Lat/Long
Issue Type +	Ma	Location *		39.758224 °
Category	Rivers, Channels & Designated Flood			-121.795853 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0060_5_c_2012_11			
Action/Comments				
Inspector Comments: Minimal, scattered obstructions and vegetation. The flow is not impeded.				

Photo 1 of 1 : CH_2020_NA0060_5_11_20200804_00035.jpg



This photo is looking upstream from under Manzanita Avenue Bridge, 2020.

Rating **	A	Issue No.	12	GPS Lat/Long
Issue Type +	Ma	Location *		39.758224 °
Category	Rivers, Channels & Designated Flood			-121.795853 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0060_5_c_2012_12			
Action/Comments				
Inspector Comments: No shoaling or sedimentation was observed.				

No Photos

Rating **	A	Issue No.	14	GPS Lat/Long
Issue Type +	Ma	Location *		39.758224 °
Category	Rivers, Channels & Designated Flood			-121.795853 °
Item	Revetments			
DWR ID	DWR_NA0060_5_c_2012_14			
Action/Comments				
Inspector Comments: Riprap is visible and appears properly maintained.				

Photo 1 of 2 : CH_2020_NA0060_5_14_20200804_00034.jpg



View looking upstream at the right bank of typical revetment around the abutment and bike path, 2020.

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2020

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Big Chico Creek	13.00	07/29/2020 07/29/2020	Brooks Weisser

Check Point / View				
Manzanita Ave. / Up (cont)				
Rating **	A	Issue No.	14 (cont)	GPS Lat/Long
Issue Type +	Ma	Location *		39.758224 °
Category	Rivers, Channels & Designated Flood			-121.795853 °
Item	Revetments			
DWR ID	DWR_NA0060_5_c_2012_14			
Action/Comments				
Inspector Comments: Riprap is visible and appears properly maintained.				



View looking upstream at the left bank of typical revetment around the abutment and bike path, 2020.

Rating **	A	Issue No.	15	GPS Lat/Long
Issue Type +	Ma	Location *		39.758224 °
Category	Rivers, Channels & Designated Flood			-121.795853 °
Item	Encroachments			
DWR ID	DWR_NA0060_5_c_2012_15			
Action/Comments				
Inspector Comments: No trash, debris, excavation, structures, or other obstructions present within the project easement area.				

No Photos

* Location
LS : Land Side
WS : Water Side
CR : Crown

** Rating	
A : Acceptable	N : Not Inspected/Rated
M : Minimally Acceptable	C : Corrected
U : Unacceptable	A/W : Acceptable but Monitor & Maintain

+ Issue Type
Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2020

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Big Chico Creek	13.00	07/29/2020 07/29/2020	Brooks Weisser

Check Point / View			
Manzanita Ave. / Down			
Rating **	A	Issue No.	16
Issue Type +	Ma	Location *	39.758224 °
Category	Rivers, Channels & Designated Flood		-121.795853 °
Item	Vegetation & Obstructions		
DWR ID	DWR_NA0060_5_c_2012_16		
Action/Comments			
Inspector Comments: Minimal, scattered obstructions and vegetation. The flow is not impeded.			

Photo 1 of 1 : CH_2020_NA0060_5_16_20200804_00036.jpg



This photo is looking downstream from Manzanita Avenue Bridge, 2020.

Rating **	A	Issue No.	17
Issue Type +	Ma	Location *	39.758224 °
Category	Rivers, Channels & Designated Flood		-121.795853 °
Item	Shoaling / Sedimentation		
DWR ID	DWR_NA0060_5_c_2012_17		
Action/Comments			
Inspector Comments: No shoaling or sedimentation observed.			

No Photos

Rating **	A	Issue No.	18
Issue Type +	Ma	Location *	39.758224 °
Category	Rivers, Channels & Designated Flood		-121.795853 °
Item	Erosion / Bank Caving		
DWR ID	DWR_NA0060_5_c_2012_18		
Action/Comments			
Inspector Comments: No erosion observed.			

No Photos

* Location
LS : Land Side
WS : Water Side
CR : Crown

** Rating
A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type
Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2020

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Big Chico Creek	13.00	07/29/2020 07/29/2020	Brooks Weisser

Check Point / View			
Manzanita Ave. / Down (cont)			
Rating **	A	Issue No.	19
Issue Type +	Ma	Location *	39.758224 °
Category	Rivers, Channels & Designated Flood		-121.795853 °
Item	Revetments		
DWR ID	DWR_NA0060_5_c_2012_19		
Action/Comments			
Inspector Comments: Riprap is visible and appears properly maintained.			


No Photos

Rating **	A	Issue No.	20
Issue Type +	Ma	Location *	39.758224 °
Category	Rivers, Channels & Designated Flood		-121.795853 °
Item	Encroachments		
DWR ID	DWR_NA0060_5_c_2012_20		
Action/Comments			
Inspector Comments: No trash, debris, excavation, structures, or other obstructions present within the project easement area.			

No Photos

Check Point / View			
Hwy 99 Bridge / Up			
Rating **	A	Issue No.	21
Issue Type +	Ma	Location *	39.738490 °
Category	Rivers, Channels & Designated Flood		-121.822810 °
Item	Vegetation & Obstructions		
DWR ID	DWR_NA0060_5_c_2012_21		
Action/Comments			
Inspector Comments: Minimal scattered obstructions or vegetation. The flow is not impeded.			

Photo 1 of 1 : CH_2020_NA0060_5_21_20200804_00037.jpg



View of the channel up from Highway 99 facing upstream, 2020.

* Location
LS : Land Side
WS : Water Side
CR : Crown

** Rating
A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type
Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2020

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Big Chico Creek	13.00	07/29/2020 07/29/2020	Brooks Weisser

Check Point / View			
Hwy 99 Bridge / Up (cont)			
Rating **	A	Issue No. 22	GPS Lat/Long
Issue Type +	Ma	Location *	39.738490 °
Category	Rivers, Channels & Designated Flood		-121.822810 °
Item	Shoaling / Sedimentation		
DWR ID	DWR_NA0060_5_c_2012_22		
Action/Comments			
Inspector Comments: No shoaling or sedimentation present.			

No Photos

Rating **	A	Issue No. 23	GPS Lat/Long
Issue Type +	Ma	Location *	39.738490 °
Category	Rivers, Channels & Designated Flood		-121.822810 °
Item	Erosion / Bank Caving		
DWR ID	DWR_NA0060_5_c_2012_23		
Action/Comments			
Inspector Comments: No erosion present.			

No Photos

Rating **	A	Issue No. 24	GPS Lat/Long
Issue Type +	Ma	Location *	39.738490 °
Category	Rivers, Channels & Designated Flood		-121.822810 °
Item	Revetments		
DWR ID	DWR_NA0060_5_c_2012_24		
Action/Comments			
Inspector Comments: Existing riprap protection is properly maintained and is undamaged. Riprap is clearly visible on both sides.			

Photo 1 of 2 : CH_2020_NA0060_5_24_20200804_00038.jpg



View of revetment along the channel right bank, looking upstream, 2020.

*** Location**
LS : Land Side
WS : Water Side
CR : Crown

**** Rating**
A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type
Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2020

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Big Chico Creek	13.00	07/29/2020 07/29/2020	Brooks Weisser

Check Point / View			
Hwy 99 Bridge / Up (cont)			
Rating **	A	Issue No.	24 (cont)
Issue Type +	Ma	Location *	39.738490 °
Category	Rivers, Channels & Designated Flood		-121.822810 °
Item	Revetments		
DWR ID	DWR_NA0060_5_c_2012_24		
Action/Comments			
Inspector Comments: Existing riprap protection is properly maintained and is undamaged. Riprap is clearly visible on both sides.			

Photo 2 of 2 : CH_2020_NA0060_5_24_20200804_00042.jpg



View of revetment along the channel left bank, looking upstream, 2020.

Rating **	A	Issue No.	25
Issue Type +	Ma	Location *	39.738490 °
Category	Rivers, Channels & Designated Flood		-121.822810 °
Item	Encroachments		
DWR ID	DWR_NA0060_5_c_2012_25		
Action/Comments			
Inspector Comments: No trash, debris, excavation, structures, or other obstructions present within the easement.			

No Photos

* Location
LS : Land Side
WS : Water Side
CR : Crown

** Rating
A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type
Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2020

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Big Chico Creek	13.00	07/29/2020 07/29/2020	Brooks Weisser

Check Point / View			
Hwy 99 Bridge / Down			
Rating **	M	Issue No. 26	GPS Lat/Long
Issue Type +	Ma	Location *	39.738490 °
Category	Rivers, Channels & Designated Flood		-121.822810 °
Item	Vegetation & Obstructions		
DWR ID	DWR_NA0060_5_c_2012_26		
Action/Comments			
Inspector Comments: Scattered obstructions and vegetation, the flow is not impeded.			

Photo 1 of 1 : CH_2020_NA0060_5_26_20200804_00043.jpg



View of the channel under Highway 99 facing downstream, 2020.

Rating **	A	Issue No. 27	GPS Lat/Long
Issue Type +	Ma	Location *	39.738490 °
Category	Rivers, Channels & Designated Flood		-121.822810 °
Item	Shoaling / Sedimentation		
DWR ID	DWR_NA0060_5_c_2012_27		
Action/Comments			
Inspector Comments: No shoaling or sedimentation present.			

No Photos

Rating **	A	Issue No. 28	GPS Lat/Long
Issue Type +	Ma	Location *	39.738490 °
Category	Rivers, Channels & Designated Flood		-121.822810 °
Item	Erosion / Bank Caving		
DWR ID	DWR_NA0060_5_c_2012_28		
Action/Comments			
Inspector Comments: No erosion present.			

No Photos

* Location
LS : Land Side
WS : Water Side
CR : Crown

** Rating
A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type
Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2020

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Big Chico Creek	13.00	07/29/2020 07/29/2020	Brooks Weisser

Check Point / View			
Hwy 99 Bridge / Down (cont)			
Rating **	A	Issue No.	29
Issue Type +	Ma	Location *	GPS Lat/Long
Category	Rivers, Channels & Designated Flood		39.738490 °
Item	Revetments		-121.822810 °
DWR ID	DWR_NA0060_5_c_2012_29		
Action/Comments			
Inspector Comments: Existing riprap protection is properly maintained and is undamaged. Riprap is clearly visible on both sides.			

No Photos

Rating **	A	Issue No.	30
Issue Type +	Ma	Location *	GPS Lat/Long
Category	Rivers, Channels & Designated Flood		39.731810 °
Item	Encroachments		-121.822810 °
DWR ID	DWR_NA0060_5_c_2012_30		
Action/Comments			
Inspector Comments: No trash, debris, excavation, structures, or other obstructions present within the easement.			

No Photos

Check Point / View			
Esplanade / Up			
Rating **	A	Issue No.	36
Issue Type +	Ma	Location *	GPS Lat/Long
Category	Rivers, Channels & Designated Flood		39.731810 °
Item	Vegetation & Obstructions		-121.841870 °
DWR ID	DWR_NA0060_5_c_2012_36		
Action/Comments			
Inspector Comments: Scattered obstructions and vegetation. The flow is not impeded.			

Photo 1 of 1 : CH_2020_NA0060_5_36_20200804_00044.jpg



View of the channel facing upstream, 2020.

* Location
LS : Land Side
WS : Water Side
CR : Crown

** Rating
A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type
Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2020

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Big Chico Creek	13.00	07/29/2020 07/29/2020	Brooks Weisser

Check Point / View			
Esplanade / Up (cont)			
Rating **	A	Issue No.	32
			GPS Lat/Long
Issue Type +	Ma	Location *	39.731810 °
Category	Rivers, Channels & Designated Flood		-121.841870 °
Item	Shoaling / Sedimentation		
DWR ID	DWR_NA0060_5_c_2012_32		
Action/Comments			
Inspector Comments: No shoaling or sedimentation observed.			

No Photos

Rating **	A	Issue No.	33
			GPS Lat/Long
Issue Type +	Ma	Location *	39.731810 °
Category	Rivers, Channels & Designated Flood		-121.841870 °
Item	Erosion / Bank Caving		
DWR ID	DWR_NA0060_5_c_2012_33		
Action/Comments			
Inspector Comments: No erosion observed.			

No Photos

Rating **	N	Issue No.	34
			GPS Lat/Long
Issue Type +	Ma	Location *	39.731810 °
Category	Rivers, Channels & Designated Flood		-121.841870 °
Item	Revetments		
DWR ID	DWR_NA0060_5_c_2012_34		
Action/Comments			
Inspector Comments: No revetments present.			

Photo 1 of 2 : CH_2020_NA0060_5_34_20200804_00045.jpg



No visible revetment left bank, 2020

* Location
LS : Land Side
WS : Water Side
CR : Crown

** Rating
A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type
Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2020

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Big Chico Creek	13.00	07/29/2020 07/29/2020	Brooks Weisser

Check Point / View			
Esplanade / Up (cont)			
Rating **	N	Issue No. 34 (cont)	GPS Lat/Long
Issue Type +	Ma	Location *	39.731810 °
Category	Rivers, Channels & Designated Flood		-121.841870 °
Item	Revetments		
DWR ID	DWR_NA0060_5_c_2012_34		
Action/Comments			
Inspector Comments: No revetments present.			

Photo 2 of 2 : CH_2020_NA0060_5_34_20200804_00046.jpg



No visible revetment right bank, 2020.

Rating **	A	Issue No. 35	GPS Lat/Long
Issue Type +	Ma	Location *	39.731810 °
Category	Rivers, Channels & Designated Flood		-121.841870 °
Item	Encroachments		
DWR ID	DWR_NA0060_5_c_2012_35		
Action/Comments			
Inspector Comments: No trash, debris, excavation, structures, or other obstructions present within the project easement area.			

No Photos

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2020

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Big Chico Creek	13.00	07/29/2020 07/29/2020	Brooks Weisser

Check Point / View			
Esplanade / Down			
Rating **	A	Issue No. 31	GPS Lat/Long
Issue Type +	Ma	Location *	39.731810 °
Category	Rivers, Channels & Designated Flood		-121.841870 °
Item	Vegetation & Obstructions		
DWR ID	DWR_NA0060_5_c_2012_31		
Action/Comments			
Inspector Comments: Scattered obstructions and vegetation is minimal. The flow is not impeded.			

Photo 1 of 1 : CH_2020_NA0060_5_31_20200804_00047.jpg



View of the channel facing downstream, 2020.

Rating **	A	Issue No. 37	GPS Lat/Long
Issue Type +	Ma	Location *	39.731810 °
Category	Rivers, Channels & Designated Flood		-121.841870 °
Item	Shoaling / Sedimentation		
DWR ID	DWR_NA0060_5_c_2012_37		
Action/Comments			
Inspector Comments: No shoaling or sedimentation observed.			

No Photos

Rating **	A	Issue No. 38	GPS Lat/Long
Issue Type +	Ma	Location *	39.731810 °
Category	Rivers, Channels & Designated Flood		-121.841870 °
Item	Erosion / Bank Caving		
DWR ID	DWR_NA0060_5_c_2012_38		
Action/Comments			
Inspector Comments: No erosion observed.			

No Photos

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2020

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Big Chico Creek	13.00	07/29/2020 07/29/2020	Brooks Weisser

Check Point / View			
Esplanade / Down (cont)			
Rating **	N	Issue No. 39	GPS Lat/Long
Issue Type +	Ma	Location *	39.731810 °
Category	Rivers, Channels & Designated Flood		-121.841870 °
Item	Revetments		
DWR ID	DWR_NA0060_5_c_2012_39		
Action/Comments			
Inspector Comments: No revetments present.			

No Photos

Rating **	A	Issue No. 40	GPS Lat/Long
Issue Type +	Ma	Location *	39.731810 °
Category	Rivers, Channels & Designated Flood		-121.841870 °
Item	Encroachments		
DWR ID	DWR_NA0060_5_c_2012_40		
Action/Comments			
Inspector Comments: Old bridge footings are within the project easement area, flow is not impeded, 2019.			

Photo 1 of 1 : CH_2020_NA0060_5_40_20200804_00048.jpg



View of old bridge footing in the channel, 2020.

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2020

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Big Chico Creek	13.00	07/29/2020 07/29/2020	Brooks Weisser

Check Point / View			
Hwy 32 / Up			
Rating **	A	Issue No. 41	GPS Lat/Long
Issue Type +	Ma	Location *	39.725776 °
Category	Rivers, Channels & Designated Flood		-121.851207 °
Item	Vegetation & Obstructions		
DWR ID	DWR_NA0060_5_c_2012_41		
Action/Comments			
Inspector Comments: Scattered obstructions and vegetation. The flow is not impeded.			

Photo 1 of 1 : CH_2020_NA0060_5_41_20200804_00049.jpg



View of the channel facing upstream, 2020.

Rating **	A	Issue No. 42	GPS Lat/Long
Issue Type +	Ma	Location *	39.725776 °
Category	Rivers, Channels & Designated Flood		-121.851207 °
Item	Shoaling / Sedimentation		
DWR ID	DWR_NA0060_5_c_2012_42		
Action/Comments			
Inspector Comments: No shoaling or sedimentation observed.			

No Photos

Rating **	A	Issue No. 43	GPS Lat/Long
Issue Type +	Ma	Location *	39.725776 °
Category	Rivers, Channels & Designated Flood		-121.851207 °
Item	Erosion / Bank Caving		
DWR ID	DWR_NA0060_5_c_2012_43		
Action/Comments			
Inspector Comments: No erosion observed.			

No Photos

* Location
LS : Land Side
WS : Water Side
CR : Crown

** Rating
A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type
Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2020

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Big Chico Creek	13.00	07/29/2020 07/29/2020	Brooks Weisser

Check Point / View				
Hwy 32 / Up (cont)				
Rating **	A	Issue No.	44	GPS Lat/Long
Issue Type +	Ma	Location *		39.725776 °
Category	Rivers, Channels & Designated Flood			-121.851207 °
Item	Revetments			
DWR ID	DWR_NA0060_5_c_2012_44			
Action/Comments				
Inspector Comments: Revetments present both sides of channel.				

Photo 1 of 1 : CH_2020_NA0060_5_44_20200804_00050.jpg



View of revetment around piers both right bank and left bank, 2020.

Rating **	M	Issue No.	45	GPS Lat/Long
Issue Type +	Ma	Location *		39.725776 °
Category	Rivers, Channels & Designated Flood			-121.851207 °
Item	Encroachments			
DWR ID	DWR_NA0060_5_c_2012_45			
Action/Comments				
Inspector Comments: Trash, debris from homeless present within the channel easement, 2020				

Photo 1 of 1 : CH_2020_NA0060_5_45_20200804_00051.jpg



View of trash and debris from the homeless living under the bridge, 2020.

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2020

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Big Chico Creek	13.00	07/29/2020 07/29/2020	Brooks Weisser

Check Point / View			
Hwy 32 / Down			
Rating **	M	Issue No. 46	GPS Lat/Long
Issue Type +	Ma	Location *	39.725776 °
Category	Rivers, Channels & Designated Flood		-121.851207 °
Item	Vegetation & Obstructions		
DWR ID	DWR_NA0060_5_c_2012_46		
Action/Comments			
Inspector Comments: Moderate vegetation on banks. The flow may be impeded.			

Photo 1 of 1 : CH_2020_NA0060_5_46_20200804_00052.jpg



View of the channel facing downstream, 2020.

Rating **	A	Issue No. 47	GPS Lat/Long
Issue Type +	Ma	Location *	39.725776 °
Category	Rivers, Channels & Designated Flood		-121.851207 °
Item	Shoaling / Sedimentation		
DWR ID	DWR_NA0060_5_c_2012_47		
Action/Comments			
Inspector Comments: No shoaling or sedimentation observed.			

No Photos

Rating **	A	Issue No. 48	GPS Lat/Long
Issue Type +	Ma	Location *	39.725776 °
Category	Rivers, Channels & Designated Flood		-121.851207 °
Item	Erosion / Bank Caving		
DWR ID	DWR_NA0060_5_c_2012_48		
Action/Comments			
Inspector Comments: No erosion observed.			

No Photos

* Location
LS : Land Side
WS : Water Side
CR : Crown

** Rating
A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type
Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2020

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Big Chico Creek	13.00	07/29/2020 07/29/2020	Brooks Weisser

Check Point / View			
Hwy 32 / Down (cont)			
Rating **	A	Issue No.	49
Issue Type +	Ma	Location *	GPS Lat/Long
Category	Rivers, Channels & Designated Flood		39.725776 °
Item	Revetments		-121.851207 °
DWR ID	DWR_NA0060_5_c_2012_49		
Action/Comments			
Inspector Comments: Revetments present on both sides.			

No Photos

Check Point / View			
Mud Creek at River Rd / Up			
Rating **	A	Issue No.	51
Issue Type +	Ma	Location *	GPS Lat/Long
Category	Rivers, Channels & Designated Flood		39.704580 °
Item	Vegetation & Obstructions		-121.939320 °
DWR ID	DWR_NA0060_5_c_2012_51		
Action/Comments			
Inspector Comments: Minimal scattered obstructions and vegetation. The flow is not impeded.			

Photo 1 of 1 : CH_2020_NA0060_5_51_20200804_00053.jpg



View of Mud Creek at River Road facing upstream, 2020.

Rating **	A	Issue No.	52	GPS Lat/Long
Issue Type +	Ma	Location *		39.704580 °
Category	Rivers, Channels & Designated Flood			-121.939320 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0060_5_c_2012_52			
Action/Comments				
Inspector Comments: No shoaling or sedimentation observed.				

No Photos

* Location
LS : Land Side
WS : Water Side
CR : Crown

** Rating
A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type
Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2020

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Big Chico Creek	13.00	07/29/2020 07/29/2020	Brooks Weisser

Check Point / View			
Mud Creek at River Rd / Up (cont)			
Rating **	A	Issue No. 58	GPS Lat/Long
Issue Type +	Ma	Location *	39.704580 °
Category	Rivers, Channels & Designated Flood		-121.939320 °
Item	Erosion / Bank Caving		
DWR ID	DWR_NA0060_5_c_2012_58		
Action/Comments			
Inspector Comments: No erosion observed.			

No Photos

Rating **	A	Issue No. 54	GPS Lat/Long
Issue Type +	Ma	Location *	39.704580 °
Category	Rivers, Channels & Designated Flood		-121.939320 °
Item	Revetments		
DWR ID	DWR_NA0060_5_c_2012_54		
Action/Comments			
Inspector Comments: Riprap is covered with vegetation. Trees and other vegetation growth should be managed/removed from riprap.			

Photo 1 of 2 : CH_2020_NA0060_5_54_20200804_00054.jpg



View of the revetment left bank that is over grown with vegetation, 2020.

Rating **	A	Issue No. 54 (cont)	GPS Lat/Long
Issue Type +	Ma	Location *	39.704580 °
Category	Rivers, Channels & Designated Flood		-121.939320 °
Item	Revetments		
DWR ID	DWR_NA0060_5_c_2012_54		

Photo 2 of 2 : CH_2020_NA0060_5_54_20200804_00055.jpg



View of the revetment right bank that is over grown with vegetation, 2020.

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2020

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Big Chico Creek	13.00	07/29/2020 07/29/2020	Brooks Weisser

Check Point / View			
Mud Creek at River Rd / Up (cont)			
Rating **	A	Issue No.	55
Issue Type +	Ma	Location *	39.704580 °
Category	Rivers, Channels & Designated Flood		-121.939320 °
Item	Encroachments		
DWR ID	DWR_NA0060_5_c_2012_55		
Action/Comments			
Inspector Comments: No trash, debris, excavation, structures, or other obstructions present within the project easement area.			

No Photos

Check Point / View			
Mud Creek at River Rd / Down			
Rating **	A	Issue No.	56
Issue Type +	Ma	Location *	39.704580 °
Category	Rivers, Channels & Designated Flood		-121.939320 °
Item	Vegetation & Obstructions		
DWR ID	DWR_NA0060_5_c_2012_56		
Action/Comments			
Inspector Comments: No obstructions observed, the flow is not impeded.			

Photo 1 of 1 : CH_2020_NA0060_5_56_20200804_00056.jpg



View looking downstream from the bridge, 2020.

Rating **	A	Issue No.	57	GPS Lat/Long
Issue Type +	Ma	Location *	39.704580 °	
Category	Rivers, Channels & Designated Flood		-121.939320 °	
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0060_5_c_2012_57			
Action/Comments				
Inspector Comments: No shoaling or sedimentation observed.				

No Photos

* Location
LS : Land Side
WS : Water Side
CR : Crown

** Rating
A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type
Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2020

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Big Chico Creek	13.00	07/29/2020 07/29/2020	Brooks Weisser

Check Point / View			
Mud Creek at River Rd / Down (cont)			
Rating **	A	Issue No. 53	GPS Lat/Long
Issue Type +	Ma	Location *	39.704580 °
Category	Rivers, Channels & Designated Flood		-121.939320 °
Item	Erosion / Bank Caving		
DWR ID	DWR_NA0060_5_c_2012_53		
Action/Comments			
Inspector Comments: No erosion observed.			

No Photos

Rating **	A	Issue No. 59	GPS Lat/Long
Issue Type +	Ma	Location *	39.704580 °
Category	Rivers, Channels & Designated Flood		-121.939320 °
Item	Revetments		
DWR ID	DWR_NA0060_5_c_2012_59		
Action/Comments			
Inspector Comments: Some of the riprap is covered with vegetation. Trees and other vegetation growth should be managed/removed from riprap.			

No Photos

Rating **	A	Issue No. 60	GPS Lat/Long
Issue Type +	Ma	Location *	39.704580 °
Category	Rivers, Channels & Designated Flood		-121.939320 °
Item	Encroachments		
DWR ID	DWR_NA0060_5_c_2012_60		
Action/Comments			
Inspector Comments: No trash, debris, excavation, structures, or other obstructions present within the project easement area.			

No Photos

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

Flood Control Project Maintenance

Unit Cover Sheet

2020 Channel Inspection Results

DWR Sutter Maintenance Yard

Channel
Lindo Channel & Sandy Gulch

Channel Rating	A
Date of Inspection	7/30/2020
DWR Inspector	Brooks Weisser
Accompanied By	

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2020

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Lindo Channel & Sandy Gulch	12.00	07/30/2020 07/30/2020	Brooks Weisser

Check Point / View			
Diversion Structure / Up			
Rating **	A	Issue No.	1
Issue Type +	Ma	Location *	GPS Lat/Long
Category	Rivers, Channels & Designated Flood		39.761590 °
Item	Vegetation & Obstructions		-121.797320 °
DWR ID	DWR_NA0060_6_c_2012_1		
Action/Comments			
Inspector Comments: Minimal, scattered obstructions and small trees exists however the flow is not impeded.			

Photo 1 of 1 : CH_2020_NA0060_6_1_20200805_00057.jpg



View of the channel facing upstream, 2020.

Rating **	A	Issue No.	2
Issue Type +	Ma	Location *	GPS Lat/Long
Category	Rivers, Channels & Designated Flood		39.761590 °
Item	Shoaling / Sedimentation		-121.797320 °
DWR ID	DWR_NA0060_6_c_2012_2		
Action/Comments			
Inspector Comments: No shoaling or sedimentation observed.			

No Photos

Rating **	A	Issue No.	3
Issue Type +	Ma	Location *	GPS Lat/Long
Category	Rivers, Channels & Designated Flood		39.761590 °
Item	Erosion / Bank Caving		-121.797320 °
DWR ID	DWR_NA0060_6_c_2012_3		
Action/Comments			
Inspector Comments: No head cutting or horizontal deviation observed.			

No Photos

* Location
LS : Land Side
WS : Water Side
CR : Crown

** Rating
A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type
Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2020

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Lindo Channel & Sandy Gulch	12.00	07/30/2020 07/30/2020	Brooks Weisser

Check Point / View			
Diversion Structure / Up (cont)			
Rating **	N	Issue No. 4	GPS Lat/Long
Issue Type +	Ma	Location *	39.761590 °
Category	Rivers, Channels & Designated Flood		-121.797320 °
Item	Revetments		
DWR ID	DWR_NA0060_6_c_2012_4		
Action/Comments			
Inspector Comments: No revetment at the upstream of the structure.			

No Photos

Rating **	A	Issue No. 5	GPS Lat/Long
Issue Type +	Ma	Location *	39.761590 °
Category	Rivers, Channels & Designated Flood		-121.797320 °
Item	Encroachments		
DWR ID	DWR_NA0060_6_c_2012_5		
Action/Comments			
Inspector Comments: No trash, debris, excavation, structures, or other obstructions present within the project easement area.			

No Photos

Check Point / View			
Diversion Structure / Down			
Rating **	A	Issue No. 6	GPS Lat/Long
Issue Type +	Ma	Location *	39.761590 °
Category	Rivers, Channels & Designated Flood		-121.797320 °
Item	Vegetation & Obstructions		
DWR ID	DWR_NA0060_6_c_2012_6		
Action/Comments			
Inspector Comments: Minimal, scattered obstructions or vegetation exists however the flow is not impeded.			

Photo 1 of 1 : CH_2020_NA0060_6_6_20200805_00058.jpg



View of the channel facing downstream, 2020.

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2020

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Lindo Channel & Sandy Gulch	12.00	07/30/2020 07/30/2020	Brooks Weisser

Check Point / View			
Diversion Structure / Down (cont)			
Rating **	A	Issue No. 7	GPS Lat/Long
Issue Type +	Ma	Location *	39.761590 °
Category	Rivers, Channels & Designated Flood		-121.797320 °
Item	Shoaling / Sedimentation		
DWR ID	DWR_NA0060_6_c_2012_7		
Action/Comments			
Inspector Comments: No shoaling or sedimentation observed.			

No Photos

Rating **	A	Issue No. 8	GPS Lat/Long
Issue Type +	Ma	Location *	39.761590 °
Category	Rivers, Channels & Designated Flood		-121.797320 °
Item	Erosion / Bank Caving		
DWR ID	DWR_NA0060_6_c_2012_8		
Action/Comments			
Inspector Comments: No head cutting or horizontal deviation observed.			

No Photos

Rating **	A	Issue No. 9	GPS Lat/Long
Issue Type +	Ma	Location *	39.761590 °
Category	Rivers, Channels & Designated Flood		-121.797320 °
Item	Revetments		
DWR ID	DWR_NA0060_6_c_2012_9		
Action/Comments			
Inspector Comments: Revetment observed at this location is intact, clearly visible, and well maintained.			

Photo 1 of 2 : CH_2020_NA0060_6_9_20200805_00060.jpg



View of revetment downstream of structure, right bank, 2020.

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2020

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Lindo Channel & Sandy Gulch	12.00	07/30/2020 07/30/2020	Brooks Weisser

Check Point / View			
Diversion Structure / Down (cont)			
Rating **	A	Issue No.	9 (cont)
Issue Type +	Ma	Location *	GPS Lat/Long
Category	Rivers, Channels & Designated Flood		39.761590 °
Item	Revetments		-121.797320 °
DWR ID	DWR_NA0060_6_c_2012_9		
Action/Comments			
Inspector Comments: Revetment observed at this location is intact, clearly visible, and well maintained.			

Photo 2 of 2 : CH_2020_NA0060_6_9_20200805_00059.jpg



View of revetment downstream of structure, left bank, 2020.

Rating **	A	Issue No.	10	GPS Lat/Long
Issue Type +	Ma	Location *		39.761590 °
Category	Rivers, Channels & Designated Flood			-121.797320 °
Item	Encroachments			
DWR ID	DWR_NA0060_6_c_2012_10			
Action/Comments				
Inspector Comments: No trash, debris, excavation, structures, or other obstructions present within the project easement area.				

No Photos

* Location
LS : Land Side
WS : Water Side
CR : Crown

** Rating
A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type
Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2020

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Lindo Channel & Sandy Gulch	12.00	07/30/2020 07/30/2020	Brooks Weisser

Check Point / View				
Manzanita Ave / Up				
Rating **	A	Issue No.	11	GPS Lat/Long
Issue Type +	Ma	Location *		39.760390 °
Category	Rivers, Channels & Designated Flood			-121.801621 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0060_6_c_2012_11			
Action/Comments				
Inspector Comments: Minimal, scattered obstructions or vegetation exists however the flow is not impeded.				

Photo 1 of 1 : CH_2020_NA0060_6_11_20200805_00061.jpg



View of the channel facing upstream, 2020.

Rating **	A	Issue No.	12	GPS Lat/Long
Issue Type +	Ma	Location *		39.760390 °
Category	Rivers, Channels & Designated Flood			-121.801621 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0060_6_c_2012_12			
Action/Comments				
Inspector Comments: Minimal shoaling or sedimentation observed.				

No Photos

Rating **	A	Issue No.	13	GPS Lat/Long
Issue Type +	Ma	Location *		39.760390 °
Category	Rivers, Channels & Designated Flood			-121.801621 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0060_6_c_2012_13			
Action/Comments				
Inspector Comments: No head cutting or horizontal deviation observed.				

No Photos

* Location
LS : Land Side
WS : Water Side
CR : Crown

** Rating
A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type
Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2020

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Lindo Channel & Sandy Gulch	12.00	07/30/2020 07/30/2020	Brooks Weisser

Check Point / View			
Manzanita Ave / Up (cont)			
Rating **	A	Issue No.	14
Issue Type +	Ma	Location *	39.760390 °
Category	Rivers, Channels & Designated Flood		-121.801621 °
Item	Revetments		
DWR ID	DWR_NA0060_6_c_2012_14		
Action/Comments			
Inspector Comments: Revetment under bridge, both right and left abutments.			

Photo 1 of 1 : CH_2020_NA0060_6_14_20200805_00064.jpg



View of revetment on both banks of bridge abutment, 2020.

Rating **	A	Issue No.	15
Issue Type +	Ma	Location *	39.760390 °
Category	Rivers, Channels & Designated Flood		-121.801621 °
Item	Encroachments		
DWR ID	DWR_NA0060_6_c_2012_15		
Action/Comments			
Inspector Comments: No trash, debris, excavation, structures, or other obstructions present within the project easement area.			

No Photos

* Location
LS : Land Side
WS : Water Side
CR : Crown

** Rating
A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type
Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2020

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Lindo Channel & Sandy Gulch	12.00	07/30/2020 07/30/2020	Brooks Weisser

Check Point / View			
Manzanita Ave / Down			
Rating **	M	Issue No. 16	GPS Lat/Long
Issue Type +	Ma	Location *	39.760390 °
Category	Rivers, Channels & Designated Flood		-121.801621 °
Item	Vegetation & Obstructions		
DWR ID	DWR_NA0060_6_c_2012_16		
Action/Comments			
Inspector Comments: Minimal, scattered obstructions or vegetation exists and the flow could be impeded.			

Photo 1 of 1 : CH_2020_NA0060_6_16_20200805_00063.jpg



View of the channel facing downstream, 2020.

Rating **	A	Issue No. 17	GPS Lat/Long
Issue Type +	Ma	Location *	39.760390 °
Category	Rivers, Channels & Designated Flood		-121.801621 °
Item	Shoaling / Sedimentation		
DWR ID	DWR_NA0060_6_c_2012_17		
Action/Comments			
Inspector Comments: No shoaling or sedimentation observed.			

No Photos

Rating **	A	Issue No. 18	GPS Lat/Long
Issue Type +	Ma	Location *	39.760390 °
Category	Rivers, Channels & Designated Flood		-121.801621 °
Item	Erosion / Bank Caving		
DWR ID	DWR_NA0060_6_c_2012_18		
Action/Comments			
Inspector Comments: No head cutting or horizontal deviation observed.			

No Photos

* Location
LS : Land Side
WS : Water Side
CR : Crown

** Rating
A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type
Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2020

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Lindo Channel & Sandy Gulch	12.00	07/30/2020 07/30/2020	Brooks Weisser

Check Point / View			
Manzanita Ave / Down (cont)			
Rating **	A	Issue No. 19	GPS Lat/Long
Issue Type +	Ma	Location *	39.760390 °
Category	Rivers, Channels & Designated Flood		-121.801621 °
Item	Revetments		
DWR ID	DWR_NA0060_6_c_2012_19		
Action/Comments			
Inspector Comments: Revetment under bridge, both right and left abutments.			

No Photos

Rating **	A	Issue No. 20	GPS Lat/Long
Issue Type +	Ma	Location *	39.760390 °
Category	Rivers, Channels & Designated Flood		-121.801621 °
Item	Encroachments		
DWR ID	DWR_NA0060_6_c_2012_20		
Action/Comments			
Inspector Comments: No trash, debris, excavation, structures, or other obstructions present within the project easement area.			

No Photos

Check Point / View			
Bike Path Bridge at Madrone Ave / Up			
Rating **	A	Issue No. 21	GPS Lat/Long
Issue Type +	Ma	Location *	39.755400 °
Category	Rivers, Channels & Designated Flood		-121.814580 °
Item	Vegetation & Obstructions		
DWR ID	DWR_NA0060_6_c_2012_21		
Action/Comments			
Inspector Comments: Minimal, scattered obstructions or vegetation exists however the flow is not impeded.			

Photo 1 of 1 : CH_2020_NA0060_6_21_20200805_00065.jpg



View of the channel facing upstream from the bridge, 2020.

* Location
LS : Land Side
WS : Water Side
CR : Crown

** Rating	
A : Acceptable	N : Not Inspected/Rated
M : Minimally Acceptable	C : Corrected
U : Unacceptable	A/W : Acceptable but Monitor & Maintain

+ Issue Type
Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2020

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Lindo Channel & Sandy Gulch	12.00	07/30/2020 07/30/2020	Brooks Weisser

Check Point / View			
Bike Path Bridge at Madrone Ave / Up (cont)			
Rating **	A	Issue No.	22
Issue Type +	Ma	Location *	
Category	Rivers, Channels & Designated Flood		GPS Lat/Long
Item	Shoaling / Sedimentation		
DWR ID	DWR_NA0060_6_c_2012_22		
Action/Comments			
Inspector Comments: Minimal shoaling or sedimentation observed.			

No Photos

Rating **	A	Issue No.	23
Issue Type +	Ma	Location *	
Category	Rivers, Channels & Designated Flood		GPS Lat/Long
Item	Erosion / Bank Caving		
DWR ID	DWR_NA0060_6_c_2012_23		
Action/Comments			
Inspector Comments: No head cutting or horizontal deviation observed.			

No Photos

Rating **	M	Issue No.	24
Issue Type +	Ma	Location *	
Category	Rivers, Channels & Designated Flood		GPS Lat/Long
Item	Revetments		
DWR ID	DWR_NA0060_6_c_2012_24		
Action/Comments			
Inspector Comments: Riprap at the foot of the bridge seems to have slid down towards the channel in previous high water events, but the capacity of the channel is not affected.			

Photo 1 of 2 : CH_2020_NA0060_6_24_20200805_00066.jpg



View looking at the left bank abutment very little revetment remaining, 2020.

<p>* Location</p> <p>LS : Land Side WS : Water Side CR : Crown</p>	<p>** Rating</p> <p>A : Acceptable M : Minimally Acceptable U : Unacceptable</p>	<p>N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain</p>	<p>+ Issue Type</p> <p>Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement</p>
---	---	--	--

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2020

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Lindo Channel & Sandy Gulch	12.00	07/30/2020 07/30/2020	Brooks Weisser

Check Point / View				
Bike Path Bridge at Madrone Ave / Up (cont)				
Rating **	M	Issue No.	24 (cont)	GPS Lat/Long
Issue Type +	Ma	Location *		39.755400 °
Category	Rivers, Channels & Designated Flood			-121.814580 °
Item	Revetments			
DWR ID	DWR_NA0060_6_c_2012_24			
Action/Comments				
Inspector Comments: Riprap at the foot of the bridge seems to have slid down towards the channel in previous high water events, but the capacity of the channel is not affected.				

Photo 2 of 2 : CH_2020_NA0060_6_24_20200805_00067.jpg



View looking at the left bank abutment very little revetment remaining, 2020.

Check Point / View				
Rating **	A	Issue No.	25	GPS Lat/Long
Issue Type +	Ma	Location *		39.755400 °
Category	Rivers, Channels & Designated Flood			-121.814580 °
Item	Encroachments			
DWR ID	DWR_NA0060_6_c_2012_25			
Action/Comments				
Inspector Comments: No trash, debris, excavation, structures, or other obstructions present within the project easement area.				

No Photos

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2020

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Lindo Channel & Sandy Gulch	12.00	07/30/2020 07/30/2020	Brooks Weisser

Check Point / View			
Bike Path Bridge at Madrone Ave / Down			
Rating **	A	Issue No.	26
			GPS Lat/Long
Issue Type +	Ma	Location *	39.755400 °
Category	Rivers, Channels & Designated Flood		-121.814580 °
Item	Vegetation & Obstructions		
DWR ID	DWR_NA0060_6_c_2012_26		
Action/Comments			
Inspector Comments: Minimal, scattered obstructions or vegetation exists however the flow is not impeded.			

Photo 1 of 1 : CH_2020_NA0060_6_26_20200805_00068.jpg



View of the channel facing downstream from the bridge, 2020.

Rating **	A	Issue No.	27
			GPS Lat/Long
Issue Type +	Ma	Location *	39.755400 °
Category	Rivers, Channels & Designated Flood		-121.814580 °
Item	Shoaling / Sedimentation		
DWR ID	DWR_NA0060_6_c_2012_27		
Action/Comments			
Inspector Comments: No shoaling or sedimentation observed.			

No Photos

Rating **	A	Issue No.	28
			GPS Lat/Long
Issue Type +	Ma	Location *	39.755400 °
Category	Rivers, Channels & Designated Flood		-121.814580 °
Item	Erosion / Bank Caving		
DWR ID	DWR_NA0060_6_c_2012_28		
Action/Comments			
Inspector Comments: There is some minor bank erosion.			

No Photos

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2020

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Lindo Channel & Sandy Gulch	12.00	07/30/2020 07/30/2020	Brooks Weisser

Check Point / View			
Bike Path Bridge at Madrone Ave / Down (cont)			
Rating **	N	Issue No.	29
			GPS Lat/Long
Issue Type +	Ma	Location *	39.755400 °
Category	Rivers, Channels & Designated Flood		-121.814580 °
Item	Revetments		
DWR ID	DWR_NA0060_6_c_2012_29		
Action/Comments			

No Photos

Rating **	A	Issue No.	30	GPS Lat/Long
Issue Type +	Ma	Location *		39.755400 °
Category	Rivers, Channels & Designated Flood			-121.814580 °
Item	Encroachments			
DWR ID	DWR_NA0060_6_c_2012_30			
Action/Comments				
Inspector Comments: No Trash, debris, excavation, structures, or other obstructions present within the project easement area.				

No Photos

Check Point / View			
Mariposa Ave / Up			
Rating **	A	Issue No.	31
			GPS Lat/Long
Issue Type +	Ma	Location *	39.752730 °
Category	Rivers, Channels & Designated Flood		-121.824560 °
Item	Vegetation & Obstructions		
DWR ID	DWR_NA0060_6_c_2012_31		
Action/Comments			
Inspector Comments: Minimal, scattered log obstructions exists however the flow is not impeded.			

Photo 1 of 1 : CH_2020_NA0060_6_31_20200805_00069.jpg



View of the channel facing upstream from the bridge, 2020.

*** Location**
LS : Land Side
WS : Water Side
CR : Crown

**** Rating**
A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type
Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2020

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Lindo Channel & Sandy Gulch	12.00	07/30/2020 07/30/2020	Brooks Weisser

Check Point / View			
Mariposa Ave / Up (cont)			
Rating **	A	Issue No. 32	GPS Lat/Long
Issue Type +	Ma	Location *	39.752730 °
Category	Rivers, Channels & Designated Flood		-121.824560 °
Item	Shoaling / Sedimentation		
DWR ID	DWR_NA0060_6_c_2012_32		
Action/Comments			
Inspector Comments: Minimal shoaling or sedimentation observed.			

No Photos

Rating **	A	Issue No. 33	GPS Lat/Long
Issue Type +	Ma	Location *	39.752730 °
Category	Rivers, Channels & Designated Flood		-121.824560 °
Item	Erosion / Bank Caving		
DWR ID	DWR_NA0060_6_c_2012_33		
Action/Comments			
Inspector Comments: No head cutting or horizontal deviation observed.			

No Photos

Rating **	A	Issue No. 34	GPS Lat/Long
Issue Type +	Ma	Location *	39.752730 °
Category	Rivers, Channels & Designated Flood		-121.824560 °
Item	Revetments		
DWR ID	DWR_NA0060_6_c_2012_34		
Action/Comments			
Inspector Comments: Revetment on slope up to the bridge abutment, both sides.			

Photo 1 of 2 : CH_2020_NA0060_6_34_20200805_00070.jpg



View of right bank, revetment on slope up to the bridge abutment, 2020.

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2020

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Lindo Channel & Sandy Gulch	12.00	07/30/2020 07/30/2020	Brooks Weisser

Check Point / View			
Mariposa Ave / Up (cont)			
Rating **	A	Issue No. 34 (cont)	GPS Lat/Long
Issue Type +	Ma	Location *	39.752730 °
Category	Rivers, Channels & Designated Flood		-121.824560 °
Item	Revetments		
DWR ID	DWR_NA0060_6_c_2012_34		
Action/Comments			
Inspector Comments: Revetment on slope up to the bridge abutment, both sides.			

Photo 2 of 2 : CH_2020_NA0060_6_34_20200805_00071.jpg



View of left bank, revetment on slope up to the bridge abutment, 2020.

Check Point / View			
Rating **	M	Issue No. 35	GPS Lat/Long
Issue Type +	Ma	Location *	39.752730 °
Category	Rivers, Channels & Designated Flood		-121.824560 °
Item	Encroachments		
DWR ID	DWR_NA0060_6_c_2012_35		
Action/Comments			
Inspector Comments: Debris and trash from campers within the project easement area needs to be removed, 2020.			

Photo 1 of 5 : CH_2020_NA0060_6_35_20200805_00072.jpg



Debris and trash from campers within the project easement area needs to be removed, 2020.

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2020

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Lindo Channel & Sandy Gulch	12.00	07/30/2020 07/30/2020	Brooks Weisser

Check Point / View			
Mariposa Ave / Up (cont)			
Rating **	M	Issue No.	35 (cont)
Issue Type +	Ma	Location *	GPS Lat/Long
Category	Rivers, Channels & Designated Flood		39.752730 °
Item	Encroachments		-121.824560 °
DWR ID	DWR_NA0060_6_c_2012_35		
Action/Comments			
Inspector Comments: Debris and trash from campers within the project easement area needs to be removed, 2020.			

Photo 2 of 5 : CH_2020_NA0060_6_35_20200805_00074.jpg



Debris and trash from campers within the project easement area needs to be removed, 2020.

Rating **	M	Issue No.	35 (cont)	GPS Lat/Long
Issue Type +	Ma	Location *		39.752730 °
Category	Rivers, Channels & Designated Flood			-121.824560 °
Item	Encroachments			
DWR ID	DWR_NA0060_6_c_2012_35			

Photo 3 of 5 : CH_2020_NA0060_6_35_20200805_00075.jpg



Debris and trash from campers within the project easement area needs to be removed, 2020.

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2020

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Lindo Channel & Sandy Gulch	12.00	07/30/2020 07/30/2020	Brooks Weisser

Check Point / View			
Mariposa Ave / Up (cont)			
Rating **	M	Issue No.	35 (cont)
Issue Type +	Ma	Location *	GPS Lat/Long
Category	Rivers, Channels & Designated Flood		39.752730 °
Item	Encroachments		-121.824560 °
DWR ID	DWR_NA0060_6_c_2012_35		
Action/Comments			
Inspector Comments: Debris and trash from campers within the project easement area needs to be removed, 2020.			

Photo 4 of 5 : CH_2020_NA0060_6_35_20200805_00073.jpg



Debris and trash from campers within the project easement area needs to be removed, 2020.

Rating **	M	Issue No.	35 (cont)	GPS Lat/Long
Issue Type +	Ma	Location *		39.752730 °
Category	Rivers, Channels & Designated Flood			-121.824560 °
Item	Encroachments			
DWR ID	DWR_NA0060_6_c_2012_35			

Photo 5 of 5 : CH_2020_NA0060_6_35_20200805_00076.jpg



Debris and trash from campers within the project easement area needs to be removed, 2020.

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2020

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Lindo Channel & Sandy Gulch	12.00	07/30/2020 07/30/2020	Brooks Weisser

Check Point / View

Mariposa Ave / Down

Rating **	A	Issue No.	36	GPS Lat/Long
Issue Type +	Ma	Location *		39.752730 °
Category	Rivers, Channels & Designated Flood			-121.824560 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0060_6_c_2012_36			
Action/Comments				
Inspector Comments: Minimal, scattered obstructions or vegetation exists however the flow is not impeded.				

Photo 1 of 1 : CH_2020_NA0060_6_36_20200805_00077.jpg



View of the channel facing downstream from the bridge, 2020.

Rating **	A	Issue No.	37	GPS Lat/Long
Issue Type +	Ma	Location *		39.752730 °
Category	Rivers, Channels & Designated Flood			-121.824560 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0060_6_c_2012_37			
Action/Comments				
Inspector Comments: Minimal shoaling or sedimentation observed, but the flow is not impeded.				

No Photos

Rating **	A	Issue No.	38	GPS Lat/Long
Issue Type +	Ma	Location *		39.752730 °
Category	Rivers, Channels & Designated Flood			-121.824560 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0060_6_c_2012_38			
Action/Comments				
Inspector Comments: No head cutting or horizontal deviation observed.				

No Photos

* Location
LS : Land Side
WS : Water Side
CR : Crown

** Rating
A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type
Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2020

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Lindo Channel & Sandy Gulch	12.00	07/30/2020 07/30/2020	Brooks Weisser

Check Point / View			
Mariposa Ave / Down (cont)			
Rating **	A	Issue No. 39	GPS Lat/Long
Issue Type +	Ma	Location *	39.752730 °
Category	Rivers, Channels & Designated Flood		-121.824560 °
Item	Revetments		
DWR ID	DWR_NA0060_6_c_2012_39		
Action/Comments			
Inspector Comments: Revetment on slope up to the bridge abutment, both sides.			

No Photos

Rating **	A	Issue No. 40	GPS Lat/Long
Issue Type +	Ma	Location *	39.752730 °
Category	Rivers, Channels & Designated Flood		-121.824560 °
Item	Encroachments		
DWR ID	DWR_NA0060_6_c_2012_40		
Action/Comments			
Inspector Comments: No trash, debris, excavation, structures, or other obstructions present within the project easement area.			

No Photos

Check Point / View			
5th Ave / Up			
Rating **	A	Issue No. 41	GPS Lat/Long
Issue Type +	Ma	Location *	39.753307 °
Category	Rivers, Channels & Designated Flood		-121.829234 °
Item	Vegetation & Obstructions		
DWR ID	DWR_NA0060_6_c_2012_41		
Action/Comments			
Inspector Comments: Minimal, scattered obstructions or vegetation exists however the flow is not impeded.			

Photo 1 of 1 : CH_2020_NA0060_6_41_20200805_00078.jpg



View of the channel facing upstream from the bridge, 2020.

* Location
LS : Land Side
WS : Water Side
CR : Crown

** Rating	
A : Acceptable	N : Not Inspected/Rated
M : Minimally Acceptable	C : Corrected
U : Unacceptable	A/W : Acceptable but Monitor & Maintain

+ Issue Type
Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2020

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Lindo Channel & Sandy Gulch	12.00	07/30/2020 07/30/2020	Brooks Weisser

Check Point / View			
5th Ave / Up (cont)			
Rating **	A	Issue No. 42	GPS Lat/Long
Issue Type +	Ma	Location *	39.753307 °
Category	Rivers, Channels & Designated Flood		-121.829234 °
Item	Shoaling / Sedimentation		
DWR ID	DWR_NA0060_6_c_2012_42		
Action/Comments			
Inspector Comments: Minimal shoaling or sedimentation observed, but doesn't impede the flow of the channel.			

No Photos

Rating **	A	Issue No. 43	GPS Lat/Long
Issue Type +	Ma	Location *	39.753307 °
Category	Rivers, Channels & Designated Flood		-121.829234 °
Item	Erosion / Bank Caving		
DWR ID	DWR_NA0060_6_c_2012_43		
Action/Comments			
Inspector Comments: No erosion present on the upstream end.			

No Photos

Rating **	A	Issue No. 44	GPS Lat/Long
Issue Type +	Ma	Location *	39.753307 °
Category	Rivers, Channels & Designated Flood		-121.829234 °
Item	Revetments		
DWR ID	DWR_NA0060_6_c_2012_44		
Action/Comments			
Inspector Comments: Existing riprap protecting is properly maintained and is undamaged. There is erosion at the toe on left bank abutment.			

Photo 1 of 2 : CH_2020_NA0060_6_44_20200805_00079.jpg



View of right bank, revetment on slope up to the bridge abutment, 2020.

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2020

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Lindo Channel & Sandy Gulch	12.00	07/30/2020 07/30/2020	Brooks Weisser

Check Point / View			
5th Ave / Up (cont)			
Rating **	A	Issue No.	44 (cont)
Issue Type +	Ma	Location *	
Category	Rivers, Channels & Designated Flood		GPS Lat/Long
Item	Revetments		
DWR ID	DWR_NA0060_6_c_2012_44		
Action/Comments			
Inspector Comments: Existing riprap protecting is properly maintained and is undamaged. There is erosion at the toe on left bank abutment.			

Photo 2 of 2 : CH_2020_NA0060_6_44_20200805_00080.jpg



View of left bank, revetment on slope up to the bridge abutment, 2020.

Rating **	A	Issue No.	45
Issue Type +	Ma	Location *	
Category	Rivers, Channels & Designated Flood		GPS Lat/Long
Item	Encroachments		
DWR ID	DWR_NA0060_6_c_2012_45		
Action/Comments			
Inspector Comments: No trash, debris, excavation, structures, or other obstructions present within the project easement area.			

No Photos

* Location
LS : Land Side
WS : Water Side
CR : Crown

** Rating
A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type
Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**


Levee Inspection Report By Mile - Channel 2020

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Lindo Channel & Sandy Gulch	12.00	07/30/2020 07/30/2020	Brooks Weisser

Check Point / View			
5th Ave / Down			
Rating **	A	Issue No.	46
Issue Type +	Ma	Location *	39.753307 °
Category	Rivers, Channels & Designated Flood		-121.829234 °
Item	Vegetation & Obstructions		
DWR ID	DWR_NA0060_6_c_2012_46		
Action/Comments			
Inspector Comments: Minimal, scattered obstructions or vegetation exists however the flow is not impeded.			

Photo 1 of 1 : CH_2020_NA0060_6_46_20200805_00081.jpg



View of channel facing downstream from the bridge, 2020.

Rating **	A	Issue No.	47
Issue Type +	Ma	Location *	39.753307 °
Category	Rivers, Channels & Designated Flood		-121.829234 °
Item	Shoaling / Sedimentation		
DWR ID	DWR_NA0060_6_c_2012_47		
Action/Comments			
Inspector Comments: Minimal shoaling or sedimentation present, but the flow is not impeded.			

No Photos

Rating **	M	Issue No.	48
Issue Type +	Ma	Location *	39.753307 °
Category	Rivers, Channels & Designated Flood		-121.829234 °
Item	Erosion / Bank Caving		
DWR ID	DWR_NA0060_6_c_2012_48		
Action/Comments			
Inspector Comments: There is erosion around bridge footing and south bank of channel.			

Photo 1 of 1 : CH_2020_NA0060_6_48_20200805_00082.jpg



View of the erosion found under the bridge south end left bank, 2020.

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2020

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Lindo Channel & Sandy Gulch	12.00	07/30/2020 07/30/2020	Brooks Weisser

Check Point / View			
5th Ave / Down (cont)			
Rating **	A	Issue No.	49
Issue Type +	Ma	Location *	
Category	Rivers, Channels & Designated Flood		GPS Lat/Long
Item	Revetments		
DWR ID	DWR_NA0060_6_c_2012_49		
Action/Comments			
Inspector Comments: Existing riprap protection is properly maintained and is undamaged. Riprap clearly visible.			

No Photos

Rating **	A	Issue No.	50
Issue Type +	Ma	Location *	
Category	Rivers, Channels & Designated Flood		GPS Lat/Long
Item	Encroachments		
DWR ID	DWR_NA0060_6_c_2012_50		
Action/Comments			
Inspector Comments: No trash, debris, excavation, structures, or other obstructions present within the project easement area.			

No Photos

Check Point / View			
Highway 99 / Up			
Rating **	A	Issue No.	91
Issue Type +	Ma	Location *	
Category	Rivers, Channels & Designated Flood		GPS Lat/Long
Item	Vegetation & Obstructions		
DWR ID	DWR_NA0060_6_c_2015_91		
Action/Comments			
Inspector Comments: Minimal, scattered obstructions or vegetation exists however the flow is not impeded.			

Photo 1 of 1 : CH_2020_NA0060_6_91_20200805_00083.jpg



View of the channel facing upstream from the channel, 2020.

*** Location**
LS : Land Side
WS : Water Side
CR : Crown

**** Rating**
A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type
Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2020

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Lindo Channel & Sandy Gulch	12.00	07/30/2020 07/30/2020	Brooks Weisser

Check Point / View			
Highway 99 / Up (cont)			
Rating **	A	Issue No.	92
Issue Type +	Ma	Location *	39.751220 °
Category	Rivers, Channels & Designated Flood		-121.840042 °
Item	Shoaling / Sedimentation		
DWR ID	DWR_NA0060_6_c_2015_92		
Action/Comments			
Inspector Comments: No shoaling or sedimentation observed.			

No Photos

Rating **	A	Issue No.	93
Issue Type +	Ma	Location *	39.751220 °
Category	Rivers, Channels & Designated Flood		-121.840042 °
Item	Erosion / Bank Caving		
DWR ID	DWR_NA0060_6_c_2015_93		
Action/Comments			
Inspector Comments: No head cutting or horizontal deviation observed.			

No Photos

Rating **	A	Issue No.	99
Issue Type +	Ma	Location *	39.751220 °
Category	Rivers, Channels & Designated Flood		-121.840042 °
Item	Revetments		
DWR ID	DWR_NA0060_6_c_2015_99		
Action/Comments			
Inspector Comments: Existing riprap protection is properly maintained and is undamaged. Riprap clearly visible both sides.			

Photo 1 of 1 : CH_2020_NA0060_6_99_20200805_00085.jpg



View of right bank revetment looking upstream on slope up to the bridge abutment, 2020.

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2020

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Lindo Channel & Sandy Gulch	12.00	07/30/2020 07/30/2020	Brooks Weisser

Check Point / View			
Highway 99 / Up (cont)			
Rating **	M	Issue No. 95	GPS Lat/Long
Issue Type +	Ma	Location *	39.751220 °
Category	Rivers, Channels & Designated Flood		-121.840042 °
Item	Encroachments		
DWR ID	DWR_NA0060_6_c_2015_95		
Action/Comments			
Inspector Comments: Growth observed near a bridge pier near the left bank should be removed, 2020.			

Photo 1 of 1 : CH_2020_NA0060_6_95_20200805_00086.jpg



View of a tree growing near a bridge pier near the left bank, 2020.

Check Point / View			
Highway 99 / Down			
Rating **	A	Issue No. 96	GPS Lat/Long
Issue Type +	Ma	Location *	39.751220 °
Category	Rivers, Channels & Designated Flood		-121.840042 °
Item	Vegetation & Obstructions		
DWR ID	DWR_NA0060_6_c_2015_96		
Action/Comments			
Inspector Comments: Minimal, scattered obstructions or vegetation exists however the flow is not impeded.			

Photo 1 of 1 : CH_2020_NA0060_6_96_20200805_00087.jpg



View of the channel facing downstream from under the north bound lanes of Highway 99, 2020.

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2020

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Lindo Channel & Sandy Gulch	12.00	07/30/2020 07/30/2020	Brooks Weisser

Check Point / View			
Highway 99 / Down (cont)			
Rating **	A	Issue No. 97	GPS Lat/Long
Issue Type +	Ma	Location *	39.751220 °
Category	Rivers, Channels & Designated Flood		-121.840042 °
Item	Shoaling / Sedimentation		
DWR ID	DWR_NA0060_6_c_2015_97		
Action/Comments			
Inspector Comments: No shoaling or sedimentation observed.			

No Photos

Rating **	A	Issue No. 98	GPS Lat/Long
Issue Type +	Ma	Location *	39.751220 °
Category	Rivers, Channels & Designated Flood		-121.840042 °
Item	Erosion / Bank Caving		
DWR ID	DWR_NA0060_6_c_2015_98		
Action/Comments			
Inspector Comments: No head cutting or horizontal deviation observed.			

No Photos

Rating **	A	Issue No. 94	GPS Lat/Long
Issue Type +	Ma	Location *	39.751220 °
Category	Rivers, Channels & Designated Flood		-121.840042 °
Item	Revetments		
DWR ID	DWR_NA0060_6_c_2015_94		
Action/Comments			
Inspector Comments: Existing riprap protection is properly maintained and is undamaged. Riprap clearly visible.			

No Photos

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2020

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Lindo Channel & Sandy Gulch	12.00	07/30/2020 07/30/2020	Brooks Weisser

Check Point / View			
Highway 99 / Down (cont)			
Rating **	A	Issue No.	100
Issue Type +	Ma	Location *	GPS Lat/Long
Category	Rivers, Channels & Designated Flood		39.751220 °
Item	Encroachments		-121.840042 °
DWR ID	DWR_NA0060_6_c_2015_100		
Action/Comments			
Inspector Comments: No trash, debris, excavation, structures, or other obstructions present within the project easement area.			

No Photos

Check Point / View			
Mangrove Avenue / Up			
Rating **	A	Issue No.	111
Issue Type +	Ma	Location *	GPS Lat/Long
Category	Rivers, Channels & Designated Flood		39.750979 °
Item	Vegetation & Obstructions		-121.844711 °
DWR ID	DWR_NA0060_6_c_2015_111		
Action/Comments			
Inspector Comments: Minimal, scattered obstructions or vegetation exists however the flow is not impeded.			

Photo 1 of 1 : CH_2020_NA0060_6_111_20200805_00088.jpg



View of the channel looking upstream, 2020.

Rating **	A	Issue No.	112	GPS Lat/Long
Issue Type +	Ma	Location *		39.750979 °
Category	Rivers, Channels & Designated Flood			-121.844711 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0060_6_c_2015_112			
Action/Comments				
Inspector Comments: No shoaling or sedimentation observed.				

No Photos

* Location
LS : Land Side
WS : Water Side
CR : Crown

** Rating
A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type
Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2020

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Lindo Channel & Sandy Gulch	12.00	07/30/2020 07/30/2020	Brooks Weisser

Check Point / View				
Mangrove Avenue / Up (cont)				
Rating **	M	Issue No.	113	GPS Lat/Long
Issue Type +	Ma	Location *		39.750979 °
Category	Rivers, Channels & Designated Flood			-121.844711 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0060_6_c_2015_113			
Action/Comments				
Inspector Comments: Moinor erosion observed on the left bank under the bridge, 2020.				

Photo 1 of 1 : CH_2020_NA0060_6_113_20200805_00090.jpg



View of erosion on the left bank looking downstream, 2020.

Rating **	N	Issue No.	114	GPS Lat/Long
Issue Type +	Ma	Location *		39.750979 °
Category	Rivers, Channels & Designated Flood			-121.844711 °
Item	Revetments			
DWR ID	DWR_NA0060_6_c_2015_114			
Action/Comments				
Inspector Comments: No visible revetment observed.				

Photo 1 of 1 : CH_2020_NA0060_6_114_20200805_00089.jpg



View looking downstream at the right bank abutment, no revetment observed, 2020.

Rating **	A	Issue No.	115	GPS Lat/Long
Issue Type +	Ma	Location *		39.750979 °
Category	Rivers, Channels & Designated Flood			-121.844711 °
Item	Encroachments			
DWR ID	DWR_NA0060_6_c_2015_115			
Action/Comments				
Inspector Comments: No trash, debris, excavation, structures, or other obstructions present within the project easement area.				

No Photos

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2020

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Lindo Channel & Sandy Gulch	12.00	07/30/2020 07/30/2020	Brooks Weisser

Check Point / View			
Mangrove Avenue / Down			
Rating **	M	Issue No.	116
			GPS Lat/Long
Issue Type +	Ma	Location *	39.750979 °
Category	Rivers, Channels & Designated Flood		-121.844711 °
Item	Vegetation & Obstructions		
DWR ID	DWR_NA0060_6_c_2015_116		
Action/Comments			
Inspector Comments: Minimal, scattered obstructions and vegetation exists which may impede the flow of the channel.			

Photo 1 of 1 : CH_2020_NA0060_6_116_20200805_00092.jpg



View of the channel facing downstream, 2020.

Rating **	A	Issue No.	117
			GPS Lat/Long
Issue Type +	Ma	Location *	39.750979 °
Category	Rivers, Channels & Designated Flood		-121.844711 °
Item	Shoaling / Sedimentation		
DWR ID	DWR_NA0060_6_c_2015_117		
Action/Comments			
Inspector Comments: No shoaling or sedimentation observed.			

No Photos

Rating **	A	Issue No.	118
			GPS Lat/Long
Issue Type +	Ma	Location *	39.750979 °
Category	Rivers, Channels & Designated Flood		-121.844711 °
Item	Erosion / Bank Caving		
DWR ID	DWR_NA0060_6_c_2015_118		
Action/Comments			
Inspector Comments: No head cutting or horizontal deviation observed.			

No Photos

* Location
LS : Land Side
WS : Water Side
CR : Crown

** Rating
A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type
Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2020

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Lindo Channel & Sandy Gulch	12.00	07/30/2020 07/30/2020	Brooks Weisser

Check Point / View			
Mangrove Avenue / Down (cont)			
Rating **	N	Issue No. 119	GPS Lat/Long
Issue Type +	Ma	Location *	39.750979 °
Category	Rivers, Channels & Designated Flood		-121.844711 °
Item	Revetments		
DWR ID	DWR_NA0060_6_c_2015_119		
Action/Comments			
Inspector Comments: No visible revetment observed.			

No Photos

Rating **	M	Issue No. 120	GPS Lat/Long
Issue Type +	Ma	Location *	39.750979 °
Category	Rivers, Channels & Designated Flood		-121.844711 °
Item	Encroachments		
DWR ID	DWR_NA0060_6_c_2015_120		
Action/Comments			
Inspector Comments: A fallen tree in the channel should be removed, 2020.			

Photo 1 of 1 : CH_2020_NA0060_6_120_20200805_00091.jpg



View of a tree in the channel downstream of the bridge, 2020.

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2020

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Lindo Channel & Sandy Gulch	12.00	07/30/2020 07/30/2020	Brooks Weisser

Check Point / View			
Esplanade / Up			
Rating **	M	Issue No. 51	GPS Lat/Long
Issue Type +	Ma	Location *	39.749458 °
Category	Rivers, Channels & Designated Flood		-121.854296 °
Item	Vegetation & Obstructions		
DWR ID	DWR_NA0060_6_c_2012_51		
Action/Comments			
Inspector Comments: Minimal, scattered obstructions or vegetation exists and the flow could be impeded.			

Photo 1 of 1 : CH_2020_NA0060_6_51_20200805_00093.jpg



View of the channel facing upstream, 2020.

Rating **	A	Issue No. 57	GPS Lat/Long
Issue Type +	Ma	Location *	39.749458 °
Category	Rivers, Channels & Designated Flood		-121.854296 °
Item	Shoaling / Sedimentation		
DWR ID	DWR_NA0060_6_c_2012_57		
Action/Comments			
Inspector Comments: Shoaling present on the upstream side underneath the bike crossing bridge, but it doesn't affect the channel capacity.			

No Photos

Rating **	A	Issue No. 53	GPS Lat/Long
Issue Type +	Ma	Location *	39.749458 °
Category	Rivers, Channels & Designated Flood		-121.854296 °
Item	Erosion / Bank Caving		
DWR ID	DWR_NA0060_6_c_2012_53		
Action/Comments			
Inspector Comments: No erosion encroaching into the channel bank that would endanger the capacity of the channel was observed.			

No Photos

* Location
LS : Land Side
WS : Water Side
CR : Crown

** Rating
A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type
Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2020

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Lindo Channel & Sandy Gulch	12.00	07/30/2020 07/30/2020	Brooks Weisser

Check Point / View			
Esplanade / Up (cont)			
Rating **	N	Issue No. 54	GPS Lat/Long
Issue Type +	Ma	Location *	39.749458 °
Category	Rivers, Channels & Designated Flood		-121.854296 °
Item	Revetments		
DWR ID	DWR_NA0060_6_c_2012_54		
Action/Comments			
Inspector Comments: There is no revetment at the bridge abutments and is not needed.			

Photo 1 of 1 : CH_2020_NA0060_6_54_20200805_00094.jpg



View of both abutments, no revetment exist, 2020

Check Point / View			
Rating **	M	Issue No. 55	GPS Lat/Long
Issue Type +	Ma	Location *	39.749458 °
Category	Rivers, Channels & Designated Flood		-121.854296 °
Item	Encroachments		
DWR ID	DWR_NA0060_6_c_2012_55		
Action/Comments			
Inspector Comments: Debris is caught on the foot bridge piles and needs to be removed, 2019.			

Photo 1 of 2 : CH_2020_NA0060_6_55_20200805_00095.jpg



View of the right bank facing upstream. Large debris and trash piles from campers, 2020.

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2020

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Lindo Channel & Sandy Gulch	12.00	07/30/2020 07/30/2020	Brooks Weisser

Check Point / View				
Esplanade / Up (cont)				
Rating **	M	Issue No.	55 (cont)	GPS Lat/Long
Issue Type +	Ma	Location *		39.749458 °
Category	Rivers, Channels & Designated Flood			-121.854296 °
Item	Encroachments			
DWR ID	DWR_NA0060_6_c_2012_55			
Action/Comments				
Inspector Comments: Debris is caught on the foot bridge piles and needs to be removed, 2019.				

Photo 2 of 2 : CH_2020_NA0060_6_55_20200805_00096.jpg



View of the left bank facing upstream. Large debris and trash piles from campers, 2020.

Check Point / View				
Esplanade / Down				
Rating **	M	Issue No.	56	GPS Lat/Long
Issue Type +	Ma	Location *		39.749458 °
Category	Rivers, Channels & Designated Flood			-121.854296 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0060_6_c_2012_56			
Action/Comments				
Inspector Comments: Vegetation and scattered obstructions exists and the flow may be impeded.				

Photo 1 of 1 : CH_2020_NA0060_6_56_20200805_00097.jpg



View of the channel facing downstream, 2020.

* Location
LS : Land Side
WS : Water Side
CR : Crown

** Rating
A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type
Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2020

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Lindo Channel & Sandy Gulch	12.00	07/30/2020 07/30/2020	Brooks Weisser

Check Point / View			
Esplanade / Down (cont)			
Rating **	A	Issue No.	52
			GPS Lat/Long
Issue Type +	Ma	Location *	39.749458 °
Category	Rivers, Channels & Designated Flood		-121.854296 °
Item	Shoaling / Sedimentation		
DWR ID	DWR_NA0060_6_c_2013_52		
Action/Comments			
Inspector Comments: Minimal shoaling and sedimentation present.			

No Photos

Rating **	A	Issue No.	58
			GPS Lat/Long
Issue Type +	Ma	Location *	39.749458 °
Category	Rivers, Channels & Designated Flood		-121.854296 °
Item	Erosion / Bank Caving		
DWR ID	DWR_NA0060_6_c_2012_58		
Action/Comments			
Inspector Comments: No erosion encroaching into the channel bank that would endanger the capacity of the channel was observed.			

No Photos

Rating **	N	Issue No.	59
			GPS Lat/Long
Issue Type +	Ma	Location *	39.749458 °
Category	Rivers, Channels & Designated Flood		-121.854296 °
Item	Revetments		
DWR ID	DWR_NA0060_6_c_2012_59		
Action/Comments			
Inspector Comments: There is no revetment in the channel at the abutments.			

Photo 1 of 1 : CH_2020_NA0060_6_59_20200730_00030.jpg



View of the right bank looking downstream, there is no revetment in the channel at the abutment, 2018.

* Location
LS : Land Side
WS : Water Side
CR : Crown

** Rating
A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type
Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2020

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Lindo Channel & Sandy Gulch	12.00	07/30/2020 07/30/2020	Brooks Weisser

Check Point / View			
Esplanade / Down (cont)			
Rating **	A	Issue No.	60
Issue Type +	Ma	Location *	39.749458 °
Category	Rivers, Channels & Designated Flood		-121.854296 °
Item	Encroachments		
DWR ID	DWR_NA0060_6_c_2012_60		
Action/Comments			
Inspector Comments: No trash, debris, excavation, structures, or other obstructions present within the project easement area.			

No Photos

Check Point / View			
Holly Avenue / Up			
Rating **	A	Issue No.	101
Issue Type +	Ma	Location *	39.749209 °
Category	Rivers, Channels & Designated Flood		-121.865682 °
Item	Vegetation & Obstructions		
DWR ID	DWR_NA0060_12_c_2015_101		
Action/Comments			
Inspector Comments: Minimal, scattered obstructions and vegetation exists however the flow does not look to be impeded.			

Photo 1 of 1 : CH_2020_NA0060_6_101_20200805_00098.jpg



View of the channel looking upstream, 2020.

Rating **	A	Issue No.	102
Issue Type +	Ma	Location *	39.749209 °
Category	Rivers, Channels & Designated Flood		-121.865682 °
Item	Shoaling / Sedimentation		
DWR ID	DWR_NA0060_12_c_2015_102		
Action/Comments			
Inspector Comments: Minimal shoaling and sedimentation present.			

No Photos

* Location
LS : Land Side
WS : Water Side
CR : Crown

** Rating
A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type
Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2020

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Lindo Channel & Sandy Gulch	12.00	07/30/2020 07/30/2020	Brooks Weisser

Check Point / View			
Holly Avenue / Up (cont)			
Rating **	A	Issue No.	103
Issue Type +	Ma	Location *	39.749209 °
Category	Rivers, Channels & Designated Flood		-121.865682 °
Item	Erosion / Bank Caving		
DWR ID	DWR_NA0060_12_c_2015_103		
Action/Comments			
Inspector Comments: No head cutting or horizontal deviation observed.			

No Photos

Rating **	A	Issue No.	104
Issue Type +	Ma	Location *	39.749209 °
Category	Rivers, Channels & Designated Flood		-121.865682 °
Item	Revetments		
DWR ID	DWR_NA0060_6_c_2015_104		
Action/Comments			
Inspector Comments: Gabion wall revetment at bridge abutment, right and left bank.			

Photo 1 of 2 : CH_2020_NA0060_6_104_20200805_00100.jpg



View of gabion wall revetment at bridge abutment, left bank, 2020.

Rating **	A	Issue No.	104 (cont)
Issue Type +	Ma	Location *	39.749209 °
Category	Rivers, Channels & Designated Flood		-121.865682 °
Item	Revetments		
DWR ID	DWR_NA0060_6_c_2015_104		

Photo 2 of 2 : CH_2020_NA0060_6_104_20200805_00101.jpg



View of gabion wall revetment at bridge abutment, right bank, 2020.

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2020

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Lindo Channel & Sandy Gulch	12.00	07/30/2020 07/30/2020	Brooks Weisser

Check Point / View			
Holly Avenue / Up (cont)			
Rating **	A	Issue No.	105
Issue Type +	Ma	Location *	39.749209 °
Category	Rivers, Channels & Designated Flood		-121.865682 °
Item	Encroachments		
DWR ID	DWR_NA0060_6_c_2015_105		
Action/Comments			
Inspector Comments: No trash, debris, excavation, structures, or other obstructions present within the project easement area.			

No Photos

Check Point / View			
Holly Avenue / Down			
Rating **	A	Issue No.	106
Issue Type +	Ma	Location *	39.749209 °
Category	Rivers, Channels & Designated Flood		-121.865682 °
Item	Vegetation & Obstructions		
DWR ID	DWR_NA0060_6_c_2015_106		
Action/Comments			
Inspector Comments: Minimal, scattered obstructions or vegetation exists however the flow does not seem to be impeded.			

Photo 1 of 1 : CH_2020_NA0060_6_106_20200805_00099.jpg



View of the channel looking downstream, 2020.

Rating **	A	Issue No.	107
Issue Type +	Ma	Location *	39.749209 °
Category	Rivers, Channels & Designated Flood		-121.865682 °
Item	Shoaling / Sedimentation		
DWR ID	DWR_NA0060_6_c_2015_107		
Action/Comments			
Inspector Comments: Minimal shoaling and sedimentation present.			

No Photos

* Location
LS : Land Side
WS : Water Side
CR : Crown

** Rating
A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type
Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2020

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Lindo Channel & Sandy Gulch	12.00	07/30/2020 07/30/2020	Brooks Weisser

Check Point / View

Holly Avenue / Down (cont)

Rating **	A	Issue No.	108	GPS Lat/Long
Issue Type +	Ma	Location *		39.749209 °
Category	Rivers, Channels & Designated Flood			-121.865682 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0060_6_c_2015_108			
Action/Comments				
Inspector Comments: No head cutting or horizontal deviation observed.				

No Photos

Rating **	A	Issue No.	109	GPS Lat/Long
Issue Type +	Ma	Location *		39.749209 °
Category	Rivers, Channels & Designated Flood			-121.865682 °
Item	Revetments			
DWR ID	DWR_NA0060_6_c_2015_109			
Action/Comments				
Inspector Comments: Gabion wall revetment at bridge abutment, right and left bank.				

No Photos

Rating **	A	Issue No.	110	GPS Lat/Long
Issue Type +	Ma	Location *		39.749209 °
Category	Rivers, Channels & Designated Flood			-121.865682 °
Item	Encroachments			
DWR ID	DWR_NA0060_6_c_2015_110			
Action/Comments				
Inspector Comments: No trash, debris, excavation, structures, or other obstructions present within the project easement area.				

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2020

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Lindo Channel & Sandy Gulch	12.00	07/30/2020 07/30/2020	Brooks Weisser

Check Point / View			
Hwy 32 / Up			
Rating **	M	Issue No. 61	GPS Lat/Long
Issue Type +	Ma	Location *	39.741277 °
Category	Rivers, Channels & Designated Flood		-121.881402 °
Item	Vegetation & Obstructions		
DWR ID	DWR_NA0060_6_c_2012_61		
Action/Comments			
Inspector Comments: Vegetation exists and may impede the flow.			

Photo 1 of 1 : CH_2020_NA0060_6_61_20200805_00102.jpg



View of the channel looking upstream, 2020.

Rating **	A	Issue No. 62	GPS Lat/Long
Issue Type +	Ma	Location *	39.741277 °
Category	Rivers, Channels & Designated Flood		-121.881402 °
Item	Shoaling / Sedimentation		
DWR ID	DWR_NA0060_6_c_2012_62		
Action/Comments			
Inspector Comments: No shoaling or sedimentation observed.			

No Photos

Rating **	A	Issue No. 63	GPS Lat/Long
Issue Type +	Ma	Location *	39.741277 °
Category	Rivers, Channels & Designated Flood		-121.881402 °
Item	Erosion / Bank Caving		
DWR ID	DWR_NA0060_6_c_2012_63		
Action/Comments			
Inspector Comments: No head cutting or horizontal deviation observed.			

No Photos

* Location
LS : Land Side
WS : Water Side
CR : Crown

** Rating
A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type
Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2020

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Lindo Channel & Sandy Gulch	12.00	07/30/2020 07/30/2020	Brooks Weisser

Check Point / View				
Hwy 32 / Up (cont)				
Rating **	A	Issue No.	64	GPS Lat/Long
Issue Type +	Ma	Location *		39.741277 °
Category	Rivers, Channels & Designated Flood			-121.881402 °
Item	Revetments			
DWR ID	DWR_NA0060_6_c_2012_64			
Action/Comments				
Inspector Comments: Revetment is present and in good condition, but maintain vegetation to keep revetment visible.				

Photo 1 of 1 : CH_2020_NA0060_6_64_20200805_00104.jpg



View of left bank concrete filled sandbag revetment, typical for both sides, 2020.

Check Point / View				
Hwy 32 / Down				
Rating **	M	Issue No.	66	GPS Lat/Long
Issue Type +	Ma	Location *		39.741277 °
Category	Rivers, Channels & Designated Flood			-121.881402 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0060_6_c_2012_66			
Action/Comments				
Inspector Comments: Vegetation exists and may impede the flow.				

Photo 1 of 1 : CH_2020_NA0060_6_66_20200805_00103.jpg



View of the channel looking downstream, 2020.

* Location
LS : Land Side
WS : Water Side
CR : Crown

** Rating
A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type
Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2020

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Lindo Channel & Sandy Gulch	12.00	07/30/2020 07/30/2020	Brooks Weisser

Check Point / View				
Hwy 32 / Down (cont)				
Rating **	A	Issue No.	67	GPS Lat/Long
Issue Type +	Ma	Location *		39.741277 °
Category	Rivers, Channels & Designated Flood			-121.881402 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0060_6_c_2012_67			
Action/Comments				
Inspector Comments: No shoaling or sedimentation observed.				

No Photos

Rating **	A	Issue No.	68	GPS Lat/Long
Issue Type +	Ma	Location *		39.741277 °
Category	Rivers, Channels & Designated Flood			-121.881402 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0060_6_c_2012_68			
Action/Comments				
Inspector Comments: No head cutting or horizontal deviation observed.				

No Photos

Rating **	A	Issue No.	69	GPS Lat/Long
Issue Type +	Ma	Location *		39.741277 °
Category	Rivers, Channels & Designated Flood			-121.881402 °
Item	Revetments			
DWR ID	DWR_NA0060_6_c_2012_69			
Action/Comments				
Inspector Comments: Revetment is present on left and right bank abutments.				

No Photos

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2020

DWR Sutter Maintenance Yard


Channel	Channel Length	Inspection Start/End	Inspector
Lindo Channel & Sandy Gulch	12.00	07/30/2020 07/30/2020	Brooks Weisser

Check Point / View			
Hwy 32 / Down (cont)			
Rating **	A	Issue No.	70
Issue Type +	Ma	Location *	GPS Lat/Long
Category	Rivers, Channels & Designated Flood		39.741277 °
Item	Encroachments		-121.881402 °
DWR ID	DWR_NA0060_6_c_2012_70		
Action/Comments			
Inspector Comments: No trash, debris, excavation, structures, or other obstructions present within the project easement area.			

No Photos

Check Point / View			
Oak Ave. / Up			
Rating **	M	Issue No.	121
Issue Type +	Ma	Location *	GPS Lat/Long
Category	Rivers, Channels & Designated Flood		39.735560 °
Item	Vegetation & Obstructions		-121.890970 °
DWR ID	DWR_NA0060_6_c_2017_121		
Action/Comments			
Inspector Comments: Various scattered obstructions or vegetation exists which may impede flows.			

Photo 1 of 1 : CH_2020_NA0060_6_121_20200805_00105.jpg



View of the vegetation looking upstream from the bridge, 2019.

Rating **	A	Issue No.	72	GPS Lat/Long
Issue Type +	Ma	Location *		39.735560 °
Category	Rivers, Channels & Designated Flood			-121.890970 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0060_6_c_2012_72			
Action/Comments				
Inspector Comments: No shoaling or sedimentation observed.				

No Photos

* Location
LS : Land Side
WS : Water Side
CR : Crown

** Rating
A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type
Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2020

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Lindo Channel & Sandy Gulch	12.00	07/30/2020 07/30/2020	Brooks Weisser

Check Point / View			
Oak Ave. / Up (cont)			
Rating **	A	Issue No.	73
			GPS Lat/Long
Issue Type +	Ma	Location *	39.735560 °
Category	Rivers, Channels & Designated Flood		-121.890970 °
Item	Erosion / Bank Caving		
DWR ID	DWR_NA0060_6_c_2012_73		
Action/Comments			
Inspector Comments: No head cutting or horizontal deviation observed.			

No Photos

Rating **	N	Issue No.	74	GPS Lat/Long
Issue Type +	Ma	Location *		39.735560 °
Category	Rivers, Channels & Designated Flood			-121.890970 °
Item	Revetments			
DWR ID	DWR_NA0060_6_c_2012_74			
Action/Comments				
Inspector Comments: No revetments present.				

Photo 1 of 2 : CH_2020_NA0060_6_74_20200805_00107.jpg



View of left abutment with no revetment, 2020.

Rating **	N	Issue No.	74 (cont)	GPS Lat/Long
Issue Type +	Ma	Location *		39.735560 °
Category	Rivers, Channels & Designated Flood			-121.890970 °
Item	Revetments			
DWR ID	DWR_NA0060_6_c_2012_74			

Photo 2 of 2 : CH_2020_NA0060_6_74_20200805_00108.jpg



View of right abutment with no revetment, 2020

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2020

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Lindo Channel & Sandy Gulch	12.00	07/30/2020 07/30/2020	Brooks Weisser

Check Point / View				
Oak Ave. / Up (cont)				
Rating **	A	Issue No.	75	GPS Lat/Long
Issue Type +	Ma	Location *		39.735560 °
Category	Rivers, Channels & Designated Flood			-121.890970 °
Item	Encroachments			
DWR ID	DWR_NA0060_6_c_2012_75			
Action/Comments				
Inspector Comments: No encroachments in the channel.				

No Photos

Check Point / View				
Oak Ave. / Down				
Rating **	M	Issue No.	71	GPS Lat/Long
Issue Type +	Ma	Location *		39.735560 °
Category	Rivers, Channels & Designated Flood			-121.890970 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0060_6_c_2012_71			
Action/Comments				
Inspector Comments: Scattered obstructions and vegetation exists which may impede the flow of the channel.				

Photo 1 of 1 : CH_2020_NA0060_6_71_20200805_00106.jpg



View of the channel facing downstream, 2020.

Rating **	A	Issue No.	77	GPS Lat/Long
Issue Type +	Ma	Location *		39.735560 °
Category	Rivers, Channels & Designated Flood			-121.890970 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0060_6_c_2012_77			
Action/Comments				
Inspector Comments: No shoaling or sedimentation observed.				

No Photos

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2020

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Lindo Channel & Sandy Gulch	12.00	07/30/2020 07/30/2020	Brooks Weisser

Check Point / View				GPS Lat/Long	No Photos
Oak Ave. / Down (cont)					
Rating **	A	Issue No.	78		
Issue Type +	Ma	Location *		39.735560 °	
Category	Rivers, Channels & Designated Flood			-121.890970 °	
Item	Erosion / Bank Caving				
DWR ID	DWR_NA0060_6_c_2012_78				
Action/Comments					
Inspector Comments: No head cutting or horizontal deviation observed.					

Rating **	N	Issue No.	79	GPS Lat/Long	No Photos
Issue Type +	Ma	Location *		39.735560 °	
Category	Rivers, Channels & Designated Flood			-121.890970 °	
Item	Revetments				
DWR ID	DWR_NA0060_6_c_2012_79				
Action/Comments					
Inspector Comments: No revetments present.					

Rating **	A	Issue No.	80	GPS Lat/Long	No Photos
Issue Type +	Ma	Location *		39.735560 °	
Category	Rivers, Channels & Designated Flood			-121.890970 °	
Item	Encroachments				
DWR ID	DWR_NA0060_6_c_2012_80				
Action/Comments					
Inspector Comments: No encroachments are visible in the channel.					

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2020

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Lindo Channel & Sandy Gulch	12.00	07/30/2020 07/30/2020	Brooks Weisser

Check Point / View			
Grape Way / Up			
Rating **	A	Issue No.	81
Issue Type +	Ma	Location *	GPS Lat/Long
Category	Rivers, Channels & Designated Flood		39.722724 °
Item	Vegetation & Obstructions		-121.912363 °
DWR ID	DWR_NA0060_6_c_2012_81		
Action/Comments			
Inspector Comments: Minimal, scattered obstructions or vegetation. The flow is not impeded.			

Photo 1 of 1 : CH_2020_NA0060_6_81_20200805_00109.jpg



View of the channel facing upstream, 2020.

Rating **	A	Issue No.	82
Issue Type +	Ma	Location *	GPS Lat/Long
Category	Rivers, Channels & Designated Flood		39.722724 °
Item	Shoaling / Sedimentation		-121.912363 °
DWR ID	DWR_NA0060_6_c_2012_82		
Action/Comments			
Inspector Comments: No shoaling or sedimentation observed.			

No Photos

Rating **	A	Issue No.	83
Issue Type +	Ma	Location *	GPS Lat/Long
Category	Rivers, Channels & Designated Flood		39.722724 °
Item	Erosion / Bank Caving		-121.912363 °
DWR ID	DWR_NA0060_6_c_2012_83		
Action/Comments			
Inspector Comments: No head cutting or horizontal deviation observed.			

No Photos

* Location
LS : Land Side
WS : Water Side
CR : Crown

** Rating
A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type
Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2020

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Lindo Channel & Sandy Gulch	12.00	07/30/2020 07/30/2020	Brooks Weisser

Check Point / View				
Grape Way / Up (cont)				
Rating **	A	Issue No.	84	GPS Lat/Long
Issue Type +	Ma	Location *		39.722724 °
Category	Rivers, Channels & Designated Flood			-121.912363 °
Item	Revetments			
DWR ID	DWR_NA0060_6_c_2012_84			
Action/Comments				
Inspector Comments: Revetments are in place and maintained properly. Concrete sandbag revetment at bridge abutments, both sides.				

Photo 1 of 2 : CH_2020_NA0060_6_84_20200805_00111.jpg



View of concrete sandbag revetment at bridge abutments, right bank, 2020.

Rating **	A	Issue No.	84 (cont)	GPS Lat/Long
Issue Type +	Ma	Location *		39.722724 °
Category	Rivers, Channels & Designated Flood			-121.912363 °
Item	Revetments			
DWR ID	DWR_NA0060_6_c_2012_84			

Photo 2 of 2 : CH_2020_NA0060_6_84_20200805_00112.jpg



View of concrete sandbag revetment at bridge abutments, left bank, 2020

Rating **	A	Issue No.	85	GPS Lat/Long
Issue Type +	Ma	Location *		39.722724 °
Category	Rivers, Channels & Designated Flood			-121.912363 °
Item	Encroachments			
DWR ID	DWR_NA0060_6_c_2012_85			
Action/Comments				
Inspector Comments: No trash, debris, excavation, structures, or other obstructions present within the project easement area.				

No Photos

* Location
LS : Land Side
WS : Water Side
CR : Crown

** Rating
A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type
Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2020

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Lindo Channel & Sandy Gulch	12.00	07/30/2020 07/30/2020	Brooks Weisser

Check Point / View				
Grape Way / Down				
Rating **	A	Issue No.	86	GPS Lat/Long
Issue Type +	Ma	Location *		39.722724 °
Category	Rivers, Channels & Designated Flood			-121.912363 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0060_6_c_2012_86			
Action/Comments				
Inspector Comments: Minimal, scattered obstructions or vegetation. The flow is not impeded.				

Photo 1 of 1 : CH_2020_NA0060_6_86_20200805_00110.jpg



View of the channel facing downstream, 2020.

Rating **	A	Issue No.	87	GPS Lat/Long
Issue Type +	Ma	Location *		39.722724 °
Category	Rivers, Channels & Designated Flood			-121.912363 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0060_6_c_2012_87			
Action/Comments				
Inspector Comments: No shoaling or sedimentation observed.				

No Photos

Rating **	A	Issue No.	88	GPS Lat/Long
Issue Type +	Ma	Location *		39.722724 °
Category	Rivers, Channels & Designated Flood			-121.912363 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0060_6_c_2012_88			
Action/Comments				
Inspector Comments: No head cutting or horizontal deviation observed.				

No Photos

* Location
LS : Land Side
WS : Water Side
CR : Crown

** Rating
A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type
Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2020

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Lindo Channel & Sandy Gulch	12.00	07/30/2020 07/30/2020	Brooks Weisser

Check Point / View			
Grape Way / Down (cont)			
Rating **	A	Issue No.	89
Issue Type +	Ma	Location *	
Category	Rivers, Channels & Designated Flood		GPS Lat/Long
Item	Revetments		
DWR ID	DWR_NA0060_6_c_2012_89		
Action/Comments			
Inspector Comments: Revetments are in place and maintained properly. Concrete sandbag revetment at bridge abutments, both sides.			

No Photos

Rating **	A	Issue No.	90
Issue Type +	Ma	Location *	
Category	Rivers, Channels & Designated Flood		GPS Lat/Long
Item	Encroachments		
DWR ID	DWR_NA0060_6_c_2012_90		
Action/Comments			
Inspector Comments: No trash, debris, excavation, structures, or other obstructions present within the project easement area.			

No Photos

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

Flood Control Project Maintenance

Unit Cover Sheet

2020 Channel Inspection Results

DWR Sutter Maintenance Yard

Channel
Little Chico Creek

Channel Rating	M
Date of Inspection	7/30/2020
DWR Inspector	Brooks Weisser
Accompanied By	

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2020

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Little Chico Creek	8.00	07/30/2020 07/30/2020	Brooks Weisser

Check Point / View			
Little Chico Ck Control Structure / Up			
Rating **	A	Issue No.	1
Issue Type +	Ma	Location *	39.733681 °
Category	Rivers, Channels & Designated Flood		-121.771865 °
Item	Vegetation & Obstructions		
DWR ID	DWR_NA0060_12_c_2012_1		
Action/Comments			
Inspector Comments: Minimal, scattered obstructions and vegetation. The flow is not impeded.			

Photo 1 of 1 : CH_2020_NA0060_12_1_20200805_00044.jpg



This is the upstream view from the Little Chico Control Structure, 2020.

Rating **	A	Issue No.	2
Issue Type +	Ma	Location *	39.733681 °
Category	Rivers, Channels & Designated Flood		-121.771865 °
Item	Shoaling / Sedimentation		
DWR ID	DWR_NA0060_12_c_2012_2		
Action/Comments			
Inspector Comments: There is a no shoaling and sedimentation, the flow is not impeded.			

No Photos

Rating **	A	Issue No.	3
Issue Type +	Ma	Location *	39.733681 °
Category	Rivers, Channels & Designated Flood		-121.771865 °
Item	Erosion / Bank Caving		
DWR ID	DWR_NA0060_12_c_2012_3		
Action/Comments			
Inspector Comments: No erosion observed.			

No Photos

* Location
LS : Land Side
WS : Water Side
CR : Crown

** Rating
A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type
Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2020

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Little Chico Creek	8.00	07/30/2020 07/30/2020	Brooks Weisser

Check Point / View			
Little Chico Ck Control Structure / Up (cont)			
Rating **	N	Issue No.	4
Issue Type +	Ma	Location *	39.733681 °
Category	Rivers, Channels & Designated Flood		-121.771865 °
Item	Revetments		
DWR ID	DWR_NA0060_12_c_2013_4		
Action/Comments			
Inspector Comments: No revetment.			

No Photos

Rating **	A	Issue No.	5
Issue Type +	Ma	Location *	39.733681 °
Category	Rivers, Channels & Designated Flood		-121.771865 °
Item	Encroachments		
DWR ID	DWR_NA0060_12_c_2012_5		
Action/Comments			
Inspector Comments: No trash, debris, excavation, structures, or other obstructions present within the project easement area.			

No Photos

Check Point / View			
Little Chico Ck Control Structure / Down			
Rating **	M	Issue No.	6
Issue Type +	Ma	Location *	39.733681 °
Category	Rivers, Channels & Designated Flood		-121.771865 °
Item	Vegetation & Obstructions		
DWR ID	DWR_NA0060_12_c_2012_6		
Action/Comments			
Inspector Comments: Scattered obstructions and vegetation. The flow may be impeded. Willow trees should be removed.			

Photo 1 of 1 : CH_2020_NA0060_12_6_20200805_00045.jpg



This is the downstream view from the Little Chico Control Structure, 2020.

* Location
LS : Land Side
WS : Water Side
CR : Crown

** Rating	
A : Acceptable	N : Not Inspected/Rated
M : Minimally Acceptable	C : Corrected
U : Unacceptable	A/W : Acceptable but Monitor & Maintain

+ Issue Type
Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2020

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Little Chico Creek	8.00	07/30/2020 07/30/2020	Brooks Weisser

Check Point / View
Little Chico Ck Control Structure / Down (cont)

Rating **	A	Issue No.	7	GPS Lat/Long
Issue Type +	Ma	Location *		39.733681 °
Category	Rivers, Channels & Designated Flood			-121.771865 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0060_12_c_2012_7			
Action/Comments				
Inspector Comments: There is no shoaling and sedimentation, the flow is not impeded.				

No Photos

Rating **	A	Issue No.	8	GPS Lat/Long
Issue Type +	Ma	Location *		39.733681 °
Category	Rivers, Channels & Designated Flood			-121.771865 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0060_12_c_2012_8			
Action/Comments				
Inspector Comments: No erosion observed.				

No Photos

Rating **	N	Issue No.	9	GPS Lat/Long
Issue Type +	Ma	Location *		39.733681 °
Category	Rivers, Channels & Designated Flood			-121.771865 °
Item	Revetments			
DWR ID	DWR_NA0060_12_c_2012_9			
Action/Comments				
Inspector Comments: No revetment.				

No Photos

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2020

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Little Chico Creek	8.00	07/30/2020 07/30/2020	Brooks Weisser

Check Point / View				
Little Chico Ck Control Structure / Down (cont)				
Rating **	A	Issue No.	10	GPS Lat/Long
Issue Type +	Ma	Location *		39.733681 °
Category	Rivers, Channels & Designated Flood			-121.771865 °
Item	Encroachments			
DWR ID	DWR_NA0060_12_c_2012_10			
Action/Comments				
Inspector Comments: No trash, debris, excavation, structures, or other obstructions present within the project easement area.				

No Photos

Check Point / View				
Bruce Rd / Up				
Rating **	A	Issue No.	114	GPS Lat/Long
Issue Type +	Ma	Location *		39.733316 °
Category	Rivers, Channels & Designated Flood			-121.787540 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0060_12_c_2019_114			
Action/Comments				
Inspector Comments: The vegetation overhangs the channel but does not appear to impede the flows.				

Photo 1 of 1 : CH_2020_NA0060_12_114_20200805_00049.jpg



View looking upstream from the bridge of the overhanging vegetation, 2020.

Rating **	A	Issue No.	12	GPS Lat/Long
Issue Type +	Ma	Location *		39.733316 °
Category	Rivers, Channels & Designated Flood			-121.787540 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0060_12_c_2012_12			
Action/Comments				
Inspector Comments: No shoaling or sedimentation observed.				

No Photos

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2020

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Little Chico Creek	8.00	07/30/2020 07/30/2020	Brooks Weisser

Check Point / View
Bruce Rd / Up (cont)

Rating **	A	Issue No.	13	GPS Lat/Long
Issue Type +	Ma	Location *		39.733316 °
Category	Rivers, Channels & Designated Flood			-121.787540 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0060_12_c_2012_13			
Action/Comments				
Inspector Comments: No erosion observed.				

No Photos

Rating **	N	Issue No.	14	GPS Lat/Long
Issue Type +	Ma	Location *		39.733316 °
Category	Rivers, Channels & Designated Flood			-121.787540 °
Item	Revetments			
DWR ID	DWR_NA0060_12_c_2012_14			
Action/Comments				
Inspector Comments: No revetments present.				

No Photos

Rating **	A	Issue No.	15	GPS Lat/Long
Issue Type +	Ma	Location *		39.733316 °
Category	Rivers, Channels & Designated Flood			-121.787540 °
Item	Encroachments			
DWR ID	DWR_NA0060_12_c_2012_15			
Action/Comments				
Inspector Comments: No trash, debris, excavation, structures, or other obstructions observed within the project easement area.				

No Photos

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2020

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Little Chico Creek	8.00	07/30/2020 07/30/2020	Brooks Weisser

Check Point / View				
Bruce Rd / Down				
Rating **	U	Issue No.	11	GPS Lat/Long
Issue Type +	Ma	Location *		39.733316 °
Category	Rivers, Channels & Designated Flood			-121.787540 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0060_12_c_2012_11			
Action/Comments				
Inspector Comments: The vegetation obstructed the view of the channel. Its likely flow will be impeded in a high water event.				

Photo 1 of 1 : CH_2020_NA0060_12_11_20200805_00050.jpg



View of the channel facing downstream, 2020.

Rating **	A	Issue No.	17	GPS Lat/Long
Issue Type +	Ma	Location *		39.733316 °
Category	Rivers, Channels & Designated Flood			-121.787540 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0060_12_c_2012_17			
Action/Comments				
Inspector Comments: No shoaling or sedimentation observed.				

No Photos

Rating **	A	Issue No.	18	GPS Lat/Long
Issue Type +	Ma	Location *		39.733316 °
Category	Rivers, Channels & Designated Flood			-121.787540 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0060_12_c_2012_18			
Action/Comments				
Inspector Comments: No erosion observed.				

No Photos

* Location
LS : Land Side
WS : Water Side
CR : Crown

** Rating	
A : Acceptable	N : Not Inspected/Rated
M : Minimally Acceptable	C : Corrected
U : Unacceptable	A/W : Acceptable but Monitor & Maintain

+ Issue Type
Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2020

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Little Chico Creek	8.00	07/30/2020 07/30/2020	Brooks Weisser

Check Point / View			
Bruce Rd / Down (cont)			
Rating **	N	Issue No. 19	GPS Lat/Long
Issue Type +	Ma	Location *	39.733316 °
Category	Rivers, Channels & Designated Flood		-121.787540 °
Item	Revetments		
DWR ID	DWR_NA0060_12_c_2012_19		
Action/Comments			
Inspector Comments: No revetments present.			

No Photos

Rating **	A	Issue No. 20	GPS Lat/Long
Issue Type +	Ma	Location *	39.733316 °
Category	Rivers, Channels & Designated Flood		-121.787540 °
Item	Encroachments		
DWR ID	DWR_NA0060_12_c_2012_20		
Action/Comments			
Inspector Comments: No trash, debris, excavation, structures, or other obstructions observed within the project easement area.			

No Photos

Check Point / View			
Forest Ave / Up			
Rating **	A	Issue No. 115	GPS Lat/Long
Issue Type +	Ma	Location *	39.737400 °
Category	Rivers, Channels & Designated Flood		-121.804530 °
Item	Vegetation & Obstructions		
DWR ID	DWR_NA0060_12_c_2019_115		
Action/Comments			
Inspector Comments: Minimal, scattered obstructions or vegetation. The flow is not impeded.			

Photo 1 of 1 : CH_2020_NA0060_12_115_20200805_00053.jpg



View looking upstream at the channel from the bridge, 2020.

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2020

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Little Chico Creek	8.00	07/30/2020 07/30/2020	Brooks Weisser

Check Point / View			
Forest Ave / Up (cont)			
Rating **	A	Issue No.	22
			GPS Lat/Long
Issue Type +	Ma	Location *	39.737400 °
Category	Rivers, Channels & Designated Flood		-121.804530 °
Item	Shoaling / Sedimentation		
DWR ID	DWR_NA0060_12_c_2012_22		
Action/Comments			
Inspector Comments: Shoaling or sedimentation present, the flow is not impeded.			

No Photos

Rating **	M	Issue No.	23
			GPS Lat/Long
Issue Type +	Ma	Location *	39.737400 °
Category	Rivers, Channels & Designated Flood		-121.804530 °
Item	Erosion / Bank Caving		
DWR ID	DWR_NA0060_12_c_2012_23		
Action/Comments			
Inspector Comments: Moderate erosion on north bank.			

No Photos

Rating **	A	Issue No.	24
			GPS Lat/Long
Issue Type +	Ma	Location *	39.737400 °
Category	Rivers, Channels & Designated Flood		-121.804530 °
Item	Revetments		
DWR ID	DWR_NA0060_12_c_2012_24		
Action/Comments			
Inspector Comments: Revetments present.			

Photo 1 of 2 : CH_2020_NA0060_12_24_20200805_00055.jpg



View of revetment on right bank, 2020.

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2020

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Little Chico Creek	8.00	07/30/2020 07/30/2020	Brooks Weisser

Check Point / View				
Forest Ave / Up (cont)				
Rating **	A	Issue No.	24 (cont)	GPS Lat/Long
Issue Type +	Ma	Location *		39.737400 °
Category	Rivers, Channels & Designated Flood			-121.804530 °
Item	Revetments			
DWR ID	DWR_NA0060_12_c_2012_24			
Action/Comments				
Inspector Comments: Revetments present.				

Photo 2 of 2 : CH_2020_NA0060_12_24_20200805_00054.jpg



View of revetment on left bank, 2020.

Rating **	A	Issue No.	25	GPS Lat/Long
Issue Type +	Ma	Location *		39.737400 °
Category	Rivers, Channels & Designated Flood			-121.804530 °
Item	Encroachments			
DWR ID	DWR_NA0060_12_c_2012_25			
Action/Comments				
Inspector Comments: No trash, debris, excavation, structures, or other obstructions present within the project easement area.				

No Photos

* Location
LS : Land Side
WS : Water Side
CR : Crown

** Rating
A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type
Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2020

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Little Chico Creek	8.00	07/30/2020 07/30/2020	Brooks Weisser

Check Point / View			
Forest Ave / Down			
Rating **	M	Issue No. 21	GPS Lat/Long
Issue Type +	Ma	Location *	39.737400 °
Category	Rivers, Channels & Designated Flood		-121.804530 °
Item	Vegetation & Obstructions		
DWR ID	DWR_NA0060_12_c_2012_21		
Action/Comments			
Inspector Comments: Scattered bushes and vegetation may impede the flow of the channel.			

Photo 1 of 1 : CH_2020_NA0060_12_21_20200805_00056.jpg



View of the channel from the bridge facing downstream, 2020.

Rating **	A	Issue No. 27	GPS Lat/Long
Issue Type +	Ma	Location *	39.737400 °
Category	Rivers, Channels & Designated Flood		-121.804530 °
Item	Shoaling / Sedimentation		
DWR ID	DWR_NA0060_12_c_2012_27		
Action/Comments			
Inspector Comments: No shoaling or sedimentation present, the flow does not appear impeded.			

No Photos

Rating **	A	Issue No. 28	GPS Lat/Long
Issue Type +	Ma	Location *	39.737400 °
Category	Rivers, Channels & Designated Flood		-121.804530 °
Item	Erosion / Bank Caving		
DWR ID	DWR_NA0060_12_c_2012_28		
Action/Comments			
Inspector Comments: No erosion observed.			

No Photos

* Location
LS : Land Side
WS : Water Side
CR : Crown

** Rating
A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type
Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2020

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Little Chico Creek	8.00	07/30/2020 07/30/2020	Brooks Weisser

Check Point / View			
Forest Ave / Down (cont)			
Rating **	A	Issue No.	29
Issue Type +	Ma	Location *	39.737400 °
Category	Rivers, Channels & Designated Flood		-121.804530 °
Item	Revetments		
DWR ID	DWR_NA0060_12_c_2012_29		
Action/Comments			
Inspector Comments: Revetments present.			

No Photos

Rating **	A	Issue No.	30
Issue Type +	Ma	Location *	39.737400 °
Category	Rivers, Channels & Designated Flood		-121.804530 °
Item	Encroachments		
DWR ID	DWR_NA0060_12_c_2012_30		
Action/Comments			
Inspector Comments: No trash, debris, excavation, structures, or other obstructions present within the project easement area.			

No Photos

Check Point / View			
Repair site upstream of Hwy 99 / Up			
Rating **	A	Issue No.	31
Issue Type +	Ma	Location *	39.735670 °
Category	Rivers, Channels & Designated Flood		-121.814510 °
Item	Vegetation & Obstructions		
DWR ID	DWR_NA0060_12_c_2012_31		
Action/Comments			
Inspector Comments: Scattered vegetation. The flow does not appear impeded.			

Photo 1 of 1 : CH_2020_NA0060_12_31_20200805_00047.jpg



View looking upstream from Hwy 99 bridge, 2020.

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2020

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Little Chico Creek	8.00	07/30/2020 07/30/2020	Brooks Weisser

Check Point / View			
Repair site upstream of Hwy 99 / Up (cont)			
Rating **	A	Issue No.	32
Issue Type +	Ma	Location *	39.735670 °
Category	Rivers, Channels & Designated Flood		-121.814510 °
Item	Shoaling / Sedimentation		
DWR ID	DWR_NA0060_12_c_2012_32		
Action/Comments			
Inspector Comments: No shoaling or sedimentation observed.			

No Photos

Rating **	A	Issue No.	33
Issue Type +	Ma	Location *	39.735670 °
Category	Rivers, Channels & Designated Flood		-121.814510 °
Item	Erosion / Bank Caving		
DWR ID	DWR_NA0060_12_c_2012_33		
Action/Comments			
Inspector Comments: No erosion observed.			

No Photos

Rating **	A	Issue No.	34
Issue Type +	Ma	Location *	39.735670 °
Category	Rivers, Channels & Designated Flood		-121.814510 °
Item	Revetments		
DWR ID	DWR_NA0060_12_c_2012_34		
Action/Comments			
Inspector Comments: The gabion wall repair is still intact and has no signs of damage. Riprap is visible and appears properly maintained under the bridge.			

Photo 1 of 3 : CH_2020_NA0060_12_34_20200805_00060.jpg



View of the revetment along the abutment of the bridge on the right bank looking upstream, 2020.

* Location
LS : Land Side
WS : Water Side
CR : Crown

** Rating	
A : Acceptable	N : Not Inspected/Rated
M : Minimally Acceptable	C : Corrected
U : Unacceptable	A/W : Acceptable but Monitor & Maintain

+ Issue Type
Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2020

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Little Chico Creek	8.00	07/30/2020 07/30/2020	Brooks Weisser

Check Point / View				
Repair site upstream of Hwy 99 / Up (cont)				
Rating **	A	Issue No.	34 (cont)	GPS Lat/Long
Issue Type +	Ma	Location *		39.735670 °
Category	Rivers, Channels & Designated Flood			-121.814510 °
Item	Revetments			
DWR ID	DWR_NA0060_12_c_2012_34			
Action/Comments				
Inspector Comments: The gabion wall repair is still intact and has no signs of damage. Riprap is visible and appears properly maintained under the bridge.				

Photo 2 of 3 : CH_2020_NA0060_12_34_20200805_00058.jpg



View looking upstream of revetment at bridge abutment left bank, 2020.

Photo 3 of 3 : CH_2020_NA0060_12_34_20200805_00059.jpg



View of the gabion wall repair 300 yards upstream of the bridge at Highway 99, 2020.

Rating **	A	Issue No.	34 (cont)	GPS Lat/Long
Issue Type +	Ma	Location *		39.735670 °
Category	Rivers, Channels & Designated Flood			-121.814510 °
Item	Revetments			
DWR ID	DWR_NA0060_12_c_2012_34			

Rating **	A	Issue No.	35	GPS Lat/Long
Issue Type +	Ma	Location *		39.735670 °
Category	Rivers, Channels & Designated Flood			-121.814510 °
Item	Encroachments			
DWR ID	DWR_NA0060_12_c_2012_35			
Action/Comments				
Inspector Comments: No trash, debris, excavation, structures, or other obstructions present within the project easement area.				

No Photos

* Location
LS : Land Side
WS : Water Side
CR : Crown

** Rating
A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type
Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2020

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Little Chico Creek	8.00	07/30/2020 07/30/2020	Brooks Weisser

Check Point / View			
Repair site upstream of Hwy 99 / Down			
Rating **	A	Issue No. 36	GPS Lat/Long
Issue Type +	Ma	Location *	39.735670 °
Category	Rivers, Channels & Designated Flood		-121.814510 °
Item	Vegetation & Obstructions		
DWR ID	DWR_NA0060_12_c_2012_36		
Action/Comments			
Inspector Comments: There is vegetation over the channel, the flow does not look to be impeded during high water.			

Photo 1 of 1 : CH_2020_NA0060_12_36_20200805_00061.jpg



View looking downstream from under the bridge, 2020.

Rating **	A	Issue No. 37	GPS Lat/Long
Issue Type +	Ma	Location *	39.735670 °
Category	Rivers, Channels & Designated Flood		-121.814510 °
Item	Shoaling / Sedimentation		
DWR ID	DWR_NA0060_12_c_2012_37		
Action/Comments			
Inspector Comments: No shoaling or sedimentation observed.			

No Photos

Rating **	A	Issue No. 38	GPS Lat/Long
Issue Type +	Ma	Location *	39.735670 °
Category	Rivers, Channels & Designated Flood		-121.814510 °
Item	Erosion / Bank Caving		
DWR ID	DWR_NA0060_12_c_2012_38		
Action/Comments			
Inspector Comments: No erosion observed.			

No Photos

* Location
LS : Land Side
WS : Water Side
CR : Crown

** Rating
A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type
Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2020

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Little Chico Creek	8.00	07/30/2020 07/30/2020	Brooks Weisser

Check Point / View			
Repair site upstream of Hwy 99 / Down (cont)			
Rating **	A	Issue No.	39
Issue Type +	Ma	Location *	39.735670 °
Category	Rivers, Channels & Designated Flood		-121.814510 °
Item	Revetments		
DWR ID	DWR_NA0060_12_c_2012_39		
Action/Comments			
Inspector Comments: Riprap is visible and appears properly maintained.			

No Photos

Rating **	A	Issue No.	40
Issue Type +	Ma	Location *	39.735670 °
Category	Rivers, Channels & Designated Flood		-121.814510 °
Item	Encroachments		
DWR ID	DWR_NA0060_12_c_2012_40		
Action/Comments			
Inspector Comments: No trash, debris, excavation, structures, or other obstructions present within the project easement area.			

No Photos

Check Point / View			
Bruce Street / Up			
Rating **	M	Issue No.	82
Issue Type +	Ma	Location *	39.733204 °
Category	Rivers, Channels & Designated Flood		-121.819610 °
Item	Vegetation & Obstructions		
DWR ID	DWR_NA0060_12_c_2015_82		
Action/Comments			
Inspector Comments: There is vegetation in the channel and it appears to potentially impede the flow.			

Photo 1 of 1 : CH_2020_NA0060_12_82_20200805_00048.jpg



View of the channel from the bridge facing upstream, 2020.

*** Location**
LS : Land Side
WS : Water Side
CR : Crown

**** Rating**
A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type
Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2020

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Little Chico Creek	8.00	07/30/2020 07/30/2020	Brooks Weisser

Check Point / View			
Bruce Street / Up (cont)			
Rating **	A	Issue No. 85	GPS Lat/Long
Issue Type +	Ma	Location *	39.733204 °
Category	Rivers, Channels & Designated Flood		-121.819610 °
Item	Shoaling / Sedimentation		
DWR ID	DWR_NA0060_12_c_2015_85		
Action/Comments			
Inspector Comments: No shoaling or sedimentaion was observed at this location.			

No Photos

Rating **	A	Issue No. 84	GPS Lat/Long
Issue Type +	Ma	Location *	39.733204 °
Category	Rivers, Channels & Designated Flood		-121.819610 °
Item	Erosion / Bank Caving		
DWR ID	DWR_NA0060_12_c_2015_84		
Action/Comments			
Inspector Comments: No erosion was observed at this location.			

No Photos

Rating **	N	Issue No. 88	GPS Lat/Long
Issue Type +	Ma	Location *	39.733204 °
Category	Rivers, Channels & Designated Flood		-121.819610 °
Item	Revetments		
DWR ID	DWR_NA0060_12_c_2015_88		
Action/Comments			
Inspector Comments: No riprap was observed.			

Photo 1 of 2 : CH_2020_NA0060_12_88_20200730_00030.jpg



View of the abutment right bank, no revetment was observed at either side, 2019.

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2020

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Little Chico Creek	8.00	07/30/2020 07/30/2020	Brooks Weisser

Check Point / View				
Bruce Street / Up (cont)				
Rating **	N	Issue No.	88 (cont)	GPS Lat/Long
Issue Type +	Ma	Location *		39.733204 °
Category	Rivers, Channels & Designated Flood			-121.819610 °
Item	Revetments			
DWR ID	DWR_NA0060_12_c_2015_88			
Action/Comments				
Inspector Comments: No riprap was observed.				



View of the abutment left bank, no revetment was observed at either side, 2019.

Rating **	M	Issue No.	87	GPS Lat/Long
Issue Type +	Ma	Location *		39.733204 °
Category	Rivers, Channels & Designated Flood			-121.819610 °
Item	Encroachments			
DWR ID	DWR_NA0060_12_c_2015_87			
Action/Comments				
Inspector Comments: Trash and debris left by campers should be removed.				



View of trash and debris left by campers, 2020.

<p>* Location</p> <p>LS : Land Side WS : Water Side CR : Crown</p>	<p>** Rating</p> <p>A : Acceptable M : Minimally Acceptable U : Unacceptable</p> <p>N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain</p>	<p>+ Issue Type</p> <p>Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement</p>
---	--	--

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2020

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Little Chico Creek	8.00	07/30/2020 07/30/2020	Brooks Weisser

Check Point / View

Bruce Street / Down

Rating **	A	Issue No.	89	GPS Lat/Long
Issue Type +	Ma	Location *		39.733204 °
Category	Rivers, Channels & Designated Flood			-121.819610 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0060_12_c_2015_89			

Action/Comments

Inspector Comments: There is some vegetation on the banks, but the channel is clear and the flow does not appear to be impeded.

Photo 1 of 1 : CH_2020_NA0060_12_89_20200805_00064.jpg



View of the channel from the bridge facing downstream, 2020.

Rating **	M	Issue No.	90	GPS Lat/Long
Issue Type +	Ma	Location *		39.733204 °
Category	Rivers, Channels & Designated Flood			-121.819610 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0060_12_c_2015_90			

Action/Comments

Inspector Comments: Sedimentation observed on the right bank downstream of the bridge should be removed, 2020.

Photo 1 of 1 : CH_2020_NA0060_12_90_20200805_00063.jpg



View of sedimentation on the downstream right bank, 2020.

Rating **	A	Issue No.	91	GPS Lat/Long
Issue Type +	Ma	Location *		39.733204 °
Category	Rivers, Channels & Designated Flood			-121.819610 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0060_12_c_2015_91			

Action/Comments

Inspector Comments: No erosion was observed.

No Photos

* Location
LS : Land Side
WS : Water Side
CR : Crown

** Rating	
A : Acceptable	N : Not Inspected/Rated
M : Minimally Acceptable	C : Corrected
U : Unacceptable	A/W : Acceptable but Monitor & Maintain

+ Issue Type
Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2020

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Little Chico Creek	8.00	07/30/2020 07/30/2020	Brooks Weisser

Check Point / View			
Bruce Street / Down (cont)			
Rating **	N	Issue No.	92
Issue Type +	Ma	Location *	39.733204 °
Category	Rivers, Channels & Designated Flood		-121.819610 °
Item	Revetments		
DWR ID	DWR_NA0060_12_c_2015_92		
Action/Comments			
Inspector Comments: No riprap was observed at this location.			

No Photos

Rating **	A	Issue No.	93
Issue Type +	Ma	Location *	39.733204 °
Category	Rivers, Channels & Designated Flood		-121.819610 °
Item	Encroachments		
DWR ID	DWR_NA0060_12_c_2015_93		
Action/Comments			
Inspector Comments: No encroachments were observed.			

No Photos

Check Point / View			
Boucher St / Up			
Rating **	M	Issue No.	41
Issue Type +	Ma	Location *	39.730240 °
Category	Rivers, Channels & Designated Flood		-121.823800 °
Item	Vegetation & Obstructions		
DWR ID	DWR_NA0060_12_c_2012_41		
Action/Comments			
Inspector Comments: There is vegetation in the channel and overhanging the channel, the flow could be impeded.			

Photo 1 of 1 : CH_2020_NA0060_12_41_20200805_00065.jpg



View of the channel from the bridge facing upstream, 2020.

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2020

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Little Chico Creek	8.00	07/30/2020 07/30/2020	Brooks Weisser

Check Point / View			
Boucher St / Up (cont)			
Rating **	A	Issue No. 42	GPS Lat/Long
Issue Type +	Ma	Location *	39.730240 °
Category	Rivers, Channels & Designated Flood		-121.823800 °
Item	Shoaling / Sedimentation		
DWR ID	DWR_NA0060_12_c_2012_42		
Action/Comments			
Inspector Comments: No shoaling or sedimentation observed.			

No Photos

Rating **	A	Issue No. 43	GPS Lat/Long
Issue Type +	Ma	Location *	39.730240 °
Category	Rivers, Channels & Designated Flood		-121.823800 °
Item	Erosion / Bank Caving		
DWR ID	DWR_NA0060_12_c_2012_43		
Action/Comments			
Inspector Comments: No erosion observed.			

No Photos

Rating **	N	Issue No. 44	GPS Lat/Long
Issue Type +	Ma	Location *	39.730240 °
Category	Rivers, Channels & Designated Flood		-121.823800 °
Item	Revetments		
DWR ID	DWR_NA0060_12_c_2012_44		
Action/Comments			
Inspector Comments: There was no riprap observed at this site.			

Photo 1 of 2 : CH_2020_NA0060_12_44_20200805_00046.jpg



View of the right bank abutment, no revetment present, 2020.

<p>* Location LS : Land Side WS : Water Side CR : Crown</p>	<p>** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain</p>	<p>+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement</p>
--	--	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2020

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Little Chico Creek	8.00	07/30/2020 07/30/2020	Brooks Weisser

Check Point / View			
Boucher St / Up (cont)			
Rating **	N	Issue No.	44 (cont)
Issue Type +	Ma	Location *	39.730240 °
Category	Rivers, Channels & Designated Flood		-121.823800 °
Item	Revetments		
DWR ID	DWR_NA0060_12_c_2012_44		
Action/Comments			
Inspector Comments: There was no riprap observed at this site.			



View of the left bank abutment, no revetment present, 2020

Rating **	A	Issue No.	45
Issue Type +	Ma	Location *	39.730240 °
Category	Rivers, Channels & Designated Flood		-121.823800 °
Item	Encroachments		
DWR ID	DWR_NA0060_12_c_2012_45		
Action/Comments			
Inspector Comments: Debris observed in the channel upstream of the bridge should be removed but will not impede the flow, 2020.			



View of debris in the channel upstream of the bridge, 2020.

<p>* Location</p> <p>LS : Land Side WS : Water Side CR : Crown</p>	<p>** Rating</p> <p>A : Acceptable M : Minimally Acceptable U : Unacceptable</p>	<p>N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain</p>	<p>+ Issue Type</p> <p>Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement</p>
---	---	--	--

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2020

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Little Chico Creek	8.00	07/30/2020 07/30/2020	Brooks Weisser

Check Point / View				
Boucher St / Down				
Rating **	M	Issue No.	46	GPS Lat/Long
Issue Type +	Ma	Location *		39.730240 °
Category	Rivers, Channels & Designated Flood			-121.823800 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0060_12_c_2012_46			
Action/Comments				
Inspector Comments: There is vegetation in the channel, overhanging the channel, and arundo. The flow does appear slightly impeded.				

Photo 1 of 1 : CH_2020_NA0060_12_46_20200805_00066.jpg



View of the channel from the bridge facing downstream, 2020.

Rating **	A	Issue No.	47	GPS Lat/Long
Issue Type +	Ma	Location *		39.730240 °
Category	Rivers, Channels & Designated Flood			-121.823800 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0060_12_c_2012_47			
Action/Comments				
Inspector Comments: No shoaling or sedimentation observed.				

No Photos

Rating **	A	Issue No.	48	GPS Lat/Long
Issue Type +	Ma	Location *		39.730240 °
Category	Rivers, Channels & Designated Flood			-121.823800 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0060_12_c_2012_48			
Action/Comments				
Inspector Comments: No erosion observed.				

No Photos

* Location
LS : Land Side
WS : Water Side
CR : Crown

** Rating
A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type
Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2020

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Little Chico Creek	8.00	07/30/2020 07/30/2020	Brooks Weisser

Check Point / View			
Boucher St / Down (cont)			
Rating **	N	Issue No.	49
Issue Type +	Ma	Location *	39.730240 °
Category	Rivers, Channels & Designated Flood		-121.823800 °
Item	Revetments		
DWR ID	DWR_NA0060_12_c_2012_49		
Action/Comments			
Inspector Comments: No riprap observed at this site.			

No Photos

Rating **	A	Issue No.	50
Issue Type +	Ma	Location *	39.730240 °
Category	Rivers, Channels & Designated Flood		-121.823800 °
Item	Encroachments		
DWR ID	DWR_NA0060_12_c_2012_50		
Action/Comments			
Inspector Comments: Debris and trash observed on the left bank under the bridge should be removed but will not impede the flow, 2020.			

Photo 1 of 1 : CH_2020_NA0060_12_50_20200805_00069.jpg



View of debris and trash left by campers on the left bank, 2020.

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2020

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Little Chico Creek	8.00	07/30/2020 07/30/2020	Brooks Weisser

Check Point / View			
Olive St / Up			
Rating **	A	Issue No.	51
Issue Type +	Ma	Location *	GPS Lat/Long
Category	Rivers, Channels & Designated Flood		39.726792 °
Item	Vegetation & Obstructions		-121.829713 °
DWR ID	DWR_NA0060_12_c_2012_51		
Action/Comments			
Inspector Comments: There is vegetation over the channel, it does not appear to impede the flow.			

Photo 1 of 1 : CH_2020_NA0060_12_51_20200805_00070.jpg



View of the channel from the bridge facing upstream, 2020.

Rating **	A	Issue No.	52
Issue Type +	Ma	Location *	GPS Lat/Long
Category	Rivers, Channels & Designated Flood		39.726792 °
Item	Shoaling / Sedimentation		-121.829713 °
DWR ID	DWR_NA0060_12_c_2012_52		
Action/Comments			
Inspector Comments: No shoaling or sedimentation observed.			

No Photos

Rating **	A	Issue No.	53
Issue Type +	Ma	Location *	GPS Lat/Long
Category	Rivers, Channels & Designated Flood		39.726792 °
Item	Erosion / Bank Caving		-121.829713 °
DWR ID	DWR_NA0060_12_c_2012_53		
Action/Comments			
Inspector Comments: No erosion observed.			

No Photos

* Location
LS : Land Side
WS : Water Side
CR : Crown

** Rating
A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type
Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2020

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Little Chico Creek	8.00	07/30/2020 07/30/2020	Brooks Weisser

Check Point / View				
Olive St / Up (cont)				
Rating **	N	Issue No.	54	GPS Lat/Long
Issue Type +	Ma	Location *		39.726792 °
Category	Rivers, Channels & Designated Flood			-121.829713 °
Item	Revetments			
DWR ID	DWR_NA0060_12_c_2012_54			
Action/Comments				
Inspector Comments: No riprap observed at this site.				

Photo 1 of 2 : CH_2020_NA0060_12_54_20200805_00074.jpg



View of the right abutment, no revetment present, 2020.

Photo 2 of 2 : CH_2020_NA0060_12_54_20200805_00075.jpg



View of the left abutment, no revetment present, 2020.

Rating **	N	Issue No.	54 (cont)	GPS Lat/Long
Issue Type +	Ma	Location *		39.726792 °
Category	Rivers, Channels & Designated Flood			-121.829713 °
Item	Revetments			
DWR ID	DWR_NA0060_12_c_2012_54			

Rating **	A	Issue No.	55	GPS Lat/Long
Issue Type +	Ma	Location *		39.726792 °
Category	Rivers, Channels & Designated Flood			-121.829713 °
Item	Encroachments			
DWR ID	DWR_NA0060_12_c_2012_55			
Action/Comments				
Inspector Comments: Trash and debris observed upstream of the bridge should be removed but will not impede the flow, 2020.				

Photo 1 of 1 : CH_2020_NA0060_12_55_20200805_00073.jpg



View of trash and debris left by campers upstream of the bridge, 2020.

* Location
LS : Land Side
WS : Water Side
CR : Crown

** Rating	
A : Acceptable	N : Not Inspected/Rated
M : Minimally Acceptable	C : Corrected
U : Unacceptable	A/W : Acceptable but Monitor & Maintain

+ Issue Type
Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2020

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Little Chico Creek	8.00	07/30/2020 07/30/2020	Brooks Weisser

Check Point / View			
Olive St / Down			
Rating **	A	Issue No.	56
Issue Type +	Ma	Location *	
Category	Rivers, Channels & Designated Flood		GPS Lat/Long
Item	Vegetation & Obstructions		
DWR ID	DWR_NA0060_12_c_2012_56		
Action/Comments			
Inspector Comments: There is vegetation over the channel, the flow does not appear impeded.			

Photo 1 of 1 : CH_2020_NA0060_12_56_20200805_00071.jpg



View of the channel from the bridge facing downstream, 2020.

Rating **	A	Issue No.	57
Issue Type +	Ma	Location *	
Category	Rivers, Channels & Designated Flood		GPS Lat/Long
Item	Shoaling / Sedimentation		
DWR ID	DWR_NA0060_12_c_2012_57		
Action/Comments			
Inspector Comments: There is minimal sedimentation in the channel, the flow does not appear impeded.			

No Photos

Rating **	A	Issue No.	58
Issue Type +	Ma	Location *	
Category	Rivers, Channels & Designated Flood		GPS Lat/Long
Item	Erosion / Bank Caving		
DWR ID	DWR_NA0060_12_c_2012_58		
Action/Comments			
Inspector Comments: No erosion observed.			

No Photos

* Location
LS : Land Side
WS : Water Side
CR : Crown

** Rating
A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type
Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2020

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Little Chico Creek	8.00	07/30/2020 07/30/2020	Brooks Weisser

Check Point / View			
Olive St / Down (cont)			
Rating **	N	Issue No.	59
Issue Type +	Ma	Location *	39.726792 °
Category	Rivers, Channels & Designated Flood		-121.829713 °
Item	Revetments		
DWR ID	DWR_NA0060_12_c_2012_59		
Action/Comments			
Inspector Comments: No riprap observed at this site.			

No Photos

Rating **	A	Issue No.	60
Issue Type +	Ma	Location *	39.726792 °
Category	Rivers, Channels & Designated Flood		-121.829713 °
Item	Encroachments		
DWR ID	DWR_NA0060_12_c_2012_60		
Action/Comments			
Inspector Comments: No trash, debris, excavation, structures, or other obstructions present within the easement.			

No Photos

Check Point / View			
Broadway St / Up			
Rating **	M	Issue No.	61
Issue Type +	Ma	Location *	39.724328 °
Category	Rivers, Channels & Designated Flood		-121.835233 °
Item	Vegetation & Obstructions		
DWR ID	DWR_NA0060_12_c_2012_61		
Action/Comments			
Inspector Comments: There are scattered obstructions and vegetation which may impede the flow of the channel.			

Photo 1 of 1 : CH_2020_NA0060_12_61_20200730_00020.jpg



View of the channel from the bridge facing upstream, 2019.

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2020

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Little Chico Creek	8.00	07/30/2020 07/30/2020	Brooks Weisser

Check Point / View			
Broadway St / Up (cont)			
Rating **	A	Issue No. 62	GPS Lat/Long
Issue Type +	Ma	Location *	39.724328 °
Category	Rivers, Channels & Designated Flood		-121.835233 °
Item	Shoaling / Sedimentation		
DWR ID	DWR_NA0060_12_c_2012_62		
Action/Comments			
Inspector Comments: No shoaling or sedimentation observed.			

No Photos

Rating **	A	Issue No. 63	GPS Lat/Long
Issue Type +	Ob	Location *	39.724328 °
Category	Rivers, Channels & Designated Flood		-121.835233 °
Item	Erosion / Bank Caving		
DWR ID	DWR_NA0060_12_c_2012_63		
Action/Comments			
Inspector Comments: No erosion observed.			

No Photos

Rating **	N	Issue No. 64	GPS Lat/Long
Issue Type +	Ma	Location *	39.724328 °
Category	Rivers, Channels & Designated Flood		-121.835233 °
Item	Revetments		
DWR ID	DWR_NA0060_12_c_2012_64		
Action/Comments			
Inspector Comments: No riprap observed.			

Photo 1 of 2 : CH_2020_NA0060_12_64_20200805_00077.jpg



View of left abutment, no revetment observed, 2020.

<p>* Location</p> <p>LS : Land Side WS : Water Side CR : Crown</p>	<p>** Rating</p> <p>A : Acceptable M : Minimally Acceptable U : Unacceptable</p> <p>N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain</p>	<p>+ Issue Type</p> <p>Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement</p>
---	--	--

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2020

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Little Chico Creek	8.00	07/30/2020 07/30/2020	Brooks Weisser

Check Point / View			
Broadway St / Up (cont)			
Rating **	N	Issue No.	64 (cont)
Issue Type +	Ma	Location *	GPS Lat/Long
Category	Rivers, Channels & Designated Flood		39.724328 °
Item	Revetments		-121.835233 °
DWR ID	DWR_NA0060_12_c_2012_64		
Action/Comments			
Inspector Comments: No riprap observed.			

Photo 2 of 2 : CH_2020_NA0060_12_64_20200805_00078.jpg



View of right abutment, no revetment observed, 2020.

Rating **	M	Issue No.	65
Issue Type +	Ma	Location *	GPS Lat/Long
Category	Rivers, Channels & Designated Flood		39.724328 °
Item	Encroachments		-121.835233 °
DWR ID	DWR_NA0060_12_c_2012_65		
Action/Comments			
Inspector Comments: Wood debris observed in the channel upstream of the bridge should be removed, 2020.			

Photo 1 of 1 : CH_2020_NA0060_12_65_20200805_00076.jpg



View of wood debris in channel upstream of the bridge, 2020.

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2020

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Little Chico Creek	8.00	07/30/2020 07/30/2020	Brooks Weisser

Check Point / View				
Broadway St / Down				
Rating **	A	Issue No.	66	GPS Lat/Long
Issue Type +	Ma	Location *		39.724328 °
Category	Rivers, Channels & Designated Flood			-121.835233 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0060_12_c_2012_66			
Action/Comments				
Inspector Comments: There is vegetation over the channel, the flow does not appear impeded.				

Photo 1 of 1 : CH_2020_NA0060_12_66_20200805_00051.jpg



View of the channel from the bridge facing downstream, 2020.

Rating **	A	Issue No.	67	GPS Lat/Long
Issue Type +	Ma	Location *		39.724328 °
Category	Rivers, Channels & Designated Flood			-121.835233 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0060_12_c_2012_67			
Action/Comments				
Inspector Comments: No shoaling observed at this site.				

No Photos

Rating **	A	Issue No.	68	GPS Lat/Long
Issue Type +	Ma	Location *		39.724328 °
Category	Rivers, Channels & Designated Flood			-121.835233 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0060_12_c_2012_68			
Action/Comments				
Inspector Comments: No erosion observed at this site.				

No Photos

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2020

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Little Chico Creek	8.00	07/30/2020 07/30/2020	Brooks Weisser

Check Point / View			
Broadway St / Down (cont)			
Rating **	N	Issue No. 69	GPS Lat/Long
Issue Type +	Ma	Location *	39.724328 °
Category	Rivers, Channels & Designated Flood		-121.835233 °
Item	Revetments		
DWR ID	DWR_NA0060_12_c_2012_69		
Action/Comments			
Inspector Comments: No riprap observed at this site.			

No Photos

Rating **	A	Issue No. 70	GPS Lat/Long
Issue Type +	Ma	Location *	39.724328 °
Category	Rivers, Channels & Designated Flood		-121.835233 °
Item	Encroachments		
DWR ID	DWR_NA0060_12_c_2013_70		
Action/Comments			
Inspector Comments: No trash, debris, excavation, structures, or other obstructions present within the easement.			

No Photos

Check Point / View			
Ivy Street / Up			
Rating **	A	Issue No. 94	GPS Lat/Long
Issue Type +	Ma	Location *	39.720476 °
Category	Rivers, Channels & Designated Flood		-121.838990 °
Item	Vegetation & Obstructions		
DWR ID	DWR_NA0060_5_c_2015_94		
Action/Comments			
Inspector Comments: Scattered obstructions and vegetation over channel should not impede the flow of the channel.			

Photo 1 of 1 : CH_2020_NA0060_12_94_20200805_00079.jpg



View of the channel from the bridge facing upstream, 2020.

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2020

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Little Chico Creek	8.00	07/30/2020 07/30/2020	Brooks Weisser

Check Point / View			
Ivy Street / Up (cont)			
Rating **	A	Issue No.	95
Issue Type +	Ma	Location *	39.720476 °
Category	Rivers, Channels & Designated Flood		-121.838990 °
Item	Shoaling / Sedimentation		
DWR ID	DWR_NA0060_12_c_2015_95		
Action/Comments			
Inspector Comments: No shoaling or sedimentation was observed at this location.			

No Photos

Rating **	A	Issue No.	96
Issue Type +	Ma	Location *	39.720476 °
Category	Rivers, Channels & Designated Flood		-121.838990 °
Item	Erosion / Bank Caving		
DWR ID	DWR_NA0060_12_c_2015_96		
Action/Comments			
Inspector Comments: No erosion was observed.			

No Photos

Rating **	A	Issue No.	97
Issue Type +	Ma	Location *	39.720476 °
Category	Rivers, Channels & Designated Flood		-121.838990 °
Item	Revetments		
DWR ID	DWR_NA0060_12_c_2015_97		
Action/Comments			
Inspector Comments: Sandbag revetment on left bank of abutment, no revetment on right bank and none needed.			

Photo 1 of 2 : CH_2020_NA0060_12_97_20200805_00081.jpg



View of right bank of abutment, no revetment present, 2020.

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2020

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Little Chico Creek	8.00	07/30/2020 07/30/2020	Brooks Weisser

Check Point / View			
Ivy Street / Up (cont)			
Rating **	A	Issue No.	97 (cont)
Issue Type +	Ma	Location *	GPS Lat/Long
Category	Rivers, Channels & Designated Flood		39.720476 °
Item	Revetments		-121.838990 °
DWR ID	DWR_NA0060_12_c_2015_97		
Action/Comments			
Inspector Comments: Sandbag revetment on left bank of abutment, no revetment on right bank and none needed.			

Photo 2 of 2 : CH_2020_NA0060_12_97_20200805_00082.jpg



View of left bank of abutment with sandbag revetment, 2020.

Check Point / View			
Rating **	M	Issue No.	98
Issue Type +	Ma	Location *	GPS Lat/Long
Category	Rivers, Channels & Designated Flood		39.720476 °
Item	Encroachments		-121.838990 °
DWR ID	DWR_NA0060_12_c_2015_98		
Action/Comments			
Inspector Comments: Wood debris is piled up against a bridge pier near the left bank and should be removed, 2020.			

Photo 1 of 1 : CH_2020_NA0060_12_98_20200805_00083.jpg



View of wood debris piled on upstream bridge pier, 2020

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2020

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Little Chico Creek	8.00	07/30/2020 07/30/2020	Brooks Weisser

Check Point / View				
Ivy Street / Down				
Rating **	M	Issue No.	99	GPS Lat/Long
Issue Type +	Ma	Location *		39.720476 °
Category	Rivers, Channels & Designated Flood			-121.838990 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0060_12_c_2015_99			
Action/Comments				
Inspector Comments: Scattered obstructions and vegetation, may impede the flow of the channel.				

Photo 1 of 1 : CH_2020_NA0060_12_99_20200805_00084.jpg



View of the channel from the bridge facing downstream, 2020.

Rating **	A	Issue No.	100	GPS Lat/Long
Issue Type +	Ma	Location *		39.720476 °
Category	Rivers, Channels & Designated Flood			-121.838990 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0060_12_c_2015_100			
Action/Comments				
Inspector Comments: No shoaling or sedimentation was observed.				

No Photos

Rating **	A	Issue No.	101	GPS Lat/Long
Issue Type +	Ma	Location *		39.720476 °
Category	Rivers, Channels & Designated Flood			-121.838990 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0060_12_c_2015_101			
Action/Comments				
Inspector Comments: No erosion was observed.				

No Photos

* Location
LS : Land Side
WS : Water Side
CR : Crown

** Rating
A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type
Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2020

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Little Chico Creek	8.00	07/30/2020 07/30/2020	Brooks Weisser

Check Point / View			
Ivy Street / Down (cont)			
Rating **	N	Issue No.	102
Issue Type +	Ma	Location *	GPS Lat/Long
Category	Rivers, Channels & Designated Flood		39.720476 °
Item	Revetments		-121.838990 °
DWR ID	DWR_NA0060_12_c_2015_102		
Action/Comments			
Inspector Comments: No revetment observed.			

No Photos

Rating **	A	Issue No.	103
Issue Type +	Ma	Location *	GPS Lat/Long
Category	Rivers, Channels & Designated Flood		39.720476 °
Item	Encroachments		-121.838990 °
DWR ID	DWR_NA0060_12_c_2015_103		
Action/Comments			
Inspector Comments: No trash, debris, excavation, structures, or other obstructions present within the easement.			

No Photos

Check Point / View			
Walnut Street / Up			
Rating **	A	Issue No.	104
Issue Type +	Ma	Location *	GPS Lat/Long
Category	Rivers, Channels & Designated Flood		39.718434 °
Item	Vegetation & Obstructions		-121.843512 °
DWR ID	DWR_NA0060_12_c_2015_104		
Action/Comments			
Inspector Comments: The channel appeared to be free of any vegetation that would impede the flow.			

Photo 1 of 1 : CH_2020_NA0060_12_104_20200805_00085.jpg



View of the channel from the bridge facing upstream, 2020.

* Location
LS : Land Side
WS : Water Side
CR : Crown

** Rating
A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type
Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2020

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Little Chico Creek	8.00	07/30/2020 07/30/2020	Brooks Weisser

Check Point / View			
Walnut Street / Up (cont)			
Rating **	A	Issue No. 105	GPS Lat/Long
Issue Type +	Ma	Location *	39.718434 °
Category	Rivers, Channels & Designated Flood		-121.843512 °
Item	Shoaling / Sedimentation		
DWR ID	DWR_NA0060_12_c_2015_105		
Action/Comments			
Inspector Comments: No shoaling or sedimentation was observed.			


No Photos

Rating **	A	Issue No. 106	GPS Lat/Long
Issue Type +	Ma	Location *	39.718434 °
Category	Rivers, Channels & Designated Flood		-121.843512 °
Item	Erosion / Bank Caving		
DWR ID	DWR_NA0060_12_c_2015_106		
Action/Comments			
Inspector Comments: No erosion was observed.			

No Photos

Rating **	M	Issue No. 107	GPS Lat/Long
Issue Type +	Ma	Location *	39.718434 °
Category	Rivers, Channels & Designated Flood		-121.843512 °
Item	Revetments		
DWR ID	DWR_NA0060_12_c_2015_107		
Action/Comments			
Inspector Comments: Revetment on right bank is overgrown with vegetation. Vegetation should be removed, 2020.			

Photo 1 of 2 : CH_2020_NA0060_12_107_20200805_00086.jpg



View of the right bank abutment, revetment present but overgrown, 2020.

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2020

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Little Chico Creek	8.00	07/30/2020 07/30/2020	Brooks Weisser

Check Point / View			
Walnut Street / Up (cont)			
Rating **	M	Issue No.	107 (cont)
Issue Type +	Ma	Location *	GPS Lat/Long
Category	Rivers, Channels & Designated Flood		39.718434 °
Item	Revetments		-121.843512 °
DWR ID	DWR_NA0060_12_c_2015_107		
Action/Comments			
Inspector Comments: Revetment on right bank is overgrown with vegetation. Vegetation should be removed, 2020.			

Photo 2 of 2 : CH_2020_NA0060_12_107_20200805_00087.jpg



View of the left bank abutment, no revetment present, 2020.

Rating **	A	Issue No.	108
Issue Type +	Ma	Location *	GPS Lat/Long
Category	Rivers, Channels & Designated Flood		39.718434 °
Item	Encroachments		-121.843512 °
DWR ID	DWR_NA0060_12_c_2015_108		
Action/Comments			
Inspector Comments: The channel appeared free of encroachments.			

No Photos

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2020

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Little Chico Creek	8.00	07/30/2020 07/30/2020	Brooks Weisser

Check Point / View			
Walnut Street / Down			
Rating **	A	Issue No.	109
Issue Type +	Ma	Location *	GPS Lat/Long
Category	Rivers, Channels & Designated Flood		39.718434 °
Item	Vegetation & Obstructions		-121.843512 °
DWR ID	DWR_NA0060_12_c_2015_109		
Action/Comments			
Inspector Comments: The channel appeared free of any vegetation that would impede the flow. Although the Arundo should be removed before it chokes down the channel.			

Photo 1 of 1 : CH_2020_NA0060_12_109_20200805_00088.jpg



View of the channel from the bridge facing upstream, 2020.

Rating **	A	Issue No.	110
Issue Type +	Ma	Location *	GPS Lat/Long
Category	Rivers, Channels & Designated Flood		39.718434 °
Item	Shoaling / Sedimentation		-121.843512 °
DWR ID	DWR_NA0060_12_c_2015_110		
Action/Comments			
Inspector Comments: No shoaling or sedimentation was observed.			

No Photos

Rating **	A	Issue No.	111
Issue Type +	Ma	Location *	GPS Lat/Long
Category	Rivers, Channels & Designated Flood		39.718434 °
Item	Erosion / Bank Caving		-121.843512 °
DWR ID	DWR_NA0060_12_c_2015_111		
Action/Comments			
Inspector Comments: No erosion was observed.			

No Photos

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2020

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Little Chico Creek	8.00	07/30/2020 07/30/2020	Brooks Weisser

Check Point / View			
Walnut Street / Down (cont)			
Rating **	M	Issue No. 112	GPS Lat/Long
Issue Type +	Ma	Location *	39.718434 °
Category	Rivers, Channels & Designated Flood		-121.843512 °
Item	Revetments		
DWR ID	DWR_NA0060_12_c_2015_112		
Action/Comments			
Inspector Comments: Revetment on right bank is overgrown with vegetation. Vegetation should be removed. No riprap was observed on left bank, 2020.			

No Photos

Rating **	A	Issue No. 113	GPS Lat/Long
Issue Type +	Ma	Location *	39.718434 °
Category	Rivers, Channels & Designated Flood		-121.843512 °
Item	Encroachments		
DWR ID	DWR_NA0060_12_c_2015_113		
Action/Comments			
Inspector Comments: The channel appeared free of encroachments.			

No Photos

Check Point / View			
Lone Pine Avenue / Up			
Rating **	M	Issue No. 71	GPS Lat/Long
Issue Type +	Ma	Location *	39.703260 °
Category	Rivers, Channels & Designated Flood		-121.868470 °
Item	Vegetation & Obstructions		
DWR ID	DWR_NA0060_12_c_2012_71		
Action/Comments			
Inspector Comments: Scattered obstructions and vegetation may impede the flow of the channel.			

Photo 1 of 1 : CH_2020_NA0060_12_71_20200805_00089.jpg



View of the channel from the bridge facing upstream, 2020.

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2020

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Little Chico Creek	8.00	07/30/2020 07/30/2020	Brooks Weisser

Check Point / View				
Lone Pine Avenue / Up (cont)				
Rating **	A	Issue No.	72	GPS Lat/Long
Issue Type +	Ma	Location *		39.703260 °
Category	Rivers, Channels & Designated Flood			-121.868470 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0060_12_c_2012_72			
Action/Comments				
Inspector Comments: No shoaling observed at this site.				

No Photos

Rating **	M	Issue No.	73	GPS Lat/Long
Issue Type +	Ma	Location *		39.703260 °
Category	Rivers, Channels & Designated Flood			-121.868470 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0060_12_c_2012_73			
Action/Comments				
Inspector Comments: Some erosion observed at this site under the revetment.				

Photo 1 of 1 : CH_2020_NA0060_12_73_20200805_00092.jpg



View of erosion under the sandbag revetment, 2020.

Rating **	A	Issue No.	74	GPS Lat/Long
Issue Type +	Ma	Location *		39.703260 °
Category	Rivers, Channels & Designated Flood			-121.868470 °
Item	Revetments			
DWR ID	DWR_NA0060_12_c_2012_74			
Action/Comments				
Inspector Comments: Concrete filled sandbags used for riprap at bridge abutments on both sides.				

Photo 1 of 2 : CH_2020_NA0060_12_74_20200805_00090.jpg



View of concrete sandbag revetment on the channels edge left bank, 2020.

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2020

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Little Chico Creek	8.00	07/30/2020 07/30/2020	Brooks Weisser

Check Point / View				
Lone Pine Avenue / Up (cont)				
Rating **	A	Issue No.	74 (cont)	GPS Lat/Long
Issue Type +	Ma	Location *		39.703260 °
Category	Rivers, Channels & Designated Flood			-121.868470 °
Item	Revetments			
DWR ID	DWR_NA0060_12_c_2012_74			
Action/Comments				
Inspector Comments: Concrete filled sandbags used for riprap at bridge abutments on both sides.				

Photo 2 of 2 : CH_2020_NA0060_12_74_20200805_00091.jpg



View of concrete sandbag revetment on the channels edge right bank, 2020.

Rating **	A	Issue No.	75	GPS Lat/Long
Issue Type +	Ma	Location *		39.703260 °
Category	Rivers, Channels & Designated Flood			-121.868470 °
Item	Encroachments			
DWR ID	DWR_NA0060_12_c_2012_75			
Action/Comments				
Inspector Comments: Debris observed upstream of bridge should be removed but will not impede flow, 2020.				

Photo 1 of 1 : CH_2020_NA0060_12_75_20200805_00093.jpg



View of debris in channel upstream of bridge, 2020.

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2020

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Little Chico Creek	8.00	07/30/2020 07/30/2020	Brooks Weisser

Check Point / View			
Lone Pine Avenue / Down			
Rating **	A	Issue No.	76
Issue Type +	Ma	Location *	39.703260 °
Category	Rivers, Channels & Designated Flood		-121.868470 °
Item	Vegetation & Obstructions		
DWR ID	DWR_NA0060_12_c_2012_76		
Action/Comments			
Inspector Comments: There is vegetation in the channel, the flow does not appear impeded.			

Photo 1 of 1 : CH_2020_NA0060_12_76_20200805_00052.jpg



View of the channel facing downstream from bridge, 2020.

Rating **	A	Issue No.	77
Issue Type +	Ma	Location *	39.703260 °
Category	Rivers, Channels & Designated Flood		-121.868470 °
Item	Shoaling / Sedimentation		
DWR ID	DWR_NA0060_12_c_2012_77		
Action/Comments			
Inspector Comments: No shoaling observed at this site.			

No Photos

Rating **	A	Issue No.	78
Issue Type +	Ma	Location *	39.703260 °
Category	Rivers, Channels & Designated Flood		-121.868470 °
Item	Erosion / Bank Caving		
DWR ID	DWR_NA0060_12_c_2012_78		
Action/Comments			
Inspector Comments: Minor erosion observed at this site under the revetment.			

No Photos

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2020

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Little Chico Creek	8.00	07/30/2020 07/30/2020	Brooks Weisser

Check Point / View			
Lone Pine Avenue / Down (cont)			
Rating **	A	Issue No. 79	GPS Lat/Long
Issue Type +	Ma	Location *	39.703260 °
Category	Rivers, Channels & Designated Flood		-121.868470 °
Item	Revetments		
DWR ID	DWR_NA0060_12_c_2012_79		
Action/Comments			
Inspector Comments: Concrete filled sandbags used for riprap at bridge abutments on both sides.			

No Photos

Rating **	A	Issue No. 80	GPS Lat/Long
Issue Type +	Ma	Location *	39.703260 °
Category	Rivers, Channels & Designated Flood		-121.868470 °
Item	Encroachments		
DWR ID	DWR_NA0060_12_c_2012_80		
Action/Comments			
Inspector Comments: No encroachments observed at this site.			

No Photos

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---