

**EAST-WEST INTERCEPTOR CANAL**  
(State of California)

Plate No. 1  
Locks - State

Unit No. 1 - West Interceptor Canal

Rock = 0.00

Mile

Inspection Log

Access: Highway 20 west to the town of Sutter. Turn right on Acacia Ave, drive through town to south side canal. Turn left, drive along canal to high ground.

0.00- 0.39	Start of right bank West Side Interceptor Canal at high ground. No access in wet weather. Two almond trees on almond trees. Mileage runs downstream.
0.00- 0.35	Fence on left bank.
0.00- 0.01	Turnaround on landward side.
0.09	Ramp on the landward slope.
0.09- 0.34	Orchard on landward side.
0.28	Ramp on the waterward side. Wooden bridge across canal to residence.
0.32- 1.34	Canal is concrete lined.
0.35	14-inch pipe with flapgate through left bank.
0.35	Cross fence with wood panel gate.
0.35	Overhead power line crosses road. Overhead telephone line crosses road. Pole on waterward side.

Unit No. 1 - West Interceptor Canal (Continued)

Mile

Inspection Log

0.35 Acacia Avenue crosses canal. Bridge across channel. 84-inch and 36-inch pipes through bridge.

0.36 Cross fence, pipe gate.

0.36-0.40 Fence along landward toe.

0.37-0.47 Fence along left bank.

0.41-0.44 Two dwellings with fence at landward toe.

0.44-0.50 Fenceposts at landward toe.

0.50 Cross fence, pipe gate.

0.50-0.84 Paved road along landward toe. (Webb Lane)

0.60-0.84 Oleander trees at landward toe.

0.62 Two trees in bank.

0.66 Wooden bridge across canal.

0.66-0.84 Crown roadway graveled. (McKee Lane).

0.71 Power pole anchor on waterward bank.

0.84 Four overhead power lines cross levee.

Unit No. 1 - West Interceptor Canal (Continued)

<u>Mile</u>	<u>Inspection Log</u>
0.84	Everett road crosses levee. Concrete bridge across canal. 84-inch pipe through bridge.
0.85	Cross fence, pipe gate.
0.85- 0.89	Barb wire fence along the landward toe.
0.89	Chain link enclosure on the waterward side with pump, power line, and distribution box. 12-inch pipe crosses canal at crown elevation.
0.89 0.90	Dwelling on landward side. Landscaping and equipment at toe.
1.09	Concrete standpipe on landward side.
1.11- 1.29	Row of black walnut trees along the landward side.
1.31- 1.33	High tower power lines cross levee.
1.34	Cross fence, pipe gate.
1.34	Three overhead power lines cross levee.
1.34	Mollett road crosses levee. Bridge across canal.
1.35	Concrete structure with 30-inch irrigation pipe through roadway, 1 foot below the crown. Pipe crosses canal.
1.35	Cross fence, pipe gate.
1.56	Irrigation ditch on opposite bank.

Unit No. 1 - West Interceptor Canal (Continued)

Mile

Inspection Log

- 1.58 12-inch pipe through left bank. Open on waterward end.
- 1.68 Wooden bridge across canal.
- 1.75 End of Unit 1, West Interceptor Canal at Wadsworth Canal,  
Unit 2, L.M. 4.50.

**EAST-WEST INTERCEPTOR CANAL**  
(State of California)

Plate No. 1  
Locks - State

Unit No. 2 - East Interceptor Canal

Rock = 0.00

Mile

Inspection Log

- 0.00 Left bank levee of East Interceptor Canal at end of Wadsworth Canal L.M. 4.50, Unit 1. Mileage runs upstream. Access by way of Butte House Road and through Wadsworth Canal, Unit No. 1.
- 0.27 Cement slough across levee. No access across slough. Turnaround provided. Go back through Wadsworth Canal. Turn left on Butte House Road, drive 0.62 miles, then left of East Butte road for 0.24 mile to canal. Turn left and drive back to slough and L.M. 0.27.
- 0.27 Pump house with power pole on waterside in canal.
- 0.27 Power pole with anchor on landward side.
- 0.36 Large oak tree on both sides of levee crown.
- 0.37 Overhead power line crosses levee. Power poles on both slopes.
- 0.37 8-inch pipe through levee, 2 feet below the crown. Pump in canal.
- 0.38 Wooden bridge across canal.
- 0.51 Cross fence, wire drag gate.
- 0.51 East Butte Road crosses levee.
- 0.52 Overhead power line crosses levee. Power pole on waterward shoulder.

Unit No. 2 - East Interceptor Canal (Continued)

<u>Mile</u>	<u>Inspection Log</u>
0.53	Cross fence, pipe gate.
0.72	Abandoned power pole and electrical box on waterward shoulder.
0.72	Overhead power line crosses levee. Power pole with electrical box on landward slope.
0.73	Power pole on waterward shoulder with pump on berm.
0.74	Concrete standpipe on landward side.
0.92	Levee raised 15 feet.
1.02	Ramp on the landward slope.
1.02	24-inch CM pipe through the levee, 8 feet below the crown.
1.20	Snake creek on opposite side.
1.38	Sutter Slough crosses the levee below crown elevation. Wooden flume in channel. No vehicular access. Turnaround provided. Go back to East Butte Road, turn left, and left again on Township Road. Proceed to south levee of Canal (Amarel Grain), turn left on levee and return to slough at L.M. 1.39.
1.39	36-inch pipe in pump house on platform. 24-inch pipe in pump house on platform. Flap gates in Sutter Slough. Power pole on levee with electrical box.
1.39	Overhead power line crosses levee. Power pole with anchor on landward side.
1.39- 1.51	Power poles along landward side.

Unit No. 2 - East Interceptor Canal (Continued)

Mile

Inspection Log

- 1.41- Concrete rubble on crown roadway and along landward side.  
1.50
- 1.51 Cross fence, pipe gate.
- 1.51- Barb wire fence on landward shoulder.  
1.78
- 1.54 16-inch CM pipe through the levee, 5 feet below the crown. Open on the waterward end.
- 1.67 4-inch pipe through levee, 4 feet below crown roadway and across channel.
- 1.68 Confluence of slough across canal.
- 1.69 Cross fence with gate.
- 1.74 Cross fence with gate.
- 1.78 Cross fence with metal drive gate.
- 1.92 Cross fence, pipe gate.
- 1.92- Amarel Grain Co. on landward side. Warehouse, grain  
2.04 storage, equipment.
- 1.99 12-inch PVC pipe under roadway, 2 feet below the crown.
- 2.02 Chain link fence with double gates.
- 2.04 Three overhead power lines cross levee. Power pole on landward side.
- 2.04 Township Road crosses levee at crown elevation.

Unit No. 2 - East Interceptor Canal (Continued)

Mile

Inspection Log

- 2.04- Paved crown roadway (Pease Road).  
3.01
- 2.04- Power poles along landward slope.  
3.01
- 2.43 Ramp on landward slope.
- 2.47 Overhead power line crosses levee.
- 2.59 Wooden bridge across canal.
- 2.68 Driveway on landward side.
- 2.81 Wooden bridge across canal with mailbox.
- 2.99 Wooden bridge across canal with mailbox.
- 3.01 End of Unit 2, East Interceptor Canal. Canal continues  
in a northeast direction.