Flood Control Project Maintenance

2013 Channel Summary Report

Overall Unit and Item Ratings

Adin Community Service District

Ash Creek

Overall Unit Rating	Rated Item	Item Rating
A	Vegetation & Obstructions	A
	Shoaling / Sedimentation	A
	Erosion / Bank Caving	A
	Revetments & Other Structural Appurtenances	A
	Encroachments	A

Dry Creek

Overall Unit Rating	Rated Item	Item Rating
A	Vegetation & Obstructions	A
	Shoaling / Sedimentation	A
	Erosion / Bank Caving	A
	Revetments & Other Structural Appurtenances	A
	Encroachments	A

Flood Control Project Maintenance

2013 Channel Summary Report

Overall Unit and Item Ratings

DWR Sutter Maintenance Yard

Big Chico Creek

Overall Unit Rating	Rated Item	Item Rating
A	Vegetation & Obstructions	A
	Shoaling / Sedimentation	A
	Erosion / Bank Caving	A
	Revetments & Other Structural Appurtenances	A
	Encroachments	A

Lindo Channel & Sandy Gulch

Overall Unit Rating	Rated Item	Item Rating
A	Vegetation & Obstructions	A
	Shoaling / Sedimentation	A
	Erosion / Bank Caving	A
	Revetments & Other Structural Appurtenances	A
	Encroachments	A

Little Chico Creek

Overall Unit Rating	Rated Item	Item Rating
A	Vegetation & Obstructions	M
	Shoaling / Sedimentation	A
	Erosion / Bank Caving	A
	Revetments & Other Structural Appurtenances	A
	Encroachments	A

Flood Control Project Maintenance

2013 Channel Summary Report

Overall Unit and Item Ratings

Fairfield Suisun Sewer District

Laurel Creek

Overall Unit Rating	Rated Item	Item Rating
M	Vegetation & Obstructions	U
	Shoaling / Sedimentation	A
	Erosion / Bank Caving	A
	Revetments & Other Structural Appurtenances	A
	Encroachments	A

Ledgewood Creek

Overall Unit Rating	Rated Item	Item Rating
A	Vegetation & Obstructions	A
	Shoaling / Sedimentation	A
	Erosion / Bank Caving	A
	Revetments & Other Structural Appurtenances	A
	Encroachments	A

McCoy Creek

Overall Unit Rating	Rated Item	Item Rating
A	Vegetation & Obstructions	M
	Shoaling / Sedimentation	A
	Erosion / Bank Caving	A
	Revetments & Other Structural Appurtenances	A
	Encroachments	A

Union Avenue Diversion

Overall Unit Rating	Rated Item	Item Rating
A	Vegetation & Obstructions	A
	Shoaling / Sedimentation	A
	Erosion / Bank Caving	A
	Revetments & Other Structural Appurtenances	A
	Encroachments	A

Flood Control Project Maintenance

2013 Channel Summary Report

Overall Unit and Item Ratings

Madera County FCWCA

Ash Slough

Overall Unit Rating	Rated Item	Item Rating
A	Vegetation & Obstructions	A
	Shoaling / Sedimentation	A
	Erosion / Bank Caving	A
	Revetments & Other Structural Appurtenances	N
	Encroachments	A

Berenda Slough

Overall Unit Rating	Rated Item	Item Rating
U	Vegetation & Obstructions	U
	Shoaling / Sedimentation	U
	Erosion / Bank Caving	U
	Revetments & Other Structural Appurtenances	U
	Encroachments	M

Chowchilla River

Overall Unit Rating	Rated Item	Item Rating
A	Vegetation & Obstructions	A
	Shoaling / Sedimentation	A
	Erosion / Bank Caving	A
	Revetments & Other Structural Appurtenances	N
	Encroachments	A

Fresno River

Overall Unit Rating	Rated Item	Item Rating
M	Vegetation & Obstructions	U
	Shoaling / Sedimentation	U
	Erosion / Bank Caving	M
	Revetments & Other Structural Appurtenances	M
	Encroachments	A

Flood Control Project Maintenance

2013 Channel Summary Report

Overall Unit and Item Ratings

Merced Streams Group

Bear Creek

Overall Unit Rating	Rated Item	Item Rating
M	Vegetation & Obstructions	M
	Shoaling / Sedimentation	A
	Erosion / Bank Caving	M
	Revetments & Other Structural Appurtenances	M
	Encroachments	A

Black Rascal Creek

Overall Unit Rating	Rated Item	Item Rating
M	Vegetation & Obstructions	M
	Shoaling / Sedimentation	M
	Erosion / Bank Caving	M
	Revetments & Other Structural Appurtenances	A
	Encroachments	M

Burns Creek

Overall Unit Rating	Rated Item	Item Rating
A	Vegetation & Obstructions	M
	Shoaling / Sedimentation	A
	Erosion / Bank Caving	A
	Revetments & Other Structural Appurtenances	N
	Encroachments	A

Mariposa Creek & Duck Slough

Overall Unit Rating	Rated Item	Item Rating
M	Vegetation & Obstructions	M
	Shoaling / Sedimentation	A
	Erosion / Bank Caving	M
	Revetments & Other Structural Appurtenances	A
	Encroachments	A

Miles Creek

Overall Unit Rating	Rated Item	Item Rating
A	Vegetation & Obstructions	M
	Shoaling / Sedimentation	A
	Erosion / Bank Caving	A
	Revetments & Other Structural Appurtenances	A
	Encroachments	A

Owens Creek

Overall Unit Rating	Rated Item	Item Rating
A	Vegetation & Obstructions	A
	Shoaling / Sedimentation	A
	Erosion / Bank Caving	A
	Revetments & Other Structural Appurtenances	A
	Encroachments	M

Flood Control Project Maintenance

2013 Channel Summary Report

Overall Unit and Item Ratings

Placer County

Truckee River

Overall Unit Rating	Rated Item	Item Rating
A	Vegetation & Obstructions	A
	Shoaling / Sedimentation	A
	Erosion / Bank Caving	A
	Revetments & Other Structural Appurtenances	A
	Encroachments	A

Flood Control Project Maintenance

2013 Channel Summary Report

Overall Unit and Item Ratings

San Joaquin County Flood Control and Water Conservation District

Duck Creek Diversion Channel

Overall Unit Rating	Rated Item	Item Rating
A	Vegetation & Obstructions	A
	Shoaling / Sedimentation	A
	Erosion / Bank Caving	A
	Revetments & Other Structural Appurtenances	A
	Encroachments	A

North Littlejohn Creek

Overall Unit Rating	Rated Item	Item Rating
M	Vegetation & Obstructions	M
	Shoaling / Sedimentation	A
	Erosion / Bank Caving	A
	Revetments & Other Structural Appurtenances	A
	Encroachments	M

South Littlejohn Creek

Overall Unit Rating	Rated Item	Item Rating
M	Vegetation & Obstructions	M
	Shoaling / Sedimentation	A
	Erosion / Bank Caving	A
	Revetments & Other Structural Appurtenances	A
	Encroachments	M

South Littlejohn Creek North Branch

Overall Unit Rating	Rated Item	Item Rating
A	Vegetation & Obstructions	A
	Shoaling / Sedimentation	A
	Erosion / Bank Caving	M
	Revetments & Other Structural Appurtenances	A
	Encroachments	A

Flood Control Project Maintenance

2013 Channel Summary Report

Overall Unit and Item Ratings

Tehama County Flood Control and Water Conservation District

McClure Creek

Overall Unit Rating	Rated Item	Item Rating
A	Vegetation & Obstructions	M
	Shoaling / Sedimentation	A
	Erosion / Bank Caving	A
	Revetments & Other Structural Appurtenances	N
	Encroachments	A

Salt Creek

Overall Unit Rating	Rated Item	Item Rating
A	Vegetation & Obstructions	A
	Shoaling / Sedimentation	A
	Erosion / Bank Caving	A
	Revetments & Other Structural Appurtenances	A
	Encroachments	A