

Appendix **C**

Miscellaneous Summary Reports

This Appendix includes two Local Maintaining Agencies that maintain Project Channels and are outside of Sacramento and San Joaquin River basins.


Appendix C includes:

- Miscellaneous Index
- Map
- Individual local Area Summary Profiles

This page is intentionally left blank

Local Agencies & Areas	County	Tab Name	Short Name	Page
Named Areas				
Fairfield Suisun Sewer District (Channels)	Solano	FSSD	NA0035	C - 5
Placer County (Channels)	Placer	Truckee River	NA0045	C - 9

This page is intentionally left blank




 **Map of LMA (Other Flood Control Systems)**

Fairfield Suisun Sewer District Channels

Solano County

Contact

Gregory Baatrup
District Manager
1010 Chadbourne Road
Fairfield CA 94534-9700
Phone: (707) 429-8930



LMA Short Name : NA0035	Bank	Unit Length (Miles)
-------------------------	------	---------------------

No Units Associated with this District.

Threat Assessment & Recommendations

- Soil and vegetation exist that may significantly impact the capacity of channels in this Area.
- The LMA should ensure that the capacity of the channel as designed and constructed is maintained.

DWR Levee Inspection Summary

Levees in this District are not Inspected.

DWR Structure Inspection Summary

No Structures Inspected in this District.

DWR Channel Inspection Summary

Channel Name	Overall Rating
Laurel Creek	M
Ledgewood Creek	A
McCoy Creek	A
Union Avenue Diversion	A

DWR San Joaquin River Erosion Summary

No Supplemental Erosion Sites.

USACE Inspection Ratings Summary

No USACE Ratings available.

DWR Flood System Repair Project Summary

No POI Repair Sites.

DWR Summary of Local Maintaining Agency Report

No Reporting by this District.

This page is intentionally left blank

Placer County Channels

Placer County

Contact

Brian Keating
District Manager
3091 County Center Drive Suite 220
Auburn CA 95603
Phone: (530) 745-7592



LMA Short Name : NA0045	Bank	Unit Length (Miles)
-------------------------	------	---------------------

No Units Associated with this District.

Threat Assessment & Recommendations

- The LMA should continue to maintain the area at the high level seen during the last Channel inspection.

DWR Levee Inspection Summary

Levees in this District are not Inspected.

DWR Structure Inspection Summary

No Structures Inspected in this District.

DWR Channel Inspection Summary

Channel Name	Overall Rating
Truckee River	A

DWR San Joaquin River Erosion Summary

No Supplemental Erosion Sites.

USACE Inspection Ratings Summary

No USACE Ratings available.

DWR Flood System Repair Project Summary

No POI Repair Sites.

DWR Summary of Local Maintaining Agency Report

No Reporting by this District.

This page is intentionally left blank