

Appendix **C**

Miscellaneous Summary Reports


This Appendix includes reporting of a Non Project Levee in the San Joaquin River Flood Control Project. It also includes channels in areas that are outside of the the Sacramento and San Joaquin River Flood Control Project. Appendix C includes:

- Miscellaneous Index
- Map
- Individual local area Summary Profiles



| Local Agencies & Areas | County | Tab Name | Short Name | Page |
|--|-------------|---------------|------------|------|
| Reclamation Districts | | | | |
| Reclamation District No. 2074 Sargent-Barnhart Tract | San Joaquin | RD 2074 | RD2074 | 5 |
| Named Areas | | | | |
| Adin Community Service District | Modoc | Adin | NA0030 | 9 |
| Fairfield Suisun Sewer District | Solano | FSSD | NA0035 | 13 |
| Placer County | Placer | Truckee River | NA0045 | 17 |





Reclamation District No. 2074 Sargent-Barnhart Tract

San Joaquin County

Contact

Nelson Bahler
President
PO Box 7576
Stockton CA 95267
Phone: (209) 473-6024



| Levee Short Name : RD2074 | Bank | Unit Length (Miles) |
|---|------|---------------------|
| No Units Associated with this District. | | |

Threat Assessment & Recommendations

- DWR does not inspect this area and no threat assessment or recommendations were done.

DWR Levee Inspection Summary

Levees in this District are not Inspected.

DWR Structure Inspection Summary

No Structures Inspected in this District.

DWR Channel Inspection Summary

No Channels Inspected in this District.

DWR San Joaquin River Erosion Summary

No Supplemental Erosion Sites.

USACE Inspection Ratings Summary

| System Name | Length (Miles) | RIP Status | RIP Date | Rating |
|-----------------------------|----------------|------------|----------|--------|
| No USACE Ratings available. | | | | |

DWR Summary of Local Maintaining Agency Report

Part 1 Information known to the Local Agency that is relevant to the condition or performance of the Project Levee (or jurisdictional Non-Project Levee)

The Agency stated that existing encroachments are regularly inspected and new encroachments will meet CVFPB, DWR, and USACE standards. The Agency also reported regular maintenance activities and good levee condition.

Part 2 Information identifying known conditions that might impair or compromise the level of flood protection provided by the Project Levee (or jurisdictional Non-Project Levee)

No information was provided by the Agency for Part 2.

Part 3 A summary of maintenance performed by the Local Agency during the previous fiscal year

The Agency provided a summary of maintenance activities accomplished for all levee units. Activities included encroachment control, erosion repair, gate repair, inspection, road maintenance, rodent control, and vegetation control.

Part 4 A statement of work and estimated cost for operation and maintenance of the Project Levee (or jurisdictional Non-Project Levee) for the current fiscal year, as approved by the Local Agency

The Agency provided a summary of expenses and maintenance activities planned for all levee units. Expenses include costs of encroachment control, erosion repair including riprap revetment, gate repair, installation of flap gates on the storm drain pipe, roadway maintenance, rodent control, and vegetation control. The reported total estimated cost for the current fiscal year is \$635,000.

Part 5 Any other readily available information contained in the records of the Local Agency relevant to the condition or performance of the Project Levee (or jurisdictional Non-Project Levee), as determined by the CVFPB or DWR

The Agency reported the Five Year Plan, Emergency Procedures Manual, Existing Encroachment Permits, and Operation and Maintenance Activity Logs are available upon request.

Adin Community Service District

Modoc County

Contact

Katie Bidwell
President
PO Box 258
Adin CA 96006
Phone: (530) 260-6396



| Levee Short Name : NA0030 | Bank | Unit Length (Miles) |
|---------------------------|------|---------------------|
|---------------------------|------|---------------------|

No Units Associated with this District.

Threat Assessment & Recommendations

- The LMA should continue to maintain the area at the high level seen during the last Channel inspection.

DWR Levee Inspection Summary

Levees in this District are not Inspected.

DWR Structure Inspection Summary

No Structures Inspected in this District.

DWR Channel Inspection Summary

| Channel Name | Overall Rating |
|--------------|----------------|
| Ash Creek | A |
| Dry Creek | A |

DWR San Joaquin River Erosion Summary

No Supplemental Erosion Sites.

USACE Inspection Ratings Summary

| System Name | Length (Miles) | RIP Status | RIP Date | Rating |
|-----------------------------|----------------|------------|----------|--------|
| No USACE Ratings available. | | | | |

DWR Summary of Local Maintaining Agency Report

No Reporting by this District.

Fairfield Suisun Sewer District

Solano County

Contact

Kevin Cullen
Senior Environmental Engineer
1010 Chadbourne Road
Fairfield CA 94534-9700
Phone: (707) 429-8930



| Levee Short Name : NA0035 | Bank | Unit Length (Miles) |
|---|------|---------------------|
| No Units Associated with this District. | | |

Threat Assessment & Recommendations

- Soil and vegetation exist that may significantly impact the capacity of channels in this Area.
- The LMA should ensure that the capacity of the channel as designed and constructed is maintained.

DWR Levee Inspection Summary

Levees in this District are not Inspected.

DWR Structure Inspection Summary

No Structures Inspected in this District.

DWR Channel Inspection Summary

| Channel Name | Overall Rating |
|------------------------|----------------|
| Laurel Creek | M |
| Ledgewood Creek | M * |
| McCoy Creek | A |
| Union Avenue Diversion | A |

* Overall channel rating average is less than 20.00%; however, U rated issues are present, so the Overall rating is M instead of A.

DWR San Joaquin River Erosion Summary

No Supplemental Erosion Sites.

USACE Inspection Ratings Summary

| System Name | Length (Miles) | RIP Status | RIP Date | Rating |
|-----------------------------|----------------|------------|----------|--------|
| No USACE Ratings available. | | | | |

DWR Summary of Local Maintaining Agency Report

No Reporting by this District.

Placer County

Placer County

Contact

Brian Keating
District Manager
3091 County Center Drive Suite 220
Auburn CA 95603
Phone: (530) 745-7592



| Levee Short Name : NA0045 | Bank | Unit Length (Miles) |
|---------------------------|------|---------------------|
|---------------------------|------|---------------------|

No Units Associated with this District.

Threat Assessment & Recommendations

- The LMA should continue to maintain the area at the high level seen during the last Channel inspection.

DWR Levee Inspection Summary

Levees in this District are not Inspected.

DWR Structure Inspection Summary

No Structures Inspected in this District.

DWR Channel Inspection Summary

| Channel Name | Overall Rating |
|---------------|----------------|
| Truckee River | A |

DWR San Joaquin River Erosion Summary

No Supplemental Erosion Sites.

USACE Inspection Ratings Summary

| System Name | Length (Miles) | RIP Status | RIP Date | Rating |
|-----------------------------|----------------|------------|----------|--------|
| No USACE Ratings available. | | | | |

DWR Summary of Local Maintaining Agency Report

No Reporting by this District.

