

**Flood Control Project Maintenance  
Levee Inspections**

**Fall 2007 Levee Maintenance Deficiency Summary Report**

**Overall LMA & Unit Ratings, including Boat Survey Erosion**

**Sacramento River Basin**

Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments		
	PO Miles	CO Miles					
<b>NA0001</b>	Overall LMA Rating		Total LMA Miles		* Overall LMA Threshold Percent is less than 10.00%; however, U Rated Miles are present, so the Overall LMA Rating is M instead of A.		
<b>American River Flood Control District</b>	<b>M *</b>		<b>34.12</b>				
Vegetation	0.01		0.01	0.03%			
Encroachments	1.49		1.49	4.37%	15.33	0.01	
Erosion / Bank Caving	0.03	0.12	0.51	1.49%			
<i>LMA Totals:</i>	1.53	0.12	2.01	5.89% *	15.33	0.01	
<b>Unit No. 01 Arcade Creek</b>							
Overall Unit Rating		Total Unit Miles					
<b>A</b>		<b>2.10</b>					
Encroachments					1.01		
<i>Unit Totals:</i>	0.00	0.00	0.00	0.00%	1.01	0.00	
<b>Unit No. 02 Natomas E Canal</b>							
Overall Unit Rating		Total Unit Miles					
<b>A</b>		<b>4.00</b>					
Encroachments					0.23		
<i>Unit Totals:</i>	0.00	0.00	0.00	0.00%	0.23	0.00	
<b>Unit No. 03 American River</b>							
Overall Unit Rating		Total Unit Miles					
<b>A</b>		<b>3.42</b>					
Vegetation	0.01		0.01	0.29%			
Encroachments	0.15		0.15	4.39%	1.89		
<i>Unit Totals:</i>	0.16	0.00	0.16	4.68%	1.89	0.00	
<b>Unit No. 04 American River</b>							
Overall Unit Rating		Total Unit Miles					
<b>M</b>		<b>11.00</b>					
Encroachments	1.34		1.34	12.18%	7.26	0.01	
Erosion / Bank Caving	0.03	0.12	0.51	4.64%			
<i>Unit Totals:</i>	1.37	0.12	1.85	16.82%	7.26	0.01	
<b>Unit No. 05 Sacramento River</b>							
Overall Unit Rating		Total Unit Miles					
<b>A</b>		<b>0.40</b>					
Encroachments					0.30		
<i>Unit Totals:</i>	0.00	0.00	0.00	0.00%	0.30	0.00	

**Flood Control Project Maintenance  
Levee Inspections**

**Fall 2007 Levee Maintenance Deficiency Summary Report**

**Overall LMA & Unit Ratings, including Boat Survey Erosion**

**Sacramento River Basin (cont.)**

<b>Unit No. 06 Linda Creek</b>		Overall Unit Rating	Total Unit Miles				
		<b>A</b>	<b>1.30</b>				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments		
					PO Miles	CO Miles	
Encroachments					1.20		
<i>Unit Totals:</i>	0.00	0.00	0.00	0.00%	1.20	0.00	

  

<b>Unit No. 07 Arcade Creek</b>		Overall Unit Rating	Total Unit Miles				
		<b>A</b>	<b>1.90</b>				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments		
					PO Miles	CO Miles	
No Items							
<i>Unit Totals:</i>	0.00	0.00	0.00	0.00%	0.00	0.00	

  

<b>Unit No. 08 Magpie Creek Diversion</b>		Overall Unit Rating	Total Unit Miles				
		<b>A</b>	<b>1.50</b>				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments		
					PO Miles	CO Miles	
Encroachments					0.72		
<i>Unit Totals:</i>	0.00	0.00	0.00	0.00%	0.72	0.00	

  

<b>Unit No. 09 American River</b>		Overall Unit Rating	Total Unit Miles				
		<b>A</b>	<b>4.50</b>				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments		
					PO Miles	CO Miles	
Encroachments					1.59		
<i>Unit Totals:</i>	0.00	0.00	0.00	0.00%	1.59	0.00	

  

<b>Unit No. 10 American River</b>		Overall Unit Rating	Total Unit Miles				
		<b>A</b>	<b>4.00</b>				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments		
					PO Miles	CO Miles	
Encroachments					1.13		
<i>Unit Totals:</i>	0.00	0.00	0.00	0.00%	1.13	0.00	

  

<b>Unit No. 11 New Arcade Creek</b>		Overall Unit Rating	Total Unit Miles				
		<b>A</b>					
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments		
					PO Miles	CO Miles	
No Items							
<i>Unit Totals:</i>	0.00	0.00	0.00	0.00%	0.00	0.00	

**Flood Control Project Maintenance  
Levee Inspections  
LMA District Cover Sheet  
Fall 2007 Levee Inspection Results**

**American River Flood Control District**

	Spring (March - May)	Summer ** (June - August)	Fall (September - November)	Winter ** (December - February)
* Overall LMA Rating (Fall Only)			<b>M</b>	

\*\* Non-receipt of Summer or Winter Inspection Reports may effect overall annual rating.

\* **SPRING INSPECTIONS:** Overall maintenance ratings are not determined for the spring inspection results. Individual maintenance deficiencies are rated using the same criteria in the spring and in the fall.

**FALL INSPECTIONS:** The overall maintenance rating shown above is based on operation and maintenance deficiencies identified within the attached unit inspection reports.

Comments


**Flood Control Project Maintenance  
Levee Inspections**

**Unit Cover Sheet**

**Fall 2007 Levee Inspection Results**

**American River Flood Control District**

Waterway		Bank	Unit Miles
Unit No. 01 Arcade Creek		Left	2.10

	Spring (March - May)	Summer (June - August)	Fall (September - November)	Winter (December - February)
Date of Inspection				
DWR Inspector			Not Assigned	
Accompanied By				
Unit Maintenance Rating (Fall Only)			A	

Check one:

During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.

During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

Comments

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :

DWR Summer/Winter Inspection Reports  
3310 El Camino Avenue, Room LL-30  
Sacramento, CA 95821-9000.


**X** \_\_\_\_\_  
Signature of LMA Representative Date

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Fall 2007**

**American River Flood Control District**

Waterway	Bank	Unit Miles	Inspection Date	Inspector
Unit No. 01 Arcade Creek	Left	2.10		Not Assigned

LMR Line	Levee Mile		Category	Item	* Location	** Rating	Action/Comment	GPS Latitude/Longitude		Photo	Issue
	Start	End						Start	End		
1	0.00	2.10	Earthen Levee	Animal Control	LS	A	Exterminate rodents and backfill and compact or grout burrows.	°	°		1
2	0.00	2.10	Earthen Levee	Animal Control	WS	A	Exterminate rodents and backfill and compact or grout burrows.	°	°		2
3	0.74	0.77	Earthen Levee	Encroachments	LS	PO	Landscaping	°	°		3
4	1.10	1.30	Earthen Levee	Encroachments	LS	PO	Landscaping	°	°		4
5	1.30	2.10	Concrete Floodwalls	Concrete Surfaces	LS	A		°	°		6
6	1.30	2.10	Concrete Floodwalls	Monolith Joints	LS	A		°	°		5
7	1.32	2.10	Earthen Levee	Encroachments	LS	PO	Landscaping	°	°		7

<p><b>* Location</b></p> <p>LS : Land Side WS : Water Side CR : Crown</p>	<p><b>** Rating</b></p> <p>A : Acceptable M : Minimally Acceptable U : Unacceptable</p> <p>PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected</p>
---	---

**Flood Control Project Maintenance  
Levee Inspections**

**Unit Cover Sheet**

**Fall 2007 Levee Inspection Results**

**American River Flood Control District**

Waterway	Bank	Unit Miles
Unit No. 02 Natomas E Canal	Left	4.00

	Spring (March - May)	Summer (June - August)	Fall (September - November)	Winter (December - February)
Date of Inspection				
DWR Inspector			Not Assigned	
Accompanied By				
Unit Maintenance Rating (Fall Only)			A	

Check one:

During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.

During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

Comments

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :  
 DWR Summer/Winter Inspection Reports  
 3310 El Camino Avenue, Room LL-30  
 Sacramento, CA 95821-9000.


**X** \_\_\_\_\_  
 Signature of LMA Representative Date

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Fall 2007**

**American River Flood Control District**

Waterway				Bank	Unit Miles	Inspection Date	Inspector
Unit No. 02 Natomas E Canal				Left	4.00		Not Assigned

LMR Line	Levee Mile		Category	Item	* Location	** Rating	Action/Comment	GPS Latitude/Longitude		Photo	Issue
	Start	End						Start	End		
1	0.00	0.23	Earthen Levee	Encroachments	LS	PO	Landscaping	°	°		1
2	0.00	3.95	Earthen Levee	Animal Control	WS	A	Exterminate rodents and backfill and compact or grout burrows.	°	°		3
3	0.00	3.95	Earthen Levee	Animal Control	LS	A	Exterminate rodents and backfill and compact or grout burrows.	°	°		2

<p><b>* Location</b></p> <p>LS : Land Side                  WS : Water Side                  CR : Crown</p>	<p><b>** Rating</b></p> <p>A : Acceptable                      PO : Partially Obstructing                  M : Minimally Acceptable        CO : Completely Obstructing                  U : Unacceptable                    N : Not Inspected</p>
---	---

**Flood Control Project Maintenance  
Levee Inspections**

**Unit Cover Sheet**

**Fall 2007 Levee Inspection Results**

**American River Flood Control District**

Waterway	Bank	Unit Miles
Unit No. 03 American River	Right	3.42

	Spring (March - May)	Summer (June - August)	Fall (September - November)	Winter (December - February)
Date of Inspection				
DWR Inspector			Not Assigned	
Accompanied By				
Unit Maintenance Rating (Fall Only)			A	

Check one:

During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.

During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

Comments

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :  
 DWR Summer/Winter Inspection Reports  
 3310 El Camino Avenue, Room LL-30  
 Sacramento, CA 95821-9000.


**X** \_\_\_\_\_  
 Signature of LMA Representative Date

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Fall 2007**

**American River Flood Control District**

Waterway				Bank	Unit Miles	Inspection Date	Inspector
Unit No. 03 American River				Right	3.42		Not Assigned

LMR Line	Levee Mile		Category	Item	* Location	** Rating	Action/Comment	GPS Latitude/Longitude		Photo	Issue
	Start	End						Start	End		
1	0.00	0.01	Earthen Levee	Vegetation	LS	M	Control annual grass and weeds on the levee slopes and easements.	°	°		1
2	0.64	1.65	Earthen Levee	Encroachments	LS	PO	Landscaping	°	°		2
3	0.64	3.42	Earthen Levee	Animal Control	WS	A	Exterminate rodents and backfill and compact or grout burrows.	°	°		3
4	0.64	3.42	Earthen Levee	Animal Control	LS	A	Exterminate rodents and backfill and compact or grout burrows.	°	°		4
5	1.58	1.86	Earthen Levee	Encroachments	LS	PO	Landscaping	°	°		5
6	2.40	3.00	Earthen Levee	Encroachments	LS	PO	Landscaping	°	°		6
7	3.00	3.15	Earthen Levee	Encroachments	LS	M	Poles	°	°		7

<p><b>* Location</b>                  LS : Land Side                  WS : Water Side                  CR : Crown</p>	<p><b>** Rating</b>                  A : Acceptable                  M : Minimally Acceptable                  U : Unacceptable                  PO : Partially Obstructing                  CO : Completely Obstructing                  N : Not Inspected</p>
---	---

**Flood Control Project Maintenance  
Levee Inspections**

**Unit Cover Sheet**

**Fall 2007 Levee Inspection Results**

**American River Flood Control District**

Waterway		Bank	Unit Miles
Unit No. 04 American River		Left	11.00

	Spring (March - May)	Summer (June - August)	Fall (September - November)	Winter (December - February)
Date of Inspection				
DWR Inspector			Not Assigned	
Accompanied By				
Unit Maintenance Rating (Fall Only)			M	

Check one:

During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.

During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

Comments

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :

DWR Summer/Winter Inspection Reports  
3310 El Camino Avenue, Room LL-30  
Sacramento, CA 95821-9000.


**X** \_\_\_\_\_  
Signature of LMA Representative Date

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Fall 2007**

**American River Flood Control District**

Waterway	Bank	Unit Miles	Inspection Date	Inspector
Unit No. 04 American River	Left	11.00		Not Assigned

LMR Line	Levee Mile		Category	Item	Location*	Rating**	Action/Comment	GPS Latitude/Longitude		Photo	Issue
	Start	End						Start	End		
1	0.00	0.30	Earthen Levee	Encroachments	WS PO	Landscaping		°	°		1
2	0.00	0.70	Earthen Levee	Encroachments	LS PO	Landscaping		°	°		2
3	0.00	4.04	Earthen Levee	Animal Control	WS A	Exterminate rodents and backfill and compact or grout burrows.		°	°		3
4	0.00	4.04	Earthen Levee	Animal Control	LS A	Exterminate rodents and backfill and compact or grout burrows.		°	°		4
5	0.42	0.49	Earthen Levee	Erosion / Bank Caving	WS U	Schedule repair of erosion site prior to the next inspection.		°	°		5
6	1.38	1.38	Earthen Levee	Encroachments	WS CO	Buildings		°	°		6
7	1.40	1.45	Earthen Levee	Encroachments	LS PO	Landscaping		°	°		7
8	1.67	1.76	Earthen Levee	Encroachments	WS PO	Landscaping		°	°		8
9	1.88	1.88	Earthen Levee	Encroachments	LS M	Signs		°	°		9
10	1.95	2.20	Earthen Levee	Encroachments	LS M	Poles		°	°		10
11	2.50	2.55	Earthen Levee	Encroachments	LS PO	Fences		°	°		12
12	2.60	2.65	Earthen Levee	Erosion / Bank Caving	WS U	Schedule repair of erosion site prior to the next inspection.		°	°		13
13	2.65	2.72	Concrete Floodwalls	Concrete Surfaces	LS A			°	°		14
14	2.72	2.88	Earthen Levee	Encroachments	WS M	Pipe		°	°		16
15	2.72	2.88	Earthen Levee	Encroachments	LS M	Equipment		°	°		15
16	2.90	3.66	Earthen Levee	Encroachments	LS M	Material		°	°		17
17	4.00	7.30	Earthen Levee	Encroachments	LS PO	Landscaping		°	°		18
18	7.70	9.00	Earthen Levee	Encroachments	LS PO	Landscaping		°	°		19
19	9.50	10.97	Earthen Levee	Encroachments	LS PO	Landscaping		°	°		20

<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected
--	--

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Fall 2007**

**American River Flood Control District**

Waterway				Bank	Unit Miles	Inspection Date	Inspector
Unit No. 04 American River				Left	11.00		Not Assigned

LMR Line	Levee Mile		Category	Item	* Location	** Rating	Action/Comment	GPS Latitude/Longitude		Photo	Issue
	Start	End						Start	End		
20	9.57	9.57	Earthen Levee	Erosion / Bank Caving	WS	M	Schedule repair of erosion site prior to the next inspection.	°	°		21
21	10.19	10.21	Earthen Levee	Erosion / Bank Caving	WS	M	Schedule repair of erosion site prior to the next inspection.	°	°		11

<p><b>* Location</b></p> <p>LS : Land Side                  WS : Water Side                  CR : Crown</p>	<p><b>** Rating</b></p> <p>A : Acceptable                  M : Minimally Acceptable                  U : Unacceptable</p> <p>PO : Partially Obstructing                  CO : Completely Obstructing                  N : Not Inspected</p>
---	---

**Flood Control Project Maintenance  
Levee Inspections**

**Unit Cover Sheet**

**Fall 2007 Levee Inspection Results**

**American River Flood Control District**

Waterway	Bank	Unit Miles
Unit No. 05 Sacramento River	Left	0.40

	Spring (March - May)	Summer (June - August)	Fall (September - November)	Winter (December - February)
Date of Inspection				
DWR Inspector			Not Assigned	
Accompanied By				
Unit Maintenance Rating (Fall Only)			A	

Check one:

During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.

During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

Comments

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :  
 DWR Summer/Winter Inspection Reports  
 3310 El Camino Avenue, Room LL-30  
 Sacramento, CA 95821-9000.


**X** \_\_\_\_\_  
 Signature of LMA Representative Date

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Fall 2007**

**American River Flood Control District**

Waterway				Bank	Unit Miles	Inspection Date	Inspector
Unit No. 05 Sacramento River				Left	0.40		Not Assigned

LMR Line	Levee Mile		Category	Item	* Location	** Rating	Action/Comment	GPS Latitude/Longitude		Photo	Issue
	Start	End						Start	End		
1	0.00	0.30	Earthen Levee	Encroachments	LS	PO	Landscaping	°	°		1
2	0.00	0.40	Earthen Levee	Animal Control	WS	A	Exterminate rodents and backfill and compact or grout burrows.	°	°		3
3	0.00	0.40	Earthen Levee	Animal Control	LS	A	Exterminate rodents and backfill and compact or grout burrows.	°	°		2

<p><b>* Location</b></p> <p>LS : Land Side                  WS : Water Side                  CR : Crown</p>	<p><b>** Rating</b></p> <p>A : Acceptable                      PO : Partially Obstructing                  M : Minimally Acceptable        CO : Completely Obstructing                  U : Unacceptable                    N : Not Inspected</p>
---	---

**Flood Control Project Maintenance  
Levee Inspections**

**Unit Cover Sheet**

**Fall 2007 Levee Inspection Results**

**American River Flood Control District**

Waterway	Bank	Unit Miles
Unit No. 06 Linda Creek	Left	1.30

	Spring (March - May)	Summer (June - August)	Fall (September - November)	Winter (December - February)
Date of Inspection				
DWR Inspector			Not Assigned	
Accompanied By				
Unit Maintenance Rating (Fall Only)			A	

Check one:

During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.

During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

Comments

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :

DWR Summer/Winter Inspection Reports  
3310 El Camino Avenue, Room LL-30  
Sacramento, CA 95821-9000.


**X** \_\_\_\_\_  
Signature of LMA Representative Date

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Fall 2007**

**American River Flood Control District**

Waterway				Bank	Unit Miles	Inspection Date	Inspector
Unit No. 06 Linda Creek				Left	1.30		Not Assigned

LMR Line	Levee Mile		Category	Item	* Location	** Rating	Action/Comment	GPS Latitude/Longitude		Photo	Issue
	Start	End						Start	End		
1	0.00	0.20	Earthen Levee	Encroachments	LS	PO	Landscaping	°	°		1
2	0.00	1.00	Earthen Levee	Encroachments	WS	PO	Fences	°	°		2
3	0.00	1.30	Earthen Levee	Animal Control	WS	A	Exterminate rodents and backfill and compact or grout burrows.	°	°		4
4	0.00	1.30	Earthen Levee	Animal Control	LS	A	Exterminate rodents and backfill and compact or grout burrows.	°	°		3

<p><b>* Location</b></p> <p>LS : Land Side WS : Water Side CR : Crown</p>	<p><b>** Rating</b></p> <p>A : Acceptable M : Minimally Acceptable U : Unacceptable</p> <p>PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected</p>
---	---

**Flood Control Project Maintenance  
Levee Inspections**

**Unit Cover Sheet**

**Fall 2007 Levee Inspection Results**

**American River Flood Control District**

Waterway		Bank	Unit Miles
Unit No. 07 Arcade Creek		Right	1.90

	Spring (March - May)	Summer (June - August)	Fall (September - November)	Winter (December - February)
Date of Inspection				
DWR Inspector			Not Assigned	
Accompanied By				
Unit Maintenance Rating (Fall Only)			A	

Check one:

During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.

During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

Comments

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :

DWR Summer/Winter Inspection Reports  
3310 El Camino Avenue, Room LL-30  
Sacramento, CA 95821-9000.


**X** \_\_\_\_\_  
Signature of LMA Representative Date

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Fall 2007**

**American River Flood Control District**

Waterway				Bank	Unit Miles	Inspection Date	Inspector
Unit No. 07 Arcade Creek				Right	1.90		Not Assigned

LMR Line	Levee Mile		Category	Item	* Location	** Rating	Action/Comment	GPS Latitude/Longitude		Photo	Issue
	Start	End						Start	End		
1	0.00	1.91	Earthen Levee	Animal Control	WS	A	Exterminate rodents and backfill and compact or grout burrows.	°	°		1
2	0.00	1.91	Earthen Levee	Animal Control	LS	A	Exterminate rodents and backfill and compact or grout burrows.	°	°		2
3	1.35	1.92	Concrete Floodwalls	Monolith Joints	LS	A		°	°		4
4	1.35	1.92	Concrete Floodwalls	Concrete Surfaces	LS	A		°	°		3

<p><b>* Location</b>                  LS : Land Side                  WS : Water Side                  CR : Crown</p>	<p><b>** Rating</b>                  A : Acceptable                  M : Minimally Acceptable                  U : Unacceptable                  PO : Partially Obstructing                  CO : Completely Obstructing                  N : Not Inspected</p>
---	---

**Flood Control Project Maintenance  
Levee Inspections**

**Unit Cover Sheet**

**Fall 2007 Levee Inspection Results**

**American River Flood Control District**

Waterway	Bank	Unit Miles
Unit No. 08 Magpie Creek Diversion	Left	1.50

	Spring (March - May)	Summer (June - August)	Fall (September - November)	Winter (December - February)
Date of Inspection				
DWR Inspector			Not Assigned	
Accompanied By				
Unit Maintenance Rating (Fall Only)			A	

Check one:

During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.

During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

Comments

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :  
 DWR Summer/Winter Inspection Reports  
 3310 El Camino Avenue, Room LL-30  
 Sacramento, CA 95821-9000.


**X** \_\_\_\_\_  
 Signature of LMA Representative Date

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Fall 2007**

**American River Flood Control District**

Waterway			Bank	Unit Miles	Inspection Date	Inspector
Unit No. 08 Magpie Creek Diversion			Left	1.50		Not Assigned

LMR Line	Levee Mile		Category	Item	* Location	** Rating	Action/Comment	GPS Latitude/Longitude		Photo	Issue
	Start	End						Start	End		
1	0.32	0.51	Earthen Levee	Encroachments	LS	PO	Landscaping	°	°		1
2	0.32	0.51	Earthen Levee	Encroachments	WS	PO	Landscaping	°	°		2
3	1.06	1.20	Earthen Levee	Encroachments	LS	PO	Landscaping	°	°		3
4	1.25	1.45	Earthen Levee	Encroachments	WS	PO	Fences	°	°		4

<p><b>* Location</b></p> <p>LS : Land Side WS : Water Side CR : Crown</p>	<p><b>** Rating</b></p> <p>A : Acceptable M : Minimally Acceptable U : Unacceptable</p> <p>PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected</p>
---	---

**Flood Control Project Maintenance  
Levee Inspections**

**Unit Cover Sheet**

**Fall 2007 Levee Inspection Results**

**American River Flood Control District**

Waterway	Bank	Unit Miles
Unit No. 09 American River	Right	4.50

	Spring (March - May)	Summer (June - August)	Fall (September - November)	Winter (December - February)
Date of Inspection				
DWR Inspector			Not Assigned	
Accompanied By				
Unit Maintenance Rating (Fall Only)			A	

Check one:

During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.

During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

Comments

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :  
 DWR Summer/Winter Inspection Reports  
 3310 El Camino Avenue, Room LL-30  
 Sacramento, CA 95821-9000.


**X** \_\_\_\_\_  
 Signature of LMA Representative Date

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Fall 2007**

**American River Flood Control District**

Waterway				Bank	Unit Miles	Inspection Date	Inspector
Unit No. 09 American River				Right	4.50		Not Assigned

LMR Line	Levee Mile		Category	Item	* Location	** Rating	Action/Comment	GPS Latitude/Longitude		Photo	Issue
	Start	End						Start	End		
1	0.00	4.32	Earthen Levee	Animal Control	LS	A	Exterminate rodents and backfill and compact or grout burrows.	°	°		1
2	0.00	4.32	Earthen Levee	Animal Control	WS	A	Exterminate rodents and backfill and compact or grout burrows.	°	°		2
3	1.15	1.15	Earthen Levee	Encroachments	LS	PO	Landscaping	°	°		3
4	1.97	1.97	Earthen Levee	Encroachments	LS	PO	Fences	°	°		4
5	2.55	3.50	Earthen Levee	Encroachments	LS	PO	Landscaping	°	°		5
6	3.70	4.32	Earthen Levee	Encroachments	LS	PO	Landscaping	°	°		6

<p><b>* Location</b></p> <p>LS : Land Side WS : Water Side CR : Crown</p>	<p><b>** Rating</b></p> <p>A : Acceptable M : Minimally Acceptable U : Unacceptable</p> <p>PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected</p>
---	---

**Flood Control Project Maintenance  
Levee Inspections**

**Unit Cover Sheet**

**Fall 2007 Levee Inspection Results**

**American River Flood Control District**

Waterway	Bank	Unit Miles
Unit No. 10 American River	Right	4.00

	Spring (March - May)	Summer (June - August)	Fall (September - November)	Winter (December - February)
Date of Inspection				
DWR Inspector			Not Assigned	
Accompanied By				
Unit Maintenance Rating (Fall Only)			A	

Check one:

During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.

During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

Comments

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :  
 DWR Summer/Winter Inspection Reports  
 3310 El Camino Avenue, Room LL-30  
 Sacramento, CA 95821-9000.


**X** \_\_\_\_\_  
 Signature of LMA Representative Date

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Fall 2007**

**American River Flood Control District**

Waterway				Bank	Unit Miles	Inspection Date	Inspector
Unit No. 10 American River				Right	4.00		Not Assigned

LMR Line	Levee Mile		Category	Item	* Location	** Rating	Action/Comment	GPS Latitude/Longitude		Photo	Issue
	Start	End						Start	End		
1	0.00	4.00	Earthen Levee	Animal Control	LS	A	Exterminate rodents and backfill and compact or grout burrows.	°	°		1
2	0.00	4.00	Earthen Levee	Animal Control	WS	A	Exterminate rodents and backfill and compact or grout burrows.	°	°		2
3	0.70	1.20	Earthen Levee	Encroachments	WS	PO	Landscaping	°	°		3
4	1.25	1.45	Earthen Levee	Encroachments	WS	PO	Landscaping	°	°		4
5	3.57	4.00	Earthen Levee	Encroachments	LS	PO	Landscaping	°	°		5

<p><b>* Location</b></p> <p>LS : Land Side WS : Water Side CR : Crown</p>	<p><b>** Rating</b></p> <p>A : Acceptable M : Minimally Acceptable U : Unacceptable</p> <p>PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected</p>
---	---

**Flood Control Project Maintenance  
Levee Inspections**

**Unit Cover Sheet**

**Fall 2007 Levee Inspection Results**

**American River Flood Control District**

Waterway	Bank	Unit Miles
Unit No. 11 New Arcade Creek		

	Spring (March - May)	Summer (June - August)	Fall (September - November)	Winter (December - February)
Date of Inspection				
DWR Inspector			Not Assigned	
Accompanied By				
Unit Maintenance Rating (Fall Only)			A	

Check one:

During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.

During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

Comments

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to : DWR Summer/Winter Inspection Reports  
3310 El Camino Avenue, Room LL-30  
Sacramento, CA 95821-9000.


**X** \_\_\_\_\_  
Signature of LMA Representative Date

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Fall 2007**

**American River Flood Control District**

Waterway	Bank	Unit Miles	Inspection Date	Inspector
Unit No. 11 New Arcade Creek				Not Assigned

LMR Line	Levee Mile		Category	Item	Location *	Rating **	Action/Comment	GPS Latitude/Longitude		Photo	Issue
	Start	End						Start	End		
1								o	o		
								o	o		

<p><b>* Location</b>                  LS : Land Side                  WS : Water Side                  CR : Crown</p>	<p><b>** Rating</b>                  A : Acceptable                  M : Minimally Acceptable                  U : Unacceptable                  PO : Partially Obstructing                  CO : Completely Obstructing                  N : Not Inspected</p>
---	---