

**Flood Control Project Maintenance  
Levee Inspections  
LMA District Cover Sheet  
Spring 2013 Levee Inspection Results**

**Butte County Public Works Department Butte County Public Works**

	Spring (March - May)	Summer ** (June - August)	Fall (September - November)	Winter ** (December - February)
* Overall LMA Rating (Fall Only)				

\*\* Non-receipt of Summer or Winter Inspection Reports may effect overall annual rating.

\* SPRING INSPECTIONS: Overall maintenance ratings are not determined for the spring inspection results. Individual maintenance deficiencies are rated using the same criteria in the spring and in the fall.

FALL INSPECTIONS: The overall maintenance rating shown above is based on operation and maintenance deficiencies identified within the attached unit inspection reports. This rating is not intended to be an indication of risk.

Comments


**Flood Control Project Maintenance  
Levee Inspections**

**Unit Cover Sheet**

**Spring 2013 Levee Inspection Results**

**Butte County Public Works Department Butte County Public Works**

Waterway		Bank	Unit Miles
Unit No. 01 Mud Creek		Right	7.29

	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - February)
Unit Maintenance Rating (Fall Only)				
Date of Inspection	04/11/2013 - 04/11/2013			
DWR Inspector	Bob Duffey			
Accompanied By	Shawn Bates Butte County			

**Summer & Winter Inspections**

The Local Maintaining Agency (LMA) is responsible for summer and winter inspections. The LMA is required to submit a report regarding summer and winter inspections to the California Department of Water Resources (DWR).

DWR must be informed on the:

- a) completion of the inspection
- b) any changes other than the results of normal maintenance
- c) corrections to deficiencies noted in this report

If additional items are noted, further documentation of those items must also be submitted.

The LMA should submit this information to DWR using the LMA web application tool available at:

<http://cdec.water.ca.gov/lma.html>

If the LMA is unable to submit information on this webpage, please contact DWR for assistance.

*The LMA should submit the information and any associated documentation by September 30 for summer inspections and March 31 for winter inspections.*

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2013**

**Butte County Public Works Department Butte County Public Works**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Mud Creek	Right	7.29	04/11/2013 04/11/2013	Bob Duffey

LMR No.	Levee Mile		Category	Item	Location	Rating	Action/Comment	GPS Latitude/Longitude		Issue No. Photo
	Start	End						Start	End	
1				Operations & Maintenance Manuals	LS	A Ma		°	°	2
DWR ID: DWR_NA0003_01_s_2013_2										
2				Emergency Supplies & Equipment	LS	A Ma		°	°	6
DWR ID: DWR_NA0003_01_s_2013_6										
3				Flood Preparedness & Training	LS	A Ma		°	°	10
DWR ID: DWR_NA0003_01_s_2013_10										
4	2.06	2.10		Encroachments	LS	U En	FE : Fence	39.748330 ° -121.918685 °	39.748867 ° -121.918533 °	3 Y
DWR ID: DWR_NA0003_01_s_2012_3										
5	2.16	2.16		Encroachments	LS	U En	BU : Building	39.749732 ° -121.918270 °	39.749732 ° -121.918270 °	24
DWR ID: DWR_NA0003_01_s_2012_24										
6	2.18	2.25		Encroachments	LS	M En	FE : Fence	39.749917 ° -121.917738 °	39.753355 ° -121.922915 °	4
DWR ID: DWR_NA0003_01_s_2012_4										
7	3.00	3.00		Encroachments	LS	M Ma	PR : Prunings	39.759755 ° -121.911160 °	39.759755 ° -121.911160 °	1 Y
DWR ID: DWR_NA0003_01_s_2012_1										
8	3.10	3.10		Encroachments	LS	M Ma	PR : Prunings	39.761085 ° -121.911048 °	39.761085 ° -121.911048 °	25
DWR ID: DWR_NA0003_01_s_2012_25										
9	3.98	3.98		Encroachments	LS	M Ma	PR : Prunings	39.770351 ° -121.901349 °	39.770351 ° -121.901349 °	5
DWR ID: DWR_NA0003_01_s_2012_5										
10	4.32	4.37	Supplemental	USACE Erosion Survey	WS	M Ma	Inspector Comments: 2011 - Two large erosion scallops at the toe from a rotational failure. Deep cracks along the slope indicate the potential for further failures. 2012: Site is part of the extended inventory, last inspected 2011. [2012 Site ID: MUD_4-4_R]	39.773969 ° -121.895078 °	39.773257 ° -121.895618 °	8
DWR ID: DWR_NA0003_01_s_2013_8										
11	4.58	4.58		Encroachments	LS	M Ma	PR : Prunings	39.775908 ° -121.893947 °	39.775908 ° -121.893947 °	21 Y
DWR ID: DWR_NA0003_01_s_2012_21										
12	4.67	4.67		Vegetation	LS	A Ma	V1 : Control annual grass and weeds on the levee slopes and easements.	39.777301 ° -121.893869 °	39.777301 ° -121.893869 °	11 Y
DWR ID: DWR_NA0003_01_s_2013_11										
13	4.82	4.82		Animal Control	LS	M Ma	A1 : Exterminate rodents and backfill and compact or grout burrows.	39.779128 ° -121.892759 °	39.779128 ° -121.892759 °	12 Y
DWR ID: DWR_NA0003_01_s_2013_12										
14	4.91	4.91		Encroachments	LS	M En	PR : Prunings	39.780068 ° -121.891469 °	39.780068 ° -121.891469 °	13 Y
DWR ID: DWR_NA0003_01_s_2013_13										

<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2013**

**Butte County Public Works Department Butte County Public Works**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Mud Creek	Right	7.29	04/11/2013 04/11/2013	Bob Duffey

Levee Mile Report Line	4
Start Levee Mile	2.06
End Levee Mile	2.10
Location	Land Side
Category	
Item	Encroachments
View of the fences along the L/S toe.	
rduffey_s_20130225_123.jpg	



Levee Mile Report Line	7
Start Levee Mile	3.00
End Levee Mile	3.00
Location	Land Side
Category	
Item	Encroachments
View of the pruning pile along the L/S toe.	
rduffey_s_20130225_122.jpg	



Levee Mile Report Line	11
Start Levee Mile	4.58
End Levee Mile	4.58
Location	Land Side
Category	
Item	Encroachments
View of the brush pile along landside toe.	
rduffey_s_20130225_124.JPG	



<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2013**

**Butte County Public Works Department Butte County Public Works**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Mud Creek	Right	7.29	04/11/2013 04/11/2013	Bob Duffey

Levee Mile Report Line	12
Start Levee Mile	4.67
End Levee Mile	4.67
Location	Land Side
Category	
Item	Vegetation
View of the levee with no vegetation on both slopes.	
rduffey_s_20130429_368.JPG	



Levee Mile Report Line	13
Start Levee Mile	4.82
End Levee Mile	4.82
Location	Land Side
Category	
Item	Animal Control
View of the rodent holes along the landside slope.	
rduffey_s_20130429_369.JPG	



Levee Mile Report Line	14
Start Levee Mile	4.91
End Levee Mile	4.91
Location	Land Side
Category	
Item	Encroachments
View of the prunings along the landside slope.	
rduffey_s_20130429_370.JPG	



<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

**Unit Cover Sheet**

**Spring 2013 Levee Inspection Results**

**Butte County Public Works Department Butte County Public Works**

Waterway		Bank	Unit Miles
Unit No. 02 Mud Creek		Left	8.20

	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - February)
Unit Maintenance Rating (Fall Only)				
Date of Inspection	04/11/2013 - 04/11/2013			
DWR Inspector	Bob Duffey			
Accompanied By	Shawn Bates Butte County			

**Summer & Winter Inspections**

The Local Maintaining Agency (LMA) is responsible for summer and winter inspections. The LMA is required to submit a report regarding summer and winter inspections to the California Department of Water Resources (DWR).

DWR must be informed on the:

- a) completion of the inspection
- b) any changes other than the results of normal maintenance
- c) corrections to deficiencies noted in this report

If additional items are noted, further documentation of those items must also be submitted.

The LMA should submit this information to DWR using the LMA web application tool available at:

<http://cdec.water.ca.gov/lma.html>

If the LMA is unable to submit information on this webpage, please contact DWR for assistance.

*The LMA should submit the information and any associated documentation by September 30 for summer inspections and March 31 for winter inspections.*

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2013**

**Butte County Public Works Department Butte County Public Works**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Mud Creek	Left	8.20	04/11/2013 04/11/2013	Bob Duffey

LMR No.	Levee Mile		Category	Item	* Location	+ Rating	Action/Comment	GPS Latitude/Longitude		Issue No. Photo
	Start	End						Start	End	
1	1.58	1.90	Encroachments	LS	U	En	FE : Fence	39.782773 ° -121.888178 °	39.778972 ° -121.891563 °	3 Y
DWR ID: DWR_NA0003_02_s_2012_3										
2	3.42	3.42	Encroachments	LS	M	Ma	PR : Prunings	39.763208 ° -121.908517 °	39.763208 ° -121.908517 °	5 Y
DWR ID: DWR_NA0003_02_f_2012_5										
3	3.45	3.45	Animal Control	CR	M	Ma	A3 : No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.	39.762853 ° -121.908653 °	39.762853 ° -121.908653 °	6 Y
DWR ID: DWR_NA0003_02_s_2013_6										
4	4.70	4.70	Encroachments	LS	C	En	PR : Prunings	39.749727 ° -121.917112 °	39.749727 ° -121.917112 °	1
DWR ID: DWR_NA0003_02_s_2012_1										
5	6.02	6.02	Encroachments	LS	M	En	PR : Prunings	39.736652 ° -121.932053 °	39.736652 ° -121.932053 °	7 Y
DWR ID: DWR_NA0003_02_s_2013_7										

<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2013**

**Butte County Public Works Department Butte County Public Works**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Mud Creek	Left	8.20	04/11/2013 04/11/2013	Bob Duffey

Levee Mile Report Line	1
Start Levee Mile	1.58
End Levee Mile	1.90
Location	Land Side
Category	
Item	Encroachments
View of the fence along the landside toe of the levee.	
rduffey_s_20130225_126.jpg	



Levee Mile Report Line	2
Start Levee Mile	3.42
End Levee Mile	3.42
Location	Land Side
Category	
Item	Encroachments
View of the brush pile along landside toe.	
rduffey_s_20130225_127.JPG	



Levee Mile Report Line	3
Start Levee Mile	3.45
End Levee Mile	3.45
Location	Crown
Category	
Item	Animal Control
View of the rodent hole in the crown roadway.	
rduffey_s_20130429_371.JPG	



<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2013**

**Butte County Public Works Department Butte County Public Works**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Mud Creek	Left	8.20	04/11/2013 04/11/2013	Bob Duffey

Levee Mile Report Line	5
Start Levee Mile	6.02
End Levee Mile	6.02
Location	Land Side
Category	
Item	Encroachments
View of the prunings along the landside toe.	
rduffey_s_20130429_373.JPG	



<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

**Unit Cover Sheet**

**Spring 2013 Levee Inspection Results**

**Butte County Public Works Department Butte County Public Works**

Waterway		Bank	Unit Miles
Unit No. 02A Channel Slough		Left	0.30

	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - February)
Unit Maintenance Rating (Fall Only)				
Date of Inspection	04/11/2013 - 04/11/2013			
DWR Inspector	Bob Duffey			
Accompanied By	Shawn Bates Butte County			

**Summer & Winter Inspections**

The Local Maintaining Agency (LMA) is responsible for summer and winter inspections. The LMA is required to submit a report regarding summer and winter inspections to the California Department of Water Resources (DWR).

DWR must be informed on the:

- a) completion of the inspection
- b) any changes other than the results of normal maintenance
- c) corrections to deficiencies noted in this report

If additional items are noted, further documentation of those items must also be submitted.

The LMA should submit this information to DWR using the LMA web application tool available at:

<http://cdec.water.ca.gov/lma.html>

If the LMA is unable to submit information on this webpage, please contact DWR for assistance.

*The LMA should submit the information and any associated documentation by September 30 for summer inspections and March 31 for winter inspections.*

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2013**

**Butte County Public Works Department Butte County Public Works**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02A Channel Slough	Left	0.30	04/11/2013 04/11/2013	Bob Duffey

LMIR No.	Levee Mile		Category	Item	* Location	+ Rating	Action/Comment	GPS Latitude/Longitude		Issue No. Photo
	Start	End						Start	End	
1	0.04	0.04		Vegetation	LS	A	V1 : Control annual grass and weeds on the levee slopes and easements.	°	°	3
					Ma			°	°	Y

DWR ID: DWR\_NA0003\_02A\_s\_2013\_3

<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2013**

**Butte County Public Works Department Butte County Public Works**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02A Channel Slough	Left	0.30	04/11/2013 04/11/2013	Bob Duffey

Levee Mile Report Line	1
Start Levee Mile	0.04
End Levee Mile	0.04
Location	Land Side
Category	
Item	Vegetation
View of the levee slopes with no vegetation.	
rduffey_s_20130429_374.JPG	



<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

**Unit Cover Sheet**

**Spring 2013 Levee Inspection Results**

**Butte County Public Works Department Butte County Public Works**

Waterway	Bank	Unit Miles
Unit No. 03 Sycamore and Sheep Hollow Creeks	Right	4.13

	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - February)
Unit Maintenance Rating (Fall Only)				
Date of Inspection	04/11/2013 - 04/11/2013			
DWR Inspector	Bob Duffey			
Accompanied By	Shawn Bates Butte County			

**Summer & Winter Inspections**

The Local Maintaining Agency (LMA) is responsible for summer and winter inspections. The LMA is required to submit a report regarding summer and winter inspections to the California Department of Water Resources (DWR).

DWR must be informed on the:

- a) completion of the inspection
- b) any changes other than the results of normal maintenance
- c) corrections to deficiencies noted in this report

If additional items are noted, further documentation of those items must also be submitted.

The LMA should submit this information to DWR using the LMA web application tool available at:

<http://cdec.water.ca.gov/lma.html>

If the LMA is unable to submit information on this webpage, please contact DWR for assistance.

*The LMA should submit the information and any associated documentation by September 30 for summer inspections and March 31 for winter inspections.*

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2013**

**Butte County Public Works Department Butte County Public Works**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 Sycamore and Sheep Hollow Creeks	Right	4.13	04/11/2013 04/11/2013	Bob Duffey

LMIR No.	Levee Mile		Category	Item	* Location	+ Rating	Action/Comment	GPS Latitude/Longitude		Issue No. Photo
	Start	End						Start	End	
1	0.06	0.06		Slope Stability	WS	M	S3 : Repair the levee slope damaged by vehicle traffic and prevent access where possible.	39.786068 ° -121.881828 °	39.786068 ° -121.881828 °	3 Y
DWR ID: DWR_NA0003_03_s_2012_3										
2	1.38	1.38		Vegetation	LS	A	V1 : Control annual grass and weeds on the levee slopes and easements.	39.779414 ° -121.860595 °	39.779414 ° -121.860595 °	4 Y
DWR ID: DWR_NA0003_03_s_2013_4										

<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2013**

**Butte County Public Works Department Butte County Public Works**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 Sycamore and Sheep Hollow Creeks	Right	4.13	04/11/2013 04/11/2013	Bob Duffey

Levee Mile Report Line	1
Start Levee Mile	0.06
End Levee Mile	0.06
Location	Water Side
Category	
Item	Slope Stability
View of the motorcycle erosion on the landside slope of the levee.	
rduffey_s_20130225_128.jpg	



Levee Mile Report Line	2
Start Levee Mile	1.38
End Levee Mile	1.38
Location	Land Side
Category	
Item	Vegetation
View of the levee slopes with no vegetation.	
rduffey_s_20130429_375.JPG	



<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

**Unit Cover Sheet**

**Spring 2013 Levee Inspection Results**

**Butte County Public Works Department Butte County Public Works**

Waterway		Bank	Unit Miles
Unit No. 04 Sycamore and Dry Creeks		Right	2.94

	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - February)
Unit Maintenance Rating (Fall Only)				
Date of Inspection	04/11/2013 - 04/11/2013			
DWR Inspector	Bob Duffey			
Accompanied By	Shawn Bates Butte County			

**Summer & Winter Inspections**

The Local Maintaining Agency (LMA) is responsible for summer and winter inspections. The LMA is required to submit a report regarding summer and winter inspections to the California Department of Water Resources (DWR).

DWR must be informed on the:

- a) completion of the inspection
- b) any changes other than the results of normal maintenance
- c) corrections to deficiencies noted in this report

If additional items are noted, further documentation of those items must also be submitted.

The LMA should submit this information to DWR using the LMA web application tool available at:

<http://cdec.water.ca.gov/lma.html>

If the LMA is unable to submit information on this webpage, please contact DWR for assistance.

*The LMA should submit the information and any associated documentation by September 30 for summer inspections and March 31 for winter inspections.*

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2013**

**Butte County Public Works Department Butte County Public Works**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 04 Sycamore and Dry Creeks	Right	2.94	04/11/2013 04/11/2013	Bob Duffey

LMR No.	Levee Mile		Category	Item	* Location	+ Rating	Action/Comment	GPS Latitude/Longitude		Issue No. Photo
	Start	End						Start	End	
1	0.98	1.05	Encroachments	LS	U	FE : Fence En	39.776013 ° -121.851175 °	39.776595 ° -121.852005 °	1 Y	
DWR ID: DWR_NA0003_04_s_2012_1										
2	1.16	1.27	Encroachments	LS	U	FE : Fence En	39.776760 ° -121.854022 °	39.777650 ° -121.855687 °	3 Y	
DWR ID: DWR_NA0003_04_s_2012_3										
3	1.32	1.40	Encroachments	LS	M	DT : Ditch En	39.778003 ° -121.856403 °	39.778378 ° -121.857953 °	2 Y	
DWR ID: DWR_NA0003_04_s_2012_2										
4	2.72	2.72	Vegetation	LS	A	V1 : Control annual grass and weeds on the levee slopes and easements. Ma	39.785659 ° -121.879249 °	39.785659 ° -121.879249 °	6 Y	
DWR ID: DWR_NA0003_04_s_2013_6										

<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2013**

**Butte County Public Works Department Butte County Public Works**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 04 Sycamore and Dry Creeks	Right	2.94	04/11/2013 04/11/2013	Bob Duffey

Levee Mile Report Line	1
Start Levee Mile	0.98
End Levee Mile	1.05
Location	Land Side
Category	
Item	Encroachments
View of the fence and trees along the landside toe of the levee.	
rduffey_s_20130225_129.jpg	



Levee Mile Report Line	2
Start Levee Mile	1.16
End Levee Mile	1.27
Location	Land Side
Category	
Item	Encroachments
View of the fence along the L/S toe.	
rduffey_s_20130225_131.jpg	



Levee Mile Report Line	3
Start Levee Mile	1.32
End Levee Mile	1.40
Location	Land Side
Category	
Item	Encroachments
View of AG ditch at the L/S toe.	
rduffey_s_20130225_130.jpg	



<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2013**

**Butte County Public Works Department Butte County Public Works**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 04 Sycamore and Dry Creeks	Right	2.94	04/11/2013 04/11/2013	Bob Duffey

Levee Mile Report Line	4
Start Levee Mile	2.72
End Levee Mile	2.72
Location	Land Side
Category	
Item	Vegetation
View of the levee slopes with no vegetation.	
rduffey_s_20130429_376.JPG	



<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

**Unit Cover Sheet**

**Spring 2013 Levee Inspection Results**

**Butte County Public Works Department Butte County Public Works**

Waterway	Bank	Unit Miles
Unit No. 05 Big Chico Diversion	Left	1.85

	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - February)
Unit Maintenance Rating (Fall Only)				
Date of Inspection	04/11/2013 - 04/11/2013			
DWR Inspector	Bob Duffey			
Accompanied By	Shawn Bates Butte County			

**Summer & Winter Inspections**

The Local Maintaining Agency (LMA) is responsible for summer and winter inspections. The LMA is required to submit a report regarding summer and winter inspections to the California Department of Water Resources (DWR).

DWR must be informed on the:

- a) completion of the inspection
- b) any changes other than the results of normal maintenance
- c) corrections to deficiencies noted in this report

If additional items are noted, further documentation of those items must also be submitted.

The LMA should submit this information to DWR using the LMA web application tool available at:

<http://cdec.water.ca.gov/lma.html>

If the LMA is unable to submit information on this webpage, please contact DWR for assistance.

*The LMA should submit the information and any associated documentation by September 30 for summer inspections and March 31 for winter inspections.*

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2013**

**Butte County Public Works Department Butte County Public Works**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 05 Big Chico Diversion	Left	1.85	04/11/2013 04/11/2013	Bob Duffey

LMIR No.	Levee Mile		Category	Item	* Location	+ Rating	Action/Comment	GPS Latitude/Longitude		Issue No. Photo
	Start	End						Start	End	
1	0.34	0.34		Vegetation	LS	A	V1 : Control annual grass and weeds on the levee slopes and easements.	39.761616 °	39.761616 °	3
					Ma			-121.795233 °	-121.795233 °	Y

DWR ID: DWR\_NA0003\_05\_s\_2013\_3

<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2013**

**Butte County Public Works Department Butte County Public Works**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 05 Big Chico Diversion	Left	1.85	04/11/2013 04/11/2013	Bob Duffey

Levee Mile Report Line	1
Start Levee Mile	0.34
End Levee Mile	0.34
Location	Land Side
Category	
Item	Vegetation
View of the native grasses on both levee slopes.	
rduffey_s_20130429_377.JPG	



<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---