

**Flood Control Project Maintenance  
Levee Inspections**

**Fall 2009 Levee Maintenance Deficiency Summary Report**

**Overall LMA & Unit Ratings**

***Miscellaneous Streams & Basins***

---

<b>NA0015</b>	Overall LMA Rating	Total LMA Miles				
<b>Plumas County</b>	<b>A</b>	<b>3.22</b>				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
No Items					PO Miles	CO Miles
<i>LMA Totals:</i>	0.00	0.00	0.00	0.00%	0.00	0.00

  

<b>Unit No. 01 North Fork Feather River</b>	Overall Unit Rating	Total Unit Miles				
	<b>A</b>	<b>1.89</b>				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
No Items					PO Miles	CO Miles
<i>Unit Totals:</i>	0.00	0.00	0.00	0.00%	0.00	0.00

  

<b>Unit No. 02 North Fork Feather River</b>	Overall Unit Rating	Total Unit Miles				
	<b>A</b>	<b>1.33</b>				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
No Items					PO Miles	CO Miles
<i>Unit Totals:</i>	0.00	0.00	0.00	0.00%	0.00	0.00

**Flood Control Project Maintenance  
Levee Inspections**  
**LMA District Cover Sheet**  
**Fall 2009 Levee Inspection Results**

**Plumas County**

---

	Spring (March - May)	Summer ** (June - August)	Fall (September - November)	Winter ** (December - February)
* Overall LMA Rating (Fall Only)			A	

\*\* Non-receipt of Summer or Winter Inspection Reports may effect overall annual rating.

\*  
SPRING INSPECTIONS: Overall maintenance ratings are not determined for the spring inspection results. Individual maintenance deficiencies are rated using the same criteria in the spring and in the fall.

FALL INSPECTIONS: The overall maintenance rating shown above is based on operation and maintenance deficiencies identified within the attached unit inspection reports.

Comments


**Flood Control Project Maintenance  
Levee Inspections**

**Unit Cover Sheet**

**Fall 2009 Levee Inspection Results**

**Plumas County**

Waterway			Bank	Unit Miles
Unit No. 01 North Fork Feather River			Left	1.89
	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - February)
Unit Maintenance Rating (Fall Only)			<b>A</b>	
Date of Inspection			10/12/2009	
DWR Inspector			Bob Duffey	
Accompanied By			Jay Pettigrew Plumas Co.	

Check one:

- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.
- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

**Comments**

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :

DWR Summer/Winter Inspection Reports  
3310 El Camino Avenue, Room LL-30  
Sacramento, CA 95821-9000

**X**

Signature of LMA Representative

Date

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Fall 2009**

**Plumas County**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 North Fork Feather River	Left	1.89	10/20/2009 10/20/2009	Bob Duffey

LMR No	Levee Mile		Category	Item	Location *	Rating **	Action/Comment	GPS Latitude/Longitude		Issue No.
	Start	End						Start	End	Photo
1							No issues were reported.	°	°	°

**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable      PO : Partially Obstructing      C : Corrected  
M : Minimally Acceptable      CO : Completely Obstructing  
U : Unacceptable      N : Not Inspected

**Flood Control Project Maintenance  
Levee Inspections**

**Unit Cover Sheet**

**Fall 2009 Levee Inspection Results**

**Plumas County**

Waterway			Bank	Unit Miles
Unit No. 02 North Fork Feather River			Right	1.33
	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - February)
Unit Maintenance Rating (Fall Only)			<b>A</b>	
Date of Inspection			10/12/2009	
DWR Inspector			Bob Duffey	
Accompanied By			Jay Pettigrew Plumas Co.	

Check one:

- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.
- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

**Comments**

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :

DWR Summer/Winter Inspection Reports  
3310 El Camino Avenue, Room LL-30  
Sacramento, CA 95821-9000

**X**

Signature of LMA Representative

Date

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Fall 2009**

**Plumas County**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 North Fork Feather River	Right	1.33	10/20/2009 10/20/2009	Bob Duffey

LMR No	Levee Mile		Category	Item	Location *	Rating **	Action/Comment	GPS Latitude/Longitude		Issue No.
	Start	End						Start	End	Photo
1							No issues were reported.	°	°	°

**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable      PO : Partially Obstructing      C : Corrected  
M : Minimally Acceptable      CO : Completely Obstructing  
U : Unacceptable      N : Not Inspected